UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE, \$300

SPECIAL FOURTH-CLASS RATE POSTAGE & FEES PAID USNRC PERMIT No. G 67

and they

NUREG-054 Vol. 10, No.

Title List of Documents Made Publicly Availab

December 1-31, 1988

U.S. Nuclear Regulatory Commission

Office of Administration



Available from

Superintendent of Documents U.S. Government Printing Office Post Office Box 37082 Washington, D.C. 20013-7082

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

itle List of Documents Made Publicly Available

ecember 1-31, 1988

te Published: February 1989

vision of Freedom of Information and Publications Services ifice of Administration
S. Nuclear Regulatory Commission ashington, DC 20555



CONTENTS

Preface	٧
Arrangement of Items by Docket Number	
Alphabetic Arrangement of Docket Items by Facility Name	
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27	i
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	7
Domestic Licensing of Special Nuclear Material — Docket 70	186
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	191
Licensing of Independent Spent Fuel Storage — Docket 72	193
Nondocketed Items	195
10 CFR — Commission Meeting Records	195
ACNW — Advisory Committee on Nuclear Waste	195
ACRS — Advisory Committee on Reactor Safeguards	195
ADVCM — NRC Advisory Committee	195
COMMISSION — NRC Commissioners	196
CONTRACT — NRC Contracts and Modifications	197
FOIA — Freedom of Information Act Requests and Releases	198
GEN TECH IS — Generic Technical Issues	203
I&E — Inspection and Enforcement	203
MISC — Public Document Room Miscellaneous	205
NUREG — NUREG Reports and Related Correspondence	205
ORG — Correspondence with Other Organizations	208
PR — Proposed Rule	209
PRM — Petition for Rulemaking	213
PROJ — Projects - Predocket Licensing	213
PT21 — Noncompliance Reports and Related Correspondence	214
QA999 — Quality Assurance Inspections	214
REGGD — Regulatory Guides	215
REVIEW GROUP - NRC Research Review Groups	216
SECY — Position Papers Before the Commission	218
STATE PROG — State Programs	218
TOPREP — Vendor Reports and Related Correspondence	219
WASTE MGT — Nuclear Waste Management	
WASTE RES — Waste Management Research Reports	
XPORTLIC — Export and Import Licenses	
Personal Author Index	
Corporate Source Index	
Report Number Index	
Cross Reference of Enclosures to Principal Documents	
Appendix A — Definitions of Docket 50 Categories	
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a cate in the listing for a docket indicates that no documents in that category were filed in the time period of the re-

The principal elements of the entries in the list are:

(1) P. Operating license stage documents & correspondence

② ③

8411270362 Submits renewed, amended & updated petition under 2.206, urging NRC to quire that util provide Commission full disclosure of intended sources & environ consequences prior to issuing full power OL.


84/11/2

2pp.

SUGARMAN, R.J.

Sugarman, Denworth & Hellegers

Denton, H. Office of Nuclear Reactor Regulation, Director



1. NRC/PDR Document category (see Appendix A).

- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9. This five-digit number is the NRC 48X microfiche designation.
- 10. The three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The five-digit portion of this entry is the number of the frame on which this document ends.
- 12. The three-digit portion of this entry is the number of the frame on which this document ends.
- 13. If this space is blank, the document is available to the public only in the NRC Public Document Room, 2120 L St., N.W., Washington, D.C. 20555. If this space is filled, it gives other source copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of prir items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal it In general, indented items are not in accession number sequence. If the docketed document has a con (FIN) number or a formal report number, it will appear in the last line of the item following entry 5

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public I ment Room. These categories and their symbols are:

10CFR-Commission Meeting Records
ACRS-Advisory Committee on Reactor Safeguards
COMMISSION-NRC Commissioners
CONTRACT-NRC Contracts and Modifications
DISCLOSURE-Financial Disclosure Information
FOIA-Freedom of Information Act Requests and Releases
GEN TECH IS-Generic Technical Issues

I done Decament Room Miscendificons NUREG-NUREG Reports and Related Correspondence ORG—Correspondence with Other Organizations PR-Proposed Rule PRM—Petition for Rulemaking PROJ-Projects-Predocket Licensing PT21—Noncompliance Reports and Related Correspondence QA999—Quality Assurance Inspections **REGGD—Regulatory Guides** RES-Research and Technical Assistance Reports REVIEW GRP-NRC Research Review Groups RM—Rulemakings SECY-Position Papers Before the Commission STATE PROG—State Programs TOPREP-Vendor Reports and Related Correspondence WASH-Regulatory Publications-Pre-NUREG Series

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.


The principal elements of the nondocketed items are:

WASTE MGT—Nuclear Waste Management

XPORTLIC—Exports and Import Licenses

WASTE RES--Waste Management Research Reports

(1) NUREG-NUREG Reports and Related Correspondence



- Nondocket category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9. Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC.: Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the documents.

- 15. This three-digit portion of this entry is the number of the frame on which this document starts.
- 16. This five-digit number is the microfiche on which this document ends.
- 17. This three-digit number is the frame on which this document ends.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Publications Services
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 487-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge card number when placing your order.

3. The address for the PDR is:

2120 L Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation. Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges and method of payment, based on the current reproduction contract, are obtainable from the PDR.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name
Low Level R 27	adwaste Disposal Sites - Docket		40-8801	WESTLAKE LANDFILL, NORTHBROOK,
27-048	RICHLAND, WA, U.S. ECOLOGY, INC.	1	40-8829	FERRET EXPLORATION CO. OF NEBRASKA, INC., CRAWFORD, NE
Domestic Lic Docket 40	censing of Source Material -		40-8857	EVEREST MINERALS CORP., CONVERSE COUNTY, WY
40-0299	UMETCO MINERALS CORP., RIVERTON, WY	1	40-8902	ANACONDA MINERALS CO., GRANTS, NM
40-1162	AMERICAN NUCLEAR CORP., JEFFREY CITY, WY	1	40-8903	HOMESTAKE MINING CO., GRANTS, NM
40-2061	KERR-MCGEE CHEMICAL CORP., WEST CHICAGO, IL	1	40-8904	BP AMERICA, INC./L-BAR URANIUM FACILITY, SALT LAKE
40-2253	ARMY, DEPT. OF, WATERTOWN, MA	1	40-8905	KERR-MCGEE CORP./QUIVIRA MINING CO., OKLAHOMA CITY, OK
40-2259	PATHFINDER MINES CORP., RIVERTON, WY	1	40-8907	UNITED NUCLEAR CORP., SANTA FE, NM
40-3392	ALLIED-SIGNAL, INC., MORRISTOWN, NJ	1	40-8911	MOBIL ALTERNATIVE ENERGY, INC., BOULDER, CO
40-3453	ATLAS MINERALS, INC., DENVER, CO	1	40-8920	BROOKHAVEN MEDICAL IMAGING
40-4492	AMERICAN NUCLEAR CORP., CASPER, WY	2		ASSOCIATES, BROOKHAVEN, PA
40-6377	ARMY, DEPT. OF, DOVER, NJ	2	40-8926	ALTAIR RESOURCES, INC., CASPER, WY
40-6500	ENERGY, DEPT. OF, CANONSBURG, PA	2	40-8943	FERRET EXPLORATION CO. OF NEBRASKA, DENVER, CO
40-6622	PATHFINDER MINES CORP., SHIRLEY BASIN, WY	2	40-8958	URANERZ USA, INC., CASPER, WY
40-7455	WHITTAKER METALS, LOS ANGELES, CA	2	40-8964	SEQUOYAH FUELS CORP., OKLAHOMA CITY, OK
40-7604	BP_CHEMICALS AMERICA, INC., LIMA,	2	40-8968	HYDRO RESOURCES, INC., DALLAS, TX
	ОН		40-8971	U.S. ENERGY CORP., RIVERTON, WY
40-8027	SEQUOYAH FUELS CORP., OKLAHOMA CITY, OK	3	40-8973	SOLUTION MINING CORP., LARAMIE, WY
40-8064	EXXON MINERALS CO., USA, HOUSTON,	3		
40-8084	TX RIO ALGOM MINING CORP., MOAB, UT	3	Domestic Lic Utilization Fa	ensing of Production and cilities - Docket 50
40-8102	EXXON CO., USA, HOUSTON, TX	3	50-2	FORD NUCLEAR REACTOR
40-8406	PESSES CO., SOLON, OH	3	50-3	INDIAN POINT STATION, UNIT 1
40-8452	BEAR CREEK URANIUM CO., CASPER, WY	4	60-10	DRESDEN NUCLEAR POWER STATION, UNIT 1
40-8502	MALAPAI RESOURCES CO., PHOENIX, AZ	4	50-16	ENRICO FERMI ATOMIC POWER PLANT, UNIT 1
40-8681	UMETCO MINERALS CORP., GRAND JUNCTION, CO	4	50-18	VALLECITOS BOILING WATER REACTOR
40-8684	MALAPAI RESOURCES CO., CASPER, WY	4	50-20	MASSACHUSETTS INSTITUTE OF TECHNOLOGY RESEARCH REACTOR
40-8714	CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH	4	60-27	WASHINGTON STATE UNIV. RESEARCH REACTOR (TRIGA)
40-8724	CHEMETRON CORP., CHICAGO, IL	4	50-29	YANKEE-ROWE NUCLEAR POWER STATION
40-8768	KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK	4	50-32	AEROJET-GENERAL NUCLEONICS
40-8778	MOLYCORP, INC., LOS ANGELES, CA	4	50-54	CINTICHEM
40-8786	URANIUM RESOURCES, IPIC., RICHARDSON, TX	4	50-57	BUFFALO MATERIALS RESEARCH CENTER

.

Docket	Name	Page	Docket	Name
50-77	CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR	9	50-243	OREGON STATE UNIV. RESEARCH REACTOR
50-83	UNIV. OF FLORIDA TRAINING REACTOR	9	50-244	ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1
50-89	GENERAL ATOMIC CO.	10	50-245	MILLSTONE NUCLEAR POWER
50-103	AEROJET GENERAL NUCLEONICS	10	30-243	STATION, UNIT 1
50-106	OREGON STATE UNIV. RESEARCH REACTOR	10	50-247	INDIAN POINT STATION, UNIT 2
50-112	UNIV. OF OKLAHOMA RESEARCH REACTOR	10	50-249	DRESDEN NUCLEAR POWER STATION, UNIT 3
50-113	UNIV. OF ARIZONA RESEARCH	10	50-250	TURKEY POINT PLANT, UNIT 3
30-110	REACTOR	. •	50-251	TURKEY POINT PLANT, UNIT 4
50-116	IOWA STATE UNIV. RESEARCH REACTOR	10	50-252	UNIV. OF NEW MEXICO RESEARCH REACTOR
50-123	UNIV. OF MISSOURI RESEARCH REACTOR: ROLLA	10	50-254	QUAD-CITIES STATION, UNIT 1
50-128	TEXAS A&M UNIV. RESEARCH	10	50-255	PALISADES NUCLEAR PLANT
50-120	REACTOR	10	50-259	BROWNS FERRY NUCLEAR POWER STATION, UNIT 1
50-131	OMAHA VETERANS ADMINISTRATION HOSPITAL RESEARCH REACTOR	10	50-260	BROWNS FERRY NUCLEAR POWER STATION, UNIT 2
50-133	HUMBOLDT BAY POWER PLANT, UNIT 3	10	50-261	H.B. ROBINSON PLANT, UNIT 2
50-139	UNIV. OF WASHINGTON RESEARCH REACTOR	11	50-263	MONTICELLO NUCLEAR GENERATING PLANT
50-142	UCLA TRAINING REACTOR	11	50-265	QUAD-CITIES STATION, UNIT 2
50-151	UNIV. OF ILLINOIS RESEARCH REACTOR	11	50-266	POINT BEACH NUCLEAR PLANT, UNIT 1
50-155	BIG ROCK POINT NUCLEAR PLANT	11	50-267	FORT ST. VRAIN NUCLEAR GENERATING STATION
50-160	GEORGIA INSTITUTE OF TECHNOLOGY RESEARCH REACTOR	12	50-269	OCONEE NUCLEAR STATION, UNIT 1
50-183	GA TECHNOLOGIES	12	50-270	OCONEE NUCLEAR STATION, UNIT 2
50-170	ARMED FORCES RADIOBIOLOGY RESEARCH INSTITUTE	12	50-271	VERMONT YANKEE NUCLEAR POWER STATION
50-171	PEACH BOTTOM ATOMIC POWER STATION, UNIT 1	12	50-272	SALEM NUCLEAR GENERATING STATION, UNIT 1
50-183	VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR	13	50-274	U.S. GEOLOGICAL SURVEY RESEARCH REACTOR
50-186	UNIV. OF MISSOURI RESEARCH REACTOR-COLUMBIA	13	50-275	DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1
50-192	UNIV. OF TEXAS RESEARCH REACTOR	13	50-276	AGN-201
50-206	SAN ONOFRE NUCLEAR STATION, UNIT 1	13	50-277	PEACH BOTTOM ATOMIC POWER STATION, UNIT 2
50-213	HADDAM NECK PLANT	15	50-278	PEACH BOTTOM ATOMIC POWER STATION, UNIT 3
50-219	OYSTER CREEK NUCLEAR POWER	16	50-280	SURRY POWER STATION, UNIT 1
	A STATION,	18	50-281	SURRY POWER STATION, UNIT 2
	ЗСН	19	50-282	PRAIRIE ISLAND NUCLEAR STATION, UNIT 1
			50-285	FORT CALHOUN STATION, UNIT 1
	₹	19	50-286	INDIAN POINT STATION, UNIT 3
		19	50-287	OCONEE NUCLEAR STATION, UNIT 3
			50-288	REED COLLEGE RESEARCH REACTOR
	·N,	19	50-289	THREE MILE ISLAND NUCLEAR STATION, UNIT 1

Docket	Name	Page	Docket	Name
50-293	PILGRIM NUCLEAR POWER STATION, UNIT 1	59	50-334	BEAVER VALLEY POWER STATION, UNIT 1
50-294	MICHIGAN STATE UNIV. RESEARCH	62	50-335	ST. LUCIE PLANT, UNIT 1
50-295	REACTOR ZION NUCLEAR POWER STATION, UNIT	62	50-33 6	MILLSTONE NUCLEAR POWER STATION, UNIT 2
50-296	BROWNS FERRY NUCLEAR POWER	63	50-338	NORTH ANNA POWER STATION, UNIT 1
50-200	STATION, UNIT 3	03	50-339	NORTH ANNA POWER STATION, UNIT 2
50-297	NORTH CAROLINA STATE UNIV. PULSTAR REACTOR	65	50-341	ENRICO FERMI ATOMIC POWER PLANT, UNIT 2
50-298	COOPER NUCLEAR STATION	66	50-344	TROJAN NUCLEAR PLANT
50-301	POINT BEACH NUCLEAR PLANT, UNIT 2	67	50-346	DAVIS-BESSE NUCLEAR POWER
50-302	CRYSTAL RIVER NUCLEAR PLANT, UNIT 3	68	50-348	STATION, UNIT 1 JOSEPH M. FARLEY NUCLEAR PLANT,
50-304	ZION NUCLEAR POWER STATION, UNIT	69	50-352	UNIT 1
50-305	KEWAUNEE NUCLEAR POWER PLANT	70	30-332	LIMERICK GENERATING STATION, UNIT 1
50-306	PRAIRIE ISLAND NUCLEAR STATION, UNIT 2	71	50-353	LIMERICK GENERATING STATION, UNIT 2
50-309	MAINE YANKEE ATOMIC POWER PLANT	71	50-354	HOPE CREEK NUCLEAR STATION, UNIT
50-311	SALEM NUCLEAR GENERATING STATION, UNIT 2	72	50-366	UNIV. OF ILLINOIS RESEARCH REACTOR
50-312	RANCHO SECO NUCLEAR GENERATING STATION	73	50-358	WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1
50-313	ARKANSAS NUCLEAR ONE, UNIT 1	75	50-361	SAN ONOFRE NUCLEAR STATION, UNIT
50-315	DONALD C. COOK NUCLEAR POWER	76		2
50-316	PLANT, UNIT 1 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2	77	50-362	SAN ONOFRE NUCLEAR STATION, UNIT 3
50-317	CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1	79	50-364	JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2
50-318	CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2	80	50-366	EDWIN I. HATCH NUCLEAR PLANT, UNIT 2
50-320	THREE MILE ISLAND NUCLEAR	81	50-368	ARKANSAS NUCLEAR ONE, UNIT 2
	STATION, UNIT 2	-	50-369	WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1
50-321	EDWIN I. HATCH NUCLEAR PLANT, UNIT 1	82	50-370	WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 2
50-322	SHOREHAM NUCLEAR POWER STATION	83	50-373	LASALLE COUNTY STATION, UNIT 1
50-323	DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2	87	50-374	LASALLE COUNTY STATION, UNIT 2
50-324	BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2	88	50-382	WATERFORD GENERATING STATION, UNIT 3
50-325	BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1	89	50 - 3 8 7	SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1
50-326	UNIV. OF CALIFORNIA AT IRVINE RESEARCH REACTOR	91	50-388	SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2
50-327	SEQUOYAH NUCLEAR PLANT, UNIT 1	91	50-38 9	ST. LUCIE PLANT, UNIT 2
50-328	SEQUOYAH NUCLEAR PLANT, UNIT 2	93	50-39 0	WATTS BAR NUCLEAR PLANT, UNIT 1
50-329	MIDLAND PLANT, UNIT 1	95	50-391	WATTS BAR NUCLEAR PLANT, UNIT 2
50-330	MIDLAND PLANT, UNIT 2	96	50-395	VIRGIL C. SUMMER NUCLEAR STATION,
50-331	DUANE ARNOLD ENERGY CENTER	96	50.000	UNIT 1 UNIV. OF VIRGINIA CAVALIER REACTOR
60-333	JAMES A. FITZPATRICK NUCLEAR POWER PLANT	97	50-396 50-397	WPPSS NUCLEAR PROJECT, UNIT 2

P

Docket	Name	Page	Docket	Name	Page
		_			181
50-400	SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1	133	STN-50- 508	WPPSS NUCLEAR PROJECT, UNIT 3	101
50-409	LA CROSSE BOILING WATER REACTOR	134	STN-50- 518	HARTSVILLE NUCLEAR PLANT, UNIT 1	181
50-410	NINE MILE POINT NUCLEAR STATION, UNIT 2	134	STN-50- 528	PALO VERDE NUCLEAR STATION, UNIT	181
50-412	BEAVER VALLEY POWER STATION, UNIT 2	135	STN-50- 529	PALO VERDE NUCLEAR STATION, UNIT	182
50-413	CATAWBA NUCLEAR STATION, UNIT 1	136	STN-50-	PALO VERDE NUCLEAR STATION, UNIT	183
50-414	CATAWBA NUCLEAR STATION, UNIT 2	137	530	3	
50-416	GRAND GULF NUCLEAR STATION, UNIT	138	50-537	CLINCH RIVER BREEDER REACTOR	184
50-417	GRAND GULF NUCLEAR STATION, UNIT	141	50-601	RESAR SP/90	184
50 (05	2		50-602	UNIV. OF TEXAS RESEARCH REACTOR	184
50-423	MILLSTONE NUCLEAR POWER STATION, UNIT 3	141	50-603	ALCHEMIE FACILITY 1 - CPDF	184 185
50-424	ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 1	142	50-604 STN 50	ALCHEMIE FACILITY 2 - OLIVER SPRINGS	186
60-425	ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2	145	STN-50- 605	GE ADVANCED BWR DESIGN	100
STN-50- 437	FLOATING NUCLEAR PLANT	147	Domestic L Material - D	lcensing of Special Nuclear Docket 70	
50-438	BELLEFONTE NUCLEAR PLANT, UNIT 1	147	70-0027	BABCOCK & WILCOX CO., LYNCHBURG, VA	186
50-439	BELLEFONTE NUCLEAR PLANT, UNIT 2	148	70-0036	COMBUSTION ENGINEERING, INC.,	187
50-440	PERRY NUCLEAR POWER PLANT, UNIT 1	148		WINDSOR, CT	107
50-441	PERRY NUCLEAR POWER PLANT, UNIT	149	70-0135 70-0143	BABCOCK & WILCOX CO., APOLLO, PA NUCLEAR FUEL SERVICES, INC.,	187
50-443	2 SEABROOK NUCLEAR STATION, UNIT 1	150	70-0143	ERWIN, TN	,31
50-444	SEABROOK NUCLEAR STATION, UNIT 2		70-0364	BABCOCK & WILCOX CO., APOLLO, PA	189
50-445	COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 1	157	70-0371	UNC NAVAL PRODUCTS, INC., UNCASVILLE, CT	180
50-446	COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 2	160	70-0398	COMMERCE, DEPT. OF, WASHINGTON, DC	188
STN-50-	BYRON STATION, UNIT 1	163	70-0622	ARMY, DEPT. OF, DOVER, NJ	106
454			70-0687	CINTICHEM, INC., TUXEDO, NY	198
STN-50- 455	BYRON STATION, UNIT 2	165	70-0734	GENERAL ATOMICS, SAN DIEGO, CA	188
STN-50- 456	BRAIDWOOD STATION, UNIT 1	167	70-0820	UNC RECOVERY SYSTEMS, WOOD RIVER JUNCTION, RI	188
STN-50- 457	BRAIDWOOD STATION, UNIT 2	169	70.0824	BABCOCK & WILCOX CO., LYNCHBURG, VA	189
50-458	RIVER BEND STATION, UNIT 1	171	70-0925	CIMMARON CORP., OKLAHOMA CITY, OK	181
50-460	WPPSS NUCLEAR PROJECT, UNIT 1	173	70-1100	COMBUSTION ENGINEERING, INC.,	181
50-461	CLINTON POWER STATION, UNIT 1	173	70 4140	WINDSOR, CT	4.0
STN-50- 470	CESSAR SYSTEM 80	174	70-1113	GENERAL ELECTRIC CO., WILMINGTON, NC	18
STN-50- 482	WOLF CREEK GENERATING STATION	174	70-1151	WESTINGHOUSE ELECTRIC CORP., COLUMBIA, SC	18
STN-50- 483		176	70-1201	B&W FUEL CO., LYNCHBURG, VA	18
97N-50- 498	SOUTH TEXAS PROJECT, UNIT 1	177	70-1257	ADVANCED NUCLEAR FUELS CORP., RICHLAND, WA	18
STN-50-		470	70-1308	GENERAL ELECTRIC CO., SAN JOSE, CA	
498		178	70-1426	TRANSNUCLEAR, INC., FALLS CHURCH, VA	18

..:

Docket	Name	Page	Docket	Name	Page
70-1703	EASTMAN KODAK CO., ROCHESTER, NY	190	71-6078	MODEL: 927A1 & 927C1, COMBUSTION	192
70-1718	SHADYSIDE HOSP., PITTSBURGH, PA	190		ENGINEERING, INC.	
70-1739	TRI-STATE MOTOR TRANSIT CO., JOPLIN, MO	190	71-6346	MODEL: FSV-1 & 1A, GA TECHNOLOGIES, INC.	192
70-2479	TRANSNUCLEAR, INC., FALLS CHURCH,	190	71-6386	MODEL: 235R001, ENERGY, DEPT. OF	192
	VA		71-6400	MODEL: 6400, WESTINGHOUSE ELECTRIC CORP.	192
70-2910	TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN	190	71-6601	MODEL: CNS 6-120, CHEM-NUCLEAR	192
70-2917	TENNESSEE VALLEY AUTHORITY,	190		SYSTEMS, INC.	
	CHATTANOOGA, TN		71-6639	MODEL: MH-1A, ENERGY, DEPT. OF	192
70-2928	TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN	190	71-9010	MODEL: NLI-1/2, NUCLEAR ASSURANCE CORP.	192
70-2932	TEXAS UTILITIES GENERATING CO., DALLAS, TX	190	71-9080	MODEL: HN-600 & NUPAC 100, WESTINGHOUSE-HITTMAN NUCLEAR	192
70-2941	TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN	190	71-9105	MODEL: RAD-WASTE CR.I, CHEM- NUCLEAR SYSTEMS, INC.	192
70-3041	INTERNATIONAL FREIGHT FORWARDERS, INC., ATLANTA, GA	190	71-9107	MODEL: 771, TECH/OPS, INC.	192
70-3054	PHILADELPHIA ELECTRIC CO	190	71-9147	MODEL: 850, TECH/OPS, INC.	192
	PHILADELPHIA, PA		71-9165	MODEL: 865, TECH/OPS, INC.	192
Transport a	of Radioactive Material for nd Transportation of Radioactive		71-9180	MODEL: 500-SU-OP, AUTOMATION INDUSTRIES, INC.	192
Material Uni	der Certain Conditions - Docket 71		71-9187	MODEL: 865, TECH/OPS, INC.	192
71-0024	HITTMAN NUCLEAR & DEVELOPMENT CORP.	191	71-9200	MODEL: 125-B, ENERGY, DEPT. OF	192
71-0102	SOURCE PROD. & EQUIP. CO., INC.	191	71-9202	MODEL: TN-BRP, TRANSNUCLEAR, INC.	192
71-0276	DUQUESNE LIGHT CO.	191	71-9206	MODEL: TN-REG, TRANSNUCLEAR, INC.	192
71-0421	NAVY, DEPT. OF	191	71-9218	MODEL: TRUPACT-II, ENERGY, DEPT.	193
71-0454	ATOMIC ENERGY OF CANADA, LTD.	191	71-9219	OF MODEL: HFIR, ENERGY, DEPT. OF	193
71-0506	BABCOCK & WILCOX CO.	191	71-9219	MODEL: GA-4, GENERAL ATOMICS	193
71-0509	MET-CHEM ENGINEERING	191	71-9227	MODEL: GA-9, GENERAL ATOMICS	193
	LABORATORIES, INC.		71-9229	MODEL: TITAN, WESTINGHOUSE	193
71-0649	UNIV. OF CALIFORNIA, BERKELEY	191	71-8228	ELECTRIC CORP.	100
71-0665	ULTRASONIC SPECIALISTS, INC.	191	71- 9 233	MODEL: TN-RAM, TRANSNUCLEAR, INC.	193
71-3005	IRRADIATOR, ROCKWELL INTERNATIONAL CORP.	191	Licensino (of Independent Spent Fuel Storage	
71-3006	MODEL: 1500, TRANSPORTATION, DEPT. OF	191	- Docket 7	2	100
71-4909	MODEL: GE-21PF-1, GENERAL ELECTRIC CO.	191	72-0001	MORRIS OPERATIONS, GENERAL ELECTRIC CO.	193
71-5971	MODEL: 200, GENERAL ELECTRIC CO.	191	72-0002	VIRGINIA ELECTRIC & POWER CO.	193
71-5984	MODEL: 5984, J.L. SHEPHERD &	191	72-0003	CAROLINA POWER & LIGHT CO.	193
	ASSOCIATES		72-0004	DUKE POWER CO., 50-269	193

--:::

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	F
Low Level Radwaste Disposal Sites - Docket 27		-	PATHFINDER MINES CORP., SHIRLEY BASIN, WY	40-6622	
RICHLAND, WA, U.S. ECOLOGY, INC.	27-048	1	PESSES CO., SOLON, OH	40-8406	
	2. 0.0	•	RIO ALGOM MINING CORP., MOAB, UT	40-8084	
Domestic Licensing of Source Material - Docket 40			SEQUOYAH FUELS CORP., OKLAHOMA CITY, OK	40-8027	
ALLIED-SIGNAL, INC., MORRISTOWN, NJ	40-3392	1	SEQUOYAH FUELS CORP., OKLAHOMA	40-8964	
ALTAIR RESOURCES, INC., CASPER, WY	40-8926	6	CITY, OK		
AMERICAN NUCLEAR CORP., CASPER, WY	40-4492	2	SOLUTION MINING CORP., LARAMIE, WY	40-8973	
AMERICAN NUCLEAR CORP., JEFFREY	40-1162	1	U.S. ENERGY CORP., RIVERTON, WY	40-8971	
CITY, WY ANACONDA MINERALS CO., GRANTS, NM	40-8902	5	UMETCO MINERALS CORP., GRAND JUNCTION, CO	40-8681	
ARMY, DEPT. OF, DOVER, NJ	40-6377	2	UMETCO MINERALS CORP., RIVERTON, WY	40-0299	
ARMY, DEPT. OF, WATERTOWN, MA	40-2253	1	UNITED NUCLEAR CORP., SANTA FE, NM	40-8907	
ATLAS MINERALS, INC., DENVER, CO	40-3453	1	URANERZ USA, INC., CASPER, WY	40-8958	
BEAR CREEK URANIUM CO., CASPER, WY	40-8452	4	URANIUM RESOURCES, INC., RICHARDSON,	40-8786	
BP AMERICA, INC./L-BAR URANIUM	40-8904	6	TX		
FACILITY, SALT LAKE	40-0004	J	WESTLAKE LANDFILL, NORTHBROOK, IL	40-8801	
BP CHEMICALS AMERICA, INC., LIMA, OH	40-7604	2	WHITTAKER METALS, LOS ANGELES, CA	40-7455	
BROOKHAVEN MEDICAL IMAGING ASSOCIATES, BROOKHAVEN, PA	40-8920	6	Domestic Licensing of Production and Utilization Facilities - Docket 50		
CHEMETRON CORP., CHICAGO, IL	40-8724	4	AEROJET GENERAL NUCLEONICS	50-103	
CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH	40-8714	4	AEROJET-GENERAL NUCLEONICS	50-32	
ENERGY, DEPT. OF, CANONSBURG, PA	40-6500	2	AEROTEST RADIOGRAPHY & RESEARCH REACTOR	50-228	
EVEREST MINERALS CORP., CONVERSE COUNTY, WY	40-8857	5	AGN-201	50-276	
EXXON CO., USA, HOUSTON, TX	40-8102	3	ALCHEMIE FACILITY 1 - CPDF	50-603	
EXXON MINERALS CO., USA, HOUSTON, TX	40-8064	3	ALCHEMIE FACILITY 2 - OLIVER SPRINGS	50-604	
FERRET EXPLORATION CO. OF NEBRASKA,	40-8943	7	ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 1	50-424	
DENVER, CO			ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2	50-425	
FERRET EXPLORATION CO. OF NEBRASKA, INC., CRAWFORD, NE	40-8829	5	ARKANSAS NUCLEAR ONE, UNIT 1	50-313	
HOMESTAKE MINING CO., GRANTS, NM	40-8903	5	ARKANSAS NUCLEAR ONE, UNIT 2	50-368	
HYDRO RESOURCES, INC., DALLAS, TX	40-8968	7	ARMED FORCES RADIOBIOLOGY RESEARCH INSTITUTE	50-170	
KERR-MCGEE CHEMICAL CORP., WEST CHICAGO, IL	40-2061	1	BEAVER VALLEY POWER STATION, UNIT 1	50-334	
KERR-MCGEE CORP./QUIVIRA MINING CO	40-8905	6	BEAVER VALLEY POWER STATION, UNIT 2	50-412	
OKLAHOMA CITY, OK		•	BELLEFONTE NUCLEAR PLANT, UNIT 1	50-438	
KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK	40-8768	4	BELLEFONTE NUCLEAR PLANT, UNIT 2	50.439	
MALAPAI RESOURCES CO., CASPER, WY	40-8684	4	BIG ROCK POINT NUCLEAR PLANT	50-155 STN 50-458	
MALAPAI RESOURCES CO., PHOENIX, AZ	40-8502	4		STN-50-456	
MOBIL ALTERNATIVE ENERGY, INC., BOULDER, CO	40-8911	6	BROWNS FERRY NUCLEAR POWER	STN-50-457 50-259	
MOLYCORP, INC., LOS ANGELES, CA	40-8778	4	STATION, UNIT 1		
PATHFINDER MINES CORP., RIVERTON, WY	40-2259	1	BROWNS FERRY NUCLEAR POWER STATION, UNIT 2	50-260	
		•	· · · · · · · ·		

Name	Docket	Page	Name	Docket	Þ
BROWNS FERRY NUCLEAR POWER	50-296	63	FORD NUCLEAR REACTOR	50-2	
STATION, UNIT 3			FORT CALHOUN STATION, UNIT 1	50-285	
BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1	50-325	89	FORT ST. VRAIN NUCLEAR GENERATING STATION	50-267	
BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2	50-324	88	GA TECHNOLOGIES	50-163	
BUFFALO MATERIALS RESEARCH CENTER	50-57	9	GE ADVANCED BWR DESIGN	STN-50-605	
BYRON STATION, UNIT 1 S	TN-50-454	163	GENERAL ATOMIC CO.	50-89	
BYRON STATION, UNIT 2	STN-50-455	165	GEORGIA INSTITUTE OF TECHNOLOGY RESEARCH REACTOR	50-160	
CALLAWAY PLANT, UNIT 1 S	STN-50-483	176	GRAND GULF NUCLEAR STATION, UNIT 1	50-416	
CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1	50-317	79	GRAND GULF NUCLEAR STATION, UNIT 2	50-417	
CALVERT CLIFFS NUCLEAR POWER PLANT,	50-318	80	H.B. ROBINSON PLANT, UNIT 2	50-261	
UNIT 2			HADDAM NECK PLANT	50-213	
CATAWBA NUCLEAR STATION, UNIT 1	50-413	136	HARTSVILLE NUCLEAR PLANT, UNIT 1	STN-50-518	
CATAWBA NUCLEAR STATION, UNIT 2	50-414	137	HOPE CREEK NUCLEAR STATION, UNIT 1	50-354	
CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR	50-77	9	HUMBOLDT BAY POWER PLANT, UNIT 3	50-133	
	STN-50-470	174	INDIAN POINT STATION, UNIT 1	50-3	
CINTICHEM	50-54	9	INDIAN POINT STATION, UNIT 2	50-247	
CLINCH RIVER BREEDER REACTOR	50-537	184	INDIAN POINT STATION, UNIT 3	50-286	
CLINTON POWER STATION, UNIT 1	50-461	173	IOWA STATE UNIV. RESEARCH REACTOR	50-116	
COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 1	50-445	157	JAMES A. FITZPATRICK NUCLEAR POWER PLANT	50-333	
COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 2	50-446	160	JOSEPH M. FARLEY NUCLEAR PLANT, UNI	T 50-348	
COOPER NUCLEAR STATION	50-298	66	JOSEPH M. FARLEY NUCLEAR PLANT, UNI	T 50-364	
CRYSTAL RIVER NUCLEAR PLANT, UNIT 3	50-302	68	2	#A DAF	
DAVIS-BESSE NUCLEAR POWER STATION,	50-346	107	KEWAUNEE NUCLEAR POWER PLANT	50-305	
UNIT 1 DIABLO CANYON NUCLEAR POWER PLANT	. 50-275	44	LA CROSSE BOILING WATER REACTOR LASALLE COUNTY STATION, UNIT 1	50-409 50-373	
UNIT 1	, 30-270	44	LASALLE COUNTY STATION, UNIT 2	• •	
DIABLO CANYON NUCLEAR POWER PLANT	r, 50-323	87		50-374	
UNIT 2 DONALD C. COOK NUCLEAR POWER	EQ 045	70	LIMERICK GENERATING STATION, UNIT 1	50-352	
PLANT, UNIT 1	50-315	76	LIMERICK GENERATING STATION, UNIT 2	50-353	
DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2	50-316	77	MAINE YANKEE ATOMIC POWER PLANT MASSACHUSETTS INSTITUTE OF TECHNOLOGY RESEARCH REACTOR	50-309 50-20	
DRESDEN NUCLEAR POWER STATION, UNIT 1	50-10	8	MICHIGAN STATE UNIV. RESEARCH REACTOR	50-294	ļ
DRESDEN NUCLEAR POWER STATION, UNIT 2	50-237	19	MIDLAND PLANT, UNIT 1	50-329	J
DRESDEN NUCLEAR POWER STATION, UNIT 3	50-249	23	MIDLAND PLANT, UNIT 2	50-330	1
DUANE ARNOLD ENERGY CENTER	50-331	96	MILLSTONE NUCLEAR POWER STATION, UNIT 1	50-245	j.
EDWIN I, HATCH NUCLEAR PLANT, UNIT 1			MILLSTONE NUCLEAR POWER STATION,	50-336	:
EDWIN I. HATCH NUCLEAR PLANT, UNIT 2		• •	UNIT 2	30-330	•
ENRICO FERMI ATOMIC POWER PLANT, UNIT 1	50-16		MILLSTONE NUCLEAR POWER STATION, UNIT 3	50-423	ì
ENRICO FERMI ATOMIC POWER PLANT, UNIT 2	50-34	1 104	MONTICELLO NUCLEAR GENERATING PLANT	50-263	;
FLOATING NUCLEAR PLANT	STN-50-43	7 147	NINE MILE POINT NUCLEAR STATION, UN 1	T 50-220)

Name	Docket	Page	Name	Docket	Pa
NINE MILE POINT NUCLEAR STATION, UNIT	50-410	134	SAN ONOFRE NUCLEAR STATION, UNIT 3	50-362	
2	50.000	400	SEABROOK NUCLEAR STATION, UNIT 1	50-443	1
NORTH ANNA POWER STATION, UNIT 1 NORTH ANNA POWER STATION, UNIT 2	60-338 50-339	102 103	SEABROOK NUCLEAR STATION, UNIT 2	50-444	1
NORTH CAROLINA STATE UNIV. PULSTAR		65	SEQUOYAH NUCLEAR PLANT, UNIT 1	50-327	
REACTOR	50-297	QΘ	SEQUOYAH NUCLEAR PLANT, UNIT 2	50-328	
OCONEE NUCLEAR STATION, UNIT 1	50-269	39	SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1	50-400	1
OCONEE NUCLEAR STATION, UNIT 2	50-270	40	SHOREHAM NUCLEAR POWER STATION	50-322	
OCONEE NUCLEAR STATION, UNIT 3	50-287	56	SOUTH TEXAS PROJECT, UNIT 1	STN-50-498	1
OMAHA VETERANS ADMINISTRATION HOSPITAL RESEARCH REACTOR	50-131	10	SOUTH TEXAS PROJECT, UNIT 2	STN-50-499	1
OREGON STATE UNIV. RESEARCH	50-243	20	ST. LUCIE PLANT, UNIT 1	50-335	
REACTOR	FO 100	46	ST. LUCIE PLANT, UNIT 2	50-389	1
OREGON STATE UNIV. RESEARCH REACTOR	50-106	10	SURRY POWER STATION, UNIT 1	50-280	
OYSTER CREEK NUCLEAR POWER PLANT	50-219	16	SURRY POWER STATION, UNIT 2	50-281	
PALISADES NUCLEAR PLANT	50-255	28	SUSQUEHANNA STEAM ELECTRIC	50-387	1
PALO VERDE NUCLEAR STATION, UNIT 1 S	TN-50-528	181	STATION, UNIT 1		
PALO VERDE NUCLEAR STATION, UNIT 2 S	STN-50-529	182	SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2	50-388	1
PALO VERDE NUCLEAR STATION, UNIT 3 S	STN-50-530	183	TEXAS A&M UNIV. RESEARCH REACTOR	50-128	
PEACH BOTTOM ATOMIC POWER STATION, UNIT 1	50-171	12	THREE MILE ISLAND NUCLEAR STATION, UNIT 1	50-289	
PEACH BOTTOM ATOMIC POWER STATION, UNIT 2	50-277	46	THREE MILE ISLAND NUCLEAR STATION, UNIT 2	50-320	
PEACH BOTTOM ATOMIC POWER STATION, UNIT 3	50-278	47	TROJAN NUCLEAR PLANT	50-344	1
PERRY NUCLEAR POWER PLANT, UNIT 1	50-440	. 148	TURKEY POINT PLANT, UNIT 3	50-250	
PERRY NUCLEAR POWER PLANT, UNIT 2	50-441	149	TURKEY POINT PLANT, UNIT 4	50-251	
PILGRIM NUCLEAR POWER STATION, UNIT	50-293	59	U.S. GEOLOGICAL SURVEY RESEARCH REACTOR	50-274	
POINT BEACH NUCLEAR PLANT, UNIT 1	60-266	37	UCLA TRAINING REACTOR	50-142	
POINT BEACH NUCLEAR PLANT, UNIT 2	50-301	67	UNIV. OF ARIZONA RESEARCH REACTOR	50-113	
PRAIRIE ISLAND NUCLEAR STATION, UNIT	50-282	52	UNIV. OF CALIFORNIA AT IRVINE RESEARCH REACTOR	60-326	
PRAIRIE ISLAND NUCLEAR STATION, UNIT 2	60-306	71	UNIV. OF CALIFORNIA RESEARCH REACTOR	50-224	
QUAD-CITIES STATION, UNIT 1	50-254	27	UNIV. OF FLORIDA TRAINING REACTOR	ፎህ ሺን	
QUAD-CITIES STATION, UNIT 2	50-265	36	UNIV. OF ILLINOIS RESEARCH REACTOR		
RANCHO SECO NUCLEAR GENERATING STATION	60-312	73	UNIV. OF ILLINOIS RESEARCH REACTOR		
REED COLLEGE RESEARCH REACTOR	50-288	58	UNIV. OF LOWELL RESEARCH		
RESAR SP/90	50-601	184	UNIV. OF MISSOURI RESEARC COLUMBIA		
RIVER BEND STATION, UNIT 1	50-458	171	UNIV. OF MISSOURI RESEARC		
ROBERT EMMET GINNA NUCLEAR PLANT,	50-244	20	ROLLA		
UNIT 1			UNIV. OF NEW MEXICO RESE/ REACTOR		
SALEM NUCLEAR GENERATING STATION, UNIT 1	50-272	43	UNIV. OF OKLAHOMA RESEAF REACTOR		
SALEM NUCLEAR GENERATING STATION, UNIT 2	50-311	72	UNIV. OF TEXAS RESEARCH F		
SAN ONOFRE NUCLEAR STATION, UNIT 1	50-206	13	UNIV. OF TEXAS RESEARCH I		
SAN ONOFRE NUCLEAR STATION, UNIT 2	50-361	112	UNIV. OF VIRGINIA CAVALIER		

1:

HEACTON			INC., ATLANTA, GA	
VALLECITOS BOILING WATER REACTOR	50-18	8	NUCLEAR FUEL SERVICES, INC., ERWIN, TN	70-0143
VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR	50-183	13	PHILADELPHIA ELECTRIC CO., PHILADELPHIA, PA	70-3054
VERMONT YANKEE NUCLEAR POWER	50-271	42	SHADYSIDE HOSP., PITTSBURGH, PA	70-1718
STATION VIRGIL C. SUMMER NUCLEAR STATION,	50-395	130	TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN	70-2917
WASHINGTON STATE UNIV. RESEARCH	50-27	8	TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN	70-2910
REACTOR (TRIGA) WATERFORD GENERATING STATION, UNIT	50-382	124	TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN	70-2941
3 WATTS BAR NUCLEAR PLANT, UNIT 1	50-390	128	TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN	70-2928
WATTS BAR NUCLEAR PLANT, UNIT 2	50-391	129	TEXAS UTILITIES GENERATING CO., DALLAS, TX	70-2932
WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1	50-369	120	TRANSNUCLEAR, INC., FALLS CHURCH, VA	70-2479
WILLIAM B. MCGUIRE NUCLEAR STATION,	50-370	121	TRANSNUCLEAR, INC., FALLS CHURCH, VA	70-1426
UNIT 2 WILLIAM H. ZIMMER NUCLEAR STATION,	50-358	112	TRI-STATE MOTOR TRANSIT CO., JOPLIN, MO	70-1739
WOLF CREEK GENERATING STATION S	TN-50-482	174	UNC NAVAL PRODUCTS, INC., UNCASVILLE, CT	70-0371
WPPSS NUCLEAR PROJECT, UNIT 1	50-460	173	UNC RECOVERY SYSTEMS, WOOD RIVER JUNCTION, RI	70-0820
WPPSS NUCLEAR PROJECT, UNIT 2	50-397	131	WESTINGHOUSE ELECTRIC CORP.,	70 1151
WPPSS NUCLEAR PROJECT, UNIT 3 ST	TN-50-508	181	COLUMBIA, SC	70-1151
YANKEE-ROWE NUCLEAR POWER STATION	50-29	8	Packaging of Radioactive Material for	
ZION NUCLEAR POWER STATION, UNIT 1	50-295	62	Transport and Transportation of	
ZION NUCLEAR POWER STATION, UNIT 2	50-304	69	Radioactive Material Under Certain Conditions - Docket 71	
Domestic Licensing of Special Nuclear			ATOMIC ENERGY OF CANADA, LTD.	71-0454
Material - Docket 70			BABCOCK & WILCOX CO.	71-0506
ADVANCED NUCLEAR FUELS CORP., RICHLAND, WA	70-1257	189	DUQUESNE LIGHT CO. HITTMAN NUCLEAR & DEVELOPMENT	71-0275 71-0024
ARMY, DEPT. OF, DOVER, NJ	70-0822	188	CORP.	71-0024
B&W FUEL CO., LYNCHBURG, VA	70-1201	189	IRRADIATOR, ROCKWELL INTERNATIONAL CORP.	71-3005
BABCOCK & WILCOX CO., APOLLO, PA	70-0135	187	MET-CHEM ENGINEERING LABORATORIES,	74.0500
BABCOCK & WILCOX CO., APOLLO, PA	70-0364	188	INC.	71-0509
BABCOCK & WILCOX CO., LYNCHBURG, VA	70-0824	189	MODEL: 125-B, ENERGY, DEPT. OF	71-9200
BABCOCK & WILCOX CO., LYNCHBURG, VA	70-0027	186	MODEL: 1500, TRANSPORTATION, DEPT.	71-3006
CIMMARON CORP., OKLAHOMA CITY, OK	70-0925	189	OF	
CINTICHEM, INC., TUXEDO, NY	70-0687	188	MODEL: 200, GENERAL ELECTRIC CO.	71-5971
COMBUSTION ENGINEERING, INC., WINDSOR, CT	70-0036	187	MODEL: 235R001, ENERGY, DEPT. OF MODEL: 500-SU-OP, AUTOMATION	71-6386 71-9180
COMBUSTION ENGINEERING, INC., WINDSOR, CT	70-1100	189	INDUSTRIES, INC. MODEL: 5984, J.L. SHEPHERD &	71-5984
COMMERCE, DEPT. OF, WASHINGTON, DC	70-0398	188	ASSOCIATES	
EASTMAN KODAK CO., ROCHESTER, NY	70-1703	190	MODEL: 6400, WESTINGHOUSE ELECTRIC CORP.	71-6400
GENERAL ATOMICS, SAN DIEGO, CA	70-0734	188	MODEL: 771, TECH/OPS, INC.	71-9107
GENERAL ELECTRIC CO., SAN JOSE, CA	70-1308	190	MODEL: 850, TECH/OPS, INC.	71-9147
GENERAL ELECTRIC CO., WILMINGTON, NO	70-1113	189	MODEL: 865, TECH/OPS, INC.	71-9165
		v.,;;;;		-

Name	Docket	Page	Name	Docket	Page
MODEL: 865, TECH/OPS, INC.	71-9187	192	MODEL: TITAN, WESTINGHOUSE ELECTRIC	71-9229	193
MODEL: 927A1 & 927C1, COMBUSTION ENGINEERING, INC.	71-6078	192	CORP. MODEL: TN-BRP, TRANSNUCLEAR, INC.	71-9202	192
MODEL: CNS 8-120, CHEM-NUCLEAR	71-6601	192	MODEL: TN-RAM, TRANSNUCLEAR, INC.	71-9233	193
SYSTEMS, INC.			MODEL: TN-REG, TRANSNUCLEAR, INC.	71-9206	192
MODEL: FSV-1 & 1A, GA TECHNOLOGIES, INC.	71-6346	192	MODEL: TRUPACT-II, ENERGY, DEPT. OF	71-9218	193
MODEL: GA-4, GENERAL ATOMICS	71-9226	193	NAVY, DEPT. OF	71-0421	191
MODEL: GA-9, GENERAL ATOMICS	71-9227	193	SOURCE PROD. & EQUIP. CO., INC.	71-0102	191
MODEL: GE-21PF-1, GENERAL ELECTRIC	71-4909	191	ULTRASONIC SPECIALISTS, INC.	71-0665	191
CO.			UNIV. OF CALIFORNIA, BERKELEY	71-0649	191
MODEL: HFIR, ENERGY, DEPT. OF	71-9219	193			
MODEL: HN-600 & NUPAC 100, WESTINGHOUSE-HITTMAN NUCLEAR	71-9080	192	Licensing of Independent Spent Fuel Storage - Docket 72		
MODEL: MH-1A, ENERGY, DEPT. OF	71-6639	192	CAROLINA POWER & LIGHT CO.	72-0003	193
MODEL: NLI-1/2, NUCLEAR ASSURANCE	71-9010	192	DUKE POWER CO., 50-269	72-0004	193
CORP.			MORRIS OPERATIONS, GENERAL ELECTRIC CO.	72-0001	193
MODEL: RAD-WASTE CR.I, CHEM-NUCLEAR SYSTEMS, INC.	71-9105	192	VIRGINIA ELECTRIC & POWER CO.	72-0002	193

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-048 RICHLAND, WA, U.S. ECOLOGY, INC.

- 8812070082 Forwards "Historical Environ Monitoring Rept of US Ecology Low Level Radwasta Disposal Facility," to satisfy License Condition 58 ADAMS,SR. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 88/11/30. INGERSCLL,CE: Washington, State of, 108pp. 47747:200-47747:307.
- 8912150151 Forwards SNM receipt & bunal rept for Nov 1988,per Condition 6 of License 16-19204-01.Rept of Isotopic activity as required for Washington License WN-1019-2 also encl. Rept withherd (ref. 10CFR2.790). RITTENBERG.R.8 U.S. Ecology, Inc. (formerly Nuctear Engineering, Inc.) 88/12/07. KNAPP,M.R. NRC - No Detailed Affil ation Given. 1p. 47869-001-47869-001.
- 8812230173 Advises that one of Oct 1986 monthly TLD results exceeded 30 mrem per month investigatory action level in Table 61 of stds manual due to normal disposal operations in proximity to station Monitering of radiation levels continuing COLEMAN.C.E. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.) 88/12/14. INGERSOLL.C.E. Washington, State of 1p. 47910 350 47910 360
- 8812230183 Informs that eight of nine listed environ air gross beta results exceeded action level during 881024-1101 Results attributed to ambient temp background gross bata level consistent wifevols previously reported for stations.

 COLEMAN, C.E. U.S. Ecology, Inc. (formorly Nuclear Engineering, Inc.) 88/12/14. INGERSOLL, C.E. Washington, State of, Dept. of Social & Health Services. 2pp. 47911.014-47911.016
- 8812230165 Forwards comments on draft Amend 8 to License 16:19204-01. Requests that NRC requirements that SNM repts submitted to State of WA also be submitted to NRC be detailed.

 CARPENTER,S.A. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.) 88/12/19 SHAFFNER,J.A. NRC No Detailed Affiliation Given, 3pp. 47911.024-47911.026.
- 8812230195 Grants permission to NFIC to copy monthly burial repts in, "Rept of Isotope Activity by Generator." Into In rept re customer Identification, waste stream & svcs provided should be withheld from public disclosure (ref. 10CFR2.790). GARPENTER, S.A. U.S. Ecology, Inc., (formerly Nuclear Engineering, Inc.), 88/12/20, JOI INSON,D. Document Control Branch (Document Control Dask), 2pp. 47911-018-47911-017.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UMETCO MINERALS CORP., RIVERTON, WY

- 8812020194 "Second-Stage Detection Monitoring at UMETCO Minerals Corp., East Gas Hills, Wyoming Site" W/21 oversize maps. TRAMMELLJW, HOFFMAN, GLUMETCO Minerals Corp. (subs. of Union Carbida Corp.), 88/10/31, 176pp. 47722
- 8812050070 Third Quarter 1988 rept for A.0 scepage collection sys. W/881021 ltr. TRAMMELL,J.W. UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 88/00/30. GARLAND,W.L. Wyoming, State of. 29pp. 47723.112-47723:140.
- 8812050315 Application for amond to License SUA-648,0stabilishing background amounts of hazardous constituents in groundwater. Fee patri.
 TRAMMELL,J.W. DMETCO Minerals Corp. (subs. of Union Carbide Corp.). 88/10/13.
 KONWINSKI,G. Uranium Rocovery Field Dic, R4. 2pp. 47731:357-47731:358.
- 8812020048 Forwards Amend 7 to License SUA-848, revising License Conditions 54(E)(1) & 58 as listed.
 SMITH, R.D. Uramum Recovery Field Olc, R4. 88/11/16. UMETCO Minerals Corp. (subs. of Union Carbido Corp.): 2pp. 47798:355-47740.032.
- --8812020053 Amend 7 to License SUA-064B for Umetco Minerals Corp., revising Conditions 64(E)(1) 8 58 as listed.
 SMITH,R.D. Uranium Recovery Field Ofc, R4, 88/11/15, 12pp. 47739.357-47740.027.
- -8812020059 Recommends that Condition 58 of Liconse SUA 648 be revised to authorize receipt & disposal of in situ wastes in A-9 disposal area per liconses 880829 application.
- HEYER, B. S. Uranium Recovery Field Ofc, R4. 88/11/15. Uranium Recovery Field Ofc, R4. 5pp. 47740.028-47740.032.
- 8812210350 Forwards annual geotechnical insp of evaporation ponds.per License Condition 52 of SUA-648.Well 21 which was included in rept was accidentally destroyed some time age 8 should not be part of monitoring program.

 TRAMMELLJ.W. UMETCO Minorals Corp. (subs. of Union Carbide Corp.) 88/11/22.

 HEYER,R. Uranium Recovery Field Ofc, R4, 20pp. 47877.073-47877.092.

DOCKET 40-1182 AMERICAN NUCLEAR CORP., JEFFREY CITY, WY

- 8812050309 Application for amond to License SUA-56, deloting Western Nuclear, Inc. from ficense & transforring ficense to American Nuclear Ortp Fee paid BAKER, SU. Wostern Nuclear, Inc. (subs. of Phelips Dodge Corp.). 68/10/14. PETTENGILL, H.J. Uranium Recovery Field Otc, R4. 3pp., 47731:159-47731:161.
- 8811280053 Informs that radiation safety officer will attend blannual refresher course in radiation protection during 1989.per License Condition 48.Decommissioning of Spilit Rock Mill made appropriate training course before and of 1998 impossible. BAKER,S.J. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 88/11/07. PETTENGILL,H.T. Uranium Recovery Field Ofc, R4. (p. 47652-239-47652-239.
- 8812050174 Application for amend to License SUA-56, dateling refs to Frazier-Lamac No processing of concentrates ever occurred at site. BAKER, S.J. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 88/11/14, PETTENGILL, H.J. Uranium Recovery Field Otc, R4, 18pp. 47731:025-47731:040.

- 88 12020114 Concludes that Spirt Rock tailings embankment parterming within design specs. 8 remains in stable condition at present, based on submitted into did 870701 No further licensing action or review necessary at present JACOBY, D.L., HAWKINS, E.F., Uranium Recovery Field Otc, R4: 88/11/15. Uranium Recovery Field Otc, R4: 3pp. 47707:161-47707:163.
- 8812010366 Approves 881107 request to extend training requirement of radiation safety officer.per License Condition 48. PETTENGILL, H.J. Uranium Recovery Field Ofc, R4. 88/11/23. BAKER,S. Western Nuclear, Inc. (subs. of Fhelps Dodge Corp.). 2pp. 47703 083-47703 084.
- 8812020128 Discusses licensee 881101 submittel of som/annual ALARA Budit rept for Split Rock U milt licensee performed acceptable ALARA audit No further action recessary.

 HEYERIRS, PETTENGILL H.J. Uranum Recovery Field Ofc, R4. 88/11/23 Uranum Recovery Field Ofc, R4. 3pp. 47716-314-47716-316
- 8812210041 Forwards Amend 48 to License SUA-1162, revising Condition 74C to reflect revised submitted dead-line for groundwater corrective action program SMTH,R.D. Utanium Recovery Field Ofc, R4, 89/12/09, BAKER,S. Western Nuclear, Inc. (subs. of Phe'ps Dodge Corp.). 3pp. 47889.298-47889.332.
- -8812210045 Amend 48 to Liconse SUA-56 for Western Nuclear, Inc., revising Condition 74C to rellect revised submittal deadline for groundwater corrective action program SMITH, R.D. Uranium Recovery Field Otc., R4. 88/12/08. 24pp. 47889.301-47889:332.

DOCKET 40-2081 KERR-MCGEE CHEMICAL CORP., WEST CHICAGO, IL

8812190078 Motion for order directing Issuance of final supplito FES & request for status conference. Board urged to enter order directing NRC to release final supplito FES by 890118-W/ Certificate of Svc MESERVERA, Kerr-McGee Chamical Corp. (subs. of Kerr-McGee Corp.) MESERVERA. Covington & Builing. #488-7650. 88/12/08. Atomic Safety and Licensing Board Panel. 7pp. 47802 210-47802-216

DOCKET 40-2253 ARMY, DEPT. OF, WATERTOWN, MA

- 8812190154 FOIA request for Inspirepts from 1986-1980 & application for renewal of license did 850529 REINERT, Silver Business Journal 88/11/23, NRC - No Detailed Affiliation Given 1p. 47841:202-47841:202.
- 8812190161 Final response to FOIA request for records.App A documents encl & available in PDR.
 PHILLIPS,J Division of Frandom of Information & Publications Serv.ces (Post 880515). 88712/16. REINERT.S. Boston Rusiness Journal. 2pp 47841/203-47841/288
- --8602250453 Forwards application for renewal of License SUR-238, authorizing possession & use of U-238 for alloy fabrication, research, development & prototype purposes & thorium oxides for high temp vacuum melting TARAS, DN. Army, Dopt of. 85/05/23. Region 1, Otc of the Director. 2pp. 47841:205-47841:288.
- --8602250459 Application for renewal of License SUB-238 authorizing use of U-238 for alloy febrication, research, development & prototype purposes & therium exide for high temp vacuum molting.
 WRIGHT,E.S. Army, Depy of, Materials Technology Laboratory, 85/03/29, 71pp, 47841:207-47841:288.

DOCKET 40-2259 PATHFINDER MINES CORP., RIVERTON, WY

- 8812210298 Forwards amend to Lir of Credit 0987, increasing amount offective 981215. BAUDON,N. Credit du Nord. 88/12/01. Uranium Recovery Field Ofc, R4. 1p. 47876:129-47876:130.
- --8812220028 Informs of amend to Ltr of Credit 0067, increasing amount effective 881215. GUTIERREZ, J. Credit du Nord. 88/11/30. Uranium Recovery Field Ofc, R4 1p. 47875-130-47876-130.

DOCKET 40-3392 ALLIED-SIGNAL, INC., MORRISTOWN, NJ

8812270212 Requests response to 871119 request for addl info re 870826 application for amend to License SUB-526 within 60 days. BIDINGER.G.H. Fuel Cycle Safety Branch. 88/12/22 BISHOP.J.C. Allied Signal Corp. ip. 47927:037-47927.037.

DOCKET 40-3453 ATLAS MINERALS, INC., DENVER, CO

- 8812060004 Application for amend to License SUA-917,amending license to show expiration date of 891231. Fee paid.
 BLUBAUGH,R.E. Atlas Corp. 88/09/29. PETTENGILL,H.J. Uranium Receivery Field Ofc, R4, 3pp. 47734:250-47734:252.
- 8811280088 Requests 60-day extension to deadline for submission of addi info re Moab mill reclamation plan. BLUBAUGH.R.E. Atlas Corp. 88/10/28. JACOBY,D.L. Uranium Recovery Field Ofc, R4. 1p. 47854:153-47854:153.
- 8812010418 Advises that NRC willing to delay receipt of reclamation plan by 45 days in response to 861028 request into requested by 890116. HAWKINS,E.F. Uranium Recovery Field Ofc. R4. 88/11/17. BLUBAUGH,R.E. Atlas Corp. 2pp. 47700.038-47700.039.

DOCKETED ITEMS

- 8612210138 Recommends that Conditions 17.21 & 49 of License SUA-917 be amended 8 12210138 Recommends that Conditions 17.21 a 45 th Cesting 300 47 to demended as slated Requirement for Allas Materials to submit decortain hat on & docum is Sorting repts within 60 days of complation of subjectivities also recommended SCOVILLYR, PETTENSILLHU, Uranium Recovery Fetd Ofic, R4 88/11/28 Uranium Recovery Fetd Ofic, R4 709 478/78/212 478/8 219
- 8812210139 Forwards Amend 3 to License SUA-917,revising License Conditions 17,21 & 49 Decommissioning plan & cost estimate discussed.
 SMITH,RID Litenium Recovery Field Ofc. R4, 68/11/28, BLUBAUGH,RIE Attas Corp. 4pp 47889 259 47889 202.
- --8812210171 Amend 3 to License SUA-917 for Atlas Corpeutnorizing use of natural U at fac.hty located in Moeb,UT.
 SMITH,R.D. Uranium Recovery Field Ofc. R4. 68/11/28 13pp. 47895.263-47689 292
- 8812220102 Recommends that License SUA 0917 be amended ray sing License Condi-tions 17 & 49 re-groundwater protection sids & environ 8 efficient anonhology program respectively KONWINSKI, G.R., MAWKINS, E.F., Uranium Recovery Field Ofc, R4, 88/12/13 Uranium R4, 88/12/13 Uran um Recovery Field Ofc, R4 5pp 47886 190-47886 194
- 8812220085 Forwards Amend 4 to Licensa SUA-0917, lexising License Conditions 17 & 49 re-compliance monitoring program. Licensee required to submit corrective action programs by 890401 SMITH.R.D. Uranium Recovery Field Old, R4, 88/12/14, 8LUBAUGH, R.E. At as Corp.
 - 3pp. 47901 321 47901 353
- -8812220088 Amend 4 to Licensa SUA-0917 ray sing License Conditions 17 & 49 re implementation of compt ance monitoring program SMITH,R D. Uranum Recovery Field Ofc. R4 (88/12/14, 12pp 47901:324-47901:353

DOCKET 40-4492 AMERICAN NUCLEAR CORP., CASPER, WY

- 8812050318 Application for amend to Licensis SUA-687,8"owing receipt of Maispai & Cloveland Cliffs wastes Waste will be placed in shallow trenches in stabilized surface of Tallings Pond 1. Fee paid. ANDRUS N.J. American Nuclear Corp. 88/08/04. SMITH,R.O. Uranium Recovery Field Otc. R4, App. 47731:359-47732 001.
- 8812210020 Submis reclamation cost estimate ta American fluctear Corp mili decomissioning Evaluation based on cost estimates presented in Andrus 680322 8 1031 litis 8 ons to inspire 1881101 linspirect enct. MONLEY,M. Wyoming, State of 88/11/708, Wyoming, State of 89/14/708-47947 018
- 8812020148 Forwards Amend 35 to Licenso SUA-667,deleting groundwater monitoring requirements is ted in Condition 13 & adding requirements to Condition 29. SMITH R D. Uranium Recovery Field Otc. R4, 88/11/14 Amendan Nuclear Corp. 3pp 47718 207-47718,249.
- -8812020155 Amend 35 to Ucense SUA-667 for Gas Hills Project American Nuclear Copp deleting groundwater mondoring requirements from Condition 13 & adding requirements to Condition 29 SMITH, R.D. Urahum Recovery Field Olic, R4 98/11/14, 11pp 47718 210 47718.244
- -8612020162 Discusses establishment of groundwater protection stds.per idensed 880329 & 1010 submittals of groundwater quality data KONWINSKI,GR., HAWKINS,EF. Uranijum Recovery Field Otc, R4 88/11/09 Uranijum Recovery Field Otc, R4 5pp 47718 245-47718 249.
- 8812210075 Discusses bond amount for Permit 352 & Incremental release process.Revegetation retainer will be held for at least 5 yrs from date of seeding to assure erosional stability & proper revegetation. WOOD,R. Wyoming, State of, 88/11/22 FERGUSON,J.C. American Nuclear Corp. 2pp. 47882:029-47882.030.
- 8811300505 Forwards Radiation Safety Insp Rept 40-4492/88-02 on 881117. No violations or deviations noted PETTENGILLHJ. Uranum Recovery Field Otc, R4. 88/11/28 FERGUSON, J. American Nuclear Corp. 1p. 47676-198-47676 205.
- --8811300516 Insp. Rept. 40-4492/88-02 on. 881117 No violations. 8 deviations noted Major areas inspected Ulimiting operations 8 rediation safety program including mpt organization 8 controls/ operations review addition protection 8 radwaste. HEYER, R. S., 405E, H.D., PETTENGILL, H.J. Uren um Recovery Field Ofc. R4, 88/11/28, 7pp. 47676,199-47676;205
- 8812210162 Forwards Bureau of Land Mgt Rept 031-87-032,per License Condition 26 re archeological & historical artifact survey of reclamation site. SALISBURY, W.C. American Nuclear Corp. 88/12/06. SMITH.R.D. Uranium Recovery Field Otc, R4. 6pp. 47875-251-47875-258.
- 8812210151 Responds to 881130 ltr.withdrawing 880804 application for amend to Li-cense SUA-0867 NRC terminates review of application. SMITH,R.D. Uranium Recovery Field Otc. R4 88/12/07. FERGUSON,J.C. American Nuclear Corp. 2pp. 47808.294-47888.295.
- 8812210387 Ack receipt of 881206 archaological & historical artifact survey. License Condition 26 survey requirement for reclamation activities at Gas Hills Project satisfi-
- fied. HAWKINS,E.F. Uranium Recovery Field Ofc, R4. 88/12/15, American Nuclear Corp. 2pp. 47875.083 47875 084.

DOCKET 40-8377 ARMY, DEPT. OF, DOVER, NJ

8812220022 Application for amends to Licenses 29.00047-02,29-00047-06, 29.00047-08,29-00047-09,\$UB-948 8 SNM-581 authorizing R Moss as alternate radiation protection officer.

TARAS.O.N. Army, Dept. of 88/11/22. Region 1, Ofc of the Director, 11pp.
47902.333-47902.343.

DOCKET 40-6500 ENERGY, DEPT. OF, CANONSBURG, PA

- 8812156287 Forwards response to NRC 886823 comments re 8u/ret_PA vicinity grope-by site (VP 2007860) survival ance 8 maint plan Response consists of June 1988 plan & addordum ARTHURW J. Energy, Dept. or 48/12/12 LOHAUS,P. Division of Low Level Wester Management & Decenium scioning (Post 070413). Tp. 47828:331-47829:200
- --8812150271 "Burral PA Vicinity Properties Surveillance & Maint Plan" W/addenoum & response to comments Energy, Dept of 88/06/30, 275pp 47828 332 47829:203.
- 812190180 Forwards Intel rept of Toe Ditch Riprap Repair Program for UMTRAP, Canonsburg PA, for IRC review Issuance of Incense for long-terming roung maint & surverlance of disposal site requested ARTHUM, W.J. Energy, Dept of 48/12/12, LOHAUS, P. Division of Low Level Waste Management & Decommissioning (Post 870413), 2pp. 47854-001-47854-128 8812190180 Forwards
- 8812 190 191 "Toe Oilch Riprap Repair Program UMTRAP, Canoneturg, PA"
 Morrison-Knudsen Engineers, Inc. 88/10/31, 126pp. 47054:003-47854:126
- 8812130063 Forwards Vots 1,2,2A,3,3A,3B & 3C to "Vicinity Proporty Completion Flort" final remodulal actions for UMTRAP All remedial action at Burrell PA UMTRAP vicinity property site comprete Addondum will be submitted in Dec 1988.

 ARTHUR,WIJ Energy, Dept of 88/12/01, LOHAUS,PIH Division of Low Loyal Wasta Management & Decommissioning (Post 870413), 2pp. 47895-001-47899.091.
- 8812130070 Vots 1,2.2A,3,3A,3B & 3C to "Vicinity Property Completion Rept," line" in medial actions for UMTRAP,Burroll,PA
 MK-Ferguson Co. B8708/31, 1,529pp, 47895-033-47899-001
- 8812190302 Forwards DOE certification summary for Burrell,PA Vicinity Property Site VP CA 269/809 All ramed all actions complated ARTHUR,W.J. Energy, Dopt. of. 88/12/13, YUSKO,J. Permsylvenia, Commonwed No. 01/3pp 47340, 124-47840-128.

DOCKET 40-6622 PATHFINDER MINES CORP., SHIRLEY BASIN, WY

- 8811230243 Responds to violations & deviations noted during Inspiral Electrical SUA-442 on 860908-11 Corrective actions greater attention to review process, completion of writing specified procedures & consuling vendor to roduce time of analysis HOPKINS.R.J. Pathfinder Mines Corp. 88/10/14 PETTENGILL,H.J. Uranium Rucovery Field Cit., Ft4. 8pp. 47657:180-47657.187.
- 8811230319 Forwards Amend 17 to License SUA-442, authorizing issuance of index to existing that credit SMITHALD, Uranium Recovery Field Olc, R4, 88/10/31, HOPKINS,R. Pathteidor Mines Corp App. 47631,219 47631 249
- -8611230324 Amen: 117 to Ucense SUA-442 for Pathlinder Minos Corp, authorizing un limited amount of U.place of use & possession of U waste failings generated by mil ing operations SMITH,R D. Uran um Recovery Field Ofc, R4, 88/10/31, 10pp, 47631 223-47631 249
- 8812020085 Ack receipt of 881014 fit providing responses to notices of violation & Jovation & recommendations per insp Rept 40-6622/88-01 Disagrees w/response to licm 1(a) of violation. Std operating procedure requested by 881220.

 PETTENG*1_t/i_J__Vranum_Recovery_Field_0c,_R4_89/11/16_HOPKINS,R_J__Pailinder_Mines_Corp__3pp__47719.008-47719.010.
- 8812210298 Forwards amend to Litr of Credit 0067,increasing amount effective 881215 BAUDON,N Credit du Nord 88/12/01. Uranium Rocovery Field Ofc, R4 1p 47875 129-47875 130.
- ~8812220028 Informs of amend to Lir of Credit 0067, Increasing amount officially 88/215 GUTIERREZ,J. Credit du Nord 88/11/30. Utanium Recovery Field Ofc, R4. 1p. 47875 130 47875 130

DOCKET 40-7465 WHITTAKER METALS, LOS ANGELES, CA

- 8811230220 "Audit Rept of Radioactive Mail Located Next to Greenvillo Meth's MILLER,F. Whittaker Corp. 88/11/14, 2pp. 47657.257-47657:258.
- 8812230169 Annual monitoring program rept (including semiannual monitoring program for erosion insphiper Conditions 11.8.12 of License SMA-1018.dtd 881608 LOUTT11,G.J. Whittaker Corp. 88/12/12 ROUSE,L. Fuel Cycle Safety Branch 4pp 47917.357-47917:359
- 8812230174 Audit rept of radioactive mail located next to Greenvillo Meta's Greenvillo-PA (located include,gates,fences, signs on fencing & fence integrity All results satisfactory

MILLER,F.L. Whittaker Corp. 88/12/14, 2pp. 47911,007-47911,008.

DOCKET 40-7604 BP CHEMICALS AMERICA, INC., LIMA, OH

- 88 11290337 Forwards schedule for decontamination of ponds,grounds,bidgs & pilho: fa ciwies on site,per License Condron 14 of License SUB-908.Schedule based on un derstanding of remarking onsite contamination SIMON.S.J BP International Ltd 88/11/11. ROUSE,L.C. Fuel Cycle Safety Branch 36pp 47667.051-47667:086
- 8811290577 Submits comments on rept by Nuclear Energy Svcs describing decontains nation actions & pre- & post-decontainnation status for five areas requested for unro-stricted release at BP Chomical Plant in Lima,OH LANDIS,M R. Oak Ridge Associated Usavs. 88/11/17. LAROCHE,G. Office of Nuclea Material Safety & Safeguards,Director. 3pp. 47665:222-47665-225.

- 8812090179 Forwards Onsite Insp Rept 40-7604788-01 on 880707-08, including Info obtained by telcons during 880728-9026 No violations noted liesp initiated in response to allegations reliuse & disposal of radioactive matts at facility.

 MALLETT, B.S. Region 3, Otc of the Director 88/12/05 WALPOLE.

 William William Co. (formerly Solvio Chemical Co.) 2pp. 47762-274-47762-286
- -6812090183 Safety linsp Rept 46-7604/88-01 on 660726-1004 No violations noted Major areas inspected six allegations derived from 880708,21 8 0829 telcons w/individual representing Allen County Citizens for Environ. FRANCE G.M., GILL, C.F., SRENIAWSKI, O.J., Regran 3, Otc of the Director, 88/12/02 Ltpp 47762/276-47762/286

DOCKET 40-8027 SEQUOYAH FUELS CORP., OKLAHOMA CITY, OK

- 8811230008 Forwards revs to Part I,Soction 2.7.4, "Design Control" & Part II,Section 9.8, "Changes in Procedures, Factilities & Equipment," for review & approval. STAUTER, J.C. Sequipyah Fuels Corp. (subsidio of Kerri-McGeo Nuclear Corp.), 88/10/17. ROUSE, L.C. Fuel Cycle Safety Branch. 5pp. 47799.300-47799.301
- 8811230008 Forwards rovs to Part I, Section 2.7.4, "Obsign Control" & Part II, Section 9.8, "Changes in Proceduras, Facrifies & Equipment," for review & approval STAUTER, J.C. Sequeyah Fuels Corp. (subs. of Kerr-MoGee Nuclear Corp.) 88/10/17. ROUSE, L.G. Fuel Cyclu Safety Branch. 2pp. 47799 300-47799 301
- --8812140220 Requests remittance of application fee of \$150 for amond to Licenso SUB-1010.

 JACKSON,G License Fee Managoment Branch 88/11/10. STAUTER,J.C. Sequoyah Fuela Corp. (subs. of Kerr-McGee Nuclear Corp.) 1p. 47799 302-47799 302.
- --8812140221 Submits application (ed.por 881110 request re Licensa SUB-1010. STAUTER,J.C. Korr-McGoo Corp. 88/11/29. JACKSON,G. Licensa Foa Management Branch Spp. 47789.303-47799-305
- 8812050028 NPDES discharge monitoring rapt for Oct 1988.W/881102 & 08 ftrs. KNIGHT.S P. Sequeyah Fuels Corp. (subs. of Kerr-McGee Nuclear Corp.) 88/10/31. 6pp. 47740;163-47740 f68
- 8811300113 Forwards "Behavior of Five Monitor Wells to Repetitive Evacuation."
 KNIGHT,S.P. Sequoyah Fuols Corp. (subs. of Kerr-McGee Nuclear Corp.) 88/11/17.
 BIDINGER,G.H. Fuel Cycle Safety Branch. 2pp. 47702 116-47702 147.
- ~8811300118 "Behavior of Five Monttor Wells to Repetitive Evacuation." COUCH.C. Sequeyah Fuels Corp. (subs. of Kerr-McGeo Nuclear Corp.) WIDMANN,R Kerr-McGeo Corp. 88711714, 33pp. 47702.118-47702,147.
- 8812210056 Forwards hydrological study of five monitor wai/s,per 880516 meeting betwoon NRC, Kerr-McGee & Soquoyah Fuels Corp. KNIGHT S.P. Soquoyah Fuels Corp. (subs. of Kerr-McGee Nuclear Corp.). 88/11/17. BIDINGER,G.H. Fuel Cycle Safety Branch. 1p. 47878.050-47876.050.
- 8812010414 Ack receipt of 881103 ftr informing NRC of stops taken to correct violations 8 deviations noted in insp. Rept. 40:0027/80-03. Acceptability of retraction of commitment Leansing issue which will be evaluated by NRC-Heartquarters. PETTENGILL, H.J. Uranum Receivery Field Olc, R4, 08711718, KNIGHT.S. Sequeyah Fuels Corp. (subs. of Korr-McGee Nuclear Corp.) 3pp. 47703-300-47703:302.
- 8812210290 Informs that liconsoo experienced exceedance of nitrate max allowable concentration limit at surface water runoil Outtail SFC 805 (OWR8 Location 003) Causod by leaching of intrates from studge pond Soils will be disposed KNIGHT, S.P. Sequeyah Fuels Corp. (aubs. of Kort-McGae Nuclear Corp.), 88/11/28. BLACHLEY, T. Oklahoma, State of, 1p. 47881:100-47881:100.
- 8812120023 Forwards response to issues relised in request,por Ht. Thempson 881026 response to request. CUNNINGITAM, R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/11/30. BARNETT, J.R. Oklahoma, State of. 4pp. 47780:107-47780.110.
- 8812150008 Forwards State of OK Water Fresources Board 881005 ftr & NRC 881100 response Decommissioning plan requested by 800301. W/o ands ROUSE, L.C. Fuel Cycle Safety Branch, 88112706. KNIGHT, S.P. Sequeyah Fuels Corp. (subs. of Kent-McGoe Nuclear Corp.), 1p. 47800-280-47800-280.
- 8812210186 Forwards soil sample analysis results for Sequevah Fuels Corp Goro OK U conversion tacility based on 880822-25 Insp. Unable to substantiate allegation of improper disposal of contaminated waste based on review of written procedures. SMITH,RD. Uranium Racovery Floid Otc., R4. 88/12/07. ROUSE,L.C. Fuel Cycle Salety Branch. 1p. 47877.082-47877.087.
- -9612210169 Forwards results of seri samples. PRICE, J.C. Oak Ridge Nahonel Laboratory. 88/11/22. KONWINSKI,G.R. NRC - No Detailed Attribution Given. 5pp. 47877:063-47877.067.
- 8812210247 Informs that revised map Inserted Into Chapter 14 of demonstration section of license application.per 881031 ft. PENNINGTON,W.S. Fuel Cycle Satety Branch. 88/12/08. KNIGHT,S.P. Sequoyah Fuels Corp. (aubs. of Kerr-McGee Nuclear Corp.) 1p. 47875:128-47875.128.
- 8812210381 Farwards review of licansee 881114 rept, "Behavior of Five Monitor Wells to Repetitive Evacuation." Site must be adequately regulated from liquid effluent standpoint to prevent further groundwater contamination from occurring, SMITH,R.D. Uranium Recovery Field Otc, R4. 88/12/15. ROUSE,L.C. Fuel Cycle Safety Branch. 5pp. 47875:240-47875:247.

DOCKET 40-8064 EXXON MINERALS CO., USA, HOUSTON, TX

- 8812060003 Application for amend to License SUA-1611, transferring Exxon Coal & Minerals Co facilities under License SUA-1064, to Everest Minerals Corp.Fee paid. MAYS,W.M. Everest Minerals Corp. 88/10/20 Uranium Recovery Field Olc, R4. 1p. 47741.066, 47741.066.
- 8612050133 Forwards application for amond to License SUA-1064, terminating licenso-Facilities covered by subj license transferred to Everest Minerals Corp w/License SUA-1511 Request for amend to License SUA-1511 also encl. PATTON,JD. Exxon Corp. 86/10/31. PETTENGILL,H.J. Uranium Recovery Field Otc, R4. 1p. 47733:312-47733:348.

- -6612050135 Application for amend to License SUA-1064 terminating (Icense Fee paid. PATTON,J D. Exxon Corp. 86/10/31. 1p. 47733 313-47733.313
- --8812050138 Application for amend to License SUA-1511, authorizing transfer of facilities covered under License SUA-1084 to License SUA-1511 Fee paid MAYS.W.M. Everest Minerals Corp. 88/10/20. Uranium Recovery Field Ofc, R4. 35pp. 47733-344-47733-348.
- 8812210358 Submits 1988 Third Quarter rept no prior in situ mining program in Converse County,WY Decommissioning completed on process facilities around & within recovery bldg,RO bldg & header house.

 RANGE,D.M. Exxon Corp. 88/11/30. Uranium Recovery Field Ofc. R4. 2pp 47876:193-47878-194
- 8812210161 Responds to 881031 application for termination of License SUA-1064 for Highland Project Compilation of enci NRC Form-314 prior to termination of License required. SMITH,R.D. Utanium Recovery F.eld Ofc. R4, 88/12/07. PATTON.J.D. Exxon Corp. 3pp. 47880 152-47880 154

DOCKET 40-8084 RIO ALGOM MINING CORP., MOAB, UT

- 8812080002 Application for amend to License SUA-1119,rovising License Condition 45B to rothin 8.5 it freeboard until 890430 Fee pald PATTISON,R.S. Rro. Algom Mining Corp. 88/11/03. SMITH,R.D. Uran'um Recovery Field Otc, Rd. 2pp. 47740-319.47740.320
- 8812050014 Forwards annual technical evaluation rept for takings embankments & Bisco Lake embankement for review re License Condition 45E. PATTISON.R.S. Rio. Algom Miring Corp., 88/11/07. SMITH.R.D. Uranium Recovery Field Ofc, R4. 4pp. 47732.059 47732.062
- 8812010352 Submits review of ALARA audit rept for Rio Algom Mining Corp for Mar-Aug 1988. Licensee performance acceptable. SCOVILLV.R. Uranium Recovery Field Otc, R4. 88/11/23. Uranium Recovery Field Otc, R4. 4pp. 47703.056-47703.059
- 8812010365 D.scusses rept of elevated urine bloassay result at Rio Algem Lisbon Mill.NRC concurs wifeensee Indings indicating that data for four individuals working in series for same period show organic Interference wifluoremetric analysis SCOVILLY R. PETTENGILLII-J. Uranium Recovery Field Otc, R4, 3pp. 47703:000-47703.062.
- 8812210274 Informs of change of telephone numbers as of 881202.New numbers lated.
 REAVEAU,B.K. R.o. Algom Mining Corp. 68711/30. SMITH,R.D. Urantum Recovery Field Ofc, R4. 1p. 47876:198-47876.198.
- 8812210175 Submits review of annual technical evaluation of embankment performance for Lisbon Mill.per License Condition 44 of License SUA-1119 Licensee performed acceptable evaluation of embankment performance No further action necessary. SCOVILL,V.R., SMITH,R.D. Uranum Recovery Field Otc, R4, 88/12/06, Uranium Recovery Field Otc, R4, 88/12/06, Uranium Recovery Field Otc, R4, 38/12/06.
- 8812210268 Forwards request for addit into ro proposed reclamation plan Criteria sot forth in 10CFR40,App A must be addressed. Response due before end of Feb 1989 HAWKINS,E.F. Uranium Recovery Flatd Olc, R4, 88/12/14, PATTISON,R S. Ro Algem Mining Corp. 15pp 47075:087-47875.101.

DOCKET 40-8102 EXXON CO., USA, HOUSTON, TX

- 8812090175 Application for amend to License SUA-1139,extending 981031 deadline re groundwater monitoring data by 60 days Fao paid PATTON, J.D. Exxon Corp. 89/11/01, FIAWKINS,E.F. Uranium Recovery Field Ofc, R4. 1p. 47741-05-47741-055.
- 8812210006 Forwards revised Enct if to JD Patton 681020 request for amond to Licones SUA-1139,por 881108 conversation. Typo corrected in last paragraph of encl. RANGE,D.M. Exxon. Corp. 68/11/08. KONWINSKI,G. Uranium Recovery Field Otc, R4. 2pp. 47876;127-478/6;128.
- 8812020033 Forwards Amend 26 to License SUA-1139,modifying License Conditions 33 & 40.
 SMITH,H.D. Uranium Recovery Fletch Otc, R4. 88/11/17. Exxon Corp. 3pp. 47765:022-47755:045.
- -8812020041 Amend 26 to License SUA-1139 for Exxon Corp.authorizing possession of byproduct matis w/o regard to form or quantity as failings or other waste produced during extraction & concentration of U in milling facilities. SMITH,R.D. Uranium Recovery Field Ofc, R4. 88/11/17. 18pp. 47756 025-47765-042.
- -8812020045 Discusses Amend 26 to License SUA-1139,modifying License Conditions 33 & 40. JACOBY,D.L., HAWKINS,E.F. Uranium Recovery Field Olc, R4. 88/11/16. Uranium Recovery Field Olc, R4. 3pp. 47755:043-47765.045.
- 8812210300 Advises that encit It of Credit (LOC) 127LC5820784 accepted in fleu of surety bond & replaces LOC 127LC5800830.

 JORDAN,P. Wyoming, State of 88711730. RANGE,D Exxon Corp. 4pp. 47875:288-47875:291.

DOCKET 40-8406 PESSES CO., SOLON, OH

8812210384 Summarizes NRC comments on 881114 draft work plan for stabilization of Pesses Co (METCOA) site in Pulaski,PA.per 881123 telcon. Site restabilization considered wasted of lime & money. FRIEDMANL.F. Region 1, Ofc of the Director. 88/12/07, KHO,P. Environmental Protection Agency. 4pp. 47881:320-47881:323.

- 8812200308 Advises that fand use within 5 miles of restricted area boundary remains as described in June 1982 environ rept No new private residences of potable water wells constructed since environ rept & grazing remains as primary use of area. BLOSSOM,J.N. Bear Croek Uranium Co. 98/11/09, JACCBY,D. Uranium Rocovery Field Otc, R4. 1p. 47867.309-47857.309.
- 8812020096 Informs that settlement monitoring layout presented on Nov 1988 Drawing 04-C-038 adequate Drawing replaces Apr 1988 Drawing 04-C-038 Annual update of reclamation cost estimate infolloust be received by 891030.

 HAWKINS,E.F. Userum Recovery Field Ofc, R4 88/11/16 SCOTT,E. Bear Creek Uranium Co. 2pp. 47718-314-47718-315.
- 8812210388 Discusses rept. "Evaluation of Landscape Stablity Based on Geomorphology,Sor's & Vegetation Indicators." Dept agrees w/rept findings that undisturbed study area landscape shows evidence of long term stablity BELDEN,S. Wyommog, State of 88/11/23 JACOBY,O. Uranium Recovery Field Olc, R4 8pp. 47875 263-47875 270
- 8812210354 Forwards licensee annual talling water mgt sys reptiper Condition 48 F.W/o and. CHASE,G Bear Creek Uranium Co. 88/11/29, JACOBY,D L. Uranium Recovery Field Ofc, R4, 1p. 47890 119-47890.119.
- 8812210150 Provides roview of 881109 annual land use survey for Bear Creek U Milland use unchanged No I consing action required JACOBY, D.L., HAWKINS E.F., Uranium Recovery Field Otc, R4, 2pp. 47875,327-47875,328

DOCKET 40-8502 MALAPAI RESOURCES CO., PHOENIX, AZ

- 8812060161 Application for amend to License SUA-1341,including process changes to Christenson Ranch & Ingaray facilities & submittal of we'ffield data package for continuation of immung in E-field Fee paid Wiche oversite figure. WICHERS,D.L. Malapsi Resources Co. 88/10/31. KONWINSKI,G.R. Uranum Recovery Field Ofc, R4. 45pp. 47758.004-47758.155
- -8812660167 "Engineering Design Rept for Filter Backwesh Pond at Christenson Rench ISL Mine" W/2 oversize plan sheats. "Western Weter Consultants, Inc. 88/09/26 16pp 47758.045 47758.060
- -8812060174 "E Field We'lfield Data Package" * Ma'apai Resources Co. 88/10/31, 67pp. 47758.061-47758.127
- --8812060194 "USMT/517 Mine Plan"
- Malapai Resources Co. 88/10/31, 7pp. 47758;128-47758:139
- -8812060197 Std Operating Procedure HP-20, "Respiratory Protection Program." BROWN,KJ Marapat Resources Co. 88/10/28, 8pp. 47758:140-47758;147. -8812060198 Std Operating Procedure HP-21, "Procedures for Respiratory Equipment
- BROWN,K. Malapai Resources Co. 88/10/28 Spp. 47758:148-47758.152
- 8812060201 Std Operating Procedure HP-22, "Procedures for Cleaning Disinfection Decontamination & Storage of Respirators." BROWN,K J. Malapai Resources Co. 88/10/28, 3pp. 47758.153-47758:155 -8812060201
- 8812050136 Ack receipt of 880415 response to 880331 request for clarification re-re-stricted area boundaries at Ingarey Mine Areas specifically designated as restricted identified in enclioversize Maps 1 & 2, WICHERS,
- 8810100204 Reviews semiannual effluent monitoring rept including environ & operational monitoring data No significant changes or trends identified No further action required wire the control of the contr
- 8812050005 Forwards proposed changes to Christensen Ranch amend application & Id-garay Mine permit application documents for Land Quality Divirewew & approval WICHERS.D.L. Malapat Resources Co. 88/11/07. GIURGEVICH,8. Wyoming, State of, 2pp. 47787;193-47767;198
- 8812050002 Submits Info required by CP 88-218 ra installation of 400 injection/production wells at Christensen Ranch Amend Area prior to Issuance of final amend to permit to Mine 478. Integrity testing summary encl WICHERS.D L. Marapa Resources Co. 88/11/10. LUCHT,B. Wycm.ng, State of, 19pp. 47732:080-47732.097.
- 8812210062 Responds to NRC 881024 für te violations noted in Insp Rept 40 8502/88. O1. Corrective actions for Nnc as 1024 in the violations noted in Insp Rept 40,8502/88.

 O1. Corrective actions Procedure 15 removed from 810 operating procedures book & Procedure 18 addresses amended monitoring location & decrease in sampling.

 DYAS, K. E. Malapai Resources Co. 88/11/21. HAWKINS, E.F. Uzan'um Recovery Field O1c, R4. Spp. 47881-021-47881-025.

DOCKET 40-8681 UMETCO MINERALS CORP., GRAND JUNCTION, CO

- 8812210250 Discusses logic behind licensee conclusion that leak from tailings impound-812/10/20 Discosses rogs, person incenses conclusion trait real from its lings impound-ments do not exist despite fund quarter monitor well analyses on 881114 Elevated levels of arsente present in every well in aquifer not Indicative of leakage HAMRICK, S. UMETCO Minerals Corp (abos of Union Carbide Corp.), 88/11/14. PETTENGILL, H.J. Uranaum Recovery Field Otc, R4, 21pp 47881.081, 47881.081.
- 8812210287 Forwards Energy Fuels Nuclear, Inc 610413 ftr re tailings excavation & design per request.

 HAMRICK,J.S. UMETCO Minerals Corp. (subs. of Union Carbide Corp.), 88/11/29.

 SCOVILL,V.R. Uranium Recovery Field Otc, R4, 7pp. 47881:304-47881:310.
- 8812220142 Discusses Umetco groundwater monitoring rept for Third Quarter 1988 dtd 881114. No unusual trends or significant variations noted in sampling data for period 8 Umetco White Mesa has compiled witcerise requirements OLSEN,T.T., HAWKINSE F. Uranium Recovery Field Otc, R4, 88/12/13. Uranium Recovery Field Otc, R4, 2pp. 47901 287-47901 298

- 8812060210 Application for amend to Liconsa SUA-1337,forwarding "Final Right Aguler Resicration Efforts & Results Willow Creek R&D," & results of one-year stability more toning pariod. Requests mod of License SUA-1337. WICHERS.D.L. Malepai Resources Co. 88/10/31. KONWINSKI.G.R. Uranium Receivery Field Ofc, R4. 1p. 47743-182-47743-323.
- -8812060212 Final Rept Aquifer Restoration Efforts & Results Willow Crock R&D W/
- one oversize figure
 * Ma'apai Resources Co. 88/10/28, 141pp, 47743-183-47743-323
- 8811280037 "Discharge Monitoring Rept for Third Quarter 1988." W/881103 ftr. WICHERS,D.L. Malapai Resources Co. 88/09/30 WAGNER,J Wyoming, State of 3pp 47651 302-47651:304
- 8812210359 Recommends that Amend 12 to License SUA-1037 be approved, ingle mening 861015 restoration & decormissioning plan subj to Islad conditions.
 KONWINSKI,G R., HAWKINS,E.F. Uranium Recovery Field Otc, R4 88/12/07. Uranium Recovery Field Otc, R4. 7pp. 47875 076-47875 082
- 8812210361 Forwards Amend 12 to License SUA-1337.Recommends that vendor oursue termination of license SMITH,RID. Uranium Recovery Field Ofc, R4, 88/12/08, Matapai Resources Co, 45p 47874 338 47874 356
- -9812210362 Amend 12 to License SUA-1937 for Melepai Resources Co., detcing Amend 11 re implementation of 861015 restoration & decorromissioning plan SMITH,RID Uranium Recovery Field Olc, R4 88/12/08, 11pp 47874-342-47074-356

DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH

8812210279 Forwards annual rept for Co'lins Draw Project for period 870939-880901,per R&D License 3RD AHQ.6.D. Cleveland Clifs, Inc. 88709702, GIURGEVICH,B. Wyoming, Stato of, 3357-47880 227-47880 264

DOCKET 40-8724 CHEMETRON CORP., CHICAGO, IL.

- 8812210234 Forwards Chemetron "Remediation Work Plan" & ORAU confirmatory radiological survey of Harvard Ava property in Newburgh halghts, OH. LAROCHE, G. Puel Cycle Salety Branch 88/12/12, DRIESBACH, K. Ohio, Stato of tp 47876.043-47876.043.
- 8812210344 Requests extension of decontamination completion date & withdraws 881115 confirmation of commitment Requests that NRC refrain from criting Chumolinn for any strength on the United States SUB-1357.
 WILNER, SM. Chemetron Corp. 88/12/12, ROUSE, L.C. Fuel Cycle Safety British Epp 47880 211-47880 218
- 8812210113 Responds to comments on evaluation of remedial work plan for Harvard Avenue See, Newburgh Heights, Ovt. WILNER, SM. Chemeteron Corp. 88/12/13. ROUSE, L.C. Fuel Cycle Safety Branch-7pp. 47875-117-47875-122.

DOCKET 40-8768 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

- 8812210241 Notices that max allowable concentration limits for intrate & arrimona at Surface Water Runoff Outle'ts 004 & 008 exceeded on 881111. Caused by leaching of ammonum nitrale solution from Pond 2

 KNIGHT S.P. Sequoyah Fue's Corp. Isubs of Korr-McGee Nucloar Corp.) 89/11/14

 BLACHLEY,T. Oklahoma, State of 1p. 47878:195-47876.195.
- 8812210239 Notifies that max allowable concentration limit for nitrates & emavionia at surface water funciff outfall 008(OWH8 005) exdeeded.Exceedances will be aliminated & submitted in quarterly self monitoring rept.

 KNIGHT,S.P. Sequeyah Fuels Corp. (subs. of Kerr-McGoe Nuclear Corp.). 89/11/17.

 BLACHLEY,T. Oklahoma, State of . 1p. 47880 265-47880 265.
- 8912210069 Nothies that nitrate max allowable concentration limit at surface water anoff Outail SFC 005 exceeded on 8B1118 & Outail SFC 008 on 8B1119. Caused by leaching from old clay liner plate & leaching of ammonium nitrate solution.

 KNIGHT, S.P. Sequeyeh Fuels Corp. (subs of Korr-McGee Nuclear Corp.) 8B/11/22
 BLACHLEY,T. Oklahoma, State of. 1p. 47892 004-47882 004.

DOCKET 40-8778 MOLYCORP, INC., LOS ANGELES, CA

- 8811300275 Forwards response to 881117 telcon re results of radiation auryoy of tost
- 8812140009 Requests proposal detailing procedures to be used for decontamination of Samarium Process Bidg at Washington PA site including waste disposal. ROUSE, L.C. Fuel Cycle Safety Branch. 88/12/07. DAWES,G.W. Molycorp, Inc. (subsoft Union Oil of California) 1p. 47799/266-47799.266.

DOCKET 40-8786 URANIUM RESOURCES, INC., RICHARDSON, TX

8811280050 Forwards survey grid for plant & wellfield area.indicating where provious gamma measurements made & sampling needed into provided in response to 860830 comment on closure plan for North Patita project.
PELIZZA,M S. Uranium Resources, Inc. 88/10/18. PETTENGILL,H.J. Uranium Rucovery Field Otc, R4, 4pp. 47654:148-47654:151.

DOCKET 40-8801 WESTLAKE LANDFILL, NORTHBROOK, IL

- 8811290578 Forwards survey of uncontrolled hazardous waste sites at Bridgeton location.ppr request Widne oversize drawing. WHITAKER,WE Rock Road Industries, to 88/11/09. SWIFT,J NRC No Detailed Affiliation Given 3pp 47705-021-47705-023
- 8812150082 Forwards Rev 1 to NUREG-1308, "Summary Rept on Radioactive Mattin West Lake Landiti," per 801206 request.W/o encl LAROCHE.G. Fuel Cycle Safety Branch 88/12/12 BURNS.M.E. Association of American Ratioans 1p 47826

DOCKET 40-8829 FERRET EXPLORATION CO. OF NEBRASKA, INC., CRAWFORD,

- 881205000B Responds to 881101 inquiry re-constituent J. Perrott Itr opposing examption to Forret Exploration Co of Nebraska based on better that exemption would result in pollution of Chadron Aquitor.

 KAY,M. Environmental Protection Agency 88/11/09. SMITH,V. House of Rep. 6pp.
 - 47740:157-47740.162
- 8812050001 Forwards Itr of credit from Norwest Bank & Itr from State of NE,Dept of Environ Control establishing standily litr of credit Change necessitated to comply w/ State of NE revised rules & change in underwilling security bands COLLINGS 97 Ferret Explication Company of Nebraska, Inc. 66/11/11. KONWINSKI,G Uranium Rocovery Field Olc. R4. 6pp. 47723:220-47723
- 8812210252 Forwards State of NB dept of environ control 881128 ftr approving ftr of crodil from Norwest bank for financial assurance for UIC permit for Crow Butte
- project COLUNGS.S.P. Ferret Exploration Company of Netwaska, Inc. KONWINSKI,G Uranium Recovery Fin³d Ofc, R4, 2pp. 47876-016-47876-017 88/11/26
- 8812220252 Forwards Amend 18 to License SUA-1441, rovising License Conditions 10,22 & 36 re authorized use, vol of discharges to evaporation pends & performance of monthly surveys for altiborne natural U in restricted area, respectively.

 SMITH, P. Uranium Recovery Fluid Oic, R4, R8/12/12 Ferrot Exploration Company of Nobraska, Inc. 3pp. 47886,329-47886,345.
- --8812220253 Amond 18 to License SUA-1441 for Ferrot Exploration Co of Nebraska,Inc.rovising listed license conditions re OA program to ensure radiological monitoring & groundwater & surface sampling will rotatin current high quality. SMITH,AID. Uranium Recovery Find Otc, R4. 88/12/12. 9pp. 47888:332-47888-345

DOCKET 40-8857 EVEREST MINERALS CORP., CONVERSE COUNTY, WY

- 8811280065 Forwards supplemental info re Section 14-50 sand mine unit hydrology test proposal Test will be started whom one aquifor & overlying & underlying monitor well water levels stable.

 MORZENTI,S.P. Everest Minerals Corp. 88/10/13. OLSEN,T. Uranium Recovery Field
 - Olc, R4. 12pp. 47656.001-47656 012.
- 8811230021 Comments on Everost Minurals 881043 submitted of pump test proposed for Section 14 proposed amond area No proposed pumping rate for pump test specified Storativity has not been prospected this E.S. Wyoming, State of 88/10/20, Wyoming, State of 2pp. 47697 249-
- 8812060003 Application for amond to License SUA-1511,transferring Exxon Coal & Min-orals Co facilities under License SUA-1064, to Everest Minorals Corp. Fee paid, MAYS,W.M. Everest Minorals Corp. 48/10/20, Uranium Recovery Field Old, R4. 1p. 47741.066 47741.066
- 8812050133 Forwards application for amond to License SUA-1084, terminating license Facilities covered by sub) license transferred to Everest Minerals Corp w/License SUA-1511. Request for amond to License SUA-1511 also enci. PATTON,J.D. Exxon Corp. 88/10/31. PETTENGILL,N.J. Uranium Recovery Field Otc, R4. 1p. 47733:312-47733:346
- -8812050136 Application for amond to License SUA-1511, authorizing transfer of facilities covered under License SUA-1064 to License SUA-1511. Fee paid.
 MAYS, W.M. Eyerest Minerals Corp. 88/10/20. Uranium Recovery Field Ofc, R4. 35pp.
- 47733:314-47733:346.
- 8812020128 Forwards listed geological data to support Section 14 of 881003 request for amend to License SUA-1511 & replacement location map showing proposed amend area including 251 wide wastewater pipeline corridor.W/seven oversize encls. MAYS.W. Everest Minerals Corp 88/11/09 OLSEN.T. Uranium Recovery Field Ofe, R4. 12pp. 47722.211-47722.218.
- 8812050017 Discussos violations noted in 880727 8 1003 notices of violation from insp of License SUA-1511.Notifies that Amend 10 to SUA-1511 re erroneous monitoring well data rescrided Response requested. MARTIN,R.D. Region 4, Otc of this Director. 88/11/14. MAYS,W. Everest Minerals Corp. 2pp. 47732 044-47732 045.
- 8812020122 Forwards Amond 11 to Licensa SUA-1511, revising License Condition 39 to rollect licensee 880919 erioquate submitted of hydrologic testing proposal. SMITH.R.D. Uranium Recovery Field Otc, R4. 68/11/16. Everest Minerals Corp. 2pp. 4721-4721 47717:073-47717:105.
- ~8812020124 Amend 11 to License SUA-1511 for Everest Minorels Corp., revising Condition 39 to reflect licensee 880919 adequate hydrologic testing proposal. SMITH,R.D. Region 4, Ofc of the Director, 88/11/16, 10pp. 47717:075-47717:102.
- ~8812020131 Recommends that Liconse SUA-1511 incorporate hydrologic test proposal submilled by Leensee 880029 fit by revising Condition 39 as stated OLSEN,T.T., HAWKINS,E.F. Uranium Recovery Field Ofc, R4, 88711/10, Uranium Recovery Field Ofc, R4, 3pp. 47717:103-47717:105.
- 8812210052 Forwards U,radium & therium analysis data for soil samples collected from proposed Section 14 of amond area Ouistanding Items include/results of hydrologic test performed in northern helf of Section 14. HILDENBRAND, P. Everest Minerals Corp. 88/11/18. OLSEN,T.T. Uranium Recovery Field Ofc, R4. 12pp. 47882-012-47882-023.

- 8812210149 Responds to inquiry re-waste water propine proposed to bo built as part of Saction 14 amand Water will be piped to first sate/life in Section 21 & will consist or wallfield progress. workover fluid & restoration fluid MAYS,W.M. Everest Mineral's Corp. 88/11/23. OLSEN,T.T. Uranium Recovery Field Otc, R4. 1p. 47888:109-47888.109
- 8812210098 Forwards Amond 12 to Liconso SUA-1511,revising Conditions 38,40 & 41 & adding Condition 49,approving baseline water quality for mining units as noted 8 spacetying lividant injection approval requirements SMITH,RD Urahium Recovery Field Olc., R4, 88/12/01. Everest Minerals Corp. 4pp 47889-054-47889-092
- -8812210104 Amend 12 to License SUA-1511 for Everest Minerals Corp. amending Li-cense Conditions 38.40 & 41 & adding License Condition 49 re-baseline water quality
 - & lixiviant intection. SMITH,R D. Region 4, Old of the Director 88712701 13pp 47889 058-47889.086
- -8812210108 Recommends amend of Liconse SUA-1511 by revising Ucense Conditions 28,40 & 41 & adding Liconse Condition 49 re-baseline water quality & Ixiviant infection OLSENT.T., HAWKINS E.F. Uranium Rocovery Field Otc. R4, 88/11/30. Uranium Rocovery Field Otc. R4, 6pp. 47889.087-47889.092
- 8812210156 Provides addl info re Section 14 of amend request for Satellite 2.per 881204 felcon Wastewater stream generated at Satellite 2 wtb.ccnsist of wellheld purgo,well workover fluid & eventually restoration fluid MAYS,W Everest Minorals Corp. 88712/09 OLSEN,T.T. Uranium Recovery Field Ofc, R4 2pp. 47881/347-47881/348.
- 8812210228 Recommends that Source Motif License SUA-1511 be amended by revising License Condition 39 re-equilor test data ner vendor 881123 amond request Aquilor testing proposal should be submitted 4 months before hair an injection.

 OLSEN.T. HAWKINS.E Furanum Recovery Field Ofc, R4-88/12/13. Uranum Recovery Field Ofc, R4-8pp. 47876-157-47876-151
- 8812210223 Forwards Amend 13 to Liconse SUA-1511 for Everest Minorals Corp Amend covers submittal of hydrologic test data per License Condition 39 SMITH,R D. Urantum Recovery Field Ofc, R4 88/12/14 Everest Minera's Corp. 2pp. 47876 162-47876 192
- --8812210224 Amend 13 to Licenso SUA-1511 for Everest Minerals Corp., revising Licenso Condition 39 to require performance & documentation of aquiter pump tost including collection of hydrologic data & analytical procedures. SMITH.R.O. Uranium Recovery Field Otc., R4. 88712714, 13pp. 47876:164-47876.192.

DOCKET 40-8902 ANACONDA MINERALS CO., GRANTS, NM

- 8812020174 Forwards "Mod of Anaconda Bluewater U Mill Reclamation Plan Malpais Area." Documentation of potential future radiation health risks of excluding major por-tions of Malpais area from remodellon provided BERGST
- -8812020189 "Mod of Anaconda B'uewater U Mill Raclamaticn Plan Malpais Area." BAKER,K., LONGLEY,J., SCHMIDT,D. Woston (Roy F. Waston, Inc.): 88/11/30 84pp 47717:119-47717:193.
- 8812210071 Discussos NRC review of licenses 880630 rept reliand use survey to Bluowater Mill Licenses performed acceptable land use survey. No further action nec
- GARCIA, J., PETTENGILL, H.J. Uranium Rocovery Floid Old, R4, 88/12/01. Uranium Recovery Floid Old, R4, 88/12/01. Uranium Recovery Floid Old, R4, 88/12/01.
- 8812210230 Discusses environ monitoring rept for Bluewater Mrt for Jan-June 1988.No stack sampling conducted since mill did not operate during reporting period & will be decommissioned the areas of concern hoted GARCIA,PJ., PETTENGILL,IJ. Uranium Recovery Field Otc, R4. 88/12/02. Uranium Recovery Field Otc, R4. 3pp. 47875 248-47875.250.
- 8812210165 Advises that R Ziegler will replace P Bergstrom as project manager, effective immediately. KRABLINR, Altentic Richield Co. (ARCO). 88/12/05. PETTENGILL, H.J., Uranium Recovery Field Otc, R4. 1p. 47901:133-47901:133.

DOCKET 40-8903 HOMESTAKE MINING CO., GRANTS, NM

- 8811230299 Forwards Amend 3 to License SUA-1417, adding Condition 35 re implementation of groundwater detection monitoring program, per 860602 request. SMITH,R.D. Utanium Recovery Field Otc., R4, 88/11/09, Homestake Mining Co. 2pp 47657:282 47657:209
- --8811230301 Amend 3 to Licenso SUA-1471 for Homastake Mining Co, authorizing possession of unlimited quantity of U. SMITH,R.D. Uranium Recovery Field Otc, R4. 88/11/09. 6pp 47657:284-47657:299
- 8812020101 Discusses insplot License SUA-1471 on 881101-03 Extends appreciation to A Datta for participation in insp. SMITH, R.D. Region 4, Old of the Director, 88/11/28, ROUSE, L.C. Fuel Cycle Safety Branch, 2pp. 4771:358-47711:359.
- 8812020108 Extends approciation to A Grella for participation in 861101-03 insp 8 881031 training session. SMITH.R.D. Region 4, Ofc of the Director. 88/11/28 BURNETT.R.F. Division of Sale guards 8 Transportation (Post 870413). 2pp. 47707:154-47707:155.
- 8812210235 Discusses environ monitoring rept for MJan Milt for Jan-June 1988 No ereas of concern noted in staff review of data & no further action necessary. GARCIA-PJ, PETTENGILL, HJ Uranium Recovery Field Ofc, R4. 88/12/01. Uranium Recovery Field Ofc, R4. 4pp. 47881:268-47881:271.

8812210374 Oscusses windb'own cleenup at Mr'en Milbased on 980531 8 0916 submittals Licensee soil cleenup & documentation acceptable,per License Condition 18.Future cleanup efforts will be based on testifs of annual sampling & survey. GARCIAP J. PETTENGILL, HJ. Utranium Recovery Field Otc, R4. 68/12/01. Utranium Recovery Field Otc, R4. 4pp. 47875.259-47875.262.

DOCKET 40-8904 BP AMERICA, INC./L-BAR URANIUM FACILITY, SALT LAKE

8812020192 "Semiannual Environ Montoring Rept L-Bar U Mine,Clob'a County,NM " W/ one oversize drawing & 880829 ltr. OSBORN,T.G. INTERA Technologies, Inc. 88/08/30, 331pp 47721 098-47722 068

- 8812210255 Advises that licensed will meet w/NRC on 881117 in Denver CO to resolve outstanding Issues in L.Bar closure plan OSBORN,T.G. INTERA Technologies, Inc. 88/11/08. GRACE,S. Uranium Recovery Field Otc, R4. 2pp. 47875;359-47875;360.
- 8812210153 Provides update on current status of BP America Libar U talings facility groundwater discharge plan DP 150 Several remaining technical concerns listed that need to be addressed before State of MM can grent renewal to plan LEWISG. New Mexico, State of 88/11/17, LAGRAFF, M.B. BP America, Inc. 5pp. 47889 293-47889:297.
- 8812010385 Forwards general agreements from 681117 meeting resolving outstanding surface water hydrology/erosion protection Issues on LiBar Mill site reclamation plan. Responses should be submitted by 881216. HAWKINS,EF, Urentum Recovery Fletd Otc, R4, 88/11/18, DELEONARDIS,R. BP America, Inc. 3pp. 47703:080-47703:092.
- 8812010398 Forwards 880829 & 0921 & 0930 & 1118 correspondence w/British Petro-leum Amorica L-Bar Mill site,per agreement w/Cebolleta Land Grant W/o encls. GRACE,S.R. Uranium Recovery Field Olc, R4. 88/11/18 Cebolleta, NM 2pp 47703.092-47703.093
- 8812210037 Informs that soveral issues re-erosion protection must be resolved before License SUA-1472 can be amended to allow completion of reclamation of LiBar tailings pile Final reclamation plan & financial surely info
- 8812210377 Informs that apparent fault noted on north side of volcan'c intrusion approx 6,000 ft north of tallings pond during 881129 site visit should be addressed prior to approval of reclamation plan HAWKINSE F. Uranium Recovery Field Ofc. R4, 88/12/09 DELEONARDISIR BP America, Inc. 2pp. 47881:272-47881:273.
- 8812220282 Forwards Amend 9 to License SUA-1472, detering License Condition 30 to require that corrective action program be directed at remediation of hazardous constituents as well as other clovated parameters. SMITHR D. Urgatium Recovery Field Ofic, R4, 88/12/12. DELEONARDIS,R. BP America, Inc. 3pp. 47900.324-47900.341.
- -8812220283 Amend 9 to License SUA-1472 for 8P America, inc. requiring that corrective action program be directed at remediation of hazardous constituents & other elevaled parameters
 SMITH,R D. Uranium Recovery Field Otc, R4, 88/12/12, 7pp. 47900 327-47900.341.
- 8812220290 Discusses Amend 8 to SUA-1472 re establishment of groundwater protection stds being exceeded for tion stds Groundwater protection stds being exceeded for antimony,nickel, selanium,U.combined Ra-226 & Ra-228,Th-230 & cyanide at several

GRACE,S.R., HAWKINS,E.F. Uranium Recovery Field Qfc, R4. 88/12/12. Uranium Recovery Field Qfc, R4, 8pp. 47901:117-47901:124.

DOCKET 40-8905 KERR-MCGEE CORP./QUIVIRA MINING CO., OKLAHOMA CITY,

- 8812200383 Submits results from sampled locations in Evaporation Pond 8, showing depth of 12 to 18 inches & below regulatory limit of 15 pC//gram for so is below 15
- CLEVELAND.J.E. Clurvira Mining Co. 88/10/18. GARCIA.P. Uranium Recovery Field Otc, R4. 2pp. 47870:335-47870:336.
- 8812050019 Confirms telcon re extension of License Condition 34 Paragraph C to 881202 Informs that deadline for submittal of monitoring data & proposed concentration limits for detection monitoring plan will be extended 881104-1202 FERDINAND, B Quivira Mining Co. 88/11/03. ROSE, H. Uranium Recovery Field Ofc, R4. 1p. 47733:298-47733:298.
- 8812020106 Confirms conversation between B Ferdinand & HiRosaira extension of the censes compliance monitoring submittal required by Amend 9 to License SUA:1473 HAWKINS,E.F. Uranium Recovery Field Ofc, R4, 88/11/15. STAUTER,J. Quivira Mining Co. 2pp. 47711;356-47711;357.
- 8812210170 Discusses review of environ monitoring rept for Jan-June 1988 for Ambrosia Lake M.II submitted by licensee in 880831 ltr. Ucensee conducted environ monitoring program in accordance w/license requirements. GARCIA, P.J., SMITH, R.D. Uranium Recovery Field Ofc, R4. 88/12/07. Uranium Recovery Field Ofc, R4. 490. 47880:155-47880:158.
- 8812220114 Submits technical evaluation of embankment performance at Ambrosia Lake Milt No areas of concern noted No further action necessary at present. GARCIA,P.J., SMITH,R.D. Usenium Recovery Field Ofc, R4. 88/12/12. Uren.um Re-covery Field Ofc, R4. 3pp. 47900:177-47900:179.
- 8812210383 Reviews 880807 request to amend License SUA-1473 for Ambrosia Lake Millauthonizing receipt of contaminated mail. Analysis of ratiological & chamical composition of sludge & processus, to store & process studge requested SMITH.R.D. Uranium.

 Millauthonizing receipt of contaminated mail. Analysis of ratiological & chamical composition of sludge & processisted SMITH.R.D. Uranium.

 Mining Co. 4pp. 4787

DOCKET 40-8907 UNITED NUCLEAR CORP., SANTA FE, NM

8812050023 Confirms understanding of G Konwinski recent instructions re spray evapt ration sys operation beyond mid-Oct so long as weather conductive to evaporation advises of I censee compliance w/subj instructions
VELASCUEZ.J.R. United Nuclear Corp. (subs. of UNC Resources, Inc.). 88/11/02 SMITH,D. Uranium Recovery Field Ofc, R4. 1p. 47733-310,47733-310.

- 8812050073 Requests that EPA be notified in writing by 881107 of interest in participal ing in future negotiations & attending 881110 triesting re-control of release of hazard ous substances,politicants & contaminants at site DAVIS,AM Environmental Protection Agency 88/11/02 JOHNSON,C G. United Nu-clear Corp. (subs. of UNC Resources, Inc.). 3pp. 47731-224-47731-226
- 8812050096 Forwards 881111 lincorrecting 881102 ftr re-instructions to operate spraevaporation sys beyond mid Det as license recurres VELASQUEZJR United Nuclear Corp. (subs. of UNC Resources, Inc.) 88/11/08 SMITH.D. Uranium Recovery F.elf Ofc. R4. 1p. 47732 078-47732 079.
- -8812050097 Confirms instructions to operate spray evaporation sys beyond license re quirements of mid Oct, if wealther roma has conducive to ovaporation VELASCUEZ JR United Nuclear Corp. (subs. of UNC Resources, Inc.) 88/11/11 Uranium Recovery Field Otc, 14. 1p. 47732 079-47732 079.
- 8812050020 Forwards corrected Page 4 to License SUA-1475,por Condition 30 rept revalues of naphihaleng & chloroform submitted on 881001.

 VELASQUEZ, J.R. United Nuclear Corp. (subs. of UNC Flosources, Inc.). 88/11/09, KONWINSKI, G. Urantum Recovery Field Ofc, R4. 4pp. 47732.046-47732.049.
- 8812050027 Requests notification in writing re-possible interest in participating in future negotations concerning spending of public funds to control releases,per Comprehensive Environ Response, Compensation & Liab lify Act of 1980.
 DAVIS.AM Environmental Protection Agency 88/11/09 COLUSSY,D.A. United Nuclear Corp. (subs. of UNC Resources, Inc.). 3pp. 47740-169-47740-171.
- 8812020235 Ack receipt of 881102 ltr re operation spray evaporation sys designed to discharge max amount of contaminated solution to atmosphere w/o recharging tail. ings HÄWKINS,E F. Urantum Recovery Field Olc, R4 88/11/17 United Nucloar Corp (subs. of UNC Resources, Inc.) 2pp 47718.037-47718:038.
- 8612210270 Summanzes 661110 meeting in Dal'as,TX & outlines components of good (aith offer for remed at design/remed at act on at UNC Superfund site WRIGHT,L. Environmental Protection Agency, 88/11/23, VELAS-OUE2,J R United Nuclear Corp (subs of UNC Resources, Inc.) 3pp. 47875:137-47875 130.
- 8812210242 Discusses licensee 881024 written procedures for control of blowing tailings Procedures adequate for control & remudiation of blowing tailings Recommends that I coasse implementation be reviewed during next tags. SCOVILLY R. PETTENGILL, H.J. Uranium Recovery Field Ofc, R4. 3pp. 47877 068-47877 070
- 8812220108 Discusses review of environ monitoring rept for Church Rock Mill for First Half 1988. Licensee performed sampling & analysis in accordance withcense require-GARCIA,P.J., SMITH,R.D. Uranium Recovery Field Ofc, R4, 88/12/13. Uranium Ro-covery Field Ofc, R4, 3pp. 47686 346-47896 34B.

DOCKET 40-8911 MOBIL ALTERNATIVE ENERGY, INC., BOULDER, CO.

- 8812050180 Application for amend, terminating License SUA-1478. Contribate of dispositon of matts enci. Fee paid CULLEN.J.F. Mobil Coal Producing, fre. 88/11/09. OLSEN, F. Uranium Rucovery Floid Ofc, R4. 1p. 47720.210-47720.231.
- ~8812050184 Cert.ficate of disposition of mails all mails procured or possossed under ucense SUA-1479 transferred to Umotco White Mesa MillLaSalte,UT.

 CULLEN,J F. Mobil Coal Producing, Inc. 08/11/04, 20pp. 47720.211-47720:230.
- -8812050186 Application for amend,terminating License SUA-1479. Rectamation completed on 880923. CULLEN,J.F. Mobil Coal Producing, Inc. 88/09/23, 1p. 47720 231-47720 231.
- 8812210186 Concludes that size decormissioned & deconteminated in accordance w/ license requirements.Requests Mobil pursue I conse turmination & related radiological surveys for crownpoint site.

 KONWINSKI,G.R., HAWKINS,E.F. Uranium Recovery Field Oic, H4. 88/12/07, Uranium Recovery Field Oic, R4. 3pp. 47888 265-47888 267.
- 8812210158 Informs that License SUA-1479 terminated offoctive 881208, per 880923 request. SMITH,R.D. Uranium Recovery Fie'd Otc, R4 88/12/08 Mobil Alternative Energy, Inc. 2pp. 47868.268-47868.269

DOCKET 40-8920 BROOKHAVEN MEDICAL IMAGING ASSOCIATES, BROOKHAVEN, PA

8812220298 Discusses review of Allair Resources suminantial root & equipment release results Rept. covers restoration & decommissioning work parformed at Bison Basin site Site in satisfactory condition. KONWINSKI, G.R., HAWKINS, E.F. Urentum Recovery Field Otc, R4, 88/12/09, Uranium Recovery Field Ofc, R4, 3pp. 47894-353-47894:355.

DOCKET 40-8926 ALTAIR RESOURCES, INC., CASPER, WY

8812210106 "Fourth Semiannual Rept Apr-Oct 1998 for Bison Basin Decommissioning Project in Situ Leach U Mine "W/881111 ltr. CATCHPOLE.G.J. Alta'r Resources, Inc. 68/10/31. KONWINSKI,G. Uranium Recovery Field Otc, R4, 250pp. 47878 186-47880.113

DOCKETED HEMS

- 8812220254 Forwards Amend 3 to License SUA-1492, revising Irsted License conditions based on site decommissioning Mods to License Conditions 6.7 & 8 prohibit vendor from processing source mall SMITH ROSOUTCH Alleir Resources, Inc. 3pp 47886.349.4786.639.4786.639.
- ~8812220255 Amend 3 to License SUA-1492 for Alleir Resources,inc, deleting listed ti-SMITH,R D. Urenium Recovery Field Ofc, R4 - 88/12/12 - 5pp - 47886-352-47886:361.

DOCKET 40-8943 FERRET EXPLORATION CO. OF NEBRASKA, DENVER, CO.

- 8812010389 Forwards draft finding of no significant impact to major Idensing action for publication to FR Advises comments on draft to be submitted within 30 days of publi-HAWKINS,E.F. Uranium Recovery Field Ofc, R4, 88/11/17, MEYER,D. Office of the Secretary of the Commission, 1p, 47/07:105-47/07:108
- -8812010371 Notice of draft finding of no significant impact relissuance of source matt license to Forret Exploration Co of Nebraske, Inc. HAWKINSE F. Urantum Recovery Field Otc, R4 88/11/17 3pp 47707.108-
- 47707:10B 8812210348 Requests review of oncl draft permit NE0122611 re licensee 871107 appli-
- cation for point for in 5 to min og in Dawes County, Commonts & respenses requested by first wk of January.

 GIOLEY, W.C. Nebraska, State of 88/11/30 KONWINSKI,G. Uranium Recovery Field Olc, R4, 37pp. 47881:231-47881:267.
- 8812210105 Forwards draft environ assessment to issuance of source mail I conse to Ferrot Exploration Co of Netraska, Inc. Commants will be received until 890101. HAWKINS.E.F. Region 4, Otto of the Director, 18612-97. COLLINGS,S. Ferrot Exploration Company of Netraska, Inc. 66pp. 47878 220-47878 287.
- 8812220106 Submits comments on draft pormit submitted 891130 Although State of NE 19quires submitted of monitoring & production repts on quarterly basis,NRC requires submitted of repts on sentlanual basis,based on minerous license requirements HAWKINS,E.F. Uranium Recovery Field Ofc, R4, 88712713, GRIDLEY,W.C. Notinska, State of, 3pp. 47892.098-47892 100

DOCKET 40-8958 URANERZ USA, INC., CASPER, WY

- 8811300379 Forwards application for SNM Econso for commorcial scale Ruth ISL project in Johnson, County, WY. Project will be satellite in situ. U mine producing 300,000 les yelloweaks each yf. Fee paid CATCHPOLE, G.J. Uranez USA, Inc. 18710/03 HAWKINS, E.F. Uranium Recovery Field Olc, R4. 1p. 47705 037-47707:092
- -8811300381 Application for license,authorizing possession & uninstricted use of sodium uranyl tricarbonato in in situ U mino producing about 300,000 bs yellowcake
- each yr. CATCHPOLE,G J. Uranorz USA, Inc. 88/10/05, 2µp 47705 038-47705,040
- 8811300386 Vol i to "Supportive Into for Wyoming DEO Permit to Mine Application & NRC Source Mail License Application." W/33 oversize figures
 Urenerz USA, Inc. 88/10/31, 400pp. 47705 041-47706 217.
- -8811300388 Vol III to "Ruth ISL Project Groundwater Suppl."
 * Hydro-Engineering 88/08/31, 200pp 47700.218-47707:092.
- 8812200311 Forward4 sampling data & Inb results for use in assessing adequacy of air monitoring program re-placeded application for North Bulta property CATCHPOLE,G.J. Uranez USA, Inc. 88/11/10 HAWKINS,E. Uraneum Recovery Field Olc, R4, 9pp. 4766-276-4786-284.

DOCKET 40-8964 SEQUOYAH FUELS CORP., OKLAHOMA CITY, OK

- 8812050095 Requests start of formal technical review of Sequeyah Fuels Smith Ranch ISL application & to coruplete review by 881220. INGLE,S. Affiliation Not Assigned. 88/11/10. Affiliation Not Assigned. 1p. 47733:311-47733:311.
- 8812050079 Informs that I-consee should commencu w/public notice of application for amend to License SUB-1010.Prollminary technical comments identified during compièleness raview anci. SHAFFER,R. Wyonling, Stato of. 89/11/18, FREEMAN,M. Sequoyah Fuels Corp. (aubs. of Kerr-McGeo Nuclear Corp.) 13pp. 47732:002-47732.014.

DOCKET 40-8968 HYORO RESOURCES, INC., DALLAS, TX

- 8812210159 Advises that listed questions & recommendations must be addressed before 80901 discharge plan can be approved, including summary of public participa-tion & afforts to inform public of operation. LAMBERT,K. New Mexico, State of. 89/12/01. PELIZZA,M.S. Hydro Resources, Inc. 3pp. 4/882.031-47862-033.
- 8812210282 Forwards rept re second pump test at Churchrock Project, indicating that Churchrock Section 8 orebody has all hydrologic properties for environmentally sound
- PELIZZA,M.S. Uranium Recovery Field

DOCKET 40-8971 U.S. ENERGY CORP., RIVERTON, WY

- 8811230254 Fowards Amend 1 to License SUA-1524, authorizing possession of process equipment purchased from Bison Basin facility.per 880900 request SMITH.R.D. Uranium Recovery Field Otc, R4_88/10/31, WEBER,K. U.S. Energy Corp. 4pp. 47657:139-47657.161.
- -8811230258 Amend 1 to Licensa SUA-1524 for US Energy Corp, authorizing possession of equipment purchased from Bison Basin facility. SMITH, FI.D. Uranium Recovery Field Ofc, R4. 88/10/31, Spp. 47657:143-47657:161.

8812210307 Ack receipt of Cartificate of Deposit B7205 Certificate accepted as add bond in Lou of surety bond JORDANP, Wyoming, State of 88/11/29 WERBER,K Affication Not Assigned. 2pp 47875.257-47875.29

DOCKET 40-8973 SOLUTION MINING CORP., LARAMIE, WY

8812210147 Forwards JW Murphy proposed lab program for column leach testing & res-loration of U bearing sands cored from ficensee Southern Powder River Basin Daposifier review.

FARRELL,C.W. Solution Mining Corp. 88/11/15. KONWINSKI,G. Uranium Recovery
Field Orc, R4. 10pp. 47888 221-47888 230

8812210182 Submits comments on column leach testing procedures, transmitted w/ 881115 ft Recommends that during each phase of leach test, at least one Disories or State of Wy Gwdehre 8 analysis be performed HAWKINS,E.F.

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION **FACILITIES**

DOCKET 50-2 FORD NUCLEAR REACTOR

F. Security, medical, emergency & fire protection plans

- 8812050129 Advises that 890725 & 0823 proposed charges to emergency plan maintain comphence w/10CFR50,App E & may be incorporated into current emergency pan pan MicHAELS,T S. Standard zalion & Non-Power Reactor Project Directorate, 88/11/29. KERR,W F. M.chigan, Univ. of, Ann Arbor, Mr. 3pp. 47733 307-47733 309.
- 8812200102 Rev 1 to Ford Nuclear Reactor emergency plan * Michigan, Univ. of, Ann Arbor, MI 88/12/08, 116pp, 47801:073-47661:188.

P. Operating license stage documents & correspondence

8812120077 Requests approval of alternate routing for shipment of spant TRIGA fuel from Chayanno, WY to Denvor, CO.
WILKINSON, B. W. Michigan State Univ., East Lansing, MI 88/11/04. Office of Nuclear Material Safety & Safeguards, Director 2pp 47780, 216 47780, 217.

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8612130047 Revised emergency plan Implementing procedures Including Rev 5 to IAP-1,Rev 3 to IAP-8,Rev 4 to IAP-10,Rev 4 IAP-13,Rev 2 to IP-1013,Rev 0 to IP-1024 & Rev 3 to IP-1027,W/881207 lin.
 - BRAM,S B. Consolidated Edison Co. of New York, Inc. 88/12/07, 80pp. 47794:160-

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 88:20 to all licensess holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnorabilities Svc liet Unic. CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- Q. Inspection reports, IE Bulletins & correspondence
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear
- Gauges." Svc hist encl.
 CUNNINGHAM.R.E. Division of Industrial & Modical Nuclear Safety (Post 870720).
 68/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257. 8611160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologi-
- cel Tests." Svc hist encl. ROSSI,CE. Division of Operational Events Assessment (Post 870411). 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc list encl. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 670726), 88/12/02. Consolidated Edison Co. of New York, Inc. 112cp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list
 - enci. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Ed.son Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812020287 NRC Into Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svc list encl. ROSSI, CE. Division of Operational Events Assessment (Post 870411) 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.

U. Congressional/Executive Correspondence

- 8811300298 Responds to 881020 ltr re operation of plants following steam generator lask at Indian Point 3 NRC evaluated event & concluded that no immediate safety concerns warrant shutdown of facilities. ZECHL.W. Commissioners. 88/11/23. GILMAN,8.A. House of Rep. 2pp. 47668:313-
- 47669:125.

- 8811300220 Popinists rept on steam generally release incident at Unit 3 & overell string of partitions should be shut down until public safety absolutely assured to the string of the 4766 3 125

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

\$\$12210174 No. 5 to Emergency Plan Implementing Procedure EPIP 200-2, "Class fica-tion & Percenters to Incident Involving Oil or Hazardous Matti (Primary Responsibility-Commitment Edison Co. 88/12/13 16pp 47880 195-47880 210

8412210205 Per 14 to Emergency Plan Implementing Procedure EPIP 300-1, "Initial Particulars & GSEP Responses" (Commonwealth Edison Co. 88/12/13, 23pp. 47876 015-47875 037.

P. Operating Scense stage documents & correspondence

8811220055 Fcrwards Rev. 52 to QA Program Topical Rept CE-1:A,per 881110 request. (I-F. A) - M.J. Commonwea'th Edison Co. 88711717. MULLER,D.R. Project Directorals: 2.10, 4163-063, 47663-068.

8811290231 Provides add/ info relictlidecommissioning plan & Tech Specs per NRC 920327 request tofic provided discussed w/P Enckson of NRC on 881117. With DANIM E. Commonweath Edison Co. 88/11/21. Document Control Branch Control Control Desk). 2pp. 47865-124-47865.125.

8411180048 General Ltr 58:20 to all licensees holding OLs & CPs for nuclear power realiting facilities re-individual plant exam for severe accident vulnerabilities Svc list

erct (NOTCHFEELD O Associate Ovector for Projects (Post 870411) 88/11/23 Consol-dated Edison Co. of New York, Inc. 81pp. 47728 303-47729 924.

O Inspection reports, IE Bulletins & correspondence

8411150211 1/80 into Notice 88-990, "Unauthorized Removal of Industrial Nuclear Sandas Suchst end: Charles Statement Devision of Industral & Medical Nuclear Salety (Post 670729) 64 11/22 Consolidated Edison Coll New York, Inc. 99pp. 47709 255-47708 257.

\$411150467 NRC into Notice 88-991, "Improper Administration & Control of Psychologital Tens Sic est end. Operational Events Assassment (Post 870411): 88/11/22. It is Souther Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.

##11290039 ARC Into Notice 88-993, "Teletherapy Events" Svc hat encl. Const. Notice AR E. Devision of Industrial & Medical Nuclear Safety (Post 870729). ## 12 92 Constituted Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.

8811290538 htRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list

erci R0551 C.E. Drisson of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708.254

8412020287 NFC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Linerisecs on Vendors." Svollist end (1935-10) Prasion of Operational Events Assessment (Post 870411), 88/12/08, Consendated Edison Collo

OCCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

J. Insurance & Indemnity Information

8811290444 Forwards temporary exemption from schedular requirements of property in-auractic rule 10CFRSO 54(M(S)()) in insurance policies that prioritize insurance pro-ceds for stabilization & decontamination after accident ERICKSON PIB Standardization & Non-Power Reactor Project Oirectorate, 88/11/18, CRSER,WIS Detrot Edison Co. 4pp. 47668 020-47668 027.

-8811290449 Temporary exemption from 10CFR50.54(w)(5)(i) re increase in onsite 54.5em; damage insurance required by power reactor licensees & insurance policies that prior braid insurance proceeds for stabilization & decontamination after accident MCLAHANIG M Dinision of Reactor Projects - III,(IV. & Special Projects (Post 873411), 88/11/18 Detroit Edison Co. 4pp. 47668.024-47668.027.

DOCKET 50-18 VALLECITOS BOILING WATER REACTOR

Y. Operator Examinations

\$812140153 Forwards revised agenda for annual operator licensing meeting on 83:110 W/o enci PATE RJ Region 5, Otc of the Director, 88/12/05, CUNNINGHAM,G. General Elec-tric Co. 1p. 47813.351-47813.351.

DOCKET 50-20 MASSACHUSETTS INSTITUTE OF TECHNOLOGY RESEARCH

P Operating Boense stage documents & correspondence

84.17050.134 Forwards "Suppl to PWR Loop SER/Use of Large Circulating Pump," safety evaluation of unreviewed safety question BEANARD J.A. Massachusetts Institute of Technology, Cambridge, MA. 68/11/28. Document Control Branch (Document Control Desk). 9pp. 47740.102-47740.121.

-8812050139 "Suppl to PWR Loop SER Use of Large Circulating Pump"
DRISCOLL.M.J., KOHSE,G.E. Massachusetts Institute of Tachnology, Cambridge, MA
88/10/24, 11pp 47740.111-47740.121

DOCKET 50-27 WASHINGTON STATE UNIV. RESEARCH REACTOR (TRIGA)

V. Querator Examinations

8812140095 Forwards revised agenda for annual operator licensing meeting on piziatuoso Porwards revised agenda for annual operator ilcansing moding on 890110 W/o enci PATE, PJ, Region 5, Ofc of the Director, 88/12/05, Will,SON,W. Washington Univ., St Louis, MO. 1p. 47799 244-47799.244.

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

8812050003 Ray 5 to Emergancy Plan Implementing Procedure OP-3320, "Activation of Technical Support Ctr "
* Yankee Atomic Electric Co. 88/11/30, 12pp, 47731:186-47731:177.

8812080077 Rev 10 to Emergency Plan Implementing Procedure OP-3344, "Security Force Actions Under Emergency Conditions"

* Yankee Atomic Electric Ca. 88/11/30, 29pp. 47754:185-47764:213.

8812090062 Requests that annual exercise be scheduled for 891128 Early confirmation of request will be appreciated PAPANIC,G. Yankes Atomic Electric Co. 88/11/30. Document Control Branch (Occument Control Dosk). 1p. 47762

P. Operating license stage documents & correspondence

8811280092 Notification of 881215 meeting what In Rockville,MD to discuss routing monthly scheduling 8 prioritization FAIRTILE,M Project Directorate I-3, 88/11/21, WESSMAN,H N, Project Directorate I-3, 2pp. 47654.166-47654.167.

8811300109 Forwards modified Tech Spoc 3/4 3/2 inadvertently omitted from util 881021 Proposed Change 222 to Tech Space.
PAPANIC,G. Yankee Atomic Electric Co. 88/11/22, Document Control Branch (Document Control Desk). 1p. 47697:209-47697.210.

-8812080185 Tech Spec Page 3/4 3-2 inadvertonly omitted from util 881021 Proposed Change 222 to Tech Specs.
* Yankee Atomic Electric Co. 88/11/22. 1p. 47697:210-47697:210

8811280048 Generic Litr 88:20 to all liconsees holding OLS & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities. Svc fist CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Canso. dated Edison Co. of New York, Inc. 81pp. 47/28/303-47729.024.

8812060276 Discusses facility review of License Amend 117.Globe design has been selected for use in application due to excellent seeting ability & history of low maint & reliable operation as isolation valvo.

PAPANIC,G. Yankse Atomic Electric Cq. 88/11/29. Document Control Branch (Document Control Desk). 1p. 47741;227.47741;227.

8812120232 Requests that util address Generic Ltr 86-17 to loss of DITR during non power operation.Ltr Issued due to potentiatly serious consequences of inadequiscy of industry response to Generic Ltr 87-12. MURICEY, TE. Office of Nuclear Regulation, Director (Post 870411). 88/12/02. TRISBLE, J.E. Yankee Atomic Electric Co. 2pp. 47780-105-47789.106.

8812130205 Forwards Amend 121 to License DPR-3 8 safety evaluation. Amend changes Tech Space to containment isolation barriers including blank flanges, expansion joine & selves.

FARTILE M.B. Project Directorate 1.3 88/12/07. PAPANIC, G. Yankoo Atomic Electric Co. 5pp. 47798.090-47798: 108.

--8812130251 Amend 121 to License DPR-3 changing Tech Spece re-containment isolation barriers including blank flanges, expansion joints & valvos. WESSMAN,R.H. Project Directorale I.3: 88/12/07. 8pp. 47708:005-47798:102.

--8812130259 Safety evaluation supporting Amond 121 to License DPR-3.
* Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/07. 4pp. 47798:103-47798:104

8812130149 Forwards Amend 122 to Liconse DPR-3 & safety evaluation. Amend modities Tech Spec to accommodate changes in incore delection sys from moveable detectors to fixed detectors.

FAIRTILE,M.B. Project Directorate 1-3. B8/12/08. PAPANIC,G. Yankoo Atomic Electric Co. 6pp. 47797:285.

-8812130158 Amend 122 to License DPR-3, modifying Tech Specs to accommodate changes in incore detection sys from removeable detectors to fixed detectors. WESSMAN,R.H. Project Directorate I-3, 88/12/08, 14pp. 47797:270-47797:283.

-8812130164 Safety evaluation supporting Amend 122 to License DPR-3.
Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/08. 5pp 47797:284-4797:284-

Q. Inspection reports, IE Bulletins & correspondence

8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list enct. CUNN:NOHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/11/22. Consolidated Edison Co of New York, Inc. 99pp. 47708/255-47708/257.

- 8811160467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Tests "Svc list and ROSSICE Division of Operational Events Assessment (Post 870411) 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142
- 8811290455 Advises that 880711 response to NRC Bulletin 88-004 fulfills requirements FAIRTHE, MB Project Directorate 1-3, 88/11/22 PAPANIC, G. Yankee Atomic Electric Co. 2pp. 47649-223-47649-224.
- 8812060208 Forwards additinto to support conclusion that rapidly propagating tubo rup-lure is not credible event at plant.per NRC Bullotin 88-002 PAPANIC,G Yankeo Atomic Electric Co. 88/12/01. Document Control Branch (Docu-ment Control Desk). 3pp. 47735-006-47735-008
- 8811290030 NRC Into Notice 88:093, "Teletherapy Events" Svc fist encl CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729), 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811.103:47811.215
- 8811290539 NRC info Notice 88-094, "Potentially Undersized Valve Actuators" Svc list
- encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/02, Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708.254.
- 8812150063 Submits addl into in response to IE. Bulletin 88-002, "Reputly Propagating Fatigue Cracks in Steam Generator Tubes." Brief description of facility primary-to-sec-
- ordary loak rate monitoring program and PAPANIC,G. Yankoe Atomic Electric Co. 88/12/07. Document Control Branch (Docu-ment Control Dask). 2pp 47823.001-47823.002.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Ucansees on Vendors" Svc list encl. ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:101-47807:302
- 8812270055 Advises that eight tubes plugged as result of Dec 1998 inservice insp of Staam Generator 3.Complete results will follow within 12 months. PAPANIC,G. Yankee Atomic Electric Co. 88/12/16. Document Control Branch (Document Control Desk). 1p. 47926:168-47926-69.
- 8812270228 Forwards Safety Insp Rept 60-029/88-20 on 881004-1114.No violations noted WIGGINS, J.T. Region 1, Ofc of the Director, 88/12/16, DRAWBRIDGE, B.L. Yankoo Atomic Electric Co. 2pp. 47927:038-47927.052.
- --8612270230 insp Hept 50-020/88-20 on 881004-1114 No violations noted. Major areas inspected operational safety verification, radiological controls, events requiring telephone notitication to NRC & maint observation.

 HAVERKAMP,D.R. Region 1, Otc of the Director. 88/12/15 13pp. 47927-040-
- S. Reportable occurrences, LERs & related correspondence
- 8812220129 Part 21 rept re cracks found in Westinghouse 20 inch gate valve. Discs returned to Westinghouse for metallurgical evaluation. Cracks do not represent substantial safety hazard Diagram of cracks end.

 PAPANIC, G. Yankee Atomic Efective Co. 88/12/14. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 4pp. 47914-064-47914-087.
- 8812210411 LER 88:010:00.on 881116.automatic ESF actuation occurred following breaker action.Caused by inadequate troubloshooting procedure Breaker repaired & returned to sec W/881215 fit. MELLOR,R.A., ST LAURENT,N.N. Yankee Atomic Electric Co. 88/12/15, 4pp. 47676.044-47678.047.

V. Operator Examinations

47927:052

- 8811300052 Notice of Licensee MgI Meeting 88:052 on 880420 to discuss untimitiatives & corrective actions re-operator ilcensing & retraining programs HAVERKAMP.D.R. Region 1, Otc of the Director. 88/04/07. Region 1, Otc of the Director. 2pp. 47668 224-47668 225.
- 8812210004 Advisos that util will procure plant ret simulator in flou of Commission approved facility. Simulator expected to be ready for training at facility in time to most certification requirements of 10CFR55.

 PAPANIC, G. Yankee Atomic Efectric Co. 88/12/09. Document Control Branch (Document Control Desk). 1p. 47877:056-47877:056.

DOCKET 50-32 AEROJET-GENERAL NUCLEONICS

V. Operator Examinations

8812140147 Forwards revised agenda for annual operator licensing meeting scheduled on 890110 W/o enci.

PATE,R.J. Region 5, Olc of the Director, 68/12/05, LAMB,1. Aerotest Operations, Inc.
1p. 47800:174-47800:174.

DOCKET 50-54 CINTICHEM

- P. Operating license stage documents & correspondence
- 8812200321 Withdraws application for exemption from current NRC requirement to convert research reactor to low enriched U fuel since funding for conversion will not be provided MCGOVERN,J.J. Cintichem, Inc. 88/11/30. MILLER,C. Standardization & Non-Power Reactor Project Directorate. 3pp. 47868:092-47868:094.

DOCKET 50-57 BUFFALO MATERIALS RESEARCH CENTER

F. Security, medical, emergency & fire protection plans

- 6812090187 Forwards Safety Insp. Ropt. 50.057/68.03 on 881017.No violation noted Buffalo Rosearch Ctr. staff performance during exercise demonstrated ability to implement emergency plan. 8 procedures to provide adequate protective measures BELLAMY, R.R. Region 1, Otc. of the Director. 88/11/128. RENNIE, D.W. New York State Univ. of, 8uffalo, NY. 2pp. 47785.038-47785-013
- -8812090191 Insp Rept 50-057788-03 on 881017 No violations noted Major areas Inspected Iconsea emergency preparedness exercise.

 LAZARUS,W.J., AMATO.C.G. Region 1, Ofc of the Director. 88/11/28. 4pp 47785 010 47785 013
- O. Inspection reports, iE Bulletins & correspondence
- 88 12090187 Forward's Safety Insp. Rept. 50-057/88-03 on 881017.No violations noted Buffato Rosparch Cir. staff performance during exercise demonstrated ability to Implement emergency plan. 8 procedures to provide adequate protective measures BELLAMY, R.R. Region. 1, Orc. of the Director. 88/11/28 RENNIE, D.W. New York, State Univ. of, Buffalo, NY. 2pp. 47785.008-47785:013.
- Inspected licensee emergency properedness exercise
 LAZARUS,W.J., AMATO,C.G. Region 1, Ofc of the Director. 88/11/28. 4pp
 47785:010-47785.013 DOCKET 50-77 CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR
- F. Security, medical, emergency & fire protection plans
- - 8812050108 Forwards fuel transfer plan for AGN-201 research & fest reactor.Plan withhold (rot 10CFR2 790).
 KEENEW E. Catholic Univ. of America, Washington, DC 88/12/02. Document Control Branch (Document Control Dosk). 1p. 47731 221-47731:221.

--8812090191 Insp Rept 50:057/88-03 on 881017 No violations noted Major areas

DOCKET 60-83 UNIV. OF FLORIDA TRAINING REACTOR

- H. General correspondence
- 8812010025 Comment opposing proposed rule 10CFR26 to Fitness for Duty Program which includes random drug testing Significant burdon would be Imposed on non-power facilities in ostablishing a maintaining superate program. VEFINETSON,W.G. Florida, Univ. of, Gainesville, FL. 88/11/17. Dockeling & Services Branch. 2pp 47678:232-47678 233.
- Q. Inspection reports, IE Bulletins & correspondence
- 8812080118 Forwards Exam Ropt 50-083/OL-88-02 administered on 881014.

 JULIAN,C.A. Region 2, Ofc of the Director, 88/11/25, WETHINGTON,J.A. Florida
 Univ. of, Gainesville, FL. 2pp. 47757:294-47757:317.
- --8812090120 Exam Rept 50:083/OL-98:02 on 881014 Exam results one reactor opera. tor passed written test. HOLMES-HAY, BROCKMAN, K.E. Region 2, Old of the Director, 88/11/10, 22pp 47757:28-47757:29.
- R. Periodic operating reports & related correspondence
- 8812070170 "Annual Progress Rept of Univ of Florida Training Reactor, Sept 1987 Aug 1988." W/881130 ltr.
 VERNETSONWO, WHALEY P.M., Florida, Univ. of, Galnesville, FL. ORO-4014-18 88/08/31, 215pp. 47737,325-47738;179.
- 8612090149 Forwards "1987-1998 Univ of Florida Training Reactor Annual Progress Rept." W/o encl. VERNETSON.W.G. Florida, Univ. of, Gainesville, FL. 88/11/30. Region 2, Olo of the Director. 1p. 47784:001-47784:001.
- 5. Reportable occurrences, LERs & related correspondence
- 8811280076 Submits followup on 881104 event re failure of temp record to track properly & requiring unscheduled shutdown.Probable cause isolated & planned recovery will be reviewed by Reactor Safety Review Subcommittee within 24 h. VERNETSON.W.G. Floride, Univ. of, Gainesville, FL. 88/11/07. ERNST,M.L. Region 2, Ofc of the Director. 1p. 47652:234-47652:234.
- 8811290120 RC.on 881104,unscheduled reactor shutdown occurred due to falure of temp recorder to indicate properly. Causod by fallure of microswitch. Microswitch 8 vacuum tube roplaced 8 calibr check performed. VERNETSON,W.G. Florida, Univ. of, Gainesville, FL. 88/11/14. ERNST,M.L. Region 2, Ofc of the Director. 3pp. 47649:279-47649:284.
- 8812140091 RO.on 881101.control blade Interlocks not checked prior to restart following shutdown Caused by administrative error. Operators retrained on requirements to porforming daily checkouts in Procedure SOP-A.2, "Reactor Startup." VERNETSON.W.G. Florida, Univ. of, Gainesville, FL. 88/11/17, ERNST,M.L. Region 2, Ofc of the Director. 2pp. 47800:192-47800:196.

V. Operator Examinations

- 8812090118 Forwards Exam Flept 50-083/OL-88-02 administered on 881014 JULIANC A Flogion 2, Ofc of the Director, 88/11/25 WETHINGTO: U.J.A. F. & de, Univ. of, Gainesville, FL 2pp. 47757 294-47757 317
- -8812090120 Exem Rept 50:083/OL:88:02 on 881014.Exem results one reactor operator passed written test. HOLMES-RAY.P., BROCKMAN,K.E. Region 2, Ofc of the Director 88/11/10 22pp. 47757.296-47757:317.

DOCKET 50-89 GENERAL ATOMIC CO.

V. Operator Examinations

8812140104 Forwards revised agentia for annual operator licensing meeting of

PATE RJ. Region 5, Ofc of the Director, 88/12/05, ASMUSSEN, K. General Atomic (formerly GA Technologies, (nc./General Atomic Co.), 1p. 47814, 175-47814-175

DOCKET 60-103 AEROJET GENERAL NUCLEONICS

V. Operator Examinations

8812140147 Forwards revised agenda for annual operator idensing meeting softeduled enality for remains revised agence for annual operator (censing mealing scheduled on \$30110.W/o and).

PATE RJ. Region 5, Ofc of the Director 68/12/05 LAMB,I. Aerotest Operations, Inc. 1p. 47800:174-47800:174

DOCKET 50-106 OREGON STATE UNIV. RESEARCH REACTOR

V. Operator Examinations

8812140085 Forwards revised agenda for annual operator licensing meeting on 690110 W/n encl. PATE RJ. Region 5, Otc of the Director, 88/12/05, ANDERSON,T. Oregon State Univ., Corvallis, OR. 1p. 47796-107-47796-107.

DOCKET 50-512 LINIV OF OXIAHOMA RESEARCH REACTOR

P. Operating license stage documents & correspondence

8812220015 Forwards notice of proposed issuance of orders authorizing disposition of component parts & terminating ticense Ri-53. MICHAELS T.S. Standard.tetion & Non Power Reactor Project Directorals, 58/12/07. SKIEKOWSKI,O. Oklahoms, Univ. of, Norman, OK. 3pp. 47892:159.47892:165.

--8812220018 Notice of proposed Issuance of order authorizing disposition of component parts & terminating License R-53
MILLEACL Standardization & Non-Power Reactor Project Directorate 98/12/07 4pp. 47892:162-47892 165.

DOCKET 50-113 UNIV. OF ARIZONA RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8812010194 Requests technical assistance in reviewing ficensee 881017 application for renewal of License R-52 section on motoprology. Completion date for review set for

MICHAELS.T.S. Standardization & Non-Power Reactor Project Directors's 68/11/26 CUNNINGHAM,L.J. Radietion Protection Branch 2pp. 47710:121-47710 122

P. Operating license stage documents & correspondence

8812010194 Requests technical assistance in roviowing licensiae 881017 application for tenewal of License 17-52 section on meleorology. Completion date for review sol for

BB0113. MICHAELS,T.S. Standard.zelion & Non-Power Reactor Project. Directorale 88/11/28. CUNN:NGHAM,L.J. Rediation Protection Branch. 2pp. 47710-121-47710.122

V. Operator Examinations

8812140100 Forwards revised agenda for annual operator ficensing meeting on 890110.W/o enci 10 anno 10 ann

DOCKET 50-116 IOWA STATE UNIV. RESEARCH REACTOR

K. Utility Final Safety Analysis Report (FSAR) & amenda

8812010319 Application for amond to License A.59 re conversion, from high to low on-Achee U for research reactor at lowa State Univ.
HENDRICKSON,A., SPINRAD,B.I. lowa State Univ. Armes, IA. 88/11/28 Document Control Branch (Document Control Desk), 2pp, 47698 057-47698 257.

-8812010331 Amend to SAR for UTR-10 reactor facility at lowe State Univ. lowa State Univ., Ames, IA. 88/11/30 59pp 47698 198-47698 257.

P. Operating l'cense stage documents & correspondence

8812010319 App dation for amend to License R-59 re conversion from high to low en-Koned U for research reactor at Towa State Univ. HEVDICKSCNB, SPINNRAD.B.L. Itowa State Univ., Annes, IA 88/11/28. Document Control Biarch (Document Control Desk) 25: 47698 057-47699 257

-8812010326 Tech Specs for UTR-10 reactor facility at fowa State Univ * cas State Univ , Amos, IA 88/11/30 139pp 47698 059 47698 197

•8812310331 Amend to SAR for UTH-10 roactor fat Hy at lowe State Univ. Nove State Univ. Ames, IA 88711730, 59pp. 47698 198 47698 257.

DOCKET 60-123 UNIV. OF MISSOURI RESEARCH REACTOR-ROLLA

V. Operator Examinations.

8912010059 Informs that operator Increasing exeminities chudulicul for www.of. 890/327-8 ind. Hallwinbinebrad for developing exam. WhiGHT,6C Region 17, Ofciol the Director 88/12/01 WARNER,D. Missouri, Univ. ct,Rt.s.,MD, 1p. 47746 oft8 47748 018.

DOCKET 50-128 TEXAS A&M UNIV. RESEARCH REACTOR

V. Operator Examinations

8812023310 Forwards rot matt requirements for reactor/servini reactor operator Leonsing erams scheduled during while the 890123 Inflo requested should be furnished by 880123 another for NYC to make schedule. CALLANLJ Region 4, 001c of the Director 88711728 FELTIZIDE, fexas A&M Univ. College Station TX 11pp, 47718 266-47718 276

DOCKET 60-131 OMAIIA VETERANS ADMINISTRATION HOSPITAL RESEARCH

F. Security, medical, emergency & tire protection plans

8812230029 Advises that 980928 emergency plan consistent w/provisions of 19CFR50 54(q) & acceptation Admin Report Reactor Project Directorate 88/12/14 LISCOTTE/RL Veterans Admin Medical Center, Omaha, NE. 3pp. 47863-068-

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

J. Insurance & Indomnity Information

8811290462 Forwards temporary exemption from schedular requirements of property ex-surance mis 100FR50.54(w)(5)(f) ralinsurance policies that prionize historico pro-ceeds for stabilization & recomamination after accident ER-CKSON/PB Standardzation & Non Power Reactor Project Directorate, BB/11/18 StiffER,JD Pacific Gos & Electric Co. 4pp. 47665-020-47665-034.

-8811290484 Temporary exemption from 10CFR50 54(w)(5)(i) ra incruaso In minount of cas to property damage insurance required by power reactor becases. 8 insurance that private produce for slab-reactor 8 deconfamination affor accident HOLAHAN,G M. Division of Reactor Projects. IIII.V.V. 8 Special Projects. (Post 870411), 89/11/18. Pacific Gas 8 Electric Co. 4pp. 47695 024-47605.034.

P. Operating Ilcense stage documents & correspondence

8811280048 Generic Lir 88.20 to all iconsees holding Ot's & CPs for nuclear power reactor facilities for individual plant exam for severe accident vulnerabilities Svc (s) CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Conscide dead Edison Co. of New York, Inc. 81pp. 47728 303:47729.024

Q. Inspection reports, IE Bulletins & correspondence

8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear

Gauyes: Sive list and CuArth Grand, R.E. Division of Industrial & Modical Nuclear Safety (Post 870729). 66/11/22, Consci dated Edison Co. of New York, Inc. 99pp. 47708-255 47708-257.

6811160467 NAC Info Notice 86-031, "Improper Administration & Control of Psychologic

ROSSICE Division of Operational Events Assessment (Post 870411), 88/11/22.

851129039 NAC Into Notice B8 093, "Telethorapy Events" Svc List encl CUNN-NGHAM R.E. Drus on of Industrial & Modical Nuclear Safety (Post 670729) 86/12/02. Conso dated Edison Co. of New York, Inc. 112pp. 47811 103-47811:215

8811290538 NRC Info Notice 88 094, "Potentially Undersized Valve Actuators." Svc "sl

HOSSICE: Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254

8812020287 NRC Info Notice 88-095, "Inadequate Procurement Roquirements Imposed by Leasses on Vendors." Svc list end.

ROSSICE: Division of Operational Evonts Assessment (Post 870411), 88/12/08
Consolidated Edison Co. of New York, Inc. 112pp. 47807.181-47807.302

V. Operator Examinations

8812140088 Forwards revised agenda for annual operator Licensing meeting on 890110 W/o encl PATE.R.J. Region 5, Ofc. of the Director 88/12/05. PRIGMORE,B Pacific Gas & Electric Co. 1p. 47736 131-47796 131.

DOCKET 60-139 UNIV. OF WASHINGTON RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8812190146 Forwards revised physical security plan Rev withheld (cot 10CFR2.790). ROBKIN,M.A. Washington, Univ. of, Seattle, WA. 88712713. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 47853.360. 47853.360.

P. Operating license stage documents & correspondence

8811300199 Forwards Amend 14 to License R-73 & safety evaluation Amend allows cartain surveillance requirements associated w/ operation of reactor to be suspended if no fuel in core
MICHAELS,T.S. Standardization & Non-Power Reactor Project Directorate 88/11/18
ROBKIN,M.A. Washington, Univ. of, Soattle, WA 3pp. 47696.227-47696.238

- -8811300202 Amend 14 to License R-73, allowing cortain surveillance requirements associated w/operation of reactor to be suspended.
 MILLER,C.L. Standardization & Non-Power Reactor Project Directorate, 88/11/18. 7pp. 47696 230-47696:236.
- -8811300205 Safety evaluation supporting Amond 14 to License R-73 Amond allows certain surveillance requirements to be suspended.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/18, 2pp. 47696:237-47696

V. Operator Examinations

8812140109 Forwards revised agenda for annual operator licensing meeting on 890110.W/o encl. PATE, R.J. Region S. Olc of the Director. 88/12/05. MILLER, W. Washington, Univ. of, Seattle, WA. 1p. 47814.035-47814.035.

DOCKET 50-142 UCLA TRAINING REACTOR

P. Operating license stage documents & correspondence

8812220002 Responds to 881012 request for add! Info re proposed Phase it or final phase research reactor decommissioning plan. Work will begin shortly on updating old RFP to commorcial organizations. MCLAUGHLIN,JE California, Unity. of, Los Angelos, CA. 88/12/07. ADAMS,A. Standardization & Non-Power Reactor Project Directorate. 2pp. 47000 033-47900.056.

W. Decommissioning Stage Documents & Correspondence

-8812220003 Forwards response to NRC 681012 questions re Phase I decommission-Ing activities undertaken per ASLB 850930 settlement agreement Requests that NRC confirm or certify that Phase I complete. MCLAUGIRUN, JE. Celliornia, Univ. of, Los Angelos, CA 86/12/07. ADAMS,A Standardzation & Non-Power Reactor Project Directorate. 22pp. 47900.035-47900.056.

DOCKET 50-151 UNIV. OF ILLINOIS RESEARCH REACTOR

V. Operator Examinations

8811280075 Requests ref matil listed in onct be provided for written & oral exam scheduled for wk of 880220 Alt reactor & server reactor operator license applications should be submitted at least 80 days prior to exam dates.
WRIGHT,G.C. Region 3, Old of the Director, 88/11/16, MILEY,G.H. Ill.nois, Univ. of, Urbana, IL. 11pp. 47654.076-47654:086.

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

8812070140 Revised emergency Implementing procedures, consisting of Rev 20 to copy-holders list, Rev 21 to Index & Rev 13 to App G, "Emergency Telephone Numbers Augmentation List."

* Consumers Power Co. 86/11/29, 13pp. 47746;308:47746;320.

8812200315 Rev 108 to Vol 9A, "Site Emergency Plan Implementing Procedures" HOBE.M.A. Consumers Power Co. 88/12/02, 23pp. 47868.307-47868.328.

8812120217 Provides status summary for Insp. Rept. 50-155/88-06 open items. Exemption request from requirements of Section III.G.2 of App. R. still under review by NRR. Additinto provided to NRR in Feb. 1988.
MARBAUGH,K.E. Consumors Power Co. 88/12/07. Document Control Branch (Document Control Desk), 38pp. 47792:027-47782:065.

8812200299 Rev 90 to Vol 9 to "Site Emergency Plan." HOBE,M.A. Consumers Power Co. 68/12/08, 16pp. 47864:325-47864:340.

8812210100 Revised emergency plan Implementing procedures, consisting of Rev 22 to "General Otc Response Team/Emergency Operations Facility (EOF) Procedures Indax" & Rev 2 to App H, "General Otc Emergency Planning:EOF Training Matrix." * Consumers Power Co. 66/12/13, 3pp. 47682.069-47682.071.

P. Operating license stage documents & correspondence

8811300178 Requests extension of schedular exemption for 1 yr from submittal of requirements for updated final hazards summary tept due to util expanding scope to include provisions from NRC SRP & Reg Guide 1.70 Fee paid.

BERRYK.W. Consumers Power Co. 88/11/22. Document Control Branch (Document Control Dask). 3pp. 47697:195-47697:197.

8811280048 Generic Lit 88-20 to all licensees holding QLs & CPs for nuclear power reactor facilities to individual plant exam for severe accident vulnerabilities. Svo lie

CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consol detect Edison Co. of New York, Inc. 81pp. 47728.303.47720.024.

8B11300282 Informs that util shall propose new plant Tech Spac pressure-temp limit derived using Rev 2 to Reg Guide 1.99, per Generic Lit 88-11 before 891231. SMEDLEY.R.W. Consumers Power Ce. 88/11/23. Document Control Branch (Document Control Desk). 2pp. 47698-204-47696-205

8812020026 Advises that Update 9 to "Pran for Big Rock Point Integrated Assessment acceptable. SCOTT,W.E. Project Directorate III-1. 88/11/30. BERRY,K.W. Consumers Power Co 4pp. 47707.168-47707.171.

8812060137 Advises that 880713 Rev 7 to suitability training & qualification plan consist ant w/provisions of 10CFR50 54(p) & acceptable GREGER, IR. Region 3, Old of the Director, 88/11/30, JOHNSON,B.D. Consumer Power Co. 2pp. 47741;161-47741.162.

8812050316 Notifies that schedule for completion of Integrated Plan Issue BN-025 "Wind & Ternado Loading," changed to 890228 due to delivery delays involving several Items needed to complete installiation & testing. MARBAUGH, K.E. Consumers Power Co. 68/12/01. Document Control Branch (Document Control Dask). 1p. 47731:355-47731:355.

8812130238 Informs that due to difficulties updated offsite dose calculation manual cannot be completed within 6 month time period Rev 3 will be submitted by 890315 MARBAUGH,K.E. Consumers Power Co. 86/12/08 Decument Control Branch (Document Control Desk). 1p. 47784:084-47704.084.

8612200025 Forwards salely evaluation accepting util response to Generic Ltr 83 28 lisem 2.1 Part 2 considered resolved SCOTTWE. Project Directorate III-1, 88/12/14, BERRY,K.W. Consumers Power Co 2pp. 47882.183-47862.186

--8612200030 Safety evaluation accepting util response to Generic Ltr 93-28.

• Office of Nuclear Regulation, Director (Post 870411), 88/12/14, 2pp 47862-185, 47862-186.

O. Inspection reports, IE Bulletins & correspondence

8811169211 NRC Info Notice 88-990, "Unauthorized Removal of Industrial Nuclea Gaugos "Svc fist onct.
CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729)
88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708 257.

8811160467 NRC Into Notice 88-081, "Improper Administration & Control of Psychological Tosts" Svc list encl.
ROSSI/CE Division of Operational Evanta Assessment (Post 870411). 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708:142

88 11280083 Forwards Safety Inap Ropt 50:155/66-22 on 66:1024-26 No violations noted One weakness re-overrellance on historical radiological hazards noted. GREGERL R. Region 3, Oto of the Director, 86/11/23, HOFFMAN,D.P. Consumer Power Co. 2pp. 47854:087-47654;104.

---8811280089 Insp. Rept 50-155/88-22 on 881024-28 No violations noted Major great inspected radiological protection program, including organizational & mg conviots training & qualif cations & internal & external exposure controls. SLAWINSKI,W.J. Region 3, Ofc. of the Director. 88/11/23, 18pp. 47654:089 47654:104

8812050270 Responds to NRC 880922 notice of violation & proposed imposition of civi penalty re-equipment qualification of electrical equipment deliciencies Corrective actions: Limitoryou SMB-00 installed & fully qualified.

BERRY,K.W. Consumors Power Co. 88/12/01. Document Control Branch (Documen Control Dosk). 4pp. 47740:182-47740.185.

8812050276 Requests Commission reconsider amount of proposed fine for imposed civil penalty for violation re environ qualification of efectrical equipment distributions of efectrical equipment distributions of the proposed fine unreasonable for plant size & age.

HOFFMAN,D.P. Consumers Power Co. 68/12/01. Document Control Branch (Document Control Desk). 4pp. 47732.074-47732.077.

8811290030 NRC Info Notice 88 093, "Teleiherapy Events." Svc list encl. CUNNINGHAM,R E. Division of Industrial & Modical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811;103-47811;215

8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc lis

ROSSI,C.E. Division of Operational Evants Assessment (Post 870411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.

8812120217 Provides status summary for Insp. Rept. 50-155/88-06 operitems. Exemption request from requirements of Section III.G.2 of App. R. st.II under review by NRR. Addt Info provided to NRR In Feb. 1988.
MARBAUGH,K.E. Consumers Power Co. 88/12/07. Document Control Branch (Document Control Deak). 38pp. 47792:027-47792:065.

8812020287 NRC Into Notice 88:095, "Inadequate Procurement Requirements Imposes by Licensees on Vendors," Evo list enct. ROSSI, CE. Division of Operational Events Assessment (Post 870411) 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp, 47807:191-47807:302.

- 8812210404 Forwards Safety Insp Rept 50-155/88/21 on 881018/1128 No violations
 - noted AXELSON W.L. Region 3, D/c ct the Director, 88/12/09, HOFFMAN D.P. Consumers Power Co. 2pp. 47875-315-47875-324.
- ---8812210405 Insp. Rept. 50-155/88-21 on 881018-1128 No violations noted Major areas inspected surveil arces of reactor protection systhypass valve & emergency diesel generator & maint activities on various components. JACKIWJ.IN Region 3, Otc oil his birector 88/12/09 8pp. 47875-317-47876-324.
- 8812210371 Forwards Salety Insp Rept 50 155/88-23 on 881114-18 No violations noted GREGER, L.R. Region 3, Ofc of the Director, 68/12/14 HOFFMAN, D.P. Consumers Power Co. 2pp 47875 203-47875 214.

--8812210376 Insp. Rept 50-155/88-23 on 881114-18 No violations noted. Major areas Inspected chemistry program, including procedures & mgt organization & training & re-actor sys water OC program. HOLTZMANTIB. SCHUMACHER.M. Region 3, Ofc of the Director. 88/12/10. 10pp

R. Periodic operating reports & related correspondence

47875 205 47875:214

8812130304 Monthly operating rept for Nov 1988 for Big Rock Point Plant W/881202 lit JOHNSTON J.R., ELWARD, T.W. Consumers Power Co. 88/11/30 6pp 47796236 47796 241

8. Reportable occurrences, LERs & related correspondence

8811290117 LER 88-008-00 on 881028 load rejection occurred due to loss of transmission has Caused by lightning rod which broke off during high winds.Control rod drive motor generator set repaired.W/881123 ltr.

ALEXANDERR J., MARBAUGH,K.E. Consumers Power Co 88/11/23 4pp. 47650 246-47650 249.

DOCKET 50-160 GEORGIA INSTITUTE OF TECHNOLOGY RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

- 8811300087 Responds to violations noted in Insp. Rept. 50.160/88-03. Corrective actions:emergency plan revised to reflect current organizational 8 functional mgt changes, Manager of radiation sately ofc delegated as alternate emergency director. KARÁM,R.A. Georgia Institute of Technology, Atlanta, GA. 88/11/23. Document Control Branch (Document Control Dask). 2pp. 47701:348-47701:350.
- 8812140008 Oraft Rev 4 to "Emergency Preparedness Plan for Neely Nuclear Research Ctr" W/881207 fr KARAMAR A. Georgia Institute of Technology, Atlanta, GA 88/12/07, 36pp. 47798-300-47798-335.

P. Operating license stage documents & correspondence

8812160053 Responds to eight Issues required to be resolved prior to resumption of reactor operation,per NRC request All unity personnel being trained in new 8/or revised procedures for callot 8 operation of radiation monitors. CRECINEJ.P. Georgia Institute of Technology, Atlanta, GA, 88/11/02. ERNST.M.t. Region 2, Ofc of the Director. 4pp. 47630 348-47830 351.

Q. Inspection reports, IE Bulletins & correspondence

- 8811230116 Decusses 880819 & 1102 ltrs ref NRC requirements imposed by 880120 order modifying license & 880317 confirmatory order modifying license Orders re utilization of facility for Irradiation experiments & operation of research reactor. ERNST.M.L. Region 2. Of cof the Director. 88/11/15. CRECINE.J.P. Georgia Institute of Technology, Atlanta, GA, 2pp. 47652.079 47652.080
- 8811300067 Responds to violations noted in Insp. Rept. 50-160/88-03. Corrective actions emergency plan revised to reflect current organizational & functional mgt changes Manager of reflection safety of delegated as atternate emergency director. KARAM,R.A. Georgia Institute of Technology, Atlanta, GA. 88/11/23. Document Control Brench (Document Control Desk). 3pp. 47701:348-47701:350.
- 8812190203 Ack receipt of 881123 fit informing NRC of steps taken to correct violations noted in Insp Rept 50-160/88-03.

 DECKER,T.R. Region 2, Cit. of the Director, 88/12/08, KARAM,R.A. Georgia Institute of Technology, Alianta, GA. 1p. 47852-098-47852-098.

DOCKET 50-183 GA TECHNOLOGIES

P. Operating license stage documents & correspondence

- 8811280123 Forwards Amond 40 to License R-67 & safety evaluation. Amend adds requirements for site boundary, allowing reactor bidg air leakage & verification thereof & installation, aveilability & surveillance of operability of reactor room.

 ADAMS, A. Standardization & Non-Power Reactor Project Directorate. 88/11/18. ASMUSSEN, K.E. General Atomics (formerly GA Technologies, Inc./General Atomic CA), 500, 4255-4184,4255-444. Co.) 500, 47654:118 47654:144.
- -8811280125 Amend 40 to License R-67,adding requirements for site boundary allowing reactor brig air leakage & vanfication thereof & installation.availability & surveit-lance of operability of reactor room activated cheroota fixer sys.

 MiLLER.C.L. Standardization & Non-Power Reactor Project Directorate. 88/11/18. 800. 47654:123-47654:130.
- -8811280127 Salety evaluation supporting Amend 40 to License R-67.

 * Standardization & Non-Power Reactor Project Directorate 88/11/18. 10pp. 47854:131-47654:140.

-8811280176 Forwards mall already faxed to NRC in response to 880830 telcon info

requested on proposed filter listed.

WHITTEMORE.W.L. General Alomics (farmorly GA Technologies, Inc./General Atomic
CO) 88/08/30 ADAMS, A Dwisson of Reactor Projects - III,IV.V & Special Projects
(Post 870411). 4pp. 47654

V. Operator Examinations

8812140104 Forwards revised agenda for annual operator licensing meeting on 690110 W/o encl. PATE, R.J. Reg on 5, Oic of the Director. 88/12/05. ASMUSSEN,K. General Alomics (formerly GA Yechnologies, Inc./General Atomic Co.). 1p. 47814:175-47814:175

DOCKET 50-170 ARMED FORCES RADIOBIOLOGY RESEARCH INSTITUTE

P. Operating license stage documents & correspondence

- 8812090007 Forwards malls for AFRRI RRFSC maeting on 880526.por request. EVANS,D. Armed Forces Radioblological Research Institute 88/07/05 ADAMS,A. NRC No Detailed Afficiation Given. 18pp. 47784.011-47784.330
- **8812090008 "10CFR50.59 SER of New Reactor Instrumentation & Control Sys at Armed Forces Radiobiology Research Inst " MOORE.M., HODGDON,K., MUNNO,A., Armed Forces Radiobiological Research Institute 88/05/11, 84pp, 47764.029.47784:112.
- -8812090009 "Console Instellation Check out & Test Plan." ชะ เรษายนหน้า Currisole instantation Uneck อย่า & Test Plan." HODGDON,K., MOORE,M. Armed Forces Radiobiological Research Institute. 87/12/ 15. 59pp. 47784:113-47784.171.
- -8812090010 "New Reactor Control Console OA Program."

 * Armed Forces Radiobiological Research Institute, 88/07/05, 83pp. 47784.172-
- -8812090011 "Description of Old & New Reactor Instrumentation & Control Sys for AFFRI Mark F. Reactor Fecility."
 HODGDON,K. Armed Forces Redlobiological Research Instituto 88/05/11, 78pp 47784 253 47784.330.

Q. Inspection reports, IE Builetins & correspondence

- 8812060015 Forwards Insp Rept 50:170/68-04 on 881028-28 & 1107. Violation noted will be discussed during enforcement conference.

 KANE,W.F. Region 1, Ofc of the Director, 88/11/28, IRVING,G. Armod Forces Radiobiological Research Institute 2pp. 47741:239-47741:253
- ~8812060019 Insp Rept 50-170/88-04 on 881026-28 & 1107-Violation noted. Major areas inspected facility operations, organization, reviews & audits operator requestion training, surveillance activities & allegation followup.
 WILLIAMS_JH, LINVILLE_J.C. Region 1, Old of the Director. 88/11/23, 14pp 47741:240-47741:253.

V. Operator Examinations

- 8812060015 Forwards Insp. Rept 50-170/88-04 on 881026-28 & 1107. Violation noted will be discussed during enforcement conference.

 KANE,W.F. Region 1, Oto of the Director, 88/11/28. IRVING,G. Armod Forces Radio biological Research institute. 2pp. 47741:238-47741 253.
- ~8812060019 Insp. Rept 50-170/68-04 on 681026-28 & 1107.Violation noted. Major areas inspected facility operations, arganization, reviews & audits, operator requaffication training, surveillance activities & allegation followup. WitLIAMS_JH., LINVILLE_JC. Region 1, Old of the Director, 88/11/23, 14pp. 47741:240-47741:253.

DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

J. Insurance & Indemnity information

- 8811300112 Forwards exemption from schedular requirements of 10CFR60.54(w)(6)() re property insurance rule effective 88/10/4. ERICKSON,P.B. Project Directorale IV. 88/11/18. ALDEN,W.M. Philladelphila Electric Co. 4pp. 47670.304-47670.311.
- ~8811300114 Exemption from schedular requirements of 10CFR60.64(w) re-property insurance required to be carried by reactor l'conseus.

 HOLAHAN,G.M. Division of Reactor Projects - III,IV.V & Special Projects (Post 870411), 88/11/18. Philadelphia Electric Co. 4pp. 47670:300-47670.311.

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 88-20 to all licensons holding OLs & CPs for nuclear power reactor facilities re individual plant exam for sovere accident vulnerabilities. Svc list EBID. CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consordated Edison Co. of New York, Inc. 81pp. 47728;303-47728.024.
- 6812050283 Responds to appeal of denial of FOIA request for documents. Forwards portions of Elsasser 880505 memo.Marcus 871222 memo withhold (rol FOIA Exemp. tion 51.

won op.
CHILK,S.J. Office of the Secretary of the Commission 88/11/30, RHODES,J. Pennsylvana, Commonwealth of. 2pp. 47729:186-47729:201.

-8812050288 Trip rept of Commissioner Carr & T Elsasser 871215 site visit to util & 871216 attendance at Region I periodic regional resident counterpart meeting. ELSASSER, T. NRC - No Data led Affiliation Given. 88/01/05. NRC - No Dataled Affiliation Carrier 1988 (1988) allon Given. 3pp. 47729:199-47729.201.

0812220020 Responds to 680907 request for add1 into re 870304 application for amend to License OPR-12 Current physical & radiological status of decommissioned facility does not wairant costs associated w/installation of detection sys GALL AGHERLY W. Philadelphia. Electric Co. 88/12/16. Document Control Branch (Document Control Dosk). 5pp. 47913-312-47913-316.

Q. Inspection reports, IE Bulletins & correspondence

8811160211 NRC Into Notice 88-090, "Unauthorized Romoval of Industrial Nuclear Gesiges "Svc list encl. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Salety (Post 870729). 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.

8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologi-

cal Tests" Syc list enct.

ROSSICE: Division of Operational Everits Assessment (Post 870411), 88/11/22.
Consolidated Edison Co. of New York, Inc. 101pp. 47708/042-47708/142

8811290030 NRC Into Notice 88:093, "Teletherapy Events" Svc fist encl CUNNINGHAM,R.E. Division of Industrial 8 Modical Nuclear Safety (Post 870729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215

8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Svc list ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Conscillated Edison Co. of New York, Inc. 121pp. 47708.143.47708.254

8812020287 NRC Into Notice 88.095, "Inadequate Procurement Requirements Imposed by Licensees on Vandors." Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302

DOCKET 50-183 VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR

8812140153 Forwards revised agenda for annual operator Iconsing monthly on 890110 W/o enci PATE,R.J. Region 5, Oic of the Director, 88/12/05, CUNNINGHAM,G. General Elec-tric Co. 1p. 47813:351-47813:351.

DOCKET 50-186 UNIV. OF MISSOURI RESEARCH REACTOR-COLUMBIA

P. Operating license stage documents & correspondence

8812070159 Application for amend to License R-103,revising Tech Spec 61.a re

additions mods or maint to sys.
MCKIBBEN,J.C., ALGER,D.M. Missouri, Univ. of, Columbia, MO. 88/11/30. Office of

Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47749 254-47749 255.

8812150007 Informs that L.A-CP-87-02, "Nonpower Reactor Sabotago Study" reviewed, corrected & returned as prescribed in 880913 ftr.
MCKIBBEN, J.C. Missouri, Univ. of, 180ta, MO 89,112/08. Document Control Branch (Document Control Dosk) 1p. 47826 250-47826 250.

V. Operator Examinations

V. Operator Examinations

8811300513 Requests that Econsee furnish encl list of ref malf 50 days prior to operator 8 serior operator licensing exams scheduled for wk of 890109. Rugulrements for administration of written exams & rubes & guidernes also encl. WRIGHT, G.C. Region 3, Otc of the Director. 88/11/22. BRUGGER,R.M. Missouri, Univ. of, Columbia, MO. 8pp. 47678.034-47876 041.

DOCKET 50-192 UNIV. OF TEXAS RESEARCH REACTOR P. Operating license stage documents & correspondence

8812220014 Forwards request for addl into re-application for amend to License R-192 Addl into to be submitted within 30 days of itridate.

ADAMS,A. Standardization & Non-Power Reactor Project Directorate. 86/12/14.

BAUER,T.L. Toxes, Univ. of, Austin, TX. 4pp. 47000:096-47900:099.

DOCKET 60-208 SAN ONOFRE NUCLEAR STATION, UNIT 1

- F. Security, medical, emergency & the protection plans
- 8811290025 Forwards Insp. Repts 50-206/88-26,50-301/88-27 & 50-362/88-29 on 881025-28 No deficiencies or violations noted.

 YUHAS,G.P. Region 5, Ofc of the Director. 88/11/10. BASKIN,K.P. Southern California Edition Co. 2pp. 47651-888-47651-038.
- --8811290032 Insp. Repts 50:206/88:26,50:361/88:27 & 50:362/88:29 on 881025-28.1/10 defictioncles or violations noted Major areas inspected open items identified during 1887 exercise & omergency preparedness exercise & associated critique GOOD,G M. Region 5, Ofc of the Director. 88/11/10. 10pp. 47651:099.47651:099.
- 8812160133 Forwards SALP Board Repts 50-206/88-25,50-361/88-26 & 50-362/88-28 for period Oct 1987 Sept 1988 Need to Improve high involvement in developing self-critical attitude at all levels of ulti-organization noted. MARTIN,JB. Region 5, Oic of the Director 88/11/25. BASKIN,K-P. Southern California Ed son Co. 3pp. 47820-321-47820-380.

- H. General correspondence

- 8811290018 Informs that 981108 request for extension of public comment period or proposed liness for duty rule denied Ample response time provided GRIMES BK Division of Reactor Inspection & Safeguards (Post 870411) 86/11/16 CINTRON,J A. Southern California Edison Co. 1p 47688 068-47668.069
 - 8811300539 Responds to 981112 request for Commission to extend public commen
 - petrod on proposed Fitness for Duty rule Comments recoved after 881121 will be considered if practical.

 GRIMES BK. Division of Reactor Inspection & Safeguards (Post 870411), 88/11/28

 JOKUMATO,J. Southern California Edison Co. 1p. 47680:172-47680,174.
 - P. Operating license stage documents & correspondence

 - 8811230311 Discusses changes made to improve use of accelerated maint processes for util Requests discussion w/NRC on changes made to Superintendent accelerated
- maint process during next visit
 MCCARTHY,CB Southern Carlornia Edison Co 88/06/20 ZIMMERMAN,R Region
 5, Ofc of the Director. 3pp. 47632 350-47632 352
- 8811230232 Forwards notice of environ assessment & finding of no significant impact ro 880428 request to detate turbine deck load bearing test from Tech Specs TRIAMMELLC M. Project Directorate V. 88/10/28 BASKIN,K.P. Southern California Edison Co. 3pp. 47631.198-47631.203
 - —8811230233 Environ assessment & finding of no significant Impact re 880428 application for amend to Liconse DPR-13 Amend delates from Tech Spec requirement to conduct furbine dock load toaring tost every four y/s KNIGHTON.G W Project Directorato V. 88710728, 3pp. 47631:201-47631:203. 8811290149 Forwards Amend 114 to License DPR-13 & safety evaluation. Amend re-
- vises surveillance requirements for ealely injection sys TRAMMELL.C.M. Project Directorate V. 88/11/18 BASKIN,K.P. Southern California Edison Co. 3pp. 47648 155-47649.168.
- --8811290155 Amond 114 to License DPR-13, revising surveillance requirements for safety injection sys. KNIGHTON,G.W. Project Directorate V. 88/11/18, 8pp. 47648,158-47648/165.
- --8811290156 Safety evaluation supporting Amend 114 to License DPR-13
 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/18, 3pp 47648-166-47648:168.
- 8811290562 Requests addition to complete review of recartification of charging pump motors to at least 700 horsepower or rewinding or replacement, per License Condition 3.L(6). Evaluation & formal certification w/new reting by milg requested. TRAMMELL, C.M. Project Directorate V. 88/11/22 BASKIN, K.P. Southern California Edson Co. 4pp. 47666.028.47666.031
- 8811300233 Informs that rovidw of Chango Noticu 29 to Topical Rept SCE-1-A, "OA Program," Amand 11 will require more than 60 days to complete review & evaluation KIRSCH.O.F. Fleglon 5, Otc of the Director, 88/11/22. BASKIN,K P. Southern California Ethison Co. 1p. 47677:139 47677:139
 - 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities to individual plant exam for severe accident vulnerabilities. See list CRUTCHI'(ELD.D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47720.024.
- 8811290085 Forwards addl Info re impact on ac/dc sys capacity 8 capability resulting from nuclear instrumentation sys upgrade.per C Trammell 881123 telcon request Addinto Incorporated into util 881110 it. 881110 it. NANDY, F.R. Southern California Edison Co. 88/11/23. Document Control Branch (Document Control Dask). 2pp. 47667:192-47667:193
- 8811290461 Forwards notice of environ assessment & finding of no significant impact re util 890428 request to transship spont fuel from Unit 1 to Units 2 & 3. TRAMMELLC M. Project Directorate V. 88/11/23. BASKIN,K.P. Southern California Edison Co. 3pp. 47649:161-47849:172.
- ~8811290457 Environ assessment & finding of no significant Impact to 880428 request to transcript spent fuel from Unit 1 to Units 2 & 3.

 KNIGHTON,G W. Project Directorato V. 88/11/23, 9pp. 47649 164-47649:172.
- 8812010345 Forwards revised pages of 870311 reactor protection sys single failure analysis, per 881122 telcon w/C Trammell. Analysis revised to include nuclear instrumentation sys upgrade mods pranned for upcoming Cycle 10 relucing outage. NANDY,F.R. Southern California Edison Co. 88/11/23. Document Control Branct (Document Control Dask), 19pp 47703:281-47703:299.
- 8812060083 Forwards Amend 115 to License DPR-13 & safety evaluation. Amend revises steam generator tube plugging criteria to allow tubes widefacts in rolled region of tube sheet to remain in svc.
 TRAMMELL.C.M. Project Directorate V. 88/11/28. BASKIN,K.P. Southern California Edison Co. 3pp. 47743:183-47743:181.
- --8812060091 Amend 115 to License DPR-13,revising steam generator tube plugging criteria to allow tubes w/defects in relied region of tube sheet to remain in svc provided first Inch of refled tube contains no imperfections.

 KNIGHTON,G.W. Project Directorate V. 88/11/28, 10pp. 47743:168-47743:175.
- --8812060093 Safety evaluation supporting Amend 115 to License DPR-13,
 **Office of Nuclear Reactor Regulation, Director (Post 870411), 8B/11/28, 4pp 47743:176-47743:179. -8812060096 Notice of Issuance of amend to License DPR-13 Amend revises steam
- --8812150141 SALP Repts 50-206/88-25,50-361/88-26 & 50-362/88-28 for Oct 1997 Sept 1988 Category 1 assigned in areas of radiological controls & security * Begins 6 Ole of the Disease 18(11/25-32co-478-27-324-478-278generator tube plugging criteria to allow tubes w/ defects in rotted region of tube sheet to remain in sec of first inch of rolled tube contains no imperfections. TRAMMED C.M. Project Directions V. 86/11/28, 2nd. 47743-184, 47743-181.

- 8812050050 Provides add info in support of NRC roview of transchipment of Sprint fuelper 881130 discussion As part of transchipment process, from yoke without call to transport GE IE-300 spart fuel cask Std forg yoke without to 150°s, lead tested MEDFORD, MO Southern Cellional Edison Co. 08/12/01. December Control Brach (Document Control Desk). 2pp. 47723-105-47723-106.
- 8812150106 Forwards notice of consideration of issuance of amena to Extensi DEE-13 refrequent for approval to change power supply for MOV-35ft to an interruptible power supply.
- supply.
 TRAVMELLICIM Project Directorate V 88/12/01 BASKALKIP Southern California Edison Co. 3pp. 47630 224-47830 230.
- -3812150108 Notice of consideration of issuance of annexal to License DPRLSE & ignorthwhy for bearing Amend would change power supply for Motor Counties Value MOV-358 to uninterruptible power supply to eliminate single to the suscept to 2 XNIGHTON,G.W. Project Directorate V. 86/12/01. 4pp. 47610-227-47810-233.
- 8812060040 Clarifies error in rept. "Transstrpmunt of Soci Orafra Unit 1 Spect Lock
- submitted by 880425 ftr.
 MEDFORD,MIO Southorn Certainia Edison Co. 08/12/02 Document Control Pranch (Document Control Desk). 1p. 47752-194-47752-194
- 8912080073 Forwards Amand 116 to License DPR-13 & sulfity eventiation. Amand no thomass transshipment of sport feet from Unit 1 sport feet pool to store in Units 2 & 3. spant full pools.
 TRAMMELL,C.M. Project. Grectorato. V. 88/12/02. BASKIN,K.P. Scrittura Calif. In a.
 Edison Co. 3pp. 47743:128-47743:141.
- -8812080074 Amond 116 to Licenso DPR-13 authorizing transchipment of spiral field from Unit 1 spent fuel pool & w/Annands 63 & 52 to 1 conser. NET-10 & SEF 15 respectively, authorizes 15 storo Unit 1 spont fael in Units 2 & 3 spiral fael pools KNIGHTON,G.W. Project Directorate V. 88/12/02, 2pp. 47743 131-47/4/1132
- **≈8812060076** Safety evaluation supporting Amend 116 to U cninio DPR-13 * Project Directorate V. 88712/02 7pp 47743 133 47743 139
- -8812080110 Notice of Issuance & azalability of Amend 116 to License (LFR-1) TRAVMELLICIM, Project Oxectorato V. 88/12/02, 2pp. 47/43 140 47/43 141
- 8812150134 Requests response to Generic Lti 88-17 re loss of BHR Lindentry response to Generic Lti 87-12 deficient his areas of provention of accident bit at on 6 ne legit in of accidents before progressing to cord damage MARLEY, TE Office of Nuclear Reactor Registation, O rector (Part 970444) 02. ALLEN.H P. Southern Callornia Edison Co. 5pg. 47630-184-478-19.169
- 8812080121 Provides additational Issues resulting from order in 991425 submitted to unasshipment of sport tool at plant per CRC 091203 request 0.1 no temper dispression availability of one train whom other train dinninged MEDFOROMO Southern California Edison Co. 88712703 Document Control Desk), 32pp. 47753:022-47753:053.
- 8812160125 Forwards notice of consideration of Issuance of America 15th to been to DPR-13 & proposed NSHC determination & opportunity for hearing Arcand with Min to allowable diosci generator load from 6.250 kM to dissign rating of 0.050 kM in TRAMMELL, C.M. Project Directorate V 68712706 BASKIN K P Southern Co-Amilia Edison Co. 3pp. 47828-095-47826-101
- --8812160127 Notice of consideration of Issuance at amount to Learne UPA 13 A 190 posed NSHC determination & apportunity for inaming Anicide world in such exactly desergent of load from 6,250 kW to design stang of 0,000 kW KNIGHTONG.W. Project Directorate V. 88/12/06 4pp. 47828 098 47828 101
- 8812120200 Forwards Amend Application 158 to Econso DPB-13, rounsiting of pro-posed Change 184 to revise Tech Specs, Appl A, incorporating leading reported as an operation & survitance requirements for auxiliary treduction for joint BASKIN, K.P. Southorn Colforns Edison Co. 88/12/68 Document Central Branch (Document Control Desk). 1p. 47787-052-47787.090
- --8812120203 Application for amond to License DPB-13 (เพราะกุ App. A Tech types a to incorporate line ling conditions for operation & euror lance (equipment) as servisted w/mod to incorporate third aux any feedwater pump into existing by/ BASKIN,K.P. Southern California Edison Co. 88/12/08, 20pp. 47787-051 47787-040
- --- 88.12.120207 Proposed Tech Specs Incorporating limiting conditions for operation A surveillance requirements for revised auriliary feedwater system of mining or project in succeptibilities in sys
- Southern California Edison Co. 89/12/08 18pp 47/87 001-47/87 000
- 8812210065 Second partal response to FOIA request for records App. C. decembers end & available in PDR.
 PHILLIPS. Dirision of Freedom of Information & Publications Survivion (Front 880515), 68/12/14. PARRISH,0. Attitution Not Assigned, 2pp. 47674 120 47874 160
- -8812210080 Forwards procedures per tolcon w/K (baskin MEDFORDM Southain Cathornia Edison Co. 88/09/20 ZWOLINGKL), NRG, Reptile 199 Affiliation Given, 4pp. 47874-142-47874-145.
- --8812210087 Rev 1 to Sita Directive NGS-D-006, "Alcolini & Drug Use " RAY,H B. Southern Cahlornia Edison Co. 88/11/14 -9pp 47874 148-47874 154
- -8812210091 Rev 1 to General Administrative Procedure 50123-XV-0.0, Triness for
- Southern Cefiforn.a Edison Co. 86/11/14, 12pp. 47874-165 47874,160
- -8812210096 Temporary Change Notice TCN 1-2 to Rov 1 to General Admin. stud vn Procedure SO123-XV-7 0. Drug Tosting Program for Protected Area Accuss * Southern California Edison Co. 86/11/14 16pp. 47874 169 47874.190
- ~8812210165 Tomporary Change Notice TCN 1-3 to Rov 1 to General Administrative Procedure SO123-XV-7.0, 'Drug Tosting Program for Protected Area Access 'Southern California Edison Co 88/03/18, 2pp. 47874;167-47874.168
- 8812210265 Forwards results of analysis done for 16 EFP7 of operation for rear for vessel malls.pdr Rev 2 to Reg Guide 1.99 & Gonoric Ltr 88-11 Changes reliect use of location-specific fluonces in reavaluating adjusted ref tempe MEDFORD.M.O. Southern California Edison Co. 88/12/16 Document Central Brench (Document Control Desk). 3pp. 47875-216-47875-217.

- Q. Inspection reports, If Dullotins & Correspondence
- 0811200025 Lowends Jusp Hepto 50 206769 2650 361760 27 & 50 guto 2, 20 No dals con es en shout no rodul YUHAS,GP Rogeo S, Olicol Be Dientia #0711710 HASsigs p. Si ada Ed son Co. Zpp. 47651 098 47651 099
- -8811200032 to p. Hopto 50 206/06 26/50 30176037 & 5136/769 2 26 No. deforms on its violations rotted Minjor indust lings (Sebagon) disaing 1007 one to 8 among my preparadius a necessary states, COODG M., 115-1161. IATOM, E. Hopeo 5, Ok. of the Distance 47651 090 47651 099.
- 80 (121022) The position could be of CT. Owners Group offer to a RECONSTRUCT TO THE TWO COUNTY TO A STATE OF THE COUNTY TH
- 00 11300211 NBC bits Motor 88 090, "Unautionzed Removit et act Changes Tax estimat CHRIMING HAMELL Divides of Industrial & Medical Nacion Saley RD744725 Concat Industrial Octool Now York (et., 190p) 3770-755
- 80.1110.0467 NRC Info Notes on 00.001, Tempropor Administrator of Research Control (Control Operational Evolute Assessment (Lor) 870-6 Control Lated Lettern Co. of Nov. York, hep-10.1pp 47700-012-4775-14
- 00 11300422 Ack account of 081114 fit enforming NFIC of steps 14: 613 (c.
- noted othop Bright 91 200700 23 YOHAS GEP Reging 5, Ok. of the Director #0711721 DASSNEED Si-ted Edison Co., Up. 47674 157 47674 363
- 80 1215 0 133 Feerwards SALP Bound Bepts 50 (2017/03/95) 36 (2017/13/6-8) for poins FCC 1390 Z Sept 1290 Plood Techns rovering broads seed as a consequence of all theory of the eigenvalum maked MARTIN THE RESIDENCE SEED OF A 1470 20 (60) 100 Proceedings of the Object of 100 Procedure 100 Ptg 1376 PASS NRCP SEED OF CONTRACT OF A 1470 20 (60)
- 8812380141 (SATE Freps) 50 286798 2550 36770 26 & 50 2577 124 Sign 1989 Cdb gory 1 we good to mean of indoorge decoase 4 & con * They ex 5, Cd. of the 1866 Cd. 1897 (1725) 3700 47020 324 4760 (170
- forca Ede on Co. App. 470 (1066-476 O 072)
- 68.12.150.150 Mgr. Necotory. Repto. 50. 2007/00.33,59 36.1705 M. A. 50. 103.10; Major nicos discressed estima of curroll interest regis it. 160.77, 11. 104.03.5 (1).244. Region 5, Ofc. of the Director, 20/11/21.
- 8812200087 Towards Toep Hepts 50 200709 2750 301705 70 & 93-IMO 13 1304 No verticues rested MICC on compass 21 to net pleas 6 prose 6 toward o pertit Cytolionication par iM322 registre (sep ZROM IMARTHE Theyon 6, 30, of the Drestor 100712703 1985) in Casteria Edward Co. 2pp. 47004 251 47664 253
- 8612200090 http://fepti. 50.200709 2750 361789 29.8. 50.50 7778 5.114 Yo. Shitaboos, reduct Major attent to type fed. Methylast 2 to the form of plant layer A menuto review of OA mater 8 coverbances 8 Lot 2 CALSYST 11 C.W., ROBERONETH, Respons 5, Olic of the Discrete 8.9 47604 235 47604 224.
- 8811290030 feBC total teacon broken. Telathicapy Events "Escribero E CHPPEREADAMERT Division of Industrial & Mode at thicker StCy 00717702 | Consolidated Edmon Collot New York, Inc. 117ys 47813
- 88 11200518 Nett Colo Rote o 66 014, "Potentially Understand Yalve A.S. ROSSTET - University of Operational Events Assessment (15st 870). Consulatated Little Co. of New York, Inc., 124pp. 47700 14 147703 25
- \$612060128 Houses too for BL5802 in plantament inscrive o BCD scored
- to the 1 per RH (OF request 34) 13 (10 A) 34 (10 A) 34 (10 A) (10 A) 4 (10
- 8812120185 Contains 1804-13 mpt mont og w/m3 in RosensestCA trick Ck 1 (mr. Soja 1900 per 1811 (mr. Econ Molico of medico extricte RULLA HTT). Trigger 5, Or chitho Date for 1807/2705 (MSS.N.K.F. S. 468 F discon Co. 7(p) 47789 015 47788 016
- 8812120188 Basto atom of BB1213 meeting white in Hoseneed CA11 de CA1 1607 Popt 1923 -KBP A3131 Begrow 5, Object Bio Checker (89712705 (Region 5, Object Bio Checker) (89712705 (Region 5, Object Bi
- 8812020287 RRC Info Nos in Bit GPS, "finadon and Procurement Register.

 By Licenseus on Verifiers", Syc. 13C on L.

 ROYS, CCL. Decision of Operational Events. Assurament (Post 6764
 Considerate Filteria Co. of New York, Inc., 117pp. 47607 101 47637 20
- 6812210065 Section part at response to FCHA request for recordings PROCESS T. December 1. Landon of Internation 8. Pub (4):43-43. 8(05):23. 80712714. PARTICIPAT ARLation Not Assigned 259, 47674. Pier a contanaya & Larg

- 8812200163 Monthly operating rept for New 1988 for San Onofre Neclear Generating Station Unit 1.W/881215 ftr MORGAN,H.E. Southern California Edison Co. 88/11/30 7pp 47864 270 47864 276
- 8812220126 Forwards Oct 1988 monthly NFOES ropt summary for facilities. No purmit violations noted at Unit 3 during reporting period.
 MORGAN,HE Southern Cattornia Edison Co. 88/12/12. Document Control Branch (Document Control Desk), 3pp. 47902 358-47902:360

S. Reportable occurrences, LERs & related correspondence

- 8811300176 PNO-V-88-062 on -881119, parthquake occurred 30 miles west of San Clomente, CA Earthquake felt by personnel in Unit 1 control room & no seismrc Instru-mentation alarms received. Licensee found no damage after visual resp of Unit 1. JOHNSON,P., HUEY,R Region 5, Ofc of the Director 88/11/21. 1p. 47678/046-47678 D46
- 8812080321 LER 88-008-01 on 880524 nadvertent om sslor af safety injection vent valves from local loak rate testing program. Caused by valves associated w/pongitation E15 omitted from local loak rate testing program.W/881129 ltr. MORGAN,H.E. Southern California Edison Co. 88/11/29, 7pp. 47743-102-47743 107
- 8812070265 PNS-V-88-007.on 881130,sonior resident informed of possible lampering events Caused by cleaning person not bring able to completely secure associated valving after work activities. Enhanced walkdown performed.

 SCHUSTER.M., MCQUEEN,A Region 5, Old of the Director 88/12/01 2pp 47740.228-47749.229
- 8812130280 LER 87-017-01 on 871201, remotely operated, normally closed, containment isolation valves in vent line did not close upon demand upon completion of venting of Loop B header. Seate of valves found worn & weight Valves replaced W/481205 tit MORGAN, ILE. Southern California Edison Ca. 88/12/05 Gpp. 47795 351-47795 356
- 8812130290 LER 88-004-01:on 880215,bonnet bleed off solenold valve SV-3903,for safety injection isolation valve HV-8518,failed to open Caused by crack in sleeve in which valve disc moves on opening.W/881205 ltr. MORGAN,H.E. Southern Cellfornia Edison Co. 88/12/05 7pp. 47798 204-47788 210.
- 8812140055 PNS-V-88-007A on 881201,actuation elem received from reactor contant pump fire protection deluge sys at Unit 2. Caused by contract watchman who deciled any literal to cause damage to plant Two watchman terminated SCHUSTER,M.D. Region 5. Ofc of the Director 88/12/07. 1p. 47803.320-47800.329
- 8812210410 LER 88-015-00 on 881114, performance of local loakingu rate tests (LLRT) on 880720 at below required pressure discovered Caused by cognitive personnel error Assessment of LLRT procedure will be performed W7801214 ltr MORGAN,H.E. Southern California Edison Co. 88/12/14, 5pp. 47890-162-47880-166

V. Operator Examinations

- 8812140090 Forwards revised agenda for annual operator licensing meeting on 800110.W/o encl. PATE,R.J. Region 5, Ofc of the Director. 88/12/05 REEDER,J Southern Carifornia
- Edison Co. 1p. 47790:140-47706:149.
- 8812160227 Ack receipt of 881021 ffr re-expiration of senior operator license for position of Unit 1 plant superintendent Requests Identification of Individuals & titles at all titres units responsible for threeling activities of licensed operators. KNIGHTON,G.W. Project Directorate V. 88/12/08 BASKIN,K P. Southorn Californ.a Edison Co. COTTON,G.D. San Diego Gas & Electric Co. 5pp. 47825-056-47825-060.

DOCKET 60-213 HADDAM NECK PLANT

F. Security, medical, emergency & fire protection plans

- 6811290219 Forwards "CRDR Summary Ropt," por Suppl 1 to NUREG-0737 & NRC 860812 Issuance of roy to 840612 order. Human engineering discrepancy corrections scheduled for four consecutive retueling outages beginning w/early 1991 outage MROCZKA,E.J. Nonnecticut Yankop Atomic Pawer Co. MRIOCZKA,E.J. Northeast Utilities. 88/10/31. Document Control Branch (Document Control Disk) 3pp. 47648-240-47849-18. 47649:157
- 8811220324 Forwards Insp. Rept 50-213/88-20 on 881014-16 No violations noted BELLAMY,R.R. Region 1, Old of the Director, 88/11/10, MROCZKA,E.J. Connecticut Yankee Atomic Power Co. 2pp. 47641.184-47641:172.
- -8811230010 Insp Rept 50-213/88-20 on 881014-16.No violations deviations or unresolved items noted. Major areas inspected emergency proparedness exercise conducted on 881014-16. AMATO.C.G., LAZARUS,W.J. Region 1, Ofc of the Director, 88/11/08, 7pp. 47641:166-47641:172.
- 8811300298 Forwards Safeguards Insp Riopts 50-213/68-21,50-245/68-22, 50-336/88-25 & 50-423/68-21 on 661017-21.No violations noted. BELLAMY,R.R. Region 1, Off. of the Director. 86/11/15 MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utildlos). 2pp. 47676:019-47676-024
- --8811300298 Physical Security Insp Repts 50-213/88-21,50-245/88-22, 50-336/88-25 & 50-423/88-21 on 881017-21.No noncompliance noted Major areas inspected safeguerds into program corporate ofcs LANCASTER,W.K. Region 1, Otc of the Director 88/11/15 4pp 47678-021-2879-021 47678.024.
- 8811300024 Revised emergency plan implementing procedures, including Rev 8 to EPIP 1.5-11, "Personnel Injuries" & Rev 7 to EPIP 1.5-42, "Manager of Operational Support MILLER,H.B. Connecticut Yankee Atomic Power Co. 88/11/23, 18pp. 47702 023-47702 040

- 8811300072 Forwards response to SALP Rept 50-213787-99.NRC will be contacted re producting presontation at Regen trofes prior to 1983 returning A maint outsign till will continue to pursue positive in falling in all "stud areas MROCZKA,E.J. Connecticut Yankog Atomic Power Co. MROCZKA,E.J. Noitheast Utilinias. 88/11/23. Document Control Branch (Document Control Dask). 12:pp. 47697 069 47697 080
- 8812020125 Informs NRC that flow 18 to emergency plan implemented which refincts changes to emergency action level tables & corrects editional emergency action level tables & corrects editional emergency action. Changes
 Changes
 Changes
 Changes
 Connecticut Yenkou Atomic Power Co MRONZKA,E J Northeast Utilities 88/11/28 Document Control Branch (Document Control Desk) 2pp 47716 312-
- 8812090209 Roy 18 to "Commercial Yankoo Emergency Plan" WGOD,C.L. Commercial Yankoo Atomic Power Co. 88/11/29 106pp. 47799.001-
- 8812140181 Revised energency plan implementing procedures, consisting of Rev 5 to EPIP 1.5-17, "Emergency Equipment" & Rev 4 to EPIP 1.5-43, "Personnet Radiation Exposure Control During Nuclear Emergencies." MCCANEE.W T. RROWN, R.E., NERICCIO, M.W. Connecticut Yarkee Atomic Power Co., 88/11/30, 18pp. 47800 140-4780.157
- 8812120039 Forwards Insp. Rept. 50/213/88/19 on 880928-1115.No violations noted Plant configurers has not mel integrated leak rate test acceptance orteins in as found configurers than not mel integrated leak rate test acceptance orteins in as found confinion ifuring two most recent lesis, as noted in Detail 10 of end upt BETTENHAUSERIL. Region 1 of 20 of the Director 8A/12/02 MHOCZKA,E.J. Connecticut Yankun Atoriic Power Co. 2pp. 47780/198 47780.215
- ~8812120041 hisp Hopt 50-213/89-19 on 880928-1115 No violations mitted. Major areas inspected plant operations, radiation protection, fire protection, security, maint, surveillance testing, I consee ovents & containment integrated test rept.

 MCCARE, E.C. Region 1, Otc. of the Director, 88712701, 16pp. 47780 200-47780 215.
- 8812090214 Forwards Amend 109 to License DPR-61 8 safety evaluation Amend revises Table 3.22-2, "Fire Delection Instruments," reducing available smoke delectors in containment from 23 to 22.

 WANIS, A.B. Project Directorate 1.4, 8#712/06 MROCZKA,E.J. Connecticut Yankos Atomic Power Co. 2pp. 47785.040.47785.049.
- -8812090216 Amend 109 to Licenso CPB-61 revising Table 3.22-2. Fire Detection Instruments" to reduce number of smoke detectors available in containment from 23 to 22 & Incorporating now suction of spirithful protection into Tech Spec 3 22G STOL 2, J.F. Project Directorate I-4, 88/12/06, 5pp. 47785,042-47785,046
- -9812090218 Saluty ovahidium supporting Amund 109 to Licenso DPR-61
 * Office of Nucleur Reactor Regulation, Director (Post 870411) 88/12/06 3pp
 47785 047-47785 049
- 8812220042 Informs of annual emergency preparedness exercise scheduled for wk of 800326 0401 (primary wk) 8 800402 08 (Bitarnative wk) Utidentands that FEMA will not evaluate any offsite partic pation in exercise Exercise objectives end MFIOCZKA,E.F., SEARS.C.F. Connucted Yaukee Atomic Power Co. MRIOCZKA,E.F., Northreast Utilities 88/12/14. Document Control Branch (Document Control Dask) 4pp. 47892-229-47802-232.

H. General correspondence

8812010055 Comment supporting proposed rule 10CFR26 to filness-tor-duty program MROCZKA,E.J. Northoast Utilities MROCZKA,E.J. Northoast Nuclear Energy Co. (subs., of Northoast Utilities) MROCZKA,E.J. Northoast Nuclear Energy Co. 88/11/21, CHILK,S.J. Office of the Secretary of the Commission. 9pp. 47679-046 47679.054.

P. Operating license stage documents & correspondence

- 8811290219 Forwards "CRDR Summary Rept," per Suppl 1 to NUREG-0737 & NRC BITZPUZTB FORWARDS "CHOLK Summary Hopt," per Suppl 1 to NUREG-0737 & NRC 680812 issuance of rev to 840812 order Human ong nearing discripancy corrections scheduled for four consecutive reliabiling outages beginning w/early 1991 outage MROCZKA,E.J. Connecticit Yankoo Atomic Povor Co MROCZKA,E.J. Northeast Utilines 88/10/31. Document Control Branch (Document Control Besk). 3pp. 47649:240-47649:157.
- -8811290222 "CRDR Summary Rept," por Suppl 1 to NUREG-0737.
 * Connecticut Yankoe Atomic Power Co. 88/10/31, 275pp. 47648:243-47649.157.
- 8811300093 Forwards Rev 1 to "Radiological Effuent Monitoring & Offsite Dose Calculation Manual & Process Control Program," for NRC approval Changes in liquid radiwaste treatment include required use of portable dominicalizer Fee paid MROCZKA,E.J. Connocicieut Yankee Atomic Power Co. MROCZKA,E.J. Connocicieut Yankee Atomic Power Co. MROCZKA,E.J. Northeast Utilities. 88/11/10. Document Control Branch (Document Control Dusk). 7pp. 47697:081-47697:191 47697:113
- ~8812060041 Rev 1 to "Radiological Effluent Monitoring & Offsite Dose Calculation Manual & Process Control Program"

 * Connecticut Yankee Atomic Power Co. 89/01/31, 26pp. 47697.088-47697-113.
- 8811280048 Ganeric Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities to individual plant exem for severe accident vulnorabilities Svc list
- CRUTCHFIELD, D Associate Director for Projects (Post 870411) 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729 024
- 8812070075 Forwards response to 881021 request for addlinto re Tech Spec changes 8120/00/3 Promitted Response to 881021 request for denote the 3-3 specifications for Genote Life 83-37. MROCZKA E.J. Northoast Utilities 88/12/02. Document Control Branch (Document Control Dosk) 16pp 47746 114-47746.129.

- 8813060369 Requests that or ladders Geron. Lth 68:17 relioss of DhR during non-power operator issue of high priority should be addressed accordingly burke 2716 Order of Notes Residon Registeron Director (Post 870411) | 68/12/ 02 ECLISIV 3 Normals United Sign 47157 008 47157 010
- 8812090214 Forwards Americ 109 to Excess CPR 61-8 safety evaluation. Amend re-vises Table 3.222. File Detection instruments, reducing available smoke detectors vises Table 3.222. File Detection instruments, reducing available smoke detectors vises Table 3722. The basecon instruments, reducing available smoking detectors in containment for 2010-22. In containment for 2010-22. 4 58/12/06 IMPOCZKAIE J. Connecticul Yankee Atomic Power Co. 200-47195 C43-47195 049.

- ■812090216 Amord 165 to Exercise CPR 61 revising Table 3.22-2 1Fine Detection in struments' to record number of smalle detectors available in containment from 23 to 22.8 incorporating revisional synik in protection into Tech Spec 3.226 STCLZ J.F. Project Disectivate 14. 8at 12/36. Spc. 47785.042-47785.046
- -8812090218 Salety exalter on supporting Amend 109 to License DPR-61
 Ofice of Notice Reactor Regulation, Director (Post 870411) 88/12/06 3pp
 47785 047-47785 049
- 8812130273 Forwards requests for 809 into the reactor protection sys lupgrade,per 881306 (according to the content) scheduled for while 1890213 MRDCZKA,E J. Connecticut Yankee MADCA B Project Orecovars 1.4 8412/08 MRDCZKA,E J. Connecticut Yankee Atom: Power Co. 8pp. 47798 219 47786 226

Q. Inspection reports, IE Bulletins & correspondence

- 8811180299 Parts FRA Applications Program for Insp. at Haddam Neck Nuclear
- 811180299 PARIA FINA APPRICATIONS PROGRET FOR INSPIRE HADdam (Neck Nuclear Power Station I del Trepl GREGG R.E. WERGHIJRE EG3G Maho, Inc. (8-bs. of EG8G, Inc.). GREGG/R.E. GREGG R.E. WERGHIJRE EG3G MAHO, Inc. (8-bs. of EG8G, Inc.). GREGG/R.E. HADO NUTIONE PROGRETOR LABORATOR EGG REO 7601 DRFT 87/03/31, NRC No Deta ed Affiliation Grien. 47pp. 47537 203-47597 249
- 8811290027 Chart as schedule for completion of thems but 8 d of IE Bulliotin 65:003 &
- 811290027 Clarins schedule dis completion of nems but & digit IE Butchin 65:003 & submission of nativests (sen fiper discussors w/NRC MROCZKA EU Northoast NumROCZKA EU Connectod Yakoe A Mono Foakin Co-MROCZKA, EU Northoast NumBoczka, EU Northoast Chullest MROCZKA, EU Northoast C
- 8811220324 Formards krop Rest: \$5-213/88 20 on Ba1014-16 No violations includ BELLANY R.R. Regon 1, Old of the Director 88/11/10 MROCZKA,E.J. Connecticut MELLAMI II II PERSON I ON OF LIE OFFICE BOTTO STATE YEAR AND PERSON PORT CO 200 47641 154-47641.172
- 8811230010 This Rich 50 213/88-20 on 881014-16 No violations deviations or unre-schied tems roted Major areas inspected emergency preparedness exercise conduct-ed on 881014-16. AZARUS W.J. Region 1. Cfs. of the Director. 88/11/08. 7pp. 4/7641-166-4/7641-172. _8811230010 hsp Rept 50.213/88-20 on 881014-16 No violations, deviations or unre
- 8811300298 Forwards Safeguards in sp. Repts 50 210/88 21,50-245/88-22, 50-339/89-25.8 50-323/88-21 on 88/017-21 No violations noted 25.8 50-323/88-21 on 88/017-21 No violations noted BELLAMY RR Pagon 1, Oct. of the Orector 88/11/1/5 MROCZKA, E.J. Northboast Nuclear Energy Co. (sucs. of Northboast UUT ea). 2pp. 47678-019-47678-024
- -9811390298 Physical Securn into Repris 50:213/88 21,50:245/88 22, 50:338/88 25 8 50:423/88 21 on 681017/21 No noncompliance noted Major areas inspected separation program organia of cs. Inspected separation program organia of cs. LACASTER M.K. CAMERON D.F., KE MIG.R.R. Region 1, Otc of the Director, 687 11/15 4pp 47678/021 47678/024
- 8811160211 NRC into Notes 68,090, Unauthorized Removal of Industrial Nuclear
- Gauges" Sicils' ex! Gauges" Sicils' ex! CUIA NOHAM RE Dassot of inclisinal & Medical Nuclear Salety (Post 870729) 82111/22 Consekdated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257
- 8811160467 NAC Into Notice 98 091, "Improper Administration & Control of Psychologi-
- partipover Substituto" ca Tests Substituto ROSSICE: Division of Operatoral Even's Assessment (Post 870411) 88/11/22. Consolidated Essor Co. cliniar York, Inc. 101pp 47/08/042-47703.142.
- 8811300072 Forwards response to SALP Rept 50-213/87-99 NRC will be contacted re
- 8811300072 Forwards response to SALP Hept 50-213/87-99 NRC will be contected re preordage presentation at Region forces prior to 1993 refueling & maint outlage Util will continue to pursus post we in taiwes in till listed eries MROCZAKE J. Contection Britishe Mother Grower Co. MROCZAKE J. Northeast Lin-des 88/11/23. Document Control Branch (Occument Control Desk). 12pp. 47697-369-47637-089.
- 8811290030 NRC this Notice 86-093. TigleIngrapy Events III Svic list encl.
 CLN-LNCHAM RE Division of Industrial & Medical Nuclear Safety (Post 870729).
 88/12/02 Consoldrad Edsen Colid New York, Inc. 112pp. 47811.103-47811.215
- 8811290538 NRC Info Notice 88 594, "Potentally Undersized Valve Actuators." Svc Lst
- enci ROSSICE Ovision of Operational Events Assessment (Post 870411). 68/12/02 Consistated Edison Co. of New York, Inc. 121pp. 47708:143 47768 254
- 8812060277 Informs that sother's peckage developed to improve surveillance tracking in response to Irap Rept 50 213/63.03 no longer in use at plant Administrative procedure describing surveillness higher registed.

 MROCZAGE Mothess Michael Register (Subsider of Northeast Utilities), MROCZAGE I Northeast Michael Serveillness (Document Control Branch (Document MROCZAGE) Northeast Wildle Serveillness (Document Control Branch (Document MROCZAGE) Northeast May 12 (1992).

Control Desk) 2pp. 47743 041-47743 042

- 8812120039 Forwards Insp. Rept. 50-213/68 IB on 880928-1115 No violations neto-Part companyment has not mot indegrated feak table lost acceptance criteria in as-found condition during the most recent lests as rolled in Delail 10 of encil rept. BETTENHAUSEN L. Region 1, Otc of the Director. 83/12/02. MROCZKA E. J. Connector Yarkee Attentic Power Co. 2pp. 47760-198-47760-215.
- -8812120041 Irisp Per: 50.213/88-19 on 660928-1115 No violations noted. Major great inspected ghan operations varieties in protection, fine protection, security mant server area to string censee events & containment integrated leak rate to 31 opt. IEBN 18-8 1931 Pagion 1, Ofc of the Director 88/12/01, 16pp. 47780:200-47780:215.

- 8812150014 Forwards Safety Impg Rept 50-213780-22 on IRBT107 to No Isolations
- GALLO,R.M. Region 1, Ofci of the Director 18712/06 MRICCZKA,E.J. Connectical Yanker Atomic Power Co. 2pp. 47873-216-47873-223
- 47873 218 47873 223
- 8812020287 NRC Info Notice 88 095, "Inadequate Propresent Proposed by Leansess on Vendos," Sec 1st and ROSSIC E. Division of Operational Events Assessment (Post 870411), 88712708 Consolidated Edison Co. of New York, Inc. 112pp. 47807,191-47807,392
- 8812220179 Forwards SALP Rept 50 213/87/90 for Apr 1987 Jul 1988 Plant operated safety & conserval voly during period Unit 88 1123 ft. his of attendrius for 88 1027 SALP mgt meeting & Witchest 88 1003 ft to Elmocika also unct. RUSSELL Will Tieggen 1. Onco of the Onects 1847/12/89 MRCX2XA,Fig. Commedicat Yankes Atomic Power Co. 2pp. 47914.088 47914.124

R. Periodic operating reports & related correspondence

- 8812060036 Forwards Bimonthly Progress Flopt 13,por innifor intestions schedule for const of new switchgear brug at facility MROCZKA,E.J. Connecticul Yankee Attance Power Co. MRCCZKA,E.J. Northeast Un-tes 88/14/30. Document Control Branch (Document Control Desk). 6pp. 47743-079 47743-084
- 8812190255 Monthly operating rept for Nov 1989 for Haildein Newk Plant, W7881215 WALLIKIC, MILLER,DIB Connectical Yackero Attentio Power Co. BB/117/30 - 10pp. 47860-018-47880-025

S. Reportable occurrences, LERs & related correspondence

8812130118 LER 88-048-02 on 861284 overpressure protection systed of valves opened lebwing inadvertient prossure spike in RCS. Critisant by inadequate operation of motor operated die in valve Procoduse used for set pro 47795 338-47795-342

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

- F. Security, medical, emergency & fire protection plans
- 8812090194 Forwards Insp. Repl. 59:219708-32 on 8810477-21 & notice of violation Actions taken to violations noted in 871210 & 880205 litre volutional by inspec-
 - BELLAMY, R.R., Region, 1, Otc. of the Director, 80/11728, FTLZPATHICK, E. General Public Usities Corp. GPU Service Corp. 2pp. 47775 097-47775 105
- -8812090200 Insp. Rept. 50-219/88-32 on 0810+17-21 Violation motest Major areas inspected mgt support, security program plann, motine, protocled its vital area physical barriers, access control, detection 8 assessment adaptioning 8 mount 8 power supply KEMS, RR, SMITR, GC, SYLVESTER, E.O. Region 1, Old of the Director 88/11/28 Epp. 47775-100-47775-105.
- 8812010250 Forwards Emergency Operating Procedure Imap 11cpt 50 210769-200 on 880908-15 linsp verified that procedures technically correct 8 conformed to owners group guidelines. Safaty significando tem rolconte minent veniting motivit.
 VARGA,SIA. Division of Reactor Projects - 1/11 (Post 1970411) 1887/11/29
 FITZPATRICK,E. General Public Utili es Corp. - GPU Servico Corp. - 8pp. 47/09/348-
- -8812010252 Insp. Rept 50 219768-200 on 880906-15 Delicionación noted. Major areas Inspected Iconser program for Imprementing emergency operating procedures.pd. NUTEG 0737,Suppl 1 GUTHR'S. WECHSELBERGER, LEW.D. Devision of Reactor Inspection & Sale-guards (Post 870411) 88/11/23, 34pp. 47/03 356-47710 020
- 8812090295 Advisos that 800517 Rev 25 to physical security plan consistent w/pto-P1299295 Advisus that bodot increase or physical states, market signs of 10CFR50 540) & acceptable BELLAMY,R.R. Region 1, Otc of the Director, 88711729, FITZPATRICK,E. General Public Utilities Corp. - GPU Service Corp. 3pp. 47785 056-47785 058.
- 8812150157 Forwards Roy 27 to security plan & summary of changes flow withhold (ref. 100FR73.21).
 FITZPATRICK,E. General Public Uthres Corp. GPU Service Corp. 88/12/09. Document Control Branch (Document Control Desk).
- 8812200024 Revised emergency plan implementing procedures including flow 1 to 0473-AOM-1319.04,Rev 7 to 9473-ADM-1319.01,Rev 5 to 9473-IMP-1300-26 & Rev 6 to 9473-IMP-1300-02. BARTON, J.J. General Public Utilities Corp. - GPU Service Corp. 88/12/12. Document Control Branch (Document Control Dask), USpp. 47862 319 47863 046

H. General correspondence

8812010400 Commont opposing proposed rule 10CFH26 to random drug tosting MUNYAN,R.A. International Brotherhood of Electrical Workers 88711718. Dockobing & Services Branch. 2pp. 47679 207-47679 208.

P. Operating license stage documents & correspondence

- 8811280111 Forwards into rollsosmic response spectraliper 881012 request, including digitalized power spectral density computed from time history WILSCN, R.F. General Public Uniteds Corp. GPU Service Corp. 88/11/14 Document Control Dask). 70pp. 47655;270-47655;341
- 8812010178 Notification of 881214 meeting w/util in Rockville,MD to discuss licensing ections at plants
 HERNAN R.W. Project Directorate I-4, 88/11/22 STOL2,J.F. Project Directorate I-4, 48P.417/22 STOL2,J.F. Project Directorate I-4, 88/11/22 STOL2,J.F. Project Directorate I-4, 88P.417/23 STOL2,J.F. Project Directorate I-4, 88P.417/22 STOL2,J.F.
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities to individual plant exam for severe accident vulnerabilities Svc tist
 - CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 86/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729-024.
- 6812010141 Summary of 881110 meeting w/util in Rockville,MD to status of facility liconsing notions DROMERICICA W. Project Directorate 1-4 88/11/23 Project Directorate 1-4, 15pp. 47699 313-47699.327
- 8812020262 Application for amount to License DPH-16, consisting of Toch Spec Change Request 178,8 lowing rod scram time testing to be performed while shuldown & re-irroving high reactor pressure isolation furnition from isolation condensors Fee paid FTZPATRICK,E. General Public Utilities Corp. GPU Service Corp. 88/11730. Office of Nuclear Reactor Regulation, Director (Post 870411). 9pp. 47718.279-47718-269.
- --8812020263 Proposed Tech Specs allowing rod scrann time testing to be portormed while shuldown 8 removing high reactor pressure isolation function from isolation condensers when reactor head removed or unbolled

 * General Public Utilities Corp. GPU Service Corp. 88/11/30 2pp 47718-288-
- 8812130283 Forwards notice of consideration of Issuance of amend to License DPR-16 & proposed NSHC dutermination & opportunity for hearing re 881130 request to delete requirement in Tech Spec Table 3.1.1.A 6 DROMERICK,A W. Project Directorate 1-4, 88/12/07, FITZPATRICK,E. General Public Unities Corp. GPU Service Corp. 2pp. 47797/098-47707/098.
- -- CB12130289 Notice of consideration of Issuance of amond to License DPR-16 & proposed NSHC determination & opportunity for linearing Amend deletes Tech Spec Table 3.1.1 A 6 for low condensor vacuum scram & rovines Table 3.1.1.C 1. DROMEHICK, A.W. Project Directorate 1-4, 88/12/07, 9pp. 47797-086-47797-086
- 8812160166 Forwards corrected Tech Spec Page 3 1-8 to 881130 Tech Spec Charge Request 178 for requirements while in shutdown made. Symbols for "greater than or inqual to" or "less than or equal to" inadventantly emitted in trip setting column F172PATHICK,E. General Public Utilities Corp. GPU Service Corp. 88/12/12 Document Centrol Branch (Document Centrol Desk). 2pp. 47624-085-47824-087.
- -6812150173 Corrected proposed Tech Spac Page 3.1-8,consisting of Table 3.1.1, "Protective Instrumentation Regularments."

 * General Public Ulrities Corp. GPU Service Corp. 88/12/12 1p. 47824-087-
- 47824.087

Q. Inspection reports, IE Bulletins & correspondence

47718 289

- 8812010039 Documents completion of tests & evaluations regulad to ment IE Bulletin 85-003 & provides required into specified in 861028 ltr rol motor-operated valve falures.
 FIEDLER, P.R. Genoral Public Utilities Corp. - GPU Sorvice Cr
 KANE, W.F. Rogron 1, Old of the Director, 10pp, 47702 237-47702 247. - GPU Servicu Corp. 88/01/15
- 8812010019 Advisos that submittal of fastoner tosting info will be completed by 880226.Delay discussed w/Region I personnel FEDLERP.B. General Public Utilities Corp. GPU Service Corp. 88/01/29. RUSSELL,W.T. Region I, Ole of the Director. 2pp. 47702 304-47702 305.
- 8812010022 Responds to NRC Bulletin 88:006, "Actions to be Taken for Transportation of Model SPEC 2-T Radiographic Exposure Device." Util does not possess any radiographic exposure devices All radiographic exposure devices All radiographic exposure devices All radiography at lacitity portionmed by contractor. FITZPATRICK,E. General Public Utilities Corp. GPU Sorvice Corp. 88/07/20. RUSSELL,W.T. Region 1, Oic of the Director. 1p. 47703:189-47703:189.
- 6811160211 NRC Info Notice 68-090, "Unauthorized Removal of Industrial Nuclear
- Gauges." Svc list unct CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Salety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257.
- 8811180467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests" Svc list end, Psychological Tests "Svc list end, Possion of Operational Events Assessment (Post 870411), 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.
- 8812090194 Forwards Insp. Right 50:219/88:32 on 881017-21 & notice of violation Actions taken re-violations noted in 871230 & 880205 lins verified by inspec-
 - BELLAMY, R.R. Region 1, Ofc of the Director, 88/11/28, FiTZPATRICK, E. General Public Utilities Corp. GPU Service Corp., 2pp. 47775/097-47775:105.
- --8812090197 Notice of violation from Insp on 881017-21. Violation noted: failure to submit rept on description of change to protected area intrusion detection sys.
 Region 1, Ofc of the Director. 88/11/28, 1p. 47775,099-47775,099.
- --8812090200 Insp Rept 50-219/88:32 on 881017:21.Violation noted Major areas Inspected mgt support, security program plans, audits, protected & vital area physical barriers, access control, detection & assessment alds, testing & maint & power supply. KEIMIG.R.R., SMITH.G.C., SYLVESTER, E.D. Region 1, Ofc of the Director. 88/11/28. 6pp. 47775:100-47775:105.
- 8812010260 Forwards Emergency Operating Procedure Insp Rept 50-219/88-200 on 880806-15 Insp verified that procedures technically correct & conformed to owners group guidelines Safety significance flem re-containment vonting noted. VARGA, S.A. Division of Reactor Projects I/II (Post 870411). 88/11/29. FITZPATRICK,E. General Public Utilities Corp. GPU Service Corp. 8pp. 47709:348-47710-92. 47710:029

- -8812010252 Insp Rept 53:219788-200 on 880906-15 Deliciencies noted. Major areas Inspected ficures or program for implementing emorganicy operating procedures per NUHEG-0737, Supplia GUTTIFIES, WECHSELBERGER, LEW.D. Division of Reactor Inspector & Safe guards (Post 870411) 88/11/23 34pp. 47709.356-47710.029.
- 8812060303 Forwards Insp Rept 50-219/88-31 on 881003-07.20 & 1031-1104 & not.cc of wolation Weaknesses also identified in air sampling & analysis program. 8ELLAMY.R.R. Region 1, Oto of the Director, 88/11/30, FRZPATRICK,E. Genera Public Utilios Corp. GPU Sorvice Corp. 2pp. 47752-164-47752-183.
- ~8812060304 Notice of violation from insp on 881003-07,20 & 1031-1104. Violations noted two workers performed work in contaminated area w/o prior survey of contami Reg on 1, Old of the Director 88/11/30, 2pp. 47752,166,47752 167.
- --8812060307 Insp. Rept. 50-219/88-31 on 881003-07,20 & 1031-1104. Violations noted Major areas inspected status of outstanding items, red-ological controls reliable 12F rollieting outage & roviow of circumstances concerning radicactive spit incident. GEYERA, SHERBINI, S. SHANBAKY, M.M. Region 1, Ofc of the Director, 88/11/29 16pp. 47752-168-47752-183.
- 8811290030 NRC Info Notice 88 083, "Totalherapy Evants." Svc list encl CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Salaty (Past 870729) 88/12/02 Consolklated Edison Ca. of New York, Inc. 112pp 47811.103.47811:215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc Tst ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708.143-47708.254.
- 8812020287 NRC Info Notice 88-095, "Inadequato Procurement Requirements Imposed by Dephases on Vondors" Svo list end. ROSSLCE Division of Opporational Events Assessment (Post 870411). 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807.181-47807-302
- 8812230035 Forwards request for addition to bill response to IE Buildin 85:003, "Motor-Operated Valve Commun Made Fallures During Plant Trensions Due to Improper Switch Seltings." Response requested within 30 days BETTENHAUSENL Region 1. Oto of the Director 88/12/08. FITZPATRICK,E General Public Unities Corp. GPU Service Corp. 3pp. 47911:018-47911.020.
- 8812210240 Forwards response to live restart concerns identified during safety sys-outage most insp.Two itoms.Including setpoint availation of sampling of instrument toops.will require substantial enginocating offort WILSON.It.F. Goneral Public Utilities Corp. GPU Service Corp. 88/12/12. Document Control Branch (Document Control Doss) 9pp. 47907:054-47907:062.

R. Periodic operating reports & related correspondence

- 8812210048 "Fishkill Monitoring at Oyster Creek Nuclear Generating Station on 881108-10" W7881208 In: FIT2PATRICK,E. General Public Utilities Corp. GPU Service Corp. 88/11/10. 11pp. 47889.001-47889.011
- 8812080042 Forwards somiannual update of project list per Amend 122 to License LONG,Fi.L. General Public Utilities Corp. - GPU Service Corp. 88/12/02. Document Control Branch (Document Control Dosk). 17pp. 47783-208-47783-224.

S. Reportable occurrences, LERs & related correspondence

- 8811290114 LER 89 026-00 on 881019 reactor scram signal received while shut down during surverlence testing Caused by inadequate procedure Procedure will be revised & LER will be made required reading for all qualified reviewers W/981117 It. GAYLEY.R.B. FIT2PATRICK,E. General Public Utilities Corp. GPU Service Corp. 88/ 11/17, 5pp. 47851 297-47651 301.
- 8811290557 LER 88-027-00 on 881022, fire watch required by Tech Specs missed due to Inadequate guidance to temporary employees. Caused by Inadequate guidance & direction being provided to temporary contractor employees W 11/21, 6pp. 47662 217-47662:222.
- 8811290561 LER 86-029-00:on 881024,containment isolation valves V-36-9, 10,16,17,22 & 23 fallod to most NUREG-0737 dosign criterion. Caused by personnel error.Mod of subj valvos planned. W/881121 ltr. CERVENKA,P., FIZPATRICK,E. General Public Utilities Corp. GPU Service Corp. 88/11/21. 4pp. 47662:213-47662 216.
- 8812150058 LER 88-030-00 on 881108,both doors of temporary alriock erected to sup-port isolation condenser A maint may have been open for 6.5 h while manway open Caused by inadequate preparation & review of maint package W/881207 ltr. GAYLEY,R B_FITZPATRICK,E_General Public Util.tiles Corp. GPU Service Corp. 88/
- 12/07. 5pp. 47825.023-47825.027. 8812210109 LER 80-020-01:on 880808,discovered that isolation condenser & emergen-cy svc water radiation monitors incapable of leak datection due to design deliciency. Caused by failure to properly evaluate radiation conditions. W/881215 ltr. GREGG,B.R., FITZPATRICK,E. General Public Utilitios Corp. - GPU Service Corp. 88/ 12/15. 6pp. 47901:224-47901:229.
- 8812210365 Forwards results of analyses, review & evaluations of isolation condensor steaming & diesel generator cable faults connected w/880929 shutdown & 881002 loss of vital electrical bus. FITZPATRICK,E. General Public Utilities Corp. GPU Service Corp. 88/12/15. Office of Nuclear Reactor Regulation, Director (Post 870411), 3pp. 47874:219-47874:308
- --8812270141 Rev 0 to Technical Data Rept TDR 950, "Oyster Creek Isolation Con-denser Performanco,Aug. Sept 1988." SMITH.P.S., DEMPSEY,T.M. General Public Utilities Corp. GPU Service Corp. TDF 950 R00. 88/12/05. 84pp. 47874 222.47874:308.

8812270260 Special Rept 88.01 on 881116 nonlinctional traid each pump 1.2 not re-stried to functional status within 7 Cays at required per Toch Spec 3.12.8 Delay due to constraints imposed by increased maint activates. FITZPATRICKE, General Public Unities Cept. GPJ, Service Corp. 88/12/16. Docu-ment Control Branch (Document Control Dost), 2pp. 47926.276.47926.277

DOCKET 50-220 HINE MILE POINT NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811260504 Forwards Insp Repis 50 220/68/30 & 50 410/85/29 on 680926 30 No vin lators noted EBI-ETER S.D. Reyon, 1, Oto. of the Director, 86/11/18, MANGAN,C.V. Nagara Worlawk Power Corp. 2pp, 47662-258-47682-249
- -8811290510 insp. Repts 50-220788-30 & 50-410768-29 on 896926-30 No violations noted Major areas inspected security plan & procedures mgt. noted Major areas inspected security plan & procedules in groups and organization audits records & repristesting & maint barriers security power supply & assessment aids TOB:INW J. CAMERON D.F., KEIWG, R.R. Region 1, Old of the Ovector 88/11/16 10pp 47E82 240-47662 249
- 8812090792 Advises that 880524 Rev 5 to physical accordy plan consistent w/provi sions of 1005R50 54(p) & acceptable BELLAMY P.R. Region 1, Ofc. of the Director, 887(11/29 MANGAN,C.V. Magera Mohawk Power Corp. 4pp. 47784 345-47784 349

P. Operating license stage documents & correspondence

- 8811230285 Application for amend to License DPR-63,changing bases for Tech Spucs 3.3.7 & 4.3.7 to update method used to verify that drywell & lorus spray inocata nimed spray systined from obstructions TERRY,C.D. Augura Wohawk. Power Corp. 88/11/21. Document Control Branch (Document Control Dosk). 1p. 47652-066-47652-067.
- -8812010174 Proposed Tech Specs,changing bases for Sections 3.3.7 & 4.3.7 in conterment spray sys
 * Niagara Mohawk Power Corp. 88/11/21, 1p. 47652 067-47652 067
- 8811290185 Provides summary of results of technical analysis for facility in response to Generic Litr 88-11,dtd 850712 & proposed schedule for updating Tech Specs pres-Buratremp Lmils TERRY C D. Niagara, Mohawk, Power, Corp., 88/11/22, Document, Control, Branch (Document Control Desk), 2pp. 47858-332-47958-333
- 8812070205 Requirist schedular exemption from requirements of 10CFR50 App U.Socrion I.I for four RCS isolation valves, specifically front requirement to perform leakage testing of shutdown cooling sys suction 8 return line isolation valves Fee
 - paid BURKHAROT,C Nagara Mohawk Power Corp. 88/11/22 Document Control Branch (Document Control Desk). 11pp. 47748.300.47748.310
- 88.1128.0048 Generic Ltr 88.20 to all incensees holding OLs & CPs for nuclear power reactor facilities ne individual plant examilior severe accident vulnerabilities Svic Est
- CRUTCHFIELD.O Associate Director for Projects (Post 870411) 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024
- 8812010256 Forwards Amend 102 to Licenso DPR-63 & safety cya'uation. Amend revises. Tech. Spec. 6.2 to make Table 6.2-1 consistent writing rements of 10CFR50.54(m)[2](i) & 6.2.2 o to clarify staffing required during hot shutdown. HAUGHEY,M.F. Project. Directorate 1.1.887/11/29. MANGAN,C.V. Nagara Moltawk. Power Corp. 2pp. 17700.043.47700.050.
- -88120102\$8 Amend 102 to License DPR-63,revising Tech Spec 6.2 to make Table 6.2-1 consistent w/requirements of 10CFR50.54(m)(2)() & 6.2.2 etio clarify staffing required during toold shutdown & rothering CAPRA,R A Project Directorate I-1, 88/11/29 4pp 47700.045-47700.045.
- -8812010280 Satery evaluation supporting Amend 102 to License DPR-63 'Office of Nuclear Reactor Regulation, Director (Post 870411) 88/11/29, 2pp. 4700.049 47700.050,
- 8812190204 Forwards carculations containing into reflective 125 volt dic sys design.per 881123 request Calculations determine cable size for 125 volt dic teeder cables to Powerboards 16.8.17.

 TERRY/C.D. Niagara Mohawk Power Corp. 88/12/08. Document Control Branch (Document Control Dask) 52pp. 47852.041.47652.032.
- 8812130219 Natification of 681220 meeting w/util in Rockville,MD to discuss inservice test program
 HAUGHEY,M.F. Project Directorate I-1. 88/12/09. CAPRA,R.A. Project Directorate I-1. 2004 A7792 103 47792 104

Q. Inspection reports, IE Bulletins & correspondence

- 8811300464 Responds to IE Bute'in 80-13 re core spray spargers & associated internal piping During 1988 refueling & maint outage re-oxam indicated that crack length remains within followed on other part of the Christin reported on 840531. TERRY, C.D. Nagara Mohawk Power Corp. 88/05/16. RUSSELL,W.T. Region 1, Occ. 11 to Christian 1, 17230-358,17270-358. of the Director 1p 47670 358-47670 358
- \$811300147 Forwards Meeping Rept 50:220/88:33 on 881027 Meeting beneficial in understanding unit action plan & sassonals for program DURRJ, Hegion 1, Oft of the Director, 88/11/14 MANGAN,C V. Niagera Mohakk Power Corp. 2pp 47671:240-47671.264
- ~8811300150 Meeting Rept 50:220/68-33 on 881027 Major areas discussed inservice has activities viewgraphs encl MCBREARTY R.A. STROSNIDER J.R. Region 1. Ofc of the Director 88/11/04. 23pp.

- 8811290504 Forwards Insp. Repts 59/220786-30 & 50/410766-29 on 856-326-56-95.
- Pacors noted
 EBN-STER,SID: Region 1, Otc. of the Director PBV11/In MANGAR, CV 5, Mchawl Power Corp. Spp. 47662 (28), 47662 (28)
- -8811290510 Irsp Rupts 50 220769 30 & 50 419788 29 on 0/00/26 35 No. 30 BBT129051D in sp. number of vertex in records a majorited seconds plan in a provide a configuration and the records a repliciesting a manufactures continuing power of the second second second plan in the provided second second plan in the provided second sessmont at 85 and 100 and 100
- 8811160211 NAC Jolo Notice 68 090, "Heranthroused Reconstal of Indice of Na. Gauges' Svc ist unch CUNNINGHAM R.E. Draston of Industrial & Medical Nucline Safety (Fold who). OUNTAINDMAN, IS C. DIASON IN MICH. HILL & GOVERN CONTROL OF THE CO
- 8811160467 NRC into Notice 88 031, "Improper Administration & Control of Eq. (1977) cal Tests "Sectional Rossical Edward Co. of New York, Inc. 101pp. 47708.042.47703.142
- 8811290448 Summary of 861117 numbing whold to Learned following a loos standing systematic step of facility. HAUGHEY,M.F. Project Directorale 41, 8il711723 Project Directorate 11, 4 p. 47651:207-47651.252
- -8811030125 Provides summary of significant findings to advisero of ling Finding (*) 80-201,so that appropriate contective actions to a feet included into reshot plus particles (see each of a must be resolved before systematical operation lists of VARGAS A Divisor of Reactor Propries 1711 (Post 870411) (16705); MANGARIC V Body Ira Mohaws Power Corp. 4 pp. 47651 (219-47651 252)
- 881*290030 NRC Into Notice H8 093, "Telephorepy Executed Sevential point COUNTINGHAM, FLE Disaston of Industrial & Medical Nucleur Safety (Front Nature 89/12/02, Consolidated Europe Carlot New York, Inc., 112:ep., 476.11
- 8811290538 NRC info Notice 89 094, "Potentially Uniforsize I Valvo Action to all teats and ROSSI,C.E. Division of Operational Eventh Assessment (Post (I70411) (Fuzz) / Consotrated Edison Co. of New York, Inc. 121pp. 4770(1143-4770) 254
- 8812070141 Forwards GE-ROE 13 0507, "Scram Volva Displacego Collines of Society Poet University per tesp. Roots 50 220766 19 & 39 40776 42 Emphragio repl. To estail CRD hydrau're control unsterraminted & cut'et virtue, con placted TERRY, CO. Niegard Mahawk Poets Corp. 88772702 (ALLO, RV. Co. Linux et C. Se Branch (Document Control Desk). 1p. 47746 143-47746 234
- -812070146 Scran Valor Displingin Fallutes at Som Mile Point Unit. CHARNEY, E. GIBO, E.Y. KLAPPROTE, F.C. Corneral Charles, Co. Rel. 13, 16327-427, 07710, Uspp. 47748-144-47746-234.
- 8812090303 Flesponds to NRC 880915 fir m violations noted in Insp Repts 50 2.5%
- 8812020287 NRC hito Nolico 89 095, "finallequata Procurement Hard aremonts to policy by Uconseos on Vendors." Such stienel. ROSSIGE. Distern of Operational Create Assessment (Part 1970111) and Consolidated Edison Co. of New York, fac. 112pp. 47897.191. 47697.392
- -8812270162 Insp. Repts. 50-220788-19. 8, 50-410788-18 on 881004-1117. Col. 1-6 noted Major, groups inspected operations an incompany admitted intensylvation groups allowed by sys well-downed ER reviews, Part 21 rept rowow & alterpartons JOHNSON, J.A. Rogion 1, Olic of the Director, 88/12/15, 22pp. 4/92/ 160-4/92/ 161

S. Reportable occurrences, LERs & related correspondence

- 8812010139 LER 88-019-00 on 881026 loservico testrop program (IS1) test in tractione w/ASME Section XI resulting in Tech Spac violation Causart by mighenites of ness 8 inadequate review of IS1 program Corrective actions planned W/88112415 PASTERNAK B. WILLES J.L. Nagara Mohawk Power Corp 88/11/23 5c: 47703.168
- 8812010199 Part 21 rept to defect in GE Type 180 and cating type maters behalfy excited on 881027 NSSS,inc identified as firm supplying component Maters will not be a lineared for use in safety related applications pointing posolution.

 BURKHARDT,I. Nagara Mohawk Power Corp. 88711723. RRISSELL, W.T. Heg on 1. Ote of the Oxector. 3pp. 47707:146-47707:148
- 8812080319 Special rept on 881101.work on 3 h ruted ponetrations in tachine bid jish completed within Tech Spec Limit & work on two floor drawing also not completed with Tech Spec time Limit.

 WILLIS,JL. Nagara Mohawk Power Corp. 88/12/01. Document Control Hranch (fixiument Control Desk). 3pp. 47734 157-47734,150.
- 8812070118 Summary of Operating Reactors Events Meeting 88-47 on #81129 Eet of attendoes, events discussed & significant elements of events, two events suggested to long sum followup & summary of reactor scrams enect LANNING.W 0. Events Assessment Branch. 88/12/01 FD/SGLC F. Dustion of Operational Events Assessment (Post 8/0411), 14pp. 47747-093-47747-106
- 8812210110 LER 88-008-01:on 880317,transversu in core prober httrogen supply 1/31 board & outboard isolation valvos tailed local loak rate fast Caused by film on 30-3 sea Occurrence repl written & work request generated W/881215 Its MAZZAFERROP A, WILLIS, J. Niagara Mohawk Power Corp (88/12/15 5/4 47888 110-47883 114.

19

Univ of, Lowe'l, MA 2pp. 47664.006-47664.007

V. Operator Examinations

8811290359 Advises that readministration of reactor operator exam scheduled for 881205 Requirements for facility review of exam encl ESELGROTH,PW. Region 1, Olc of the Director, 88/11/23. BEGHIAN,L.E. Lowell,

DOCKET 50-224 UNIV. OF CALIFORNIA RESEARCH REACTOR

G. Adjudicatory correspondence

8812020135 Joint motion for dismissal of hearing procedure.* Requests that Board accept 881121 settlement agreement & Apps A & B, dismiss hearing procedure & teturn request for amend to License R-101 to NRC for further processing.

GELB,M Berke'ey, CA, PIGOTT,D.R. California, Univ. of, Berkeley, CA. PIGOTT,D.R. Ornck, Herrington & Sutcliffe. #488 7571 88/11/21. Atomic Safety and Licensing Board Panet. 4pp. 47844:158-47644-312.

-8812020141 Settlement agreement.* Agreement made & entered into on 881121 between intervenor & licensee to 880108 application for amond to License R-101 re decommissioning & removal of reactor. Related documentation & Certificate of Svc encl GELB.M. Borkeley, CA. KING,C J. California, Univ. of, Berkeley, CA. 68/11/21, 151pp. 47844:162-47644:312.

8812190059 NRC Staff response in support of joint motion for dismissal of hearing procodures. Board urgod to dismiss proceeding based on settlement between univ & city of Berkoley Notice of appearance & Certificate of Svc encl. HODGDON A.P. Assistant General Coursel for Hearings. #488 7636, 88/12/07. Atomic Safety and Licensing Board Panel. 5pp. 47802:168-47802:160

P. Operating license stage documents & correspondence

8812050104 Forwards request for addl Info re 881010 application for amend to Licenso R-101.Response requested within 30 days ADAMS.A. Standardization & Non-Power Reactor Project Directorate 88/11/30. FOWLER,T.K. California, Univ. of, Berkeley, CA. 4pp. 47733:349-47733:352.

8812200137 Responds to requests for addl info re proposed Amend 6 to License R-101.Revised proposed amend and. LIMT.H. California, Univ. of, Berkeley, CA. 88/12/08. ADAMS,A. Document Control Branch (Document Control Desk). 6pp. 47871-042-47871-047.

8812200186 Requests addl Info re application for decommissioning & termination of Li-cense R-101, including blank fast flux measurements. ADAMSA. Division of Reactor Projects | II,IV.V & Special Projects (Post 870411) | 887 12/14. FOWLER,T.K. California, Univ. of, Borkeloy, CA. Bpp. 47864:294-47864:301

V. Operator Examinations

8812140133 Forwards revised agenda for annual operating licensing moeting on 890110.W/o enci. PATE, R.J. Region 5, Otc of the Director, 88/12/05, LIM, T. California, Univ. of, Berkeley, CA. 1p. 47800:360-47800:360.

DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR

V. Operator Examinations

8612140147 Forwards revised agenda for annual operator licensing meeting scheduled

PATE,R.J. Region 5, Otc of the Director, 88/12/05, LAMB,I. Aerotest Operations, Inc. 1p. 47800:174-47800:174.

DOCKET 60-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8812210174 Rov 5 to Emergency Plan Implementing Procedure EPIP 200-2, "Classifica-tion & Responses to Incident Involving Oil or Hazardous Matt (Primary Responsibility-station Practor)." Station Director)

Commonwealth Edison Co. 88/12/13, 16pp. 47880:195-47880:210

8812210205 Rev 14 to Emergency Plan Implementing Procedure EPIP 300-1, "Initial Notifications & GSEP Responses."

* Commonwealth Edison Co. 88/12/13, 23pp. 47875:015-47876.037.

P. Operating license stage documents & correspondence

8811300450 Forwards corrected Tech Space pages summary of changes & description of proposed amend request for plant.

8811280048 Genoric Ltr 88:20 to all liconsoos holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities. Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 8704.1.1) 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.

8811300087 Forwards safety evaluation accepting util response to Generic Ltr 83-28,ttem 2 1,Part 2, "Vendor Interface Program," for reactor trip sys components. SIEGEL,B. Project Directorate III-2 88/11/23 BLISS,H.E. Commonwealth Edison Co 4pp. 47695-343-47695-349

-8811300092 Safety evaluation accepting util response to Generic Lir 83-28, from 2.1 (Part 2) in vendor interface program for reactor trip sys components. Afficial Afficiation General 311/23, 3pp. 47995-347-47895-349.

8812010129 Discusses interim operating restrictions to preclude regional neutron flux instabilities Listed restrictions will remain in effect until further study 8/or revised recommendations rosolive industry & staff concerns
SILADY, J.A. Commonwealth Edison Co. 88/11/23 MURLEY, T.E. Office of Nuclear
Reactor Regulation, Director (Post 870411). 2pp. 47698 294-47698:295.

8812010305 Provides analysis of Reg Guide 1.99,Rov 2, "Radiation Embrittlement of Roactor Vessel Matis" for Impact on pressure-temp freatup & cooldown curves contained in Tech Specs,per Generic Ltr 88-11

RICHTER,M11. Commonwealth Edison Co. 88/11/28, Document Control Branch (Document Control Desk) 2pp 47703.049-47703.050.

8812160056 Provides MSIV design evaluation third progress rept. Sargent & Lundy porsonnel prosently onsite to review affects of MSIV control sysichanges on existing station procedures Next progress rept will be provided by 890201.

SILADY, JA Commonwealth Edison Co. 88/12/01. DAVIS, A.B. Region 3, Ofc. of the Director 2pp. 47830.354-47830:355.

8812200014 Requests review of BWR Owners Group position prior to requiring commit-ment to replace analog transmittor frip units circuit boards. SILADY_JA. Commonwealth Edison Co. 88/12/15 MURLEY.T.E Office of Nuclear Reactor Regulation, Director (Post 870411) 2pp. 47862:198-47862:199

Q. Inspection reports, IE Bulletins & correspondence

8811160211 NRC Info Not'co 88.090, "Unauthorized Removal of Industrial Nuclear Gaugus" Svc Iss enct CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Sefety (Post 670729) 88/11/22 Consolidated Edison Co of New York, Inc. 90pp. 47708.255-47708.267.

8811180467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Tosts." Svc list end ROSSI,C.E. Ovision of Opurational Events Assessment (Past 870411), 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042 47708 142.

8812010171 Forwards Safety Insp. Ropts 50-237/88-22 & 50-249/88-23 on 880910-1122 Np violations noted

CLAYTON,B Regkin 3, Ote of the Director, 88/11/25 REED,C. Commonwealth
Edison Co. 2pp. 47707:111-47707.132

-8812010175 Safety Insp Repty 50:237/88-22 & 50:240/88-23 on 880910-1122.No vio-lations noted Major areas inspected TMI action plan requirements, operational safety verification, to lowup of events & monthly man observation RING,M A. Region 3, Oic of the Director, 88/11/25, 30pp. 47707:113-47707.132.

8811290030 NRC Info Notice 88:003, "Telothorapy Events." Svc List and CUNNINGHAM,R.E. Division of Industrial & Madical Nuclear Sularly (Post 870729); 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:216 8811290538 NRC Info Notice 88-094, "Potentially Unidersized Valve Actuators." Svc list

ROSSI,C E. Division of Operational Eventa Assessment (Post 870411), 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp 47708.143.47708:254.

8812020287 NRC into Notice 88-995, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" "Svc list and ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/09. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.

R. Periodic operating reports & related correspondence

6612190416 Monthly operating repts for Nov 1988 for Drosdon Units 2 & 3 W/861201 MAXWELL,D.C., EENIGENBURG,E Commonwealth Edison Co. 88/11/30. 41pp. 47860:061-47860:101.

9. Reportable occurrences, LERs & related correspondence

8812010151 I.ER 88-017-00 on 881029,HPCI sys made inoperable to facilitate preventa-tive maint HPCI turbine overspood turbine trip testing Caused by Intentional station ingl decision to portion subj tosting Further testing planned W/88 I 128 Irt. GEIGER.J., EENIGENBURG,E. Commonwealth Edison Co. 88/11/28. 4pp. 47702:248-47702:251.

8812060031 LER 88-018-00 on 881030,leak rate limits exceeded in drywell head seal Caused by improper sealing of outer gasket due to deficient installation procedure.On 881103,discovered that MSIV 2-203-1D exceeded leakage limits.W/881129 ltr. JOHNSON, R.H., EENIGENBURG,E. Commonwealth Edison Co. 88/11/29. 8pp.

47744 287-47744 294

- 8812150250 LER 68 021-00 on 631113 standby gas treatment sijs automatically in tated which the 29 dearlighted Gaused by its time of bits 29 main feed breaker to close 8 tailed feed breaker asklagy tortaet Swith cleaned W/661212 III.
 BIHLMANT 6. ERNIGENBURG E. Commonwealth. Edison. Co. 88/12/12. 7pp. 47825 204 47826 418.
- 8812210280 LER 88 022 00 on 681114 fourth & fillh drywell elevations experienced ex-cessing temps during previous operating cycle. Caused by procedure deficiency Procedures will be revised to ensure that hatches left open during LICHNISCHIER LEGISLATURGES. CARREST CARROLL CO. 894(2)(12) 2800 JOHNSON, A. H. EEN. GENBURGE Commonwealth Edison Co. 88/12/13 28pp

DOCKET 50-243 OREGON STATE UNIV. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8811290448 D.scusses rept of changes to Diegon State Univ TRIGA reactor emergency response plan which do not decrease effectiveness of plan per 10CFR50 54(q). "Revs to Emergency Response Plan 8 implementing Procedures" encl. DNHSON 4 G. Oregon State Univ. Conjatis. OR. 68/11/21. Document Control Branch (Document Control Desk). 4pp. 47665 016-47665 019.

V. Operator Examinations

8812140085 Forwards revised agenda for annual operator ficensing meeting on PATERJ Region 5, Orc of the Director, 88/12/65 ANDERSON,T Oregon State Univ., Corval.s, OR 10, 47796 107-47196 107.

DOCKET 50-244 ROBERT EMMET GIRNA NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812080209 Forwards Insp Rept 50-244/68-21 on 891018-20 No violations noted BELLAMY, R.R. Region 1, O'c of the Director, 88/11/28, MECREDY, R.C. Rochester Gas & Electric Corp. 2pp. 47783-153-47763-160
- -8812080212 Insp Rept 50:244/68-21 on 981018-20 No violations deviations or unre-solved riems noted Major areas inspected emergency proparedness exercise conduct-ed on 881018-20 AMATO,C.G. LAZAR 47783-155-47783-160 LAZARUS,W.J. Region 1, Otc of the Oxector. 86/11/28 Spp.
- 8812150075 Forwards Safety Insp Repi 50:244/88-22 on 881017-1120 & notice of violation
 BETTENHAUSEN,L. Region 1, O'c of the Director 88/12/07 MECREDY,R. Rochaster Gas & Electric Corp. 2pp. 47833 052-47833 065
- -8812150080 Insp Rept 50-244/88-22 on 681017-1120 Violations noted Major argas inspected station story besincluding operational safety verification, plant operations, surveil ance testing, maintradiological protection & physical security. COWGILL, C.J. Region 1, Otc of the Osseciol. 88/12/07. 11pp. 47833 055-47833.065

H. General correspondence

8812010410 Comments supporting proposed rule 10CFR25 re Fitness for Duty Program is substance abuse tirges Commission to adopt suggested specific changes indicated by NUMARC comments. SHRDUDER.W.J. SMITH.R.E. Rochester Gas & Efectric Corp. 88/11/21. CHILK.S.J. Office of the Secretary of the Commission. 4pp. 47679 255.47679.258.

K. Utility Final Safety Analysis Report (FSAR) & amends

8812190248 Rev 4 to updated FSAR for RE Ginna Nuclear Power Plant W/ 881218 ltr.
MECREDY,R C Rochester Gas & Electric Corp. 88112/31. STAHLE,C. NRC · No Detailed Attitistion Given. 500pp. 47846 162-47848 249.

P. Operating license stage documents & correspondence

- 8811290226 Forwards proprietary Adder.da 2-P to CEN.320 P. "Steam Generator Tuba Repair Using Leak Tight Steaves" for review to establish use of peripheral steaves Rept withheld (ref 10CFR2.790(b)[4]) MECREDY.R.C. Rochester Ges & Electric Corp. 68/11/18. STAHLE,C. Project Direc-torals 1-1, 5pp. 47668-070-47669-074
- 8811290531 Forwards application for amend to License DPR-18 re required boric actd storage tank level per mods to safety injection pump recirculation flows & application 1898
 SMITH,R.E. Rochester Gas & Electric Corp. 88/11/21, STAHLE,C. Document Control Branch (Document Control Desk). 1p. 47650-172-47650-184.
- -8811290536 Application for amend to Dicense OPR-18 changing Tech Specs to obtain mode to safety killection pump recitational flows Fee paid SMITH.R.E. Rochester Gas & Electric Corp. 88/11/21, 3pp. 47650.173-47650:175.
- -8811290539 Proposed Tech Specs 3.2 & 3.3,establishing consistency between specs & segured boric acid storage tank level resulting from mode to sately injection pump * Rochester Gas & Electric Corp 88/11/21, 9pp 47850:176-47850:184
- 8811280048 Genenc Ltr 88-20 to all licensees holding Dts 8 CPs for nuclear power reactor facilities to individual plant exam for severe accident vulnerabilities Svc field
- enci.
 CRUTCHFIELD.D. Associate Orector for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729.024.

- 8812010088 Forwards documentation to technical support ciri.operational support ciri.operational supports on NUREG-0737, Items III.A 1.2.8 WECREDY, R.C. Rochester Gas & Electic Corp. 88711723 | STARLE, C. NRC tailed Affic
- 8812870183 Advises that all saleby-related structures affected by new designoundwater level change reanalyzed & acceptable MECREDY, R.C. Rochester Gas & Electric Corp. 68/11/23 STAHLE, C. NRC tailed Affiliation Given. 1p. 47746 687-47746 667
- 8812060320 Informs that licensee contracted Westinghouse to provide technifor response to Generic Lin 88.11.5 information respond by 890122 Generic uses implementation of Reg Guida 1.99
 MECREDY RC Rochester Gas & Electric Corp. 88711729 STATILE, C. Control Branch (Document Control Dask). 1p. 47741.063-47741.063
- 8812070218 Forwards application for amend to Liconse DPR-18, modifying root of RHR pump & safety injection pump surveillance tests following mode to choulation tiows Fee paid SMITH, E. Rochester Gas & Electric Cosp 88/11/29 STATILE, G. NRC No Aff-lation Given. 1p. 47747-156-47747-190
- -8812070222 Application for amond to Figures DPH-16, changing Tech Spocs requirements for RHR pump 8 safety infaction pump surveillance tests SMITH, R.E. Rochester Gas & Electric Corp. 88/11/29, 2pp. 47747:157-4774
- -8812070225 Proposed Tech Specs, medifying requirements for RHR plimp & Jection pump surveillance tests
 * Rochester Gas & Electric Corp. 88/11/29, 12pp 47747,150-47747,199.
- 8812050259 Advisos that 881012 response to request for additinto re-steam peoplery steaving program self-control for NRC to conclude that program selved adequate data on newly proposed periphery sleaving STAHLEC Project Directorate 1-3 887 (2/01. MECREDY, R.C. Rochester Gallice Corp. 3pp. 47734:173-47734:175
- 8812128226 Requests that will address Generic Ur 88-17 to toss of OHR dupower operation Ur issued due to potentially scrous consequences resulting adequecy of industry response to Generic Ur 87-12 MURICEYTE Office of Nuclear Reactor Regulation, Oractor (Post 870411 02 BRIGGS,P. Rochester Gas & Electric Corp. 3pp. 47788.110.47789.112
- 8812130190 Not fication of 881214 meeting whitel in Rockvilla,MD to discuss shuctural upgrada program. STAHLE,C. Project Directorate 1:3: 88/12/09: WESSMAN,R 11: Project Direc
- 2pp. 47794:111-47794.112 8812220017 Requests withdrawal of 840119 application for amond to Licons in P-10 Interlock & pressurizer level flowing request will be automated in in SMITHRE Rechester Gas & Electure Corp. 801/27/2 STAHLE, C. Office of Reactor Regulation, Director (Post 870411) 1p. 47003 036-47903 036

- 8811290047 Forwards responses to NRC Bulletin 87-001 re thinning of pipe wicker power plants ANSI 31.1 Code remains an current analysis bases for a formed on safety related piping.

 KOBERRY Rochester Gas 8 Electric Corp. 87709708. RUSSELL,W.T. Ofc of the Director. 75pp. 47663 283 47663 357.
- 8811300299 Notification of significant licensed meeting on 881122 in King of 6 to discuss IPAT inspite long form Improvement program. COWGILL CJ. Region 1, Oto of the Director 88/11/15 Region 1, Oto of the 2pp. 47674:168-47674:169.
 - 6811160211 NRC Into Natice 68 090, "Unauthorized Ramoval of Industria Gauges "Sec list enct CUMN NGHAM,R.E. Division of Industrial & Modical Nuctors Soluty (Post 88/11/22, Consolidated Edison Co. of Now York, Inc. 99pp. 47708.255-477(
- 8811180467 NRC Into Notice 88 091, "Improper Administration & Control of Pical Tests." Svc fist encl. POSSLC E. Division of Operational Events Assassinant (Post 870411). Conso Jeted Edison Co. of New York, Inc. 101pp. 47708 042-47708:142.
- 8811290093 Informs that recent NRC insplot records belonging to Plan Systing of Mount Vernorul, Indicated util purchased Class 1E components. WESSMAN.H.P. Project Directorate 13, 88/11/23. SM(TH,R. Rechoster Gildic Corp 5pp 47649:199-47649:203
- 8812080209 Forwards insp. Rept 50-244/88-21 on 881018-20 No violations no 8ELLAMY,R.R. Region 1, Old of the Director, 88/11/28 MECHEDY,R.C. Ges & Electric Corp. 2pp. 47783-153 47783-160.
- ~8812080212 Insp Rept 60-244/89.21 on 881018.20 No violations,treviation solved litems noted Mejor areas inspected enlargency proparadiness exercised on 881018.20.

 AMATO.C.G., LAZARIUS.W.J. Region I, Dic of the Director, 88/11 47783:155-47793:160.
- 8812080155 Forwards Safoty Insp. Repl. 50 244/88-23 on 8B1024-27.No noted Concerns Membred the controls applied to storage & handling of email's at plant Response requested within 30 days.
 GALLO,R.M. Region 1, Otc of the Director. 88/11/30. MECREDY,R.C. Roc & Electric Corp. 3pp. 47756-347-47756:358.
- ~8812080168 Insp. Rept. 50.244/88-23 on 881024-27.No violations noted. A imspected receipt storage & handling of equipment & mails. DEV.M. BLUVBERG,N. Region 1, Old of the Director. 88/11/28. 9pp. 4776-26.
- 8811290030 NRC Info Notice 88-893, "Telethorapy Events" Svc list encl. CUNNINGHAM,R E. Division of Industrial & Modical Nuclear Safety (Pot 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-

21

- 8811290538 NRC Into Notice 88-094, "Potortially Undersized Valve Actuators" Syc list
 - ROSSI,C E. Division of Operational Events Assessment (Post 870411) 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708.143-47708.254.
- 8812160075 Forwards Safety Insp Rept 50-244/88-22 on 081017-1120 & notice of vio-
 - BETTENHAUSEN, Region 1, Old of the Director 88/12/07 MECREDY,R. Rochester Ges & Electric Corp. 2pp. 47633-052-47833-065.
- -8812159077 Notice of violation from insp. on 881017-1120 Violation noted mod to change to condensate storage tank,described in Chapter 10 of updated FSAR as main source of water for auxiliary feedwards sys,installed w/o safety evaluation. * Region 1, Ofc of the Director 88/12/07, 1p, 47833.054-47803.054.
- -8812150080 Insp Rept 50-244/88-22 on 881017-1120 Violations noted Major areas
- operations, surveillance testing, maint radiological protection & physical security COWGILL, C.J. Region 1, Otc of the Orector 88/12/07, 11pp 47833.055-47833.085.
- 8812020287 NRC Into Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" Svc list and ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807 191-47807 392
- 8812230082 Forwards request for addf into re-util response to IE Buttelin 85:003, "Motor-Operated Valve Common Mode Falures During Plant Transients Due to Improper Switch Settings." Info requested within 30 days. BETTENHAUSENL. Region 1, Ofc of the Director. 88/12/08 MECREDY,R C Rochester Ges & Electric Corp. 3pp. 47811-021-47911-023.
- R. Periodic operating reports & related correspondence
- 8812190387 Monthly operating rept for Nov 1988 for RE Ginna Nuclear Power Plant W/ MCNAMARA, A.E., MECREDY, R.C. Rochoster Gas & Electric Corp. 88/11/30, 5pp 47850 237-47850 241.
- S. Reportable occurrences, LERs & related correspondence
- 8811300201 Special reption 870630 & 0713,potential problems wifire dicers due to several small door skin spot wold fractures identified Caused by inability of hydraulic door closer to control door operation (Doors repaired KOBER,R.W. Rochester Gas & Electric Corp. 87/10/05, RUSSELL,W.T. Region 1, Old of the Director, 3pp. 47676 019-47676.021.
- 8811300527 Special reption 881018,furbine driven auxiliary feuriwater pump inoporable per Procedure A-52.4 Existing check valve toakage indicated by higher than ambient temp in turbine driven auxiliary loodwater discharge piping MECREDY,R.C. Rochester Gas & Electric Corp. 88/11/23. RUSSELL,W.T. Region 1, Ofc of the Director. 2pp. 47876:178-47678. 178.

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8811300296 Forwards Sateguards Insp Ropts 50-213/88-21,50-245/88-22, 50 336/88-25 & 50-423/88-21 on 891017-21, No violations noted BELLAMY,R.R. Region 1, Oto of the Director 89711/15, MROCZKA,E J. Northeast Utilifies) 2pp 47678.019-47678.024.
- -8811300298 Physical Security Insp Ropts 50:213/88-21,50:245/88-22, 50:336/88-25 & 50-423/88-21 on 881017-21.No inoncomprished noted Major sines inspected setogeards info program corporate ofcs.

 LANCASTER,W.K. Region 1, Otc of the Director 88/11/15. 4pp. 47678/021-
- 8811300493 Forwards Insp Rept 50-245/88-17 on 880830-1017. No violations noted Mgt attention to correct inconsistent treatment of emergency svc water sys as ESF & as
 - OA Catogory I sys requested.

 BETTENHAUSEN,L. Region 1, Otc of the Director. 88/11/23. MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Unifices). 2pp. 47674:170-47674:185.
- -8811300495 Insp. Rept. 50-245/88-17 on 880830-1017.No violations noted. Major areas inspected praviously identified items plant operations physical security.loss of emergency six water sys & loss of standby gas treatment systems. AccASE,E.C. Region 1, Otc of the Director. 88/11/18. 14pp. 47674.172-47674:185.
- 8811280068 "Millstone Nuclear Power Station Emergency Response Exercise, Nov 1988 Northeast Nuclear Energy Co. (subs. of Northeast Utritios). 88/11/30. 395pp.
- 47858.052-47659:056.
- 8812070178 Rev 13 to Emergency Plan Implementing Procedure EPIP-4304, "Emergency Response Fecilities Operating Instructions" SCACE.S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 88/12/01. 35pp. 47745:288-47745:332.

H. General correspondence

47678 024

- 8812010055 Comment supporting proposed rule 10CFR26 re fitness-for-duty program. MROCZKA,E.J. Northeast Utilities. MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA,E.J. Connecticut Yankee Atomic Power Co. 88/11/21. CHILK,S.J. Office of the Secretary of the Commission. 9pp. 47679.046-43670.054 47879 054.
- P. Operating license stage documents & correspondence
- 8811290215 Discusses arrangements made for disposal of deformed low level radwaste liner from facility.

- 8811280048 Generic Ltr 88-20 to all Licensees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnerabilities.Svc list CAUTCHFIELD.D. Associate Director for Projects (Post 870411), 88711/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729 024.
- 8812070078 Responds to 881116 request for additinfo re spant fuel pool capacity oxpansion Evaluation of resultant gaps & retinement of setsmic displacement analysis performed to reconcre as-fabricated condition.W/revised modulo layout & add Info MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA,E J Northeast Utilities 88/12/02, Document Control Branch (Document Control Desk) 8pp 47745.254.
- 8812120063 Application for amend to License DPR-21,revising Tech Specs to reflect implementation of mode in degrated grid protection for Class 1E power sys Fee paid. MROCZKA,E.J., SEARS,C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA,E.J. Northeast Utilities) MROCZKA,E.J. Northeast Utilities, MROCZKA,E.J. Northeast Utilities, MROCZKA,E.J. Northeast Utilities, MROCZKA,E.J. Northeast Utilities 1897/12/02 Document Control Branch (Document Control Desk.). 6pp. 47785-163-47785-163.
- --8812120064 Proposed Tech Specs,providing for new limiting conditions for operation, survo liance requirements & nominal selpoints for new 4160 volt bus undervoltage/limiting relay input circuits & loss of-normal power actuation circuits mods. Northeast Utilities 88/12/31 15pp 47785 169-47785.183
- 8812140004 Advises that util plan to install new spant five racks,per 881202 submittal of addl into acceptable Proposod data of 881209 for issuance of safety evaluation for Phase 2 of const cannot be supported due to tatenass of submittal STOLZJ.F. Project Directorate 1-4 88112708 MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utililas). 3pp. 47798-353-47798-355.
- 8812120214 Forwards Rev 1 to "Radiological Efficient Monitoring & Offsite Doso Calculation Manual & Process Control Program." Attachment 1 provides data led list of proposed changes for NRC approval Fee paid.

 MROCZKA,E,J., SEARS,C.F. Ng:theast Nuclear Energy Co. (subs. of Northoast Utilities). MROCZKA,E,J. Northoast Utilities 88/12/09. Document Control Branch (Document Control Dosk). 11pp. 47788 120-47788 167.
- -8812120250 Rov 1 to, "Red-ological Effluent Monitoring & Offsite Dose Calculation Manual & Process Control Program."

 Northeast Nuclear Energy Co (subs of Northeast Utalities) 89/01/31, 37pp. 47788-131-47788-167.
- 8812220262 Forwards Amend 26 to Licenso DPR-21 & safety evaluation. Amend reinoves requirements to monitor temp at reactor vessel bottom head drain during heatup/coolidown & during operation w/core critical BOYLE.ML Project Directorate 1-4 88/12/15 MROCZKA.E.J. Northeast Nuclear Energy Co (subs. of Northeast Unities) 2pp 47892 145-47892 155.
- --98 12220263 Arnord 26 to License DPR-21, removing requirements to monitor reaction vessel bottom head drain during heatup/cooldown & during operation w/core critical. STOLZ,JF. Project Directorate 1-4, 88/12/15, Spp. 47892 147-47892 151.
- -8812220265 Safety ovaluation supporting Amend 26 to License DPR-21.

 * Office of Nuclear Reactor Regulation, Director (Post 870411) 68/12/15 4pp 47892.152-47892.165.
- Q. Inspection reports, IE Bulletins & correspondence
- 8811180348 Draft "Millstone Nuclear Power Station Unit 1 PRA-Based Sys Insp Plans" HIGGINSJ, FULLWOOD,R, COPPOLAA Brookinven National Laboratory FIN A-3453, A-3453-3-87 DRFT, 87/03/31, NRC No Duta led Afficiation Giren, 166pp.

47508 100 47698 355

- 8811290027 Clarifies schedu'e for completion of Items b.c & d of IE Bu'letin 85 003 & submission of final rophs (Item I),por discussions w/NRC.

 MROCZKA,E J. Connecticut Yankee Atomic Power Co MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA,E J. Northeast Utilities. 87/12/30. RUSSELL,W.T. Reg on 1, Old of the Director. 5pp. 47667:198-47667:201.
- 8811300296 Forwards Safeguards Insp Repts 50-213/88-21,50-245/88-22, 50-336/88-25 & 50-423/88-21 on 881017-21 No violations noted BELLAMY,R.R. Region 1, Old of the Director, 89/11/15, MROCZKA,E.J. Northoast Nuclear Energy Co (subs. of Northeast Ulfsities) 2pp. 47678:019-47678:024.
- --8811300298 Physical Socurty Insp Ropts 50-213/88-21,50-245/88-22, 50-336/88-25 & 50-423/88-21 on 881017-21.No noncompliance noted Major sreas inspected safeguards info program corporate ofcs. LANCASTER,W.K., CAMERON,D.F., KEIMIG,R.R. Region 1, Ofc of the Director. 88/11/15-4pp. 47878:021-47678.024.
- 8811160211 NRC Info Notice 88:090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list enct. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729): 88/11/22 Consolidation Edison Co. of New York, Inc. 99pp. 47708:255-47708:257.
- 8811160467 NRC Into Notice 88:091, "Improper Administration & Control of Psychological Tests" Svc list and.
 ROSSIGE. Division of Operational Events Assessment (Post 870411), 88/11/22.
 Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708:142.
- 8611300493 Forwards Insp Rept 50:245/86-17 on 880830-1017 No violations noted Mg attention to correct inconsistent treatment of emergency svc water sys as ESF & as QA Category I sys requested RETTENHAUSEN,L. Region 1, Okt of the Director, 88/11/23, MROCZKA,E J. North east Nuclear Energy Co. (subs. of Northeest Utililins), 2pp. 47674-170-47674-185
- --8811300495 Insp. Rept. 50:245/88-17 on 880830-1017.No violations noted. Majo aross Inspected previously identified items.plant operations.physical security.loss o emergency sec water sys & loss of standby ges treatment sys. MCCABE, E.C. Region 1, Otc. of the Director. 88/11/18, 14pp. 47674:172-47674:185.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events," Svc list encl

DOCKETED HEMS

- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list
- ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47709 143-47709 254
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Uccasees on Yundors" "Svolistienci ROSSICE, Division of Operational Evonts Assessment (Post 870411) 88/12/08 Consolidated Edison Collo New York, Inc. 112pp. 47807 191-47807:302

R. Periodic operating reports & related correspondence

8812140021 Monthly operating rept for Nov 1988 for Milistone 1.W/881209 ft/ NEWBURGH.G., SCACE,S.E. Northoast Nuclear Energy Co. (subs. of Northeast Utilities). SCACE,S.E. Northeast Utilities 88/11/30. 5pp. 47800.167-47800.171

S. Reportable occurrences, LERs & related correspondence

- 8812200182 LER 88-010-00:on 881115, hydraulic shubber had no visitule signs of fluid in reservoir Caused by personnol error during previous rebuild Salety-related hydraulic shubbers in containment visually inspected W/881213 Itt GEORGIAN.E.J. SCACE.S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). SCACE,S.E. Northeast Utilities 88/12/13 4pp 47871.281-47871.284.
- 8812200264 LER 88-009-00 on 881114,ATWS Drv 1 trip received white reenergizing ATWS Drv 1.Caused by inadequate procedural guidance Operations procedure for 125 volt do systemiod to include refs to ISC Procedura 409A W/881213 ltr. MORPHY,K.E., SCACE,S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) SCACE,S.E. Northeast Utilines 88/12/13 3pp. 47864:358-47864-360.
- 8812200122 LER 88-008-00 on 681114.cold shuiddwn condition achieved when drywell unidentified leakage rate exceeded 2.5 gellons/ minute.Caused by 3-inch vacuum breater failing in partial open position. Vative assembles replaced W/681214 III. KANE, S.E., SCACE, S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) SCACE, S.E. Northeast Utilities, 88/12/14 5pp. 47871.075.47871.078.
- 8812200113 LER 88-011-00:on 681117. Isolation signal on trigh flow in main steam tine B occurred Caused by plugged low pressure sensing line AT eight lines back-flushed w/hydropump to trea restriction 8 vority Lines W/8812151 Co. GN BERT.E., SCACE.S.E. Northeast Nuclear Energy Co. (subs. of Northeast Unities), SCACE,S.E. Northeast Utilities, 88/12/15, 3pp. 47871:345-47871:347.

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8811300559 Notification of Significant Licensee Meeting 88:184 w/util on 881208 in King of Prussia,PA to discuiss security sys upgrade W/egonda. SWETLAND,P.D. Region 1, Ofc of the Director, 3pp. 47877:265-47877:287.
- 8811290134 Forwards summary of 880823-1108 meetings in Region I to discuss operafor professional sm, maint, source term reduction, corrective notions, engineering mode &
- wenziency planning WENZINGER.E.C. Region 1, Oto of the Oriector 88/11/23. BRAM,S. Consolidated Edison Co of New York, Inc. 2pp. 47648 174-47648:180.
- —8811290139 Summary of 880823 1108 meetings w/ull in King of Prussia, PA to li-censes interives in gress of operators professionalism maint, source term reduction, corrective action programs and heeting programs & salety philosophy. DUDLEY, N.F., SWETLAND, P.D. Region 1, Otc of the Director, 88/11/22, Region 1, Otc of the Director, 5pp. 47648:176-47848:180.
- 8811290 177 Advises that Region I will participate in emergency preparedness exercise scheduled for 881207 & requests provision of briefing/training session on plant facility & emergency response organization at Region I on 881201.
 EBNETERS D. Region I, Otc of the Director, 88/111/23. BRAM,S. Consolidated Edison Co. of New York, Inc. 4pp. 47851:114-47851:117.
- 8812080153 Forwards Insp Rept 50-247/88:30 on 881018-21 No violations noted DURR, J.P. Region 1, Oic of the Director, 88/11/28, BRAM, S Consolidated Edison Co. of New York, Inc. 2pp. 47783 271-47783:282.
- -8812060154 Insp Rept 50:247/68-30 on 881018-21. No violations noted. Major areas inspected fire protection/prevention program, including program administration & organization & administrative control of combustibles KRASOPOULOSA, MATHEW, R., ANDERSON, C.J. Region 1, Old of the Director, 88/11/15, 10pp, 47783-273-47783-282.
- 8812130309 Forwards Insp Rept 50:247/88:29 on 881004:1107 No violations noted. WENZINGER,E.C. Region 1, Ofc at the Director, 88/12/01, BRAM,S. Consolidated Edison Co. of New York, Inc. 2pp. 47798:189-47798:199.
- -8812130310 Insp. Rept. 50-247/88-29 on 881004-1107.No violations noted. Major areas inspected operations rad ological controls, maint/surva, lance testing, emergency preparedness, security, engineering/technical support 6 safety assessment. SWETLAND,P. Region 1, Otc of the Director. 88/11/29, 9pp. 47798:191-47796.199.
- 8812130047 Revised emergency plan Implementing procedures,Including Rev 5 to IAP-1,Rev 3 to IAP-8,Rev 4 to IAP-10,Rev 4 IAP-13,Rev 2 to IP-1013,Rev 0 to IP-1024 & Rev 3 to IP-1027.W/891297 III. BRAM.S.B. Consolidated Edison Co of New York, Inc. 68/12/07, 60pp. 47794:160-47794:230

P. Operating license stage documents & correspondence

6812020011 Remits (se for 080502 plan to expand near-site emergency operations facility.per 881101 request Fee paid. BRAMS.B. Consolidated Edison Co. of New York, Inc. 88/11/15 Document Control Branch (Document Control Desk). 1p. 47722 187-47722:187.

- 8812010336 Forwards response to request for addit into re loak-before, break per 891027 discussion w/NRC.
 BRAMS.B Consolidated Edison Co of New York, Inc. 88/11/18. Document Control Branch (Document Control Desk) 5pp 47710.087-47710.091.
- 8811280048 Generic Ltr 88-20 to all Icensees holding CLs & CPs for nuclear power reactor tacifies re individual plant exam for severe accident vulnerabilities Svc list CRUTCHFIELD,O. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729:024.
- 8811290134 Forwards summary of 880823 1108 meetings in fleepin I to discuss operation professional sm,maint, source term reduction, corrective actions, engineering, model 8 embrigency planning WENZINGER,E.C. Rogion 1, Ofc. of the Director 88/11/23 BRAM,S. Consolidated Edison Co. of New York, Inc. 2pp. 47848:174-47849180.
- --8811290139 Summary of 880823-1108 meetings w/util in King of Prussia, PA recensee initiatives in areas of operators professionalism,maint.source for reduction.corrective action programs.ong/neering programs & safety philosophy, DUDLEY,NF, SWETLAND,PD. Region 1, Ofc of the Director. 88/11/22. Region 1, Ofc of the Director. 5pp. 47648:176-47648:180.
- 8611300269 Notification of 881212 meeting w/util in Rockville,MD to discuss status of compliance w/Generic Ltr 85:09 re Tech Spec for reactor trip breakers & shunt & undervollage hip attachments.

 LNNGFORD, Droject Directorate 1-1, 88/11/28, CAPRA,R A. Project Directorate 1-3, 29p. 47670.302-47670.303.
- 8612070263 Responds to request for additinto to reactor coolant pump trip criteria,per NRC 861014 request concerning Generic Ltr 85-12.

 BRAM,S B. Consolidated Edison Co. of New York, Inc. 86/11/29. Document Control Branch (Document Control Desk). 13pp. 47745:208-47745:221.
- 8612090012 Forwards response to Generic Ltr 88-11, "NRC Position on Radiation Embrillement of Reactor Vessel Mails & Impact on Plant Operations "
 BRAM,S B. Consol dated Edison Co. of New York, Inc. 88/11/30. Document Control Branch (Document Control Branch (Document Control Branch (Document Control Desk). 6pp. 47782.007-47782.092.
- -8812090013 "Reactor Vessel Matr Surveillance Program for Indian Point Unit 2 Analys's of Capsule V. IDD:NGS.F.A., CROSS.B.T. SRI International, 88/10/31, 78pp, 47782.013-47782.032.
- 8912070228 Requests that util address Generic Ltr 88-17 re loss of DHR during non-power operation Issue of high priority 8 should be addressed accordingly. MURLEYT.E. Office of Nuclear Reactor Regulation. Onector (Post 870411): 88/12/ 02 HAUSPURGA. Consolidated Edison Co. of New York, Inc. 4pp 47749:271-4774B 274
- 68 12140016 Proposes installation of replacement recorders prior to startup from projected 1989 refueling outage BRAM,S.B. Conscridated Edison Co. of New York, Inc. 88/12/06. Document Control Branch (Document Control Desk). 2pp. 47797:221-47797:222.

- 8811180312 Rev 2 to "Pulot PRA Applications Program for Insp at Indian Point 2."
 IRNTON,M.F., WRIGHT,R.E. EG&G Iddho, Inc. (subs. of EG&G, Inc.). HINTON,M.F.
 Idaho National Engineering Laboratory. FIN A-6553 EGG.EA-713G R02. 67/02/28.
 NRC No Detailed Affiliation Given. 49pp. 47597:250-47597.297.
- 8811290020 Responds to 880407 request for addit into re IE Bulletin 85-003, "Motor-Operated Valve Switch Sollings." BRAM,SB. Consolidated Edison Co. of New York, Inc. 88/05/09. WENZINGER,E.C Region 1, Ofc of the Director
- 8811290059 Forwards Salety Insp. Rept 50-247/88-28 on 881003-07 & notice of violation. Findings of insp along w/past similar liss findings indicate need for more mgt Involvement in inservice testing area. DURR.J.P. Region 1, Otc of the Director. 88/11/21. BRAM,S. Consolidated Edison Co. of New York, Inc. 2pp. 47650:281-47650:294.
- --8811290074 Notice of violation from insp on 881003-07. Violation noted: stated valves tequired to mitigate consequence of accident not periodically tested based on failure to include valves in inservice testing program
 * Region 1, Ofc of the Director, 88/11/21, 2pp. 47650;283-47650;284.
- ~8811290076 Insp. Rept 60-247/88-28 on 681003-07.Violations noted.Major areas inspected implementation of inservice testing activities,Including organization review,discussions w/cognizant personnel & review of documentation. PRIVIDY_LJ_, EAPEN_P.K., Region 1, OIc of the Director, 88/10/26, 10pp. 47650-285-47650-98. 47650.204
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list encl. CUNNINGHAM.R.E. Division of Industrial 8 Medical Nuclear Satisty (Post 970729). 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257.
- 8811160487 NPC Info Notice 88-091, "Improper Administration & Control of Psychological Tests." Svc list and.
 HOSSICE: Division of Operational Events Assessment (Post 870411). 88/11/22.
 Consolidated Edison Co. of New York, Inc. 101pp. 47708-042-47708:142.
- 8812060153 Forwards insp Rept 50-247/88-30 on 881018-21.No violations noted. DURR,J.P. Region 1, Ofc of the Director 88/11/28 BRAM,S. Consolidated Edison Co. of New York, Inc. 2pp. 47783-271-47783-282.
- --8812080154 Insp. Rept. 50: 247/88-30 on 881018-21.No violations noted. Major areas inspected, the protection/prevention program, including program administration & organization & administrative control of combustibles. KRASOPOULOS,A, MATHEW,R., ANDERSON,C.J. Region 1, Ofc of the Director. 88/11/15. 10pp. 47783:273-47783;282.

- 8811290930 FRC, into Notice BR 093 "Totalberrapy Events." Svc list and CUNNINGHAMIR E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88712702 Consordated Edison Co. of New York, Inc. 112gp. 47811-103-47811-215.
- 8811290538 BHC Into ratice 88:094, "Potentially Unifersized Valve Actuators." Sec 1st et C. IROSSICE Division of Operational Events Assessment (Post 870411), 88/12/02 Prescripted Litson Co. of New York, Inc. 123pp. 47708 143-47708 254.
- 8812080002 Pesa pela to NRC 851103 it re-violations noted in to Pleats 50:247/86-11 & 50:247/87-38 on 80:512 16 & 87/12/4-18, respectively & remais cert penetry to an ouncid 575,000 Contention actions blacks replaced wi/qualified blacks BHAM-531 Consultated Edison Co. of New York, Inc. 887/12/02. Old of Enforcement (Post 870413), 16pp. 47754-118-47754-133.
- 881122093 Forwards response to NHC 881102 III re-concerns on 880924 incident concerns up refuelting water storage tank love' solicating dower not in place, por hisp Rept 50,24780-26 INSAM,5 Considerate Folson Co. of New York, Inc. 80/12/202. WENZINGER,F.C. Hegbor 1, Ohr of the Director 2pp. 47789-066 47783-067.
- 8812020287 NRC felo Notice 88 095, "Inadequatu Proceroment Regeiroments Imposed by Elemicos on Vendaria" Sve 1st end. HOSSI C.C. There is not Operational Events Assessment (Post 970411). IRE/12/08. Consentated Fide as Co. of New York, but 11/2pp. 47807.191-47807.392.
- 8812210373 Ack recept of 880929 lir informing NRC of stops taken to correct violations noted in in a Rept 50.247789-23.Response to Violation C of original notice within 30 days of the date requested RAME, will integrate to the Circuit, 88712709 BRAM,S. Consolidated Edison Co of Now York, Inc. 2pp. 47876-228-47876-229

A. Periodic operating reports & related correspondence

8812199241 "Ammat Bartotogical Emergency Onli,1988"
* Consolidated Entron Co. of New York. Inc. 897/10714- 650pp. 47853-004-47853-230

S. Reportable occurrences, LERs & related correspondence

- 8312080110 LET 08 015 09 on 881020, ittl entered into Tech Spin 3.0.1. Caused by simultaneous and ratibility of sec water pump & unorganity deset generator due to note for repairs & materity to use nonessontial header W7881128 lin DAHLG, 819AM,SE Computated Edeon Co. of New York, for 88/11/21 5pp 47757,096 47757,100
- 8912020236 RO on 881107.Tech Spec 3.5.5 withted Caused by number of operable channe's being loss than required into number of channels operable due to inoporable vent notableges efficient monder 1/27 Modifor will be returned to see around 890210 BRAMS 8 Consultated Euton Co. of New York, Inc. 88711728. Occument Confrot Branch (Deciment Cuntrol Posk). 2pp. 47717.063-47717.064
- 8812120097 I.ER 88-017-00 on 881102.determined that single failure could cause loss of an supply to promine controlled amorgancy diesel garunator (EDG) bidg viunifial lion sys Causad by mulcapatio dostyn of EDG Procedure issued.W/881201 ltr. DELPERICOLUS, BRAMAS Consolicited Edison Co. of New York, Inc. 88/12/01. 5pp. 47785 101-47788 105.
- 8812130018 LER 88 016-00 on 881101.undursized solarise supports discovered which could induce stresses in oblitting support which would excool inax allowed Caused by failure to modify support Revised support will be installed W7801201 ftr ELLWANGERJU, BRAMU. Consolidated Edison Co. of New York, Inc. 88/12/01 4pp 47797.125-47797.128

U. Congressional/Executive Correspondence

- 8811300288 Responds to 881020 itrire operation of plants following steam generator test at Indian Point 3 NRC evaluated event & concluded that no immudiate safety concerns warrant chuldown of facilities EECHL by Commissioners 88711723. GILMAN BIA. House of Rep. 2pp. 47668/313-
- 47669 125
- --8811300290 Requests rept on stnam generator release incident at Unit 3 & overall safety of plant Plant should be shut down until public safety absolutely assured. GluMAN,B A House of Rep. 88/10/20. ZECH,L A. Commissionure. 3pp. 47669-123-47669-125.

V. Operator Examinations

- 8811300291 Notification of Significant Licensed Meeting 98-183 on 881118 w/util in King of Priessa,PA to discuss requalification exams GALLO,R M. Region 1, Otc of the Director, 80/11/15 Region 1, Otc of the Director, 20p. 47701.358 47/01.357
- 8812120228 Approves 881104 request for exemption from licensed operator requalification program cycle Understands that facility will commonce 24 month requalification program cycle in Fob 1989. GALCJR M Region 1, Olc of the Director 88/12/02 BRAM,S Consolidated Edison Co of New York, Inc. 2pp. 4/782.071-47792.076

- 8812210174 Rev 5 to Emergency Plan Implementing Procedure EPJP 200.2, "Classification & Responses to the dent Involving Office Hazardons Mail (Primary Responsibility-Station Director)."
 - Commonwealth Edison Co. 88/12/13, 16pp. 47880-195-47880-210.
- 8812210205 Nev 14 to Emergency Plan Implementing Procedure EPIP 300-1, "Inhibit Notifications & GSEP Responses."

 **Commonwealth Edison Go. 88712/13, 23pp., 47875 015, 47875 637.

P. Operating license stage documents & correspondence

- 8811300450 Forwards corrected Tech Specs pages,summary of changes & description of proposed around request for plant DEYOLING,GL Communicipality Edison Co. 88711707, MURLEY,T.E. Office of Nicoles Provided Review Provided Review 1, 144, 17611365 4,7671.200
 - ar Reactor Regulation, Birector (Post 87041.1) 115-17671-265-47671-200.
- -8811300453 Corrected proposed Tech Spacs re-administrativa controls * Cerrinal wealth Edison Co. 88711707 - 15pp - 47671 266 47671 280
- 8811220055 Forwards Hov 52 to QA Program Topical Rupt CE-1-Aiper 891110 request SHEWSKI,W J. Commonwealth Eulsch Co. 88711717 MULLER,DIR. Project Directorate 81-2 Tp. 47663 063-47663 068
- 8811280048 Goneric Etr 88:20 to all licensees holding OEs & CPs for nuclear power reactor facilities ro individual plant exam for nevero accident vurinisabilities Svc list encl CRUTCHFIELDD Associate Director for Projects (Post 870411) 88/11/23 Consciudated Edison Collei New York, Inc. 81pp. 47728 333-47729-024
- 8811300087 Forwards safety ovaluation accepting util response to Gunero IIIr 83-28,ttem 2-1,Part 2, "Vendor Interface Program," for reactor trip sys components SIEGET,B. Project Directorate III-2-88/11/23. BLISS,FE Commonwealth Edison Co. 4pp. 47695-343-47695-348.
- --8811300092 Safety ovaluation accepting with response to Generic Lift 83-28,term 2 in Part 2) re-vender interface program for mector true systemments. NRC No Detailled Affination Given 89/11/23 3pp. 47695-347-47695-349.
- 8812010129 Discusses Interim operating restrictions to proclude regional neutron flux instabilities tilsted restrictions will remain in official until further study 87cr revised recommendations resolvu industry 8 stuff concerns SILADYUA Constigniesalli Edison Co. 80/11/23 MURLEY,T.E. Official of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47698.204-47698-295.
- 8812010305 Provides analysis of Rog Goldo 1 99,Rov 2, "Radiation Ententilloment of Hoactor Versul Matis" for impact on prossure-temp heature & cooklown curves contained to Fech Space, por Generic Lir 88-11 RiCHTETH,MH Cerumonwalth Edison Co. 88711728 Document Centrel Branch (Document Centrel Doss), 2pp. 47703 049 47703 050.
- 8012160056 Provides MSIV design evaluation third progress rept Sargent & Lundy personnul presently ensite to review effects of MSIV control sys changes on existing Station procedures Next progress rept will be provided by 890201.

 SILALYJAA. Commanwealth Edison Co. 88/12/01 DAVIS,A.8. Region 3, Old of the Director 2pp. 47830-354-47830-355.
- 8812200014 Requests roview of BWR Owners Group position prior to requiring commitment to replace analog transmitter trip units circuit heards SHADY.JA Commonwealth Edison Co 88/12/15 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 47862.186-47862.199

- 8811160211 NRC Into Notice 88-000, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list enct. CUNNINGHAM.R.F. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/11/22. Consolidated Edison Co. of New York, Inc. 08pp. 47708 255-47708.257.
- 8811180487 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Teers." See ast each.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/11/22, Consol.datud Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.
- 8812010171 Forwards Safety Insp. Repts 50-237/88-22 & 50-249/88-23 on 880010-1122,Np violations noted CLAYTON,B. Region 3, Otc. of the Director, B6/11/25, REED,C. Commonwealth Edison Co. 2pp. 47707:111-47707:132.
- -8812010175 Safety Insp Repts 50:237/88-22 & 50:249/88-23 on 880910:1122.No violations noted Major areas inspected TMI action plan requirements operational safety vanification, followup of events & monthly maint observation. RING.M A. Hogion 3, Oic of the Director 88/11/25-30pp 47707:113-47707.132.
- RING M A Hogion 3, Old of the Director 88/11/25 30pp 47707:113-47707.132.

 8811290030 NRC Into Notice 88-093, "Teletherapy Evants." Svc list end.

 CUNNINGHAM R E. Division of Industrial & Madical Nuclear Safety (Post 870729)

 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Into Notice 88-094, "Potentially Undersized Valve Actuators," Svc list end ROSSI, C.E. Division of Operational Events Assessment (Post 970411) 88/12/02. Consolidated Edison Co. of Now York, Inc. 121pp. 47708
- 8812020297 NRC Into Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svc list end: ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 68/12/08 Conspitation Edison Co. of New York, Inc. 112pp. 47807:191-47807.302

A AXIII LIJE EKIMPEMBINDE OF COURT OF MARRIED CO SON CO 47850 061 47860 101

S. Reportable occurrences, LERs & related correspondence

8812209205 LER 88 018-00 on 881115 potential violation of secondary containment integrity occurred due to might deficiency. Personnel fett interlack inner door open & unattended Event reviewed whate contractor personnel W/881215 lin. AttANOAPPAA. ECKIGETHBURGE. Commonwealth Edison Co. 89/12/15. 5pp. 47861-048-47061-052.

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8812150148 Advises that 881130 Rev 15 to physical security plan involves most changes consistent w/provisions of 10CFR50 54(p) & acceptable Ericl into details changes which require clarification Ericl will held tref 10CFR73 21) CLINE, WE Alegion 2, Official field brector, 88/11/30 WOODY, C.O. Florida Power & Light Co. 3pp. 47816 355-47816 357.

8812090125 Revised Emergency Plan Implementing Procedures 20102,20106, 20103 & 20110 W/681202 IIr. CROSS.J.E., CONWAY,W.F. Florida Pawer & Light Co. 88/12/02, 36pp. 47762 311-47782 346

8812200352 Revised Emergency Plan Implementing Procedure 20107, "Fire/Explosion Emergencies." W/881216 itr CROSSUE, CONWAY,W.F. Florida Power & Light Co. 88/12/16 8pp. 47868.070-

G. Adjudicatory correspondence

8812140078 Establishment of ASUB to preside in proceeding * Board established in stated proceeding to rule on poblions for leave to intervene 8/07 requests for hearing 8 to preside over proceeding Served on 881205 COTTER,8 P. Atomic Safety and Licensing Board Panel. #488 7609 80/11/30. 2pp 47770.189-47770 190.

8812140079 Licensee response to request for hearing & poston for feave to intervene re-license amonds for pressure/temp limits? Amends would modify Toch Spacs to incorporate revised pressure/temp limit curves Certilicate of Six encil FRANTZ-SP. Florida Power & Light Co. FRANTZ-SP. Newman & Hottunger #488 7624 88112/02 Afomic Salety and Licensing Board Pane. 18pp. 47769 278 47769 293.

8812190068 Notice of appearance * Advises that author will enter appearance in pro-ceeding on behalf of NRC W/Cert tide e of Svo. MOOREJE, Assistant General Counsel for Mearings #498 7659 88/12/07. 3pp. 47802:207-47802

8812190111 NRC Staff response to request for hearing 8 pelvion for leave to intervene of Ctr for Nuclear Responsibility 8 J Lorion * Request for hearing prior to issuance of amends should not be granted Certificate of Svc enct. MOCREJE: Assistant General Courset for Hearings, #488 7640, 88/12/07. Atom.c Safety and Licensing Board Panel, 13pp. 47801.150-47801.162.

8812270086 Notice of appearance.* Advises that author will enter appearance in pro-ceeding on behalf of NRC Certificate of Svc and. JEHLEP-A. Assistant General Counsel for Hearings #488 7684. 88/12/13 3pp 47872 285-47872 287.

8912270119 Petitioners response to licensee & Staff response to patitioners request for hearing & petition for trave to intervene w/respect to ticense amends for pressuro/ temp limits.* Certificate of Svc enct.
LORION,J. Center for Nuclear Responsibility. #488 7709, 68/12/14. Atomic Safety and Licensing Board Panel. 6pp. 47872:155-47872-160.

1. Financial Information

8812220136 Forwards financial disclosure into Including 1987 annual 10-K, Sept 1998 10-O & util statement of Internal cash flow excluding rotained carnings for 12 months ending Sept 1989, per 100FR140-21 & Reg Guide 9.4. CONWAY, W.F. Florida Fower & Light Co. 86/12/14. Document Control Branch (Document Control Dock), 91pp. 47886 195.47886:285.

P. Operating license stage documents & correspondence

8811230001 Confirms 881102 telcon re 881122 meeting to discuss status of performance enhancement program & emergency dieset generator upgrade program. ERNSY,ML. Region 2. Off. of the Oirector. 88/11/10. CONWAY,W.F. Flonda Power & Light Co. 2pp. 47652:107-47852:108.

8811290010 Notification of 681122 meeting w/util in Region II ofc to discuss performance enhancement program & emergency diesol generator upgrade program. CRLENJAK,R.V. Region 2, Ofc of the Director. 88/11/10. Region 2, Ofc of the Director. 1p. 47664:198-47664:199.

8811290046 Generic Lt/ 88-20 to all ticensees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnerabilities, Syc list enci CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consoli-dated Edison Co. of New York, Inc. 81pp. 47728 303-47729:024.

8012120137 Requests that util addresses Generic Ltr 88-17 reliess of DHR during roa. power operation Industry has not aggressively responded to resolve concern to low a identification in Generic Ltr 87-12. WURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) (1972) 02 HUDBURG, J.J. Flor da Power & Light Co. 3pp. 47780 139-47780 141.

80 t2120186 Forwards current schedule for completion of SPDS items,per NEIC 061827

TOONWAY, W.F. Florida Power & Light Co. 88/12/07. Document Control Branch (1976) ment Control Desk). 2pp. 47/86 185-47786.186

8812130198 Informs of decision not to review will 880203 proposed from a prior translatory injection accumulators, based on 1sted reasons including formed. MitG ω EDISON,G.E. Project Directorate II-2, 88/12/08, CONWAY,W.F. Florida Power & Lett. Co. 4pp 47796 013-47796 016

8812130211 Notification of series of meetings between 881212 8 and of Jan 100 will in Rockville,MD to discuss Tech Spec improvement project EDISON,G.E., Project Directorate III-2, 88/12/09 Project Directorate III-2, 2gc 47792.101.47792 (02.

8812160034 Clarifies 881202 discussions w/NRC re drawing update activities & provides additional activities undertaken to assure accuracy of suborted fram 475 to be used in control room for restart 8 subsequent operation of Unit 3 CONWAY WF Florital Power 8 Light Co. 88/12/69. Document Control Branch (Poc.) ment Control Desk). 6pp. 47830.321-47830.326.

8812200197 Submits requested addition to emergency power systembringer of project Project will be implemented in two phases consisting of outlage & preloting activities to meet integrated schedulo 1990 complation date.

CONWAY,W.F. Florida Power & Light Co. 88/12/14 Document Control Briefich (Occument Control Desk). 3pp. 47864:193-47864.195

8812230027 Application for amonds to Licenses DPR-31 & DPR-41, superating cut. 11 requirements for electrical sys into three subgroups & add more restrictive for target conductors for operation for diesel generator operation For paid CONWAY, W.F. Florida Power & Light Co. 88/12/20. Document Control Branch (No ulment Control Dosk), 18pp. 47916.087-47916:110.

-8812230029 Proposed Tech Specs to electrical power sources.
* Florida Power & Light Co. 88/12/20, 26pp. 47916,085-47916,110.

Q. Inspection reports, IE Bulletins & correspondence

8811300209 Forwards summary of 680921 meeting releasessment of SALP Repta 50-250768-15 & 50-251768-15 Corrected pages to SALP topts also end: ERNST,ML Region 2, Official this Director, 98/11/18 CONWAY,W.F. Flunds Power & Light Co. 39pp. 47673-285-47673-339

--8812050272 Corrected pages to SALP Repts 60-250/88-15 & 50-251/88-15 for June 1987 - June 1988.

* NRC - No Detailed Attitiation Given 88/11/18 10pp. 47673.330-47673.330

8811300565 Forwards Insp. Repts. 50-250/88-29 & 50-251/88-29 on 881017-21.No vo lations of deviations noted.
DECKER,T.R. Region 2, Ofc of the Director. 88/11/18. CGNWAY,W.F. Florida Power 8 Ught Co. 2pp. 47873 223-47873 238.

~8811300567 Insp Repts 50:250/08:29 & 50:251/88:29 on 891017:21 No violations of deviations noted Major areas inspected confirmatory measurements, PASS & Aug 1998 spent tuel pool spi1.

ADAMOVITZ.S.S. KAHLE.J.B. Region 2, Ofc of the Director. 89/11/17. 14pp. 47673:225-47673:238.

8811160211 NRC Into Natice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svo 1st enct.
CUNN'NGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729)
88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708-255-47708-257.

8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychology cal Tests," Svo list enci. ROSSI,C.E. Division of Operational Events Assessment (Post 970411). 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142.

8612080050 Forwards Inap Repts 50:250/88:28 & 50:251/88:28 on 881003:07 8 #81017-21 & notice of violations
HERDY.A.R. Region 2, Ofc of the Director. 88/11/23 CONWAY,W.F. Florida Power & Light Co. 2pp. 47783-161-47783:183.

~8812080051 Notice of violation from insp on 881003-07 & 17-21. Violational nated measures to assure that design basis adequately transmitted to procedures & instructions not adequate & fautre to establish has program for HS. HERDT,A.R. Region 2, Otc of the Director, 88/11/23, 3pp. 47783:163-47783:165.

--8812080054 Insp Repts 50-250/88-28 & 50-251/88-28 on 881003-07 & 17-21 Violations noted Major areas inspected, HX replacement, insorvice Insp, housekeeping matidenth-cation & control & matidenth-cation & control & matidenth-cation & Control & Matiden Repts (17. 18pp. 47783:186-47783:189).

8612080057 Forwards Insp Ropis 50-250/88-30 & 50-251/88-30 on 880926- 1028 & notice of Violation

REYES,L.A. Region 2, Ofc of the Director 88/f1/23, CONWAY,W.F. Florida Power & Light Co. 2pp. 47750.085-47750:105. --8812080058 Notice of violation from hispinn 880926-1028 Violation noted and big neuto makeup using solely bond and using Section 8.8 of AP 0103.32

REYES,LA Region 2, Old of the Director, 88/11/23, 2pp. 47750.097-47750.088

- --8812080059 trisp Repts 50.250788-30 & 50.251788-30 on 880926-1028 Violations noted Major areas inspected surveillance observations, ESF operational safety verification & facility mode & plant events BUTCHFR, R.C., McELHINNEY, J. F., SCHENBLI, G.A. Region 2, Ofc of the Director 88711723 17pp. 47750-099-47750-105.
- 9812080192 Forwards Insp. Repts 50-250/88-33 & 50-251/88-33 on 881031- 1104 No

vollations or deviations indust HERDT,A.R. Rog on 2, Otc of the Director 88/11/29, CONWAY,W.F. Florida Power & Hight Co. 2pp. 47701 299 47783 314.

-8812080193 Insp Repts 50:250/88:33 & 50:251/88:33 on 881031:1104.No violations or dovalions noted Major areas inspected inservice insp (ISI) including rowew of ISI plan for outage for Unit 4 & royow of NDE procedures. NEWSOME,R.W., BLAKE,J.J. Region 2, Ofc. of the Director. 88/11/22, 14pp. 47783:301-47783:314

- 88.11290030 NHC Into Notice 88.093, "Telethorapy Events" Svc fist and CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88712702 Consolidated Edison Co. of New York, Inc. 112pp. 47811;103-47811.215
- 8811290538 NRC Into Notice 88-094, "Potentially Undursized Valve Actuators" Svc 1st ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708.143-47708:254
- 8812160140 Forwards hisp Rept 50:250/68:35 on 881114-18.No violations or deviations noted HERDI , A.R. Rogen 2, Old of the Director, 88/12/05 CONWAY,W.F. Florida Power & Light Co. 2pp. 47832 259-47832 284
- -8812160156 Insp. Rept. 50-250/88-35 on 881114-18 No violations or deviations noted Major areas inspected engineered safequands integrated festing & review of provious enforcement matters.
- SPARKS,S.E., JAPF,F. Region 2, Otc of the Director, 88/12/01, 4pp. 47832.261-47832 261.
- 8812020287 NRC Into Notice 88-095, "Inadequate Procurement Requirements Imposed by Licenser's on Venders" "Svo list and ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88712708 Cansolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302.
- 8812200161 Forwards Insp Repts 50:250/88:34 8 50:251/88:34 on 881031- 1104 &
- notice of volation. JULIAN,CA. Region 2, Ofc of the Director. RB/12/15. CONWAY,W.F. Flor.da Power & Light Co. 2pp. 47867.288-47887.298. --8812200164 Notice of violation from inspirent 881031. Violation noted. Procedure O-ADM-209 requirements not adhered to in that NRC inspectors identified several com-
- ponent coving water sys components not lagged w/metal tag within 24 h. JULIAN,C A. Region 2, Olc of the Director, 08/12/15, 2pp. 47867:200-47867.291. ~8812200167 hisp Hopts 60:250/88:34 & 50:251/88:34 on 881031-1104. Violation noted Major areas inspected mode & dissign control, hispoctor followip liem re Inconsistent practices in record retention for completed design packages noted.

 JUFFYK, GIBDS II., RELISLE,G.A., Region 2, Ofc. of this Durector, 88/12/08. 7pp

R. Periodic operating reports & related correspondence

47867:202-47867.298

- 8811280041 Forwards summary of mgt on shift weakly repts per Commission 871019 order CONWAY,W.E. Florida Power & Light Co. 88/11/07. ERNST,M.L. Region 2, Ofc of the Director. 36pp. 47692-321-47692-356
- 8811290141 Forwards mgt-on-shift wookly ropts for wk starting 881104, per 871019 order & plant supervisor-nuclear shift ropts COMWAY.WF Florida Power & Light Co 68/11/16 ERNST,ML. Region 2, Old of the Director, 34pp. 47663:001-47663.034.
- 8811290367 Forwards select sys assessment progress summary for Oct 1988. CONWAY,W.F. Florida Power & Light Co. 88/11723 Document Control Branch (Document Control Dask). 2pp. 47664;213-47664;214.
- 8812060114 Forwards mgt-on-shift wookly rept for wk starting 881111,por 871019 order.Plant supervisor nuclear sh-ft repts also end CONWAY,W F. Florida Power 8. Light Co 88/11/23. ERNST,M.L. Region 2, Ofc of the Director. 34pp. 47734:199-47734:232.
- 8812160071 Forwards mgf-on-shift weakly rept for wk starting 881118,per Commission 871019 order. CONWAY,W.F. Florida Power & Light Co. 88/11/30. ERNST,M.L. Region 2, Ofc of the Director. 29pp. 47873:237-47873:265.
- 8812200131 Forwards summary of mgt-on-shift weekly rept & plant supervisor-nuclear shift rept for wk starting 881125. CONWAY.W.F. Florida Power & Light Co. 88/12/07. ERNST,M.L. Region 2, Olc of the Director. 31pp. 47864 233-47864 263.
- 8812200008 Forwards monthly operating status repts for Nev 1988 for Turkey Point Units 3 & 4 & St Lucle Units 1 & 2 & corrected unit shutdown & power reductions rept for Turkey Point Unit 3 10 Oct 1988.

 CONWAY,W.F. Florida Power & Light Co. 88/12/13 Document Control Branch (Document Control Dask). 1p. 47868.333-47868-349.
- --8812200013 Monthly operating repts for Nov 1988 for Turkey Point Units 3 & 4 & St Eucio Unis 1 & 2. BONETT,D M. Florida Power & Light Co. 68/11/30. 16pp. 47886:334-47668:349.
- ~8812200015 Corrected monthly operating rept for Oct 1988 for Turkey Point Unit 3 BONETT, D.M. Florida Power & Light Co. 86/10/31. 1p. 47868:350-47868:350.

S. Reportable occurrences, LERs & related correspondence

- 8811230275 Special ropt on 881012.13.25 8 28,tive the protection impairments let open in oxcass of Toch Specs permitted time fimits Caused by extrer plant mods o aguingment maint Plant continues to implantant companisatory measures as applicable CONWAY,W.F. Florida Power & Light Co. 88/11/18 Document Control Brench (Document Control Desk), 5pp. 47651/318-47651/322
- 8811280084 LER 86 041-00 on 880201,RHR pumps not in operation.per Tech Specularing refueling pool till during provious rolueling outlage Caused by inadoquate raview of plant procadures Admin strative Procedure 103 18 revised W/861125 lt. GROSS.K.W., CONWAY,W.F. Florida Power & Light Co. 88/11/25 4pp. 47654:297 47654:300
- 8812120190 LER 88 026:00 on 881107,Units 3 & 4 cuts-de FSAR design basis we regard to humicane llood protection Caused by lack of plant drawings that provide clear details of stop logs & inadequate design Safety evaluation prepared W/881207 LYONS,E., CONWAY,W.F. Florida Power & Light Co. 88/12/07 6pp. 47789-055-47789-060
- 8812200203 LERI 88 028 00 on 881117 control room vanilation sys shifted to recircula tion mode while conducting test of Channel 8 ar intake radiation monter RA 5642 Caused by maladjustment of menter during caler fastruction revised W/881214 GHOSS,K.W., CONWAY,W.F. Florida Power & Light Co. 88/12/14, 4pp. 47871;310-

V. Operator Examinations

47871.313

812090119 Requests that att provide tised tems for requalification program evaluation scheduled for Feb & Mar 1880 JULIANCA Region 2, Oic of the Director, 88/11/25 CONWAY,W.F. Florida Power & Light Co. 6pp. 47784 338 47784 343

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F. Security, medical, emergency & fire protection plans

- 88.12150.148 Advises that 88.1133 Ray 15 to physical security plan invalves most changes consistent w/provisions of 10CFR50.54(p) & acceptable Encl info details changes which require claim/cnition Encl willlifed (red 10CFR73.21) CLINE, W.E. Rag on 2, Otc of the Director, 88/11/30, WOODY, C.O. Florida Power 8 Light Co. 3pp. 47816.355.47816.357.
 - 8812090125 Royled Emergency Plan Implementing Procedures 20102,20108, 20108 8 20110 W/881202 III CROSS_JE , CONWAY,W.F Florida Power & Light Co. 88/12/02, 36pp. 47782.311 47702 346
- 8812200362 Rowised Emergency Plan Implementing Procedure 20107, "Fire/Explosion Emergencies" W/881216 ttr CROSSUE, CONWAY,W.F. Florida Power & Light Co. 88/12/16, 8pp. 47868-070 47869.077.

G. Adjudicatory correspondence

- 8812140078 Establishment of ASLB to provide in proceeding.* Board established in stated proceeding to rule on pathlons for leave to intervene &/or requests for hearing & to provide over proceeding Served on 881205.
 COFIER.B.P. Atomic Safety and Licensing Board Panel #488 7609 88/11/30, 2pp 47770 189-47770 190.
- 8812140079 Liconsec response to request for hearing & petition for feave to intervent to license amends for pressure/temp limits. *Amends would modify Toch Specs to incorporate revised pressure/temp limit curves Certificate of Svc cerct. FRANTZ,S.P. Florida Power & Light Co. FRANTZ,S.P. Nowman & Holtzinger. #486 7694. 88/12/02. Atomic Safety and Licensing Board Panel. 19pp. 47769.278
- 8812190068 Notice of appearance.* Advises that author will enter appearance in proceeding on behalf of NRC W/Certificate of Svc.
 MOORE,J.E. Assistant General Counsel for Hearings, #486-7659, 88/12/07, 3pp
 47602-207-47602
- 8812190111 NRC Stalf response to request for hearing & petition for leave to intervent of Cir for Nuclear Responsibility & J Lorion.* Request for hearing prior to issuance of amends should not be granted. Certificate of Svc encil MOORE. J.E. Asis stant General Counsel for Hearings. #488 7640. 88/12/07, Atomic Satety and Liconsing Board Panel. 13pp. 47801:150-47801:162.
- 8812270086 Notice of appearance * Advises that author will onter appearance in pro-ceoding on behalf of NRC Certificate of Svc onct. JEHLE.P.A. Assistant General Counsol for Hearings. #488 7684, 88/12/13. 3pp 47872:285-47872-287.
- 8812270119 Petitioners response to licensee & Staff response to petitioners request to hearing & petition for leave to Intervene w/respect to license amends for pressure temp limits. Certificate of Svc end LORION, Center for Nuclear Responsibility. #48B 7709. 8B/12/14. Atomic Safet and Licensing Board Panel. 6pp. 47872:155-47872:160.

I. Financial information

8812220136 Forwards financial disclosure infolincluding 1987 annual 10-K, Sept 198 10-0 8 util statement of Internal cosh flow excluding retained earnings for 12 month ending Sept 1989, per 10CFR140.21 & Reg Guide 9-4. CONWAY.W.F. Florida Power & Light Co. 88/12/14. Document Control Branch (Doctment Control Desk). 91pp. 47886:195-47886:285.

P. Operating license stage documents & correspondence

- 8811230001 Confirms 881102 talent to 881122 moeting to discuss status of perform and annuar cement program & entergency diesol generater upgrade program. ERNST,ML, Ragino 2, Otto the Director 867/1/10 CONWAY,W Fillionda Power & Light Co 2pp. 47652:107-47652:108
- 88112900 to Notification of 881122 incolling w/ut. In Region if old to discuss performance enhancement program & emergency discollegendror upgrade program CRLENIAKIR V. Region 2, Otc of the Director. 88711710; Region 2, Otc of the Director. 10, 47664-198-47664-198.
- 8811280048 Generic Ltr 88:20 to all Idensess Folding OLs & CPs for nuclear power reactor factities re individual plant examiliar severa accident vultierati ities Svc list end CRUTCHFIELD,D. Associate Oriector for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729 024.
- 8812070138 Provides add into to thrawing update program at plant,per 891114 mgs meeting Small bore piping & tubing on selected safety related & miscriant to safety sys were watered down to varily functional by & dovelop isomotries consider, W.F. Flonda Power & Eight Co. 86711730 Document Control Branch (Document Control Dosk). 2pp. 47745-242-47745.243
- 8812050118 Informs that IAEA not find Dept of State that lamity deteled from subsidiary arrangement 1 stang per Article 39 (A)(1) of US/IAEA Sateguards Agroement 8 that Condition 3J of LiCourse OPI-41 team regret per 10CFR75.41. EDISONIGE Project Directorate II 2: 89/12/02. CONV/AY,W F. Florida Power 8: Light Co. 2pp. 47733 357-47733 358
- 8812120137 Requests that util addresses Generic Ltr 88-17 re loss of CHR during nonpower operation Industry has not aggressively responded to resolve concern following identification in Generic Ltr 87-12 MCREST, E. Office of Nuclear Reactor Regulation, Director (Post 870411) 69/12/ 02 HD:BURG.J.J. Florida Power & Light Co. 3pp. 47760 139-47780 141.
- 8812120186 Forwards current schedule for completion of SPDS items per NRC 861027 request CONWAY,W.F. Florida Power 8 Light Co. 88/12/07. Godunnent Control Branch (Document Control Desk). 2pp. 47786:105-47786 186
- 8812130198 Informs of decision not to review util 880201 proposed (censo amend resafety injection accumulators based on listed reasons,)) cluding limited NRC resources EDISONIG E. Project Directorate III.2 88712708 CCNWAY,W F. Fronda Power & Light Co. 4pp. 47796 013-47796 016.
- 8912139211 Not fication of series of meetings between 881212 & and of Jan 1989 w/ util in Rockville,MD to discuss Tech Spec improvement project. EDISON G.E. Project Directorate III-2 68712703 Project Directorate III-2. 2pp 47792.101-47792.102
- 8812160034 Clarifies 881202 discussions w/NRC re drawing update activities & provides add details on notwiles undertaken to assure accuracy of selected drawings to be used in control from for restail & subsequent operation of Unit 3. CONWAY Wiffiord Power & Light Co. 88/12/09 Document Control Branch (Document Control Desk). 6pp. 47830-321-47630-326.
- 8812200197 Submits requested addition of emergency power systemacement project Project with be impremented in two phases consisting of outage & pre-outage activities to meet kilograted schedule 1990 completion date CONYMY/WF Flords Power & Light Co. 88/12/14 Document Control Branch (Document Control Dosh). 3pp. 47664 193-47864:195
- 8812230027 Application for amends to Licenses DPR-31 & DPR-41, separating current requirements for effective liming conditions for operation for deset generator operation Fee paid.

 CONWAYW F. Florida Power & Light Co. 88/12/20 Document Central Branch (Document Central Desk). 18pp. 47916.087-47916;110
- -8812230029 Proposed Tech Specs to electrical power sources
 Florida Power 8 Light Co. 88/12/20 26pp 47916 085-47916 110

Q. Inspection reports, IE Bulletins & correspondence

- 8811300209 Forwards summary of 880921 meeting to assessment of SALP Repts 50-250/89-15 & 50-251/89-15 Corrected pages to SALP repts also enci ERNST,M.L. Region 2, Otc of the Director, 88/11/18 CONWAY,W.F. Flonds Power & Light Co. 39pp. 47673 285-47673 339.
- --8812060272 Corrected pages to SAI P Repts 50:250/08-15 & 50:251/88-15 for June 1987. June 1988. June 1988. NBC N
- 8811300585 Forwards Insp Repts 50:259/88:29 & 50:251/88:29 on 681017:21.No violations or devisitions noted. DECKERJT R Region 2, Oto of the Director, 89/11/18, CONWAY,W.F. Florida Power & Light Co. 2pp. 47673:223-47673:238.
- -8811300567 Insp Repts 50:250/88 29 & 50:251/88:29 on 681017:21.No violations or devations noted Major areas inspected confirmatory measurements,PASS & Aug 1988 spent fuel pool spil.

 ADAMOVITZ.S.S. KAHLE,J.B. Region 2, Ofc of the Director 88/11/17, 14pp 47673:225-47673:238.
- 8811160211 NRC Info Notice 68-030, "Unauthonzed Removal of Industrial Nuclear Gauges." Svc list onci.
 CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Satety (Post 870729) 88/11/22. Consolidated Ed son Co. of New York, Inc. 99pp. 47708 255-47708:257.
- 8811160467 NRC Info Natice 88 091, "Improper Administration & Control of Psychological Tests," Swit Ist and IROSSICE, Division of Operational Events Assessment (Post 870411), 88/11/22 Consolidated Edison Co. of Naw York, Inc. 101pp 47708 042-47708 142.

- 8812080050 Forwards Insp. Repts. 50-250788-28 & 50-251788-28 on 861003.01 & 881017-21 & nonce of violations. HERDT A.R. Region 2, Otto of the Oriector 88711723 CONWAY,W.F. Florida Poses & Light Co. 2pp. 47783:161-47783
- -8812080851 Notice of violation from inspiron 881003-07 & 17-21 Violation roll measures to assure that design basis adoquately transmitted to procedure & instructor's not adequate & fature to establish inspirogram for HXs. HEROT, A.R. Rug on 2, Oic of the Director 88/11/23, 3pp. 47783-163-47783-165.
- --8812080054 Insp Riapts 50-250/88-28 & 50-251/88-28 on 881003-07 & 17-21 Vice fors noted Major areas inspected HX replacement, Inservice Insp,housekeeping 133 dentication 8 control 8 mail control KERINSORIGE, W.O. CARRICON, R.P. BLAKE J.J. Region 2, Otc of the Circutt, 89:11/17, 18pp 47783-166-47703-183
- 8812080057 Forwards insp. Hopis 50:250/88:30 & 50:251/88:30 on 880926. (028 & notice of vikidation. REYES,L A Region 2, Ofc of the Director 88/11/20. CONWAY,W.F. Florida Pener & Ught Co. 2pp. 47750:085-47750:105.
- -8812080058 fronce of violation from Inspion 880920-1028 Violation noted and tite neutron flux monitor in control from silenced by operations personnel & fICO attempted to makeup using sofely bond each using Socren 88 of AP 0100,32.

 REYES, L.A. Rog on 2, Otc of the Director 88/11/23, 2pp. 4/750,087,47750,060
- --8812080059 Insp. Ropts 50-250/68-30 & 50-251/88-30 on 880926-1028. Victobrs noted Major areas inspected suive/lance observations,ESF, operational entity vents at the 8 factily mode & plant events 8817CHER.R.C., MCELHINNEY,T.F., SCHENBULG A. Region 2, Old of the Date 9 89/11/23, 17pp. 47750 G89-47750 105.
- 8812080192 Forwards Irisp Flopts 50-250/88:33 & 50-251/88:33 on 881031- 11947ct violations or deviations rested HERDTIAR Rigging 12, Oficial the Director 88/11/29 CONWAY,W.F. Florida Power & Light Co. 2pp. 47783 299-47783 314.
- -6812080193 (nsp. Repta 50-250/68/33 & 50-251/68/33 on 881031-1104 (Nu. v.claces) or deviations noted. Major atoms inspected inservice insp. (ISI) including review of ISI plan for outlage for Unit 4 & review of NDE procedures. NEWSOME, R.W., BLAKE, J.J. Region 2, Ofc. of the Director. 88/11/22 14₈₇ 47763 331-47763 314.
- 8811290030 NRC Info Notice 89 093, "To'etherapy Events" Svc tist enct. CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Safety (Post 670729; 68/12702 Consolidated Echson Co. of New York, Inc. 112pp. 47811 103 47811 215
- 8811290538 GRC Info Notice 88 034, "Potentially Undersized Valve Actuators 1 Svc Island ROSSI,C.E. Owis on of Operational Events Assessment (Post 870411) 8871272 Conschdated Edison Co. of New York, Inc. 121pp 47708:143-47708:254.
- 8812140199 Advisos that Steam Generator A tube plugged on 881122.per 881027-1115 1350. CONWAY,W.F. Florida Power & Light Co. 88/12/07. Document Control Branch (Occurrent Control Desk). 1p. 47812-058-47812.059
- 8812020287 NRC title Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Veridous," Svc 1st encl. ROSSICE. Division of Operational Events Assessment (Post 870411). 68/12/08 Censolated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302.
- 8812200161 Forward9 Insp. Ropts 50:250/88:34 & 50:251/88:34 on 88:1031- 1:104 & notice of violation JULIANIC A. Floging 2, Ofc of the Director, 88/12/15. CONWAY,W.F. Florida Power & Light Co. 2pp. 47867-288. 47867;298.
- -9612200164 Notice of violation from insp on 881031 Violation noted: Procedure G ADM-209 requirements not adhered to in that NRC inspectors identified several components not tagged wimpted tag within 24 h JULIAN.C.A. Region 2, Otc of the Director, 86712715, 2pp. 47667-280-47867:291
- -8812200167 Insp. Plopts 50:250/88:34 & 50:251/88:34 on 881031-1104. Violation noted Major arona inspected mods & dosign control. Inspector followup hom to increasisent practices re-record rotention for completed design packages noted JURY.K. GIBSS.R. BELISLE,G.A. Ridgion 2, Ofc. of the Director. 68/12/08. 7pp. 47867:292-47867:298.

R. Periodic operating reports & related correspondence

- 8811288041 Forwards summary of mgt-on-shift wookly repts,per Commission 871019 order.
 CONWAY,W E. Florida Power & Light Co. 88/11/07. ERNST,M L. Region 2, Ctc of the Director, 36pp. 47662:321-47662:356.
- 8811290141 Forwards mgt-on-shift weekly ropts for wk starting 881104, por 871016 order & plant supervisor-nuclear shift ropts. COMMAY WF. Florida Power & Light Co. 88/11/16. ERNST,M.L. Region 2, O'c of the Director 34pp. 47863:001-47863:034.
- 8811290367 Forwards select sys assessment progress summary for Oct 1988 CONWAY,W.F. Florida Power & Light Co. 88/11/23 Document Control Branch (Document Control Desk). 2pp. 47664 213-47684:214.
- 8812060114 Forwards mgt-on-shift weekly rept for wk starting 881111,per 871019 order Plant supervisor nuclear shift repts also end. CONWAY.WF. Florida Power 8. Light Co. 88/11/23 ERNST,M.L. Region 2, Oic of the Director. 34pp. 47734:199-47734:232.
- 8812160071 Forwards mg1-on-shift weekly rept for wk starting 881118,per Comm-ssof 871019 order. CONWAY,W.F. Florida Power & Light Co. 88/11/30. ERINST,M.L. Region 2, Oic el the Director, 29pp. 47873 237-47873-285

8812200131 Forwards summary of mgt-on-shift weekly rept & plant supervisor-nuclear shift rept for wk starting 881125
CONWAY,W.F. Florida Power & Light Co. 88/12/07 ERNST,M.L. Region 2, Ofc of the Director 31pp 47864 233

8812200008 Forwards monthly operating status repts for Nov 1988 for Turkey Point Units 3 & 4 & St Lucie Units 1 & 2 & corrected unit shuldown & power reductions rept for Turkey Point Unit 3 for Oct 1988 CONWAY,W.F. Flori

-8812200013 Monthly operating repts for Nov 1998 for Turkey Point Units 3 & 4 & St. Lucia Unite 1 & 2 BONETT, D.M. Florida Power & Light Co. 88/11/30, 16pp. 47868-334-47868.349.

S. Reportable occurrences, LERs & related correspondence

8811230275 Special reption 881012,13:25 & 23.lvd line protection impairments left open in excess of Tech Specs purmitted time I mits Gaused by either plant mode or equipment maint Plant continues to implement compensatory measures as applicable CONWAY,W.F. Flurida Power & Light Co. 88/11/18. Document Control Branch (Document Control Desk). 5pp. 47651:318-47651.322

V. Operator Examinations

8812080119 Requests that ut I provide fisled items for requalification program evaluation scheduled for Feb & Mar 1889
JULIAN,C A. Region 2, Oic of the Director, 88/11/25 CONWAY,W F. Fleilda Power & Light Co. 6pp. 47784 338-47784 343

DOCKET 50-252 UNIV. OF NEW MEXICO RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8812140211 Advises that licensoo 881110 update to physical security plan classified as proprietary into per 100FR2.790(d)(1) MURRAY,B. Region 4, Ofc of the Birector. RR/12/08 WILLIAMS,F. New Mexico, Univ. of, Albuquerque, NM. 2pp. 47821:104-47821:105.

DOCKET 50-264 QUAD-CITIES STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812150130 Ack receipt of 881118 its in response to NRC 880928 fir describing labor relations allegation to adverse impact on guard force supervisors due to terminations of two supervisors & lack of corporate mpt support
 NORELIUS, C.E. Region 3, Ote of the Director, 88/12/02 REED,C. Commonwealth
 Edison Co. 2pp. 47826 290 47826 292

--8812160131 Forwards response to allegations to society activities. Response withhold (ref. 10CFR2.780).
BLISS,H.E., Commonwealth Edison Co., 86/11/18, DAVIS,A.B. Fteglan 3, Ofc of the Director. 1p. 47826 292-47826 292.

- 8812130050 Forwards results & conclusions of umergency operating procedures Insp. Repts 50:254/88-200 & 50:265/88-200 on 880/18-28 Insp. identified facility not having complete understanding of emergency procedures development process. HOLAHAN,G.M. Division of Reactor Projects III.V.V & Special Projects (Post 870411), 88/12/05, REED,C. Commonwealth Edison Co. 9pp. 47798:140-47798.184.
- →8812130051 Emergency Operating Procedure Insp Repts 60-254/88-200 & 50-265/88-200 on 880718-29.Major areas insp compared Rev 4S of BWR Owners Group emergency procedures guidelines to plant specific technical guidelines VANDENBURGH.C. KONKLIN,J.E. HAUGHINEY,C.J. Division of Reactor Inspection & Safeguards (Post 870411), 88/11/21, 36pp. 47798:149-47798.184
- 8812190365 Forwards Salety Insp Repts 50 254/88-28 & 50-265/88-27 on 8B1001-1203 & notice of violation CLAYTON,B. Repton 3, Otc. of the Director. 88/12/13. REED,C. Communicalith Edison Co. 2pp. 47850:208-47850 223.
- -8812190376 Insp. Repts 50:254/88:26 & 50:265/88:27 on 881001-1203. Violations noted Major larges inspected plant operations, radiological controls, maint/ surveillance, emergency preparedness, security & engineering/technical support. RING,M.A. Region 3, Otc of the Director. 88/12/13 13pp. 47850:211-47850:223.

P. Operating license stage documents & correspondence

- 8811290129 Application for amonds to Liconses OPR-29 & DPR-30,doleting snubber listing w/Tech Specs Section 3/4.7.9 & ref to hydraulic snubbors which are no longer used at pant in safety-related applications.Fee paid JOHNSON,LM. Commonwealth Edison Co. 88/11/15. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47650.214-47650.237.
- -8811290131 Proposed changes to Tech Spacs, deleting snubber tables & ref to hydraulic snubbors

Commonwealth Edison Co. 88/11/15, 22pp. 47650 216-47650.237.

- 8812070033 Application for amends to Uconses OPR-29 & DPR-30,changing Intervals at which local leak rate tests of MSIVs performed from 18 to 24 months Fee paid JOHNSON,I.M. Commonwealth Ed.son Co. 88/11/16. MURLEY,T.E. Document Control Branch (Document Control Branch (Document Control Disk). 2pp. 47745 343-47745-348.
- -8812070034 Proposed Tech Specs re surveillance requirements & leak rate testing of
 - MSIVs. * Commonwealth Edison Co. 88/11/16 4pp. 47745 345 47745 348
- 8811220055 Forwards Rev 52 to OA Program Topical Rept CE-1-A.por 881110 request SHEWSKI,W.J. Commonwealth Edison Co. 88/11/17. MULLER,D.R. Project Directorate III-2. 1p. 47663-063-47663-088.

- 8811230025 Not lies of typo in Page 2 of IM Johnson 881110 ftr ra util commitment for providing indication for reactor, water level in order to meet NRC Reg Guide 1.97. Correct value for Reg Guide 1.97 complance is "1.57." JCHNSON,IM Commonwealth Edison Co. 88/11/17 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 1p. 47651.323-47651.323.
- 8812120020 Forwards revised Tech Spec pages replacing Attachment 1 in its entirety & refliciting changes resultant from hydrogen water chemistry program,per 880916 sub-initial of proposed license amond. Revincorporates additinto & corrects types JOHNSON, M. Commonwealth Euison Co. 88/11/10, MURLEY,T. E. Office of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 47797:335-47797.348.
- --8812120021 Proposed Tech Spec Pages 3.174.1-3,3.174.1-8,3.174.1-9, 3.174.1-10,3.27 4 2-6 & 3,2/4 2-11.
 * Commonwealth Edison Co. 88/11/18, 12pp, 47797,337-47797,348.
- 8811280048 Generic I.tr 88-20 to all Econsees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list
 - CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024
- 8812010305 Provides analysis of Reg Guide 1.99,Rev 2, "Radiation Embrittlement of Reactor Vessol Mat's" for impact on pressure-temp heatup & cooldown curves con-tained in Tech Spocs per Genoric Lir 88-11. RICHTER,M.H. Commonwealth Edison Co. 88/11/28 Document Control Branch (Doc-ument Control Besk). 2pp. 47703-049-47703-050.
- 8812070243 Requests FH publication of netro of consideration of issuance of amends to Licenses DPR-28 & DPR-30 & proposed NSHC determination & opportunity for hearing on 881116 request to revito Tech Spec 4.7 A 2.d.2 concerning MSIV6 ROSS,T. Project Directorate III-2 88/12/01 NRC No Detailed Athillation Given 6pp 47748.349-47748.354.
- 8812070030 Requests FR publication of notice of consideration of issuance of amends to Licenses DPR-29 & DPR-30 & proposed NSHC determination & apportunity for hearing on 880916 & 1118 requests to change Toch Specs to help reduce ISSCC HOSS,T.M. Project Directorate III-2, 88/12/02, NRC No Detailed Affiliation Given. 7pp. 47746-238-47746-244
- 8612200014 Requests review of BWR Owners Group position prior to requiring commitment to replace analog transmitter trip units credit beards
 Sit ADY, J.A. Contributed Billion Co. 88/12/15. MURLEY, T.E. Office of Nuclear
 Reactor Regulation, Director (Post 870411). 2pp. 47862 198-47862.199.

- 8811290014 Forwards response to NRC 881021 ltr ru violations colled in Insp. Repts 50-2547(NJ-15 & 50-2657(BI-15 Corrective actions wire landed per drawings & mod test for Mod MH-2-8B-66A successfully completed. BLISS,H.E. Commonwealth Edward Co. 89/11/21. Document Control Branch (Document Control Desk), 5pp. 47864 001-47894 005.
- 8811300037 Responds to NHC 881020 ftr re violations noted in Insp Repte 50-254/88-21,50-254/88-11,50-255/88-21 & 50-265/87-11 & proposed imposition of civil penalty in amount of 5150,000 Corrective actions AMP spaces repaired & instalted. DELGEORGE, L.O. Commonwealth Edison Co. 88/11/21, LIEBERMAN,J. Otc of Enforcement (Post 870413), 4pp. 47698 332-47698 335.
- 8811300041 Responds to NRC 881020 ftr re violations noted in Insp. Ropts 50-264/86-21,50-254/87-11,50-265/86-21 & 50-265/87-11 re use of unqual fied AMP hylon-insu lated butt splices in GE FOI containment penetration anclosures at factily. FIELDMANU, Sidipy & Austin. 18/11/21 LIERERMANU, Orc of Enforcement (Post 870413), 9pp. 47680-253-47680-261.
- 8811160211 NRC Into Notice 88 090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list encl CUNNINGHAM,H.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88711722. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811180467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Tests." Svc 1st encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/11/22 Conspirituated Edison Co. of New York, Inc. 101pp. 47708.042-47708 142.
- 8811290153 Submits supplemental response to IE Bulletin 84-03, "Refueting Cavity Water Soal" Util confident in ability to ensure sale & effective plant condition during Water Soal refueling outage.

 JOHNSON,I.M. Commonwealth Edison Co. 88/11/22, MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 4pp. 47649 255-47649,258.
- 8812020198 Forwards Safety Insp. Repts 50-254/88-05 & 50-265/88-05 on 880808-1028 Unresolved items klonitical boing reviewed for potential enforcement actions.
 GREGER, L.R. Ragion 3, Otc. of Illia Director. 88/11/28. REED,C. Commonwealth
 Edison Co. 2pp. 47717.205-47717:218
- -8812020201 Insp 13ppts 60-254788-05 & 50-265788-05 on 880808-1028. Violations noted Major areas inspected licensee action following identification that loding removal design basis used in control room habitability differs from Tech Spec.

 GILL, C.F., GREGER, R. Region 3, Otc of the Director, 88/11/28, 12pp, 47717:207-47717:218
- 8812020240 Contirms plans for 690104 public meeting at plant visitor ctr to prosont SALP 7 rept for plant Appropriate corporate & plant mpt representation oncouraged to attend meeting to ensure mutual understanding of NRC issues & lindings. GREENMAN,E.G. Region 3, Ofc of the Orector 88/11/29, REED,C. Commonwealth Edison Co. 2pp. 47721:093-47721-094
- 8812080222 Forwards SALP 7 Board Repts 50:254/88:01 & 50:265/88:01 for Apr 1987 Sept 1988 DAVIS,A B. Region 3, Olc of the Director, 88/12/01 REEO,C. Commonwealth Edisor Co. 3pp. 47755:187-47755:228.
- --8812080224 SALP Ropts 50-254/98-01 & 50-265/88-01 for Apr 1987 Sept 1988.
 * Region 3, Otc of the Director, 887/12/01, 39pp, 47755,190-47755 228.

- 8811290030 NRC Info Notice 88-093, "Teretherapy Events." Syc list end. CUNN NGHAMIRIE. Orvision of Industrial 8 Medical Nuclear Safety (Post 870729) 68/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88:094, "Potentially Undersized Velve Actuators." Svc fist enci ROSSI C.E. Dists on of Operational Events Assessment (Post 870411) 89/12/02 Consolidated Edison Co. of New York, Inc. 121pp, 47708 143-47708:254.
- 8812130050 Forwards results & conclusions of emergency operating procedures Insp. Repts. 50:254/88:200 & 50:265/88:200 on 880718:29 has identified facility not having complete understanding of emergency procedures development process. HOLAHANIG.M. Division of Reactor Projects 13,10V. & Spacial Projects (Post 870411), 89/12/05 REED.C. Commonwealth Edison Co. 9pp. 47798:140-47798:184
- ~8812130051 Emergency Operating Procedure Insp Repts 50-254/88:200 & 50-265/89: 200 on 880718-29. Major areas insp compared Rev 4S of BWR Owners Group emer-gency procedures guidefines to plant specific technical Guideinas VANDENBURGH, C., KONKLINJ, E., HAUGHNEY, C.J. Division of Reactor Inspection & Safeguerds (Post 870411), 88/11/21, 36pp. 47798-149, 47798-184
- 8812020287 NRC Info Notice 88 695, "inadequate Procurement Requirements Imposed by Licensees on Vendors" Svc list end! ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/08 Consolidated Edison Collof New York, Inc. 112pp. 47807:181-47807.302
- 8812190343 Forwards Safety Insp. Repts 50:254/88:27 & 50:265/88:28 on 881114-1213 8 notice of violation.
 MILLER, J. Region 3, Otc. of the Director. 88/12/13 REED,C Commonwealth
 Edison Co. 2pp. 47855 029 47855 043.
- -8812190346 Notice of violation from inspiron 8811114-1213. Violation noted failure to provide adequate testing for environ qualification of electrical equipment important to safety MILLER, H.J. Region 3, Otc of the Director, 88/12/13, 1p. 47855-031-47855-031.
- -8812190350 Insp Repts 50-254/88.27 8 50-265/88.28 on 681114-1213. Violations noted Major areas inspected instrumentation sys for assessing plant conditions during 8 following accident 8 licensee action on previously Identified 10CFR50.49 finding GAUTAM, S., GARDNER, N. Region 3, Old of the Director 88/12/13: 12pp 47855.032-47855.043.
- 8812190365 Forwards Safety Insp Repts 50-254/88-26 & 50-265/88-27 on 881001-1203 & notice of violation. CLAYTON,B. Region 3, Otc. of the Director. 88/12/13. REED,C. Commonwea/th Edison Co. 2pp 47850:208-47850.223
- --8812190370 Notice of violation from inspiron 681001-1203. Violation noted instrument air dryor returned to sec w/o reviewing applicable drawing resulting in improper shut off of sec air supply to instrument air hoader. CLAYTON,B. Regon 3, Ofc of the Director 88/12/13 1p. 47850 210-47850 210.
- -8812180376 Insp. Repts 50:254/88:26 & 50:265/88:27 on 881001:1203. Violations noted Major areas Inspected plant operations, radiological controls maint/ surveit ance emergency preparedness, security & engineering (technical support. RING, M.A. Region 3, Otc of the Oriector, 88/12/13 13pp 47850 211-47850 223.
- 8812270202 Forwards atfidavit of PM Holzman supporting utli response to NRC 881020 notice of violation & proposed civil penalty reluse of AMP hylon-insulated butt splices at plant per listed insp repts
 FIELDMAN,J. Sidley & Austin. 88/12/19 LIEBERMAN,J. Old of Enforcement (Post 870413) 4pp. 47927:130-47927:133

R. Periodic operating reports & related correspondence

- 8812190388 Forwards listing of changes tests & experiments completed for Nov 1988 ROBEY, R.A. Commonwealth Edison Co. 88/11/28. Office of Nuclear Reactor Regulation, Director (Post 870411). 17pp. 47852 097-47852.113
- 8812200010 Monthly operating repts for Nov 1988 for Cuad Citios Nuclear Power Station Units 1 & 2 W/861128 lfr.
 DEELSNYDER,L. ROBEY,R.A. Commonwealth Edison Co. 88/11/30, 37pp. 47870.348-47871.023.

DOCKET 50-255 PALISADES NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

- 8811280116 Rev 2 to Emergency Implementation Procedure El-15.2, "Communications BRUNET, J.R., DAWSON,M. Consumers Power Co. 88/07/20 5pp. 47654.052-
- 8812010190 Rev 0 to Emergency Plan Implementation Procedure Ef-12.3, "Search & Rescue Team Responsibilities" GADDIE.K., FORD,W.L., ROGERS,D.W. Consumers Power Co, 88/11/16. 5pp. 47703-023-47703-027.
- 8812010195 Temporary Change Notice TCN:EI-88-001 to Pages 3.4 & Atlachments to Rev 15 to Emergency Implementation Procedure EI-1, "Activation of Site Emergency Plant/Emergency Classification."

 DAWSONIA, ROLLEYJ, KOZUP,C.S. Consumers Power Co. 88/11/17, 11pp. 47703.028-47703:039.
- 8812020143 Forwards Safety Insp Rept 50-255/88-25 on 881013-1114.No violations NOTES ON W.L. Region 3, Ofc of the Director, 88/11/22, HOFFMAN, D.P. Consumers Power Co 2pp 47707:195-47707:297.
- -8612020144 Insp. Rept. 50-255/88-25 on 881013-£114.No violations noted. Major areas inspected-quarterly rigit meeting, followup on previous (nsp. fundings, operational safety, mainteurveillance & physical security, BURGESS, B.L. Region 3, Oic of the Director. 88/11/21, 11pp. 47707.197-47707:207.

- 8812060129 Ack receipt of 881101 ltr requesting change to plant site enrorgercy planspectically, change to minish it staffing guidelines Changes will not recrease at fectiveness of emergency plan atthough some items need clarification GREGERL R Region 3, Otto at the Director 88/11/28 HOFFMAN, DP Consumers Power Co. 2pp. 47743-014-47743.015
- 8812070140 Revised emergancy Implementing procedures, consisting at Rev 20 to day holders histRay 21 to Index 8 Rev 13 to App G, "Emergency Telephone Nurters Augmentation List"
- Consumers Power Co. 88711729, 13pp, 47746:308-47746-320
- 8812140219 Rev 2 to Attachments 1,2,3 & 4 to Emergency Plan Implementing Procedure Et 15.2, "Communications Test."
 * Consumers Power Ca. 88711729 Gpp. 47812.063-47812.068
- 8812140223 Rev 8 to Section 8 of site emergency plan RIDLEY,J. Consumers Power Co. 88/11/29, 15pp. 47813,336-47813,350
- 8812140225 Rev 0 to Page 3 of Emergency Plan Implementing Procedure F1121 "Search & Rescue Team Responsibilities" Consumers Power Co. 88/11/29, 2pp. 47811 271-47811 272
- 8812050226 Submits addl into In response to IE Insp. Rept. 50:255/86-22 re-tre protection Commitment to carry portable lanterns withdrawn. SMEDLEY,R.W. Consumers Power Co. 88/12/01. Document Control Brench (Ibserment Control Desk). 2pp. 47733:156-47733-157.
- 8812060069 Responds to 880415 request for add, Info re NUREG-0737,fform 1-K-56, "Reactor Coolant Pump Trip " Emergency operating procedures and SMEDLEY,R.W. Consumers Power Co. 88/12/01. Document Control Brain to (N.Y., ment Control Desk), 11pp. 47740-334-47741-039.
- -8812060078 Rev 1 to Emergency Operating Procedure EOP 1.0, "Std Post Tro Ac SMITH,B.H. Consumers Power Co. 88/08/11, 23pp. 47740,345,47741,007,
- 8812090280 Advises that Rev 7 to suitability, from ng & qualification plan coreasterit will provisions of 10CFR50.54(p) & acceptable. GREGERIL R. Rigion 3, Otto of the Director. 88/12/01 JOHNSON,RID Centurys Power Co 2pp. 47782 277-47782 278
- 8812120243 Flov 8 to Section 5 of site emergency plan. KOZUP,C S. Consumers Power Co. 88/12/08, 33pp. 47/85 310-47785 345
- 8812120254 Rev 9 to Section 4 of site emergency plan DAWSONIAL KOZUPICIS, FIDLEY J. Consumers. Power: Co. 88712766 14pp 47788 282-47786 275
- 8812210100 Revised emergency plan implementing procedures, consisting of Flov 22 to "General Otc Response Team/Emergency Operations Faculty (FOF) Procedures Indox" & Rev 2 to App. H. "General Otc Emergency Planning EOI

P. Operating license etage documents & correspondence

- 8811290467 Flav.ses util 801218 commitment medd in response to NURFG-07127 in 1C 2, "Shift & Relief Turnover Procedures." Util will maintein sys which evaluates of factiveness of shift & relief turnover procedure on period c basis FRISCHARA Consumers Power Co. 88/11/21. Document Control Branch (Dorman) Control Desk) 2pp. 47651.199.47651.200
- 8811290479 Discusses impact of Reg Guide 1,99,Roy 2 on operations in response to Generic Ltr 88-11.
 SMEDLEY, R.W. Consumers Power Co. 88/11/21. Document Control Branch (15-59 ment Control Desk). 2pp. 47850-139-47650-140.
- 8811280048 Generic Etr 88-20 to all Ficensina holding Ots & CPs for nuclear positivactor facilities to individual plant exam for severe accident varioustatifies 6-c (4 CRUTCHFIELD.D Associate Director for Projects (Post 670411) 88/11/23 Comparing dated Edison Co. of New York, Inc. 81pp 47728:303-47729:024.
- 6811298505 Forwards correction to Amond 118 to License DPR-20,adding limitatio 4.9 plant operations witess than 4 reactor coofent pumps operating Revised Tech Spr. Regs. 3-th correcting error end.

 WMMBACH, I.V. Project Directorate III-1 88/11/23 BERRY,R.W. Costumers 102 a.

 Co. 3pp. 47640-194-47640-197.
- →8811290511 Errata to Amend 118 to License UPR-20 revising Tech Specifoladd its Discussions on plant operations w/less than four reactor coolant pumps operate (in Project Directorate III-1, 88/11/23, 1ρ. 47648,197-47648 197
- 8812050231 Forwards pretiminary "Analysis of Reactor Prossure Vessel Fast Flurcic for Pallsades Nuclear Plant Through End of Cycle 8," per 880309 communical Fluoria neutron source file noted in right Revised rept will be submitted by 880401 SMEDLEY,R.W. Consumers Power Co. 88/11/30. Decument Control (trauch (Desument Control Desk), 2pp. 47720.067-47720.068.
- 8812050233 Proliminary "Analysis of Reactor Pressure Vessel Fast Fluence for Pasades Nuclear Plant Through End of Cycle 8."
 * Consumers Power Co. 88/11/30, 61pp. 47720,089-47720,130
- 8812060069 Responds to 880416 request for additinfoire NUREG-0737,ttom: K-35, "Reactor Coolant Pump Ting." Emergency operating procedures and: SMEDLEY,R.W. Consumers Power Co. 88/12/01. Document Control Branch (\$3.50) ment Control Dest), 11pp. 47740-334-47741-039.
- -8812060078 Rev 1 to Emergency Operating Procedure EOP 1.0, "Std Post-Tep At lons." SMITH,B.H. Consumers Power Co. 88/08/11, 23pp. 47/40.345 47741 097
- --8812060089 Rev 0 to Engineering Analysis Workshoot EA-RJC-88-01, * Calculation of Loop Accuracies for Rosemount Transmitters Ouring Small Break LOCA ** Consumers Power Co. 88/11/22, 8pp. 47741:008-47741.015.

* Consumers Power Co 88/11/22, 13pp, 47741-016-47741-02B

- -8812060101 Roy 0 to Engineering Analysis Workshoot EA-RJC-88-03, "Instruction Loop Accuracy Calculations PCS Temp Loops."

 * Consumers Power Co. 68/11/22, 11pp. 47741 029-47741.039.
- 8812080114 Requests that util address Generic Ltr 88-17 re loss of DHR during non-power operation Industry response to Generic Ltr 87-12 deficient in areas of preven-tion of accedent initiation & milgation of accidents MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/ 02 MCCORMICK,W.T. CMS Energy Corp. 3pp. 47756 359-47756 361
- 8812080158 Confirms 881208 mouting in Hegion III afcito dicuss ficensee actions ro 881028 fit & plant personnol contamination avents,per 881129 telcon GREENMAN,E.G. Region 3, Old of the Director, 88/12/02 HOFFMAN,D.P. Consum-ers Power Co. 1p. 47754.078.47754.078
- 8812120076 Forwards corrected Page 2 to ulil 881201 llr re response to NUREG-0737, Item II K 3.5 re reactor coclant pump trip. Correct statement is "nominal post-trip steam generator pressure expected in range of 800 psia to 980 psia." SMEDLEY, R.W. Consumers Power Co. R8/12/06 Document Control Branch (Docu-ment Control Desk). 2pp. 47788.168.47788.169.
- 8812200312 Advises that implementation of fitness for duty program described in util 880928 fit appropriate.

 NORELIUS,C E Region 3, Ofc of the Director 88/12/09. HEINS,G.L Consumers.

 Power Co. 2pp. 47868 351-47868 353
- --8810070105 Forwards response to litness for duty allegation analyzing allegation & addressing actions taken Encl withheld.
 JOHNSON B D. Consumers. Power Co. 88/09/28. Document Centrol Branch (Document Control Desk). 1p. 47868.353-47968.353
- 8812160107 Forwards Amend 118 to License DPR-20 & safety evaluation. Amend de-letes steam generator differential pressure limit from 1ech Spacs. WAMBACH,T.V. Project Directorite III-1, 88/12/12 BERRY,K.W. Consumers Power Co. 3pp. 47873:334-47873.342
- --8812160109 Arnend 119 to License DPR-20, detailing steam generator differential pros-sure limit from Tech Space
- QUAY, T.R. Project Directorate III-1 88/12/12 4pp. 47873.337-47873.340.
- --8812180110 Safety evaluation supporting Amend 119 to License DPH-20.

 **Office of Nuclear Reactor Regulation, Director (Post 870411) 88712712 2pp 47873 341-47873:342
- 8812220168 Informs of change of completion date for both painel & wiring diagram verification & drawing update efforts by and of first quarter of 1991 FRISCH.R.R. Consumers Power Co. 88/12/13 Document Control Branch (Document Control Dosk) 1p. 47903-188-47903-198.

O. Inspection reports, IE Bulletins & correspondence

- 8811300262 EN-88-102 on 881123,notice of proposed imposition of civil panalty in amount of \$150,000 will be issued to licensee. Action based on violations of requirements for environ qualification of certain items of electrical equipment WONG,N. LIEBERMAN,J. Ofc. of Enforcement (Post. 870413) 88/11/18, 1p. 47670-380-47670.360.
- 0811160211 NRC Info Notice 88-099, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list ond CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 90pp. 47708 255-47708:257.
- 8811160467 NDC Info Notice 88-001, "Improper Administration & Control of Psychologi-
- cat Tests." Svc list encl. ROSSI.C.E. Dwiston of Operational Events Assessment (Post 870411). 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142.
- 8812020143 Forwards Safety Insp Rept 50-255/88-25 on 681013-1114 No violations AXELSON,W.L. Region 3, Ofc of the Director, 88/11/22, HOFFMAN,D.P. Consumers Power Co. 2pp. 47707:195-47707:207.
- --8812020144 Jusp Hept 50-255/88-25 on 881013-1114 No violations noted Major Bruas inspected quarterly migh meeting following on previous insp. lindings, operational safety, maint, survollance & physical security.

 BURGESS,B.L. Region 3, Ofc of the Director. 88/11/21, 11pp. 47707;197-47707;207.
- 8811300534 Forwards notice of violation & proposed Imposition of civil penalty in amount of \$150,000-Violation based on failure to specify appropriate performance requirements & to conduct appropriate testing of electric equirement DAVIS.A.B. Region 3, Otc of the Director, 68/11/23 HEINS,G.L. Consumers Power Co. 5pp. 47673 249-47673.284.
- --8811300540 Notice of violation & proposed imposition of c'v.l penalty in amount of \$150,000.Violation noted as of 881200.util falled to qualify listed equipment designated important to safety by appropriate testing or testing & analysis.

 DAVIS.A.B. Region 3, Otc of the Director. 88/11/23. 5pp. 47873:254-47873:284
- 8812050226 Submils addi Info in response to IE Insp Ropt 50-255/86:22 re fire protection Commitment to carry portable fanterns withdrawn SMEDLEY,R.W. Consumers Power Co. 88/12/01. Document Control Branch (Document Control Desk). 2pp 47733:156-47733.157
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc list end CUNNINGHAM,R.E. Division of Industrial 8 Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811.103-47811.215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.

- HOSSICE Division of Operational Events Assessment (Post 970411), 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp 47807.191-47807.302
- 8812160073 Forwards Safety Insp Ropt 50-255/88-19 on 880816-1118 Isofated violation noted to valve findup procedure. Description of how util methodology meets re-quirements specified in 10CFR50,App.J should be submitted MILLER.H.J. Region 3. Oic of the Director 89/12/09 HOFFMAN,D.P. Consumers Power Co. 2pp. 47834-337-47834.357
- -8812180075 Insp Ropt 50-255/88-19 on 880916-1118 Violation noted Major areas inspected licensee actions on previous insp findings, containment integrated leak rate lost (CILRT) & CILRT performance winessing MENDEZ R. PHILLIPS, M.P. Rog on 3, Ofc. of the Director 88/12/08 19pp 47834:339-47834:357
- 8812220308 Forwards "Second Interval Inservice Insp Program,Class 1,2 & 3 Components & Supports " Fee pard FRISCH,R.R. Consumors Power Co 88/12/19 Document Control Branch (Document Control Desk). 2pp. 47894:054-47894.318
- -8812220323 "Second Interval Inservice Insp Program, Class 1,2 & 3 Components & Supports " BINNINGTON,W A. Consumers Power Co. 88/12/12, 400pp, 47894.056-47894:318

R. Periodic operating reports & related correspondence

- 8812140261 Monthly operating rept for Nov 1988 for Palisades Nuclear Plant W/881205 PACKARD,G.C., GORALSKI,G. Consumers Power Co. 88/11/30 5pp. 47800.214-47800 218
- 8812220029 Forwards corrective work order backlog & open control room deficiencies for Oct & Nov 1988 Mixt ropt will be submitted in Feb 1989 covering Dec 1988 & Jan
 - 1999 JOHNSON,B.D. Consumers Pawer Co. 88/12/10 Document Control Branch (Document Control Dosk). 2pp. 47903.063-47803.064.

S. Reportable occurrences, LERs & related correspondence

Ing to meet acceptance criteria.Caused by electrical penetrations in control room floor being opened for outage mods W/881117 ltr. KOZUP.C.S., JOHNSON,B.D. Consumers Power Co. 88/11/17 8pp 47654:105-47654:113

8811280019 LER 88-013-01:on 880823,control room HVAC declared inoperable for laif-

- 8812050085 Part 21 rept to potential for counterfed Masonicillari valvo parts being supplied to commercial nucleor facthios. All Identified parts from plant named in 881021 rept segregated 8 reptaced Independent investigation underway. ALLEN.W.1. Dresser Industries, Inc. 88711718 GRIMES.B. Dw. on of Reactor Inspection & Safeguerds (Post 870411). 2pp. 47723 103-47723.104.
- 8811290140 Trip ropt of 881028 s to visit ru nonconforming parts received from Samplo-Webtrof for Masonorian valves Related Info enct. GIRLLENJ, Generic Communications Branch 88/11/23 BERLINGER,CH Generic Communications Branch, 8pp. 47650 238-47650 245.
- 8812020220 LER 88-020-00 on 881027,as-found lift pressure of pressureur sefety valve RV-1039 exceeded Tech Spec limits. Causn unknown & under investigation RV-1039 disassembled, inspectori & adjusted & valve disc replaced W/861128 lt/.
 KOZUP.C.S., JOHNSON,B.D. Consumers Power Co. 88/11/28 4pp. 47707-238-
- 47707:242.
- 8812020167 Forwards ropts of norreal ological NPDES permit violations for 8-month period of May-Oct 1988.

 JOHNSON,8 D. Consumors Power Co. 887/11/29. Document Control Branch (Document Control Dosk). 2pp. 47722 083-47722 089
- --9812020187 NPDES noncompliance notification on 680516 routine sample of turbine sump oil separator tank T-41 analyzed & reported to be 24 mg/L.Caused undetermined Quarterly routine cleaning of oil separator M-18 occurred between sample & analysis time.
 FOBES,R.L. Consumers Power Co. 88/05/23. MORLEY,F. Michigan, State of 2pp 47722 085-47722 086
- ←8812020190 NPDES noncompliance notification on 890616,TRC at discharge rose to 0.3 mg/l Caused by higher than normal amount of sodium hypochilorite inadvertently added during chlorination of cooling tower A.Ut-I will evaluate causes. FOBES,R.L. Consumers Power Co. 88/06/20. 2pp. 47722.087-47722.089.
- 8612050317 LER 86-031-01 on 860912 potential common mode problem re excessive vibration & rosultant failure of confermant air cooler sys identified caused by overlubrication Fan motor hearings replaced & procedures revised W/881201 ltr. KOZUP,C.S., FRISCH,R.R. Consumers Power Co. 88/12/01. 6pp. 47740-172-47740-177.
- 8812060105 LER 86-040-03 on 801217 & 880921,CRD seal housings tested had positive dye penotration indications Causad by transgranular stress corrosion cracking.C-E contracted to perform destructive exams W/881202 III.

 KOZUP.C.S., JOHNSON,B D. Consumers Power Co. 88/12/02 6pp. 47743 070-

47743:076.

- 8812130126 LER 88-021-00 on 881104, several spurious unexplained svc water pump trips occurred Caused by original re'sy settings which did not account for motor svc lactor rating Protective relays reviewed W/881205 ltr.

 KOZUP,C.S., JOHNSON,B.D. Consumers Power Co. 88/12/05. 6pp. 47794/344-
- 47794:340.
- 8812200134 PNO-III-88-097 on 881205 tube leak identified In Steam Generator B.Unit shut down Outage planned to repair leak 8 porform other maint, ac'uding rep'acement of primary coolant pump seal 8 repair of primary safety valve leak.

 BURGESS,B., AXELSON,W. Rogion 3, Olc of the Director. 88/12/08. 1p. 47868:148-47866.146

- 8812200139 PNO-III-88-101 on 881207,ut1 & Bechiel announced signing of egreements for jointly claims acquire facility & to resolve outstanding claims associated w/Midtand Nuclear Frant const project State of MI will be informed BURGESS B., AXELSON,W. Region 3, Ofci of the Director 88/12/08 ip 47870 340-47870 340
- 8812140047 LER 88-015-01 on 880903 fuel bundle observed hanging from bottom of upper guide structure Caused by bundle adhering to guide pins Romainder of fuel bundles in core visually inspected W/881209 for KOZUPICIS JOHNISON BIO Consumers Power Co. 88/12/09 8pp 47814-181-47814-183

V. Operator Examinations

8812210378 Informs that written & operating requalification exams scheduled for wk of 890417 Licensee requested to provide items listed in Encl 1 at lease 60 days prior to exam date

WRIGHT.G.C. Region 3, Ofciol the Director, 88/12/14. HCFFMAN,D.P. Consumers Power Co. 8pp. 47875 292-47875 299.

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 6811300164 Forwards addl into to resolve certain App R draft SER open ttems,per 87023 request Main steam relief valves have two stated shuddown functions GRIDLEY,RIL Tennessee Verley Authority 87/06/22 Document Control Branch (Document Control Desk) 12pp 47676 001-47676 012.
- 8812160091 Forwards "Browns Ferry Muclear Plant Annual Exercise Scenano 1988," per 841011 request Exercise scheduled for wk of 880919. GRIDLEY,R Tennessee Valley Authority 89/08/04 Region 2, Ofc of the Director. 1p 47631/245-47832 243
- -8812160096 "Browns Ferry Nuclear Power Plant Annual Exercise Scenario 1988"
 * Tennessee Valley Authority, 88/06/02, 400pp, 47831,246,47632,243
- 8811290512 Informs that requested into supporting App R audit rescheduled & will be provided by 830203 GRIDLEY,R Tennessee Valley Authority 88/11/22, Document Control Branch (Document Control Oesk) 3pp 47650 078-47650 080
- 8812140029 Forwards safety evaluation of ficensee 860101 & 880404 submittals re 10CR50 App R studiewn analysis Proposed sale shudown capability salisfies re-quirements based upon NRC 881021 approval of exemptions to App R BLACK, SC. Ofc of Special Projects 88/12/08. KINGSLEY, OD Tennessee Valloy Author: y 2pp 47799 245-47789 265.
- --\$512140933 Safety evaluation accepting util App R submittal as applied to adequacy of minimum safe shutdown sys
 * Ofc of Special Projects 68/12/08, 19pp 47799 247-47799 265
- 8812200232 Advises that 881014 Rev 88.2 to radiological emergency plan consistent w/planning stds of 10CFR50.47(b) 8 acceptable. Change re meteorological equipment not consistent w/Reg Guide 1.23. DECKER,TR. Region 2, Ofc of the Director. 88/12/12. TUCKER,H.B. Duke Power Co. 2pp. 47868.302-47868.303.
- 8812200079 Forwards replacement pages to 870611 Rov 8 to physical security/contin-gency plan End withheld [rol 10CFR73 21). GRIDLEY,R Tennessee Valley Authorny, 88/12/13. Document Control Branch (Docu-ment Control Desk) 2pp. 47862 200. 47862 201.
- 881216 # GRIDLEY,R.L. Tennessee Valley Authority 88/12/16 86pp. 47908 304 47907:053.
- 8812210206 Forwards Rev 1 to radiological emergency plan & Rev 18 to Emergency Plan Implementing Procedure BFN EP.P-1. GRIDLEVR. Tennossee Valley Authority, 88/12/16. Document Control Branch (Document Control Desk). 2pp. 47907.063-47907.076.
- -\$812219273 Rev 1 to "Radiological Emergency Plan."
 Tennessee Valley Authority, 88/12/07, 11pp. 47907.065-47907.075.
- -8812210276 Rev 3 to Emergency Plan Implementing Procedure 8FN EPIP-1, Attachment 1.
 * Tennessee Valley Authority, 88/12/16, 1p. 47907.076-47807.078

P. Operating license stage documents & correspondence

- 8811300184 Forwards addition to resolve certain App R draft SER open items.per 870323 request Main steam relief valves have two stated shutdown functions. GRIDLEY.R L. Tennessee Valley Authority 87/06/22 Document Control Branch (Document Control Desk), 12pp. 47676-001-47678-012.
- 8812130143 Forwards Amends 160,157 & 131 to Licenses DPR-33.0PR-52 & DPR-68,respectively & safety evaluation Amends replace all water level refs to top of active bell withoutsponding rel to vessel zero
 BLACK,S. Otc of Special Projects 88/10/19. WHITE,S.A. Tennessee Valley Authority.
 2pp. 47/98/248-47/98:284.
- -8612/30150 Amends 160,157 & 131 to Licenses DPR:33,DPR:52 & DPR:68, respectively, replacing all water level rols to top of active fuel w/corresponding ref to yeseet zero. BLACK, S. Ofc of Special Projects 88/11/28 33pp. 47798 250 47798 282
- -8812130174 Salety evaluation supporting Amends 160.157 & 131 to Ucanses DPR-33.DPR-52 & DPR-88 respectively

 'Office of Nuclear Reactor Regulation, Director (Post 870411) 88/11/28 2pp.
 47788.283-47788.284

- 8812020185 Forwards Amends 158,154 & 129 to Elconsis DPR-33,DPR-52 & DPR-68,respectively & safety ovaluation Amend changes definitions of mode of operations,core afteration & reactor conditions BLACK,S. Otic of Special Projects 88/11/18, WHITE,S.A. Tonnessee Valley Authority, 2pp. 47710-171 47710-335.
- --8812020186 Amends 158,154 & 129 to Licenses DPR-33,DPR-52 & DPR-69, respectively, changing definitions of mode of operation, core alteration & reactor conditions for facility.
- BLACK,S. Ofc at Special Projects 88/11/18 155pp 47710 173-47710:327.
- -8812020191 Safety evaluation supporting Amends 158,154 & 129 to Licenses DFR-33,DFR-52 & DFR-68,respectively.
 * Otc of Special Projects 88/11/18 8pp 47710 328-47710 335.
- 8812080235 Forwards Amends 159,155 & 130 to Licenses DPR-33,CPR-52 & DPR-68,respectively & safety evaluation Amend will add ASME Section XI pump & varve program dofinition & change applicatio testing frequencies to reliablination BLACKS, Ober of Special Projects 88/11/22, KINGSLEY,O D. Tonnessee Valley Authority, 2pp. 47755-047-47755:163.
- ~8812060243 Amends 159,155 & 130 to Licensos DPR-33,DPR-52 & DPR-68, respectively,adding ASME Section XI pump & valve program detention & changing applicable tosting frequencies to ret definition. BLACK,S. Ofe of Special Projects, 88/11/22 113µp, 47755.040-47755-161
- -8812080246 Safety evaluation supporting Amonds 159,155 & 130 to Licenses DPR-33,DPR-52 & DPR-68,respectively.
 * Otc of Special Projects 88/11/22 2pp 47755 162-47755-163
- 8811280048 Generic Ltr 88-20 to all licensoes holding Obs & CPs for nuclear power reactor facilities re individual plant exem for severe accident vulnerabilities Svc list encl CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729 024.
- 8811300510 Notification of 881130 meeting w/ut1 in Rockvilla,MD for presentation on issue resolution for fuolificities adjinctuding cable separation MORAND,DH Oic of Special Projects 89/11/23, BLACK,S. Oic of Special Projects 12cp 47677.081-47677.092
- 8812010324 Forwards add' info re moderate energy line break evaluation, per NRC 881017 request GRIDELY.R. Tennessee Valley Authority, 88/11/29. Document Control Branch (Document Control Dask) 3pp. 47710.097-47710.099.
- 8812060088 Advisos that fleg Guldo 1.09,flev 2 mothorology has no Immodiato impact on plant operations,por encil ordination of plants for Generic Lit 88-11, "NRC Position on Rad aton Embrittlement of Reactor Vossel Matte 8, Impact on Plant..."

 GRIDLEY,R Tennosseo Valley Authority, 88/11/1/30, Document Control Branch (Document Control Desk) 20pp 47752:203-47752:222.
- 8812060112 Requests withdrawal of Tech Specs 224 to 10CF1150 App. J. 8. 2591. doclar-ing control form emergency vontilation sys inoperable Temperary Tech Spec amend for control room emergency vontilation sys will be submitted by 881230. GRIDLEY,R. Tennessee Valley Authority, 88122702. Document Control Branch (Docu-ment Control Desk). 3pp. 47743.076-47743.078.
- 8812070050 Concurs w/approach to withdraw first sot of surveillance specimens from reactor vessel at and of each unit cycle or approx 8 EFPY of operation, but requires that revised surveillance program be developed from 8 EFPY capsule BLACKSC. Ote of Special Projects 88/12/02. KINGSt EY,O D. Tennessee Valley Authority. 3pp. 47746 282 47746 284.
- 8812120068 Summary of 881130 meeting w/util kn fluckville,MD re cable separation. Attendance roster & viewgraphs enct.

 MORAND H. Otc of Special Projects. 88/12/06 Oic of Special Projects 15pp 47785 260-47785 277.
- 8812120237 Informs of NRC setsoric audit schedulori for 881219-23.
 BLACK,S. Otc of Special Projects: 88/12/06 KINGSLEY,O D. Tennossee Valley Authority, 3pp. 47786,057-47786-059.
- 8812140029 Forwards safety evaluation of liconesco 060101 & 800404 submittals re-10CFR50,App R stutdown analysis Proposed safe children capability satisfies re-quirements based upon NRC 881021 approval of exemptions to App R BLACK,SC Ofic of Special Projects, 88/12/08. KINGSLEY,O.D. Tennessee Valley Authority, 2pp. 47799 245-47799:285.
- 8812130022 Forwards response to 881121 request for addl into on cable ampacity program.cab's installation program.tuse program 8 thormal overload program.Unit will provide status on testing by 890131.

 GRIDLEY,R. Tennessee Valley Authority, 88/12/09 Document Control Branch (Document Control Desk), 18pp. 47792.281.47792.298.
- 8812140157 AppScation for amends to Licenses DPH-33,DPR-52 & DPR-88, andring requirement 10.MM 8 to Tech Specs,requiring Implementation of program to imported piping made of eustomitic stainless steeld per Generic Lts 88-01 Fee patr. RAY,M J. Tennessee Velley Authority, 88112/09. Document Control Branch (Document Control Desk), 2pp. 47814.041-47814
- ~8812140159 Proposed Tech Specs.adding Requirement 1 0.MM 6 to require Implemental on of Inservice Inspiragram to monitor ploing made of austonitic stanless stoel per Generic Ltr 88-01 for Indications of IGSCC.

 * Tennessee Valley Authority. 88/12/09. 11pp. 47814.044-47814.054.
- 8812140165 Responds to Generic Ltr 88-11 re radiation embrittlement of reactor vessel mat's & Impact on plant operations using methodology in filev 2 to Rog Guide 1 99. GRIDLEY,R Tennessee Valley Authority 88/12/09. Document Control Desk). 6pp. 47800;206-47800;212.
- 8812160129 Natification of 681220 meeting w/util at site for licensee presentation of cable installation assessment & action plan.

 MCRAN,D.H. Olic of Special Projects 88/12/13, BLACK,S. Ofc of Special Projects and Appar 9pp 47835.154-47835:162

- 8812200177 Requests temporary exemption from GDC 17 re electrical cable separation Exemption requested for I miled I-ma period between fuel reload &
 - restart Foe poid GRIDLEY,H. Tonnessee Valley Authority. 88712715. Decument Control Branch (Occu-ment Control Dosk). 12pp. 47868-054-47868-065.
- 8812230017 Provides claif cation to statements contained in util 881109 submitted on plant DCRDR.Review concluded that human engineering discrepancy not required to be corrected before restart GRIDLEY,R Tennossee Valley Authority, 88/12/16, Document Control Branch (Document Control Dock), 2cp. 47914-351-47914-352
- 8812270210 Summarzos NRC sonior ingt 881296-07 intentings re review of performance of operating nuclear power plants licensed by NRC Public incenting scheduled for 881221 to roview rosults of fatest meeting of NRH inanagers.
 STELLOY Offic of the Executive Director for Operations 88/12/16 KINGSLEY,OID Tennessee Valley Authority. 3pp. 47926.273-47926.275.
- 8812270104 Forwards Site Director Std Practice SDSP 16.8, "Fuso Control," delining requirements for controlling procurement, installation & maint of alectrical tuses Submittal complinition response to NRC 881123 request for into refuse program GRIDLEY,B. Tennessue Valley Authority, 88712720, Document Control Branch (Document Control Disk), 2pp. 47926-036-47926-140.
- -8812270107 Site Director Std Practice SDSP-16-8, "Fuso Control."
 Tennosse Valley Authority 89/12/16, 103pp, 47926-038, 47926,140

Q. Inspection reports, IE Bulletins & correspondence

- 8812220101 Forwards Environ Qualification Insp Repts 50-259/88-11, 50-260/88-11 & 50.296/88-11 on 880509-13.Insp roviewed implementation of program for instablishing & maintaining qualification of aluctric equipment within 10CFR50-49 RICHARDSON,S.D. Ofc. of Spucial Projects. 80/09/01. WHITE,S.A. Tennorsob Valley Authority 3pp 47894.319 47894.344
- #8812220105 Insp. Repts 50-259/80-11,50-260/88-11 & 50-296/88-11 on 880509-13 No violations noted Major areas inspected. Implementation for establishing & mantaining qualification of electric equipment within scope of 100FR50-49. HUBBARD,G.T., PIERSON,R.C. Old of Special Projects 88/08/26, 22pp. 47894.322-47894-344.
- 8812270244 Forwards Toam Insp. Repts 50:259/88 07,50:260/88:07 & 50:296/88:07 on 880418:22 No violations noted.NRC concludes that Roy 4 of plant design baseine & ventication program incorporatios desired calculation. RICHARDSON,S.D. Ofte of Special Projects. 88/09/08 WHITE,S.A. Tennossee Vallay Authority 4pp. 47926 337-47927 025.
- #8812270245 Toem Insp. Rupts 59:250/88-07,50:260/88-07 & 50:296/88-07 on 880418-22.No violations noted. Major areas inspected plant design baseline & vanication program. GEORGIEV.G B., LIAW,B.D. Old of Special Projects 88/08/31, 46pp. 47926-340-
 - 47927 025
- 8809290002 Forwards propriotory "Browns Forry Nuclear Plant Solety Sys Functional Insp Emergency Equipment Cooling Water Sys,RHR Svc Weter Sys "Recommendations for observations being prepared Rept withhold (ref. 10CFH2.790)
 GRIDLEY,RL Termiosson Valley Authority, 88709723 Document Control Branch (Document Control Dosk). 2pp. 46998,256-46998.257.
- 8812220212 Forwards Wolding Toam Insp. Ropts 50-259/88-13,50-260/88-13 & 50-296/88-13 on 880516-27 & 0606-10 NRC findings in general agreement w/results of util welding project Phase II rept. RICHARDSON, S.D. Otc. of Special Projects 08/10/03 WHITE,S.A. Tennossee Valloy

Authority 3pp 47892:101-47892 143

- -8812220215 Insp Ropts 50-269/68-13,50-260/88-13 & 50-296/88-13 on 880516-27 & 0606-10 No. significant dovintions from rosults reported in util Phase II ropt noted Major areas inspected in util Phase II ropt & ong nouning calculations. GEO/GIGEV.G.B., LIAW, B.D., MCLELLAN, T. Ofc of Special Projects 88/09/22, 39pp 47892:104-47892:143.
- 8812050294 Advises that NRC 880817 commitment to perform inspa prior to fuel reload Postponed until Feb 1989. PICHARDSON,S1). Old of Special Projects 89/11/21. WHITE,S A Tonnessee Valley
- Authority. 2pp 47740.091-47740.092
- 8811160211 NRC Info Notice 88 090, "Unauthorized Flomoval of Industrial Nuclear
- Gauges" Svc list encl CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708.257.
- 8811180467 NRC Into Notice 86 091, "Improper Administration & Control of Psycholog-
- cal Tests." Svc list and ROSSI.C.E. Division of Operational Events Assessment (Post 970411) 9B/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142
- 881300140 Responds to NRC 881025 ltr re violations noted in Insp Repts 50-259/68-21,50-260/88-21 & 50-290/88-21 Corrective action generic reviews completed at plant & corrective action procedure rovised to restructure generic reviews GRIDLEY,R. Terinessee Valley Authority. 88/11/23 Document Control Branch (Document Control Desk). 7pp. 47668:286-47668.202.
- 8812010186 Forwards V Stello 881117 ftr to all that executives ra presence of NRC inspector at plants,rev to enforcement policy & proposed enforcement actions for operator inattentiveness at Peach Bottom.

 BLACK, SC Off of Sportal Projects 88/11/23 KINGSLEY,O D. Tennessee Valley Authority. 3pp 47709:258-47708:309.
- -8812010188 Advises of new rules re announcing presence of NRC inspector at power plant revita NRC enforcement policy effective on 881014 & proposed enforcement action for operators at plant STELLO.V. Ofc of the Executive Director for Operations 88/11/17. Philadelphia Electric Co. 35pp. 47709.261-47709.309.
- 8812090006 Ack rece.pt of 881007 ftr Informing NRC of steps taken to correct violations noted in Insp Ropts 50-259/38-16, 50-260/38-16 & 50-296/38-16.

 MCCOY,F.R. Ofc of Special Projects 88/11/28, KINGSLEY,O.D. Tennessee Valley Authority, 2pp. 47782-198-47782-199.

- 8812090018 Ack receipt of 881006 lir informing NRC of steps taken to correct violations noted in Insp Rights 50:259/87-33, 50:260/87-33 & 50:298/87-33 MCCOY,F.R. Ofc of Special Projects. 88/11/28. KINGSLEY,O D. Tennessee Valloy Authority. 2pp. 47762:315-47762-316
- 8812090074 Ack receipt of 881021 lir informing NRC of steps taken to correct violations noted in Insp Repts 50:259/88-18, 50:260/88-18 & 59:296/88-18 MCCOY,FR Ofc of Special Projects 88/11/28. KINGSLEY,O D Tennessiro Valley Authonity. 2pp. 47761.123-47761.124.
- 80 12090114 Ack receipt of 880428 & 0602 lits informing NRC of steps taken to correct violation noted in Insp. Ropts 50:259788-02, 50:260788 02 & 50:266788-02. MCCOY,F.Fl. Oic of Special Projects 88711/28 KINGSLFY,O.D Tennossoe Valloy Authority. 2pp. 47775-095-47775-096
- 8812020265 Forwards ref purchase order numbers & dates for suspected purchases by utl of Class 1E components or sizes from Planned Maint Systinc for appropriate action, per NHC Info Notice 88-019, "Quastionable Certification of Class 1E...."

 BLACK, SC Otto of Special Projects 88/11/29 KINGSLEY, O 0 Tonnesseu Valley Authority 5pp 47722 660-47722 073.
- 8811290030 NRC Info Notice 88-093, "Telathorapy Events." Svc list onci. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02. Consolidated Euson Co. of New York, Inc. 112pp. 47811:103-47811.215.
- 8811290538 NRC; Info Notice 88-094, "Potentially Undersized Valvo Actuators." Svc list ROSSI,C E. Division of Operational Events Assessment (Post 870411) 88/12/02. Consultdated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812020287 NRC Info Notice 88.095, "Inadequate Procurement Requirements Imposed by Lecensons on Vendors" "Svc list encl. ROSSI,C E. Division of Operational Events Assessment (Post 870411). 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47037.191-47807.302.
- 8812140157 Application for amousts to Licenses DPR-33,DPR-52 & DPR-68, adding re-quirement 1.0.MM 6 to Toch Specs,requiring implementation of program to monitor piring made of austorititic standess steel per Generic Lit 88-01 Fee part RAY,M J. Tennessoo Valley Authority, 88/12/U9. Document Control Branch (Docu-ment Control Dosk). 3pp. 47814-041-47814-054.
- -8812140159 Proposed Tech Spacs, adding Requirement 1.0 MM 6 to require implementation of insurvice inspiring to insurvice inspiring made of austenitic stainless shelper Generic Ltr 88 01 for Indications of IGSCC * Tennessee Varley Authority, 88/12/09 11pp 47814 044-47814 054
- 0812200361 Forwards Insp. Repts 50:259/88:20,50:260/88:28 & 50:296/88:28 on 880905-39 & notice of violation MCCOY,F.F. Ofc of Special Projects, 88/12/09, KINGSLEY,O.D. Tennessoe Valley Authority, 2pp. 47868-113-47868-138
- -8812200353 Notice of violation from insp on 880905-30 Violations noted. Initire to adequately correct discrepancy hetwoon as full plant conliguration & umergency equipment couling water Drawing 1-47E859-1 until 880222. MCCOY,F.R. Old of Special Projects 88/12/09. 2pp. 47868.115-47868.116.
- --8812200355 Insp. Repts 50:259/88:28,50:260/88:28 & 50:296/68:28 on 880905-30.Violations & unrosolvod items noted Major areas inspected operational safety, surveillance observations, systetum to syc,ROs & restart tost program CAMPENTER.DR. LITTLE,W.S. Region 2, Ofc. of the Director. 88/12/09, 22pp. 47868:117-47868.138

R. Periodic operating reports & related correspondence

- 8811300008 Monthly operating repts for Oct 1988 for Browns Ferry Nuclear Plant Units 1.2.8.3.W/861121 ltr. CRAWFORD.J.D., CAMPBELL,G.G. Tennossee Valley Authority. 88/10/31, 70pp. 47702-107-47702-236.
- S. Reportable occurrences, LERs & related correspondence
- 8812120018 LER 86-023-00 on 880818 ground water entering pump room through sub-torranean pipe penetration observed Caused by efforts to further compact ground for support of large crane Water tight seat being designed W/880916 lir. JONES, S.B., CAMPBELL, G.G. Tannessee Valley Authority. 68/09/16. 5pp. 47789-122-47789:126.
- 8811300070 LER 88-035-00 on 881021,unplanned actuation of control room emergency ventilation sys occurred. Caused by procedural inadequacy Operating Instruction for CREV revised to describe how to resot initiation logic W/881121 ftr. JONES,S B. Tennessee Valley Authority, 88/11/18, 6pp. 47696 296-47696:301.
- 8612010024 LER 88-041-00:on 881028 radiochemical lab analyst failed to perform compensatory sampling required by Tech Spac 3.2.D becauso raw coding water offluent radiation monitors out-of-svc.Caused by personnel error W/881125 tir. NAVELED., CAMPBELL,G.G. Tonnessee Valley Authority. 88/11/21 4pp. 47702-324-
- 8812200145 LER 88-039-00:on 881017,standby gas treatment exhaust detected coming out of offgas dilution lans inlets Caused by design error made in original plant design Proceedures that govern design process upgraded W/881215 ltt.
 JONES,S.B., CAMPBELL,G.G. Tennessee Velley Authority. 88/12/15 4pp.
- 8812200222 LER 88 038-00.on 881017, discovered that min set of electrical calculations not available to confirm technical adequacy of plant electrical sys & compliance w/regulatory requirements Gaused by design failure.W/88121b ltr. JONES.S.B., CAMPBELL.G.G. Tennasson Valley Authority 88/12/15. 5pp 47871 314-47871.318.

- 8812200244 LER 88-034-00 on 881018 discovered that Condition Adverse to Quality Rept BFP871062 initially determined to be reportable actually was reportable Caused by inadequate design of sys 8 arrangement of equipment in generator room.W/ 881215 tr
 - CAMPBELLIGIG Tennessee Valley Authority 88/12/15. 4pp MEADE KE. CAMP 47860 219 47860 222
- 8812210051 LER 88-036-00 on 681018.unanalyzed conditions identified, involving over-loating of diesel generators & violation of 10CFR50.App K Caused by inadequate design control & program review Accident signal logic revaluated W/881215 lift wtL4R0.SC CAMPBELL.GG Tennessee Valley Authority 88/12/15 Spp. 47875 123 47875 127
- 8812210074 LER 88.037.00 on 851018.d.screpancies involving design 8 se.smic qualification of HVAC duct work identified Caused by inadequate design criteria 8 inadequate review of emisting criteria Stress analysis conducted W/881215 ltr.
 WEADEKE, CAMPBELLIG G. Tennessee Valley Authority 89/12/15 5pp. 47888 104-47888 108

V. Operator Examinations

- 8811290270 Informs that NRC will administer requalification exams in order to evaluate requalification program Administration of requalification exams to all Group IV opera
 - requestioning program account of requestion exams to all droup by operators at that time also intended. PARTLOW J.G. Ofciol Special Projects, 88/11/21, WHITE,S.A. Tennessee Vailley Authority 3pp. 47663-358-47663-360.
- 8812160041 Forwards request for additinto tisted in refilmall requirements & for licensed senior reactor operator from both operations dept & training dept to be representa
 - tres for exams
 MCCOYFR Of of Special Projects 88/12/01, KINGSCEY.OD Tennessee Valley
 Authority 7pp 47832/345-47832/351.

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8811300164 Forwards addl into to resolve certain App R draft SER open items.per 870323 request Ma'n steam re'iel valves have two stated shutdown functions GRIOLEY,RL Tennessee Valley Authority 87/06/22. Document Control Branch (Document Control Desk) 12pp 47676 001-47676 012
- 8812160091 Forwards "Browns Ferry Nuclear Plant Annual Exercise Scenario 1988." per 841011 request Exercise scheduled for wk of 880919 GRIDLEYR. Tennessee Valley Authority 58/08/04. Region 2, Ofc of the Director 1p. 4780 47831 245 47832 243
- -3812160096 "Browns Ferry Nuclear Power Plant Annual Exercise Scenario 1986."
 Tennessee Valley Authority, 88/06/02, 400pp, 47831,246-47832 243.
- 8811290512 informs that requested info supporting App R audit rescheduled & will be 811/0312 minima visit occurred by 890203 GRIDLEY,R. Tennessee Valley Authority 88/11/22. Document Control Branch [Document Control Desk). 3pp. 47650 078-47650 080.
- 8812140029 Forwards safely evaluation of licensee 860101 & 880404 submittals re 10CFR90.App R shutdown analysis Proposed safe shutdown capability satisfies requirements based upon NRC 881021 approval of exemptions to App R BLACK, S.C. Otc of Special Projects, 88/12/08. KINGSLEY,O.O. Tennessee Valley Authority 2pp, 47799 245-47799 265.
- -8812140033 Safety evaluation accepting util App R submittel as applied to adequacy of minimum safe shutdown sys.
 ' Ofc of Special Projects 88/12/08, 19pp. 47799 247-47789 265
- 8812200079 Forwards replacement pages to 870611 Rav 8 to physical security/contingency plan Enci withhold (ref 10CFR73 21)
 GRIPUE LYR. Fannesse Valley Authority 88/12/13 Document Control Branch (Document Control Desk) 2pp 47862 200-47862:201.
- 8812210195 Revised central emergency control cir emergency plan implementing procedures including Rev 1 to CECC-EPIP-1, Rev 2 to CECC-EPIP-2, Rev 2 to CECC-EPIP-3, Rev 3 to CECC-EPIP-4, Rev 2 to CECC-EPIP-7, W/
- MCANALLY,J L GRIDLEY, R.L. Tennessee Valley Authority, 86/12/16, 86pp 47908 304 47907:053.
- 8812210206' Forwards Rev 1 to radiological emergency plan & Rev 19 to Emergency Plan Implementing Procedure BFN-EP-P-1. GRI/DLEY/R. Tennesse Valley Authority, 88/12/18. Document Control Brench (Document Control Deck). 2pp. 47907.063-47907.076
- -8812210273 Rev 1 to "Radiological Emergency Plan."
 Tennessee Valley Authority. 88/12/07, 11pp 47907,065-47907,075
- -8812210278 Rev 3 to Emergency Plan Implementing Procedure BFN-EPIP-1, Attachment 1. * Tennessee Valley Authority 88/12/16 1p. 47907.076-47907.076.

P. Operating license stage documents & correspondence

- 8811300164 Forwards additinfo to resolve certain App R draft SER open items,per 870323 request, Main steam rehef valves have two stated shutdown functions GRIDLEY,R L. Tennessee Valley Authority. 8708/22. Document Control Branch (Oocument Control Desk). 12pp. 47676.001-47676.012.
- 8812130143 Forwards Amende 160,167 & 131 to Licenses DPR-33,DPR-52 & DPR-88,respectively & safety evaluation Amends replace all water level refs to top of active fuel wicorresponding ref to vessel zero BLACK,S. Otc of Special Projects 88/10/19 WHITE,S.A. Tennessee Valley Authority. 2pp. 47798 248-47798 284

- ~8812130160 Amends 160,157 & 131 to Licenses DPR-33,DPR-52 & OPR-58, respectively,replacing all water level rela to top of active fluid w/corresponding ret to VASSAL 2010
 - BLACK, S Cit. of Special Projects 88/11/28 33pp 47790 250-47798 202
- -8812130174 Salety evaluation supporting Arnands 160,157 & 131 to Licansos Cha. 33.0PR-52 & DPR-69,rospectively Onico of Nuclear Reactor Regulation, Oxidator (Post 870411) 88/11/28 2pp 47798 283-47798 284.
- 8812020185 Forwards Amends 158,154 & 129 to Licenses DPR-33,DPR-52 & DPR-88/aspectively & safety evaluation Amend changes definitions of mode of operations, core alteration & reactor conditions

 BLACK_S_OIC of Special Projects 88/11/18 WHITE,S.A. Temposare Valley Authority
- 2pp 47710 171-47710 335
- ~8812020188 Amends 158,154 & 129 to Liconsos DPR-33,0PR-82 & 0PR-68 respectively,changing definitions of mode of operation,corn alteration & reactor conditions for facility BLACK,S. Cfc of Special Projects: 88/11/18, 155pp. 47710 173-47710 327
- -8812020191 Salety evaluation supporting Amonds 158,154 & 129 to Licensos DPR 33.DPR-52 & DPR-68,respectively
 * Oto of Special Projects -88/11/18 -8pp, 47/10 328-47710 335.
- 8812020181 Forwards Amend 156 to License DPR-52 & safety evaluation. Amend concerns RWCU pipetrench temp sensor BLACK,S. Old of Special Projects (88/11/21) WHITE,S.A. Trinnussod Valley Authority
- -8812020274 Amend 156 to License DPH-52 to RWCU pipetrench temp sensor BLACK,S. Oic of Special Projects 68/11/21, 9pp. 47718.059 47718.067.

3pp. 47718 056-47718 070

- --8812020276 Safety evaluation supporting Amond 156 to License DPR-52
 * Office of Nuclear Reactor Fleg-fation, Director (Post 870411) 88/11/21, 3pp 47718-056-47718-076
- 8812010277 Forwards list of submittals needed to support NRC decisions re-restart.List of Leansing actions targeted for completion prior to next montrig on 681220 also onci BLACK,S Ofc of Special Projects 88/11/22, KINGSLEY,O D. Tormossoe Valley Authority 5pp 47707:141-47707.145
- 8812060235 Forwards Amends 159,155 & 130 to 1 consus DPR-33,DPR-52 & DPR-68,respectively & safety evaluation Amend will add ASME Section XI punip & valve program definition & change applicable testing frequencies to rail definition BLACK,5 Oto of Special Projects 88711722 KINGSLEY,O.D. Townseen Valley Authority 2pp 47755.047-47755.163.
- --8812060243 Amends 159,155 & 130 to Licenses DPR-33,DPR-52 & DPR-68, respectively,cdding ASME Section XI pump & valve program definition & changing applicable testing frequencies to ret refination.

 BLACK, S. Ole of Special Projects 88/11/22, 113pp 47755,049,47755,161.
- **8812060246 Safety evaluation supporting Amends 159,155 & 130 to Licinises DPR-33,DPR-52 & DPR-88,respectively.
 * Oto of Special Projects, 88/11/22, 2pp. 47755;162-47755 163
- 8811280048 General Ltr 88-20 to all ficensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnorabilities Svc Tst
- GRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88711723, Chrisoir dated Edison Co. of New York, Inc. 81pp. 47728.303-47729:024.
- 8811300455 Forwards SER accepting plant upgraded training program described in Rev 2 to Browns Ferry nuclear performance plan, Vol 3 Program adequately addresses deficiencies identified in Socion II 2.3.

 BLACK,S.C. Ofc. of Special Projects

 88/11/23, KINGSLEY,O.D. Termossoo Valley Authority, 1p. 47696:206-47696:226.
- ~8811300457 Safety evaluation.accoping upgraded training program #1 TVA Flov 2 to Vol 3,Section II.2 3 of plant nuclear performance plan.

 **Oto of Special Projects 88/11/23, 6pp. 47696.207-47696 226
- 8811300510 Not lication of 881130 meeting w/util in Rockvillo,MD for presentation on issue resolution for fuel reload/including cable separation. MORAN,DH. Ofc. of Special Projects. 88/11/23, BLACK,S. Ofc. of Special Projects. 12pp. 47677.081-47677.092.
- 8812010310 Forwards revised cover lit for Salety Sys Functional Insp. (SSFI) Rept BFA 88811 SSFI rept considers emergency equipment cooling water & RHR syc water functional Requests proprietary statement in earlier submitted be withdrawn. GRIDLEY,R. Tennessee Velley Authority, 88711/29. Document Control Branch (Document Control Desk) 2pp. 47709:190-47709.191.
- 8812010324 Forwards addt into re moderate energy line break evaluation, per NRC 881017 request.
 GRIDELY,R. Tennessee Valley Authority. 88/11/29. Document Control Branch (Document Control Desk). 3pp. 47710-099.
- 8812080088 Advises that Reg Guide 1.99, Rev 2 methodology has no immediate impact on plant operations, per end evaluation of plants for Generic Ltr 88-11, "MRC Position Redeaton Embrattement of Reactor Vessel Matts & Impact on Plant ..."
 GRIDLEY, R. Tennessed Valley Authority. 88/11/30. Document Control Branch (Document Control Desk). 20pp. 47752-203-47752-222.
- 8812060112 Requests withdrawal of Tech Specs 224 to 10CFR50,App J & 259T declaring control room emergency ventilation sys imperable. Temporary Tech Spec amend for control room emergency ventilation sys will be submitted by 881230.

 GRIDLEY,R Tennesses Velley Authority. 88/12/02 Document Control Branch (Document Control Dask). 3pp 47743.078-47743.078.
- 8812070050 Concurs w/approach to withdraw first set of surveillance spectimens from reactor vessel at end of each unit cycle or approx 8 EFPY of operation,but requires that revised surveitlance program be developed from 8 EFPY capsule.

 BLACK,S.C. Of of Spacial Projects 88/12/02 KINGSLEY,O.D. Tonnessee Valley Authority, 3pp. 47746/292-47746/294.

- 8812080133 Documents TVA position on plant electrical cable separation issue Mods to correct separation discrepancies affecting unit (& common) sys will be completed
- before restart
 GRIDLEY,R Tennessee Valley Authority 88/12/02. Document Control Branch (Coccentrol Control Desk) 9pp 47755:229-47755:237
- 812120068 Summary of 881130 meeting w/util in Rockville,MD re cab'e soparation Attendance roster & viewgraphs enct.

 MORAN,D.H. Old of Special Projects 88/12/06 Ofc of Special Projects 15pp. 47785-260-47785-277
- 8812120237 Informs of NRC seismic and 1 scharkled for 881219-23.
 BLACK,S. Old of Special Projects 88/12/06. KINGSLEY,O.D. Tennassee Valley Authority 3pp 47786-057-47786.059
- 8812090210 Notification of 881213 mosting w/util in Rockville,MD to discuss use of arti-Itical Fine history to support serimic ovaluations
 GEARIS,G E. Olic of Special Projects 88/12/08. BLACK,S. Olic of Special Projects
 2pp. 47785.067-47785.068.
- 8812130054 Forwards safety evaluation to Vol 3 of facility performance plan, Section III.2 0, "Configuration MgI Program" Design Baseline & Verification Program" BLACK, S. Ofc of Special Projects 88/12/08. KINGSLEY, O.D. Tennessee Valley Authority 2pp 47792-310-47792-315.
- -9812/30057 Safety oveluation supporting Vol 3 of facility performance plan Section III.2.0, Configuration Mgt Program Design Baseline & Vontication Program "Oto of Special Projects 887/12/08. 4pp 47792.312-47792.315.
- 8812140029 Forwards safety evaluation of ficunsee 860101 & 880404 submittels re-10CFR50,App R shutdown analysis Proposed sate shutdown capability satisfies re-quirements based upon NRC 881021 approval of exemptions to App R. BLACK,S C Offic of Special Projects. 88/12/08 KINGSLEY,O.O. Tennissee Valley Authority, 2pp. 47799.245-47799:265.
- 8812140042 Forwards satisfy ovaluation accepting responses to Generic Ltrs 84-11, "Insp of BWR Stainless Steel Piping," & 88-01, "NRC Position on IGSCC in BWR Austerute Stainless Steel Piping."

 BLACK.S.C. Ote of Special Projects 88/12/08. KINGSLEY,O.D. Tennessee Valley Authority, 4pp. 47798 285-47798-298.
- -8812140048 Safety evaluation supporting Generic Lirs 84-11, "Insp of BWR Staintess Steel Piping," 88-01, "NRC Position on IGSCC Austentic Stainless Steel Piping,"
 Otc of Special Projects 80/12/08, https://doi.org/10.1006/10.1006/10.
- 8812130022 Forwards response to 881121 request for additinfo on cab'e ampacity program, cable instellation program, fuse program & thermal everload program. Util will provide status on resting by 890131. GRIDLEY, F. Tennessee Valley Authority, 88/12/09. Document Control Branch (Document Control Dosk): 18pp. 47792:281-47792:208.
- 8812140157 Application for amonds to Licensos DPR-33,DPR-52 & DPR 68, ariding requirement 1.0 MM 6 to Tech Spacs,requiring implementation of program to monitor piping made of austentic statistics steel per Generic Lift 88-01.Fee part RAY,M.J. Tennossee Valley Authority, 88712709. Document Control Branch (Document Control Desk), 3pp. 47814:041-47814.054.
- -8612140159 Proposed Tech Specs.adding Requirement 1.0.MM.8 to require implamentation of insprived inspryagam to monitor plaing made of austrinitic stainless steet per Generic Ltr 88-01 for indications of IGSCC.
 * Tennessee Valley Authority. 88/12/08. 11pp. 47814.044-47814:054.
- 8812140165 Responds to Generic Ltr 88-11 ro radiation embrittlement of reactor vessel matis & impact on plant operations using mothodology in Rev 2 to Reg Guide 1.99 GRIDLEY,R. Tennessee Valley Authority. 88/12/09. Document Control Branch (Document Control Dosk). 6pp. 47800:206-47800:212.
- 8812160129 Notification of 881220 moeting w/util at site for licensee presentation of cable installation assessment & action plan MORAN,D.I.I. Ofc of Special Projects 88/12/13. BLACK,S. Ofc of Special Projects. 9pp. 47835:164-47835:162.
- 8812200177 Requests temporary exemption from GOC 17 re electrical cable separation. Exemption requested for limited lime period between fuel relead &
- Separaturit Control State Processor Valloy Authority, 88/12/15. Document Control Branch (Document Control Dosk). 12pp. 47868-054-47868:085.
- 8812210199 Forwards Ilcunsed Joint Audit Ropt BFK88901, "Sys Preoporability Check-list & Sys Plant Acceptance Evaluation Programs" & results of engineering assurance oversight of sys plant acceptance evaluation.
 GRIDLEY,R. Tennessee Valley Authority. 88/12/16. Document Control Branch (Document Control Desk). 2pp. 47875;142-47875:176.
- -8812210200 "Sys Preoperability Checklist & Sys Plant Acceptance Evaluation Programs." KEHOE,D.V., BARNES,J.T., MALONE,D.L. Tennessoe Valley Authority. 88/11/18. 32pp. 47875:144-47875:178.
- 8812230017 Provides clarification to statements contained in util 881109 submittal on plant DCRDR.Review concluded that human engineering discrepancy not required to be corrected before restart.

 GRIDLEY,R. Tennessee Valley Authority, 88/12/16. Document Control Branch (Document Control Dosk), 2pp. 47914:351-47914:352.
- 8812270210 Summarizes NRC senior mg1 881206-07 meetings re review of performance of operating nuclear power plants licensed by NRC.Public meeting scheduled for 881221 to review results of latest meeting of NRR managers.

 STELLOV. Ofc of the Executive Director for Operations. 88/12/16. KINGSLEY,O.D. Tennessee Valley Authority. 3pp. 47926:273-47926:275.
- 8812270104 Forwards Site Director Std Practico SDSP 16.8, "Fuse Control," defining requirements for controlling procurement, installation & maint of electrical fuses Submittal completes response to NRC 881123 request for info re fuse program. GRIDLEY,R. Tonnossee Valley Authority, 88/12/20. Document Control Branch (Document Control Desk). 2pp. 47926:036-47926:140.
- -8812270107 Site Director Std Practice SDSP-16.8, "Fuse Control." Tennessee Valley Authority. 88/12/16. 103pp. 47926:038-47926:140.

- Q. Inspection reports, IE Bulletins & correspondence
- 8812220101 Forwards Environ Qualification Insp. Repts 50:259/88-11, 50:260/88-11 & 50:266/88-11 on 80509-13 Insp.rouswed Insprementation of program for establishing 8 maintaining qualification of electic equipment within 10CFR50-49 RICHARDSON,S.D. Ofc of Special Projects 88/09/01, WHITE.S.A. Tennesare Valley Authority. 3pp. 47894-319-47894-344
- -8812220105 Insp. Repts 50:259/88-11,50:260/88-11 & 50:296/68-11 on 880509-13-No violations noted Major areas inspected implementation for establishing & main-taining qualitication of efforts equipment within scope of 10CFR50-40-HURBARD,G.T., PIERSON,R.C. Ofc of Special Projects 88/08/26 22pp 47894.322-47894.344
- 8812270244 Forwards Team Insp. Ropts 50:259788-07;50:260788-07-8-50:206788-07-0n-880418-22 No violations noted NRC concludes that Rev-4-of-plant design baseline & verification program incorporates desired calculation RICHARDSON,S-D-Otc of Special Projects, 88709708-WHITE,S-A. Tennessee Valley Authority, 4pp. 47926-337-47927.025.
- ~8812270245 Team Insp. Repts. 50-259/88-07,50-260/88-07 & 50-296/88-07 on 880418-22 No violations noted Major areas inspected plant design baseline & verifica-GEORGIEV.G.B., LIAW.B.D. Ctc of Special Projects 88/08/31, 46pp. 47926/340-
- 8809290002 Forwards proprietary "Browns Ferry Nuclear Plant Safety Sys Functional Insp.Emorgency Equipment Cooling Water Sys,RHR Svc Water Sys," Recommendations for observations being prepared Ropt withheld (ref 10CFR2.790) GRIDLEY.R.L. Tennessee Vallay Authority, 88/09/23 Document Control Branch (Document Control Desk) 2pp 46998 256-46998 257
- 8812220212 Forwards Wolding Team Insp. Ropts 50:259/88-13,50:260/88-13 & 50:296/88-13 on 880516-27 & 0606-10.NRC lindings in general agreement w/rosults of util wolding project Phaso II rept RICHARDSON,S () Ofc of Spucial Projects 88/10/03, WHITE,S A Tennessee Valey Authority 3pp 47892 101-47092 143
- --8812220215 Insp Repts 50-259/88-13,50-260/88-13 & 50-286/88-13 on 880516-27 & ou rezerva in mp repris 30-299700-13,50-260708-13 & 50-296708-13 on 880516-27 & 6066-10 No spriticant dovisitions from results reported in util Phase II replicated in the Phase II rep
- 8812050294 Advises that NRC 880817 commitment to perform Inspa prior to fuel reload postported until Feb 1999. BICHARDSON,S D. Olic of Special Projects. 08/11/21. WHITE,S A. Tennossee Valley Authority. 2pp. 47/40/091-47740/092
- 8811180211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list and CUNNINGHAMRE | Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811160487 NRC Info Natice 88-091, "Improper Administration & Control of Psychologicel Tests "Svc list oncl ROSSI,C.E. Div.sion of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142
- 8811300140 Rosponds to NRC #81025 ftr re violations noted in Irisp Ropts 50:259/88-21.50:260/88-21 & 50:296/88-21 Corrective action, generic reviews completed at plant & corrective action procedure revised to restructure generic review GRIDLEY,R. Tennessae Valley Authority, 68/11723 Document Control Branch (Document Control Desk), 7pp. 47668-286-47668-292
- 8812010186 Forwards V Stello 881117 ltr to all util executivos re prosence of NRC inspector at plants, rev to enforcement policy & proposed enforcement actions for operator ingitientiveness at Poach Bottom
 BLACK, S.C. Ofc ot Special Projects. 89/11/23. KINGSLEY, O.D. Tennossee Valley
 Authority. 3pp. 47709.258-47709.309
- 8812090006 Ack receipt of 881007 lir informing NRC of steps teken to correct violations noted in Insp. Repts 50:259/88-16, 50:260/88-16 & 50:298/88-16. MCCOY,F.R. Of: of Special Projects. 88/11/28. KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47782:198-47782.199
- 8812090018 Ack receipt of 881006 ltr informing NRC of stops taken to correct violations noted in Insp. Ropts 50:259/87-33, 50:260/87-33 & 50:296/87-33. MCCOY,F.R. Old of Spacial Projects 88/11/28. KINGSLEY,O.D. Tennessee Valley Authority. 2pp 47782:315-47782:316
- 8812090074 Ack receipt of 881021 ltr Informing NRC of steps taken to correct violations noted in Insp Ropts 50-259/88-18, 50-260/88-18 & 50-296/88-18. MCCOY,F.B. Old of Special Projects, 89/11/28 KINGSLEY,O.D. Tennessee Valley Authority, 2pp. 47761:123-47761:124
- 8812090114 Ack ruceipt of 880428 & 0802 ftrs Informing NRC of steps taken to correct violation noted in Insp Repts 50:259/88 02, 50:260/88-02 & 50:299/88-02. MCCOY,F.R. Oic of Special Projects, 88/11/28. KINGSLEY,O D. Tennessee Valley Authonly. 2pp. 47775.095 47776.096
- 8812020255 Forwards rel purchase order numbers & dates for suspected purchases by util of Class 1E components or syes from Planned Maint Sys,inc for appropriate action per NRC Info Notice 88-019, "Questionable Certification of Class 1E...." BLACK,S.C. Ofte of Special Projects 88/11/29. KINGSLEY,O.D. Tennessee Valley Authority. 5pp. 47722.069-47722.073.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc fist encl. CUNNINGHAM,R E. D.vislon of Industrial & Madical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:216.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list ROSSI,C E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47/08:143-47708.254.

DOCKETED ITEMS

- 8812020287 NRC Info Notice 88-095. Inadequate Procurement Requirements Imposed by Leansees on Vondots." Suchist and ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/08 Consolidated Edison Color Mew York, Inc. 112pp. 47807 191-47897,302
- 8812140157 Application for amends to Licenses DPR-33, DPR-52 & DPR-68, adding re-quiremant 1.0 PM 6 to Tuch Specs, requiring implementation of program to monitor poing made of austentic stamless stool per Generic Lir 88-01 Fee paid RAY,M-J. Ten ressee Valley Authority. 897(12/00. Document Control Branch. [Docu-ment Control Desk.). 3pp. 47814-041-47814-054.
- -8812140159 Pruposod Tech Spacs adding Requirement 1.0 VM 6 to require implementation of inservice inspiragram to monitor piping made of austentic stantess steel per Generic Lir 88 01 for Indications of IGSCC Transessne Vator Authority 68/12/03, 11pp 47614;044-47814-654
- 8812200351 Forwards Insp Repts 50-259/68-28,50-260/68-28 & 50-296/88-28 on 883905 30 & notice of victation MCCOY F.H. (1to of Special Projects, 89/12/09, KINGSLEY,O.O. Tempessee, Valey Authority 2cp. 47869 113 47868 136
- -8812200353 Nintco of violation from inspiron 880905 30 Violations moted failure to adequately correct discrepancy between as-built plant configuration. & emergency equipment cooling water Drawing 1,47E859 trunts 880222. MCCOY,FIR Official Special Projects. 88/12/09, 2pp. 47868;115.47888.116
- -8812200355 Insp Ropts 50-259/88-28.50-269/88-28 & 50-296/88-28 on 880905 30 Victations & unlessived frems noted Major ereas inspected operational safety, survey lanculobs ovations, systetum to svo, ROs & restart test program. CARPENTER D.R., LITTLE, W.S. Region 2, Otc. of the Director 88/12/09 22pp 47868 117-47868 138
- 8812220113 Discusses programmatic milesiones & commitments for addressing IE Bulletins 79-14 & 79-02 MRC will continue to review adequacy of rigorous analysis & effectiveness of generic implication ovaluations in upcoming audit. BLACK-SC. Official Special Projects. 88/12/14. KINGSLEY,OID Tennossee Valey Authority. 3pp. 47892-194-47892-196.

R. Periodic operating reports & related correspondence

- 8811300008 Monthly operating repts for Oct 1998 for Browns Ferry Nuclear Plant Units 1,2.8.3 WW881121 tr. CRAWFORD,JD., CAMPBELL,G.G. Tonnessee Valley Authority 88/10/31, 70pp. 47702 167-47702 236
- S. Reportable occurrences, LERs & related correspondence
- 8812140234 LER 88-014-00 on 881103,received reactor scram signation high water level in scram discharge instrument vol Caused by Intedequate review of tagout request Procedure written to provide addit check in clearance request W/881209 it. MEADE, KE, CAMPBELL,G.G. Tennessee Velley Authority. 89/12/01. 4pp. 47821-083.

V. Operator Examinations

- 8811290270 Informs that NRC will administer requalification exems in order to evaluate requalification program Administration of requalification exems to all Group IV operators at that time also intended. PARTLOW JG. Oct of Special Projects 68/11/21 WHITE,S.A. Tennessee Velley Authority. 3pp. 47663 358-47663-360.
- 8812160041 Forwards request for addl into listed in ref mail requirements & for licensed senior reactor operator from both operations dept & training dept to be represents.
 - Ness for exams.

 MCCOY, F.R. Otc. of Special Projects 68/12/01. KINGSLEY, O.D. Tennossee Valley Authority 7pp 47832:345-47832:351.

DOCKET 50-261 H.B. RODINSON PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

30:261/88-28 on 880911-1010 & notice of violation the Orector, 88/11/10, UTLEY,E.E. Carolina Power

tions noted Major areas ety verification physical

Prector, 88/11/09.

ing facilities to ippression ca-

Director, 3pp.

diameters.

. & ts 8812200337 Forwards Insp. Rept. 50-261/88-30 on 881011-1110.No violations or deviunzervosar norwarus inspiriept 50-zerized-du on Betrotti-1110/No vollations or deal atons noted Concern te washkess in identifying applicability of containment setated wasy. Tech Spuc 36.3 oxpressed 8 discussed to rept. REYES LA Fleg on 2, Ofc of the Director 88/12/09. UTLEY,E.E. Cardina Power 8 Light Ca. 2pp. 47868-288-47868-292

- -8812200338 Insp. Rept. 50:261/88:39 on 881011-1110 No violations rigided. Major proat special operational safety verification, physical protection, sinval of control of the con
- 0812200342 Revisud plant emergency procedures, consisting of flow 4 to PEP-401 & Rev 20 to PEP-301.W/681216 lin MORGANIRE Carolina Power & Light Co. 88/12/16, 11pp. 47868 091-47868 001
- 8912220278 Approves 830415 requests for approval of use of atternate locations at place of backup energency operations facilities for plants LO,RIH, Project Eurocorate 161, 88712716, UTLEY,E.F. Carolina Power & Tight Co

P. Operating !!cense stage documents & correspondence

- 8811280048 Genoric Lir 88-20 to all licensees holding Otts & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list enci
 - CRUTCHFIELO,D. Associate Director for Projects (Post 870411), 88/11/20. Consesdated Edison Co. of New York, Inc. 81pp. 47728 303-47729.024
- 8812010246 Forwards safety evaluation concluding that proposed inother of measuring flow during testing of containment spray & component cooling water jump acceptable, providing ASME requirements met flow of inservice testing program re quested
 LO,R.H. Project Directorate #-1, 88/11/28, UTLEY,E.E. Caretria Power & Light Co.
 - 2pp 47703 094-47703 100.
- -8812010248 Safety evaluation accepting proposed method of immasuring flow during testing of containment spray & component cooling water pumps provided that accep-cy exists as stated & ASME requirements met. Rev. of inservice testing program in dnesteq Office of Nuclear Reactor Regulation, Director (Post 870411), 86/11/28 5;p
 - 47703 096-47703.100
- 8812120171 Forwards summary of 891116 meeting w/util in Region II ofc re-several work activities to be performed during prosprit refuving outage Holated into also end HEHLICW, Region 2. Ofc of the Overeion 88/11/28 UTLEY,
- 8812160007 Confirms that control room control board annunclators will be deenargized for 4 h 8 start will not be declared during evolution, per 881128 telepin Compensatory actions include monitoring of spent fuel pit level & tump.

 DIETZ,C.R. Cerebna Power & Light Co. 88/11/28, ERNST,M.L. Region, 2, Crc of the Director 2pp. 47630-352-47830-353.
- 8812050263 Application for amend to License CPR-23,increasing quantity of thosel generator fuel of required to be stored on situ. For paki MCDUFFIE,M.A. Caroline Power & Light Co. 88/11/30. Document. Control Branch (Document Control Dusk). 2pp. 4/731.178.47/31-185
- -8812050264 Proposed Tech Specs,Increasing quantity of dirisel generator fire! oil required to be stored onsite.
 * Carolina Power & Light Co. 88/11/30, 6pp. 47731:180-47731.185
- 8812070132 Requests that utit address Generic Ltr 88-17 re-loss of DHR during non-powor operation Industry response to Generic Ltr 87-12 deficient in areas of preven-tion of accident initiation & miligation of accidents. MURILEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02. SMITH,S.H. Carcina Power & Light Co. 3pp. 47748;263-47749.265.
- 8812070232 Notification of 881215 meeting w/ull in Rockville,MD to discuss ficensing
- status at prant LO.R.H. Project Directorate II-1, 88/12/02, ADENSAM,E.G. Project Directorate II-1 3pp. 47749.242-47749.244
- 8812130089 Advises of util intention to roplace portions of svc water sys piping located Institut reactur containment vessel. Piping being replaced due to extensive microbiological corosion of original mail, Type 304 staintess steet.

 LOFLIN,L.t. Carclina Power & Light Co. 88/12/05. Document Control Branch (Document Control Desk), 2pp. 47794:109-47794:110.
- 8812130288 Provides responses to action items identified during 881020-21 electrical Issues meeting. LOFLINL1. Carolina Power & Light Co. 88/12/05. Document Control Branch (Pocument Control Desk). 168pp. 47796.261-47797.068
- 8812120148 Notification of 890111 meeting w/util in Rockville,MD for util presentation of design basis documentation program.

 LORIH Project Directorate II-1. 88/12/07 ADENSAM,E.G. Project Directorate II-1 3pp. 47789:204-47789-208.
- 8812160123 Forwards notice of environ assessment & finding of no significant impact re 880826 & 1101 requests to change Tech Specs for certain parameters applicable to reactor coolant loop resistance temp detector & elimination of bypass sys LO.R.H. Project Directorate II-1. 98/12/12. UTLEY.E & Carolina Power & Light Co 2pp 47873.350-47873.355
- -8812180125 Environ assessment & finding of no significant impact supporting pro-posed amend to Tech Specs re-certain reactor parameters applicable to reactor cool-ant loop resistance tomp detector (RTO) & elimination of RTO bypass sys. LO.R.H. Project Directorate II-1, 88/12/12 4pp. 47873 352-47873.355.

Q. inspection reports, IE Bulletins & correspondence

- 8611280081 Forwards Insp Rept 50-261/88-28 on 880911-1010 & notice of violation VERRELLI,0 M, Region 2, Otc of the Director, 88/11/10 UTLEY,C.E. Carolina Power & Light Co. 2pp. 47651-276-47051-296
- --8811280087 Notice of violation from inspiran 880911-1010. Violation noted licensee did not have program to control or calibristop watches utilized for stroke liming of safety-related valves of for turning of other oruginment. VERNECLLIO M. Rogion 2, Oto of the Director. 88711710, 2pp. 47651-278-47651-279.
- -8811280098 Insp Rept 50-261/88-28 on 880911-1010.Violations noted Major areas BB1128008B Insp. Hopt. 50-261/88-28 on 880911-1010.Violations includ Major areas inspected followup: on provious Insp. items,operational safety verification,physical protection,maint observation & soil directwiste & transportation GARNEFIL W., LATTA,R.M., STARKEY,R.D. Region 2, Old of the Director 89/11/08 17pp. 47651.280-47651/296
- 8811290151 Contirms 681208 enforcement conference in Region II ofc to discuss recent security problem at facility.per 881108 te/con. ERNST,ML Region 2, Otc. of the Director 88/11/18 UTLEY,E.E. Caro'ina Power & Light Co. 1p. 47664.270-47664:270.
- 8811160211 NRC Info Notice 88-090, "Unputhorized Removal of Industrial Nuclear Ga. ges." Svc. set encl. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp 47708.255-47708:257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologycal Tosts," Svc list and.

 ROSSI,C E. Division of Operational Events Assessment (Past 070411) 88/11/22.

 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708.142.
- 8812020238 Confirms 881117 discussion re util 881012 request for alternative schedule to perform actions required by NRC Bulletin 88-009 LOFLIN, L.I. Carolina Power & Light Co. 88/11/28 Decument Control Branch (Document Control Drisk) 1p. 47717:195-47717:195
- 8811290030 NRC Info Notice 86 093, "Teletherapy Events" Svc 1st encl CUNNINGHAM,R E. Orviston of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47611:216
- 8811290538 NRC Info Notice 89-094, "Potentially Undersized Valve Actuators." Svc list ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708.143-47708:254.
- 8812020287 NRC Info Notice 88 095, "Inadequate Procurement Requirements Imposed by Licensons on Vendors." Svc list and ROSSI,CE Division of Operational Events Assessment (Post 870411). 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807.481-47007.302
- 8812160088 Responds to NRC ltr re violations noted in Insp Rept 50-261/88-28 Corrective actions Plant Operations Procedure OMM-017 for calibr,control & repair of portable test equipment will be revised.

 MORGAN R.E. Carolina Power & Light Co. 88/12/09. Document Control Branch (Document Control Desk). 4pp. 47825-051-47025.054
- 8812200337 Forwards Insp Rept 60-261/88-30 on 801011-1110 No violations or devionaccount forwards may represent the second attention applicability of containment isolation valve Tech Spoc 3.6.3 expressed in Identifying applicability of containment isolation valve Tech Spoc 3.6.3 expressed & discussed in represent a Region 2, Old of the Director, 88/12/09, UTLEY,E.E. Carolina Power & Light Co. 2pp. 47860:288-47868-299
- -8812200338 Insp Rept 50-261/88-30 on 881011-1110.No violations noted. Mejor areas Inspected aperational safety worlfication, physical protection, surveillance observation, maint observation & onsite followup of events.

 GARNER L.W. FREDRICKSON,P. Region 2, Otc of the Director. 88/12/00. 10pp. 47868 290-47868 290

R. Periodic operating reports & related correspondence

- 8812140262 Monthly operating rept for Nov 1888 for Robinson Unit 2, W/881207 ltr. HAYNESWORTH,V., MORGAN,R.E. Carolina Powor & Light Co. 88/11/30. 4pp. 47821:076-47821:079.
- S. Reportable occurrences, LERs & related correspondence
- 8811280070 LER 88-024-00.on 881028,containment fan coolers inoperable due to lack of environ qualified spices on motor leads. Caused by Installation of unqualified spices on motor leads. Caused by Installation of unqualified spice configuration. Spices removed & replaced w/correct spices W/881123 ltr. SAYRE,D., MCRGAN.R.E. Carolina Power & Light Co. 88/11/23. 5pp. 47654.071-47654.075
- 8812060293 Special reption 881102 fire barrier penetration seal spare blockout SP 2817 FB inoperable beyond 7 day limit of Tech Specs Caused by Inadvertent broaching during drilling Penetration repeired.
 MORGAN,R.E. Carolina Power & Light Co. 88/12/02. Document Control Branch (Document Control Desk). 2pp. 47755.164-47755:165.
- 8612200146 LER 88-026-00 on 881114-saleguard actuation received from inadvertent saloty injection signal due to removal of low pressurizer pressure safety injection blocked permissive. Operating procedures revised W/881209 ltr.
 LEGETTE,F.L. MORGAN,R.E. Carolina Power & Light Co. 88/12/09. 4pp. 47881:318-47881:319
- 8812200340 Special reption 881205, steam generator C Tube R7C92 plugged, due to indications found during eddy current exam. Digital motal impact monitoring sys revealed irrogular noise levols in steam generator C atter 1987 rofueling outage. MCRGAN, R.E. Carolina Power & Light Co. 88/12/16. Document Control Branch (Document Control Desk). 2pp. 47864:354-47864:355.
- 8812270241 LER 88-028-00 on 881121,noted that sys operation requires access to several locked closed manual valves,during roview of environ qualification of hydrogen recombiner sys.Caused by inadequacy of Emergency Instruction E-16-W/881221 lir. LEGETTE-F.L., MORGAN,R.E. Carolina Power & Light Co. 88/12/21. 4pp. 47925-305-47825,308.

Y. Dry Cask Independent Spent Fuel Storage Installations

- 8812150052 Application for amond to Licensu SNM-2502,raising limits in Tech Spec 2.4.1 for beta & gamma surface contamination of dry shielded canister Fee paid. UTLEY-LE. Cardonia Power & Light Co. 88/08/09 ROUSE Division of Industrial & Medical Nuclear Safety (Post 870729). 6pp. 47833-030-47833-035
- 8811300042 Requests clantication of amended ISFSI decommissioning funding plan LOFLINLL. Carolina Power & Light Co. 88711717. Document Control Branch (Document Control Dosk). 2pp. 47668-222-47688-223

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

F. Security, medical, emergency & fire protection plans

- 8811290310 Forwards Emergency Operating Procedure Insp Rept 50:263/88:290 on 880711:22.Deficiencies noted Executive summary of insp w/overview of Insp team findings in dreas reviewed and HOLAHAN,G.M. Division of Reactor Projects - III,IV,V. & Special Projects (Post 870411) 88/11/14. LARSON,C. Northern States Power Co. 8pp. 47667-205-
- -8811290314 Insp Ropt 50:263/88:200 on 880711:22 Deviations noted Major areas inspected program for implementing emergency operating procedures,per NUREG-0737, Suppl 1.

 GUTHERIE, S. Division of Reactor Inspection & Safeguards (Post 870411). HARTYMANN,P.L., VANDERNETT,C.L. Othico of Nuclear Reactor Regulation, Director (Post 870411). 88/11/08. 44pp. 47667.213-47867.256.

8812200048 Forwards Amend 94 to Licenso DPR-22 & safeguards evaluation. Amend Prizezouse Forwards Ameniu 94 to Licenso DPR-22 & sareguards evaluation Amenium modifies Peragraph 2.C 3 re physical security plan. STEFANO,J.J. Project Directorate III-1, 88/12/13. MUSOLF,D.M. Northern States. Power Co. 3pp. 47868.177-47868.184.

- --8812200051 Amend 94 to Liconse DPR-22_changing Paregraph 2.C.3 to require compilance w/amended physical security plan QUAY,T. Project Directorate III-1 88/12/13 2pp 47808 180-47868 181.
- -8812200080 Safeguards evaluation supporting Amond 04 to License (DPR-22.
 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/12/13. 3pp 47868:182-47868 184.

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 88-20 to all licensues holding OLs & CPs for nuclear power reactor facilities to Individual plant exam for severe accident vulnerabilities Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47728.024
- 8811300273 Advises that 881004 & 20 responses to design flaw existing w/DC power supply systeffect of design flaw on ECCS performance & justification for continued plant operation until modific correct design flaw instal
- 8812080147 Notitios Commission of change in completion schedule for Improvements in Instrument valve identification procedures described in util 880328 ftr LARSON,C.E. Northern States Power Co. 88/11/30. DAVIS,A B. Rugion 3, Ofc of the Director. 2pp. 47703 227-47783:228.
- 8812140101 Requests verification of design of automatic depressurization sys power supply per design deficiency reported by licensee on 881028 Submittel should include operational procedures implemented to ensure operability.

 STEFANO,J.J. Project Directorate III-1. 88/12/08. MUSOLF,D.M. Northern States Power Co. 3pp 47800.198-47800:200.
- 8812200048 Forwards Amend 94 to Liconse DPR-22 & safeguards evaluation. Amend modifice Paragraph 2.C 3 re physical security plan. STEFANOJ.J. Project Directorate III-1. 68/12/13. MUSQLF,D.M. Northern States Power Co. 3pp. 47808:177-47868:184.
- -6812200051 Amend 94 to License DPR-22 changing Paragraph 2.C.3 to require compliance w/amended physical security plan. QUAY,T. Project Directorate III-1, 88/12/13, 2pp. 47868.180-47868.181
- -8812200060 Safeguards evaluation supporting Amend 94 to License DPR-22.
 Diffice of Nuclear Reactor Regulation, Director (Post 670411), 68/12/13. 3pp

Q. Inspection reports, IE Bulletins & correspondence

47868:182-47868:184.

- 8811290310 Forwards Emergency Operating Procedure Insp. Rept. 50-263/88-200 on 880711-22.Deficiencies noted Executive summary of insp. w/overview of Insp. team findings in areas reviewed encl.
 HOLAHAN,G.M. Division of Resctor Projects III.IV.V. 8 Special Projects (Post 870411), 98/11/14. LARSON,C. Northern States Power Co. 8pp. 47667-205-47687-365
- -8611290314 Insp Rept 50-263/68-200 on 880711-22 Deviations noted. Major areas inspected program for implementing emergency operating procedures,per NUREG-0737, Suppl 1.

 GUTHERIES Division of Reactor Inspection & Safeguards (Post 870411) 0/3/,Suppl 1.
 GUTHERIE,S. Division of Reactor Inspection & Safeguards (Post 870411).
 HARTMANN,P.L., VANDERNEIT,C.L. Office of Nuclear Reactor Regulation, Director (Post 870411). 88/11/08. 44pp. 47667:213-47667:256
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gaupes " Svc list onc.
 CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Safety (Post 870729).
 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47700.255-47708-257.

- 8811160467 NRC Info Notice 88 031. Improper Administration & Control of Psychologi
 - cal Tosts "Svolistienci ROSSICE Orison of Operational Events Assessment (Post 870411) 88/11/22 Conschaled Edison Co. of New York, Inc. 101pp. 47703-042-47705-142
- 8812020204 Forwards Safety Insp. Rept. 50-263/88-22 on 881102-03 No violations HARRISON, J.J. Region 3. Ct. of the Director 88/11/28 LARSON, C.E. Northern States Power Co. 2pp. 47711 008 47711 014
- -8812020206 Insp Rept 50 263/89 22 on 881102-03 No violations noted. Major areas inspected evaluation of I censee program for microffming radiographs of piping sys WARDK D. DANELSCHIDH Region 3, Old of the Director 88/11/28 5pp 47711010-47311014
- 8812050213 Forwards Insp Rept 50-263/68-20 on 881024-26 No violations noted HARR SCNUU Region 3. Orc of the Director 88/11/29 LARSON,C.E. Northern States Power Co. 2pp. 47731-261-47731-267
- ~8812050214 Insp. Rept. 50.263/68-20 on 681024-28 No viciations or deviations noted Major areas inspected imprementation of Generic Ltr. 83-28 in areas of equipment classification ventor interface & reactor protection systematics tellability. NEISLERU H. GARDNERIR N. Region. 3. Oto. of the Director. 68/11/29. 5pp. 47731 263 47731 267
- 8811290030 t.RC into Nonce 88.093. Teletherapy Events "Svolist end CUNNINGHAM R.E. Davison of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York. Inc. 112pp. 47811:103-47811.215
- 8811290538 TIAC Into Notice 88 094, "Potentially Undersited Valve Actuators." Svc list enct. ROSSICE Drasion of Operational Events Assessment (Post 870411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254
- 8812020287 NRC Into Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" Svot istlenct ROSSICE Dryson of Operational Events Assessment (Post 870411) 88/12/08 Consolidated Edison Collidate York, Inc. 112pp. 47807.191.47807.302.
- 8812200241 Responds to NRC Builetin 88,004 re min flow rates for core spray, HPCI, RCIC & RHR (sumps Revs to plant operating procedures will be completed by 8901150 (pearlor training will be completed by 8901150 (pearlor training will be completed by 8901150). LARSONIC, El Northern States Power Co. 88/12/13. Office of Nuclear Reactor Regulation, Director (Post 870411), 32p. 47870 337-47870 339.
- 8812270253 Discusses 680528 & 0012 responses to Supplin to 15 Butletin 85,003, "Motor Operated Valve Common Mode Failures During Plant Transients Due to Improper Switch Selfings." Selection of additivativas requested by Item e acceptable GREENMAN.E.G. Region 3, Otc. of the Director 88/12/16 LARSON,C.E. Northern States Power Co., 1p. 47925,299,47925,299.

R. Periodic operating reports & related correspondence

- 8812140249 Monthly operating rept for Monticello Nuclear Generating Plant for Nov 1998 W/881207 IV MYRABO.A E., MUSOLF,D. Northern States Power Co. 88/11/30, 5pp. 47802 224-47802 228
- S. Reportable occurrences, LERs & related correspondence
- 8812200240 LER 86-007-01 on 860224,EFT sys transferred to toxic chemical emergency mode as result of choone montor tape broak which resulted in apparous trip of monitor Caused by worth pinch to lier creating missing-ment-W1881214 tit. HAMLETT,M.A. MUSOLF.D. Northern States Power Co. 88712714, 3pp. 47855,232-47855 234
- 8812200246 LER 85-021.01 on 851218.25 & 28.EFT sys (control from HVAC) transferred to emergency mode Cause of first event undetermined Cause of other events due to defective tape. Tape quality to be resolved W/881214 ftr.
 HAMLETTM A. MUSOLF.D. Northern States Power Co. 88/12/14 3pp. 47864.196-
- 8812200253 LER 56-004-01 on 860127.EFT sys (control room HVAC) transferred to emergency mode as result of chlorine monitor lape break,resulting in spurious trip of monitor Caused by defective lape Logic scheme changed W1881214 to.
 HAMLETT.M.A., MUSOLT.D. Northern States Power Co. 88/12/14, 3pp. 47868-162-47868 164

V. Operator Examinations

8812120198 Requests listed refs mail be submitted 60 days prior to written & oral exams scheduled for wk of 890320. WRIGHT 6.0 days prior to written & oral WRIGHT 6.C Region 3, Oic of the Director 88/12/07. LARSON.C.E. Northern States Power Co. 12pp. 47786-187-47786-199.

DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

F. Security, medical, emergency & lire protection plans

- 8812150130 Ack receipt of 881118 ltr in response to NRC 880928 ltr describing labor relations allegation relations empact on guard force supervisors due to term nations of two supervisors & lack of corporate med support. NORELUS_CE Region 3, Ofc of the Director. 88/12/02. REED.C. Commonwealth Edison Co. 2pp. 47826 290-47826 292

- 8812130050 Forwards results & conclusions of emergency operating procedures leg. Repts 50.254/88 200 & 50.265/89 200 on 880718-20 https://dent.loo/illectry.nd/ having complete understanding of entergoncy procedures development process HOLAHARI, 6M Division of Reactor Projects MINV & Special Projects (Pcts 870411), 88/12/05, REED,C Commonwealth Edison Co. 9pp. 47788 140 47798 184
- -8812130051 Emergency Operating Procedure InspiRepts 50:254/88 200 & 50:265/88 200 on 880718 29 Major areas inspicompared Revi 45 of BWR Owners Group emergency procedures guidolinos to plant specific technical guidolines VANDENBURGHC Division of Reactor Inspection & Safeguards (Post 870411) 69/11/21 36cp 47798 149 47798 184
- 8812190365 Forwards Salety Irisp Ropis 50-254/88-26 & 50-265/88-27 on 881001 1203 & notice of violation
 CLAYTONB Region 3, Ofci of the Director 88/12/13 REED,C Commonweath
 Edison Co. 2pp. 47850 208-47850 223
- -8812190376 Insp. Repts. 50-254/88-26. & 50-265/88-27. on 881001-1203. Violators noted Major areas inspected plant operations, and original controls, as an surveilance, emergency preparedness socially 8 enganoemic/tacherial support RING, M.A. Region 3, Ore of the Ovector, 88/12/13. 13pp. 47850-211-47850-223.

P. Operating license stage documents & correspondence

- 8811290129 Application for amonds to Licenson DPIT-29 & OPH 30 defeting snobbel listing w/Tech Specs Section 3/47.9 & ref to hydrautic snuhbers which are no longer used at plant in safety retated applications Fee paid
 JOHNSON, I.M. Commonwealth Edison Co. 88/11/15. MURLEY, 1.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 2pp. 47650 214-47650 237
- -8811290131 Proposed changes to Tech Spacs, deloting snutiber tables & rol to by draulic shubbers
- Commonwealth Edison Co. 88/11/15, 22pp. 47650 216, 47650 237
- 8812070033 Application for amonds to Licenses DPR-29 & OPR-30, changing intervals at which local leak rate tests of MSIVs performed from 18 to 24 months Fee pad JOHNSON,I M. Commonwealth Edison Co. 88711716. MURLEY,T. E. Document Cortrol Branch (Document Control Desk). 2pp. 47745-343-47745-348.
- ~8812070034 Proposed Tech Specs to surveillance requirements & feak rate testing of
 - Commonwealth Edison Co. 88/11/16, 4pp. 47745;345-47745;348
- 8811230025 Notities of typo in Page 2 at IM Jahrinson 681110 fir to util commitment by providing indication for reactor water level in order to meet NRC Hog Guido 1 97 Corroct value for Reg Guido 1 97 compliance is "+57." SOHINSON,IM Commonwealth Edison Co. (87.11/17). MURLEY,T.E. Office of Nuclear Reactor Regulation, Ovector (Post 670411). 1p. 47651.323-47651.323.
- 8812120020 Forwards revised Tech Spec pages replacing Attachment 1 in its entirety & reflecting changes resultant from hydrogen water clientestry program per 800916 submitted of proposed license among flav more proposed add into & corrects typos JOHNSON,I M. Commonwealth Edison Co. 887/11/18 MURLEY,T.E. Office of Nucles: Reactor Regulation, Director (Post 870411), 2pp. 47797-335-47797-348.
- -8812120021 Proposed Tech Spec Pages 3.1/4.1-3.3 1/4.1-8.3.1/4-1-9. 3.1/4.1-10.32/
- 4.2.6.8.3.2/4.2.11. * Commonwea's Edison Co. 88/11/18. 12pp. 47797:337-47797.346
- 8811280048 Generic Ltr 98-20 to all Iconsees holding Otis & CPs for nuclear power reactor facilities re individual plant exam for severe acculant vulnerabilities Svc list
- encl CRUTCHFIELD.D. Associate Director for Projects (Post 870411), 98/11/23 Corsolidated Edison Co. of New York, Inc. 81pp. 47728 303-47779-924
- 8812010305 Provides analysis of Reg Guido 1.00,Rev 2, "Radiation Embittlement of Reactor Vessel Matis" for Impact on pressure temp heatup & cookfrown curves coatained in Tech Specsiper Generic Ltr 88-11.

 RICHTER,M.H. Commonwealth Edson Co. 88/11/28 (Document Control Branch (Document Control Desk), 2pp. 47703.049-47703.050.
- 8812070243 Requests FA publication of notice of consideration of issuance of amends to Licenses DPR-29 & DPR-30 & proposed NSIC determination & apportunity for hearing on 881116 request re-roy to Tech Spoc 4.7.4.2 d.2 concorning MSIVs. ROSS, 7-roject Directorate III-2, 88/12/01, NRC No Dotared Althation Given, 6pp 47748 349-47748 354.
- 8812070030 Requests FR publication of notice of consideration of issuance of amends to Licenses DPR-29 & DPR-30 & proposed NSHC determination & opportunity for hearing on 860916 & 1118 requests to charge Tech Spacs to help reduce IGSCC ROSS, TM, Project Directorate III-2 88/12/02, NRC No Dotalind Affiliation Given 7pp. 47746 238-47746,244
- 8812200014 Requests review of BWR Owners Group position prior to requiring commit ment to replace analog transmitter trip units directly boards. SILADY,J.A. Commonwealth Edison Co. 88/12/15. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47862-196-47862:199.

- 8811290014 Forwards response to NRC 881021 lit ro violations noted in Insp. Repts 59-254/88-15 & 50-285/88-15 Corrective actions wire landed per drawings & mod test for Mod Ma-2-98-06A successfully completed BLISS,H.E. Commonwealth Edison Co. 88/11/21. Document Control Branch (Docu-ment Control Dask) 5pp. 47664:001-47684-005.
- 8811300037 Responds to NRC 881020 ftr re-violations noted in Insp. Repts 50-254/86-21,50-254/87-11,50-265/86-21 & 50-265/87-11 & proposed imposition of civil pensity in amount of \$150,000. Corrective actions AMP splices repaired & Installed. DELGEORGEL O. Commonwealth Edison Cd. 88/11/21, LIEBERMAN, J. Otc. of Enforcement (Post 8704131 and Arga 8323-2568-256). forcement (Post 870413). 4pp. 47698 332-47698 335

- 811300041 Responds to NRC 801020 lit re-violations noted in less Repts 50-254/86-21,50-254/86-21 & 59-265/87-11 re-use of unqualified AMP hyton-insulated butt spices in GE FOI contaminant per-virgion enclosures at facility FIELDMANJ Sidey & Austin 8/3/11/21, LIEBERMANJ Old of Enforcement (Post 870413), 9pp. 47680-253-47680-261
- 611160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Syc list encl CUNNINGHAM,A E Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22 Conscidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257
- 811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Control of Control Control Control of Control Contro cal Tosts "Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp 47708 042-47708 142
- 811290153 Submits supplemental response to IE Bulletin 84:03, "Refueling Cavity Water Seal." Util confident in abrity to ensure safe & effective plant condition during
- refueling outage.

 JOHNSON,I M. Commonwealth Edison Co. 88/11/22 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 4pp. 47649-255-47649-258
- 812020198 Forwards Safety Insp Repts 50-254/88-05 & 50-265/88-05 on 880808-1028 Unresolved items identified being reviewed for potential enforcement actions GREGEA, R. Region 3, Otc of the Dractor 88/11/28 REED,C. Commonwealth Edison Co. 2pp. 47717:205-47717.218.
- 8812020201 Insp Repts 50:254/88-05 & 50:265/88-05 on 880808-1028 Violations noted Major areas inspected iconsoc action following identification that adino removal design basis used in control room habitability differs from Toch Spec GILL.C.F., GREGER,L.R. Reg on 3, Oic of the Director. 88/11/28 12pp 47717:207-47717:218
- B12020240 Confirms plans for 890104 public monling at plant visitor cfr to present SALP 7 rept for plant. Appropriate corporate & plant ingli representation encouraged to attlend modifing to ensure instudel understanding of NRC issues & findings GREENMAN,E.G. Rogton 3, Otc of the Director 88/11/29. HEED,C. Commonwealth Edison Co. 2pp. 47721:093-47721.084.
- B12080222 Forwards SALP 7 Board Ropts 50:254/88-01 & 50:265/08-01 for Apr 1987 - Sapt 1989 DAVIS.A.B. Reg on 3, Otc of the Director. 88/12/01. REED,C. Commonwealth Edison Co. 3pp. 47755 187-47755 228
- 8812080224 SALP Ropts 60-254/88-01 & 50-265/88-01 for Apr 1987 Sept 1988. * Rogion 3, Ole of the Director 88/12/01, 30pp. 47755:190-47755:228.
- 811290030 NRC Into Notice 86:093, "Totaltierapy Events." Svc list and CUNNINGHAM,R E. Division at Industrial & Medical Nuclear Safety (Post 870729), 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215
- 811290538 NRC Info Notice 88 094, "Potentially Undersized Valve Actuators" Svc list onct.

 ROSSI,C E. Division of Operational Events Assessment (Post 870411). 88/12/02.

 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 812130050 Forwards results & conclusions of emergency operating procedures insp. Repts 50:254/88:200 & 50:265/88:200 on 880718:20 has identified facility not having complete understanding of emergency procedures development process. HOLAHAN,GM. Division of Reactor Projects III,IV,V & Special Projects (Post 870411), 88/12/05. REED,C. Commonwealth Edison Co. 9pp. 47708:140-47798:184.
- -8812130051 Emirgancy Operating Procedure Insp Repts 50-254/88-200 & 50-265/88-200 on 880718-28 Major areas Insp:compared Rev 4S of BWR Owners Group emergency procedures guidelines to plant specific technical guidelines. VANDENBURGH,C., KONKUN,J.E., ItAUGHINEY,C.J. Dwision of Reactor Inspection & Safeguards (Post 870411). 88/11/21. 36pp. 47798:149-47798:184.
- 812020287 NRC Into Notice 88-995, "Inadequate Procurement Requirements Imposed by Licensees on Vandors" Svc list encl.
 ROSSI.CE. Division of Operational Events Assessment (Post 870411) 88/12/08.
 Consolidated Edison Co. of New York, Inc. 112pp. 47807:101-47807:302
- 812190343 Forwards Safety Insp Repts 50-254/88-27 & 50-265/88-28 on 881114-
- 1213 & notice of violation.

 MILLER, H.J. Region 3, Ofc of the Director, 88/12/13, REED,C. Commonwealth Edison Co. 2pp. 47855.029-47855:043
- -8812190346 Notice of violation from insp on 881114-1213. Violation noted failure to provide adequate teating for environ qualification of electrical equipment important to
- MILLER,H J. Region 3, Ofc of the Director, 68/12/13, 1p. 47855:031-47855:031.
- -8812190350 Insp. Repts 50:254/88-27 & 50:265/88-28 on 881114-1213. Violations noted Major areas inspected instrumentation sys. for assessing plant conditions during & following accident & licensee action on previously identified 10CFR50.49 Inding. GAUTAMA S., GARDNER,R.N. Region 3, Ofc of the Director. 88/12/13. 12pp. 47855:032-47855.043.
- 1812190365 Forwards Salety Insp Repts 50 254/88-26 & 50 265/88-27 on 881001-
- 1203 & notice of violation.

 CLAYTON,B. Region 3, Ofc of the Director. 88/12/13. REED,C. Commonwealth Edison Co. 2pp. 47850:208-47850:223.
- -8812190370 Notice of violation from Insp on 881001-1203. Violation noted instrument air dryer returned to svc w/o reviewing applicable drawing,resulting in improper shut off of svc air supply to instrument air troader. CLAYTON,B. Region 3, Ofc of the Director. 88/12/13 1p. 47850.210-47850:210.
- -8812190376 Insp Repts 50:254/68:26 & 50:265/88-27 on 881001-1203. Violations nated Major areas inspected plant operations, radiological controls maint/ surveillance, emergency preparedness, security & engineering/technical support. RING, M.A. Region 3, Otc of the Director. 88/12/13. 13pp. 47850:211-47850:223.
- \$812270202 Forwards affidavit of PM Holzman supporting util response to NRC 881020 notice of violation & proposed civil ponelty relies of AMP hylon-insulated butt splices. at plant per listed insp ropts.
 FIELDMAN,J. Stiley & Auslin. 88/12/19. LIEBERMAN,J. Old of Enforcement (Post 870413). 4pp. 47927:130-47927:139.

- R. Periodic operating reports & related correspondence
- 8812190388 Forwards "isling of changes tests & experiments completed for Nov 1988 ROREY,R A Commonwalith Ed son Co 88711/28 Office of Nuclear Reactor Regula-tion, Director (Post 870411) 17pp 47852 097-47852 19
- 8812200010 Monthly operating ropts for Nov 1988 for Quart Cities Nuclear Power Station Units 1 & 2 W/881128 itr.

 DEELSNYDER.L., ROBEY.R.A. Commonwealth Edison Co. 88/11/30. 37pp. 47870 348 47871 023
- S. Reportable occurrences, LERs & related correspondence
- 8812190375 LER 88-027-00 on 881114,high drywell pressure auto blowdown/ HPCI intertation functional testinistrument mechanic caused TIPCI to receive momentary initiation signal Caused by personnel error Cautions will be added W/881129 ltr.
 HILL.K.J. BAX,R.L. Commonwealth Edison Co. 88/11/29, 7pp. 47849 086-47849 092.

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

P. Operating license slage documents & correspondence

- 8811280208 Notification of 881201 meeting w/util in Rocky.llu,MD to discuss contain-STEEDAD ROUNCESON OF BETTEEN THOSE BY WILLIAM RECEIVING MD TO discuss containment liner feak chase channel venting SWENSON,W.H. Project Directorate III-3 88/11/22, HANNON,J.N. Project Directorate III-3 3pp 47662/318/47662/320
- 8611280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svo list CRUTCHFIELD,D Associate Director for Projects (Post 870411) 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp 47728 303-47729 024.
- 8812050188 Advises that util has no plans to further attempt ultrasonic tosiling of reactor coolant pump casing wolds for plant due to unsalisfactory results per 880125 & 0531 requests for relief from ASME Code Section XI FAY,C.W. Wisconsin Electric Power Co. 88/11/28 Document Control Branch (Occument Control Dosk), 2pp. 47731:353-47731:354.
- 8812050121 Requests higher review priority for WCAP-11394, "Methodology for Analysis of Dropped Rod Event," to allow I censed to take advantage of methodology to reduce number of furbing runbacks
 FAY,C.W Wisconsin Electric Power Co. 88/11/29, MURLEY,T.E. Office of Nuclear
 Huactor Regulation, Director (Post 870411), 2pp. 47733:290-47733 291
- 8812090090 ftosponds to Generic Ltr 88-11, "Analysis of Embridlemont of Reactor Vessel Build in Mells" Impact of Reg Guida 1 99, Rev 2,on pressure temp I mits low temp everpressure protective sulpornts 8 PTS screening calculations ericl. FAY,C.W. Wisconsin Electric Power Co 88/11/29. Document Control Branch (Document Control Dock) 33pp. 47761.081-47781:113.
- 8812050059 Forwards notice of consideration of issuance of amend to Licenses DPR-24 & DPR-27 & opportunity for hearing to 880026 application.

 SWENSON,WH 1 Project Directorate III-3 88/11/30 FAY,CW Wisconsin Electric Power Co 2pp 47734.013-47734.019
- --8812050661 Notice of consideration of issuance of amond to Licensus DPR-24 & DPR-27 & opportunity for houring to 880826 application Amends revise Tech Speciconcerning design & optication of fuel cycle w/upgraded core WAMBACH,T.V. Project Directorate III-3 88/11/30 5pp. 47734 015-47734 019.
- 8812090281 Forwards proprietary Addendum 2 to Rev 1 to WCAP-10924-P & nonpro-prietary WCAP-12071, "Westinghouse Large-Break LOCA Best Estimate Methodolo-gy," in support of 880826 request for Tech Spec change Proprietary rept withhold (ref IOCFR2790). FAYC.W. Wisconsin Electric Power Co. 88/11/30 Document Control Branch (Docu-
- --8812090283 Requests that proprietary Addendum 2 to Rov 1 to WCAP-10924-P, "Whistinghouse Large Break LOCA Best Estimate Methodology..." be withheld from public disclosure (ref 10CFR2-790). WIESEMANN,R.A. Wostinghouse Electric Corp. 88/11/29 MURLEY,T. Office of Nuclear Reactor Regulation, Director (Post 870411) 21pp 47781:124-47781:144.
- --8812090285 Addondurn 2 to Vol 2 to WCAP-12071, "Wastinghouse Large-Break LOCA Bast Estimate Molthodology,Vol 2: Application to Two-Loop PWRs Equipped W/Upper Planum frigetion, Addondum 2: PBNP Plant Spec-fic Analysis." DEDEFIBER,S.L. HOCHREITER,L.E., SCHWARZ,W.R. Westinghouse Electric Corp. WCAP-12071 V02 ADD02, 88/12/31, 183pp. 47781:145-47781:327.
- 8812070195 Requests that util address Generic Ltr 88-17 re loss of DHR during non-power operation.Industry response to Generic Ltr 87-12 deficient in ereas of preven-tion of accident initiation 8 mitigation of accidents. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02. MCNEER,C. Wisconsin Electric Power Co. 2pp. 47749.224-47749.226.

Q. Inspection reports, IE Bulletins & correspondence

mont Control Dask), 3pp. 47781:121-47781 327.

- 8811290021 Responds to NRC 881028 fir re-violations noted in Insp. Rept 50-266/88-02 Corrective actions personnel Involved in procedural violations counselled & rev of O2-Controlled actions personnel minimum in 1988.

 FAY,C.W. Wisconsin Electric Power Co. 88/11/17. Decument Control Branch (Decument Control Deek). 2pp. 47648:214-47848:215.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges Svc list end.

 CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729).

 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257.

- 8611160497 NRC into fracco 89-691. Improper Administration & Control of Psychologi-
 - ROSSI C E Dize on CO peratonal Events Assessment (Post 870411) 88/11/22 Consentiated Each Co of New York, Inc. 101pp 47708042-47708142.
- 88.112900.30 NAC Info Natice 88.693 "Telethorapy Events" Svollist encl CONNINTENANT REL Diction of Industrial & Medical Nuclear Safety (Post 870728) 88/12702 Contof Jaced Edison Colld Rew York, Inc. 112pp. 47811.103-47611.215
- 8811290538 NRC Info Notice 83 C94. Potentially Undersized Valve Actuators." Svc Ist enci ROSSI C.E. Dission of Operational Events Assessment (Post 870411) 88/12/02 Const. Carell Edison Co. of tiew York, Inc. 121pp. 47708 143 47708 254
- 8812020287 NRC Info Notice 68,035, Inadequate Procurement Requirements Imposed by Nectsension Vendors i Systistiand. ROSSIC El Diatron of Operational Events Assessment (Post 870411) 88/12/08 Consolidated Edison Collect
- 8812200173 Proguests NFC Region III & NRR attendance at 690110 formal demonstra-tion of reactor vessel flaw sizing techniques. Flaws identified in reactor vessel safety expection forzite words during inservice regis. FAYC Will Wiscons in Euclide Power Co. 88/12/14. Document Control Branch (Docu-ment Control Dask). 3pp. 47868-171-47868-173.
- 8812270136 Ack roce ptict 681020 ftr informing NRIC of steps taken to correct violations noted in Altegation R 1-88 A 0126 NOPEL USC E Region 3, Orb of the Director 88/12/16 FAY C.W. Wisconsin Electric Power Co. 2pp. 47926

R. Period.c operating reports & related correspondence

- 8812190218 Monthly operating rep's for Nov 1988 for Point Beach Nuclear Plant, Units 1 & 2 W/881208 ** KRAUSE,C.W., FAY,C.W. Wisconsin Electric Power Co. 68/11/20. 9pp. 47840:130-
- 47840138

S. Reportable occurrences, LERs & related correspondence

- 8812010006 LEH 85-010 00 on 881026,emergency diesel generator red tagged out of skid w/kwd 483 VAC safeguards buses Led tagether indeed investigation team reported 18 text supported conclusions & 26 corrective actions Wi881123 III. FAY,C.W. Wisconsin Electric Power Co. 88/11/23, 2pp. 47703-254-47703-255
- 8812210095 LER 88:009:00 on 881118,nadequacy of EOP 1.3. "Transfer to Containment Sump Recirculation." Caused by higher level of emphasis being placed on more likely exent of small break LOCA when EOP was written Order to be Issued W/881218. FAY,CW Wisconsin Electric Power Co. 88/12/16, 5pp. 47675 132:47875.136
- 8812270234 LER 88-003 01 on 881121 discovered that procedures which defined telesting of undervotage channels of 4,160 vot safeguards power supplies did not ensure adequate testing of channels of saled by inadequate procedure W/881219 ftr. FAY,C.W. Wisconsin Electric Power Co. 88/12/19, 7pp. 47926 144-47926 150.

DOCKET 50-267 FORT ST. VRAIN NUCLEAR GENERATING STATION

F. Security, medical, emergency & fire protection plans

- 8811300083 Issua 6 to emergency plan class, Event 8 Emergency Class fication Over-Mew "W/881114 Itr. FULLERC H Public Service Co of Colorado 88/10/21 126pp. 47672.303-
 - 47673 068.
- 8811300424 Issue 9 to Radiological Emergency Response Plan Section 10 D. * Procedures That Implement or Suppl Plan ** W/881115 ts** FULLERCH Public Service Co. of Colorado 88/10/26 5pp. 47677.005-47677.011.
- 8811300560 Forwards Insp Rept 50-267/88-25 on 880911-1022 & notice of violation. CALLANIL J. Region 4, Otc of the Director 88/11/17, WILLIAMS.R.O. Public Service Co. of Coloredo 2pp 47673-207-47673-222.
- -8811300561 Notice of violation from insp on 880311-1022-Violation noted Fire Doors 13 & 9 between 480 VAC switchgear room & Blidg 10 propped opened w/no fire watch established
- Region 4, Cfc of the Director, 88/11/17, 1p. 47873 209-47873 209
- 8811300327 Forwards Insp. Rept. 50.267/88-21 on 880926-30 & notices of violation & deviation One unresolved item identified in Paragraph 7 a 2 CALLANLJ Region 4, Oto of the Director, 68/11/18, WILLIAMS,R.O. Public Service Co. cf. Colorado. 2pp. 47677.222-47677.250
- --8812050331 Notice of inclation from inspiron 880926-30 Violation noted incresee established radwaste storage area on Elevation 4,771 ft of reactor bldg whate combustives within not identified in App R evaluation rept.

 * Region 4, Ofc of the Director 88/11/18 Tp 47677:224-47677:225
- -3811390329 Insp Rept 50-267/88-21 on 880926-30-Violation & deviations noted Major areas inspected implementation of & comprance to safe shutdown requirements of IDCFR50App R MURPHY.M E., IRELAND,R E., SEIDLE,W.C. Region 4, Ofc of the Director. 88/11/21, 24pp. 47677 227-47677 250
- 68 12020 109 Revised radiological emergency response plan implementing procedure including Issue 3 of RERP Notification, "Followup Natifications," & Issue 19 of RERP, 1SC, "Activation of Technical Support Ctr."
 FULLERICH Public Service Co. of Colorado 88/11/22, 46pp. 47711.047-47711.092
- 8812140027 Advises that 880722 Rev 20 to physical security plan consistent w/provisions of 10CFR50 54(b) & acceptable CALLANLJ, Region 4, Otc ct the Director 88/11/30, WILLIAMS,R O. Public Service Co of Colorado 2pp 47799

- 8812150193 Ciscussos Operational Safety Team Insp Thept 50:267788:200 (832150193 G SCHOSE COPHINER TO SERVICE THE TOTAL THE COLOR OF SERVICE OF SERVICE OF COLOR OF SERVICE OF SE
- -9812159200 Notice of violations from inspirent 880509-20 Violations noted operating procedures not adequately maintaineducation glack of Fusio Figure 1997 and to be pulled by operator 8 no supply of replacement fuses. Region 4, Oto of the Orector 88/17/07, Spp. 47826-314-47826-318.

H. General correspondence

8812010393 Comment supporting proposed rule 10CFR26 to Filmost for Out WILLIAMS,RIO Public Service Co. of Coloraids, 88711721 Docketing Branch 15pp. 47679,192-47679 206

P. Operating license stage documents & correspondence

- 8811290391 Informs that portions of 880923 application for amound to Licon not in compliance wiregulations Portions rejected from consideration include cover fits, notice of separance 8 8-50 agroument HETNER, K.L. Project Directorate 10, 88711718 WILLIAMS, R.O. Public Ser Colorado, 4pp. 47668 103-47668 106.
- 8811290400 Forwards request for additinfo rolinity gaton of possible ATWS partial review of 881015 response to Generic Lin 65-06. HETNER,KIL Project Divertorate W 88/11/18. WILLIAMS,RIO. Public Ser Colorado 5pp. 47685-079
- 8811300069 Advises that ut1 should consider asted SHP sections in eval posed conversion plan.

 HETIMERIKL Project Directorato IV 88/11/21 WILLIAMS,RIO Public Ser Colorado. 4pp. 47668 309 47688 312.
- 8811280048 Generic Ltr 88:20 to all licensees holding Otis 8 CPs for nucl reactor facilities to individual plant exem for severe accident vidinorabilit
- GRUTCHFIELD O. Associato Dirocler for Projects (Post 670411) 8871172 dated Edisch Co. of New York, Inc. 81pp. 47728.303-47729.024
- 8812190248 Forwards response to Generic Lit 88-11, "NRC Pusition on Ra-brittlement of Reactor Vessel Malls & Impact on Plant Operations," prosor Guide 1 99,Rov 2 Subj reg gud en of diretily applicabilit to facility WILLIAMS.R O Public Service Co of Colorade 88/12/07 Document Con (Document Control Desk) 11pp 47849 055 47849 065
- 8812230276 Forwards response to request for extill into re-rich of operations in high energy line breaks Reanalysis of bldg temp profiles completed & 860928 Branch (Document Control Dask). 13pp. 47916 149:47916 161

- 8B11300560 Fcrwards Insp Rept 50:267/88:25 on 880011-1022 & notice of CALLAN,L.J. Region 4, Ofc of the Director, 88/11/17 WILLIAMS,R.O. Put Co. of Co'orado 2pp 47673 207-47673 222.
- -8811300561 Notice of violation from inspirence 880911-1022 Violation noted 13 & 9 between 480 VAC switchgear room & Bidg 10 propped opened watch established.
- Region 4, Ofc of the Director, 88/11/17, 1p. 47673 209-47673 209.
- -8811300563 Insp. Rept. 50-267/88/25 on 880911-1022 Violations noted. Nispected previously, identified insp. Indrings, licensia, action in response Bulletins, operational safety verification & monthly maint observation. FARRELL, R.E., MICHAUD, P.W., WESTERMAN, I.F., Region. 4, Old of the D. 11716-13pp. 47673-210-47673-222
- 8811300327 Forwards Insp Rept 50-267/88:21 on 880926:30 & notices of deviation One unresolved item ident field in Paragraph 7 a 2 CALLANL J Regon 4, Ot cot the Director 88/11/18, WILLIAMS,R O. Put Co. of Co'orado 2pp. 47677:222-47677:250
- -8812050331 Notice of violation from inspirent 880926-30. Violation noted in labilished radwaste storage area on Elevation 4,771 It of reactor bldg where bles within not identified in App R evaluation root.
 Region 4, Ofc of the Director, 68/11/18, 1p. 47677-224-47677-225.
- 8812050332 Notice of deviation from insp on 880926-30 Deviations noted tration sea's found in aux-lary boiler room were not 3-h rated & docume developed to substantiate portable fans.
 Region 4, Ofc of the Director 88/11/18 2pp. 47677-226-47677-226
- **8811300329 Insp Rept 50-267/86-21 on 880926-30 Violation & deviations a areas inspected implementation of & compliance to safe shutdown requirections of App R. MURPHY.M.E., IRELAND.R.E., SEIDLE,W.C. Region 4, Ofc of the Director 24pp. 47677-227-47677-250
- 8811180211 NRC Into Notice 88-090, "Unauthorized Removal of Industri Gauges" Svc list and CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Pot 86/11/22, Consolidated Edison Co. of New York, Inc. 99pp 47708
- 8811160467 NRC into Notice 88-091, "Improper Administration & Control of Cal Tests" Svc1 stience ROSSI.C.E. Division of Operational Events Assessment (Post 870411) Cansolidated Edison Co. of New York, Inc. 101pp 47708.042-47708.142

8811300074 Advises that util 881026 response to NRC Bullotin 88-008, "Thormal Stresses in Piping Connected to RCS" acceptable Conditions addressed by bullotin infligit to occur at plant.

HETNER, K. L. Project Chectorate IV. 80/11/22, WILLIAMS, R.O. Public Service Cn. of Cotorado, 4pp. 47597, 249, 47697, 252.

- 8811290469 Ack receipt of 881104 ftr informing NRC of steps taken to correct violations noted in Irsp Ropt 50-267/88-20 CALLAN,L.J. Region 4, Ofc of the Director 88/11/25 WILLIAMS,R.O. Public Service Co. of Colorado 2pp 47649 285-47649 286
- 8812010111 Ack receipt of 880920 ftr informing NHC of steps taken to correct violations CO of Colorado 2pp 47702 296-47702 303
- 88 12010 128 Ack recept of 88 i 104 ltr informing NRC of slops taken to correct violations includ in Insp. Repts. 50: 267/88: 15.8. 50: 267/88: 23. CALLAN, L.J. Region. 4, Ofc. of the Direction. 88/11/28. WILLIAMS, R.O. Public Service Co. of Colorado. 2pp. 47702: 278-47702: 295.
- 6812020312 Ack receipt of 881104 ftr informing NRC of steps taken to correct violations noted in Insp Rept 50:267789-17
 CALLANL J. Region 4, Olic of the Director 88741729, WILLIAMS,R.O. Public Service Co. of Colorado 2pp. 47718 277-47718 278
- 8811290030 NHC Info Notice 88 093, "Telotharmy Events." Svc. st. enct. CUNNINGHAM,R.E. Ovision of Industrial & Modical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811 103-47811 215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708.254.
- 8812150193 Discussos Operational Safety Team Insp Rept 50-267/88-200 on 880509-20 & forwards notice of visitations Aridi response to unresolved items including control of check! sis for complex activities & control of maint activities requiested CALLANLU NRC - No Detailed Affiliation Given 88/12/07. WILLIAMS,R.O. Public Servico Co. of Colorado. 20p. 47826 312-47826 318
- --8812150200 Notice of violations from insp on 880509:20 Violations noted emorgancy operating procedures not adequately maintained, including lack of Fuse F-254 which was required to be pulled by eperator & no supply of replacement fuses.

 * Flag on 4, Olic of the Director 88/12/07, 5pp. 47826 314-47826 318
- 8812020287 NRC Into Notice 88:095, "Inadequate Procurement Requirements Imposed by Leonsees on Venifors." Svc list and ROSSI,C.E. Division of Operational Events Assussment (Post 870411) 88/12/08 Consolidated Edison Co. of New York, Int. 112/pp. 47807.181-47807.302
- 8812200149 Responds to NRC 861107 lit re-violations noted in Insp. Rept 50-267/88-26 Util concludes that FSV design documents, licensing basis & plant drawings do not contain inconsistencies to load sequencing associated w/480 V Bus 2 BREY.H L. Pubic Service Co. of Colorado 86/12/15. Document Control Branch (Decument Control Desk). 32pp. 4/865.001-47865.035.
- R. Perladic operating reports & related correspondence
- 8812200019 Monthly operating right for Nov 1988 for Fort St Vrain Nuclear Generating Station W/881215 It.

 Station W/881215 It.

 BLOCK,M.L., FULLER,C.H. Public Sorvice Co. of Coforedo. 88/11/30. 8pp.
 47871.088-47871.085
- S. Reportable occurrences, LERs & related correspondence
- 8811290266 Forwards Rev A to EE-93-0007, "Engineering Evaluation of Interaction & Effects of Plant Protection Sys & Steam Line Rupture Defection/Isolation Sys." Submittal addresses concerns railsed by NRC WAREMBOUNG, DW. Public Service Co. of Colorado 88/11/22. Document Control Branch (Document Control Dosk). 2pp. 47665.126-47665:158

- --8811290272 Rev A to "Engineering Evaluation of Interaction & Effects of Plant Protection Sys & Steam Ling Rupture Detection/ Isolation Sys."

 BATES,G.S. Public Service Co. of Colorado EE-93-0007 R A. 88/11/21, 31pp. 47665:128-47665:158.
- 8812150040 PNO-IV-98-093 on 881205,NRC informed of plans to discontinue facility operations on or before 900630 w/no final date selected Plans include power coastdown using fuel presently in reactor w/no fourth rofueling or addition of new fuel WESTERMAN,T.F. Rog on 4, Ofc of the Director, 88/12/05, 2pp. 47826:323-47826.324
- 8812190354 LER 88-015-00 on 881011, loss of power to 480V assential buses occurred during loss of outside alactric power tost Caused by dirty or sticking contact condition. Contacts replaced 8 Operations Order 88 06 issued. W/881214 ltr. CHESNUTT, SW., FULLER, CH., Public Service Co. of Colorado 88/12/14, 13pp. 47853.259-47853.271

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8812050130 Forwards public version of Rev 88-2 to emergency plan, Vol A & Revs 88-6 & 88-8 to implementing procedures manual, Vols B & C respectively.W/DH Grimsley release memo
 - TUCKER, HB, Duke Power Co. 88/11/10 Document Control Branch (Document Control Desk) 5pp. 47719:180-47720-066
- -8812050131 Rev 88-2 to plant emergency plan, Vol A. TUCKMAN, M.S. Duke Power Co. 88/10/14, 87pp. 47719 185-47719:272
- →8812050132 Revised emergency plan implementing procedures.including Revs 68-6 & 88-8 to implementing procedures emergency plan manual, Vols B & C, respectively. TUCKMAN,M S. Duke Power Co. 88/10/14, 164pp. 47719 273-47720 066

- 8812090029 Forwards public version of Rev 28 to "Crisis Mgt Pien" W/ DH Grimsley undated release memo TUCKER, H.B. Duka Power Co. 89/11/22. Decument Control Branch (Decument Con-
- trol Dosk), 4pp, 47757:171-47757.215
- -8812090034 Public version of Rev 28 to "Crists Mgt Pian for Nuclear Stations" * Duke Power Co. 88/12/01, 41pp. 47757,175,47757,215
- 8812080243 Advises that 880929 Rev 6 to guard training & qualification plan consistent w/provisions of 10CFR50.54(p) & accupiable CLINE,W.E. Region 2, Otc of the Director, 88/11/29, TUCKER,H.B. Duke Power Co. 2pp 47783 260-47783,270
- 8812090085 Forwards environ assessment & finding of no significant impact rejutil 831111 request for exemption from requirements of 10CFR50.App R PASTIS,H.N. Project Directorate II-3, 88/12/05 TUCKER,H.B. Duke Power Co. 3pp. 47762 236 47762 243
- --8812090087 Environ assossment & finding of no arginficant impact rolul 1 831111 re-quest for exemption from requirements of 10CFR50,App R. MATTHEWS,D.B. Project Directorate II-3 88/12/05 Spp. 47762 239 47762 243

H. General correspondence

- 8812090335 Confirms moeting w/util on 881209 at Region II ofcire reorganization,per B81121 folcon ERNST.M.L. Flegron 2, Clc of the Director 88/12/01. TUCKER,H.B. Duko Power Co 1p. 47782:231-47782 231.
- P. Operating license stage documents & correspondence
- 8811290197 Responds to Generic Ltr. 88-11, "NRC Position on Radiation Embritifement of Reactor Vessel Matis & Its Impact on Pant Operations." TUCKER,H.B. Duke Power Co. 88/11/21. Document Control Branch (Document Control Dask) 2pp. 47649.197-47649.198.
- 8811280196 Discusses NRC response to B&W Owners Group on ATWS issue. Licensee requested to submit plant-specific conceptual design for option selected among three options considered in end NRC fir. PASTISHIN Project Directorate II:3 88/11/22, TUCKER,HB, Duke Power Co. 4pp. 47656-310-47656-316
- 8811280048 Generic Litr 88-20 to all ficensees holding Otis & CPs for nuclear power reactor facilities re-individual plant exem for severe accident vulnorabilities. Svc list GRUTCHFIELD.D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 8812020315 Discusses will 881107 llr ro problem of Loo Steam Station supporting sud-danty applied amergancy loads during unavailability of Knowge hydroelectric ganera-MATTHEWS,D.B. Project Directorate II-3, 88/11/23, TUCKER,H.B. Duke Power Co. 3pp. 47711.117-47711.119.
- 8812070012 Forwards responsu to NRC 880920 request for addit into re application for amonds for Licenses DPR-38,DPR-47 & DPR-55, adding requirements re standby shutdown factify Motor operators to to added to valves in auxiliary see water sys. TUCKER,H-B, Duke Power Co. 88/11/28, Document Centrel Branch (Document Control Desk) 6pp. 47746-092-47746-097.
- 8812010274 Forwards Suppl 2 to safety evaluation to simulator modelling of upper head volding per 880718 ftv.
 PASTIS.H.N. Project Directorate III-3. 88/11/29. TUCKER,H B. Duke Power Co. 2pp.
 47707 093-47707 095
- -8812010276 Safety evaluation supporting response to simulator modeling of upper head voiding.
 * Project Directorate II-3, 88/11/29 1p. 47707.095-47707.095
- 8812050150 Discusses 8B1017 request for approval of route for transport of spent reactor fuel from Oconee Nucleer Station, Senece, SC to B&W Lynchiburg, Research Ctr.Lynchburg, VA.
 MACDONALD, C.E. Transportation Branch 88/11/30. SNIPES, R.G. Duke Power Co 10pp. 47732.320-47732.329
- 8812080080 Requests that util address Genoric Ltr 88-17 ro loas of DHR during non-power operation. Issue of high priority & should be addressed accordingly. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 88/12/ 02 LEE,W.S. Duke Power Co. 5pp. 47753.129-47753.133.
- 8812080027 Responds to 860909 ltr requesting NRC concurrance on util understanding of App H, "Reactor Vessel Matt Survallance Program Requirements." Separate cavity dosimetry Installation for each unit unwarranted. MATTIREWS D.B. Project Directorate II-3. 88/12/05 TUCKER, H.B. Duke Power Co. 4pp. 47783-243-47783.246.
- 8812120012 Forwards "Emergency Dose Assessment Manual"
 TUCKER,H.B. Duke Power Co. 88/12/07. Document Control Branch (Document Control Desk) 3pp. 47780 219-47781:120
- ~8812120014 "Duke Power Co Emergency Dose Assessment Manual." TUCKER,H.B. Duke Power Co. 88/11/21, 259pp 47780:222-47781:120.
- 8812210063 Forwards Request for Reliof 88-09 from Section XI of ASME Boiler & Pressure Vessel Code (w/addenda litrough Winter 1080) re pressure testing specific welds during second 10-yr inservice Insp Interval W/one oversize drawing.

 TUCKER,H.B. Duke Power Co. 88/12/09. Document Control Branch (Occument Control Desk), 4pp 47887:151-47887.155.
- 8812210114 Application for amonds to Licenses DPR-38,DPR-47 & DPR-55, providing edequate standby bus voltage for all design basis accident scenarios. Fee paid TUCKER,H.B. Duke Power Co. 88/12/15. Document Control Brench (Document Control Desk) 3pp. 47888:276-47888 289

- -8812210115 Proposed Tech Specs re-standby bus voltage for all design basis accedent scenarios
 - Oska Power Co. 88/12/15 | 11cp 47868 2/9-47688 289
- 8812220310 Informs that util 980525 response to Generic Ltr 88-03, "Steam Binding of Aux any Feedhater Pumps" acceptable NRC of signerment what I conclusion that pro-cedures addressing steam tinding of energonic feedhater pumps unmecessary, PASTISHIN Project Dicctorate II-3 88/12/19 TUCKER HIB Ouke Power Co. 4pp 47903072 47903 075

Q. Inspection reports, IE Bullotins & correspondence

- 88 #1290559 Ack receipt of 860309 fir informing NRC of steps taken to correctly olahons noted in hisp Repts 50 269788-11, 50 270788-11 & 50-287788-11 ERNST.M.L. Region 2, Ofc of the Director 88/11/17, TUCKER,HIB. Duke Power Co tp. 47662 200-47662 200
- 6811160211 NRC Info Notice 88 090, "Unauthorized Removal of Industrial Nuclear Gauges "Stocksterd CU-MINGHAM RE Division of Industrial & Medical Nuclear Saloty (Post 870729). 89/11/22 Consolidated Edison Co. of New York, Ind. 99pp. 47708-255-47708-257
- 8811160467 NRC Info Notice 88 091, "Improper Administration & Control of Psychological Tests " Svc list and ROSSIC E: Owis on of Operational Events Assessment (Rost 870411) | 89/11/22 Conscilated Edison Co. of New York, Inc. 101pp | 47708.042-47708.142
- 8811300145 Responds to NRC 881024 lin rely plations noted in Insp Repls 50-269/88a Tradition Response to time, called in the Valuation Finest in the Property Representation of the Associated RepOrt Report of the Valuation Finest Report R
- 8812050280 Forwards Insp. Repts 50:269/88/33,50:270/68/33 & 50:287/88/33 on 681015-1115 hap violations or deviations noted BROWNLEE/V L. Region 2, Ofc of the Director 88/11/23 TUCKER,H.B. Duko Power Co. 2pp. 47731:255 47731:250
- -8812050282 Insp. Repts 50 269/88:33.50:270/88:33 & 50:287/88:33 on 881015 1115 No violations or devations insted Major aleas inspected operations surveillance testing maint activities, safeguards & rad at on protection & inspired operations. SKINNER,P H. Region 2, Ofci of the Director (88/11/23) 14pp (47731:237-47731:250)
- 8812050312 Ack receipt of 881028 ftr informing NRC of sleps taken to correct violations noted in finsp Rept 50-269/88-28 Response to Violation 287/88-28 02 did not address actions taken to improve effectiveness of fest program ERNSTIME. Region 2. Ofic of the Director. 887/11/25 TUCKER,HIB. Duke Power Co to 47740.122-47740.122
- 8812050072 Advises that use of ASME Code Cases N.401,N.416,N.426 & N.427 in inservice inspiprogram approved, per 880302 request MATTHEWS D.B. Project Oriectorata II-3 88/12/01 TUCKER,H.B. Duke Power Co 7pp. 47734 020-47734 020
- 8812060018 Forwards revised response to NRC 891028 fit re-violation noted in Insp. Repts 50-269/88-28.50-270/88-28 & 50-287/86-28 Corrective actions test procedure revised to require tags to be placed on removed control power fuses TUCKER,H.B. Duke Power Co. 68/12/01. Document Control Branch (Document Control Desk) 4pp. 47741.055 47741.059
- 8812120118 Provides action status update re NRC Builetin 88:004, "Potential Safety-Related Pump Loss" Milgs cornacted re anticipated response time after 830601. TUCKER-H8 Duke Power Co. 88/12/01 Document Control Branch (Document Con-trol Desk) 2pp. 47791-339-47791-340.
- 8811290020 NRC Info Notice 88-093, "To etherapy Events." Suclist encl. CUNNINGHAM, RE Division of Industrial & Medical Nuclear Safety (Post 870729). 881/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811-103-47811-215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list enci.
 ROSSI C E Division of Operational Events Assessment (Post 870411) 88/12/02.
 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254.
- 8812120117 Responds to NRC 881102 ftr re volations noted in Insp Repts 50-269/88-32,50-270/88-32 & 50-287/88-32 Corrective actions: craft personnel & supervisors cautioned against applying pressure to any line w/o engineering knowledge TUCKER/NB Duke Power Co. 88/12/0/2 Document Control Branch (Document Control Oesk) 3pp 47789.107-47789-109
- 8812070149 Informs that util 880307 response to NRC Bulletin 88.001. "Defects in Washinghouse Circuit Breakers," satisfactory.
 PASTISHIN Project Ovectorate II-3 68/12/05 TUCKERHIB Duke Power Co. 2pp 47746 247-47746 248
- 8812150198 Requests resubmittal of response to v.o'alions colod in Insp Repls 50.269/ 88.13,50.270/88 13 & 50.287/88 13 Ut. 180332 response to Violations A,B,D,E.1 & C to Valve HP-98 meat 10CFR2 201 regurements Violation E 2 requires resubmittal. GIBSON,A.F. Region 2, Otc of the Director. 88/12/07, TUCKER,H.B. Duke Power Co. 4po 47826 319 47826 322
- 8812020287 NRC Into Notice 88-095, "inadequato Procurement Requirements Imposed by tixensees on Vendors" Svc ist and ROSSIC E. Division of Operational Events Assossment (Post 870411) 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807;191-47807:302.
- 8812140122 EN 88-105.nobce of violation 8 proposed imposition of civil penalty in amount of \$25,000 will be issued on 891213. Action based on ficensee facure to provide adequate procedural guidance to ensure MPSI remain operable. LUEHMAN_J_LIEBERMAN_J. Old of Enforcement (Post 870413) 88/12/08. tp. 47800 213 47800 213
- 8812210063 Forwards Request for Relief 88 03 from Section XI of ASME Boiler & Pressore Vesset Code (w/addenda trirough Winter 1990) re pressure testing specific welde during second 10 yr inservice insp interval W/one oversize drawing TUCKER HB. Duke Power Co. 88/12/09. Document Control Branch (Occument Control Desk) 4pp 47887-161-47887-155

- 8812210326 Responds to NRC 881110 fir re violations noted in Insp Repts 50-269/88 17,50-270/88-17 & 50-287/88-17 Procedures MP/O/A/2001/13 & MP/O/A/2001/3C revised to include proper resistance/forque values & specify proper lubricant TUCKEA.H.B. Duke Power Co. 88/12/09. Document Control Branch (Document Control Dask) 9pp. 47877 248-47877-256
- 8812200307 Discusses violations noted in linsp Repts 50-269/88-25, 50-270/88-25 a 50-287/88-25 on 880801-15 & lorwards notice of violation & proposed impostion of cwil pena ty W/o notice ERNST.M.L. Region 2. Old of the Director 88/12/13. TUCKER.H.B. Duke Power Co. 4pp. 47868 086-47868 069
- 8812210068 Ack receipt of 881123 ftr informing NRC of step taken to correct violations noted in Insp. Repts 50-289/88-31, 50-270/88-31 & 50-287/88-31. Violation occurred as stated in notice of violation
 COLLINS.D M. Rogion 2, Ofc of the Director, 88/12/14 TUCKER,H.B. Duke Power
 Co. 1p. 47878 219-47878.219
- 8612270207 Forwards additiperformance test & analysis info,per requost during 861104 enforcement conference re-potential degraded capabilities of reactor bridg cooling units (RBCU) Further into re-RBCU & LPI cooler operability chiene also onci-TUCKER,H.B. Duke Power Co. 88/12/15. Document Control Branch (Document Control Branch (Document Control Branch) trol Dosk) 11pp 47924 213 47924 223

R. Periodic operating reports & related correspondence

- 8812200212 Forwards monthly operating ropts for Nov 1088 for Occured Station Units 1.2.8.3.8 corrected monthly operating repts for Oct 1988. TUCKER-H.B. Duke Power Co. 88/12/15. Document Control Branch (Document Control Ossk), 1p. 47861-033-47861-019.
- -8812200297 Monthly operating repts for Nov 1988 for Occurro Station Units 1,2 & 3. WILLIAMS,R A. Duke Power Co. 88/11/30, 14pp. 47861.004-47861-018.
- -8812200301 Addenda to monthly operating right for Nov 1988 for Occineo Nuclear Station Units 1,2 & 3 Duke Power Co. 88/11/30. 1p. 47861 019-47861.019

S. Reportable occurrences, LERs & related correspondence

- 8812070064 Advises that listed Tech Spec changes committed to In LER 269/88 66 re inadequate design analysis of HPIS in ECCS aump recirculation mode will be submit
- TUCKER HB. Duke Power Co. 88/12/01. Document Control Branch (Document Control Dask). Tp. 47746.249-47746.249.
- 8812080119 LER 88.008.00.on 880301.teating of standby shutdown facility HVAC Sec water sys rovealed max sys flow capacity bolow design value for worst case event No introdukte conactive action taken Cause not positively confirmed W78812014.

 NORTH,P.J., TUCKER,H.B., Duke Power Co. 88712701. 7pp. 47783.234-47783.240.
- 8812270261 Advises of Incensed decision not to install cavitating venturis & to pursue other alternatives,per ref. supplemental into to LER 289786-10 re. Installation commitment Emergency feedwater piping sys not qualified TUCKER,H.8. Duke Power Co. 86/12/16. Document Control Branch (Nocument Control Desk) 2pp. 47922 355-47922 356

Y. Dry Cask Independent Spent Fuel Storage Installations

8812130117 Forwards responses to NRC 880727 questions re-util Econso application ToriSFSI SAR.
TUCKER,H.B. Duke Power Co. 88/11/23. Document Control Branch (Document Control Dask). 322pp. 47793;100-47794:061.

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8812050130 Forwards public version of Rev 88.2 to emergency plan, Vol A & Revs 88.6 & 88.8 to imprementing procedures manual, Vols B & C respectively W/DH Grimsley release mome.
 TUCKER,H.B. Duke Power Co. 88/11/10. Document Control Brench (Document Control Dask). Spp. 47719.180-47720:088
- ~8812050131 Rev 88:2 to plant emergency plan, Vol. A. TUCKMAN,M.S. Duke Power Co. 88/10/14, 87pp, 47718;185-47719,272
- --8812050132 Revised emergency plan Implementing procedures including Revs 88-6 & 88-8 to Implementing procedures emergency plan manual Vols B & C. respectively. TUCKMAN,M S. Duke Power Co. 88/10/14. 154pp. 47719:273-47720:066.
- 8812090029 Forwards public version of Rev 28 to "Crisis Mgt Plan." W/ DN Grimsley undated release momo.
 TUCKER,H.B. Duke Power Co. 88/11/22. Document Control Branch (Document Control Desk). 4pp. 47757;171-47757;215.
- --8812090034 Public version of Rev 28 to "Crisis Mgt Plan for Nuclear Stations." * Duke Power Co. 88/12/01, 41pp. 47757:175-47757:215.
- 8812080243 Advises that 880929 Rev 6 to guard training & qualification plan consistent w/provisions of (ICCFR50.54(p) & acceptable. CLINE,W.E. Region 2, Orc. of the Director, 88/11/29, TUCKER,H.B. Duke Power Co. 20p. 47783 269 47783 270.
- 8812090085 Forwards environ assessment & finding of no significant impact re usi 831111 request for exemption from requirements of 10CFR50,App R. PASTIS,H.N. Project Directorate II-3, 88/12/05, TUCKER,H.B. Duke Power Co. 3pp 47762-236-47762-243.

- --8812090087 Environ assessment & Ending of no significant impacting util 831111 request for exemption from requirements of ICCFR50,App R MATTHEWS,D 8 Project Directorate II-3, 88712705 Spp. 47762 239-47762,243
- 8812200232 Adwsos that 981014 flev 88-2 to radiological emergency plan consistent wipterring stds of 10CFR59.47(b) 8 acceptable. Change re meteorological equipment not consistent w/Rug Guide 1.23. DECKEN,11.8. Region 2. Ofc of the Director. 88/12/12. TUCKEN,11.8. Duke Power Co. 2pp. 47868:302-47868.303

H. General correspondence

- 8812090005 Confirms meeting w/ohl on 881209 at Region It ofcite reorganization,pcr 881121 felcon
 EHNST, M.L. Region 2, Ofc. of the Director. 88/12/01, TUCKER,H.B. Duke Power Co.
 19, 47/82-231, 47/82-231
- P. Operating license stage documents & correspondence
- 8811290197 Responds to Generic Litt 89-11, "MHC Position on Radiation Embrillement of Reactor Vossal Malis, 8 its Impact on Plant Operations."
 TUCKERH B. Duke Power Co. 48711/21. Document Control Branch (Document Control Desk). 2pp. 47649 197-47649 198.
- 8811280196 Discussos NRC response to B&W Owners Group on ATWS issue. Licensea requested to submit plant specific conceptual design for option solected among three options considered in each NRC lit. PASTIS, H.N. Project Directorate III-3, 88/11/22, TUCKER, H.B. Duke Power Co. 4pp. 47656 310-47656 316
- 8811280048 Generic Ur. 88-20 to all Teensees holding OLS & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnerabilities Svc list
- onel CRUTCHFIELD.D. Associate Director for Projects (Post 870411): 88/11/23. Consei-dated Edison Co. of New York, Inc. 81pp. 47/28 303-47729 024.
- 8812020315 Discusses will 881107 thrite problem of Loa Steam Station supporting auddenly applied emergency leads diring unavailability of Kaowee hydroniectric genera-
- MATTHEWS.D.B. Project Directorate III-3, 887/11723, TUCKER,FIB. Duke Power Co. 3pp. 47711:117-47711:119
- 8812070012 Forwards response to NRC 880920 request for adult into re application for amonds for Licenses DPR-38,0PR-47 & DPR-55, adding requirements re stantiby shutdown facility Motor operators to be added to valves in auxiliary sec water sys TUCKER,118, Divide Power Co. 88711728. Document Control Desk) 6pp. 47748-092-47746-097.
- 8812010274 Forwards Suppl 2 to safety evaluation re-simulator modelling of upper head vcking.pdr 880718 itr PASTIS,LLN, Project Directorate III:3 88711/20 TUCKER,H 8: Deko Power Co. 2pp. 47707:093-47707:005
- -8812010276 Safety evaluation supporting response to simulator modelling of upper Project Directorate 8-3, 88711728, 1p. 47707:005-47707:085
- 88 12080080 Requests that unit address Generic Etr 88-17 re loss of DHR during non-power operation Issue of high priority & should be addressed accordingly. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02. LEE,W.S. Duke Power Co. 5pp. 47753,129-47753, 133
- 8812080027 Responds to 860908 ftr requesting NRC concurrence on util understanding of App H, "Reactor Vessel Matt Survollance Program Requirements." Separate cavity desimetry Installation for each unit unwarrented MATTHEWS.D.B. Project Directorate II-3, 88/12/05, TUCKER.H.B. Duke Power Co 4pp. 47783:243-47783.246.
- 8812120012 Forwards "Emorgency Doso Assessment Manual "
 TUCKER, H.B., Duko Power Co. 88/12/07, Document Control Dask), 3pp. 47780.210-47781.120.
- --8812120014 "Duko Power Co Emergency Dose Assessment Mariual." TUCKER,H B Duke Power Co 88/11/21, 259pp 47780 222-47781:120
- 88 12210063 Forwards Request for Ruliof 88-09 from Soction XI of ASME Boller & Prossure Vessel Code (w/addenda through Winter 1980) to pressure testing specific wolds during second 10-yr inspirate inspiraterial Myone oversize drawing.

 TUCKER,H B. Duke Power Co. 88/12/09. Document Control Branch (Document Control Dosk), 4pp 47887;151-47887;155
- 8812210114 Application for amends to Licenses DPR-38,DPR-47 & DPR-55, providing adequate standby bus vollage for all design basis accident scenarios Fee pald. TUCKER,H.B. Duke Power Co. 88/12/15. Document Control Branch (Document Control Dusk), 3pp. 47888/276-47888/289.
- --8812210116 Proposed Tech Specs re standby bus voltage for all design basis accidont scongrios Duke Power Co. 88/12/15 11pp. 47888.279-47888 289
- 8812220310 Informs that util 880525 response to Genetic Ltr 88-03, "Steam Binding of Auxiliary Feedwater Pumps" acceptable NRC disagreement witut conclusion that procedures addressing steam binding of emergency feedwater pumps unnecessary. PASTIS,H.N. Project Directorate It.3. 86712719, TUCKER,H.B. Duke Power Co. 4pp. 47903:072-47903:075
- Q. Inspection reports, IE Bulletins & correspondence
- 8811290559 Ack receipt of 880909 fir informing NRC of steps taken to correct violations noted in lasp Repts 50:269788-11, 50:270788-11 & 50:287788-11. ERNST,ML. Region 2, Ofc of the Director, 88/11/17 TUCKER,H.B. Duke Power Co. 1p. 47682:200-47682:200

- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc 1st enct.
 CUNNINGHAM,R.E. Dwision of Industrial & Medical Nuclear Safety (Post 870729)
 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708:257
- 8611160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tosts "Svc Ist and ROSSI.C E. Duvision of Operational Events Assessment (Post 870411) 88/11/22 Consolidated Edson Co. of New York, Inc. 101pp. 47708.042.47708.142
- 8811300145 Responds to NRC 881024 ltr re violations noted in Insp Ropts 50-269/88-31.50-270/88-31 & 50-287/88-31 Corrective actions. Procedure HP/O/8/1000/57 mod field to include specific test of sampling main condensor offgas. TUCKERJ-H.B. Duke Power Co. 88/11/23. Document Control Branch (Document Control Desk). 3pp. 47677 023-47677.025.
- 8812050280 Fo:wards Insp. Repts 50:269/88:33:50:270/88:33 & 50:287/88:33 on 881015:1115 No violations or deviations noted BROWNLEF, V.L. Region 2, Otc of the Oroctor 88/11/23, TUCKER, H.B. Duke Power Co 2pp. 47731:235-47731
- --8812050282 Insp. Repts. 50-269/88-33.50-270/68-33 & 50-287/88-33 on 881015-1115 No violations or deviations noted Major areas inspected operations, surveillance testing,maint activities, safeguards & rachation protection & inspirit open items SKINNER,P.H. Region 2, Old of the Director 88/11/23 14pp 47731,237-47731,250.
- 8812050312 Ack recopt of 881028 fit informing NRC of steps taken to correct violations noted in Insp Rept 50:269/88:28 Response to Violation 287/88:28:02 did not address actions taken to improve disclaveness of test program ERNST ML. Regen 2, Ofc of the Director. 88/11/25, TUCKER,H.B. Duke Power Co 1p. 47740 122-47740 122.
- 8812050072 Advisos that uso of ASME Code Casos N-401,N-416,N-426 & N-427 in in-service insp program approved,per 880302 request MATTHEWS,D.B. Project Directorate II-3 88/12/01. TUCKER,H.B. Duke Power Co. 7pp. 47734.020-47734.026
- 8812080018 Forwards revised response to NRC 881026 fir re-viciation noted in Inap Repts 50:269/88:28,50:270/88:28.50:287/08:28.Corrective actions lest procedure roused to require lags to be placed on removed control power luses.

 TRICKER, H.B. Duke Power Co. 88/12/01 Document Control Branch (Document Control Desk), 4pp. 47741,056-47741 059
- 8812120118 Provides action status updato re NRC Bulletin 88-004, "Potential Safety-Related Pump Loss" Migs contected re anticipated response time after 890601. TUCKER,HB Duke Power Co. 88/12/01. Document Control Branch (Document Con-trol Dosk). 2pp. 47791:339-47791:340
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc I.st encl. CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8911290538 NRC Info Notice 88 094, "Potentially Undersized Valve Actuators." Svc flat ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812120117 Responds to NRC 881102 ftr re violations noted in Insp Repts 50-269/88-32,50-270/98-32 & 50-287/88-32 Corrective actions: craft personnel & supervisors
- caulionod against applying prossure to any line w/o engineering knowledge.

 Tuker H.B. Duke Power Co. 89/12/02. Document Centrol Branch (Document Centrol Dosk) 3pp. 47789. 107-47789.109. 8812070149 Informs that util 880307 response to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Broakers, "satisfactory.
 PASTIS,HTN. Project Directorate II-3 88/12/05. TUCKER,H.B. Duke Power Co. 2pp.
 47746:247-47746;248.
- 8812150198 Hoqueste resubmittal of response to violations noted in Insp. Repis 50-289/88-13.50-270/88-13 & 50-287/88-13.Uiii 880902 response to Violations A,B,D,E,1 & C re Valvo HP-98 meet 10CFR2 201 requirements Violation E 2 requires resubmittal. GIBSON,A F. Region 2, Olc of the Director. 88/12/07, TUCKER,H.B. Duke Power Co. 4pp. 47826-319-47826:322.
- 8812020287 NRC Info Notice 88-085, "Inadequate Procuroment Requirements Imposed by Licensees on Vendors." Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807-391-47807:302.
- 8812140122 EN 88-105:notice of violation & proposed imposition of civit penalty in amount of \$25,000 will be issued on 881213. Action based on licensed failure to provide adequate procedural guidance to ensure HPSI remain operable. LUETIMANJ., LIEBERMANJ. OIC of Enforcement (Post 870413), 88/12/08. 1p. 47800:213-47800:213.
- 8812210063 Forwards Request for Relief 88-99 from Section XI of ASME Boder & Pressure Vossel Code (w/addende through Winter 1980) to pressure testing specific welds during second 10-yr Inservice Insp. interval Wome oversize drawing TUCKER, H.B. Duke Power Co. 88/12/09. Document Control Branch (Document Control Branch (D trol Desk), 4pp. 47887;151-47887;155.
- 8812210326 Responds to NRC 881110 ltr re violations noted in Insp Repts 50:269/88-17,50:270/88-17 & 50:267/88-17 Procedures MP/O/A/2001/3 & MP/O/A/2001/3C revised to include proper resistance/torque values & specify proper lubricant TUCKER,H.B. Duke Power Co. 88/12/09. Document Control Branch (Document Control Dask). 9pp. 47677:248-47877:256.
- 8812200307 Discusses violations noted in Insp Repts 50:269/88:25, 50:270/88:25 & 60:287/88:26 on 880801-16 & torwards notice of violation & proposed imposition of civit penalty. W/o notice.
 ERNST, ML. Region 2, Ofc of the Director: 88/12/13. TUCKER,H.B. Duke Power Co. 4pp. 47888.066:47868.069.

- 8812210068 Ack redect of 681123 fir informing NRC of step taken to correct violations noted in large Repts 50 269/85 31, 50/270/64/31 & 50/287/86/31 Violation occurred as stated in notice of worldon COLUMISTO M. Regin 2 Cife of the Director 89/12/14. TUCKER H.B. Dirko Power Co. tp. 478/8 219 478/8 219
- 8812270207 Forwards add performance lest 8 analysis into per request during 881104 enforcement conference religiously degraded capabilities of reactor bidg cooling units (RBCU) Further inforce RBCU 8 LPI cooler operability chiena also and TUCKER HB Duke Power Co. 887(2715) Document Control Branch (Document Control Desk). 11pp. 47924-213-47924-223

R. Pertodic operating reports & related correspondence

- 8812200212 Forwards monitify operating repis for Nov 1988 for Occines Station Units 1,2 & 3 & contected monitify operating repis for Oct 1988 TUCKER HB Dute Power Co. 88/2715 Document Control Branch (Document Control Desk) 1p. 47861-003-47861-019
- --8812200297 Monthly operating regts for Nov 1998 for Oconee Station Units 1,2 & 3 WilliamS,R A. Duke Power Co. 88/11/30, 14pp. 47851-004-47851-018
- -8812200301 Addignos to monthly operating rept for Nov 1988 for Oconee Nuclear Station Units 1,2 & 3
 - Duke Power Co. 88/11/30 1p. 47861 019 47861 018

S. Reportable occurrences, LERs & related correspondence

- 8812070064 Admiss that usted Tech Specichanges committed to in LER 269/88-06 re inadequate design analysis of HPIS in ECCS sump recaculation mode will be submit-ted by 890228 TUCKER HIB Duke Power Co. 58/12/01. Document Control Branch (Document Con-trol Desk). 1p. 47746-249-47746-249
- 8812270261 Advises of licensed decision not to install cavitating venture & to pursue other alternatives,per ref supplemental info to LER 269/86-10 re installation commitment Emergency leadwater piping sys not qualified. TUCKER,HR Bibuke Power Co. 88/12/16 Document Control Branch (Document Control Desk). 2pp. 47922-355. 47922-356.

Y. Dry Cask Independent Spent Fuel Storage Installations

- 8812130117 Forwards responses to NRC 880727 questions relict license application
- tor ISFSI SART TUCKER.H.B. Duke Power Co. 88/11/23 Document Control Branch (Document Control Desk) 322pp. 47793 100-47784 061

DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

- 8812060150 Ravised emergency clan implementing procedures including Rev. 15 to OP 3510, "Offsite 8 Site Boundary Monitoring." Rev. 14 to OP 3508, "Onsite Medical Emergency Procedure." 8 Rev. 8 to CP 3524, "Emergency Actions to Ensure..."

 **Vermont Yankee Nuclear Power Corp. 88/11/128, 38pp. 47741.067-47741.106
- 8812140229 Dept Instruction 1 to Procedure OP-3531, "Emergency Ca'l-In Method " PORTER,E C. Vermont Yankee Nuclear Power Corp. 88/12/01, Spp. 47814-072-47814-072
- 8812220331 Forwards Safety Insp Rept 50-271/88-19 on 881011-1114 & notice of violation.
 WIGGINS.J.T. Region I, Ofc of the Director. 68/12/15 MURPHY.W.P. Vermont Yankee Nuclear Power Corp. 2pp. 47900.057-47900.095
- --8812220338 Safety Insp. Rept. 50-271/88-19 on 881011-1114 Violation noted Major areas inspected actions on past insp. findings, operational safety,security,plant operations maint & survivilance,engineering support & radiological controls. HAVERKAMP,O.R. Region 1, Ofc. of the Director. 88/12/13 32pp. 47900.060-47900.095

G. Adjudicatory correspondence

- 8812140075 Interrogations propounded by Vormont Yankee Nuclear Power Corp to State of VT (Contentions 2 & 3).* Certificate of Svc and Related correspondence GAD.R.K. Vermont Yankee Nuclear Power Corp. GAD.R.K. Ropes & Gray. #488 7622 88/11/28. Vermont, State of the part 770.164.47770.172.
- 8812140086 Interrugationes propounded by Vermont Yankee Nuclear Power Corp to New England Coation on Nuclear Pollution,Inc. (Contentions 2 & 3).* Certificate of Svc end Related correspondence.

 GAD,R K. Vermont Yankee Nuclear Power Corp. GAD,R K. Reid & Priest. #488 7620.

 88/11/28 New England Coation on Nuclear Pollution. 9pp. 47770 122-47770.130.
- 8812140093 Interrogations propounded by Vermont Yankee Nuclear Power Corp to Commonwealth of MA (Corrientions 2 & 3) * Certificate of Svc and Related corre-
- spondence GAD,R.K. Vermoni Yankee Nuclear Power Corp. GAD,R.K. Ropes & Gray. #488 7521, 88/11/28 Massachusetts, Commonwealth of .9pp. 47770.155.47770.163.
- 8812140111 Vermont Yankee answer to New England Coalition on Nuclear Pollution environ interrogatories * Certhicate of Svc each Related correspondence REIDDA, GAD,R.K. Vermont Yankee Nuclear Power Corp. GAD,R.K. Ropes & Gray #488 7625 88/12/01. New England Coalition on Nuclear Pollution 28pp. 47769 234-
- 8812190127 NRC Staff response to New England Coalition on Nuclear Pollution first set of Intercoatches & request for production of documents to NRC Staff on Staff environ assessment, * Related correspondences HOOGDON,A.P. Assistant General Counsel for Hearings. #488 7663, 88/12/06. New England Coalition on Nuclear Pollution 13pp 47801:125-47801:143.

- --8812190130 Allidavit of FC Stort.* Advises that author prepared responsible regulations Related correspondence. STURZ.F.C. Fuel Cycle Safety Branch 68/12/08 1p. 47801.138-47801.13
- -8812190139 Affidable of MB Fastile. Advisors that multiproproperty response interrogationes Certificate of Svc end. Radiert correspondence FARATILE, M.B. Project Directorale (3) 88772708 5pp. 47801 138-47801-17
- 8812190227 Vermont Yankeo spent fuel pool expansion.* Advises that Ni Coation on Nuclear Pollution does not intend to respond to incoused 8811 Cost on on Nuclear Political trees not middle to respond to inconsent 811 alones due to questions being out-of time Pulated correspondence FERSTER, AC New England Coat! on on Nuclear Politidon FERSTER A Curan & Tousloy, #488-7670, 88/12/12 GAD,R.K. Vermont Yankee Nu Corp GAD,R.K. Ropos & Gray 1p 4/801 164-4/7801:164
- 8812270042 Advises that Commonwee'th of MA within respond to recipion requests in proceeding due to reasons being out-of time Rulated correspondences. B Massachusetts. Commonwea'th of #480 7801 88712713 Ropes 8 Gray 15 47873 083-47873 083.
- 8812280058 New England Coalition on Nicigar Pollution Hitel set of inter-request for production of documents to MRC on NRC onwron assessment too significant impact: * W/Certificate of Svc Related correspondence required to production of decembers to tent, on the control tespesation of scale and impact. *W.Gerfichale of Svc Retailed correspondence FERSTERA New England Coddition on Nuclear Pollution FERSTER. Curan & Tousley #488 7738 88/12/20 Office of the Gordraf Co. 47886 134-47868 145
- 8812280065 New England Coultion on Nuclear Poliution motion for extension the second round interrogatories & document requests to NRC Staff on five pool expansion safety evaluation. Curtificate of Svc onci. FERSTER, New England Coalition on Nuclear Poliution FERSTER, Curran & Touslay. #486.7739. 88/12/20. Atomic Safety and Licensing Eupp. 47886.146-47886.149.
- 8812280226 Memorandum & order (extension of thio) * Grants New Engla on Noticeal Poliution 881220 request for 1 wk extension until 890103 to NRC second discovery requests Served on 881221. BECHHOEFER,C. Atomic Safety and Licensing Board Penel #488 7736 New England Coal fron on Nuclear Poliution, 2pp. 47886 132-47886 133.

H. General correspondence

8812010667 Comments on rule 10Cf R26 to filtures for thity program rule. Be that NRC include rule stating that NRC regulations procumpt static 8/or regulations to ensure no conflict over jurisdiction develops.

WEGANDG J. Vermont Yankoe Nuclear Power Corp. 88/11/18. CHILK.S. the Secretary of the Commission. 2pp. 47878.131-47678.132.

I. Financial information

- 8812010133 Forwards annual cashflow statements for util & nine apprisor co 1988 as exidence that util maintains approved quarantian of payment in militor retrospective premium assessment under Price Antieuson Act PEARSON, I Vermont Yankoa Nuclear Power Corp #8/11/28. Docur Brench (Document Conirol Desk) 3pp. 47702:321-47702:323.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8812070029 Rev 6 to updated FSAR for Vermont Yankon Nuclear Pov MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 88/11/30, 202pp 47749 223

P. Operating Ilcense stage documents & correspondence

- 8811280174 Application for amend to License DPR-28 revising Tech Spect 0737 llams (I.K. 3.13.8 ILK. 3.22,per GL-63-02,Fee pald MURPHY,W.P. Vermont Yankee Nuclear Power Corp. 68/11/18. Document (Oocument Control Desk). 10pp. 47653 310-47653.332.
- -8811280178 Proposed Tech Specs re Generic Ltr 83-02.
 * Vermont Yankee Nuclear Power Corp. 88/11718, 13pp. 47653 320-4765
- 8811280048 Generic Lit 88:20 to all ficensees holding OLs & CPs for n reactor facilities re individual plant exam for severe accident vulnorab
 - GRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11 dated Edison Co. of New York, Inc. 81pp. 47728-303-47729.024.
- 8812070133 Application for amond to License DPR-28,consisting of Chaining fuel cladding integrity safety limit for use in calculating critical povinitis in future reload analyses Foe paid.

 MURPHY,W.P. Vermont Yankee Nuclear Power Corp. 88/11/30. Docu Branch (Document Control Dask). 3pp. 47749,266-47749,270.
- ••8812070134 Proposed Tech Specs revising fuel cladding integrily safety in calculating critical power operating limits in future reload analyses.
 Vermont Yankee Nuclear Power Corp. 88/11/30, 2pp. 47749,268-4774.
- 8812990308 Forwards SPDS Isolator test rosults.
 CAPSTICK,R.W. Vermont Yankee Nuclear Power Corp. 88/12/05. DocuBranch (Document Control Desk), 2pp. 47775-278-47775-320.
- -8812090307 "Emergancy Rosponsu Facilities Into Sys Isolator Typo Te Vermont Yankee Nuclear Power Corp 88/12/05, 4tpp. 47775:200-477
- 8812140072 Advises that util 880916 request for 10CFR50,App J exempt talinment teak rate testing methods unnecessary due to final formations. teinment teak rate tooung troubles (53FR45990). FAIRTILE,M.B. Project Directorate 1-3 88/12/09. CAPSTICK,R.W. Ver Nuclear Power Corp. 3pp. 47799.237-47799-239.

Q. Inspection reports, IE Bullelins & correspondence

- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nac'ear Gauges " Svc list encl. CUNNINGHAM,R E. Division of Industrial & Modical Nuclear Safety (Past 870729). 88/11722. Consolidated Edison Co. of New York, Inc. 99pp. 47708.235-47708.257.
- 8811150467 NRC Into Notice 88:091, "Improper Administration & Control of Psychological Tests." Svc list encl. ROSSI,C E. Division of Operational Events. Assessment (Post 870411): 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.
- 8811290030 NAC Into Notice 88-093, "Teletherapy Events." Svc 1st end CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811 103 47811 215.
- 8811290538 NRC Into Notice 88-094, "Potentially Undersized Valve Actuators." Svc list encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812090298 Responds to NRC 881104 ltr re-violations noted in Insp Rept 50-271/88-14 Corrective actions foam sys restored to operable status
 MURPHY,W.P. Vermont Yankoe Nuclear Power Corp. 88/12/02. Document Control Branch (Document Control Desk), 6pp. 47762.073-47762.078
- 8812120015 Responds to NRC 881104 lit ro violations noted in Insp Rept 50-271/88-18 Corrective action taken rotraining of all I&C Dopt personnel in radiation protection requirements initiated.

MURPHYW P. Vermant Yankee Nuclear Power Corp. 88/12/02. Document Control Branch (Document Control Desk). 4pp. 47780.111-47780.114

- 8812020287 NRC Into Notice 88-095, "Inadequate Procurement Requirements Impused by Licensees on Vendors." Svc list encl. PIOSSI, C.E. Division of Operational Events. Assessment (Post 870411): 88/12/08 Censol dated Edison Co. of New York, Inc. 112pp. 47807:101-47807:302
- 8812220331 Forwards Safety Insp Rept 50-271/88-19 on 881011-1114 & notice of vio-WIGGINS, J.T. Rog on 1, Old of the Diructor, 88/12/15, MURPHY, W.P. Vormant Yankoe Nuclear Power Corp. 2pp. 47900.057-47800.095
- -8812220334 Notice of violation from insp on 881011-1114. Violation noted accessus to contaminated areas including northwest corner room of reactor bidg & section of torus area not appropriately posted nor reped off.

 * Region 1, Ofc of the Director. 88/12/15. 1p. 47900.059-47900.059.
- --8812220338 Salety hisp Rept 50:271/86-10 on 881011-1114 Violation noted Mejor areas Inspected actions on past hisp finithings, operational satisty, security, plant operations, maint & surveillance, onglineering support & rind-ological controls HAVERKAMP,D.R. Region 1, Old of the Director, 88/12/13, 32pp., 47900,060-47000.005

R. Periodic operating reports & related correspondence

8812140284 Morthly operating rept for Nov 1088 for Vermont Yankea Nuclear Power Station W/881210 ftr.

WALLIN,G.A., MURPHY,W.P. Verinont Yankoe Nuclear Power Corp. 88/11/30 6pp.
47821:108-47821:113

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812020133 Rov 7 to Artificial Island Emorgancy Plan Station Procedure EPIP-202S, "Operations Support Cir (OSC) Activation & Operations."

 * Public Service Electric & Gas Co. of New Jersey. 80/12/02, 26pp. 47/22.158-
- 8812150264 "Artificial Island Emorgoncy Plan, Annual Exercise," conducted on 881123-
- 1202. Public Service Electric & Gas Co. of New Jersey, 88/12/31 450pp 47815:138-47816 296

P. Operating license stage documents & correspondence

- 8611280046 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities.Svc list
- encl CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729.024.
- 8811300303 Summary of 881116 meeting w/util in Rockville,MD re util long-range programs at plants & NRC long-range efforts.

 STONE,J.C. Project Directorate I-2, 88711725 Project Directorate I-2, 4pp. 47677.132-47677.135.
- 8812050041 Forwards response to Generic Ltr 88-11, "Rediation Embrittlement of Re-actor Vessel Matts." Util will submit keense amend requests to incorporate new heatup & cooldown curves in Toch Specs for Salom Units 1 & 2 by Dec 1988 MILTENBERGER, 5. Public Sorvice Electric & Gas Co. of New Jersey, 88/11/28, Doc-ument Control Branch (Document Control Desk), 7pp. 47732.021-47732-027.
- 8812060222 Summary of 681122 meeting w/util in Rockvillo,MD re preparation of blo-logical assessment of sea turtle occurrences at plant Agenda encl. STONE,J.C. Project Directorate I-2, 88/12/01, Project Directorate I-2, 5pp. 47745.009-47745:013
- 8812120175 Notification of Significant Licensee Mooting 86-149,Rev 1.on 890113 in Region Lote to discuss design basis reconstitution SWETLAND,PD. Region 1, Ofc of the Director. 88/12/01. Region 1, Ofc of the Director. 28/12/01. Region 1, Ofc of the Director. 29p 47786.118-47786.119.

- 8812070216 Forwards Generic Lti 88-17 re loss of DHR during nonpower operation Belief that Industry as whole has not aggressively responded to resolve concern following identification in Genoric Lti 87-12 stated.

 MURLEY, T.E. Olicc of Nuclear Reactor Regulation, Director (Post 870411), 88/12/02 FERLAND, J. Public Service Electric & Gas Co. of New Jersey. 4pp. 47749.256-4740.
- 8812150094 Documents agreement between util & J Stone & G Rivenbark of NRC re-extending response submittal date for Genaric Ltr 88-14 concerning instrument alir supply sys MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersay. 88/12/06. Document Control Branch (Document Control Dask). 2pp. 47835-001-47835-002.

- 8812150004 Requests withdrawal of util 851119 application for amends to Licenses DPR-70 & DPR-75 consisting of License Change Request 84-23 deteiting App B of environ Tech Spucs & substituting w/environ protection plan MILTENBERGER, Public Service Electric & Gas Co. of New Jersey. 88/12/09 Document Control Brench (Document Control Desk). 2pp. 47823.013-47823.014.
- 8812200106 Notifies NHC of Intention to use ASME Section XI Code Case N-416 as relates to mod Code Case permits deferred of sys hydrostatic resting unit next regularly schiduled test for repair or replacement of Class 2 piping MILTENBERGERS, Public Service Electric & Gas Co of New Jersey, 88/12/13. Document Control Branch (Document Control Desk). 2pp. 47860 293-47860-294.

8812210025 Approves 881022 outline of biological assessment release turtles, subjite In-

cluding description of trash bar cloaning process & dotals of operational aspects to minimize capture at sea turtles. STONE_IC. Project Directorate 1-2, 88712714 MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 4pp. 47881:157-47881:160

- 8812090078 Forwards response to NRC Bullouri 88-602 re-potential for rapidly propogating fatigue cracks in sleam generator tubes MILTENBERGER,S. Publ.c Survice Electric & Gas Co. of New Jersey, 88/03/28. RUSSELL,W.T. Region 1, Oic of the Director, 21pp. 47757 318-47757:338.
- 8811300351 Responds to NRC 881013 ltr re violations noted in Insp Repts 50-272/88-17 & 50-311/88-17. Short term actions have been developed to quickly establish necossary controls to offactively prevent future surveillance problems
 MILTENBERGER,S. Public Service Electric & Gas Co. of New Jorsey 88/11/18. Document Control Branch (Document Control Desk). 5pp. 47674 (30-47674:140.
- 8811290404 Forwards Saluty Insp Repts 50:272/88-19 & 50:311/88-20 on 880927-1107 No violations noted
 WENZINGER,E.C. Region 1, Old of the Director 88/11/21. MILTENBERGER,S
 Public Service Electric & Gas Co. of New Jersey. 2pp. 47657-305-47657 324.
- ~8611290412 Insp Rupts 50-272/08-18 & 50-311/08-20 on 860027-1107 No violations noted Major areas inspected plant operations including operational safety verification, maint, LERs review, surveillance, Unit 2 outage activities & Insp items followup. SWETLAND,P.D., BROCHARDT,R.W., GIBSON,K.H. Region 1, Oic of the Director. 88/11/21, 18pp. 47657-307-47657:324.
- 8812020018 Advisos that util 880811 response to NRC Bullotin 88-004 adequately provided into requested in Itams n.b.c & d of sub) bulletin Min recticulation flow results requested within 30 days of completion of evaluation. STONE_JC_Project Directorate 1-2, 88/11/21, MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 4pp. 47707:164-47707:167.
- 8811160211 NRC Info Notice 88 090, "Unauthorized Removal of Industrial Nuclear
- Gauges." Svc hist and: CUNNINGHAM.R E. Division of Industrial & Modical Nuclear Safety (Post 870729). 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 6811180467 NRC Info Notice 88-091, "Impropur Administration & Control of Psychological Tests" Svc list and ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/11/22. Consolitidated Edison Co. of New York, Inc. 101pp. 47708-042-47708-142.
- 8811290034 Forwards Radiological Controls Insp Repts 50-272/88-18 & 50-311/88-18 on 880926-1008 & notice of violation BELLAMY,R.R. Report 1, Otc of the Director, 88/11/22 MILTENBERGER,S. Public Service Electric & Gas Co. of New Jorsey. 3pp. 47650-250-47650-280.
- -88 (1290036 Notice of violation from insp on 880926-1006 Violation noted rolling tool withdrawn from reactor cavity pool w/o required dose rate survey performed & work crew allowed to work in restricted seel table room. Rogian 1, Old at the Director, 88/11/22, 2pp. 47650,259-47650,260.
- --8811290040 Insp. Repts 50:272/68:18 & 50:311/88:16 on 680926:1006. Violation noted Major areas inspected rad-ological controls organization & staffing personnel qualifications & starring, corrective action sys & performance monitoring & ALARA. NIMITZ, R.L., O'CONNELL, P.V., SHANBAKY, M.M. Hogion 1, Otc of the Director, 687 11/16, 20pp. 47650-261-47650-280.
- 8811290364 Forwards Mgt Meeting Ropts 50-272/88-18 & 50-311/88-18 on 881020.Moeting repts summarize discussion on NRC identified weaknesses in area of industrial safety-adiotogical controls & fall of worker into reactor cavity on 881018. EBNETER,S D. Region 1, Olc of the Director, 88/11/22, Mill.TENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 3pp. 47665.049-47665.078
- ~88.11290365 Mgt Mepting Reptis 50-272/88-18 & 50-311/88-18 on 881020 Major areas discussed recent NRC identified weaknosses in area of industrial safety & radio-logical controls & fall of worker into Unit 7 reactor cavity on 881018 NIMITZ,R.L. Region 1, Otc of the Director. 88/11/18. 27pp. 47665-052-47665-078
- 8812010338 Forwards attachment inadvortently omitted from util 880606 request for rolled from requirements to 10-yr hydrostatic testing of buried piping in unit auxiliary Heedwalur sys.

 MILTENBERGER,S Public Service Electric & Gas Co. of New Jorsey. 88/11/28. Document Control Branch (Document Control Dask). 4pp. 47710 083-47710 086

CUNNING/IAM,R.E. Division of Industrial & Medical Nuclear Satisfy (Post 670729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811-103-47811-215

8811290538 NRC Info Notice 68 094, "Potentially Undersized Valve Actuators." Svc list enci ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708.143-47708.254

8812020287 NRC Inito Notice 88,085, "Inadequate Procurement Requirements Imposed by Licensession Vendors" Svc list end:
ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/12/08
Consolidated Edison Co. of New York, Inc. 112pp. 47807 191-47807 302

R. Periodic operating reports & related correspondence

8811290465 "NPDES Discharge Montoring Rept for Oct 1988" W/881123 III TRECO,J. Public Service Electric & Gas Co. of New Jorsey, 88/10/31. CAPORALE Now Jersey, State of, 25pp. 47650.053-47650.077

8812190271 Monthly operating rept for Nov 1988 for Salem Unit 1, W/881211 ltr.
WHITE,P., MILLER,L.K. Public Service Electric & Gas Cg of New Jersey 68/11/30 10pp 47860 115 47860 124

S. Reportable occurrences, LERs & related correspondence

8812070065 LER 87-019-01 on 871227 oxygen concentration within weste gas holdup sys was greater than 2% for more than 48 h contrary to Tech Specs Cause attributed to design Oxygen concentration towered below 2% timit W/881130 ft/ POLLACK M.J., M. LERILL K. Public Service Electric & Gas Co. of New Jersey 88/11/30 5pp. 47737:318-47737-322

8812130114 Supplemental Special Rept 68-3-4 during Aug 1988-138 addl ponetration see's found impered Cause not positively determined Hourly fire watch to continue pending resolution of tire protection concerns in area MILLERIL K. Public Service Electric 8 Ges Co. of New Jersey 88/12/07 Document Control Branch (Document Control Branch (Document Control Desk.) 6pp. 47792-076-47792-081.

DOCKET 60-274 U.S. GEOLOGICAL SURVEY RESEARCH REACTOR

P. Operating license stage documents & correspondence

8812150010 Responds to 881117 ltr approving restart of reactor info re rechation levels present ever top of annulus between old & new tanks & any change in pool water temp resulting from installation of smaller tenk provided per request MitLARD.H II Interior, Dept. of, Goological Survey, 88/11/28, MARTIN,R D. Region 4, O'c of the Director. 2pp. 47829:203-47829.210.

Q. Inspection reports, IE Bulletins & correspondence

8812140136 Forwards Insp. Rept 50:274/88-01 on 881110 & notice of violation.W/o notice of violation.
MURRAY,B Rogion 4, Ofc of the Director 88/12/05, MILLARD,H Intenor, Dept. of,
Geological Survey, 2pp. 47800/357-47800/359.

~8812140142 Insp. Rept. 50:274/88:01 on 881110 Violations inoted Major areas Inspected:startup insp. Including reactor status, startup procedures & radiation protec-MU/IRAY,B. Region 5, Oic of the Director, BANGART,R L. Region 4, Oic of the Director, 88/12/05, 1p. 47800 359-47800:359

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8811300077 Rev 6 to "San Luis Obispo County/Cities Nuclear Power Plant Emergency Response Plant W7891122 Itr. SHIFFER.J D. Pacific Gas & Electric Co. 68/10/31, 348pp. 47671;317-47672:302.

8812130244 Forwards Insp Repts 50-275/88-28 & 50-323/89-24 on 880904-1022 No. violations noted Discusses events
KIRSCH.D.F. Rogion 5, Otc of the Director, 88/11/23 SHIFFER,J.D. Pacific Gas &
Electric Co. 3pp. 47798:107-47798:128.

-8812130245 insp Repts 50:275/88:26 & 50:323/88:26 on 880904:1022.No violations or devictions noted.Mejor areas inspected; plant operations, maint & surveillence activities, onsite events, open item silens & selected independent insplactivities, WAGNER.W., JOHNSTON, K.E., NARBUT, P.P., Region 5, Oic of the Director, 88/11/22 16pp. 47798:110-47798 128.

Implementing

> PB Bloch chairman & GA Lin-#488 7654 88/12/07, 2pp.

> > od FSAR for Dahlo introl Branch (Docu

8812210107 FOIA request for all closed sessions &/or meetings of Commissioners Felt between Jan 1960 & Dec 1985 re plant SCHMEGE,PIA O'Melveny & Myors 88704706 NRC - No Detailed Afficiation Given

2pp 47874 057 47874 058

8811230225 Forwards notice of issuance of withdrawal of applications for americs to Licenses DFR-80 & DPR-82 HOOQH, Project Orectorate V | 68/19/31 | SHIFFER J () | Pacific Gas & Flectric Co 4pp 47622 275-47622 280

-8811230227 Notice of withdrawal of 871030 & 0924 applications for amends to the censes DPR 80 & DPR 82.

ROOD,H Project Directorato V 88/10/31 2pp 47622 2/9 47622 280

8811290434 Forwards notice of consideration of issuance of amend to License DPB 60 8 proposed NSHC deformation 8 opportunity for financing in 881.118 application to toward took Spec 4.3.1.1.Table 4.3.1.

ROOD,H. Project Directorate V. 89/11/21. SHIFFER J.D. Pacific Gas 8. Electric Co. 4pp 47662:201-47662 212

+8811290441 Notice of consideration of issuance of amond to License DPR-80 & pieposed NSHC determination & apportunity for huaning Americ revises Tech Spines in regular Requency interval identified in Tech Specs 4.3.1.1, Table 4.3.1. ROOD,H Project Directorato V 88/11/21 8pp. 47652 205 47662 212

8811280048 Generic Ltr 68:20 to all receives historing Cals 8, CPs for nuclear peaks reactor facilities to individual plant exam for severa accurrent vulnerabilities Svo 1st CRUTCHFIELD.D. Associate Director for Projects (Post 870411), 80/11/23. Consult dated Edison Co. of New York, Inc. 81pp. 47728/303/47729/024.

8812050055 Responds to Goneric Lir 89-11. "NRC Position on Radiation Enternitionent of Reactor Vessor Malis & Impact On Plant Operations." SHIFFER.J.D. Pacific Gas & Election Co. 88/11/28. Document Centrol Branch (Document Control Desk), 1p. 47733-294-47733-294.

8812060117 Forwards diagrams to high pressure injection sys error egusly crinitled from 881028 fir ro long-term seismic program & PBA documentation for LPIS Auxiliary salt. water sys documentation wit be submitted by 891209 as agreed on 881128 SHIFFERUD Pas-to Gas & Electric Co. 88/11/29. Document Centrol Branch (Document ment Control Desk) 100pp 47741 254-47741 353

8812070187 Forwards approach on for amonds to Euconson DPR-80 & DPH-82, consisting of License Amend Request 88-98 authorizing use of 17X17 VAN FAGE 5 fiel assembly a consisting of the control of the co SHIFFER, J.D. Pacific Gas & Electric Co. 887+1729 | Document Control Branch (Document Control Dask) | 2pp. 47738 180 47739 331

--8812070188 Application for emends to Licenses DPR-80 & 0298-82, consisting of License Amend Request 88-08, changing Tech Specs to refeel use of 17X17 VANTAGE 5 fuel assemblies SHIFFER,J D. Pac. c Gas & Electric Co. 88/11/29, 42pp, 477(8) 182-47738:231

--8812070189 Proposed Tech Specs, reflecting use of 17X17 VANTAGE 5 fuel assemblies
• Pacific Gas & Electric Co | 68/11/29 | 458pp | 47/38 234-47739 331

8812220348 Requests that Leansee address concerns in Generic Ltr 88-17 to loss of DHR during recipiower operation NHC censions size to be of high priority as result of 870410 incident.
MURLEY,T.E. Office of Nuclear Reactor Regulation, O rector (Post 870411), 897127
05 CLARKE,R.A. Pacific Gas & Electric Co. 6pp. 47892 244-47892 249.

8812150268 Forwards proposetary WCAP-11594 & equipropriotury WCAP-11595 "Wes-highouse Improved Thermal Design Procedure Instrument Uncortainty Calculations for Diable Caryon Units 1 & 2" & application for withousing proprietury Info SHIFFER.J.D. Pag & Gas & Electric Co. 88712709. Document Cantrol Branch (Docu-ment Control Desk). 3pp. 47816:287-47816.354.

--8812159289 Application for withholding proprietory WCAP-115H4, "Westinghouse for proved Thermal Design Procedure Instrument Uncertainty Calculations for Diable Canyon Units 18.2" Canyon Units 1 & 2 "
WIESEMANN,R.A. Westinghouse Electric Corp. 68711717 Office of Mixiliae Regulation, Director (Post 870411). 10pp. 47816 303-47816 309

-8812150270 "Westinghouse Improved Thermal Design Procedure Instrument Cocertainty Calculations for Diablo Canyon Units 1 & 2" TULEY.C.R. Westinghouse Electric Corp. WCAP 11595-87709/30, 44pp. 47818-319. 47816 354

8812160011 Responds to NRC 881031 request for into re Generic Etr 83-28, tiem 4.3, "Reactor Trip Sys Reliability." Survolvance Test Providure STP 1-16C modes Tech Spac requirement to verify undervoltage trip & shunt trip every 18 months SHIFFER, J.D. Pacific Gas & Electric Co. 88/12/09. Document Control Branch (Debi ment Control Desk), 3pp. 47834.271-47834:273

6812190072 Forwards PRA for auxiliary saltwater system util 881129 commitment re Clong term setsmic program.

SHIFFER, J.D. Pacific Gas & Electric Co. 88/12/09. Cocument Control Branch (Cocument Control Desk), 85pp. 47848 241-47848 327.

8812180014 Forwards proprietary WCAP-11312,Rev 1 & nonpropositary WCAP-11966 "Westinghouse Owners Group Tech Spoc Subcommitted Reautor Trip Breaker Merol! Survailance Optimization..." WCAP-1312,Rev 1 withhold (rol 10CFR2 790) SHIFFER,J.D. Pacific Gas & Electric Co. 88/12/12 Document Control Branch (D-Kument Control Desk). 3pp. 47834;276-47834;336

-8812160016 Requests that proprietary WCAP-11312,Rtw 1, "Westinghouse Owners Group Tech Spec Subcommittee Reactor Trip Breaker Maint/Surveillance Optimize-tion Program," be withhold from public dischaure (roll 10CFR2 790) WIESEMANN/R A. Wostinghouse Electric Corp. 88712/05 MURLEY,T. Office of Nuclear Reactor Regulation, Director (Post 870411) 10pp 47834 279-47834-288

- --8812160018 "Visitinghouse Owners Group Tech Spec Subcommittee Reactor Trip Breaker Mant/Surveinance Optimization Program" MCCUTCHAN,D A, PEFFER,DR., MAGUIRE II Washinghouse Electric Corp. WCAP-11966 88/10/31 49pp 47834:289-47834:336
- 8812160026 Forwards proprietary WCAP-12064 & nonproprietary WCAP-12065 ropts in support of util review of steam generator tubing at plant for susceptibility to folique SHIFFEH.I.D. Pacific Gas & Electric Co. 88/12/12. Document Control Branch (Document Control Dosk). 4pp. 47869.125-47869.332.
- --8812160027 Submits application withholding propriotary rept WCAP-12064, "Diable Canyon 1 & 2 Evaluation For Tube Vibration Induced Faligue," from public disclosure (ref 10Cf ft2 700(b)(4)) WIESEMANN,R A Westinghouse Electric Corp. 88/12/02 MURLEY,T. Office of Nuclear Reactor Regulation, Director (Post 870411), 10pp. 47869-129-47869-138.

- -8812160029 "Diablo Canyon 1 & 2 Evaluation For Tube Vibration Induced Fatique." CONNORS,H.J., FRICK,T.M., HALL.J.M. Westinghouse Electric Corp. WCAP-12065 88711/30 194pp 47869 139-47869 332
- 8812200230 Forwards request for addit into re-plant long-term selsmic program final rept Response to PRA questions should be submitted by 890115 & response to other Questions by 890130 ROCOLI Project Orectorate V. 88/12/13 SHIFFEH, J.D. Pacific Gas & Electric Co. 14pp. 47868 148-47868.161.
- Q. Inspection reports, IE Bulletins & correspondence
- 8812050200 Forwards SALP MgL Meeting Repts 50-275/88-30 & 50-323/88-28 on
 - BR1020 KIRSCHILD F Region 5, Otc of the Director, 88/11/10, SHIFFER, J.D. Pacific Gas & Electric Co. 2pp. 47731:138-47731.144
- -8812060201 Mgt Maeling Ropts 50-275/88-30 & 50-323/88-28 on 881026. Major areas discussed SALP rept for plant & recent plant events developed since last right meetings hold on 800722 & 0426.

 O'BRIEN, I.P., MENDONCA, M.M. Region 5, Ofc of the Director. 88/11/08. 5pp. 47731:140-47731:144.
- 8811160211_NRC Info Notice 88-090, "Unauthorized Romoval of Industrial Nuclear Gauges" Svc 1st and.
 CUNNINGHAM,R.E. D.vision of Industrial & Medical Nuclear Saloty (Post 870729).
 08/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257.
- 8811160467 NRC Into Notice 88-091, "Improper Administration & Control of Psychologi-ROSSIC E. Division of Operational Events Assessment (Post 870411). 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp 47708.042-47708:142.
- 8812130244 Forwards Insp Hopts 50-275/88-26 & 50-323/88-24 on 880904-1022.No viciations noted Discusses events.

 KIRSCH,D.F. Region 5, Otc of the Director. 88/11/23 SHIFFER,J.D. Pacific Gas & Electric Co. 3pp. 47798:107-47798:128.
- ~8812130245 Insp. Repts 50-275/98-26 & 50-323/88-26 on 880904-1022 No violations or downtons noted Major areas inspected plant operations,maint & surveillance activates,onsite events, open items.LERs & selected independent insp activities. WAGNER,W., JOHNSTON,KE, NARBUT,P.P. Region 5, Ofc of the D-roctor 98/11/22 16pp. 47798.110-47708:128
- 8812010259 Ack receipt of 881005 ftr informing NRC of steps taken to correct violations noted in Insp Repts 50-275/ff8-15 & 50-323/08-14.Response to encl list of questions requested within 30 days.
 KIRSCHIDE. Region 6, Ote of the Director. 88/11/25. SHIFFER,J.D. Pacific Gas & Electric Co. 3pp. 47709.075-47709:144.
- 8012080094 Forwards propriolary WCAP-12084, "Diablo Canyon 1 & 2 Eva'uation for Tube Vibration Induced Fatigue." All five tubes requiring corrective action removed from see during Unit 2 refueling outlage. Rept withheld (ref 10CFR2.790). SHIFFER.J.D Pacific Gas & Electric Co. 89/11/30. Document Control Branch (Document Control Dosk). 2pp. 47736.221-47736-222
- 8811280030 NRC Info Notice 88-093, "Feletherapy Events." Svc list encl. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729): 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88 004, "Potentially Undersized Valve Actuators." Svc list MOSSI,C.E. Division of Operational Events Assossment (Post 870411). 98/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254
- 8812150093 Ack receipt of 881107 ltr informing NRC of stops taken to correct dovi-ations noted in Insip Repts 50-275/88-25 & 50-323/88-23. PATE.R.J. Rogion 5, Old of the Director, 88/12/02. SHIFFER.J.D. Pacific Gas & Elec-tric Co. 1p. 47835-003-47835-007.
- 8812130191 Informs that per 881130 tolcon,agreement reached between NRC & util that required response date to questions contained in NRC 881125 ftr re violations noted in Insp Riopts 50-276788-15 & 50-323788-14, would be 890109.
 SHIFFER,J.D. Pacific Gas & Electric Co. 88/12/05. MENDONCA,M.M. Region 5, Old of the Director. 1p. 47794.130-47794:130.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Liconsees on Vendors," Svc list encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/08. Consolidated Edson Co. of New York, Inc. 112pp. 47807:191-47807:392.
- 8812230121 Forwards safety evaluation accepting first 10-yr interval inservice insp pro-gram plan for pfant Technical Evaluation Repts enci. RCOD.H. Project Directorate V. 88/12/14. SHIFFER,J.D. Pacific Gas & Electric Co 5pp. 47915 221-47916:021.
- --8812230139 SEH accepting plant first 10-yr Interval Inservice Insp program plan.per 10CFH50.55a(g) & Tech Spec 4.0.5.

 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/14, 11pp.
 - 47915:226-47915:236.

- -8710140219 "Technical Evaluation Ropt on First 10-Yr Interval Inservice Insp Program Plan:PG&E, Diable Canyon Power Plan!, Unit 1," Informal rept BROWN,B W. EG&G Idaho, Inc. (subs. of EG&G, Inc.), FIN D-6022, EGG-SD-7619-87/08/31, NRC No Detailed Affiliation Given. 84pp. 47815-237-47915-301.
- -8812230155 SER accepting plant first 10-yr Interval Inservice Insp program plan.por 10CFR50.55a(g) & Tech Spac 4 0.5.

 * Office of Nuclear Reactor Regulation, Director (Post 870411) 08/12/14. 12pp. 47915 302-47915 313
- ~8710140231 "Technical Eva'uation Rept on First 10-Yr Interval Inservice Insp Program Plan PG&E_Diatro Canyon Power Plan,Unit 2," Informat rept. BROWN, BW, MUDLIN,J D E&E of Inc. (subs. of EG&G, Inc.) FIN D-6022 EGG-SD,7620 87/08/31 NRC No Detailed Affiliation Given 68pp 47915:314-47916 021.

R. Periodic operating reports & related correspondence

- 8811290426 "Rept on Dischargo Monitoring at Diablo Canyon Power Plant During Month of Oct 1988" W/981121 ltr. TOWNSENDJD Pacific Gas & Electric Co 88/10/31. 81pp. 47651:118-47651:198.
- 8612190233 Monthly operating repts for Nov 1988 for Diablo Canyon, Units 1 & 2.W/ BEDESEM,P., NOLAN,J., TOWNSEND,J.D. Pacific Gas & Electric Co. 88/11/30 11pp. 47854:127-47854:137.

S. Reportable occurrences, LERs & related correspondence

- 8812050236 LER 88-023-00 on 881102.Inadvertant containment ventilation isolation occurred.Caused by personnel error Rev of Operating Procedure (OP) G-1:II underway to remove excessive source chocks W/881130 Itr. POGUE_R.D., SHIFFER.J.D. Pacific Gas & Electric Co. 88/11/30. 6pp. 47740-237-
 - 47740 242
- 8812160008 LER 88-028-01 on 881014.foreman declared two MSIVs for each unit inoperable due to Inadequate environ qualification of surge suppressors.Caused by personnel arror.Surge suppressors romaved W/881209 ftr. MALONE 47835:123.
- 8812200098 LER 88.027-00.on 881109, surveillance interval of Tech Spoc 4.2.4.1b exceeded Caused by personnel error in that liconsed operators did not reviow stated section of annunciator response procedure Procedure to be reviow W/981212 ltr. GREBELT, SHIFFER, J.D. Pacific Gas & Electric Co. 88/12/12 6pp. 47867:238-47867.243.

T. Hearing transcripts on non-antitrust matters

- 8612210118 Partial rusponse to FCIA request for closed Commission meeting transcripts between Jan 1980 & Dec 1985 re plant App A documents available in PDR App B partially withheld & App C documents completely withheld per Sunshine Act. GRIMSLEY, D.H. Division of Freedom of Information & Publications Services (Post 880515) 88/12/19, SCHMIEGE, P.A. O'Molvony & Myers 7pp. 47874:059-47874:127.
- -8812210120 Partially withheld transcript of 810331 closed Commission meeting in Washington,DC to discuss plant order Pp 1-18.
 * Commissioners, 81/03/31, 13pp. 47874.066-47874.078.
- -8812210122 Partially withheld transcript of 810825 closed Commission briefing in Washington,DC re-ponding adjudicatory proceedings Pp. 1-83.
 * Commissioners. 81/08/25. 16pp. 47874:079-47874:123.
- --8812210128 Parilally withheld transcript of 821021 closed Commission briefing in Washington, DC re-ponding Investigations Pp. 1-71.

 * Commissioners. 82/10/21. 4pp. 47874:124-47874:127.

U. Congressional/Executive Correspondence

- 8811300421 Responds to 881020 ltr to Chairman Zech urging NRC to study util rept reevaluating selsmic design basis for plant. Concludes that plant design seismically adequate.
 STELLO.V. Ofc of the Executive Director for Operations, 88/11/18, BOXER,B. House
 - of Rep. 9pp. 47755:012-47755.021.
- --8811300423 Requests studying of seismology rept which reassesses seismic design basis of facility recently released by PG&E. BOXER,B. House of Rep. 88/10/20. ZECH,L.W. Commissioners. 1p. 47755:021-47755:021.

V. Operator Examinations

8812140046 Forwards revised agenda for annual operator licensing meeting on 980110.W/o enct.

PATE,R.J. Region 5, Oic of the Director. 88/12/05 MARTIN,T. Pacific Gas & Electric.
Co. 2pp. 47800:185-47800.166.

DOCKET 50-278 AGN-201

P. Operating license stage documents & correspondence

8812160053 Responds to eight Issues required to be resolved prior to resumption of reactor operation.per NRC request All unity personnel being treined in new 8/or revised procedures for callor 8 operation of radiation monitors. CRECINE_J.P. Georgia Institute of Technology, Atlanta, GA. 88/11/02. ERNST,M.t. Region 2, Ofc of the Director. 4pp. 47630.348-47630:351.

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8811300342 Forwards Safety Insp. Repts 50 277/89.41 & 50 278/88.41 on 881003-07 No violations noted Steps taken to correct violations noted in NRC 870729 & 1204 MARTIN,T T. Region 1, Ofc of the Director 89/11/14, MCNERL C.A. Philadolphia Electric Co. 2pp. 47671 230-47671:239
- ~8811308346 Insp. Repis 50:277/68:41 8 50:278/89:41 on 681003:07.No violations noted Major areas inspected fire protection/ provenion program XRASOPDULOS A, ANDERSON,C J. Region 1, O'c of the Director 83/11/08 8pp 47671:232-47671:239.
- 8812020152 Forwards Emerger cy Operating Procedure (nsp. Repts 50:277/89:200 & 50:278/88:200 on 880822-0901-Weaknesses noted VARGA, SA Oxid-son oft Reaction Projects 1/13 (Post 870431) 99/11/29 MCNEALLC. Ph. ade ph. a Electric Co. 6pp. 47717-019-47217:062
- -8812020153 Insp Ropt 50:277/88 200 & 50:278/88 200 on 890922.0901 Major areas inspected evaluation of emergency operating procedures program, notucing procedures evaluations & walkflowns, smultipriexercises & training & containment venting ARCHITZEL,RE, KONKLINJE, HAUGH-KEY,CJ Division of Reactor Inspection & Safeguards (Post 870411) 88/10/25, 38pp. 47717.025-47717.062
- 8812020298 Comments on SALP Repis 50.277/87/99 & 50.278/87/98 for June 1987. Jul 1988 Effective 880401, plant security operation began reporting to support manager onsite & friewatch & security persounds no longer shared resource MCNEILL, C.A. Philadelphia Efective Co. 687/11/29 RUSSELL, W.T. Ragion 1, Old of the Director. 3pp. 47721,084-47721 096.
- 6812120033 Forwards request for add: info re wh 880930 intention to compline order, gency operations facilities for plants at single Coatsvite sec bldg facility. Straight and direct 8 driving of stances between plants & Coatsvite's sec bldg foquested BUTLER.W.R. Project Directorate I-2: 88/12/06 HuNGER.G.A. Philadelphia Electric Co. 4pp. 47785:184 47785:187
- 8812230134 Forwards Safety Insp Repts 50-277/89-40 & 50-278/88-40 on 881015-1118 & notice of violation KANE,W.F. Region 1, Oic of the Director 88/12/66 MCNEILL,C.A. Philadelphia Elec-tric Co. 2pp. 47821:282-47921 321.
- -8812230141 Insp. Repts 50-277/08-40 & 50-278/38-40 on 681015-1118 Violations noted Major larges inspected accessible portions of Unit 2 & 3,operational safety, advation protection, physical security, surveillance testing & maint Witt IAMS_JH_LINVILLE_JC. Region 1. Ofc of the Director, 88/12/05, 36pp. 47921:286-47921-321
- 8812120208 Forwards rovs to physical security plan Revs withheld (ref. 16CFR2.790 & 73.21). GALLAGHER,J.W. Philadelphia Electric Co. 88/12/08. RUSSELL,W.T. Region 1, Ofc of the Director. 4pp. 47786-221-47786-224
- 8812210094 Advises that util ready for security program inspit agrining on 881219 or as soon as personnel can be scheduled to visit plant site. SMITH, D.M. Philade phia Electric Co. 89/12/16. Document Control Branch (Document Control Desk). RUSSELL,W.T. NRC No Detailed Affiliation Given. 1p. 47890 361-47990 361-47990 361-47990 361-47990 361-47990 361-47990 361-47990 361-47990 361-47990 361-47990 361-47990 361-47990 361-47990 361-47990 361-47990 361-47990 361-4790 361-47990 361-47990 361-4790 361-4790 361-4790 361-4790 361-4790 361-4790 361-4790 361 4788D.361

G. Adjudicatory correspondence

8812290206 PECO consented to immore for 32-day extension to respond to Commonwealth of PA contentions. Served on 681221 Granted for Board on 881220. Philadelphia Election Co. 7468 7734, 88/12/20, Atomic Safety and Licensing Board Panel. 1p. 47686.095-47886.095.

H. General correspondence

- 8812080048 Informs that Commissioners will be unable to attend 981116 hearing re-plant restart per 881026 request ZECH.L.W. Commissioners. 98/11/10. BELL.C.D. Pennsylvania, Commismwallth of 1p. 47753:111.47753.116.
- -8812080049 Requests Commission attendance at 681116 hearing on Sanate Resolution 218 in Harrisburg PA 85LLC.D. Pennsylvan.a, Commonwealth of 86/10/26 ZECH,L. Commissioners 5pp. 47755:112-47753:116

P. Operating license stage documents & correspondence

- 8811300550 Documents substance of 881116 discussion following Pennsylvania Senate Committee hearing Discussed possible motifieds available to incorporate into NRC requirements contemptated agreement between Commonwealth & util AUSSELL,W.T. Region 1, Olic of the Director, 88/11/22 SEARCHINGER,T. Pennsylvania, Commonwealth of 3pp. 47701 314-47701.316.
- 8812010180 Forwards Amend 139 to Licenso DPR-44 & safety evaluation. Amend re-vises Tech Spec Figures 3.6.1 M & 3.5.1 N to correct errors & revise nomenclature, MARTIN,R.E. Project Ottectorato 1.2. 88/11/22 HUNGER,G.A. Philadelphia Efectric Co. 10pp. 47710.103-47710.120.
- --8812010182 Amend 139 to License DPR-44 rovising Tech Spec Figures 3.5.1 M & 3.5.1.N to correct errors 8 revise nomenclature.
 BUTLER,W.R. Project Directorate 1-2, 88/11/22, 5pp. 47710.113-47710.117.
- 8812010184 Safety evaluation supporting Amend 139 to License DPR-44
 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/22 3pp. 47710:118-47710:120.
- 8611280048 Goneric Ltr 88-20 to all licensess holding Ots & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list
 - enci. CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23, Consolidated Edison Co. of New York, Inc. 81pp. 47728/303-47728/024.

- 8811280350 Responds to Generic Lir 88-11, "NRC Position on Radiobort Embiritor of Reactor Vessel Matts & Impact on Plant Operations." Submittal dates for fee Speciamends & results of fracture toughnoss analyses for plants stated GALLAGHER, J.W. Prayactoph & Electro Co. 88/11/23, MURLEY, 1, Chillio d Nukly Reactor Regulation, Director (Post 870411), 3pp. 47665, 276, 47655, 322.
- #8811290355 Rev 1 to "7mpact of Reg Guide 1.99,Rev 2 on Pearth Bellow Allow Power Station Unit 3." CANNET A., PAPANDREA.C.J., BANGANATH.S. General Electric Co. SASN 65 to R01, 89/10/31, 19pp. 47665 279.47665 29
- -8811290357 Rev 1 to "Impact of Reg Guido 1.99,Rev 2 on Limetick Generally 51 PAPANDREA,C.J., CAINE,T.A. RANGANATH,S. Gunural Elucino Co. Saist et el R01 88/10/31 25cp. 47685 298 47665 322
- 8811300322 Forwards safely evaluation for Topical Rept PECO FMS 0034. "Netroble for Performing BWR Sys. Transient Analysis." NRC approval limited to use the riches from of compolence to use RETHAN computer code for facility MARTIN,R.E. Project Directorate 1-2, 88/11/23. HUNGER,G.A. Priradirphi Exception 30, pp. 47677.106-47877.123.
- -8611300325 Topical rept evaluation of PECO-FMS-0004, "Methods for Pedativing BWR Sys Transfert Analysis." Rept approved but Irmited to util compositione to use PETRAN computer code for facility. Office of Nuclear Reactor Regulation, Director (Post 870411) UN/11/23 315
- --981115D355 "Technical Evaluation PECO Topical Rept PECO-RMS-G04 Methods for Performing BWR Sys Transfert Analysis, Peach Bottom Atomic Power Station (July 12 6.5. International Technical Services, Inc. ITS/NRC/88-9-88/10/31, NRC - No Datates Affiliation Given, 12pp 47677;112-47677,123.
- 8812020217 Responds to 881007 lit re OA program description changus for thing 2.6.3 updated FSAR Rev 6 Response incorporates into exchanged at 881102 minuting HELWIG,DiR. Privadolphia Efectic Co. 68711/28 MARTIN,R E. Project Directifials 2, 12pp. 47707 208-47707 219.
- 8812010279 Requests that Amend 139 issued to License DPR-44 be changed 5 Amend 136 Due to administrative error incorrect amend number was assigned. MARTIN,R.E. Project Directorate 1/2 88/11/30 HUNGER,G.A. Philadelphia Electric Co. 2p. 47707.097-47707:098.
- 8812050283 Responds to appeal of dorial of FOIA requist for documents. Fers. 31 portions of Eisassor 880505 memo.Marcus 871222 memo withheld (ref. FOIA Frame) tion 5).
 CHILK,S.J. Office of the Societary of the Commission, 88/11/30, RHODES,J. Per-sylvania, Commonwealth of 2pp. 47729,188,47729,201.
- -8612050288 Trip ropt of Commissioner Carr & T Elsassor 8/1215 site visit to et & 871216 attendance at Region 1 periodic regional resident counterpart modificing ELSASSERT, NRC No Detailed Afficient Given, 88/01/05, NRC No Detailed Afficient Given, 3pp. 47728-199-47729 201.
- 8812080052 Forwards proprietary EDE-38-0988, "Source Range Monitor Count Rate vs. S/N Ratio for Peach Bottom Units 2 & 3" & EDE-44-1088, "Source Range Monitor in support of 891021 application Affidavitienci Repts withhold (ref. 10CFR2 790) HUNGER,G. A. Philadelphia Efector Co. 88/11/30 MARTIN,R.E. Project Directoral 2, 5pp. 47743-001.

Q. Inspection reports, IE Bulletins & correspondence

47677:103-47677:111

- 8811210050 Rev 0 to "Peach Bottom Atomic Power Station Unit 2 PRA-Based Sys Irsp Tielli USHER, J., MACDOUGALL, E. Brookhaven Notional Laboratory, FIN A.3453 A.3684-2 R00, 88/04/30, NRC - No Detailed Affiliation Given 101pp 47599,049,47593 148
- 8811300342 Forwards Safety Insp. Hepts 50:277/88-41 & 50:278/88-41 on 86103 07.No violations noted Steps taken to correct violations noted in NRC 970729 & 1214 fits verified.

 MARTIN,T.T. Region 1, Oto of the Director, 88/11/14, MCNEILL,C.A. Philade.pha Electric Co. 2pp. 47671:230-47671,239.
- ~8811300346 Insp. Repts 50:277/88-41 & 50:278/88-41 on 881003.07.No victations noted. Major areas inspected fire protection/ prevention program. KRASOPOULOS, A., ANDERSON, C.J. Region 1, Otc. of the Director. 88/11/69 889 47671 232-47671 239
- 8811300106 Advisos of three issues of current regulatory significance, including nearlie announcing presence of NRC inspector at nuclear power plant revite NRC enforcement policy & proposed enforcement actions religious inattentivenues et plant STELLOY, O'to of the Executive Director for Operations, 88/11/17. Philadelphia Electing Co. 35pp. 47709,020-47709.068.
- 8611290563 Forwards Environ Qualification Insp Repts 50-277/88-38 & 50-278/89-35 on 880926-30 & notice of violation
 MARTIN,T.T. Region 1, Old of the Director, 88/11/21, MCNEILL,C.A. Philadelphil
 Electric Co. 2pp. 47650:197-47650 203.
- --8811290565 Notice of violation from Insp on 880926:30.Violation noted, wito compliance Limitorque valve actuator housings not grounded & qualification of Reyonal splices. Idoal wird rust Amp but splices not established.

 * Region 1, Ofc of the Director. 88/11/21. 2pp. 47650:199.47650:200.
- --881129667 Insp. Repts 50:277/86:38 & 50:278/88:38 on 880926:30 Violators noted Major areas inspected liconsee corrective actions for previous anviron qualification (EQ) findings & licensee EQ documentation re-cable splices qualificability. CHEUNGL., ANDERSON.C.J. Region 1, Otc of the Director, 88/11/01, 9pp. 47650:201-47650:209.
- 8811160211 NRC Info Notice 88-800, "Unauthorized Removal of Industrial Nuclear Gauges." Svc fist enct. CUNNINGHAMR E. Division of Industrial & Medical Nuclear Safety (Post 670725) 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.

- 8811160467 NRC Info Notice 88 091, "Improper Administration & Control of Psychologi-
 - ROSSI,CE Division of Operational Events Assessment (Post 870411) 88/11/22 Cansolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708 142.
- 8811300310 Informs that NRC awaits rescription of long-term resolution actions in response to NRC Bulletin 88-004, "Potential Safety-Related Pump Loss." Discription due within 30 days of completion of actions MAHTIN, HE Project Directorate 1-2 88/11/23. HUNGER,G A. Philadulphia Electric Co. 4pp. 47677:128-47677:131.
- 8812010186 Ferwards V Stello 881117 fit to all util executives to projected of NRC inspector at plants review to enforcement policy & proposed enforcement actions for operater institutiveness at Poach Bottom BLACK,SC Ofc of Special Projects 88/11/23 KINGSLEY,O.D. Tennessoo Valley Author.y. 3pp. 47709.258-47709.309
- -88120 10188 Advisos of new rules re-announcing presence of NRC inspector of power plant, rev to NRC enforcement policy effective on 881014 & proposed enforcement action for operators at plant.
 STELLO,V Orc. of the Executive Director for Operations, 88/11/17. Philadelphia Electure Co. 35pp. 47/09.261-47/09.309.
- 8612020152 Forwards Emergency Operating Procedure Insp Ropts 50:277/86:200 & 50:278/86:200 on 860822:0901.Weaknessos noted VARGA.SA Division of Reactor Projects I/III (Post 870411) 88/11/29 MCNEILL.C Philadorphia Electric Co. 6pp. 47717-019:47717-062
- -8812020153 Insp. Ropt 50:277/88-200 & 50:278/88-200 on 880822:0901 Major greas inspected evaluation of emergency operating procedures program, including procedures evaluations & walkdowns, simulator exercises & training & confaminant venting ARCHITZELRE, KONKLIN.J.E., HAUGHNEY.C.J. D. welcon of Reactor Inspection & Safeguards (Post 8704+1), 88/10/25 38pp. 4/717.025-47717.062.
- 8812020298 Commonts on SALP Floris 50-277/87-99 & 50-278/87-99 for June 1987 Jul 1988 Effective 880401, plant security opuration began reporting to support manager onsite & linewatch & security personnel no longur shared resource. MCNETL, CA. Philadelphia Efectic Co. 887/11/29. RUSSELL, W.T. Region 1, Okc. of the Director. 3pp. 47721-084-47721-086.
- 8611290030 NRC Info Notice 88:003, "Toluthorapy Events." Svc list encl. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02, Consolidated Edison Co. of New York, Inc. 112pp. 47811 103:47811 215
- 8611290538 NRC Info Notice 88:004, "Potentially Uniforsized Valva Actuators." Svc list enci ROSSI,C E. Division of Operational Events Assessment (Post 870411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 4/708 143-47708 254
- 88 12130084 Responds to NRC 881108 ltr re violations noted in Insp Hepts 50 2777/88 32 & 50 278/88 32 SMITH, D.M. Philadelphia Electric Co. 88/12/06 MARTIN, T.T. Region 1, Ole of the Decelor, 7pp. 47791:351-47791:357.
- 8812230134 Forwards Safety Insp Ropts 50:277/88:40 & 50:278/88:40 on 881015
- 1118 & notice of violation.
 ICANE,W.F. Hegion 1, Otc of the Director, 88/12/06 MCNEILL,C.A. Phradelphia Electric Co. 2pp. 47921-282-47921:321.
- -8812230140 Notice of violation from insp. on 881015-1118 Violations noted licensite failed to establish requirements to compare lost dosmatry rept & audit results of their moluminascent destinators before shipment to contractor.

 * Region 1, Ofc of the Director. 88/12/06. 2pp. 47921.284-47921.285.
- --8812230141 Insp. Repts 50:277/88-40 & 50:278/88-40 on 881015-1118 Violations noted Major areas Inspected accessible portions of Unit 2 & 3 operational satisty, addition protection, physical security, surveillance testing & maint WILLEAMS_J.H., LINVILLE_J.C. Region 1, Ofc of the Director. 88/12/05 38pp 47021:286-47921:321.
- 8812020287 NRC Into Notice 88 095, "Inadequate Procurement Requiremental Imposed by Licensees on Vondors" Svc list encl. HOSS1,C.E. Division of Operational Events Assessment (Post 6704+1). 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812130125 Responds to NRC 881101 litr re-violations noted in Insp Ropts 50:277788-34 & 50:278788-34 Administrative procedure for performing temporary procedure revised in Sept to facilitate process & training provided SMITH_OM_Philadelphia Electric Co. 88/12/09. KANC,W.F. Region 1, Otc of the Director. 5pp. 47794:068-47794.072.
- 8812210320 Forwards response to NRC 881021 fir re-concerns noted in Safety Insp. Repts 50-277/88-28 & 50-278/88-28 Administrative procedures new provide addiguidance on steps to take upon discovery of procedure discrepancies. SMITH, D. Philadelphila Electric Co. 88/12/13, MARTIN, T. Document Control Branch (Document Control Desk), 3pp. 47875:350-47875:352.
- 8812290126 Requests that liconsoc provide NRC w/current schodule, including dates & topics for self-assessment activities KANE,W.F. Region 1, Olc of the Director. 88/12/15. MCNEILL,C A Philadelphile Electric Co. 2pp. 47946:292-47946:293
- 8812210094 Advisos that util roady for socurity program linsp heginning on 881219 or as soon as personnel can be scheduled to visit plant site SMITH_OM. Philadelphile Electric Co. 881/12/16. Document Control Branch (Document Control Desk). RUSSELL,W.T. NRC No Detailed Affiliation Given, 1p. 47880/361-3780/361

A. Periodic operating reports & related correspondence

- 8811300193 Summary of Operating Reactor Events Meeting 88-46 on 881122. LANNING.W.D. Events Assessment Branch. 88/11/25. ROSSI.C E. Division of Operational Events Assessment (Post 870411). 11pp. 47880-201-47880-211.
- 8812090151 Forwards plant status rept for 881107-28.

 LINVILLE,J.C. Region 1, Otc of the Director. 88/11/30. KANE,W.F. Region 1, Otc of the Director. 8pp. 47786:327-47786.331.

S. Reportable occurrences, LERs & related correspondence

- 8811300462 NPDES noncompliance notification on 881017 pH samples from discharge Point 301 incheded injuries noncompanies indication on 881017,pH samples from discharge Point 301 inxideded injurity point for Caused by Palkings of sump discharge valves Action taken to neutralize setting basin w/addition of act. SMITH,D M. Philaderisa Electric Co. 88/11/22 Ponnsylvania, Commanwealth of 2pp. 47576 (42)-47676 (43).
- 8812010144 LER 88-026-00 on 881029 primary containment isolation resulted from undervoltago tr.p. of reactor protection sys Channel A due to sonsitive rhoostal Caused by craftsman inadvetentity laring may voltage control rhoostal W/881128 ltr. CRIBBETTE SMITH (D.M. Philadelphia Electric Co. 88/11/28 4pp. 47703 277-
- 8812010157 LEH 89-025-00 on 881027.Group II primary containment isolation sys actu-ation result of from personnel error to tripping of breaker Causert by inartvertently grounding "B" phase of turbe phase circuit breaker W-981128 III. CRIGRET E., SMITLID M. Phaladelphia Efectine Co. 88/11/28. 8pp. 47703-205-47703 210
- 8812020225 Addresses delayed submittal of util event repts, required by plant Toch Specs & 10CFR50 73 tata repts include LERs 2-88 07,08,12,17 & 18 GALLAGHERJ W. Phrade/pha Electric Co. 88/11/28 KANE,W.F. Region 1, Otc of the Director 3pp 47711 032-47/11 034
- 8812120247 LER 88.028.03.on 881104.LPCI mode of RHR sys actuated which resulted in starting of PHR pumps A. 8. C. 8 addition of 6,000 gallons to reactor voscel from tonis Caused by personnel error. Surveillance teets reviewed & reviewed W/881205 ftr. CHINHELT E., SMITH, D.M. Pyfarleiphia. Electric Co. 88/12/05 Spp. 47797.349. 47797 353.
- 8812150276 LER 88 029-00 on 881110-16 conditions found that resulted in plant being cutside dustyn basis for internal flood protection of ECCS compartments deused by inadequate seeling of ECCS pump rooms Walls being seeled W/H81212 ltr CRIBBETE SMITH,DM Philadriphia Electric Co R8/12/12 5pp 4/830.138-
- 8812200121 LER 88-021-01 on 880013 primary containment isolation sys Group II isolaflon occurred due to momentary toss of power to sys logic Caused by personnel error.tsolation resot & personnel counseled W/891214 ltr. CRIBBE,T.E., SMITH,D.M. Philadelphia Electric Co. 69/12/14 Gpp. 47864 264-47864:269

V. Operator Examinations

8811300108 Advises of three visues of current regulatory significance, including new rule announcing presence of NRC inspector at nuclear power plant, revito NRC enforcement policy & proposed enforcement actions re-operator inattentiveness at plant. STELLOY. Offic of the Executive Director for Operations. 88/11/17. Philadelphia Electric Co. 35pp. 47709 020-47709 068

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8811300342 Forwards Safety Insp Repts 50-277708-41 & 50-278788-41 on 881003-07.No violations noted Steps taken to correct violations noted in NRC 870729 & 1204 MARTIN,T.T. Region 1, Old of the Director, 88/11/14 MCNEILL,C.A. Philadelphia Electric Co. 2pp. 47671 230-47671.239
- -8811300346 Insp Repts 50 277/88-41 & 50-276/88-41 on 881003-07 No violations noted Major großs inspected fre protection/ prevention program.
 KRASOPOULOS,A. Region 1, Ofc of the Director. 88/11/08 8pp. 47671.232-
- 8812020152 Forwards Energrincy Operating Procedure Insp. Repts 50:277/88-200 & 50:278/89:200 on 880822-0001.Washnossus noted VARGA, SA Division of Reactor Projects I/III (Post 870411) 88/11/29. MCNEILL,C Philadelphia Electric Co. 6pp. 47717:010-47717:062.
- -8812020153 Insp Rept 50-277/88-200 & 50-278/88-200 on 880822-0901 Major areas inspected evaluation of emergency operating procedures program. Including procedures evaluations & walkdowns, simulator exercises & treining & containment venting ARCHITZEL, R.E. Division of Reactor Inspection & Safeguards (Post 870411), 68/10/ 25 38pp 47717.025-47717.062
- 8612020298 Commonts on SALP Hapts 50:277/87-99 & 50:278/87-99 for June 1987 Jul 1988 Effective 860:401, plant security operation began reporting to support manager onesite & firewatch & security personnel no longer shared resource MCNELL, CA. Philadelphia Electric Ca. 88/11/29. RUSSELL,W.T. Region 1, Otc of the Director. 3pp. 47721:084-47721.086
- 8812120033 Forwards request for additinto re util 880930 intention to combine emerpurtuent of the project Directors of the State of Hunger of the Project Directors of the Puritue Co 4pp. 47785 184-47785 187
- 8812230134 Forwards Salety Insp Repts 50:277/88-40 & 50:278/88-40 on 881015-1118 & notice of violation KANE,W.F. Region 1, Otc of the Director, 88/12/06. MCNEILL,C.A. Philadelphia Elec-tric Co. 2pp. 47921:282-47921:321.
- --8812230141 Insp. Repts 50:277/88:40 & 50:278/88:40 on 881015-1118. Violations noted Mejor areas. Inspected accessible portions of Unit 2 & 3.oporetional safety, radiation protection, physical security, surveillance testing & maint. WILLIAMS_IH Regen 1, Otc. of the Director. 88/12/05, 36pp. 47821:286-47921.321.
- 8812120206 Forwards revs to physical security plan. Revs withheld (ref. 10CFR2.790 & 73.21)
 GALLAGHER,J.W. Philadelphia Electric Co. 88/12/08. RUSSELL,W.T. Region 1, Old of the Director. 4pp. 47786 221-47786 224

48 DOCKETED ITEMS

8812210094 Artrises that chliready for security program inspibaginning on 681219 or as soon as personnel can be scheduled to visit plant site. SMITH, DM. Philadelphia Election Co. 88/12/16. Document Control Branch (Document Control Desk). 1p. 47830-361-47890-361.

G. Adjudicatory correspondence

8812280208 PECO consented to motion for 32-day extension to respond to Commonwealth of PA contentions.* Served on 881221 Granted for Board on 881220.

Philadelphia Electric Co. #488 7734 88/12/20 Atomic Salety and Licensing Board Panel. 1p. 47686 095 47885 095

H. General correspondence

- 8812080048 Informs that Commissioners will be unable to attend 831116 hearing re plant restart,per 881026 request ZECHLW. Commissioners 88/11/10. BELL,C D. Pennsylvania, Commonwealth of 1p. 47753/111-47753:116
- -8812080049 Roquests Commission attendance at 881116 hearing on Senato Resolution 218 in Hamsburg,PA, BELL,C.D. Pennsylvania, Commonwealth of 88/10/26 ZECH,L. Commissioners Spp. 47753 112 47753 116.

P. Operating license stage documents & correspondence

- 8811300569 Documents substance of 881116 discussion following Pennsylvania Senate Committee hearing Discussed possible methods available to incorporate into NRC requirements contemplated agreement between Commonwealth & util RUSSELL.W.T. Region 1, Oic of the Disector, 89/11/22 SEARCHINGER,T. Pennsylvania, Commonwealth of 3pp. 47701;314-47701.316.
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facinies re individual plant exam for severe accreent vulnerabilities Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024
- 8811290350 Responds to Generic Ltr 88-11, "NRC Position on Rediation Embrittiement of Reactor Vessel Matis & Impact on Plant Operation on Rediction Embrittement Specialments & Impact on Plant Operations "Submittal dates for Tech Specialments & results of tracture loughness analyses for plants stated. GALLAGHER, J.W. Philadelphia Electric Co. 88/11/23 MURLEY.T. Office of Nuclear Reactor Regulation, Director (Post 870411), 3pp. 47665.276.47665.322.
- --8811290355 Rev 1 to "Impact of Reg Guido 1.99,Rev 2 on Peach Bottom Alon" of Power Station Unit 3."

 CAINE,T A., PAPANDRIEA,C.J., RANGANATH,S. General Electric Co. SASR 88-84 R01 88/10/31, 19pp. 47685:279-47665:297.
- 6811300322 Forwards safety evaluation for Topical Rept PECO FMS 0004, "Methods for Performing BWR Sys Translant Analysis" NRC approval limited to util demonstration of competence to use RETRAN computer code for facility. MARTIN,R.E. Project Directorale I-2, 88/11/23, HUNGER,G.A. Philadelphia Electric Co. 3pp. 47677:106-47677:123.
- --8611300325 Topical rept evaluation of PECO-FMS 0004, "Methods for Performing BWR Sys Transient Analysis," Rept approved but him ted to util competence to use RETRAN computer code for facility.

 **Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/23, 3pp 47677:109-47677:111,
- --8611150355 "Technical Evaluation.PECO Topical Rept PECO.RMS 004 "Methods for Performing BWR Sys Transient Analysis,Peach Bottom Atomic Power Station.Units 2 2.3.""
- \$ 3." International Technical Services, Inc. ITS/NRC/88-9, 88/10/31 NRC No Detailed Affiliation Given 12pp 47677:112-47677:123.
- 8812020217 Responds to 881007 ltr re QA program description changes for Units 2 & 3 updated FSAR Rev 8 Response incorporates into exchanged at 881102 meeting. HELWIG,DR. Philaderphia Electric Co. 88/11/28 MARTINIRE Project Directorate J-2, 12pp. 47707:208-47707:219.
- 8812050283 Responds to appeal of denial of FOIA request for documents. Forwards portions of Elsasser 880505 many March 2012 memo withhold (ref FOIA Exemption 51)

in 88/11/30, RHODES,J Penn-

Linassor 871215 site visit to util & isident counterpart meeting.

'8/01/05, NRC - No Detailed Affiri-

> for Count Rate vs Range Monitor...; CFR2.790). ulect Directorate I-

8/89-41 on 861003-IRC 870729 & 1204

.. C.A. Philadelphia

3-07.No violations

₩ ₩49ctor, 88/11/08, 800

- 8811300 f08. Advises of three issues of content regulatory significance in a large sea rule announcing presence of NRC inspector at nuclear power plant toy to fulfill colorcement power pant toy to fulfill colorcement power by a preposed enforcement actions to operator inattent roads at first STELLOV Offic of the Executive Director for Operations 88711717. Planticiphia Excitor Co. 35pp. 47709-020-47709-068.
- 8811290563 Forwards Environ Qualification Insp. Repts 50 277788 38 8 50 278783 39 on 860926-30 & rotice of violation
 MARTINITY Region 1, City of the Oriector 88/11/21 MCNEILL.C.A. Physik...)
 Electric Co. 2pp. 47650-197-47650 209
- #8811290565 Notice of violation from inspice 880926-39 Violation noted with carresting to function value actuality housings not grounded & qualification of Paydich spices, Ideal wire rule Amp built spices not ostablished:

 * Region 1, Oto of the Director, 68/11/21, 2pp. 47650-199-47650-200
- ~8811290567 Insp. Repts. 50-277/88-39 & 50-278/88-38 on 880926-30 Violators noted Major areas inspected Lensee corrective actions for gravious environ quality ton (EQ) findings & licensee EQ recumentation relicable splices qualificativity CHEUNGL. ANDERSON.CJ. Region 1, Ofc. of the Overtor 88/11/01 Sip. 47650-301 47650-301 47650 201-47650 209
- 8811160211 NRC Info Notice 88-090, "Unauthorized Flemoval of Industrial Nation Gauges "Svc list end: CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safuty (Post 67075), 88/11/22, Consolidated Edison Co. of New York, Inc. 09pp. 47708 255 47700 257
- 8811160467 NRC Info Notco 86-091, "Improper Administration & Control of Psychological Psychological Research (NRC Info Notco 86-091), "Improper Administration & Control of Psychological Research (NRC Info Notco 86-091), "Improper Administration & Control of Psychological Research (NRC Info Notco 86-091), "Improper Administration & Control of Psychological Research (NRC Info Notco 86-091), "Improper Administration & Control of Psychological Research (NRC Info Notco 86-091), "Improper Administration & Control of Psychological Research (NRC Info Notco 86-091), "Improper Administration & Control of Psychological Research (NRC Info Notco 86-091), "Improper Administration & Control of Psychological Research (NRC Info Notco 86-091), "Improper Administration & Control of Psychological Research (NRC Info Notco 86-091), "Improper Administration & Control of Research (NRC Info Notco 86-091), "Improper Administration & Control of Research (NRC Info Notco 86-091), "Improper Administration & Control of Research (NRC Info Notco 86-091), "Info Notco 86-091), Consoldated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142
- 8811300310 Informs that NRC awaits description of long-term resolution actions and appoints to NRC Bulletin 88 004, "Potential Safety Related Pump Loss." Description due within 30 days of completion of actions, MARTIN,RE Project Directorate F2 88711/23 HUNGER,G.A. Pindadorphia Etitle Co. 4pp. 47677.128-47677.131.
- 8812010186 Forwards V Stello 881117 lin to all little executives re-presence of MRC / spector at plants, roy to enforcement policy & proposed enforcement actions for cyclator inattentizaness at Peach Bottom BLACK, C. Otc of Special Projects 88/11/23 KINGSLEY, O.D. Tonnosseo Va cr Authority. 3pp. 47708 258-47709 339
- -8812010188 Advises of new rules relarrouncing presurce of NRC inspiritor all power planties to NRC enforcement policy offective on 881014 & proposed enforcement action for operators at plann STELLO,V. Otc of the Executive Director for Operations 88/11/17. Philadelphia f. et Inc Co. 35pp. 47709:261-47709:309
- 8812020152 Forwards Emergency Operating Procedure Insp. Repts. 50-277789 200 \$
 50-278788-200 on 860822-0901 Wooknosses noted.
 VARGA,S.A. D.vision of Reactor Projects 178 (Post 870411). 88711729. MCNUILL C
 Philadelphia Electric Co. 6pp. 47717-019-47717-062.
- -8812020163 Insp Rept 50-277788-200 & 50-278788-200 on 880822-0901 Motor areas date valuation of emorgency operating procedures programinationally Procedures available of emorgency operating procedures programinationally Procedures availables & walkdowns, a milator exercises & training & containment views, ARCHITZEL, R.E., KONKLIN, J.E., HAUGHNEY, C.J. Driston of Reactor Inspect of & Saleguards (Post 870411) 88/10/25, 38pp. 47717-025-47717.062.
- 8812020298 Comments on SALP Repts 50:277/87-99 & 50:278/87-99 for June 1657-Jul 1998 Effective 880401 plant security operation bugan reporting to support intenes et onsite & frewatch & security personnel no longer shared resource MCNEILL, G.A. Philadelphia Effectic Co. 88/11/29 RUSSELL, W.T. Roylon 1, O'c of the Director, 3pp. 47721:084-47721:086.
- 8811290030 NRC Info Notice 88:093, "Teletherapy Events." Svc list encl CUNNINGHAM.R.E. Division of Industrial & Maclical Nuclear Safety (Post 670/28) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47611.103-4/811:215
- 6811290536 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Svc list ROSSI,C E. Dwiston of Operational Events Assessment (Post 870411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708-254.
- 8812130084 Responds to NRC 881108 fit re-violations noted in Insp Repts 50 277/58-32 & 50-278/88-32. SMITH, D.M. Philadelphia Electric Co. 89/12/06. MARTIN, T.T. Region 1, Oic of the Dr rector 7pp 47791:351-47791.357
- 8812230134 Forwards Safety Insp Ropts 50 277/88 40 & 50 278/88 40 on 881015 1118 & notice of violation.

 KANE,W.F. Region 1, Old of the Director, 88/12/06 MCNEILL,C.A. Philadelphia Electric Co. 2pp. 47921:282-47921:321.
- --8812230140 Notice of violation from inspiron 881015-1118. Violations noted ("censed failed to establish requirements to compare lost dosimetry rept & audit results of their moluminescent dosimeters before shipment to contractor." Region 1, Old of the Circular, 88/12/98, 2pp. 47921:284-47921;285.
- --8812230141 Inso Repts 50-277/68-40 & 50-278/88-40 on 881015-1118. Violations noted Major areas inspected accessible portions of Unit 2 & 3.operational safety-radiation protection, physical security surveillance tosting & maint. WILLIAMS.J.H., LINVILLE.J.C. Region 1, Otc of the Director. 887/12/05 36pp 47921:286-47921:321.
- 88 12020287 NRC Into Notice 88 095, "Inadequate Procurement Requirements In:posed by Licensees on Vendors" Svc I'st encl ROSSICE Division of Operational Events Assessment (Post 870411), 88/12/08. Consolidated Edison Co. of New York, Inc. F12pp 47607.191-47807.302.
- 8812130125 Responds to NRC 881101 ltr re violations noted in thisp Repts 50:277/68-34 & 50:278/88-34 Administrative procedure for performing temporary procedure ravs revised in Sept to facilitate process & training provided.

 SMITH.D.M. Philadelphip Electric Co. 88/12/09. KANE,W.F. Region 1, Ofc of the Director. 5pp. 47794 068-47794:072.

- 8812216320 Forwards response to NRC 881021 fit re-concerns noted in Safety Insp. Repts 50 277/68-28 & 50-278/68-28 Attrinistrative procedures now provide additional dance on steps to take upon discovery of procedure discinepancies. SMITH, C. Philadelph & Electric Co. 88/12/13, MARTIN, L.T. Document Control Branch (Document Control Dosk). 3pp. 47875-350-47875-352.
- 8812210094 Advisos that ut1 ready for security program insp beginning on 801219 or as soon as personnel can be scheduled to visit plant site.

 SMITH_D M. Philadrighta Electric Co. 88712/16. Document Control Branch (Document Control Branch (Document Control Desk). RUSSELL,W.T. NRC No Datailed Affiliation Given. 1p. 47880.361-47883.361.

R. Periodic operating reports & related correspondence

- 8811300193 Suntmary of Operating Reactor Events Modling 88-46 on 881122 LAPINING.WID Events Assessment Branch 88/11/25 ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 11pp 47680 201-47680 211.
- **0812090151** Forwards plant status rept for 881107-28. LINVILLE_J.C. Region 1, Oic of the Director 88/11/30, KANE,W.F. Region 1, Oic of the Director 5pp. 47786-327-47786-331.

S. Reportable occurrences, LERs & related correspondence

- 8811300462 NPDES noncompliance notification on 881017.pH samples from discharge Point 301 exceeded monthly permit limit Caused by leakage of sump discharge valves Action taken to neutralize setting basin w/addition of acid SMITH_DIM Philadelphia Electric Co. 88/11/22 Pennsylvania, Commonwealth of 2pp 47576.042-47076.043.
- 8812020225 Addrossos delayed submittal of util event ropts,required by plant Tech Specs & 10CFR50 73 tate repts include LERs 2-88-07,08,12.17 & 19 GALLAGHERJ, W. Philadelphia Efectic Co. 88/11/28, KANE,W.F. Region 1, Otc of the Director 3pp. 47711.032-47711:034.

V. Operator Examinations

8811300106 Advises of three issues of current regulatory significance, including new rule announcing presence of NRC inspector at nuclear power plant, roy to NRC unforcement pokey & proposed enforcement actions re-operator inattentiveness at plant. STELLOY Otcidition Executive Director for Operations 88/11/17, Philadelphia Electric Co. 35pp. 47709.020-47709:058.

DOCKET 50-280 SURRY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811300394 Informs of 800216 emergency exercise to be conducted to demanstrate capability of assessing radiological conditions & determine protective actions necessary to ensure public health & safety CARTWRIGHT.W.R. Virginia Power (Virginia Electric & Power Co.). 88/11/17. ERNST.M.L. Region 2, Ofc of the Director. 3pp. 47705:024-47705:026
- 8812080181 Forwards Insp Repte 50-280/88-42 & 50-281/88-42 on 881011-14 & notice of violation

DECKER, T.A. Region 2, Oto of the Director, 88/11/29, CARTWRIGHT, W.R. Virginia Power (Virginia Efectric & Power Co.), 2pp. 47783:254-47783:268.

- --8812080182 Notice of violation from Insp on 881011-14. Violation noted, requirement to follow radiation control procedures not mot in that people sighted exiting site through alarming portal monitors w/o being stopped by security personnel. DECKER, T.R. Region 2, Otc of the Director. 88/41/29, 2pp. 47783:256-47783:267.
- 8812190244 Advises that 881001 revito corporate emergency plans mosts requirements of 10CFR50 47(b) & App E & acceptable.

 DECKERT.T.R. Region 2, Otc of the Director. 88/12/05. CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co). 1p. 47851:270-47851:270.
- 8812190282 Forwards Insp Repts 50:280/88-43 & 50:281/08-43 on 881031- 1102.No violations or deviations noted Scope & objectives for 890301 omergency exercise requested.
 - quissed.

 GOLLINS,D.M. Region 2, Ofc of the Director. 88/12/07. CARTWRIGHT,W.R. Virginia

 Power (Virginia Electric & Power Co.): 2pp. 47855:107-47855:124.
- --8812190263 Insp. Repts 50:280/88:43 & 50:281/88:43 on 881031-1102. No violations or deviations noted Major areas inspected annual emergency preparedness exercise & associated critique & followup on open Items. SARTOR, M.M., RANKIN, W.H., Region 2, Old of the Director. 88/12/05. 16pp. 47855.109-47855.124.
- 8B12130068 Forwards Rov 13 to nuclear security personnel training & quelification program Rov withheld (rot 10CFR73.21). CARTWRIGHT,W.R. Virginla Power (Virgina Electric & Power Co.). 88/12/08. Document Control Branch (Document Control Desk). 1p. 47794:089-47794:089.
- 88 12 130071 Forwards Rev 13 to ISFSI nuclear security personnel training & qualification program Rev withheld (rof 10CFR73.21).

 CARTWRIGHT,W.R. Virgin's Power (Virginia Electric & Power Co.). 88/12/08. (Jocument Control Branch (Document Control Desk). 1p. 47792:128-47792:128.
- 8812130081 Forwards replacement transmittal cover firs for 880914 Rev 13 to personnel training & qualification program & plant ISFSI nuclear personnel training & qualification program.W/o encl.
 CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.): 88/12/08. Document Control Branch (Document Control Desk). 1p. 47794:088:47794;088.

- P. Operating license stage documents & correspondence
- 8811300374 "Surry Power Station Un: 1 Reactor Containment Bidg Integrated Leakage Hate Test Types A, B & C Ponodic Test June 1988." W/881123 ltr. CARTWRIGHT,W R. Virgin'a Power (Virgin'a Electric & Power Co.). 88/06/30.
- 8911230397 Forwards summary of radiation protection program upgrade status,per 881031 telcon CARTWHIGHT,WIR Virgicia Power (Virgicia Electric & Power Co.) 88/11/10 ERNST,M Region 2, Otc of the Oirector, 12pp. 47631:275-47631
- 8811280048 Genoric Ltr 88-20 to all licenshos holding OLs & CPs for nuclear power reactor facilities in Individual plant exam for severe accident vulnerabilities Svc list enct.
 CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024
- 8812150135 Forwards "Surry Simulator Certification Submittal"

 CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 88/11/23. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 47821:205-47822
- --8812150137 "Surry Simulator Certification Submittal "

 * Virginia Powor (Virginia Efectric & Power Co.) 88/11/30, 200pp. 47821:206-47822.144
- 8812010263 Notification of 881208 meeting w/util in Rockville,MO to discuss status of control room vantilation childers & mods to & tosting of emergency doset generators. BUCKLEY,B.C. Project Directorate II-2. 88/11/30. BERKOW,H.N. Project Directorate II-2. 3pp. 47703.321-47703.323
- 8812080102 Responds to Generic Ltr 88-11 re embrittlement of reactor vessel belitine mails,por Reg Guide 1.99,Rev 2.Proposed Tech Specs which implement Rev 2 to Reg Guide 1.90 under NRC review CARTWRIGHT.WR Virgina Power (Virgina Electric & Power Co.), 88/11/30 Document Control Branch (Document Control Branch (Document Control Desk), 2pp. 47734:354-47734:355.
- 8812120079 Requests that util address Generic Ltr 88-17 re less at DHR during conpower operation. Ltr Issued due to potentially scrious consequences resulting from madequecy of industry response to Generic Ltr 87-12.

 MURLEY, T.E. Office of Nuclear Reactor Hegulation, Director (Post 870411), 86/12/ 02. FERGUSON, J.H. Virginta Power (Virginia Electric & Power Co.). 3pp. 47789.119-47789-121.
- 8812160081 Advises that BC Buckley assigned as new project manager for plant, offective 881204
 BERICOW H.N. Project Directorate II-2 88/12/13. CARTWHIGHT, W.R. Virginia Power (Virginia Electric & Power Co.). 2pp. 47832,358-47832,359.
- 8612200078 Notification of 661222 meeting w/util in Rockville,MD to discuss into to support restart
 BUCKLEY,B. Project Directorate II-2. 66/12/15. MURLEY,T., SNIEZEK,J., MIRAGLIA,F. NRC - No Dotallod Alfalatori Given. 3pp. 47668-165-47868:167.
- 8812200314 Requests meeting to restart of plant in light of safety- significant design dolicencles,including mislabeled motor- operated Valves MOV 863A & B. ERNST, M.L. Region 2, Otc of the Director, 69/12/15 CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.), 1p. 47864-293-47864:293.
- 8612270232 Forwards "Surry Unit 2 Cycle 9 Core Performance Rept," for Info. CARTWRIGHT,W.R. Virginia Powor (Virginia Electric & Power Co.). 88/12/20. Document Control Branch (Document Control Desk). 2pp. 47926:278-47926:330.
- -8812270243 Rev 0 to "Surry Unit 2.Cycle 9 Core Performance Rept."
 MANN,B.D., FORD,C.A., DZIADOSZ,D. Virginia Power (Virginia Electric & Power Co.).
 859 R00. 86/10/31, 50pp. 47926:280-47926:330.
- 8812270201 Ack receipt of NRC 881121 request for addlinfo re capability of plant svc water sys to perform safety function during hurricane as required by GDC-2-Requested into will be provided by 893403.

 CARTWIGHT, W.R. Virginta Power (Virginia Electric & Power Co.). 88/12/21. Document Control Branch (Document Control Dask). 1p. 47926-021-47926-021.

- 8811210082 "PRA Applications Program for Insp at Surry Nuclear Power Station,Unit 1," draft topt. GREGG,RE., FISHER,J.E. EG&G Idaho, Inc. (subs. of EG&G, Inc.) GREGG,R.E., Idaho National Engineering Laboratory, FIN A-6553, EGG-REC-7746 DRFT, 87/07/ 31. NRC - No Detailed Affiliation Given, 56pp. 47599;288-47599;318.
- 8811290248 Forwards request for addl into re-svc water sys design.per NRC evaluation of svc water sys performance in event of hurricane as required by GDC-2, resulting from safety sys functional insp. Response requested within 30 days.

 PATEL, C.P. Project Directorate in 2. 88/11/21. CARTWRIGHT, W.R. Virginia Power (Virginia Electric & Power Co.). 3pp. 47664;195-47664;197.
- 8811160211 NRC Into Notice 88:090, "Unauthorized Removal of Industrial Nuclear Gauges." Suc list enct. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Satety (Post 870729): 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests" Svc list encl. ROSSI,CE. Division of Operational Events Assessment (Post 870411), 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708142.
- 8812050265 Forwards Insp. Repts 60:280/88:39 & 50:281/88:39 on 881003: 21.No violations or deviations noted Unresolved Item Identified.
 HERDT,A.R., Region 2, Oic of the Director. 88/11/23. CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 2pp. 47723:168-47723:183.

- -8812050267 Insp Repts 50-280/88-39 & 50-281/88-39 on 881003-21. No violations or deviations noted Major areas inspected pipe replacement resulting from erosion/corrosion effects on plant secondary side piping sys made of carbon steel matt. ECONOMOS.N., BLAKE,J.J. Region 2, Ofc of the Director. 887/11/17, 14pp. 47723.170-47723.183.
- 8812070247 Forwards Insp Repts 50:260/68-44 & 50:281/88-44.No violations or deviations noted

 BERDT A.R. Region 2, Ofc of the Director, 88/11/23, CARTWRIGHT, W.R. Virginia

 Fower (Virginia Electric & Power Co.), 2pp. 47746:250-47746:255.
- 8812070240 Insp. Repts 50-280/68-44 & 50-281/68-44 No violations or deviations observed Major areas inspected insense inspire rejectable indications found in certain easiety-related sockel welds evaluation & proposed corrective action. ECONOMOS,N., BLAKE, J.J., Region 2, Ofe of the Director, 88/11/16, 4pp. 47746:252-4774.8255.
- 8312830033 Forwards Insp Repts 50-280/88-40,50-281/88-40,50-338/68-28 & 50-339/ 88-28 on 980926-30 No violations or deviations noted. COLLINS.D.M. Region 2, Oto of the Director, 88/11/23, CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.), 2pp. 47750:119-47750:132.
- -8812080039 Insp. Repts 50-280/88-40,50-281/88-40,50-338/88-28 & 50-339/88-28 on 880926-30 No violations or deviations noted. Major areas inspected control room habitability & insp followup items. dicenses NW 8, MARSTON,R.R., KAHLE,J.B. Region 2, Ofc of the Director. 88/10/26, 12pp. 47750; 121-47750; 132.
- 8812060170 Confirms 881123 talcon re 881222 enforcement conference at Region II of concerning corrective action problems at plant. ERNST.M.L. Region 2, Ofc of the Director. 88/11/28. CARTWRIGHT,R.W. Virginia Power (Virginia Electric & Power Co.). 2pp. 47741:222-47741:225.
- -8812060173 Notification of 881222 enforcement conference w/util in Atlanta,GA to discuss failure to take adequate corrective action during & after reactor cavity soal & CAHTRELLE, Region 2, Ofc of the Director, 68/11/25, Region 2, Ofc of the Director, 2pp. 47741:224-47741:225.
- 8812080163 Forwards Insp Repts 50-280/88-38 & 50-281/80-38 on 881003-07 & 1009-14.No violations or deviations noted. HEROT, A.R., Region 2, Ofc of the Director. 88/11/29, CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.), 2pp. 47756:215-47755:226.
- -3812080165 Insp Repts 50-280/88-38 & 50-281/88-38 on 881003-07 & 1009-14-No violations or deviations noted Major areas inspected, reactor cavity water seal assem-tayton, control room envelope air conditioning sys test & pipe supports. AYTOR, P.A., LENAHAN, J.J., JAPE, F. Region 2, Ofc of the Director, 88/11/23, 10pp.
- 8812080181 Forwards Insp Repts 50-280/88-42 & 50-281/88-42 on 881011-14 & notice
- of violation.

 DECKER,T.R. Region 2, Ofc of the Director. 88/11/29. CARTWRIGHT,W.R. Virginia DECKER,T.R. Region 8 Power Co.). 2pp. 47783:254-47783:268.
- -8812080182 Notice of violation from insp on 881011-14. Violation noted: requirement to follow radiation control procedures not met in that people sighted exiting site through DECKER, T.R. Region 2, Ofc of the Director. 88/11/29, 2pp. 47783:256-47783:257.
- -8812080184 Insp. Repts. 50:280/88-42 & 50:281/88-42 on 881011-14. Violation noted Major areas inspected:facility radiation protection program,including followup on BASSETT.C.H., HOSEY.C.M. Region 2, Ofc of the Director. 88/11/28. 11pp.
- 8812080159 Forwards Insp Repts 50-280/88-41 & 50-281/88-41 on 881002- 1105.Vio-tation noted Violation for failure to take appropriate corrective actions identified in encl rept being considered for escalated enforcement action. REYES,L.A. Region 2, Ofc of the Director. 88/11/30. CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.), 2pp. 47756:325-47756;348.
- -8812080162 Insp Repts 50-280/88-41 & 50-281/88-41 on 881002-1105. Violation noted Major areas inspected licensee actions on provious enforcement matters operations, maint, suvvoillance, LER review & design changes & mods. 11/30. 20pp. 47756:327-47756:348.
- 8811290030 NRC Info Notice 68-093, "Teletherapy Events." Svc list enct. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Salety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list
- enct.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02.
 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812190142 Discusses Mgt Meeting Insp. Repts 50-280/88-46 & 50-281/88-46 on 881117 re status of commitments made to NRC to upgrade radiation protection program at facility Meeting summary enct. ERNST,M.L., Region 2, Ofc of the Director, 88/12/02, CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.), 9pp. 47849:166-47849:174.
- 8812190262 Forwards Insp Repts 50-280/88-43 & 50-281/88-43 on 881031- 1102.No violations or deviations noted Scope & objectives for 890301 emergency exercise re-
- volations or deviations of deviations and account of the Director 88/12/07. CARTWRIGHT, W.R. Virginia COLLINS, D.M. Region 2, Ofc of the Director 88/12/07. CARTWRIGHT, W.R. Virginia Electric & Power (Virginia Electric & Power Co.). 2pp. 47855:107-47855:124.
- -8812190283 Insp Repts 50-280/88-43 & 50-281/88-43 on 881031-1102.No violations of deviations noted Major areas inspected annual emergency preparedness exercise & SARTIORIWM. RANKIN.W.H. Region 2, Ofc of the Director. 88/12/05. 16pp. 47855:109-47855:124.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/08, Consolidated Edison Co. of New York, Inc. 112pp. 47607:191-47807:302.

- 8812200087 Responds to NRC 881109 ltr re violations noted in Insp Repts 50:280/88-35 & 50:281/88-35 Corrective actions:respiratory equipment in question removed from svc,refurbished w/hoses & recalibr to ensure required discharge flow. CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.), 88/12/09, Document Control Branch (Document Control Desk), 4pp. 47871:071-47871:074.
- 8812200170 Responds to NRC 881110 lit re violations noted in Insp Repts 50-280/88.
 28 & 50-281/88-28 & proposed imposition of civil penalty in amount of \$50,000.Corrective actions:Special Test Procedure 1-ST-214, "Operability of..." performed.Fee periormed.Fea CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 88/12/08. Dec. ment Control Branch (Document Control Desk). 7pp. 47858:291-47858:297.
- 8812210229 Ack recaipt of 881028 response to violations noted in Insp Repts 50-280/ 88-30 & 50-281/88-30. HERDT,A.R. Region 2, Oic of the Director. 88/12/15. CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 1p. 47876:231-47876:231.
- 8812220021 Forwards Insp Repts 50-280/88-32 & 50-281/88-32 on 880912-16,26-30 & 1114-18. Violations notodisse water sys would not have met safety design objectives w/o relying on nonsafety-grade equipment. Executive summary encl. ERNST.M.L. Region 2, Oic of the Director. 88/12/15. CARTWRIGHT.W.R. Virginia Power (Virginia Electric & Power Co.). 4pp. 47900:342-47901:062.
- --8812220028 Insp Repts 50-280/88-32 & 50-281/88-32 on 880912-16,28-30 & 1114-18 Violations noted Major areas inspected operational readinoss of svc water & recirculation spray sys to meet intended design functions under postulated conditions. BELISLE,5.A., MELLEN,L.S., JULIAN,C.A. Region 2, Olc of the Director. 88/12/15, 77pp. 47900:348-47901:082.
- 8812220291 Ack receipt of 881209 ltr & payment of civil penalty in amount of \$50,000 proposed by NRC 881110 ltr.Corrective actions will be examined during future insps. LIEBERMAN,J. Ofc of Enforcement (Post 870413), 88/12/20, CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 1p. 47903:049-47903:049.

R. Periodic operating reports & related correspondence

- 8812200104 Monthly operating rept for Nov 1988 for Surry Power Station Units 1 &
- 812200104 Monthly operating rept for Nov 1998 for Surry Power Station Units 1 a 2.W/88125 ft., WARREN,L.A., CARTWRIGHT, W.R. Virginia Power (Virginia Electric & Power Co.), 88/ 11/30, 22pp. 47876:312-47870:333.

S. Reportable occurrences, LERs & related correspondence

- 8811230272 LER 89-042-00:on 881016,w/Unit 1 in retueling shutdown & Unit 2 in cold shutdown,process vent high range officent monitors declared inoperable.Caused by falled flow control circuit board.Preplanned operation varified.W/881115 ltr. 47652:075-47652:076. (Virginia Electric & Power Co.). 88/11/15. 4pp.
- 8811280072 LER 88-041-00:on 881016,engineering evaluation revealed that existing lift-ing frames installed over FHR pumps, associated w/piping & electrical supply lines,not solsmically qualified. Caused by Inadequate analysis. W/881114 ltr. BENSON,DL. Virginia Power (Virginia Electric & Power Co.). 88/11/15, 4pp.
- 8812070206 LER 88-014-01:on 870630, datermined that unique scenario could exist whereby auxiliary feedwater could be tost to operating unit. Administrative controls established & safety analysis reviewed for high-energy line break. W/881130 ltr. 47749:238-47749:241. Power (Virginia Electric & Power Co.). 86/11/30, 4pp.
- 8612060281 LER 88-033-00:on 881102,discovered main control room envelope air conditioning sys inadequate. Caused by inadequate design control program & inadequate preventive main. Mods will be implemented. W/861202 ltr, tr, Virginia Power (Virginia Electric & Power Co.), 86/12/02, 5pp. 47734:331-47734:335.
- 8812150122 LER 68-043-00; on 981110, engineering evaluation determined that recirculation sprays B & C HX svc water Inlet valve & outlet valve have understeed motors. Cause undetermined. Motors will be replaced prior to unit restart, W/861209 tr. 47826:251-47826:254.

 William Power (Virginia Electric & Power Co.). 88/12/09. 4pp.
- 8812150190 LER 87-009-01:on 870330.discovered that inside containment isolation valve for containment sump pumps would not close. Caused by corrosion product KANSLER.M.R. Virginia Power (Virginia Electric & Power Co.). 68/12/09. 4pp.

Y. Dry Cask Independent Spent Fuel Storage Installations

- 8812130071 Forwards Rev 13 to ISFSI nuclear security personnel training & qualification program. Rev withhold (ref 10CFR73.21).
 CARTWRIGHT, W.R. Virginia Power (Virginia Electric & Power Co.), 88/12/08, Document Control Branch (Document Control Dosk), 1p. 47792:128-47792:128.
- 8812130081 Forwards replacement transmittal cover fire for 860914 Rev 13 to personnel training & qualification program & plant ISFSI nuclear personnel training & qualification program.W/o encl.

 CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.), 88/12/08, Document Control Branch (Document Control Deak), 1p. 47794:088-47794:088.

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8811300394 Informs of 890216 emergency exercise to be conducted to demonstrate capability of assessing radiological conditions & determine protective actions necessary to ensure public health & safety CARTWRIGHT, WR Virginia Power (Virginia Electric & Power Co.) 88/11/17 ERNST,M.L. Region 2, Ofc of the Director, 3pp. 47705.024-47705.026
- 8812010037 Revised emergency plan implementing procedures, consisting of Rev 13 to EPIP-5.03, "Personnel Accountability" & Rev 5 to EPIP-5.05, "Site Evacuation," W/ 881123 if & Page 3 to Index CARTWRIGHT, W.P., Vrgina Power (Vrgina Electric & Power Co.) 88/11/23 19pp
 - 47702 257 47702 275
- 8812080181 Forwards Insp Repts 50 280/88-42 & 50-281/88-42 on 881011-14 & notice
 - of violation.
 DECKER,T.R. Region 2, Old of the Director 88/11/29, CARTWRIGHT,W.R. Virgin a
 Power (Virginia Electric & Power Co.). 2pp. 47783:254-47783:268.
- ~8812080182 Notice of violation from insp on 881011-14. Violation noted requirement to follow radiation control procedures not mot in that people sighted outing sile through afarming portel monitions w/o being stopped by Security personnel.

 DECKER, T.R. Region 2, Ofc of the Director. 88/11/29. 2pp 4/783:256-47783.257
- 8812190244 Advises that 881001 roy to corporate emergency plans moots requirements of 10CR50 47(b) 8 App E & acceptable
 DECKER,T.R. Region 2, Ofc of the Director, 88/12/05, CARTWRIGHT,W.R. Virginia
 Power (Virginia Electric & Power Co.), 1p. 47851 270-47851:270.
- 8812190262 Forwards Insp Ropts 50-280/88-43 & 50-281/88-43 on 881031- 1102 No violations or deviations noted Scope & objectives for 890301 emergency exercise re
 - quested COLLINS,O.M. Region 2, Ofc of the Director, 88/12/07, CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.), 2pp. 47855;107-47855;124.
- ~8812190263 Insp. Repts 50:280/88:43 & 50:281/88:43 on 881031-1102.No violations for deviations noted Major areas inspected annual emergency preparedness exercise & associated critique & following on open floris. SARTOR,W.M. Region 2, Ofc of the Director. 88/12/05 16pp. 47855:109:47855:124.
- 8812130066 Forwards Rov 13 to nuclear security personnel training & qualification program Rov withheld (rd 10CFR73.21)
 CANTWRIGHT,WR, Virginla Power (Virginla Electric & Power Co.). 88/12/08. Decument Control Branch (Document Control Desk). 1p. 47794:089-47794:089.
- 8812130071 Forwards Rov 13 to ISFSt nuclear security personnel training & qualifica-tion program Rov withhold (rof 10CFR73.21). CARTWRIGHT,WR. Virginia Power (Virginia Electric & Power Co.). 88/12/08 Decu-ment Centrel Branch (Document Centrel Desk). 1p. 47792:128-47792.128
- 8812130081 Forwards ruplacement transmittel cover firs for 880914 Rev 13 to personnel training & qualification program & plant ISFSI nuclear personnel training & qualification program.W/o oncl.
 CARTWRIGHT,WR. Virginia Power (Virginia Efectric & Power Co.). 88/12/08. Document Control Branch (Document Control Dosk). 1p. 47794:088-47794.088.

P. Operating license stage documents & correspondence

- 881f230387 Forwards summary of radiation protection program upgradu status, per 88 (03) telcon.
 CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 88/11/10
 ERNST,M. Region 2, Old of the Director. 12(pp. 4783) 275-47631:288.
- 8811280175 Forwards notice of exemption re-schedular requirements of 10CFR50 App J Examption allows util to resunte normal Type A ratest schedule per Socion III.D PATEL.C.P. Project Oktockrate II.2. 88/11/21. CARTWRIGHT,W.H. Virginia Power (Virginia Electric & Power Co.) 3pp. 47652 248-47652 259.
- -8811280180 Exemption from regulroments of 10CFR50,App J to allow util to resume normal Typo A relust schedule per Section III.D.

 VARIGA,S.A. Division of Reactor Projects - I/II (Post 870411), 88/11/21, Virginia Power (Virginia Electric & Power Co.), 5pp. 47652:251-47652:255
- -6811280182 Safety evaluation supporting request for exemption from containment in-
- tegrated leakage rate test.
 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/21, 4pp. 47652 256 47652 259.
- 8811280048 Goneric Ltd 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for sovere accident vulnerabilities.Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024
- 8812150135 Forwards "Surry Simulator Certification Submittat."
 CARTWRIGHT.W.R. Virginia Power (Virginia Electric & Power Co.). 88/11/23. Office of Nucloar Reactor Regulation, Director (Post 870411). 1p. 47821:205-47822:144.
- -8812150137 "Surry Simulator Certification Submittal." Virginia Power (Virginia Electric & Power Co) 88/11/30. 200pp 47821:206-47822.144.
- 8812010263 Notification of 881208 meeting w/util in Rockvillo,MD to discuss status of control from variitation chillers & mods to & testing of emergency diesal generators. BUCKLEY,B.C. Project Directorate II-2. 88/11/30. BERKOW,H.N. Project Directorate II-2. 3pp. 47703-321-47703-323.
- 8812050105 Discusses plans for Cycle 10 roload core Cycle will mark first use of plant improved fuel product in Unit 2.per 880106 approval. CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 88/11/30. Document Control Branch (Document Control Dosk). 2pp. 47730:265-47730:266.
- 8812060102 Responds to Goneric Ltr 88-11 re embrittlemont of reactor vessel baltime matts, per Reg Guido 1.99, Roy 2. Proposed Tech Specs which implement Rev 2 to Reg Guido 1.99 under NRC review.

 CARTWRIGHT,W.F. Virginia Power (Virginia Electric & Power Co.). 88/11/30. Document Control Branch (Occument Control Desk). 2pp. 47734:354-47734:355.

- 8812120079 Requests that util address Generic Lir 88-17 re loss of DHR during non-powor operation Lir issued due to potentially sorticus consequences resulting from in-artiquacy of Industry response to Generic Lir 87-12 MURILEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/ 02 FERGUSONJ.H. Virgina Power (Virgina Electric & Power Co.) 3pp. 47789.119-47789.12 47789.121
- 8812160061 Advises that BC Buckley assigned as new project manager for plant effective 881204
 BERKOW,H N. Project Directorate II-2, 88/12/13 CARTWRIGHT,W R. Virgin a Power (Virginia Electric & Power Co.) 2pp. 47832-358-47832-359.
- 8812200078 Notification of 881222 meeting w/util in Rockville,MD to discuss info to Support restert
 BUCKLEY,B Project Bractorate II-2 88/12/15 MURLEY,T, SN
 MIRAGLIA,F NRC - No Dotated Albitation Given 3pp 47868 185 47868 187 SNIEZEK,J
- 8812200314 Requests meeting to restart of plant in light of safuty, significant design detrooncles, including mislate/ed motor operated Valves MOV 863A & B ERNST, ML. Region 2, Otc. of the Director 88/12/15 CARTWRIGHT, W.R. Virgima Power (Virgina Efectric & Power Co.). 1p. 47864.293-47864.293
- 8812270232 Forwards "Surry Unit 2 Cycle 9 Core Performance Rept," for Info CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.) 88/12/20 Docu-ment Control Brench (Document Control Desk) 2pp. 47926.278-47926.330
- 8812270201 Ack receipt of NRC 881121 request for add info re capability of plant svowator sys to porform safety function during humosono as required by GDC-2-Requested info will be provided by 890403.

 CARTWIGHT, WR. Vrignla Power (Virgin'a Electric & Power Co.). 88/12/21. Document Control Branch (Document Control Desk.). 1p. 47926-021-47926-021

- 8811290246 Forwards request for addlinfo releval water sysidesign, per NRC evaluation of sec water sys performance in event of hurricane as required by GDC-2, resulting from safety sys functional risp Response requested within 30 days.

 PATEL C P Project Directorate #12 88/11/21. CARTWRIGHT, W.R. Virginia Power (Virginia Electric & Power Co.) 3pp 47664:195-47664:197.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gaugos "Svc list encl CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708-255-47708.257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologi-ROSSI,C E. Division of Operational Events Assessment (Post 870411). 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.
- 8812050265 Forwards Insp. Repts 50-280/88-39 & 50-281/88-30 on 881003- 21 No vio-lations or deviations noted Unresolved dom identified. HERDTA.R. Rugon 2, Otc. of the Director. 88/11/23 CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 2pp. 47723.168-47723:183.
- -8812050267 Insp Repts 50-280/88-39 & 50-281/88-30 on 881003-21.No violations or dowallons noted Major areas inspected pipe replacement resulting from eroston/corre-sion effects on plant secondary side piping sys made of carbon steel mult ECONOMOS,N. BLAKE,I.J. Region 2, Ofc. of the Director. 88/11/17
- 8812070247 Forwards Insp. Ropts 50-280/88-44 & 50-281/88-44.No violations or deviations noted.
 HERDT,A.R. Region 2, Ofc of the Director. 88/11/23 CARTWRIGHT,W.R. Viliginia.
 Power (Virginia Electric & Power Co.). 2pp. 47746-250-47746-255.
- -8812070248 Insp. Repts 50 280/88-44 & 50-281/88-44 No violations of deviations noted Major areas inspected insorvice inspire renjectable indications found in certain safety-related socket wolds ovaluation & proposed corrective action. ECONOMOS,N., BLAKE,J.J. Region 2, Old of the Director, 88/11/18, 4pp. 47746.252-
- 47746 255
- 8812080033 Forwards Insp Hupts 50-280/88-40.50-281/88-40,50-338/88-28 & 50-339/88-28 on 880928-30 No violations or devatrons noted.
 COLLINS.O.M. Rogion 2. Oic of the Director. 88/11/23. CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 2pp. 47750.118-47750.132
- -8812080039 Insp Repts 50-280/88-40,60-281/88-40,60-338/88-28 & 50-339/88-28 on 880926-30 No violations or deviations noted. Major greas inspected control room habitability & insp followup itoms. GLOERSEN,W B., MARSTON,R.R., KAHLE,J B. Region 2, Otc of the Director. 88/10/ 26. 12pp 47750.121-47750.132.
- 8812960170 Confirms 881123 telcon re 881222 enforcement conference at Region II
 - ote concerning corrective act on problems at plant.
 ERNST,M.L. Region 2, Otc of the Director, 88/11/28, CARTWRIGHT,R.W. Virgin'a
 Power (Virginia Electric & Power Co.), 2pp. 47741:222-47741:225.
- ~8812080173 Notification of 881222 onforcement conference w/util in Atlanta,GA to discuss failure to take adequate corrective action during & after reactor cavity seal & Svc water sys design control issue.

 CANTRELL, F. Region 2, Oic of the Diructor. 80/11/28. Region 2, Oic of the Diructor. 20/11/28. Region 2, Oic of the Diructor.
- 8812080163 Forwards Insp Ropts 50-280/88-36 & 50-281/88-38 on 881003-07 & 1009-14 No violations or deviations noted. HERDT-A.R. Region 2, OIC of the Director 88/11/29 CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.) 2pp 47756-215-47756-226
- -8812080165 Insp. Repts 50-280/80-38 & 50-281/88-38 on 881003-07 & 1009-14 No violations or deviations noted Major areas inspected reactor cavity water soal assombly mode, control room envelope eir conducioning systems & pipe surports TAYLOR, P.A., LENAHAN, J.J., JAPE, F. Region 2, Otc of the Director 88/11/23, 10pp 47756 217-47766 226

- 8812000181 Forwards Insp Repts 50-280/88-42 & 50-281/89-42 on 881011-14 & notice of viciation DECKER,T.R. Region 2, Ofc of the Director, 88/11/29 CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 2pp. 47783-254-47783-268
- =88 #2080 #82 Notice of violation from inspiren 86 1011-14. Violation halled requirement to follow radia: on control procedures not mat in that people sighted exting site through alarming portal monitors w/o being stopped by security personnel. DECKER,T.R. Region 2, Ofc of the Director, 88/11/28, 259, 47783, 256-47783, 257.
- -8812080184 Insp. Repis 50-260/88 42 & 50-281/89-42 on 881011-14. Violation noted Major areas inspected lacilly radiation protection program including followup on tensee performance incrovement program tems.

 BASSETT.CH. HOSEY.CM. Region 2, Otc. of the Director 88/11/28. https://doi.org/10.1006/
- 8812080169 Forwards Insp. Repts 50:280/88:41 & 50:281/88:41 on 881002: 1105 Violation noted V.o'at.on for failure to take appropriate corrective actions identified in ending to the source of th
- ~8812080162 (asp. Repts 50-289/88-41 & 50-281/88-41 on 881002-1105 Vigitation noted Major areas inspected I censee actions on provious enforcement matters operations maint survoillance, LER review & design of angus & mods. HOLLAND,W.E., NICHOLSON,L.E., CANTRELL,F.S. Region 2, Ofc of the Director 88/11/30 20pp. 47758-327-47758-348.
- 8811290030 NRC Info Natice 88 093 "Teletherapy Events" Svo list end CUNNINGHAM,R.E. Division of Industrial & Medical Nuclea: Salety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Svc list
 - encl ROSSI,CE, Division of Operational Events Assessment (Post 870411) 89/12/02 Consolidated Edison Co. of New York, Inc. 121pp 47708 143-47708 254.
- 8812190142 Discusses Mgt Moeting Insp Repis 50-280/88-46 & 50-281/88-46 on 881117 re-status of commitments made to NRC to upgrade radiation protection program at facility. Meeting summery enci.
 ERNST,M.L. Region 2, Ofc. of the Director, 88/12/02, CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.) 9pp. 47849 186-47849.174.
- 8812190282 Forwards Insp. Repts. 50-280/88 43 & 50-281/88-43 on 881031- 1102.No. violations or deviations noted Scope & objectives for 890301 emergency exercise re-Quested.
 Quested.
 Que
- --9812190263 Insp Repts 50-280/88-43 & 50-281/88-43 on 881031-1102 No violations or devations noted Major areas Inspected annual emergency preparedness exercise & associated critique & followup on open items SARTOR.W.M., RANKIN.W.H. Regon 2, Olc of the Director, 88/12/05 16pp.
- 47855:109-47855:124.
- 8812020287 NRC Into Notice 88-095, "Inadequate Procurement Requirements Imposed by Liconsees on Vendors" Svc list encl. ROSSIC E Division of Operational Events Assessment (Post 870411). 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp 47807:191-47807-302.
- 8812200067 Responds to NRC 881109 lit re-violations noted in lnsp Repts 50-280/98-35 & 50-281/88-35. Corrective ections respiratory equipment in question removed from svc_refurbished w/hoses & receibtr to ensure required discharge llow. CARTWRIGHT.WR. Virgins Prom: (Virgins Electric & Power Co.) 88/12/09. Docu-ment Control Branch (Document Control Desk). 4pp. 47871-071-47871.074.
- 88 f2200170 Responds to NRC 891110 lit re violations noted in linsp Repts 50 280/66-28 & 50 281/86 28 & proposed imposition of civil penalty in amount of \$50,000 Corrective actions:Special Test Procedure 1-ST-214, "Operablity of "performed Fee
- pald.
 CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 88/12/09. Document Control Branch (Document Control Desk). 7pp. 47858 291-47858 297.
- 8812210229 Ack receipt of 681028 response to violations noted in Insp Repts 50:2807 68:30 & 50:281788:30. HEROTA R Region 2, Otc of the Offector, 68/12/15. CARTWRIGHT,W.R. Virginia Power (Virginia Efectric & Power Co.). 1p. 47876:231-47878:231.
- 8812220021 Forwards Insp Repts 50-280/88-32 & 50-281/88-32 on 880912-16,26-30 & 1114-19 Violations noted svc water sys would not have met safety design objectives w/o refying on nonsafety grade equipment Executive summary encil ERNST M. Region 2, Otc. of the Director, 86/12/15 CARTWRIGHT, W.R. Virginia Power (Virginia Electric & Power Co.). 4pp. 47900-342-47901-082.
- -8812220028 Insp Repts 50-280/88-32 & 50-281/88-32 on 880912-16,26-30 & 1114-18 Violations noted Major areas inspected operational readiness of six water & reck-culation spray sys to meet intended design functions under postulated conditions BELISLEG A, MELLEN,L.S., JULIAN,C.A. Region 2, Ofc of the Director, 88/12/16, 77pp. 47900.346-47901.082

R. Periodic operating reports & related correspondence

- 8812200104 Monthly operating rept for Nov 1988 for Surry Power Station Units 1 & 2.W/881216 Itr.
 WARREN,L A., CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.): 88/11/30, 22pp. 47870:312-47870.333.
- Y. Dry Cask Independent Spent Fuel Storage Installations
- 8812130071 Forwards Rev 13 to 19FSI nuclear security personnel training & qualification program.Rev withhold (ref 10CFR73.21) CARTWRIGHT.W.R. Virginia Power (Virginia Etectric & Power Co.) B8/12/08. Document Control Branch (Document Control Desk). 1p. 47792.128-47792.128.

8812130081 Forwards replacement transmittal cover litrs for 880914 Rev 13 to person-nel training & qualification program & plant ISESI nucleur personnel training & quarti-cation program W/o end CARTWAIGHT, WR. Vriginia Power (Virginia Electric & Power Co.). 88/12/08. Docu-ment Control Brench (Document Control Dask). 1p. 47794-088-47794-088

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812210232 Forwards Physical Security Insp. Repts 50-282/88-23 & 50-308/89-24 un-881108-18 No violations noted. NORELIUS C.E. Region. 3. Oct. of the Director. 88/12/09. LARSON,C.E. Northern States Power Co. 2pp. 47881-183-47881-185
- -9812210244 Partially withhold Physical Security Insp. Ropts 50-282/88-23 & 1,0-30-07 88-23 on 681108-18 Violations noted Major areas inspected migt support, such typic grain plans & audits, protected & vital area physical barriers. FUNK DE, PIRTLE, 61, CREED, J.R. Region 3, Ofc of the Director, 88/12/08 259 47681:165-47881.166.
- 8812210198 Forwards set of F3 tabs for emergency plan implementing procedures FEY,F.L. Northern States Power Co. 88/12/14. Document Control Branch (Document Control Desk) 2pp. 47906 290-47906.300.

J. Insurance & Indemnity Information

8811300469 Advises that 861017 ftrire financial into for 1988 satisfies requirements of 10CFR140 21 re maint of approved guarantee of payment of deferred premiums for each operating reactor over 100 MW(e) owned in whole or part NASH,DA Polycy Devolopment & Technical Support Branch (Post 870411) 86/11/ 21 HALL,E J Northern States Power Co. 1p. 47677:268-47677-268

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 88-20 to all ficonsees holding OLs & CPs for nuclear power reactor facilities to individual plant examility several accident vulnorabilities Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 970411), 88/11/23. Gorsc. dated Edison Co. of New York, Inc. 81pp. 47728:303-47720-024.
- 8812080122 Requests that uhi address Generic Ltr 86-17 re loss of DHR during non-power operation Industry response to Generic Ltr 87-12 detected in areas of preven-tion of accident initiation & mitigation of accidents MURICEY.T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02. HOWARD,JJ Northern States Power Co. 3pp. 47755:184-47765.186.

- 8812190396 Responds to NRC 880527 & 0607 hrs re-violation noted in Insp Repta 50-282/86-05 & 50-336/88-05. Corrective actions blown fuso for Bus 16 voltage restoring scheme replaced & bus declared operable within 20 minutes. LARSON,C E. Northern States Power Co. 88/06/27, GULDEMOND,W.G. Region 3, Otc of the Director. 2pp. 47851,330-47851;331.
- 8811290345 Forwards "...Inservice Insp Exem Summary,880815-0914, Holueting Oualge 12,Insp Period 2,Second Interval." Rept Identifies components examined,exam methods used & exam number for insps conducted during last refuciing guitage.
 MUSOLF,D. Northern States Power Co. 88/11/18. Office of Nuclear Reactor Regulation, Director (Past 870411). 1p. 47686-148-47687-008.
- -- 9811290391 "Prairie Island Nucloar Gonerating Plant Unit 1,inservice Insp Exam Summary, 880815 to 880914, Relueting Outage 12, Insp Parlod 2, Second Interval "KELLERHALL, FIA. RICKEH, J.L. Northorn States Power Co. 68/10/25. 219pp 47866:140-47667.008.
- 8811300506 Forwards Safety Insp Repts 60-282/88-16 & 50-306/88-16 on 880016 1026 & notice of violation

 WRIGHT,G.C. Region 3, Old of the Director, 88/11/21, LARSON,C.E. Northern Status

 Power Co. 2pp. 47677:303-47677,321.
- -8611300512 Notice of violation from Insp. on 880016:1026.Violation noted procurement documents which requisition call broot flowmeters did not requisition that as-lourd condition by determined.
 WRIGHT,G C Region 3, Ofc of the Director. 88/11/21, 3pp. 47677:305-47677:307.
- ~8811300517 Insp Repts 50-282/88-16 & 50-306/88-16 on 880918-1026. Violations noted Major areas inspected licensee action on previous insp findings contement in tegrated leak rate test (CILRT) & CILRT performance witnessing & results review.

 MENDEZ.R., PHILLIPS.M.P. Region 3, Ofc of the Director. 88/11/17. 14pp. 47677:30B-47677:321
- 8811160211 NRC Info Notice 88 090, "Unauthorized Removal of Industrial Nuclear Gauges: Svc list and Countries & Medical Nuclear Safety (Post 870729) 08/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708.255-47708 267.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests" Svo list enct.
 ROSSICE. Division of Operational Events Assessment (Post 870411). 88/11/22.
 Consolidated Edison Co. of Now York, Inc. 101pp. 47708:042-47708:142.
- 6812020213 Forwards Safety Insp Repts 50-282/88 19 & 50-308/88-19 on 880925-105 & notice of violation 105 & notice of violation AXELSON.W.L. Region 3, Ofc of the Director, 88/11/23, LARSON,C.E. Northern States Power Co. 2pp. 47707:182-47707:194.

noted Major areas inspected providus insp. lindings.plant operational safety maint-jurvoillances.ESF sys.LER followup & info notice & butletin followup BURGESS.B. Region 3. Ofc of the Ozector 88/11/23, 10pp, 47/07/185-47/07/194 cperational

- 8812060149 Forwards Insp Repts 50:282/88-18 & 50:306/88-18 on 890919-22 No vio-
- lations noted GREGERI, B. Region 3, Ofc of the Director 88/11/30 LARSON,C.E. Northern States Power Co. 2pp. 47740 326-47740.333.
- --B812060151 Insp. Repts. 50-292/88-18. 8. 50-306/88-18. on. 880918-22 No. violations noted Major areas inspected concerns associated w/Allogation Rilli-A-0111, JANUSKA, A., FUNK, D., SCHUMACHER, M. Region. 3, Ofc. of the Director. 88/11/30. 6pp. 47740-328-47740-333.
- 8611290030 NRC Info Notice 88-093, "Telotherapy Events" Svc list encl CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729), 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47611 103-47811 215
- 8811290538 NRC Info Notice 86-094, "Potentially Undersized Valve Actuators." Svc list ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708;143-47708;254.
- 88 12120110 Forwards addl response to NRC IE Bulloto 80-08 re exam of containment liner genetration welds Util behaves that inability to rad ograph wolds not of concern, MUSDLF_D. Northorn States Power Co. 89 12/05. Office of Nuclear Reactor Regula-tion, Director (Post 870411). 7pp. 47789 068-47789 074.
- 8812140237 Forwards Safety Insp Repts 50-282/88-21 & 50-306/88-21 on 881114-18.No violations noted
 GREGERIL R. Rogion 3, Otc of the Director, 88/12/06 LARSON,C.E. Northern States
 Power Co. 2pp. 47800 344-47800.351.
- -8812140239 Insp Repts 50-282/88-21 & 50-306/88-21 on 881114-18 No violations noted Major areas inspected action on proviously Identified items, emergency plan activations & operational status of emergency proparedness program. SMITH.M.J., SNELL,W. Rogion 3, Oic of the Director. 08/12/05 6pp 47800.346-7806.05
- 47800 351 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Liconsess on Vendors" Svc 1st and. ROSSI, CE. Division of Operational Events. Assessment (Post 870411). 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807;191-47007;302.
- 8812120005 Forwards proprietary & nonproprietary safety evaluation to NRC Bulletin 88-002, "Repklify Propagating Fatigue Cracks in Steam Generator Tubes." Finding subjite adoption of addit administrative controls.

 DIIANNI,D.C. Project Directorate III-1, 88/12/08, MUSOLF,D.M. Northern States Power Co. 4pp. 47787:193-47787:190.
- ~8812120009 Safety evaluation accepting Leansee analyses documented in WCAP-11787.Based on satisfactory resolution of flore C 2 of Bulletin 88 002 liconage may terminate commitment to enhanced loak rate monitoring program.
 * Office of Nuclear Reactor Regulation, Director (Post 870411), 89/12/08, 3pp. 47787:197-47787:199.
- 8812210232 Forwards Physical Security Insp Ropts 50-282/88-23 & 50-306/88-23 on 881108-18 No violations noted. NORELIUS,C.E. Region 3, Olc of the Director. 88/12/09. LARSON,C.E. Northern States Power Co. 2pp. 47881:163-47681:166.
- -8812210244 Partially withhold Physical Security Insp Repts 50:282/88:23 & 50:306/88:23 on 881108:18 Violations noted Major areas inspected.mgl support, security program plans & audits, protocted & vital area physical barriers. FUNK.D.E., PIRTLE,G.L., CREED,J.R. Rag on 3, Old of the Director. 88/12/08, 2pp. 47681:165-47881:166.

R. Periodic operating reports & related correspondence

S. Reportable occurrences, LERs & related correspondence

- 8612140253 Monthly operating ropts for Nov 1988 for Prairie Island Nuclear Generating Plant.W/881207 ftr. DUGSTAD,D., MUSOLF,D. Northern States Power Co. 88/11/30. 9pp. 47821.061-47821.069
- 8811300044 LER 88-006-00:on 881027,fallure to perform alrifock seal tost within required lime period as result of personnel error. Caused by fallure of reactor operator to identify containment entry of 880526 Artifick seal test performed. HUNSTAD. A.A., MUSOLF,D. Northern Status Power Co. 88/11/21, 4pp. 47680:303-42688-682.
- 8812020094 LER 88-007-00:on 881029.spike on radiation monitor caused automatic start of auxiliary bidg special ventilation sys. Caused by faulty detector Radiation monitor detector replaced Event discussed w/mvolved personnel W/881128 ltr. HUNSTAD, A.A., MUSOLF,D. Northern States Power Co. 88/11/28. 4pp. 47711:132-47711,136.
- 8812070209 LER 88-008-00.on 881101 gaseous elfluent analysis not completed when elfluent samples lost enroute to tablicaused by fillers being discarded accidentally upon opening of container. Filters will be bota counted .W/881201 ltr. HUNSTAD.A.A., MUSOLF.D. Northern States Power Co. 88/12/01. 4pp. 47745/349-47745:352
- 8812200056 LER 88-009-00:on 881111.Interlocked double doors in auxiliary bldg special ventilation zone boundary found open. Caused by failure in interlock & alarm mechanism Door strikes will be replaced.W/881212 ltr.
 HUNSTAD,A.A., MUSOLF,D. Northorn States Power Co. 88/12/12. 4pp. 47862:169-47862:172.

- 8812010340 Requests exemption from 10CFR50 12.App R.Soction III.0, "O.I Collector Sys for Reactor Coolant Pumps" NRC approved current tank capacity based on App A to Branch Tochnical Position 9.5-1, prior to Issuance of App R. MORRIS,J.K. Omaha Public Power District 88/11/28 Document Control Branch (Document Control Desk). 13pp. 47709.208-47709.220
- 8812070056 Revised emergency plan Implementing procedures,including Rev 14 to EPIP-OSC-1,Rov 3 to EPIP-RR-35,Rov 4 to EPIP-RR-48,W/ 881202 Itr FRANCO F.F MORRIS,KJ Omaha Public Power District. 88/12/02. 28pp 47747 031 47747 062
- 8812160133 Forwards environ assessment & finding of no significant impact re exemp-tion from 10CFR50.App R.Section III 0 requirements.po: util 881128 request MILANC.P.D. Project Directorate IV. 88/12/13 MORRIS.K.J. Cmaha Public Power District. 3pp. 47835 163-47835-168.
- ~8812160135 Environ assessment & finding of no significant impact to examption from requirements of 10CFR50,App R,Socilon III 0. CALVO,J A. Project Directorate IV 88/12/13, 3pp 47835 186-47835.168.
- 8812210330 Revs 6 & 5 to Sections I & L of "Radiological Emergency Response Plan" MORRIS,K J. Omaha Public Power District. 88/12/14, 32pp. 47881.167-47881:209.

H. General correspondence

- 8812020103 Comment on proposed rule 10CFR26 re filness for duty Endorses NUMARC comments Believes that 100% annual testing frequency appropriate as adequate deterrent & more than 100% would install burden of excuss for certain employ
 - ags MORRIS,K.J. Omaha Public Power District 88/11/21 CHILK,S.J. Office of the Secre-lary of the Commission. 2pp. 47680 031-47680 032

J. Insurance & Indemnity Information

- 8812130034 Forwards exemption from requirements of 10CFR50.54(w)(1), extending schedule date to 900604 Environ assessment also erct. CALVO_J.A. Project Directorate IV 88/12/05. MORRIS,K J. Omaha Public Power District. 4pp. 47792:107-47792:116 -8812130036 Requests exemption from requirements of 10CFR50.54(w)(1) to extend
- schodulo data to 900604 HOLAHAN,G M. Division of Reactor Projects III,IV,V & Special Projects (Post 870411) 88/12/05 Omaha Public Powor District 4pp. 47792 111-47792:114.
- -8812150091 Environ assessment & finding of no significant impact re exemption from requirements of 10CFR50.54(w)(1)
 O'CONNOR,P.W. Project Directorate IV. 88/11/30. 2pp. 47792:116-47792:116
- 8812160137 Advises that State of NE Supreme Court donled reheating on 881116 re-request for declaratory judgment Meeling hold to discuss stated insurance company roquirements VOIGT, H.H. LeBoout, Lamb, Leiby & MacRau 88/12/06, TREBY S.A. Assistant General Counsel for Rulemaking & Fuel Cycle. 2pp. 47833 081-47833 082.

P. Operating license stage documents & correspondence

- 8812190290 Forwards addl into re-safety enhancement program listing representing in-togration of corrective actions from approximately 19 areas. JONES,W.C. Omaha Public Power District 88/11/11. MARTIN,R.D. Region 4, Ofc of the Director: 2pp. 47849:176-47849.176.
- 8811300095 Discusses potential environ impact of Cycle 12 reload analysis.per request No EIS or anviron assassment would need to be prepared based on stated
 - MORRIS,K.J. Omaha Public Power District. 88/11/22. Document Control Branch (Document Control Dosk). 2pp. 47697:307-47697:308.
- 8811300176 Forwards addt info re util response to NUREG-0737,ttem II D.1,per util 880630 commitment Complete responses will not be available until 990110. MORRIS,K.J. Omatia Public Power District. 88/11/22. Document Control Branch (Document Control Obsk). 4pp. 47676.314-47676.317.
- 8811280048 Generic Lir 86-20 to all ticonseos holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303 47729:024.
- 8812050083 Forwards environ assessment & finding of no significant impact re 880002 application concerning extended fuel irradiation levels. MILANO,P.D. Project Directorate IV. 88/11/30. MORRIS,K.J. Omaha Public Power District, 4pp. 47732.332-47732.339.
- --8812050084 Environ assessment & Ending of no significant impact relicensee 880902 application supporting Cycle 12 operation w/ extended fuel irradiation levels. O'CONNOR,P.W. Project Directorate IV. 88/11/30. 4pp. 47732:336-47732:339.
- 8812060125 Submits status of radiation improvement program for Oct & Nov. 1988.Pro-vides programs of immediate importance to successful radiological protoction & ongo-ing technical support for rotuelling outage. MORRIS,K.J. Omaha Public Power District. 88/11/30. Document Control Branch (Document Control Dosk). 31pp. 47741:164-47741:194.

- M LATIO P.D. Project Discriptato IV. 68/12/01. MORRIS,K.J. Omaha Public Power District 4pp. 47743-124-47743-127
- 8812080035 Proguests review & approval of and, "Alternative Seismo Chloria & Melinido og esitis Fori Cambon Station," Vols 1-8-2 MORRISKI, J. Omsta, Petitis Power Distrol, 88/12/02 Document Control, Branch (Document Control Dosh), 2pp. 47750-185-47750-282
- -8812080036 "Attemate Science Citiena & Methodologies for Fort Cathour Station Vol 1 Criteria & Methodologies *
 * Omaha Publis Power District 89/07/31 E0pp 47750 183 47750 224
- -8812080337 Ameniate Seismic Chiteria & Memodulogies for Fort Calficturi Station Vol. 2 Justifications of Criteria & Methodologies (** Comars Petr.) 1964; Observation 1964
- 8812390233 Regulots uit address Generic Etrie6.17 re less of DHR during nonpower operation accordingly due to industry responding deficiently to Generic Etri87-12 MURENTIFE Office of Nuclear Peactor Regulation Operator (Post 87041) (88/12/ C2 FETEPSON FIM Omana Public Power District 3pp 47793 358-47783 360.
- 8812090150 Address that no stram generally tubes plugged as result of eddy current testing conducted during 1988 returning cutago. MCPR-SK V Omaha. Public Power District. 85/12/05. Document Control Branch (Occurrent Control Dissk), up. 47763-323-47763-323.
- 8812150206 Forwards swexpraphs releasting weeting weeting weeting new Otorie philoso-phy & intentions after printenement program CALLANT J. Roy on 4, Otor of the Onector 88732707 MORRIS,K.J. Chaha Public Power District 20pp. 47630 155-47830 180
- 8812220174 Forwards evaluation re compliance w/ATWS rule (10CFR50 62) re installation of diverse schemistic Sections for including to the transfer of the transfer of auxiliary feedwater sys Concorning ted the registern devices. MILANOPO Project Directorate IV 86112/07 MCRRISK J. Omaha Public Power Disnot 4pp 47886 502-47886 502
- -8812220176 Safety evaluation re-comptrance w/ATWS rufs (10CFR50 62). Open items national restrictions & isolation devices. NRC No Detailed Affiliation Green 88/12/07, 23pp. 47886 305, 47686 328.
- 8812200057 Ack receipt of 880608,0901 & 31 responsos to Generic Ltr 88.05, 180nd And Corrosion of Carbon Shed Reactor Boundary Components in PWR Plants 1 Response demonstrates that program in place 10 actress bond and leakage MILATIO PIO Project Directorate IV. 88/12/12. MCRR S.K. J. Omaha Public Power District 4pp 47850 255 47860 258
- 8812230069 Forwards application for amend to License DPR-40,rewising Tech Spec Section 2.3 to correct organizational structure & refly Fee paid MCRRISK J. Omeha. Public Power. Distinct. 88/12/16. Document Control Branch (Document Control Desk). 1p. 47911-331-47911-348
- -8812230071 Application for amend to License CPA-40, revising organizational structure & correcting rais MORRIS K.J. Omaha Public Power District, 88/12/16, 2pp. 47811,332-47911,333
- -8612230073 Proposed Tech Specs re-organizational structure & administrative controls * Omaha Public Power District 88/12/16, 5pp, 47911,334,47911,348.

- 8811160211 NRC Info Notice 88 090, "Unauthorized Remove! of Industrial Nuclear Gauges: Svc Lst enct CUNNINSHAM,R.E. Diason of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 6811160467 NRC Info Notice 88-031, "Improper Administration & Control of Psychologi-Call Tests: "Svc Fist end:

 ROSSICE Division of Operational Events Assessment (Post 970411), 88/11/22.

 Consolidated Edison Co. of New York, Inc. 101pp. 47709.042-47708.142
- 8811290579 Forwards Insp Rept 50-285/68-34 on 881016-21.No violations or davi-CALLAN, J. Region 4, Ofc of the Director 68/11/23 MORRIS, K.J. Omaha Public Power District, 2pp. 47664, 199, 47664, 211.
- -8811290580 Insp. Rept. 50-285/88-34 on 681016-211to violations or deviations noted Mejor sneas inspected rad alion protection program activities associated w/currient refuering outlage & ellogations re-conduct of radiation protection program CHANEY,HID, RICKETSON,LIT., BAER,RIE, Region 4, Cit of the Director 88/11/14, 11pp. 47664-201-47664-211.
- 8812020313 Ack recept of 881109 ftr informing NRC of steps taken to correct violations noted in Insp Rept 50-285/88-25 CALLAN L.J. Region 4, Otc. of the Exector, 88/11/29, MORRIS,K.J. Omaha Public Power District 2pp. 47718-303-47718-313
- -8812020314 Responds to vicilation noted in thisp Rept 50:285/88-25 re-fature to maintain records Corrective actions satisfactory liquid penetrant exam completed on safety injector lank union weed & training given to QC inspectors MORRI-S.K.J. Omaha Public Power Distort 88/11/09. Document Control Branch (Document Control Desk). 3pp. 47718-311-47718-313.
- 8812060237 Confirms that response to Salety Sys Outage Mid Insp Rept 50-285/88-200 extended to 881219 per tation trativeen PD Milano & 3J Fisicaro MORRIS,K J. Omaha Public Power District 88/11/30. Document Control Branch (Document Control Desk), 1p. 47740-318, 47740-319.
- 8812960274 Ack receigt of 881199 ftr informing KRC of steps taken to correct violations noted in Insp Rept 50/285/88/24.
 CALLANLI J. Region. 4, Ofc. of the Orector. 88/11/30. MORRIS,K J. Omaha Public Power District. 2pp. 47753 004/47753 008
- 8811290030 NRC Into Notice 88 093, "Teletherapy Events" Svc 1st enct. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Salary (Post 870729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp 47811:103-47811:215

- ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 4/708 143-47708 254.
 - 8812050297 Forwards Insp Ropt 50-285/88-43 on 891114-18 & notice of violation CALLANIL J. Region 4, Cit. of the Director. 89/12/02. MCRIPIS, K.J. Omaha Public Power District. 2pp. 47731-227-47731-234.
- ~8612050296 Notice of violation from insp. on 861114-18 Violation noted: four QC accepted flare bevef welds in Mod Packago MR-FC-88 60 Identified on Drawing A 5606 as Wolds VAS-79-7 through VAS-79-10 loss from flush. *Region 4, Otc of the Director 88/12/02 to 47731:220-47731:229. -8812050299 Insp. Rept. 50-285768-43 on 881114-18 One violation & unresolved item
- noted Major areas inspected I censed action on previous insp tridings & structural welding activities GILBERT, L.O., BARNES, Region 4, Ofc of the Director 88/12/01, 5pp. 47731 239. 47731,234.
- 8812060065 Ack receipt of 881115 lin 8 payment of civil penalty in amount of \$50,000 proposed in NAC 881012 lin LIEBERMANUL Circ of Enforcement (Post 870413). 68/12/02 MORFIIS,K J. Omeha
- Public Power District 1p. 47743-013-47743-013
- 8812130127 Forwards Insp. Ropt 50:285/88:42 on 881108 & notice of violation CALLAN, J. Region 4, Otc of the Director 88712702 MORRIS, K.J. Omaha Public Power District. 2pp. 47795:329-47705-335
- -8812130129 Notice of viciation from hispion 881108 Viciation noted (iconsee determined that decontamination prisonned onlined very high radiation area around reactor coolant drain tank w/o continuous coverage by qualified technician.

 * Region 4, Otc of the Director, 88/12/02, 1p. 47795.331-47705.331
- -8812130132 Insp. Rept. 50-285/88-42 on 881108 Violations noted Major areas Inspected radiation protection program including circumstances re unauthorized entry of personnel into posted very high radiation area MURHAY,B., BAER,R.E. Region 4, Old of the Director, 68/11/30, 4pp, 47795,332-47795 335
- 8812090147 Advises that pages included in util 880910 fir changed to include implementation dates 8 status updates to SALP.

 MORRIS,K.J. Omaha Public Power District 98/12/05 Document Centrol Branch (Document Control Oosk) 6pp 47784 005-47784 010
- 8812140069 Forwards Insp. Rept. 50-285/68-39 on 881024-28.No violations or deviations noted. Delicioncy to pipo support design atomitted as unresolved item. CALLANIL J. Region. 4, Old of the Director. 88/12/05. MORRIS, K.J. Omaha Public Power District. 2pp. 47821-092-47821-103.
- -8812140077 Insp Ropt 50-285/88-39 on 881024-28 No violations or deviations noted Major areas inspected design changes, mosts & testing of pipo supports & restraint sys SINGH A. JOHNSON,CE, STETKA,T.F. Region 4, Otc of the Director, 88/12/01, 10pp, 47821-094-47821-103.
- 8812130234 Responds to NRC Bullolin 88.003, "Indiadequate Latch Engagement in HFA Type Latching Relays Mfg by GE." Bullolin not applicable to HFA rulays in use at Bedniy, MORRIS.K.J. Omaha Public Power District. 88/12/07 Document Control Branch (Document Control Desk). 2pp. 47784-082-47794-083
- 8812140214 Forwards Insp Rept 50-285/88 45 on 881114-1814o violations or doviations noted.

 ations noted.

 CALLANL J. Region 4, Ofciol the Oxisotor 88/12/07, MORRIS,K.J. Ornaha Public Power District. 2pp. 47821 084-47821-081.
- ~8812140215 Insp. Rept. 50-285/88-45 on 881114-18.No violations or deviations noted Major areas inspected licensee actions on provious insp findings.complex survallance & local leak rate testing
 MURPHY.M.E., MCKERNON,T.O., SEIDLE,W.C. Region 4, Ofc of the Director, 88/12/
 05. 6pp. 47821:086-47821.091
- 8812020287 NRC Info Natice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svc list encl. ROSSIC E. Dwiston of Operational Events Assessment (Post 870411) 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp 47807.191-47807:302
- 8812150123 Forwards Insp Ropt 50-285/88-44 on 881114-18 No violations or fleviations noted CALLAN,L.J. Region 4, Ofc of the Director, 88/12/08, MORRIS,K.J. Omeha Public Power District, 2pp. 47807:183-47807-150
- -8812150124 Insp. Rept. 50-285/88-44 on 8811114-18 No violations or deviations noted Major areas inspected instrument calibr program & followup on previous NRC insp. findings & reportable events with the Christian Control of the Director 88/12/06 6pp. 47807:185-47807:190.
- 8812140016 Responds to NRC 881107 litire violations noted in Insp. Ropt 50-285/88-37.Corrective actions test equipment togged in test equipment log w/fate entry & re-quiremons to log test equipment emphasized to technic
- 8812200345 Forwards Insp. Rept 50-285/88-29 on 981017-28 No violations or deviations noted buriosolved liem Identified.

 CALLAN,L.J. Region 4, Oic of the Director. 88/12/12. MORRIS,K.J. Omaha Public Power District. 2pp. 47882:292-47862 215
- -8812200346 Insp Rept 50-285/88-29 on 881017-28 No violations noted. Unresolved 881200349 Insp. Hept 50-285/88-29 on 881017-28 No violations noted. Unrescrived item noted Major areas inspected plant mod. & replacement projects,including emergency feedwater storage tank repair. & mods to pressurizer spray sys. KERCH,H.W., HARRIS,R.H., OLIVERI,M.A. Region 1, Otc of the Director. 88/11/29 12pp. 47862-204-47862-215.

- 8812190399 Responds to NRC 881109 ftr re-violations noted in Insp Rept 50-285788-40 Corrective actions weld regain procedure will be developed by Mir. 1989 3 repost of Welds F-33,F45 & F144 will be completed prior to startup for a 1988 nursage MORRISK J. Omaha. Public. Power. District. 88/12/14. Locument. Critict. Branch. (Document Control Desk) 3pp 47851 284 47851 286
- 8812210308 Forwards Insp. Rept. 50.285788-35 on 881003-14 & notice of Viciation Unrosolved item also noted

 CALLANI, J. Region 4, Olic of the Director #8712714 MCPIBIS, K.J. Chiaba Public

 Fower District 2pp 47876.136-47876 156

- -8812210312 Notice of violation from inspiren 681003-14. Violation noted, between 8E0301-0930 procedure changes not revowed during formal committee inclavings & surveillance procedure or main stoam safety valve lest aftered.
 * Region 4, Oto of the Director: 88/12/14, 2pp. 47876 138-47876 139.
- --8812210313 Insp. Rept. 50-285/88-35 on .881003-14 Violations insted Major, creas inspected icensee ontitle plant review committee activities ulfaite is aloty audit. & review. committee activities 8 safety roview group activities.
 HUNTER,D.R., STEWARL, J.P., GAGLIARDO,J.E., Region 4, Old of the Director, 887
 12/07, 17pp, 47876,140-47876,156.

R. Poriodic operating reports & related correspondence

8812200282 Monthly operating rept for Nov 1998 for Fort Callinouri Station Uset 1 W/

MAACK,KiLl, MORRIS,KiJ. Omaha Public Power District 88/11/30, 24pp, 47860 309. 47860.332

S. Reportable occurrences, LERs & related correspondence

- 8811230038 RO on 981001-31 asted line barriers & idelection sys rendered inoperable Fire detection. Zerius 9 8 30 rendered inoperable on 981001 & 05 respectively Restoration within Tech Spec limit could not be accomplished MORRISK J. Omaha Public Power Distinct 80/11/14 Document Control Branch (Document Control Dosk), 3pp. 47652 072-47852 074
- 8811280120 LER 88-028-00-on 881020,farting of YCV-1045A instrument nin check valve.Caused by a metal particle lodged in valve seat Air check valve bench tested & Successfrily passind LEHMAN,L.L., MORHIS,K.J. Ornahn Public Power District, 88711721, 4pp. 47654 162-
- o Fizeutza LEN 88-027-00 on 881020,stoanhiter desabled by heat exhibistion after ex-iting steam generator.Caused by contamination of protective clothing First aid provided & victim taken to hosp for medical treatment W7881122 tit WOODWARD.W.C., MORRIS,K.J. Omeby, Putric, Power, District, 88/11/21, 4pp. 47854-114-47654:117. 8811280124 LERI 88-027-00 on 881020, stoamhiter disabled by frequenciary after ex-
- 8812010347 LER 88-031-00 on 881029 bus-lie brenker (BT-184C) tripped open & de-onorgized 480 volt buses 183C & 183C-4C Caused by excessive leading of buses 183C & 183C-4C Procedure change to OFEE-2B made to caution operators W7 881128 llr

MOLZER,D., MORAIS,K.J. Omaha Public Power District 88/11/28 4pp 47721.001-47721 004

- 8812050334 LER 88-012-01 on 880428 discovered that special rept on fire barrier Ineperability not submitted,per Toch Spec 5.9.3. Caused by millit order not properly tracked & Inadequate procedure controls Procedures changed W/881130 ftr. LEHMAN, LL, MORRIS, K.J. Omaha Public Power District. 88/11/30. 3pp. 47740.097-47740.099.
- 8812070238 LER 88-032-00 on 881101,satoty injection/containment spray rec-roulation piping design deficiency noted Caused by design deficiency in rec-roulation header Minillow host of safety injection pumps performed W/881201 ttr. HOLLINGSED.M.W., MORRIS,K.J. Omaha, Public Power District. 88/12/01. 4pp
- 47745 236 47745 239. 8812130015 LER 08-033 00.on 881103, electrical distribution sys design deficiency noted Sequencing logic for containment spray pumps 8 cooling lans will be modified W/881205 tir.

OLLINGSED,M.W., MORRIS, K.J. Omeha Public Power District 86/12/05. 4pp. 47797:133-47797:136

- 8812130217 Forwards corrected into on untimely submitted of LERs,per 881003 in Correction concerns type re-procedure changed as part of corrective actions &
- when change completed
 MORRIS,K.J. Ornaha Public Power District 88/12/07. Document Control Branch
 (Document Control Desk). 2pp. 47794-128-47794-128
- 8812130224 Follow up special rept to inoperability of fire harrier. Fire doors returned to
- operable status as listed.

 MORRIS,K J. Omalia Public Power District 88/12/07. Document Control Branch (Document Control Desk). 2pp. 47792.153.47792:154.
- 8812140217 PNO-IV-88 094 on 8B1207 onsite release of toxic chloring gas occurred Caused by meding of fusible safety plug in gas cylinder containing approximate 150 lb of chloring gas due to close proximity of hoater to cylinder Cylinder romoved CALLAN, J. Region 4, Otc of the Director 88/12/08 2pp 4/7814 055-4/7814 056
- 8812210277 LER 88-034-00.on 861114,nadvortent actuation of ventilation isolation signal occurred.Caused by high background count rate on radiation amounter RM-050 Alarm resolucional rate on RM-050 monitored & maint order written W/881214 ltr. ROSLONEIC.D.J., MORRIS,K.J. Omaha Public Power District. 86/12/14 4pp 47876-224-47876-227.
- 8612270211 LER 88-029-00 on 881120 unplanned actuation of ventilation isolation actuation signal occurred Caused by increase in background radiation levels due to rating-raphy being conducted in room where Alarm RM-060 located W/081220 It WOODWAHD,B., MORHIS,K J. Omaha. Public Power District. 88/12/20 4pp. 47928 017-47926 020.

V. Operator Examinations

8812010122 Informs that regulal Scalien programs for licensed personnel detailed to Publishing PA reviewed & acceptable
CALLAGL J. Region 4, Ofc. of the Director -88711/28 (MORRIS,K.). Orrata Public
Power District. 2(p): 47702-314-47702-315.

6812200107 Advisors that requelification program evaluation scheduled for wk of 890123 Crew simulator evaluation tentatively scheduled for wk of 870417 at Wickson Locks CT GALLAN,L.J. Region 4, Old of the Director 88/12/07 MORRIS,K.T. Onulla Public Power District. 7pp. 47860-297-47860-303

DOCKET 50-286 INDIAN POINT STATION, URIT 3

H. General correspondence

86 120 10423. Comment on proposed rule 10CFR26 re Filness for Outy Program ULI has constitutional concerns on programd random testing which should his buy activessed poor to role bring promulgated Enderses NUMARC & EEL comments BRONS, IC. New York Power Authority (cornerly Power Authority of the State of New York). 88711718. Decketting & Servicus Branch. 12pp. 47679-282-47679-383.

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 88-20 to all finances holding OLy & CPs for nuclear power reactor facilities re-individual plant usan for severe accident vulnerabilities Svc 1st GRUTCHFIELD,D. Associate Director for Projects (Post 970411). 89711723. Consul-dated Edison Co. of New York, Inc. Alpp. 47728:303-47729.024.
- 8611280163 Forwards SER accepting off responses to Generic Ltr 83-28, Item 2.1, "Equipment Class feature Heactor Trip Sys Components" NEIGHBORS.J.D. Project Directorate 1: 803/11/23 BRONS.J.C. New York Power Authority (formarly Pawar Authority of the State of New York) 3pp. 47657,023-47657,028
- -8811280165 SEH accepting util responses to Generic Ltr 83 28,ttem 2.1, "Equipment Classification Reactor Trip Sys Compensation": Project O rectorate 11-1861/1723 3pp. 47657-026-47657-028
- 8811290420 Summiny of 881115 meeting w/ulil re steam generator tube plugging Attendee list & viewgraphs encl NEIGHBORS.J.D. Project Directorate 1-1, 88/11/23 Project Directorate 1-1, 33pp 47665 189 47665 221
- 8812070235 Requests that util address Generic Ltr 88-17 to fess of DHR during nonpower operation issue of high profits & should be addressed accordingly
 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/
 OZ FLYNN,R.M. New York Power Authority (formerly Power Authority of the State of New York). Opp. 47/46.069-47746.073
- 8812130007 Forwards application for amend to License DPR-64 rovising Tech Spocs re-applicability of action requirements of Friting conditions for operation associated w/ photological account of the pattern of the State of New York. 80/12/02 December Control Branch (Document Control Branch (Document Control Deek). 2pp 47799 137 47799 150
- -8812130069 Application for amend to License DPR-64 revising Tech Specs to clarify applicability of limiting conditions for operation & associated action requirements when surveillance not performed within allowed surveillance interval.

 * New York Power Authority (formuly Power Authority of the State of New York) 88/
- -8812130045 Proposed Tech Spec changes re-applicability of missed surveillance re-

12/02. Ip 47799.139-47795.139

- qurenicats.

 * New York Power Authority (formerly Power Authority of the State of New York) 88/12/02 11pp 47709140-47789150
- 8812070028 Requests remittance of two for 880907 application to review & approve revised mothodology for postulating single passive failures of six water sys piping during post-LOCA rectrectation for facility.her 10CFR170.21 & 12(c) DIGGS.H.M. Liconse Foe Management Branch. 88712705. BHONS.J.C. New York Power Authority (formerly Power Authority of the State of New York). 1p. 47753.067-47753.067.
- 8812130060 Requests robot from Section XI sys pressure & hydrostatic test requirements of ASME Boilor & Precsure Vossel Code actions applicable to first & second 10-yr Insp Intervals of hydrostatic test program Fee spaid BRONS_J C New York Power Authority (formerly Power Authority of the State of New York). 88712706. Document Control Branch (Document Control Desk). 45pp. York). 88/12/06. D 47792 193-47792 237
- 8812130003 Forwards application for amond to License DPR-64, revising limiting condi-
- lion of operation (LCO) for auxiliary feedwater pumps to more closely reflect application (LCO) for auxiliary feedwater pumps to more closely reflect applicable LCO provided by Westinghouse STS Fee paid BRONS.J.C. New York Power Authority (formerly Power Authority of the State of New York). 88/12/08. Document Control Branch (Document Control Desk) 2pp. 47797.137-47797.147.
- --8812139004 Application for amond to Licenso DPR-64 revising finiting condition of operation for auxiliary feedwater pumps.

 New York Power Authority (formetly Power Authority of the State of New York) 887 12709 1p 47797
- --8812130048 Proposed Tech Specs re auxiliary leedwater pumps
 New York Power Authority (formerly Power Authority of the State of New York) 887
 12/08. 8pp 47797:140-47797 147.

Q. Inspection reports, IE Bulletins & correspondence

- 8811180327 Rev 0 to "Indian Point Unit 3 PRA-Based Sys InspiPians" FRESCOIA COPPOLAIA, GUNTHER W. Brookhaven (tational Laboratory, FIN A-3453 A-3453-3 87(-1) RC9 87/03/31 NRC No Detailed Alfulation Given 143pp
- 8811290490 Forwards SALP Rept 50 286/87-99 for June 1987 Aug 1988 RUSSELL,W.T. Region 1, Old of the Director 89/11/21 BRONS J.C. New York Power Authority (formerly Pawer Authority of the State of New York). 2pp. 47850 091-47650 134
- ~8811290496 SALP Rept 50 286/87/93 for June 1997 Aug 1988 * Region 1, Ofc of the Director 88/10/19 42pp 47650 693-47650 134
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Size list encl.
 CUNNINGHAM.R.E. Drus on of Industrial & Medical Nuclear Salety (Post 870729)
 88/11/22 Conscitated Edison Co. of New York, Inc. 99pp. 47709-255-47709-257.
- 8811160467 NRC Into Notice 88:091, "Improper Administration & Control of Psychologic cal Tests: "Svc I stiend ROSSIC E Dws on at Operational Events Assessment (Post 870411) 88/11/22 Conspidated Edison Co of New York, Inc. 101pp. 47708.042-47708.142
- 8812090259 Notification of 881215 Significant Licenses Meeting 88-188 in Buchanan,NY to discuss SALP JOHNSON,JR Region 1, Otc of the Director 88/11/23 Region 1, Otc of the Director 259 47784 344-47784 345
- 8812050216 Forwards inspiresults of 881019 tube leak in Steam Generator 31 After o Advance or numerous inspiresories of Bibliotic tible leak in Steam Generator 31 After completion of plugging operations plant proceeded whyreparations for startup & will run at full power until refueling outage scheduled to begin in Feb 1989. 3-OSIGER WiA Mew York Power Authority (formerly Power Authority of the State of New York) 88/11/28 Document Control Branch (Document Control Desk). 79pp. 47720 131-47720 209.
- 8812060165 Responds to NRC 881103 ltr re violations noted in Insp. Rept 50-286/88-17 Corrective act on taken mail condition has program instituted.

 JOSIGER,W A New York Power Authors; (formerly Power Authority of the State of New York) 88/11/30 WENZINGER,EC Region 1, Ofc of the Director. 4pp. 47741,218.
- 8812120273 Responds to violations noted in Insp Rept 50-286/88-18 on 881031.Corrective actions administrative directives reviewed to address concerns & commits to 890131 submittal of procedures for review & procedures reviewed JUSISER,W A New York Power Authority (formerly Power Authority of the State of New York), 88/11/30 MARSH,L B. Region 1, Ofc of the Director, 6pp. 47769 197-47789 202.
- 8811290030 NRC Into Natice 88-093, "Teletherapy Events" Svc 1st encl CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 670729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811.103.47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list enci ROSS),C.E. Division of Operational Events Assessment (Post 870411), 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708.143.47708.254
- 8812130060 Requests relief from Section XI sys pressure & hydrostatic test requirements of ASME Botier & Pressure Vessel Code editions applicable to first & second 10-yr insp Intervals of hydrostatic test program Fee paid BRONS-LC. New York Power Authority (formerly Power Authority of the State of New York) B8/12/08 Document Control Branch (Document Control Desk) 45pp 47792 193-47792 237.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensbes on Vendors" Svc1 st enci. PIOSSIC E. División of Operational Events Assessment (Post 970411). 88/12/08. Cansolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302.
- 8812270233 Forwards Insp Repl 50-266/88-20 on 881107-10 No violations noted GALLO,R,M. Region 1, Ofc of the Director 88/12/19 JOS/GER,W. New York Power Authority (formerly Power Authority of the State of New York). 2pp 47926-007-47926 016
- --8812270235 Insp Rept 50-286/88-20 on 881107-10.No violations noted. Major areas inspected licensee actions in areas of maint of surveil lance procedures & records that verify component availability to meet Tech Spec requirements. REBLOWSKITA, BLUMBERG, N.J. Region 1, Old of the Director, 88/12/16, 8pp. 47926 009-47926 016
- 8812270273 Forwards Insp Rept 50-286/68-19 on 881018-1201 No violations noted. WENZINGER,E.C. Region 1, Ofc of the Director, 88/12/19 JOSIGER,W. New York Power Authority (formerly Power Authority of the State of New York) 2pp. 47923-346-
- ~8812270275 Insp Ropi 50-286/88-19 on 881018-1201 No violations noted. Major areas inspected shift logs & records, steam generator tube leak followup & corrective actions, temporary instruction RI-86 03, maint & sys welkdowns. JOHNSON, J.R. Region 1, Ofc of the Director. 88/12/15, 12pp. 47923:348-47923:359.

S. Reportable occurrences, LERs & related correspondence

8811300221 Special rept on 881020 pressurzer power operated relief valve actuation occurred Caused by tomp lines on graph RCS-3B being combination lines Procedure SOP-CVCS-6 being revised.

JOSIGER,W.A. Now York Power Authority (formerly Power Authority of the State of New York). 88/11/18. Document Control Branch (Document Control Desk). 3pp. 47671:222-47671:224.

U. Congressional/Executive Correspondence

8811300286 Responds to 881020 ftr re operation of plants to lowing steam generally leak at Indian Point 3 NRC evaluated event & concluded that no immortate safety concerns warrant shuldown of tankhos ZECHL W Commissioners 88/11/23. Git,MAN,B.A. House of Rep. 2pp. 47658.313.

47669 125

-8811300290 Requests rept on steam generator release incident at Unit 3 & overell safety of plant Plant should be shut down until public safety absolutely assured GILMAN_BA House of Rep. 88/10/20 ZECHL A Commissioners 3pp 47659 123.

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8812050130 Forwards public version of Rev 88-2 to emergency plan, Vol A & Revs 93 5 8 88-8 to implementing procedures manual, Vols B & C respectively W/DH Ginestes release memo
 - TUCKER.H.B. Duke Power Co. 88/11/10. Document Control Branch (Ducument Control Desk). 5pp. 47719:180-47720:066.
- ~8812050131 Rev 88-2 to plant emergency plan,Vol A TUCKMAN,MS Duke Power Co. 88/10/14 87pp, 47719.185-47719.272
- -8812050132 Revised emergency plan implementing procedures inclining Roys 86 6 8 88 to implementing procedures emergency plan inanual V05 B & C, respectively TUCKMAN,M S Duke Power Co 88/10/14, 154pp, 47719 273-47720 GC
- 8812090029 Forwards public version of Rnv 28 to "Crisis Mgt Plan" W/ DH Grins'ey undated release memo TUCKER,H.B. Duke Power Co. 88/11/22 Dricument Control Branch (Document Con trol Desk) 4pp 47757:171-47757.215.
- →8812090034 Public version of Rev 28 to "Crisis Mgt Plan for Nuclear Stations." * Duke Power Co. 88/12/01 41pp. 47757:175-47757-215
- 8812080243 Advises that 880929 Rev 6 to goard training & quablication plan consistent w/provisions of 10CFR50 54(p) & acceptable CLINE WE Region 2, Oto of the Director, 88/11/29, TUCKER,H.8, Duke Power Co 2pp. 47783,269-47783.270
- 8812090085 Forwards environ assessment & finding of no significant impact reluling 31111 request for exemption from requirements of 10CFB59.App R PASTIS,HN Project Directorate II-3 88/12/05 TUCKER,HIB. Duke Fewer Co. 3pp
- -8812090087 Environ assessment & Inding of too sughillcont impact rejurt 831111 m-quest for exemption from requirements of 1005/H50,App R MATTHEWS,D B. Project Directorate II-3 (88/12/05) 5pp. 47762,239-47762;243
- 8812200232 Advises that 881014 Roy 88.2 to tathological emergency plan consistent w/planning stds of 10CFR50.47(b) & acceptable. Change is implementation consistent w/Rog Guide 1.23. DECKER, R.R. Rog on 2, Old of the Director, 88/12/12, TUCKER, H.B., Disko Power Co. 2pp. 47868 302-47868 303.

H. General correspondence

8812090335 Confirms meeting w/ut1 on 881209 at Region II ofc re-reorganization.per 881121 telcon. ERNST.M.L. Region 2, Oic of the Director, 88/12/01, TUCKER,H.B. Duka Power Ca 1p. 47782 231-47782:231.

P. Operating Roanse stage documents & correspondence

- 8811290197 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embratisment of Reactor Vessel Matte & Its Impact on Plant Operations "TUCKER,H.B. Duke Power Co. 68/11/21. Document Control Branch (Document Control Desk). 2pp. 47649:197-47649.198.
- 8811280196 Discusses NRC response to 88W Owners Group on ATWS Issue. Licensed requested to submit plant-specific conceptual design for option artected among three options considered in anci NRC ltr.
 PASTIS,HN Project Directorate II-3. 88/11/22. TUCKER,H.B. Duke Power Co. 4pp.

47656-310-47656.318

- 8811280048 Generic Lift 88:20 to all liconsees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnorabilities Svc list enct. CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consol-dated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 8812020315 Discusses with 881107 ftr re-problem of Leo Steam Station supporting sud-denly applied emergency loads during unavailability of Koowee hydroelectric genura
 - tors.
 MATTHEWS.D.B. Project Directorate II-3, 88/11/23, TUCKER,H.B. Duke Power Co.
 3pp. 47711:117-47711:119.
- 8812070012 Forwards response to NRC 880920 request for addl info re application for amends for Licenses DPR-38,DPR-47 & DPR-55, adding requirements to standby shutdown facility-Motor operators to be added to valvos in auxiliary svc water sys. TUCKER.H B. Duke Power Co. 88/11/28. Document Control Branch (Document Control Dask). 6pp. 47746:092-47746.097.
- 8812010274 Forwards Suppl 2 to safety evaluation re simulator modelling of upper head volding per 880718 ltr.

 PASTIS,H.N. Project Directorate 31-3. 88/11/28. TUCKER,H.B. Duke Power Co 2pp.
 47707:093-47707:095.

- -8812010275 Safety evaluation supporting response to simulator modeling of upper tread voiding
 * Project Directorate II 3 88/11/29 Tp. 47707.095-47707.095
- 8812080080 Requests that util address Generic Ltr 80-17 rd toss of DHR during non-power operation Issue of Ingh priority & should be addressed accordingly. MURLEY/TE Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/ 02 LEEW'S Duke Power Co. 5pp. 47753 129-47753 133
- 8812080027 Responds to 860908 fit requesting NRC concurrence on util understanding of App H. "Reactor Vessel Mall Service ance Program Requirements." Separate cavity
- Observotiving a latin for each unit unwarranted MATTHEWSD 8 Project Directorate II-3 88/12/05 TUCKER,H B Cuke Power Co 4pp 47783 243-47783 246
- 8812120012 Forwards "Emergency Dosu Assessment Manual"
 TUCKER,HB Duke Power Co. 88/12/07 Document Control Branch (Document Control Desk) 3pp. 47700.219-47781.120
- --8812120014 "Duke Power Co. Enlergency Dose Assessment Manual." TUCKERTHB: Duke Power Co. 88/11/21, 259pp, 47780-222-47781-120.
- 8812210063 Forwards Request for Relief 88 09 from Section XI of ASME Boiler & Pres-
- sure Vessel Codo (w/addonta though Winter 1980) to prossure testing specific wolds during second 10-yr inservice inspiritorya Wigne oversize drawing TUCKER,H.B. Duke Power Co. 88/12/09. Discurrent Control Branch (Document Control Branch (Document Control Branch)
- trol Dusk) 4pp 47887 151-47887 155 8812210114 Application for amonds to Licenses DPR-38,DPR-47 & OPR-55, providing adequate standby hos vollage for all design basis accident scenarios Fee paid TUCKER,HB, Duko Power Co. 88/12/15, Eocuriont Control Branch (Document Con
- trol Dask) 3pp 47888 276 47888 289 -8812210115 Proposed Tech Specs to standby bus voltage for all design basis acci-
- dent scenurios
 * Duke Power Co. 80/12/15, 11pp, 47888.279-47888.289
- 8812220310 Informs that um 880525 response to Generic Lir 88-03, "Steam Binding of Auxhary Feedwater Pumps" ucceptatio NRC disagraemant w/ull conclusion that procedures addressing steam binding of emergency feedwater pumps unnecessary PASTS, H.N. Project Directorate II-3 (BR/12/19) LUCKER, H.B. Duke Power Co. 4pp 47003 072 47903.075

Q. Inspection reports, IE Bulletins & correspondence

- 6611180260 Forwards risk-based inspiguidus described in mods to InspiManual Chapter
- 2515 W/o onc's LONG,SM Risk Applications Branch 88/11/16 LANHAM,D Document Control Branch (Document Control Desk) 1p. 47597,114-47601.019.
- 8811290559 Ack receipt of 680909 fir informing NRC of stops taken to correct violations noted in losp Repts 50 269789 11, 50-27078-11 & 50-287789-11. ERNST,M.L. Region 2, Old of the Director. 88/11/17. TUCKER,H.B. Duka Power Co. 1p. 47662:200-47662.200
- 8811160211 NRC Info Notice 88 090, "Unauthorized Removal of Industrial Nuclear
 - Gauges " Svc list end. CUNNINGHAM,R.E. Ovision of Industrial & Modical Nuclear Safety (Post 870729). 88711722. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811160467 RRC Into Notice 98-091, "Improper Administration & Control of Psychological Tests" Svc list and ROSSICE Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708:142.
- 8811300145 Responds to NPC 881024 ftr re-violations noted in Insp Ropts 50-269/88-31,50-270/88-31 & 50-297/88-31 Corrective actions: roted in Insp. Hopts 50-289/88-31,50-270/88-31 & 50-297/88-31 Corrective actions: Procodure HP/O/B/1009/57 mod flod to include specific task of sampling mani condenser offgas. TUCKER,11.B. Duke Power Co. 98/11/23. Document Control Branch (Document Control Desb). 3pp. 47677-023-476/77-025
- 8812050280 Forwards Insp. Rupts 50.269/08-33,50-270/88:33 & 50-287/88:33 on 881015-1115 No violations or deviations noted BROWNLEE,V.L. Region 2, Oic of the Director 88/11/23. TUCKER,H.B. Duke Power Co. 2pp. 47731:235-47731:250
- --8812050282 Insp. Ropts 50:289/88:33,50:270/88:33 & 50:287/88:33 on 881015-1115 No violations or deviations noted Major areas inspected operations, surveillance tosting, maint activities, safeguards & radiation protection & Insp. of open Items. SKINNER,P.H. Rogion 2, Old of the Director, 88/11/23, 14pp. 47731:237-47731:250
- 8812050312 Ack roce pt of 881028 ftr informing NRC of stops taken to correct violations roted in Insp Rept 50-269/88-28 Response to Violation 267/88-29-02 did not address actions taken to improve effectiveness of test program ERNST.M 1. Region 2, Ofc of the Director 88/11/25, TUCKER,H.B. Duke Power Co. 1p. 47740:122-47740:122
- 8812050072 Advises that use of ASME Codo Cases N-401,N-416,N-426 & N-427 in in-service linsp program approved.por 880302 request. MATTHEWS,D.B. Project Directorate II-3, 88/12/01, TUCKER,H.B. Duke Power Co. 7pp. 47734-020-47734-028
- 8812060018 Forwards revised response to NRC 881028 fir re violation noted in Insp. Repts 50:269/88-28,50:270/88-28 & 50:287/88-28.Corrective actions:test procedure revised to require legs to be placed on removed control power fuses.

 TUCKER,H.B. Duke Power Co. 88/12/01. Document Control Desk). 4pp. 47741.056-47741.059.
- 8812120118 Provides action status update re NRC Bulletin 88-004, "Potential Safety-Related Pump Loss "Migs confacted re-anticipated response time after 890601. TUCKER, H.B. Duke Power Co. 88/12/01. Document Control Branch (Document Control Desk) 2pp. 47791.339-47791.340.
- 8811290030 NRC Info Notice 88-093, "Toteltherapy Events" Svc list enct. CUNNINGHAM,R.E. Dwiston of Industrial & Medicel Nucleor Selfety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.

- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Adjustors." Svc 1st GOSSI,C.E. Div.sion of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254
- 8812120117 Responds to NRC 881102 tir re-violations noted in Insp Repts 50-269/88-32.50-270/88-32 & 50-287/89-32 Corrective actions, craft personnel & suppresors caulioned against applying pressure to any line w/o engineering knowledge TUCKER,HB Duke Power Co. 88/12/02 Document Control Branch (Document Control Branch (Document Control Branch) trol Desk) 3pp 47789 107-47789 109
- 8812070149 Informs that util 980307 response to NRC Bulletin 88-001, "Dofects in Wostinghouse Circui Breakers," satisfactory PASTIS,H.N. Project Directorate II/3 86/12/05 TUCKER,H.B. Duke Power Co. 2pp. 47746-247-47748-248
- 8812140200 Forwards info re inservice msp & tubo plugging/repair operation for end of Cycle 10 refueling outage completed on 880907.per Toch Spec 4.17.6(a) Lists of tubes having oddy current Indications of degraded tubes end TUCKER,H B. Duke Power Co. 88/12/07. Document Control Desk). 11pp. 47824-088-47824-098.
- 8812150198 Requests resubmittal of response to violations noted in Insp. Repts 50:269/ 88.13.50:270768-13 & 50:267768-13 Ut.I 880902 response to Violations A,B,D,E,1 & C re Valve HP-98 meet 10CFR2 201 requirements Violation E 2 requires resubmittal GIBSON.A.F. Region 2, Otc of the Director: 88/12/07. TUCKER,H.B. Duke Power Co. 4pp. 47826-319-47826-322
- 8812200099 Forwards inservice inspirent for and of Cycle 10 refueling outage,per Tech Spec 4.2.8 ASME Code Section XI W/o and. TUCKER,H8 Duke Power Co. 88/12/07. Document Control Branch (Document Con-trol Desk). 1p. 47871
- 8812020287 NRC Into Notice 88-085, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" "Svc list encl. ROSSLC E. Division of Operational Events Assessment (Post 870411). 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807.302.
- 8812140122 EN-88-105 notice of violation & proposed imposition of civ.l penalty in amount of \$25,000 will be issued on 881213. Action based on liceusee failure to provide addequate procedural guidance to ensure HPSI remain operable. LUEHMANU, Orc of Enforcement (Post 870413). 88/12/08 1p. 47800.213-47800:213.
- 8812210063 Forwards Request for Relief 88:00 from Section XI of ASME Boiler & Pressura Vossel Codo (w/addenda through Winter 1980) to pressure testing specific welds during second 10-yr Inservice Insp Interval W/one oversize drawing.
 TUCKER,14 B. Duke Power Co. 88/12/09. Document Control Branch (Document Control Desk). 4pp. 47887:151-47887:155
- 8812210326 Responds to NRC 881110 ltr re-violations noted in thisp Repts 50:269/88-17,50:270/88-17, & 60:287/88-17.Procedures MP/O/A/2001/13 & MP/O/A/2001/3C revised to include proper resistance/torque values & specify proper lubricant.

 TurkeR.H.B. Duke Power Co. 88/12/09. Document Control Branch (Document Control Dosk) 0pp. 47877:248-47877.255
- 8812200307 Discusses violations noted in Insp Repts 50-269/88-25, 50-270/88-25 & 50-297/88-26 on 880801-15 & forwards notice of violation & proposed imposition of Solvent Constitution of the Director B8/12/13: TUCKER,H.B. Duke Power Co. 4pp. 47868.066-47868.089.
- 8812210068 Ack receipt of 881123 fir informing NRC of step taken to correct violations noted in Insp Repts 50-269/88-31, 60-270/88-31 & 50-287/88-31. Violation occurred as stated in notice of violation. COLLINS,D M. Region 2, Otc of the Director. 88/12/14, TUCKER,H.B. Duke Power Co. 1p. 47878 219-47878:219.
- 8812270207 Forwards addl performance test & analysis info,por request during 881104 enforcement conference re-potential dograded capabilities of reactor bldg cooling units (RBCU) Further info ro-RBCU & LPI coolor operability critoria also encil TUCKER,H.B. Duke Power Co. 88712/15. Document Control Branch (Document Contr
- trol Dosk). 11pp. 47924:213-47924:223

R. Periodic operating reports & related correspondence

- 8812200212 Forwards monthly operating repts for Nev 1988 for Oconee Station Units 1.2 & 3 & corrected monthly operating ropts for Oct 1988.
 TUCKER,H.B. Duke Power Co. 88/12/15. Document Control Branch (Document Control Desk). 1p. 47861:003-47861:019.
- -8812200297 Monthly operating ropts for Nov 1988 for Oconee Station Units 1,2 & 3, WILLIAMS,R A. Duke Power Co. 88/11/30, 14pp. 47861;004-47861;018.
- --8812200301 Addenda to monthly operating ropt for Nov 1988 for Oconee Nuclear Station Units 1,2 & 3

S. Reportable occurrences, LERs & related correspondence

Duke Power Co. 88/11/30, 1p. 47861:019-47861:019.

- 6812070064 Advises that listed Tech Spec changes committed to in LER 269/68-06 re inadequate design analysis of HPIS in ECCS sump recirculation mode will be submitted by 890228.
 TUCKER,H.B. Duke Power Co. 88/12/01. Document Control Branch (Document Con-
- trol Desk). 1p. 47746:248-47746:249
- 8812220046 Informs that LER 287/88-06 to three reactor trips on 681114 in preparation TUCKER,H.B. Duke Power Co. 88/12/14. Document Control Branch (Document Control Desk). 1p. 47893:001-47893:001.

- 8812270261 Actuses of iconsequed son rior to install devitating senting 8 to pursue other latting trusper into suppliers into latting to LER 109798 for included accounting to Energy regional ripping special qualitied. TUCKER 19 18 Edition Power Co. Sent 2716. Document Control Branch (Document Control Desk). 26p. 47672,355,37922,356.
- Y. Dry Cask Independent Spent Fuel Storage Installations
- 8812130117 Forwards responses to NRC 689727 quostions reliabilities sa application
 - TUCKER HB: Dura Power Co. 85/11/23 Document Control Brauch (Document Control Des). 322op. 47793 (00.47794)581

DOCKET 50-288 REED COLLEGE RESEARCH REACTOR

V. Operator Examinations

- 8812140138 Forwards revised agenda for annual operator Idensing meeting schaduled on 490110 Wzg and PATE RJ Region 5, Old of the Director 88712765 RUSYL Reed College, Portland, OR, up 47606 197-47800 197

DOCKET 50-203 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8812220380 "TMI Annual Emergency Exercise" " General Poth's United Corp. GPU Service Corp. 88/11/16, 400pp. 47907 189-47909 255
- 8812020142 Forwards Amend 146 to License DPR-50 & safety evaluation. Amend removes details of TMI fire protection program from Yech Speciper Generic Etris6-10 & revises Condition 2 ci4. HERRANLR W. Project Directorate 14. 88/11/30. HUXILL, H.D. General Public Utilities Corp. GPU Service Corp. 2pp. 47710 349 47711 307.
- -8812020151 Amend 148 to License DPR-50 ramoving details of TMI the protection program from Tech Speciper Generic Lin 66-10 & rowsing Condition 2 c.4. STOLZ, JF Project Directorate I/4 88/11/30 14pp 47710 351-47711 004
- -8912020158 Safety evaluation supporting Amend 146 to License DPR-59 * Officer of Nuclear Reactor Regulation, Director (Post 870411) 66/11/20 Opp 47714-005-47711-005-47711-005
- 8812130177 Forwards application for amend to Ucense OPR-50,consisting of Tech Spec Change Request 188 removing restriction it at offsite personnel shall be ut fixed to perform annual fire protection & less prevention program into 8 audit Fee paid HUKILL,HID General Public Utilies Corp. 1 GPU Service Corp. 88/12/02 Decument Control Branch (Document Control Desk). Spp. 47796-059-47798-066.
- -- 8812130180 Apphication for amend to License DPR-50 consisting of Tech Spec Change Request 188 removing restriction that offsite License personnel shall be utilized to perform annual fire protection & loss prevention program map & audit HUKILLHD General Public Utilines Corp GPU Service Corp 88/12/02 2pp 47798.064-47796.065
- -8812130221 Proposed Tech Specs Page 6.8.consisting of Change Request 18876 moving restriction that I censee personnel shall be unitzed to perform annual five protection & loss prevention program has 8 audit.

 General Public Utilities Corp. GPU Service Corp. 86/12/02 1p. 47796.066-47796.066
- 88 12 120 199 Forwards Annual Emergency Preparedness Exercise Insp Repl 50-289/88-27 on 881115-17 No violations noted BELLAMY, RR Regan 1, Old of the Director. 88/12/05 HUKILL, ND. General Public Utilities Corp. GPU Service Corp. 2pp. 47787 097-47787.103.
- ~8812120201 Insp. Rept. 50-289/88-27 on 861115-17.No violations or deviations noted Major areas inspected consee parial participation annual emergency preparedness exercise conducted 881116 FOX.EF. LAZARUS.W.J. Region 1, Otc of the Orector, 68/11/28 Spp. 47787:093-47787:103.
- 8812210168 Forwards FEMA & Regional Assistance Committee final exercise rept of offsite emergency preparedness plans for facilities Descrences noted nonparticipation of Lower Paston Township & distribution of dostinetry hits KRIMM-R.W. Federal Emergency Management Agency, 98/12/12 CONGEL.F.J. Distribution of Redietion Protection & Emergency Preparedness (Post 870411) 1p. 47888-120-47888-212
- -8812210173 "FEMA & Regional Assistance Committee Exercise Rept of 871022 Exerciso."
 • Federel Emergency Management Agency 88/11/04, 92pp. 47888.121-47888.212
- 8812220185 Temporary Chango Notice 1-88-0120 to Rev 0 to Emergency Plan Implementing Procedure 9471-ADM-1300 01, "Maintaining Emergency Preparedness."

 General Public Utilities Corp. GPU Service Corp. 88/12/12 7pp. 47892 233-47892 239.
- 8812220400 Forwards partially deleted Physical Safeguards Insp Repts 50:289/88:01 & 50:320/88:18 on 881114:17 (ref. 10CFA73:21) No violations observed Steps taken to correct woldstons noted in NRC 841213,850603 & 18 lits siss verified BELLAMY, R.R. Region 1, Ort of the Director, 88/12/12, HUK'LLH U. General Public Utilities Corp. GPU Service Corp. 3pp. 47903:298-47903:308.
- -881222040.1 Partially withhold Physical Security Insp. Repts 50-289/88-31. 8. 50-320/88-18 on 881114-17. No violations noted Major areas inspected unresolved items & inspector followup name, ingl support & security program plans. SMITHG C., CAMERON, D.F., KEIMIG,R.R., Region 1, Dic of the Director, 88/12/09. 8pp. 47903-301-47903-308.

H. General correspondence

- 8811309222 Forwards I, Drey IIIr in delay which has occurred in connection of hadder hip tools from TMI.

 CLAY, WI House of Rep 89/10/31 ZECITLLW Commissioners 1; 47709.011
- -8811300224 Finquests into about incidents that have occurred during four in stripment of TMI faul & about related concerns.

 DREY,K. Affugion Not Assigned 88/09/29. COWGH.L.C.J. Flegion 1, 6 rector 6pp. 47703.012-47709.019.

P. Operating ficense stage documents & correspondence

- 8811300430 Informs that B&W Owners Group generic design for ATWS pled to facility sairst as 881066 fit & intent of ATWS rule Robertus in gram with reprove dearter trip sys operation & improved plant response to HUNKLLIN Connect Public United Corp. 807177 Control Branch (Document Control Desk), 26pp. 47671.196.47671.221
- 8811290425 Advisos that integrated schedule ABC List update in compliance parning program & acceptative STOL7 J.F. Project Directorate 14, 88711722 LONG,RIL General Public GPV Service Corp. 2pp. 47648 216-47648-217.
- 8811290443 Documents NRC 880629 agreement w/util re Instabilities in storage tank level indication & low-low-level alarm New level indication requirements HERNAN R.W. Project Directorate I-4, 60/11/22, HUKILL,H.D. General F. Corp. - GPU Service Corp. 2pp. 47646-191-47646-192
- 8812010178 Notification of 881214 meeting within Reckville,MD to disc actions at plants
 HERNAN,R W. Project Directorate 1-4, 88/11/22, STOLZ,J.F. Project Di
- 4ρρ. 47703 112-47703 115. 8911280048 Generic Ltr 88-20 to all ficensess holding OLs & CPs for in reactor facilities re-individual plant exam for severe accident vulngrab
- ONC.. CRITICHFIELD,D. Associate Director for Projects (Post 870411) 88711 dated Edison Co. of Now York, Inc. 81pp 47728:393-47729 024.
- 8012020142 Forwards Amend 140 to License DPR-50 & safety evaluation moves details of TMI tire protection program from Tech Specifier General House Condition 2 c 4
 HERNAN,R W. Project Directorate 1-4 -08/11/30; HUKILL,H.D. General F
 Corp. - GPU Service Corp. 2pp. 47710.349-47711.007.
- ~8812020151 Aniond 146 to Licensin DPR-50 removing details of TMI in program from Tech Speciper Generic Lir 86-10 & revising Condition 2 c 4 STOLZ J.F. Project Directorale I-4 88/11/30, 14pp 47710.351-47711.00
- -8812020158 Solidy evaluation supporting Amend 146 to License DPR-50.

 * Office of Muclear Reactor Regulation, Oractor (Post 870411), 88-4711 (05-4711 (07).
- 8812080029 Requests that util address Generic Ltr 88-17 to toss of DISF power operation
 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870
 02 CLARK,P.R. General Public Utilities Corp. + GPU Service Corp. 2pp
- 8812130177 Forwards application for amend to License DPR-50 consists Spec Changa Ruquest 188 removing restriction that offeth personnel shift to perform annual fire protection & loss prevention program insp. & audit F HUKILL, H.D. General Public Utilities Corp. GPU Service Corp. 86/1270 Control Branch (Document Control Desk). 5pp. 47796.059-47786.066.
- --8812130180 Application for amond to License IDPR-50, consisting of Charge Request 188, removing restriction that offsite ficensee personnel fized to perform annual free protection & loss provention program loss & a HUKILL H.D. General Public Utilities Corp. GPU Service Corp. 88/ 47796.064-47796.065
- -8812130221 Proposed Tech Specs Page 6-8 consisting of Change Rud moving restriction that licensee personnel shall be utilized to perform an tection & loss prevention program insp & guidi.
 General Public Utilities Corp. GPU Servico Corp. 68/12/02. 1p. 47796.066
- 8812120107 TMI-1 Cycle 7 Startup Ropt." W/881205 ltr. HUKILL.H.D. General Public Utilities Corp. GPU Service Corp. 887/ 4778825-47788.291
- 8812190062 Forwards Amend 147 to License DPR-50 & satety evaluation, porates requirements for operability & calibr frequencies for reactor cool trending sys in Tech Specs,por NUREG-0737,ltom II.F.2.

 HERNAN,R.W. Project Directorate I-4. 88/12/13. HUKILL,H.D. General F. Corp. GPU Servico Corp. 2pp. 47850-255-47650-276
- -8812190074 Amend 147 to License DPR-50.Incorporating requirements to a calibr traquoncies for reactor coolant inventory fronding sys in Tech Spr STOLZ, J.F. Project Directorate I-4, 88/12/13, 8pp. 47850:257-4/850.264.
- -9812190077 Safety evaluation supporting Americal 147 to Elecense DPR-50.
 Office of Nuclear Reactor Regulation, Director (Post 870411), 88, 47850 285-47850 287.
- -8812190081 Final salidty evaluation supporting Amend 147 to License D strumentation to detect inadequate core cooling *Office of Nuclear Reactor Regulation, Director (Post 870411), 88 47850 268 47850 276

8812220239 Advises that this should maintain records of boric acid leakage monitoring & preventive maint program per Generic Ltr 88-05 to boro acid corrosion of carbon steet reactor boundary components in PWRs
HERNAN,R W Project Directorate 1-4, 88/12/15, HUKILL,H D. General Public Utilities
Corp. - GPU Sorvice Corp. 2pp. 47900 202-47900 203

Q. Inspection reports, IE Bulletins & correspondence

- 8812140176 Advises that plant does not use Westinghouse Series DS circuit treakers, or NRC Bulletin 88-001, "Defects in Westinghouse Circuit Broakers" HUKILLHD. General Public Utilities Corp. GPU Service Corp. 88/04/04 RUSSELL,W.1. Region 1, Old of the Director 1p. 47800.160-47800.160
- 8812080143 Responds to violations noted in Insp. Rept. 50-289/68-17. Corrective actions Procedure 1401-14 rowned to correct forque value effective 860920 HUKILLH D. General Public Utilities Corp. GPU Service Corp. RUSSELLW T Region 1, Ofc of the Director 5pp 47783 229-47783 233 88/11/21
- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list encl CUNNINGHAM,R.E. Division of Industrial 8 Medical Nuclear Safety (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708-255, 47708-257.
- 8811160467 NRC Into Notice 80-091, "Impreper Administration & Control of Psychological Tests" Svc list onci ROSSI,CE Division of Operational Events Assessment (Post 870411) 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708-042-47708-142.
- 8811290030 NRC Info Notice 88-093, "Telethorapy Events." Svc list oncl. CUNNINGIAMA E. Division of Industrial & Modual Nuclear Safety (Post 670729) 88/12/02 Consolidated Edison Co. of New York, Inc., 12pp. 47811:103-47811
- 8811280538 NRC Info Notice 80-094, "Potentially Unitersized Valva Actuators." Svc list ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708:254
- 8012120190 Forwards Annual Emergency Preparedness Exercise Insp Rept 50-289789 27 on 881115-17 No violations rated BELLAMY,R.R. Ragion 1, Olc of the Oroctor, 88/12/05, HUKILL,H.O. General Public Ulritos Corp. - GPU Service Corp. 2pp. 4//87 097-47787-103
- +8612120201 Insp. Rept. 50-289788-27 on 861115-17.No violations or deviations noted Major areas inspected licenses partial participation annual umergency prepared ness exercise conducted 881116 FOX.E.F., LAZARUS,W.J. Region 1, Old of the Director 88/11/28 5pp. 47787:009 47787:003
- 88 12020287 NRC Into Notice 88:095, "Inadequate Procurement Requirements Imposed by Licensees on Vandors:" Svellist and ROSSI,CE, Division of Operational Events Assessment (Post 870411), 88/12/08 Consolidated Edison Co. of New York, Inc. 112pg., 47807:191-47807.302.
- 8812220400 Forwards partially defeted Physical Safeguards Insp Repts 50-289/98-31 & 50-320/88-18 on 081114-17 (rof. 10CFR73.21) No violations observed Stups taken to correct violations noted in NRC 841213,850803 & 18 firs also verified BELLAMY,R.R. Region 1, Otc of the Director. 88/12/12 HUKILL,H.D. General Public Utilities Corp. GPU Service Corp. 3pp. 47803.298-47903.308.
- -88.12220401 Partially withhold Physical Security Insp. Ropts 50-209/88-31 & 50-320/88-16 on 861114-17 No violations noted Major drens inspected unresolved items & inspected followup Items, maj support & security program plans. SMITH G C., CAMERON, D F., KEIMIG, R.R. Reg on 1, Ofc of the Director 88/12/09 8pp. 47903 301-47903 308.

R. Periodic operating reports & related correspondence

- 8811300519 Forwards TMI monthly status ropt for 881007-1105.

 COWGILL, C.J. Region 1, Oto of the Circotor 88/11/15. BETTENHAUSEN, L. Rug on 1, Oto of the Director. 7pp. 47670.111-47876.117.
- 8812200174 Monthly operating rept for Nov 1988 for TMI-1.W/881215 fir.
 SMYTH,C.W., HUKILL,H.D. General Public Utilities Corp. GPU Service Corp. 88/11/30. 6pp. 47867:314-47867:319.

S. Reportable occurrences, LERs & related correspondence

- 8812020136 LER 88-006 00 on 881030 high RCS pressure reactor trip due to main turbino EHC mathunction Caused by rapid closure of main turbine control valves two components replaced upon troubleshooting & relay within EHC replaced W/881128 ltr. HASSLER.D.V., RUMILLI,H.D. General Public Utibines Corp. GPU Service Corp. 88/11/28, 4pp. 47710-345-47710.348
- 8812270288 PNO-1-88-126.on 881215.plant shutdown in excess of 48 h to investigate cause of high flow in Number 1 soal teak-off line for reactor coolant pump 1D.Damaged O-ring found & replaced Outage expected to last 7-8 days Press in-
 - JOHNSON,D., BETTENHAUSEN,L. Rogion 1, Ofc of the Director. 88/12/18. 1p. 47928.006-47928.006

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8811230077 Responds to 881017 ltr re plunt & status of offsite emergency preparedness for town of Plymouth,MA.Plant will not restart until NRC satisfied that plant can be operated safety. V Stello 881102 mome and SECHLUW. Commissionors 88/11/17. HADFIELD.J.D. Plymouth, MA. 4pp.

47657 233 47657:242

- --9811230088 Commints on "under advisement" volo of NRC on 881014,which would have given permission to restart plant/NRC should contact author for current 8 up-to-date assessment of where Plynouth Is an planning process.
 HADFIELD J.D. Plynouth, MA 88/10/17, ZECH,L.W. Commissioners. 1p. 47657.242-47657 242
- 8812010210 Requests placement of and 881115 mento & ends to PDR. BATES,A. Operations Branch 80/11/18. SHELBURNE,B. Public Document Branch by 47698 344-47698 344.
- --8811210016 Discusses plant progress in area of emergrancy preparedness, per Commission 881014 moding All restart open items resolved & plant considered physically ready for realiert w/ exception of toose holls for supports Related into encl. STELLO,V. Ofc of the Executive Director for Operations. 88/11/15. ZECH, ROBERT, CARR Commissioners. 35pp. 47743.325-47744.045.
- --8811210029 Forwards lables identifying speakers, affiliation & general emergency pre-paredness sult area discussed during meetings between NRC & public, local & Com-monwealth of MA officials Meetings listed CONKLIN,C. Region 1, Olicid line Director. 88/11/01. LAZARUS,W. Region 1, Olicid. the Director 19pp 47744 014-47744 032.
- --9811210031 Summary of 881027 moeting w/civit delenso officials of town of Carvor in Carvor Town Hall rolemangerity plans, implementing procedures & facilities. LAZARUS,W. Region 1, Ofc of the Circutor HOGAN,R. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/11/01 RUSSELL,W. Region 1, Ofc of the Director. 3pp. 47744/033-47744/035
- -8811210036 Summary of 881026 meeting w/civil defense officials in town of Duxbury ro status of emergency plans, implementing procedures & facilities LAZARUSW, Region 1, Oto 4 the Director (HOGANAR Office of Nuclear Reactor Regulation, Director (Post 870411) 88/11/01, RUSSELL,W. Region 1, Oto of the Director (Post 870411) 88/11/01, RUSSELL,W. Region 1, Oto of the Director (Post 870411) 88/11/01. rector 4pp. 47744 036-47744 039
- ~8811210039 Summary of 681026 meeting w/civ1 defends officials in town of Kingston residus of intergency plans, importing wron't reterice officials in town of Kingston residus of intergency plans, imprementing procedures & facilities LAZARUS,W. Region 1, Ofc of the Director HOGAN,R. Office of Nuclear Reactor Ruguration, Director (Post 870411), 88/11/01. FlUSSELL,W. Region 1, Ofc of the Director 6pp. 4/744-040-4/744-045.
- ~8611210042 Summary of 881025 meeting w/civil defense officials in town of Plymo.ith related of congruency plans.implementing procedures & facilities 1.47AHUS,W Region 1. Otc of the Director. HOGAN,R Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/01 RUSSELL,W. Region 1, Otc of the Director 4pp 47/44.046 4/741 049
- ~8811210045 Summary of 881028 meeting w/civil defense officials in town of Taunton or status of emergency plans implementing procedures & fachines (AZARUS W. Region 1, Oto of the Oroctor (IGCANR, Office of Nuclear Reactor Regulation, Director (Post 870411) 88/11/01 RUSSELL,W. Region 1, Oto of the Director (Post 870411) 88/11/01 RUSSELL,W. Region 1, Oto of the Director (Post 870411) rector. 26pp 47744 050 47744:145.
- --8811210067 Forwards Itr from till & "Evacuation Time Estimates & Butch Population Sheltoring," "Mohiting Impaired" & "Special Facilities," for review & consideration W/ BELLAMY,R R Rogion 1, Old of the Director (87/08/12 THOMAS,E A Federal Emergency Management Agency, 2pp. 47744:148-47744.180
- ~8811210070 Roy 0 to "Pilgrim Station Evacuation Time Estimates & Traffic Mgt Plan KLD Associates, Inc. 113-203A R00 88/08/25, 33pp. 47744:148-47744:180
- ~8811210074 Forwards rept on problems of evacuation & sheltering of braich/transient populations due to proximity of Psyrin 1 Station for consideration Related Info and: OTT,MC, MURILEAD,O.M. Dubbuy, MA 88/09/30 BELLAMY,R Region 1, Otc of the Director, 53pp. 47744.181-47744-243.
- -8811210041 Summary of 881025 mosting w/civil defense officials in town of Marshhold to status of enorgency plans,implament ng procedurus & facilities.

 1.AZARUS,W. Region 1, Olic at the Director, HOGANR Office of Nuclear Reactor Regulation, Director (Post 870411) 88/11/01. RUSSELL,W. Region 1, Otc of the Director, 3pp. 47744:244-47744 253.
- --8811210084 Discusses toldon w/R Boulay,director of Commonwealth of MA civil defense agency re NRC meetings w/local civil defense directors in vicinity of plant. RUSSELL W.T. Region 1, Ofc of the Director. 88/10/25 Region 1, Ofc of the Director 1p 47744:254 47744.251.
- ~8611210061 Discusses four of Duxbury Gurnet & Saquish Beaches frequently identified as major evecuation concorn

 LAZARUS,W. Rag on 1, Ofc of the Director HOGAN,R. Office of Nuclear Reactor
 Regulation, Director (Post 870411) 88/11/04. RUSSELL,W. Region 1, Ofc of the Director (2pp. 47744-259.
- ~8811210077 Summary of 801102 meeting w/civil defense officials in fown at Bridge-water re status of plant emotigency preparedness LAZARUS,W Region 1, Olc of the Director, 88/11/04 RUSSELL,W. Region 1, Olc of the Director
- ~8811020340 Forwards list of speakers,affiliation & general emergency preparedness subjarce discussed during fisted meutings.

 RUSSELL,W.T. Region 1, Otc of the Director, 88/10/19 TAYLOR,J.M. Deputy Executive Director for Regional Operations, EDO (Post 870413) 24pp. 47744 263-

47744:286

- 8812140160 Ack receipt of 881011 fir to Massachusetts Public Interest Research Group rept addressing mgt Issues Concludes that rept contains no new info to reconsider previous conclusions drawn in Decision DD-98-16. MURILEY TE. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/ 18. GOLDEN,WB Massachuseits, Commonwealth of, 6pp. 47821;127-47821;185.
- --8812140164 Forwards addendum to 960715 polition re deficiencies in mgt, containment & emergency response plans for facility,per forthcoming Commission meeting concerning leathly related to 1607FR 206.641 to suspond OL for facility relaterated SHIMSHAK.R. Massachusetts Public Interest Research Group 89/10/11 MURLEY.T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 1p 47821-133-47821-185

- -8812140188 "Whitewash Painting Over MgI Problems at Pilgrim Nuclear Plant 1986 -
- NOGEE, A. BRACH, W. Massachusetts Public Interest Research Group 88/10/31. 50pp 47821.134.47821.185
- 8912020012 Responds to 881124 th re-restant of Pitgrim Nuclear Power Station Notification of 881209 meeting in Rockville MD re-status of emergency planning zone & reception of communities re-public protection. ZECH,L. Comm.ss.oners 88/11/28 KIRBY,E.P. Massachusetts, Commonwealth of 7pp 47717.196-47717.204.
- -8812020014 Reguests withhold of approval of operation at Prighm Nuclear generating plant kinday,E.P. Massachusetts, Commonwea'th of 86/10/24 ZECH,L. Commissioners
- 8812050044 Responds to 881012 fit re-restart of plant informs that Commission postponed decision on proposed restart of plant interms (nat Commiss on post-poned decision on proposed restart of plant to further evaluate emergency planning issues & scheduled 881203 public meeting in Rocky, le MD for hearing 2ECHL. Commissioners 88/11/28 LAWLER, R.A. Brewster, MA 2pp 47757-078-47757-080
- -8812050047 Informs that Board of Selectmen for Town of Brewster voted during 681011 meeting to request NRC not to reopen plant. Board opposed to reopening of lacify unit adequate evacuation plan developed.

 LAYLERRA Brewster, MA 68/10/12 ZECHT. Commissioners 1p 4775/080-4751-080 47757 080
- 8812070174 Forwards response to 881101 notice of violation & proposed impostion of civil penalty in amount of \$50,000 Payment of civil penalty also encil Encl safeguards into withheld. BRD,RG Boston Edison Co. 88/11/28 Oic at Entercement (Past 870413). 2pp 47747 107-47747 108
- 8812020171 Forwards comments on "Repl on Progress Made in Emergency Planning for Response to Accident at Prighm Nuclear Power Station." Comments not intended to be chical of Commonwealth concerns but explain basis of NRC position. STELLO,V. Qto of the Executive Director for Operations. 88/11/20. BARRY,C.V. Massachusetts, Commonwealth of 10pp 47707 265 47708 041
- -3812020175 * Rept on Progress Made in Emergency Planning for Response to Accident at Pignim Nuclear Power Station."

 BARRY C.V. Massachusetts, Commonwealth of 89/10/11, 115pp. 47707.287-47708 041.
- 8812070010 Partial response to FOIA request for documents Forwards partially withhield App R documents feel FOIA Examption 4)
 GRIMSLEY, DIST Drawson of Freedom of Information & Publications Services (Post 880515) 88/12/01 JOHNSON,G E Swider & Berlin 4pp 4/7/29/202-4/7/29/324.
- --8812070016 Partially deleted memorandum relistop work order at utilized into relevants leading to Idensee decision to stop contain work being performed by contractor employees at prant include deterioration in radiation protection & security. GWYNNP, NRC No Detailed Affiliation Gwen 88/11/11. ADER,C., MILLER,C., ELSASSER,T. NRC No Detailed Affiliation Given 116pp 47729 209-47729 324.
- 8812140129 Responds to 681019 & 31 litra re status of omergency planning in town of
- Plymouth 22CHLW. Commissioners 88/12/05 THOMPSON,A.C. Plymouth, MA. 4pp. 47931-156-47931-177
- -8812140150 Requests opportunity to speak directly to Commissioners to facts of Plymouth adfological emergency response plan THOMPSON A C Plymouth, MA. 88/10/19. ZECH,L.W. Commissioners. 1p. 47931-169-47931-177.
- 6812120189 Partial response to FOIA request for documents Forwards. App T & partially deleted App U documents (rel. FOIA Exemption: 5) App S & T also available in FDR App V documents totally withheld (ref. FOIA Exemption: 5). GRIMSLEY.D.H. Division of Freedom of Information & Publications Services (Post 880515). 88/12/08. JOHNSON,G.E. Swidler & Berlin. 14pp. 47790.261-47791:170.
- -8812120239 Summarizes observations re CV Barry "Rept to Governor on Emergency Preparedness for Accident at Prigram Nuclear Power Station." BELLAMY R. Region 1, Orc of the Director. 67/01/21. MARTIN,T.T. Region 1, Ofc of the Director. 23pp. 47790 276-47790 359
- 8612190164 Requests NRC extend deadline for conduct of next blennial exercise until 120 days after competition of power ascension program. Fee will be electronically mailed to NRC.

 BIRD R.G. Boston Edison Co. 88/12/08. Document Control Branch (Document Control Desk) 6pp. 47849.234.47849.239
- 8812210178 Staff requirements memo re 881208 meeting w/public officials in Rockville,MD re-responsibility for emergency planning for plant CHUK.S. J. Office of the Secretary of the Commission. 88/12/20. Office of the Secretary of the Commission. 2pp. 47877:071-47877.072

H. General correspondence

- 8812070241 Responds to 881019 ftr re-incident during Commission 881014 meeting Meeting scheduled for 881209 re-status of emergency plans & readiness of local communities to protect public in event of emergency.

 ZECH,L.W. Commissioners. 88/11/28 DOWD,P.A., VOGLER,D.J., HAMADEH,A.C. Durbury, MA 2pp. 47739 351-47739 353.
- ~8812070245 Expresses outrage re forcible ejection of State of MA, Assistant Secretary of Public Safety. P Agnes from 881014 Commission meeting. DOWIGP. A. VOGLERD J. HAMADEH.A.C. Duxbury, MA. 88/10/19. Commissioners 1p. 47739 353-47739 353.
- 8812080011 Responds to 881031 requests from Town of Plymouth & Commonwealth of MA for additionable see plant emergency preparedness issues. ZECH L.W. Commissioners 88/12/01. KENNEDY.E.M., KERRY,J.F. Senate. STUDDS,G.E. House of Rep. 4pp. 47758 259-47758 264.

- 8812130276 Responds to 881020 fir to Secretary Child which provided Contrassion a 812130276 Responds to be tived in to Successiv Chark Within Provided Continuesses with membrage accounts of plants flushon Assumes that Mich with role authorize restoring plant unless convinced at safe operation. Within the Charlest Continues to Successive Reactor Regulation, Christian Reactor (Regulation, Christian Reactor) (Regulation) (Reactor) (Regulation) (Reactor)
- ~8812130276 Summanzos Martin observations martie during focilità del my, Giard L Saguish beaches to status of energer cypreparatities. Saguish beaches to status of energy reparatities. LAZARUS W. Region 1, Ofc of the Director. 887 (1701) Hergion 1, Ofc of the Creaty 2pp. 47796.074.47796.075.
- #8812130292 Forwards 881020 issue of Old Colony Montanual containing pre-8 colors cles on Pigem 1 question QUAID,D.L. Affidation Not Assigned: 68/10/23 | CHER,S. J. Office of the Secretary of the Commission: 14pp: 47796-076-47796-092

P. Operating license stage documents & correspondence

- 8811290378 Forwards transcript of NRC 880829 public incerting in Plymonto MA reducing entagosce norwards interserpt of NHC 800829 pathic meeting in Plymonto MA release nical & rigilissues at plant & transcript of 801005 public meeting an Productivity (2) of status of read noses of restart of plant COLLINS, SU. Region 1, Oto of the Decetor, 88711716 Massaudio Cetts, County, wealth of 2pp 47668 098-47668 099
- 8812010210 Requests placement of encl 881115 monto & encisito PDR BATESA Operations Branch 88717718 510 (1907NF) H. Public Deciment Breech 1p. 47698-344 47698-344.
- 8812010210 Requests placement of end 861115 meter & couls to Physic Steps Update," in PDR 6ATES A Operations Branch 88/11718 SPR (BURIN) (Fig. Patric 10) we entitle out.
- 10 47743 324-47744 286.
- -8811210016 Discusses plant progress in area of unintgeney pre-purediress, per Coamission 881014 moeting A1 restart open dums resolved & plant considered physics arealy for restart w/ exception of loose balls for supports the later and one in STELLO, Violocial the Executive Director for Operations 1897/11715 (VEC); (CORCII) CARR Commissioners 35pp. 47743-325-47744-045.
- -8811210029 Forwards tables identifying speakurs affiliation. 8, gor and uningrissy preparedness subjected discussed during in eetings between NRC 8, politicial VA Los monwealth of MA officials. Meetings isted. CONKLINC Region 1, Ofciol in e. Director 188711701. LAZARUS, W. Begrow I, Ofciol the Director 19pp. 47744-014-47744.032.
- ~8811210031 Summary of 881027 meeting w/c vil defense officials of town of Carveric Carver Town Hall re-emergency plans, implementing procurings carcinists the startific structure. A further structure of the procure of the Office of Inc Off
- ~8811210036 Summary of 881026 meeting w/c vid detensu officials, a flower of Directy re-status of emergency plans implementing procedures, & fund ties. LAZARUS,W. Region 1, Otc of the Director IndiGANI,H. Office of fundamental Regulation, Director (Post 87041) 98711701. RUSSELT W. Frequent, Otc of the Director App. 47744,036-47744,039.
- ~8811210039 Summary of 881020 mouting w/c vil deferred offices in trained largestor of status of emergency plans, implementing procedures & families. LAZARUS,W. Region 1, Ofc of the Director HCGAN, 11 Office of NacCook Region. 2, Ofc of the Director HCGAN, 11 Office of NacCook Region. 2, Office of the Director (Post 870411) 88/11/01. RUSSERT W. Region. 1, Office of the Director. 6pp. 47744.040-47744.045
- -8811210042 Summary of 881025 mooting w/cvs dolorese officials in town of Piya ord. re status of entergency plans, replicationing procedures & familiars.

 LAZARUS W. Region 1, Old of the Director HOGANTR Office of number floates.

 Regulation, Director (Post 870411), 88/11/01, RUSSELL W. Region 1, Old of the Director floates. reclor. 4pp. 47744 046-47744 049
- -8811210045 Summary of 881026 muoting wicovil defense officials in toward Facal 1 re slatus of energency plans implementing procedure 4 & inclinics LAZARUS.W. Region 1, Old of the Erector FIRGAN,P. Office of Country License Regulation, Circuit (Post 870411) 88/11/01. BUISSELL W. General 1, Okt of the Prector, 26pp. 47744-050-47744;145.
- -8811210067 Forwards Itr from util 8 "Evacuation Time Editioners & Reach Percultion Shallesing," "Mobang Impared" 8 "Special Factions," for recovers committee to a Wi BELLAMY,R.R. Region 1, Ole of the Director 87/08/12 IPCMASE A Technol Compensy Management Agency 2pp. 47744-146-47744-149
- -8611210070 Rev 0 to "Pagein Station Evacuation Tyre Estimates & Traffic May Plan KLD Associates, Inc. TR-203A R00_88/08/25, 33µp -47744,149 -47744,180
- -8811210074 Forwards rept on problems of evacitation & sheltening of beachitems of populations due to proximity of Pilgrim 1 Station for consideration Beinted and rept OTT.M.C., MURRIEAD.D.M. Duxbury, MA. 887/09/30. Bell LAMY, R. Tregico T. Oft of the Director. 53pp. 47744 181-47744 243.
- #8811219041 Summary of 881025 meeting wholed defense officials in town of Marsh-field related of emergency plans. Implementing productions & facilities. LAZARUSW, Region 1, City of the Director HCGAN/II Office of Norther Treatist Regulation, Director (Post 8704-11) 897/11/01 RUSSELT, W. Tiegron 1, City of line Director 3pp. 47744:244-47744.253
- -8811210084 Discusses telcon w/R Bouley,director of Colemonweigh of MA and detionse agency to NRC meetings w/focal civil defense directors in vicinity of plant RUSSELL,W.T. Region 1, Old of the Director. 88/10/25. Hegion 1, Old of the Director. 88/10/25. Hegion 1, Old of the Director. 19. 47744:254-47744:257.

- -8811210081 Discusses four of Daxbury, Gernet & Saquish Beaches frequently identified As major everuation concerns
 (AZARIUS,W Region 1, Clc of the Circtor NOSAN,R Office of Nuclear Reactor Regionation, Director (Post 870411), 88/11/04 RUSSELL,W Region 1, Ofc of the Director 2pp 47744-255 47744-259
- -8611210077 Summary of 861102 meeting w/civ1 detense officials in town of Bridgewater ru status of plant emorgency preparathess LAZARUS,W. Region 1, Ofc of the Director 88/11/04 RUSSELL,W. Region 1, Ofc of the Director 3pp 47744 260-47744 202
- -8611020340 Forwards list of speakers, affiliation & general emergency preparedness sub; area discussed during listed meetings RUSSELL,W.1. Region 1, Ofc of the Director 80/10/19. TAYLOR,J.M. Deputy Execu-tive Cirector for Regional Operations, FOO (Post 870413), 24pp. 47744:263 47744:286

8812140160 Ack receipt of 881011 ftr re Massachusetts Public Interest Research Group

- ropt addressing inglinessues Concludes that ropt contains no new info to reconsider previous conclusions trawn in Decision (DD 88-16). MURLEY,T.E. Office of Nuclear Reactor Regulation, Oirector (Post 870411), 88/11/ 18. GOLDEN,W.B. Massachusetts, Commonwealth of 6pp. 47821 127-47821 185 -8812140164 Forwards addendum to 060715 publich re deliciencies in mgt, contain-
- posture 144 Forwards disconding to Butt/15 postion for delicancies in mgl. containment 8 euergancy response plans for facility per fourthcoming Commission meeting concerning facility restart 8 10CFR2 206 Call to suspend OL for facility restarted SHIMSHAK A. Massachusotts. Public Indoost Absearch Group 88/10/11 MURLEY, TE. Office of Nuclear Heactor Hugolation, Diructor (Post 870411). 1p. 47021;133:47821.185. -8812140168 "Whitewash Painting Over Mgt Problems at Prigrim Nuclear Plant 1986 -
- NOGEE A BRACH W Massachusetts Public Interest Research Group 88/10/31 50pp 47821:134-47821:185
- 8811300412 Advises that QA program description chargins, dtd 880707, consistent w/ provisions of 10CFR50 54-8 acceptable MARITIN, 11 T. Region 1, Otc of the Director 88711721 BRD,R.G. Boston Edison Co-2pp. 47680 159-47680.160
- 8811300518 Advises that secondary contaminant look rate test satisfactorily performed on 886921. Test world secondary contaminant integrity, as defined by Tech Spec 4.7 C.L.C., pror to REO #7 CRD venting HIGHFILL K. Boston Edison Co. 88/111/22. December Control Branch (Document
- Centro! Dusk) 1p 47696 311-47696 330
- --8811300522 Rev 23 to Proceduro 8.7.3, "Secondary Containment Look Rate Test." * Buston Edison Co. 87/09/22, 18pp, 47696-312-47696-330
- 8811280048 Generic Ltr 80-20 to all homoros, holding OLs & CPs for nuclear power reactor facilities re individual plant exam for soverul accident viderabilities Svc list
- CRUTCHHELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47/28/303/47729/024.
- 0812020195 Nablication of #81212 meeting w/util in Rackville,MD to discuss ATWS implementation at plant TROTHER,E.H. Project Directorate L3, 88711720, WESSMAN,R.H. Project Directorate T-3, 2pp. 47717:116-47717:117
- 8812120092 Responds to Gorenic Lit 88:11 to fleg Guido 1,99,Rov 2, "Radiation Embritt'omant of Reactor Vescol Malls." URL plans to submit proposed license amend to extend reactor pressure vescol pressure-temp Fluids Enyond 10 EFPYs. URL (F.G. Boston Edison Co. 88/12/02. Document Control Branch (Document Control Dosk). 1p. 47/92.001-47/92.001.
- 8812120189 Parkal response to FOIA request for documents Forwards App 1.8 partially deleted App U documents (ref. FCIA Examption 5) App S. 8. T. also available in PDR App V documents totally withheld (ref.FOIA Examption 5). GRIMSLEY, D.H. Dwisten of Freedom of Information 8. Publications Services (Post 880515), 88712708 JOHNSON,G.E. Switter & Borro. 14pp. 47790-261-47791.170.
- --8705290224 Forwards comments requireff containment response to WB Goldon et al 860715-2-206 polition Commission of staff resources on high priority requested Target data of 870605 for draft response regionsted TAC 62090-es-squed. VARGA, S.A. Diwsen of Reactor Projects I/II (Post 870411), 87/05/21, SHAO,L. Division of Engineering & Systems Technology (Post 870411), 2pp. 47791.017-47701.017 47791 018
- --0812120246 Discusses testimony tecloro special joint committee en investigation & study of util on 870202 KERR,G W. NRC No Detailed Affication Girin. 87702/10. NRC No Detailed Affication Girin. 87702/10. NRC No Detailed Afficiation Girin. 10pp. 47701:001-47791:016.
- -8812120268 Summanzes in autors of util resturt assossment panel 870921 meeting restatus of NRC & Femsee activities associated w/ proposed plant restart Outstanding actions as of end of 870993 panel meeting discussed COLLINS,S.J. Hugfon 1, Ote of the Director, 87710707 RUSSELL W.T. Region 1, Ote of the Director, 37710707 RUSSELL W.T. Region 1, Ote of the Director, 3pp. 47791 049 47791 051.
- --8812120289 Summarizes minutes of util restart assessment panel 871008 meeting restatus of NRC & recrisee activities associated w/ proposed plant restart Oustanding actions as of ouril of 879921 panel meeting discussed.

 COLLINGS J. Region 1, Ofc of the Director 87/10/21. RUSSELL,W.T. Region 1, Ofc of the Director. 4pp. 47791:052-47791.055.
- -8812120276 Summarzes manutes of 871023 meeting w/project manager re-proposed schedule & approach to response to State of MA-871015-2.206 polition BOGERJB A Assistant Director for Region 1 Beactors 87710/26. MIRAGLIA,F. Office of Nuclear Reactor Regulation, Orector (Post 670411), 2pp. 47791-056-47791-061.
- --8812130067 Discusses mourtor, of util restart assessment panel 871208 meeting restatus of NRC & densou activities associated w/ proposed plant restart COLLINS.S.J. Region 1, Ofc of the Director. 87/12/29. RUSSELL.W.T. Region 1, Ofc of the Director. 5pp. 47791.062-47791.066
- --8812130078 Discusses mirrates of oth restart assessment panel 880202 telcon restatus of NRC & licensee activates associated w/ proposed plant restart C/LLINS.S.J. Region 1, Olc of the Director. 88/02/09 TIUSSELL,W.T. Region 1, Olc of the Director. 6pp. 47791.070.47791.080.

- -8812130082 Forwards responses to questions raised by Senator Kennedy during 880107 hearing an proposed plant restart
 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/
 01 REHM,T.A. Otc of the Executive Director for Operations 31pp. 47791097 47791.125
- -8812130086 Discusses minutes of util restart assessment panel 880426 meeting restatus of NRC & licensee activities associated w/ proposed plant restart COLLINS. J. Region 1, Otc of the Director 88/05/09 RUSSELL,W T. Region 1, Otc of the Director 68/05/09 RUSSELL,W T. Region 1, Otc of the Director 6pp 47791:126-47791.131.
- ~8812130087 Discusses minutes of util restart assessment panel 880519 telcon re-status of NRC & licensee activities associated w/ proposed plant restart COLLINS.5.J Region 1, Otc of the Director 88/05/25 RUSSELL.W T Region 1, Otc of the Director 5pp 47791:132-47791:146
- --8812130090 Discusses minutes of util restart assessment panni 880630 meeting rustatus of NRC & licensea activities associated w/ proposed plant restart COLLINS. J. Region 1, Ote of the Director. 88/07/12 RUSSELL,W.T. Region 1, Ote of the Director. 7pp. 47791-157.
- -8812130092 Discussos mínutos of util rostart assessment panel 880811 teleon re status of NRC & licensea activities associated w/ proposed plant restart COLLINS.5 J. Region 1, Otc of the Director. 88/08/15. RUSSELL,W.T. Rogion 1, Otc of the Director 6pp. 47791.158.47791.168.
- -8812130106 Partially deleted litrite proposed agenda for restart assessment panel 880825 moeting in King of Prussia PA

 * Massachusetts, Commonwealth of 87/09/29. MILLER,M. NRC No Detailed Affiliation Given 2pp. 47791 169-47791 170

- 8811290372 Ack receipt of 881101 lir informing NRC Rept 50-293/88-29 steps taken
- for corective 8 preventive actions BELLAMY,RR Region 1, Otc of the Director, 88/11/18, BIRD,R.G. Boston Edison Co. 3pp. 47849 191-47649:196
- 8811290573 Forwards Insp Rept 50:293/88:30 on 881027-1118 No violations noted MARTIN,T.T. Ragion 1, Ofc of the Director 88/11/21, BIHD,R G. Boston Edistin Co 2pp. 47650 141-47650.169
- --8811290576 Insp. Rept. 50-203/88-30 on 881027-1118 No welstions noted. Major areas respected iconsea followup activities no loose archer bolts in pipe support base plate, set of y significance of subj discrepancy & response to Bulletins 78 002 & 79-014. CHAUDHARY, S. CARRASCO J., STROSNIDER, J.R. Region 1, Oic of the Director. 88/11/21, 27pp. 47650.143-47650.169.
- 8811160211 NRC Info Notice 88-000, "Unauthorized Removal of Industrial Nuclear Guiges Svc list and: CUNNINGHAM R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 8U/11/22 Cunsel Jaleu Edison Co. of New York, Inc. 99pp. 47708 255 47708 257
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Centrol of Psychological Tests" Svc 1st encl. HOSSI,C E. Division of Operatorial Events Assessment (Post 870411). 88711722 Consokidated Edison Co. of New York, Inc. 101pp. 47708-042-47708-142.
- 6812070174 Forwards response to 881101 notice of violation 8 proposed imposition of civil portally in amount of \$50,000.Payment of civil portally also end Encl safeguards into withhold
- BIRD, H.G. Boston Edison Co. 88/11/28. Ofc of Enforcement (Post 870413) 2pp 47747:107-47747.108.
- 8812090321 Informs that no changes to SALP Coard Ropt 50-293/87.99 warranted based on review of util 880919 comments Ack enprovement afforts util outlined in functional areas of radiological controls & training effectiveness. RUSSELL,W.T. Region 1, Ote of the Director 88/12/01 BIRD,R.G. Boston Edison Co. 3pp. 47761:177-47761:261.
- 8811290030 NRC Info Notice 88-093, "Telethorapy Events." Svc Lst onci CUNNINGHAM,R E. Division of Industrial & Mortical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811.215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valvo Actuators." Svc list
- enci ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp 47708.143 47708 254
- 8812020287 NRC Into Notice 88-985, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svc list ericl.

 ROSSLC E Division of Operational Events Assessment (Post 870411), 88/12/08.

 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807.302.
- 8812120189 Partial response to FOIA request for deciments Forwards App T & partially deleted App U documents (ref FOIA Exemption 5) App S & T also available in PDR App V documents totally withheld (ref FOIA Exemption 5) GRIMSLEV.D.H. Division of Freedom of Information & Publications Services (Post 880515), 88712708 JOHNSON,G E Swidler & Berlin, 14pp, 47790 261-47791:016
- --8803300034 Requests review of encl Insp Rept 50-293/87-53 on 871116-20 re loss of offsite power event on 871111,for determination of any generic implications resulting from event Response requested within 30 days. VARGA,S.A. Division of Reactor Projects 1/II (Post 870411) 88/63/21. SHAO,L. Division of Engineering & Systems Technology (Post 870411). ROSSI,C.E. Division of Operational Events Assessment (Post 870411). ROSSI,C.E. Division of Operational Events Assessment (Post 870411). ROSSI,C.E. Division of Ingring Results (Post 870411). ROSSI,C.E. Division of Operational Events Assessment (Post 870411). ROSSI,C.E. Division of Ingring Results (Post 870411). ROSSI,C.E. Division of Operational Events Assessment (Post 870411). ROSSI,C.E. Division of Operational Events (Post 870411).
- 8812220110 Ack receipt of 881028 lit & payment of \$50,000 for civil panalty proposed by NRC on 881101 Corrective actions for violations identified in notice noted. LIEBERMAN, J. Otc. of Enforcement (Post 870413), 88/12/15 BIRD,R.G. Boston Edison Co. 1p. 47892:360-47892.360.

R. Periodic operating reports & related correspondence

- 8811300264 Forwards biweekly status rept for 881105-18 Resident & regional inspec-tors closely monitoring itemsee activities & independently assessing plant readiness for restact
 - NA 1531611 BLOUGH,A.R. Region 1, O'c of the Director 88/11/22 WIGGINS,J.T. Region 1, O's of the Director 6pp. 47698 010 47698 015
- 8812190224 Monthly operating rept for Nov 1988 for Prigrim Nuclear Power Station W/ 881209 ft/ HAM LION P. H.GHEILL K.L. Boston Edison Co. 89/11/30 7cp 47851 256-47851 262
- 8812150005 Forwards bi-weckly status rept for period 881118-1202 BLOUGH A.R. Region 1, Oto of the Director 88712707, Wildig NS, J.T. Region 1, Oto of the Director 6pp 47800 244-47800 249
- 8812120189 Part at response to FOIA request for documents Forwards App T & partially detelled App U documents (ref. FOIA Exemption 5) App S & T also available in FDR App V documents totally within 1 (ref. FOIA Exemption 5) GPHISLEVOH Direction of Freedom of Information 5 Publications Services (Post 880515) 88112108 JOHNSON GE Swider & Bertin, 14pp, 47790-281-47791-016
- ~8812120262 Forwards util bimpokly status rept for period 876604-17
 W.GG-NSJT Region 1, Oto of the Director, 87706/19 CCLLINS.S.J. Region 1, Oto of the Director, 11pp, 47791 019-47791 048
- -8812130073 Forwards u.t. biweekly status rept for period 880101-15 8LOUGHAR Region 1, Oto of the Director 68/01/22, WiGGINS, J.T. Region 1, Oto of the Director 3pp. 47791 067-47791 069

T. Hearing transcripts on non-antitrust matters

- 8811300180 Forwards transcript of NRC 880929 public meeting in Plymouth,MA re toch-nical & right issues at plant & transcript of 881005 meeting in Rockvite,MD re status of readiness for restant of plant Wiro encil COLLINS SJ Region 1, Offic of the Director 88/11/16 PiLLSBURY,M. Massachu-setts, Commanwea'th of 2pp 47701:317-47701.318
- 8811300287 Forwards transcripts of 880929 public moleting in Plymouth, MA re bases for NRC conclusion on technical & mgt issues at plant & 881005 meeting in Rockville, MD on status of read ness for plant restant W/o encis. COLLINS SJ Region 1, Old of the Director. 88/11/16. THOMPSON, A. Plymouth, MA. 200. 47677 126-47677.127.
- 8811300292 Forwards transcripts of 880929 public meeting in Plymouth,MA re-bases for NRC conclusion on technical & mgt Issues for plant & 881005 meeting th Rockville,MD on status of read ness for restart of plant W/o encis COLLINS SJ Region 1, Oto of the Director 88/11/16 DRISCOLLIM Kingston, MA. 2pp. 47680 220-47680.221
- 8811300335 Forwards transcript of NRC 880929 public meeting in Psymouth,MA de-scribing bases for NRC conclusion to technical & right issues & 881005 meeting in Rockello,MD on status of readmoss for restart of facility Wife cross COLLINS,SU Region 1, Official file Director 88/11/16. CORCORAN,D. Marshfield, MA 2pp 47877 124-47877.125
- 8811300347 Forwards transcripts of 880929 public meeting in Psymouth MA re-bases for NRC conclusions re-technical 8-mgt issues at facility 8-881005 public meeting in Rockwie-ND on status of readmess for restant of plant Wire entits.

 COLLINS SJ. Regen 1, Oft of the Director. 88/11/16 MAZZILLIF R. Carver, MA. 2pp. 47680-218-47680-219.
- 8811300419 Forwards transcripts of 860323 public meeting in Plymouth,MA to bases for NRC conclusion rellectmical 8 mgl issues at plant 8 881005 public meeting in Rockville,MD on status of readines. It plant restart W/o encis COLLINS 3 Region 1, O'c of the Oteclor, 86/11/16 NEUBAUER,J. Duxbury, MA. 2pp. 47677 142-47677 143
- 8811300474 Forwards transcripts of 880929 public meeting in Plymouth, MA re-bases for NRC conclusion on technical & mgt issues at plant & 681005 public meeting in Rockville, MD on status of readiness for restart of facility WTo encis.

 COLLINS.S.J. Region 1, Oft of the Director. 88711716. VALLA E.H. Kingston, MA. 2pp. 47677 301-47677.302.
- 8811300478 Forwards transcripts of public meetings on 860929 in Plymouth,MA re technical 8 mgt issues at plant 8 881005 public meeting in Rockville,MD re status of readiness for restant of plant W/o excls.
 COLLINS.S.J. Region 1, Ofc of the Director 89/11/16. LEV/N,R. Marshile'd, MA. 2pp. 47880 212-47680 213
- 8811300485 Forwards transcripts of public meetings on 880929 in Plymouth,MA re technical & mgt issues at plant & 891005 public meeting in Rockville,MD re status of readiness for restant of plant W/o ancits COLLINS,S.J. Region 1, Orc of the Director. 89/11/16 Cerver, MA. 2pp. 47680.214-
- 8811300520 Forwards transcripts of 880928 public meeting in Plymouth,MA its NRC conclusion on technical & mail issues at plant & 881005 meeting in Rockville,MO an status of readness for restart of plant W/o and; COLLINS,S.J. Region 1, Otc of the Director. 88/11/16, DOWD,P. Duxbury, MA. 2pp. 47677.140-47677.141
- 8811300577 Forwards transcript of 880929 meeting in Plymouth,MA re-technical & mgl Issues W/o enct COLLINS S.J. Region 1, Ofc of the Director 88/11/16. KARBOTT G. Plymouth, MA. 250, 4764-1914/674-192
- \$\$12270268 Extends thanks for excellent court reporting performed in past & in particular reporting by 3 Trowbridge at Cormission 881109 meeting focusing on evacuation plans in event of emergency at lacity.

 ZECH_LW. Commissioners, 88/12/16, RILEY Ann Ritay & Associates, 1p. 47926.213-

U. Congressional/Executive Correspondence

- bilization responds to 881017 lit to plant & status of offsite emergency prepared ness for fown of Plymouth, MA Plant will not restart until NRC satisfied that plant can be operated safety V Stoto 881102 memo end. 2ECHL W Commissioners. 88/11/17. HADFIELD,J.D. Plymouth, MA 45/247657.233.47657.242. 8811230077 Responds to 881017 lir to plant & status of offsite emergency prepared
- -8811230088 Comments on "under advisorment" vote of NRC on 861014,which word have given permission to restart plant NRC should contact author for current & up to date assessment of where Plymouth is in planning process. HACFIELD,J.D. Plymouth, MA 88/10/17 ZECH,I. W. Commissioners. 1p. 47657 242. 47657 242
- 8812020002 Responds to 881012 ltr re-restant of plant. Commission has dicided to help public meeting in Rockvillu MD to status of energency plans. 2ECHŁ Commissioners. 88/11/28. YOUNG, A.P., Chatham, MA., 2pp., 47754,224.
- -8812020004 Urgos that plant not be reopened until viable evacuation plan devised approved based on 881011 mouting to discuss reopening at plant. YOUNG A.P. Chalbam, MA 88/10/12 ZECH,L. Commissioners ip 47754 226-47754 228

V. Operator Examinations

8812090321 Informs that no changes to SALP Board Rept 50-293/87-99 warranted based on review of util 880919 communis Ack improvement efforts util sulfined intentional areas of radiological controls 8 training offectiveness. RUSSELWT. Region 1, Oto of the Director. 89/12/01 BIRD,R G Basich Edison Co 3pp. 47/61:177-47761-261

DOCKET 50-294 MICHIGAN STATE UNIV. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8812190141 Forwards Rev 7 to physical security plan Rev withhold.
WILKINSON,B.W. Michigan State Univ., East Lansing, Mr. 89/12/15. Document Control Branch (Document Control Dusk), 1p. 47853-367-47853-357.

P. Operating license stage documents & correspondence

- 8812050268 Application for amend to Licenso R-114 nationality THIGA license to "Fos session Only status as part of current plans to decommission reactor Decommissioning plan will be submitted by 800102 for NRC review. WILKINSCN.R.E. Michigan State Univ. East Jansing. Mi. 80/12/01. Document Control Branch (Document Control Branch
- -8812050269 Proposed Rev 3 to Tech Specs
 * Michigan State Univ , East Lansing, Mil 99/11/30, 20pp. 47720 237-47720 257.
- -8812080044 Amend 5 to License FI-114, minording license in entirely. EISENHUT, D.G. Division of Licenshig (800428-051124), 84709719, 3pp. 47720-258-47720 260
- -8812080067 Floy 2 to Tech Spacs for TRIGA reactor. Michigan State Univ., East Lansing, Ml. 84/08/30, 77pp. 47720-261-47720-330.
- 8812180057 Advises that 881104 request for route to transport sport reactor fiel to Deriver, Co-meets 10CFR73.37 requirements & accopitation. MACDONALD, CE Transportation Branch. 88/12/13 WILKINSON, B.W. Michigan State Univ., East Larieng, M. 20pp. 47835.096.47835.115
- 8812220198 Forwards rowiged Toch Spacs to 881201 application for amend to License R-114 involving conversion to possession-only status Fiscin chamber, containing 2 9 U-235 & startup source will be rate ned during possession only stage.
 WILKINSON,B.W. Michigan State Univ., Fast Linsing, Mr. 88/12/14. Document Control Branch (Document Control Branch (Document Control Dosk). 1p. 47001.299-47901.320.
- -881220201 Ray 3 to Tech Spocs.
 * Michigan State Univ., East Lansing, Ml. 88/12/31, 21pp. 47901:300-47801:320.

DOCKET 60-295 ZION NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & tire protection plans

- 8812090267 Requests submittal of allegation investigation results & disposition of a legation within 45 days of lit receipt. Enci withheld.

 NORELIUS C.E. Region 3, Otc of the Director. 88/12/02. REED,C. Commonwealth Edison Co. 2pp. 47/81:339 47/81,380.
- 8812270051 Responds to exercise weaknesses noted in Insp Ropts 50:295/88-18 8 50:304/88-18 on 880927-29 Corrective actions, accident mgt course for onshift personnel developed by plant training dept in conjunction w/Westinghouse. TRZYNA.G.E. Commonwealth Edison Co. 88/12/06 DAVIS.A B. Region 3, Ofc of the Director, 3pp. 47926:178-47926:180.

P. Operating license stage documents & correspondence

- 8811280040 Genetic Ltr 68-20 to all licensees holding OLs & CPe for nuclear power reactor facilities re individual plant exam for severo accident vulnerabilities Svc fist
- erici. CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728-303-47729.024

63

- 8812010305 Provides analysis of Rog Guide 1,99,Rov 2, "Radiation Embritllement of Reactor Vessel Matts" for impact on pressure-temp heatup & cooldown curves contained in Tech Specs,per Generic Lir 88-11.

 RICHTER,M.H. Commenwealth Edison Co. 88/11/28. (Jocument Control Branch (Document Control Desh.) 2pp. 47703 049-47703.050.
- 8812070061 Advises NRC of 880824 meeting to address issue of imital ref temp points for WF-70 wild metal in plant reactor vissels W/encl
 TRZYNA_GE Communiwalith Edison Co. 88/11/29, Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47737:323,47737.324.
- 8812070035 Forwards safety evaluation supporting util 831105,880822 & 1031 rd sponses to Generic Ltr 83-28,temis 3.1.3 & 3.2.3 rs Tuch Specs for post-meint testing Sponson to Committee to 03-20, norms 3.1.3 & 0.2.3 fb. Luch Specs for post-maint lesting requirments.

 MULLER D.R. Project Directorate fill-2, 88/12/02, BLISS, H.E. Commonwealth Edison Co. 3pp. 47748-086-47748-093.
- --8812070038 Safety evaluation supporting util responses to Generic Etr 83-26.tjoms 3.1.3 & 3.25 re-post-maint testing requeriments.

 **NRC No Detailed Affiliation Gwon 88/12/02, 3pp. 47748.089-47748.093
- 8812220206 Forwards proprietary & nonproprietary NFSR-0033, "VIPREZ WITE-1 DNBH Thornal Limit for Westinghouse OFA Fire!" Affidavit & application for withholding proprietary rept also each Proprietary version withhold (ref. 10CFR2.790) TRZYNA,G.E. Commonwealth Edison Co. 88/12/15 Office of Nuclear Reactor Regulation, Director (Post 870411). 4pp. 47892-257-47892.330.
- -8812220211 Requests that proprietary version of NFSR-0033, "VIPRE/ WRB-1 DNBR Thermal Limit for Westinghouso OFA Fuol" be withheld from public disclosure (rof 10CFR2.790). WIESEMANN,R.A. Westinghouse Electric Corp. 88/10/12. MURLEY,T. Office of Nuclear Roactor Regulation, Director (Post 870/411). 11pp. 47892:261-47892:271.
- -8612220214 Rev 0 to "VIPRE/WRB-1 DNBR Thermal Limit for Wostinghouse OFA BOERGER, J.C., GRIFFIN. J.L., KIM,H-S. Commonwealth Edison Co. NFSR-0033-R00. 88/10/14. 59pp. 47892-272-47892:330.

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear
- Gauges." Svc tsi and CUNNINGHAM.R.E. Division of Industrial & Modical Nuclear Safety (Post 870729). 88/11/22. Consolidated Edison Co. of New York, Inc. 90pp. 47708.255.47708.257.
- 8811180467 NRC Info Notice 88:091, "Improper Administration & Control of Psychological Tosts" Swc list end ROSSI-CE Division of Operational Events Assessment (Post 870411) 88/11/22 Consol dated Edison Co. of New York, Inc. 101pp. 47708:042-47708:142.
- 8811280094 Forwards Safety Insp Repts 50:205/88:24 & 50:304/88:24 on 881024-28 No we'stions noted GREGER, L.B. Hugion 3, Old of the Director, 88/11/22, REED,C. Commonwealth Edison Co. 2pp. 47854.037-47854.050.
- -8811280097 Insp. Repts 50-205/88-24 & 50-304/88-24 on 861024-28.No violations noted Major areas inspected chemistry program, including procedures,organization & training & primary & secondary sys water GC programs
 HOLIZMAN,R.B., SCHUMACHER,M.C. Region 3, Otc of the Director, 88/11/22, 12pp. 47654-039-47654-050
- 8811300442 Forwards Safety Insp Repts 50:285/88-19 & 50:304/88-19 on 880824-
- 1110 & notice of violation
 HINDS.J.M. Region 3, Old of the Director, 88/11/25, PEED,C. Commonwealth Edison
 Co. 2pp. 47871:171-47871:195.
- -8811300446 Notice of violation from Insp on 880824-1110. Violations noted:no program Implemented to assure that survoltance testing of svc water pumps performed & con-dition adverse to quality not corrected on 880508. CLAYTON,B. Region 3, Ofc of the Director. 88/11/26. 2pp. 47871:173-47671:174
- -8811300449 Insp Repts 50-295/88-19 & 50-304/88-19 on 880824-1110 Violations noted Mejor areas inspected Ilcensee action on previous insp findings,summary of operations Unit 2 rip on 69 1008 & 12 & 881019 Unit 2 valve block slipport HIRDS_J M. Region 3, Ote of the Director. 88/11/25, 21pp 4/67/1:175-4/67.
- 8812020186 Forwards addendum to Insp. Ropts 50-295/88-04 & 50-304/88-05 on 880210, consisting of comparisons of results of Laurd spike sent to plant & criteria for comparing analytical measurements Conservative disagreement for II-3 noted GREGEFt.L.R. Region 3, Old of the Director, 88/11/28, REED,C. Commonwealth Edison Co. 1p. 47722 090-47722-092.
- -8812020214 Addendum to Insp. Rapts 50-295/88 04 & 50-304/88-05, consisting of comparisons of results of Louid spike sent to plant & criteria for comparing analytical measurements.
 - Old of Enforcement (Post 870413), 08/11/28, 2pp 47722 091-47722:002
- 8612120024 Informs that investigation of Allegation RIII-A-88-0086 re alloged door prob-Teme discussed in anci util 880929 itr sufficient.

 NORELIUS,C.E. Region 3, Otc of the Director, 88/12/01. REED,C. Commonwealth
 Edison Co. 2pp. 47780:151-47780:161.
- -8812120026 Provides response to Allegation Rill-A-88-0086 re operation of vital area
- BUISS,H.E. Commonwaelth Edison Co. 88/09/29. DAVIS,A.B. Region 3, Ofc of the Director. 9pp. 47780:163-47780.161
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events" Svc list encl. CUNNINGHAM,R.E. Dwisson of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Into Notice 88-094, "Potentially Undersized Valve Actuators" Syc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254.

- 8812270051 Responds to exercise weaknesses noted in Insp Repts 50-295/88-18 & 50-304/48-18 on 880927-29 Corrective actions: accident mgt course for onshift per-sonnel developed by plant training dept in conjunction w/Westinghouse TRZYNA,G.E. Commonwealth Edison Co. 88/12/06. DAVIS,A.B. Region 3, Old of the Director, 3pp. 47926 178-47926:180.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vanders." Sec 1st and POSSI, C.E. Division of Operational Events Assessment (Post 870411) 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807-191-47807-302

R. Periodic operating reports & related correspondence

- 0812230081 Forwards monthly operating repts for Nev 1988 for Zierr Generating Station Units 1 & 2 & summary of operating expenses for Oct 1988 PLIML.G.J. Commonwealth Edison Co. 88/12/06 Document Control Branch (Document Control Dosh). pp. 47911-315-47911-325
- -8812200126 Monthly operating repts for Nov 1988 for Zion Units 1 & 2 AUSTIN,G. Commonwealth Ed.son Co. 88/11/30. 9pp. 47911:316-47911.324
- --8812230084 Monthly operating repts for Oct 1988 for Zion Generating Station Units 1 8 2,consisting of summary of operating experience
 * Commonwealth Edison Co. 88/10/31. Ip. 47911 325-47911 325

S. Reportable occurrences, LERs & related correspondence

- 8811280188 LER 88-019-00 on 881025,motor driven auxiliary feedwater pumps inoperable during blackout event Caused by anti-pump design deliciency, Mod installed to correct design deliciency ter auxiliary feedwater 8 sev water pumps. Wundated the LETZEL, PLIML.G.J. Commonwealth Edison Co. 88/11/25 6pp 47656.013-47658 018
- 8812070052 LER 88-022-00 on 881102,3-inch core hole penetration found in west wall of inner crib house which degraded functional integrity of fire barrier.Caused by deficiency in Identifying fire protection concorns W/881201 ftr. BERRY,F.M., PLIMIL,G.J. Commonwealth Edison Co. 88/12/01. 3pp. 47753:100-47753:102
- 8812080029 LER 88-021-00 on B81102 inadvertent autostart of guis de dosimotor component cooling pump occurred Caused by motel filing shorting out Metal particle re-moved from limit contact W/881202 ltr. SODENB, PLIMIL, G.J. Commonwealth Edison Co. 88/12/02 4pp 47743-018-47743 019
- 8812130197 LER 88 023-00 on 881108 low isolation valvo seal water tank pressure due to falled check valve Temporary afteration issued to machinically jumper around check valve & work request generated to disassemble check valve W/881208 tir. ASHLEYJ., PLIML.G.J. Commonwealth Edison Co. 88/12/08. 4pp. 47792:155-47792:155.
- 8812190362 LER 88-024-00 on 881118,station blackout signal inadvertontly initiated Caused by tack of adequate administrative controls during floid walkdowns.Initiation policy to limit field walkdowns initiated.W/undated itr. NETZELJ, PLIML.GJ Commonwealth Edison Co. 88/12/18 3pp. 47853.272-47853.274.

DOCKET 50-298 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8811300164 Forwards addl into to resolve certain App R draft SER open items, per 870323 request Main steam relief valvos have two stated shutdown functions
 GRIDLEY,R.L. Taringssen Valley Authority. 87/08/22. Document Control Branch
 (Document Control Desk). 12pp. 47676:001-47676.012
- 8812160091 Forwards "Browns Forry Nuclear Plant Annual Exercise Scenario 1988," per 841011 request Exercise scheduled for wk of 880919. GRIDLEY,R. Tennessee Velley Authority. 88/08/04. Region 2, Ofc of the Director. 1p. 47831:245-47832 243.
- 8812160096 "Browns Ferry Nuclear Power Plant Annual Exercise Scenario 1988."
 Tennossee Valley Authority. 89/16/02 400pp. 47831:246-47832:243.
- 8811290512 Informs that requested into supporting App R audit rescheduled 8 will be provided by 890203.
 GRIDLEY,R. Tennessee Valley Authority. 88/11/22. Document Control Branch (Document Control Dask). 3pp. 47650.078-47650.080.
- 8812140029 Forwards safety ovaluation of licenson 880101 & 880404 submittals re 10CFR50,App R shutdown analysis.Proposed safe shutdown capability satisfies requirements based upon NRC 881021 approval of exemptions to App R BLACK, SC Otc of Special Projects 88/12/08. KINGSLEY,O.D. Tennosseo Valloy Authority. 2pp. 47789 245-47789:285
- --8812140033 Safety evaluation accepting util App R submittal as applied to adequacy at minimum safe shutdown sys.
 Oto of Special Projects, 88/12/08, 19pp. 47799 247-47798,265.
- 8812200079 Forwards replacement pages to 670611 Rev 8 to physical security/contingency plan Encl withheld (rel 10CFR73 21).
 GRIDLEY,R. Tennessee Valley Authority, 88/12/13. Document Control Branch (Document Control Desk). 2pp. 47862.200-47862:201.
- 8612210195 Revised central emergency control cir emergency plan implementing procedures, including Rev 1 to CECC-EPIP-1, Rev 2 to CECC-EPIP-2, Rev 2 to CECC-EPIP-3, Rev 3 to CECC-EPIP-4, Rev 2 to CECC-EPIP-5 & Rev 2 to CECC-EPIP-7.W/ 881216 (6. GRIDLEY,R.L. Tennessne Valley Authority. 88/12/16 86pp 47906 304 47907 053.

- 8812210206 Forwards Rev 1 to radiological emergency plan & Rev 19 to Emergency Plan Implementing Procedure BFN EPIP-1 GRIDLEY.R Technoseov Valloy Authory 58/12/16 Document Control Branch (Occument Control Desk) 2pp 47507
- -8812210273 Roy 1 to "Radiological Emergency Plan" *Tennessee Valley Authority 89/12/07 | 11pp | 47907 065 47907 075
- -8812210276 Rev 3 to Emergency Plan Implementing Procedure BEN-EP(P-1, Artach-
 - Ternessea Valley Authority 88/12/16 1p 47907 076 47907 076

P. Operating license stage documents & correspondence

- 8811300164 Forwards and info to resolve certain App R draft SER open items.pcr 870123 request Nan steam retail valves have two stated shufdown functions GRIDLEY,RL Tennessee Valley Authorby 87/69/22. Document Control Branch (Document Control Desk) 12pp 47676 001-47676 012
- 8812130143 Forwards Amends 160,157 & 131 to Licenses DPR-33,DPR-52 & DPR-68,respectively & safety existation Amends replace all water lavel refs to top of active hely w/corresponting ret to vessel zero BLCKS Ofic of Special Projects 68/10/19 WHITE,S.A. Tennessoe Valley Authority
- 2pp 47795 248 47798 284
- -8812130150 Amends 160,157 & 131 to Licenses DPR-33 DPR-52 & DPR-68, respectively,replacing all water level refs to top of active fuel w/corresponding ref to BLACK,S Ofc of Special Projects 88/11/28 33pp 47798 250 47798 282
- -8812130174 Satety evaluation supporting Amends 160,157 & 131 to Licensos DPR-33 DPR-52 & DPR-68,respectively

 **Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/28 2pp. 47799 281-47799 281-47799 28
- 8812020185 Forwards Amends 158,154 & 129 to Licenses DPA-33,0PA-52 & CPR-68,respectively & safety evaluation Amend changes definitions of mode of operations,core atteration & reactor conditions
- BLACK S Old of Special Projects 88/11/18 WHITE S A Tennessae Velloy Authority 200, 47710 171-47710 335
- -8812020188 Amends 158,154 & 129 to Licenses DPR-33,DPR-52 & DPR-68, respectively,Chagring definitions of mode of operation,core attention & reactor conditions for the conditions of the condit tions for facility
- BLACK,S Ofc of Special Projects 88/11/18 155pp 47710.173 47710.327
- --8812020191 Safety evaluation supporting Amends 158,154 & 129 to Licenses DPR-33,0/PR-52 & DPR-68.respectively. * Otc of Special Projects 88/11/18 8pp 47710,328 47710,335
- 8812060235 Forwards Amonds 159,155 & 130 to Licenses DPR-33,DPR-52 & DPR-681espectively & safety evaluation Amend will add ASME Section XI pump & valve program definition & change spit cable testing frequencies to ref definition. BLACK, S. Oto of Special Projects 68/11/22 KINGSLEY,O.D. Tennessee Valloy Authority 2pp. 47755.047-47755.163
- -8812060243 Amends 159,155 & 130 to Licenses DPR-33,DPR-52 & DPR-68, respectively,adding ASME Section XI pump & valve program definition & changing applicable lesting frequencies to ret definition.
 BLACK,S Ofc of Special Projects 68/11/22 113pp, 47755.049-47765.161.
- --8812060246 Safety evaluation supporting Amends 159,155 & 130 to Licensee DPR-33,078-52 & DPR-68,respectively * Orciol Special Projects, 88/11/22, 2pp, 47755,162-47755,163.
- 8811280048 Generic Ltr 88.20 to all licensees hording OLs 8 CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc hat

870411). 88/11/23 Consol-

- 8812140029 Forwards safety evaluation of Licensee 860101 & 880404 submittals re
- 8812130022 Forwards response to 881121 request for addition on cable ampacry program, cable installation program, fuse program & thermal overload program. Util w provide status on testing by 890131 GRI/DLEVR. Tennessee Valley Authority. 88/12/09 Document Control Branch (Document Control Desk). 18pp. 47792-281-17792-298.
- 8812140157 Application for amonds to Licenses DPR-33,DPR-52 & DPR-68, adding requirement 10 MM 6 to Tech Specs, requiring Implementation of program to monetal piping made of austeritic stantless stool per Gonoric Ltr 88-01 Fee paid RAY,MJ Tennesseo Valley Authority 88/12/09 Document Control Branch (Document Control Branch (Basel Branch (
- -8812140159 Proposed Tuch Specs adding Requirement 1.0 MM 6 to require implementation of instruce map program to include pump made of austoritic stainless steeper Generic Lit 88-01 for indications of IGSCC. Tennessee Valley Authority, 88/12/09, 11pp, 47814:044-47814-054
- 8812140165 Responds to Genoric Ltr 86-11 ro radiation embrittlement of reactor vessel matts & impact on plant aperations using methodology in Roy 2 to Rog Guide 199 GRIDLEY,R Tennessee Valloy Authority 88712709 Document Control Branch (Cocument Control Dask) 8pp. 47800 206 47800 212
- 8812160129 Not fication of 861220 meeting w/util at site for licensee presentation of cable installation assessment & action plan MORANID H. Otciol Special Projects 88/12/13. BLACK,S. Otciol Special Projects 8pp. 47835-164-47835-162
- 8812200177 Requests temporary examption from GOC 17 to electrical cable separation. Examplion requested for Limitot time period between first relead &
- GRIDLEY,R. Tennessee Valley Authority, 88/12/15. Document Control Branch (Document Control Dosk), 12/pp. 47868-054-47868.085.
- 8812230017 Provides clarification to statements contained in util 881109 submittal on plant DCRDR Review concluded that human engineering discrepancy not required to be corrected before restart. GRIDLEY,R. Tennessee Valley Authority. 88/12/16. Document Centrel Branch (Decument Centrel Desk). 2pp. 47914:351-47914:352.
- 8812270210 Summarizos NRC sorilor ingl 881206-07 modings re review of performance of operating nuclear power plants beensed by NRC.Public meeting scheduled to 881221 to review results of latest meeting of NRR managers.

 STELLO,V. Oto of the Executive Director for Operations 88/12/16. KINGSLEY,O.D. Tennessee Vafley Authority. 3pp. 47926:273-47926:275
- 8812270104 Forwards Site Director Std Practice SDSP 16.8, "Fuse Centrel," defining requirements for controlling procurement, installation & maint of clinicing tuses Submitted completes response to 1/1/C 081123 request for Info to tuse program GRIDLEY,R. Tennessee Valley Authority, 88/12/20. Document Central Branch (Dorument Central Branch (Dorument Central Desk), 2pp. 47926-036-47926:140.
- -8812270107 Site Director Std Practice SDSP-16.8, "Fit60 Control." Tennesses Valley Authority. 88/12/16. 103pp. 47926 038-47926:140.

- 8812220101 Forwards Environ Qualification Insp Ropts 50.259/88-11, 50.260/88-11 50.266/88-11 on 880509-13-Insp reviewed implementation of program for establishing a maintaining qualification of electric equipment within 10CFR50.49.

 RICHARDSON,S.D. OTC of Special Projects. 88/08/01. WHITE,S.A. Tennessea Valey Authority. 3pp. 47894.319 47894.344.
- -8812220105 Insp. Repts. 50:259/08:11,50:260/08:11. 8. 50:296/08:11 on 800509-13 No violations noted Major areas inspected: Implementation for establishing & maintaining qualification of electric equipment within scope of 10CFR50.49. HUBBARD,G.T., PIERSON,R.C. Old of Special Projects. 88/08/26, 22pp. 47894:322-47804-474 47894:344
- 8812270244 Forwards Team Insp Repts 50:259/88-07.50.260/68-07 & 50:296/68-07 on 880418-22 No violations noted NRC concludes that Rov 4 of plant design baseline & verification program incorporates dostred calculation. RICHARDSON.S.D. Oic of Special Projects. 88/09/08. WHITE,S.A. Tennessoo Valley Authority. 4pp. 47926 337-47927.025
- --8812270245 Team Insp Rapts 60:259/88-07.50:200/88-07 & 50:296/88-07 on 880418-22.No xiblations noted Major areas inspected plant design baseline & venticetion program. GEORGIEV.G.B., LIAW.B.D. Old of Special Projects, 68/08/31, 48pp. 47826,340.
- 8809290002 Forwards proprietary "Browns Ferry Nuclear Plant Safety Sys Functional Insp.Emergency Equipment Cooling Water Sys,RHR Svc Water Sys "Tecommendations for observations being propared Rept withhold (ref 10CFR2.790). GRIDLEY,RL. Tennessee Valley Authority, 88/09/20. Document Control Branch (Document Control Desk). 2pp. 46998.256-46998.257.
- 8812220212 Forwards Welding Team Insp Repts 50-269/88-13,50-260/88-13 & 60-296/88-13 on 880518-27 & 0806-10.NRC findings in general agreement w/results of util welding project Phase It rept. RICHARDSON,S.D. Oic of Special Projects 88/10/03, WHITE,S.A. Tennessee Valley Authority. 3pp. 47892:101-47892:143.
- -8812220215 Insp Repts 50-259/88-13,50-260/88-13 & 50-296/88-13 on 880516-27 & 0606-10 No significant deviations from results reported in util Phase II rept noted Major areas inspected; into in util Phase II rept & engineering calculations. GEO/GECV.G.B., LIAW.B.D., MCLELLAN,T. Ofc of Special Projects. 88/09/22. 39pp. 47892-104-47892-142 47892 104-47892 143

- 8812050294 Advises that NRC 880817 commitment to perform insps prior to fuel reload postpaned until Feb 1989. RICHARDSON,S D. Ofc of Special Projects. 88/11/21. WHITE,S.A. Tonnassee Valloy Authority. 2pp. 47740 091-47740 092
- 8811160211 NRC Info Notice 88:090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc Ist encl.
 CUNNINGHAM,R.E. Division of Industrial 8 Medical Nuclear Safety (Post 870729)
 88711/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologi-ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142
- 8811300140 Responds to NRC 881025 ltr re violations noted in Insp Repts 50:259/88-21,50:260/88:21 & 50:296/88:21.Corrective action, generic reviews completed at plant & corrective action procedure revised to restructure generic review. GRIDLEY,R. Tennossee Velley Authority, 88/11/23. Cocument Control Branch (Document Control Desk). 7pp. 47668-286-47668:292
- 8812010186 Forwards V Stello 881117 ftr to all util oxecutivos re presence of NHC in-spector at plants,rev to enforcement policy & proposed enforcement actions for oper-ator inattentiveness at Poach Bottom. BLACK,S.C. O
- 8812090006 Ack receipt of 881007 fir informing NRC of steps taken to correct violations noted in Insp Repts 50-259/88-16, 50-260/88-16 & 50-296/88-16. MCCOY,F.R. Ote of Special Projects 88/11/28 KINGSLEY,O.D. Tennessno Valley Authority. 2pp. 47782:198-47782-199.
- B812090018 Ack receipt of 881006 fir informing NRC of steps taken to correct violations noted in tripp Repts 50:259/87-33, 50:260/87-33 & 50:298/87-33. MCCOY,F.R. Off. of Special Projects 88/11/28. KINGSLEY,O.D. Tennosso
- 8812090074 Ack receipt of 881021 ftr informing NRC of steps taken to correct violations noted in Insp Repts 50:259/88-18, 50:260/88-18 & 50:298/88-18. MCCOY,F.R. Ole of Special Projects, 88/11/28 KINGSLEY,O.D. Tennessee Vel'oy Authority, 2pp. 47761:123-47761:124.
- 8812090114 Ack receipt of 880428 & 0602 tirs informing NRC of steps taken to correct violation noted in Insp Repts 50-259/88-02, 50-260/88-02 & 50-296/88-02 MCCOY,F R. Otc of Special Projects. 88/11/28. KINGSLEY,O.D. Termossoo Valloy Authority. 2pp. 47775.095-47775.096.
- 8812020255 Forwards ref purchase order numbers & dates for suspected purchases by util of Class 1E components or svcs from Planned Maint Sys,Inc for appropriate action.per NRC Info Notice 88-019, "Ouestionable Certification of Class 1E....." BLACK,S.C. Ofc of Special Projects, 88/11/20, KINGSLEY,O.D. Tennessee Valley Authority, 5pp. 47722.069-47722:073.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc 1st end CUNNINGHAM,R.E. Division of Industrial & Madical Nuclear Safety (Post 870729), 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811.215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc fist
- enci. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812920287 NRC Into Notice 88-995, "Inadequate Procurement Requirements Imposed by Licensees on Vendors," Svc list oncl ROSSI, CE. Division of Operational Events Assessment (Post 870411), 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:392.
- 6812140157 Application for amends to Licenses DPR-33,DPR-52 & DPR-68, adding requirament 1.0 MM.6 to Tech Space,requiring implamentation of program to monitor pip ng made of sustentitis stainless stool per Generic Lir 68-01.Fee pald. RAY.M.J. Tennessee Val'ey Authority, 88/12/09. Document Control Branch (Document Control Desk). 3pp. 47814.041-47814.054.
- --- 8812140159 Proposed Tech Spacs, adding Requirement 1.0.MM.6 to require implementation of inservice insp program to monitor piping made of austonitic stainless steel per Generic Ltr 88-01 for indications of IGSCC.
 * Tennessee Valley Authority, 88/12/09, 11pp. 47814.044-47814:054.
- 8812200361 Forwards Insp. Repts 50:259/88:28,50:250/88:28 & 50:298/88:28 on 869805:30 & notice of violation. MCCOY,F.R. Oic of Special Projects. 88/12/09. KINGSLEY,O.D. Tennessoo Valloy Authority. 2pp. 47668:113-47868:138.
- ~8812200353 Notice of violation from Insp on 880905-30. Violations noted: failure to adequately correct discrepancy between as-built plant configuration & emergency equipment cooling water Drawing 1-47E859-1 until 880222. MCCOY,F.R. Old of Special Projects. 88/12/09. 2pp. 47868:115-47868:116.
- ~8812200355 Insp Repts 50:259/86:28,50:260/88:28 & 50:296/80:28 on 880305-30.Violations & unresolved tioms noted Major areas Inspectiod-operational safety, surveillance observations, say return to svc,R0s & restart tost program. CARPENTER,D.B., LITTLE,W.S. Region 2, Ofc of the Director. 88712/09. 22pp. 47868:117-47868:138.

8811300008 Monthly operation roots for Oct 1988 for Browns Ferry Nuclear Plant Units

R. Periodic operating reports & related correspondence

S. Reportable occurrences, I.ERs & related correspondence

- 8812140236 LER 88 005-00 on 881109 loss of power to 4160 volt shuldown board due to inadequate breaker alignment causes ESF actuations Breaker reinstalled & properly racked into normal position W/891208 ltr.
 MEAOE,K.E., CAMPBELL,G.G. Tennesson Valley Authority, 88/12/08 5pp 47800-334-47800.338
- 8812210064 LER 88-006-00 on 881116.compensatory sampling required by Tech Specs erronopusty discontinued.Caused by procedural deficiency Precedures revised W/

881212 III. NAVE, E.D., CAMPBELL, G.G., Tennessco Valloy Authority, 88/12/12 5pp. 47876 038-47876 042.

V. Operator Examinations

- 8811290270 Informs that NRC will administer requalification exams in order to evaluate requalification program Administration of requalification exams to all Group IV operators at that time also intended PARTICOWUJG Oic of Special Projects 88/11/21. WHITE, SIA Technessee Valley Authority 3pp 47663 358 47663:360
- 8812160041 Forwards request for additinto listed in refinally requirements & for licensed senior reactor operator from both operations dept & training dept to be representa-

lives for exams
MCCOY,F.R. Okc of Special Projects 88/12/01 KINGSLEY,O.D. Tennessee Valey
Authority 7pp 47832 345 47832 351.

DOCKET 50-297 NORTH CAROLINA STATE UNIV. PULSTAR REACTOR

F. Security, medical, emergency & fire protection plans

- 8812010198 Requests technical assistance in reviewing licensed 880819 emergency plan Completion requested by 890203.
 ADAMS,A. Standard zation & Non-Power Reactor Project Directorate 88/11/23
 TRAVERS,W.D. Emergency Proparedness Branch 2pp 47710.101-47710:102
- 8812010205 Requests technical assistance in reviewing 880819 security plan of applica-bon for Of renewal for State of NC PULSTAR reactor facility Review should be com-pleted by 890203 ADAMS, A. Standardization & Non-Power Reactor Project Directorate. 88/11/23. ERICKSON, IT A. Reactor Sateguards Branch 2pp 47709 252-47709 253

P. Operating license stage documents & correspondence

- 8812010219 Requests technical assistance in reviewing geology, seismology & hydrotogy sections of 880819 Ot. renewal application Review to be completed on 980203 ADAMS.A. Standardization & Non-Power Reactor Project Directorate. 88/11/23 BAGCHt.G. Structural & Geosciences Branch. 2pp. 47707:109-47707:110.
- 8612050117 Requests assistance in reviewing financial qualifications for renewal of Li-cense R-120.Review completion by 890203 requested. ADAMS,A. Standardzation & Non-Power Reactor Project Directorate. 88/11/29. THOMAS,C.O. Policy Development & Technical Support Branch (Post 870411). 2pp. 47733:359-47733:360.
- 8812160040 Requests technical assistance in reviewing meteorology section of 880819 licensee renewal application for North Carolina State PULSTAR Reactor Facility by
- ADAMS,A. Standardization & Non-Power Reactor Project Directorate 88/12/08 CUNNINGHAM,L J. Radiation Projection Branch. 2pp. 47834:358-47834:359.

Q. Inspection reports, IE Bulletins & correspondence

- 8811300198 Responds to NRC 881102 ftr re-violation noted in lasp Rept 50-297/88-04.Corrective actions radiation protection ofc in process of updating all procedures including procedures associated w/radiation surveillance & effluent moni-ELLEMAN,T.S. North Carokna State Univ., Ralokyh, NC. 88/11/21. Document Control Branch (Document Control Desk), 3pp. 47674:165-47674:187.
- 8812200006 Ack receipt of 881121 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50.297/88.04.
 DECKER,T.H. Region 2, Otc of the Director, 88/12/08, ELLEMAN,T.S. North Carolina State Univ., Releigh, NC. 1p. 47859 355-47859.355.

R. Periodic operating reports & related correspondence

8811300552 Forwards Attachment A,Section 6.7.51, "Erwiron Radiation Surveillance Rept for Pariod 670728-880308," to 1987-88 Tech Specs annual rept did 880830 Attachment A delayed in printing & unavailable w/main body of rept. MILLER,G.D. North Caroling State Unity, Raleigh, NC. 88/11/17. Document Control Branch (Document Control Desk). 1p. 47677.289-47677-287.

--0811300554 "Environ Ratiation Surveillance Rept for Period 880728-0803." HARRIS,R.J. North Carolina State Univ., Rateigh, NC 88/08/03, 18pp. 47677:270-

V. Operator Examinations

8812010212 Requests technical assistance in reviewing Fedrace 880819 submitted of

DOCKET 50-298 GOOPER NUCLEAR STATION

F. Security, medical, emergency & fire protection plans

- 8011300239 Forwards Irisp Rept 50 298/88-31 on 861001-31 & notice of violation CALLANT J. Rigion 4, Ofc. of the Director, 88/11/18 TREVORS,G A. Nobraska Public Rower District, 2pp. 47677:251-47877,260
- #8811300246 Notice of violation from inspiron 881001-31.Vigitation coted on 881023 & 24 consee did not temporarily meet vate badge of individual wiretraining requirements not accomplished & individual was allowed unescorted access to protected
 - Region 4, Ofc of the Director, 88/11/18, 1p. 47677/253-47677/253
- -8811300248 insp. Rept. 50-298/88-31 on. 881001-31 Viciations noted Major areas Inspected followup of plant events, operational safety verification access control monthly surveitance & maint observations & emergency expects PICK, G. A. BENNETT, W.R., CONSTABLE, G.L. Region 4. Ofc of the Director. 68/11/15 7pp. 4767-254-47677-260.
- 8811300488 Provides additional on status of Open Item 6614-07 of Insp Rept 50-2987 8-14 Spart Leit corting oney plain would be revised into two separate vois, A. & B. Vol. A. will contain parts of plan which did contain safeguards into TREVORS 6. Next asks a Public Power District. 88/11/21. Document Control Branch (Document Control Dock). 1p. 47676:208-47676.206
- 8811290459 Forwards Insp. Rept. 50-298788-29 on 881017-20 No violations or devi-
- Bilons holod CALLANL J. Region 4, Ofc of the Director 88/11/23 TREVORS,G.A. Nebraska Public Rower District. 2pp. 47657-328-47857:338
- -8811290460 Insp. Flept 50.298/88-29 on 681017-20No violations or deviations and Major areas inspected licensed performance & capabilities during annual oxer clse of emergency plan 8 procedures TERCINM, EVERETT,R J. Rogion 4, City of the Director 88/11/14, 9pp. 47657 320 47657 336
- 8812160031 Acustes that portions of flev 23 to facility safeguards plan consistent w/ provisions of 10CFH50.54(p) & acceptable. Portions indicated the end as unacceptable studied be controlled & resubmitted to maintain continuity Wio and: CALLAN,L.J. Region 4, Oto of the Drestor 88/12/09 TREVORS,G.A. Nebraska Public Pawar Cistrict. 2pp. 47873.235-47873.236
- 8812220208 Ray to 870610 & 880304 applications for amend to License Drft-46,consisting of Tech Spec Change Request 32,deleting changes to Limiting concilions for operation & surveillance requirements on tire barriers & penetrary seals. KUNCL, G. Nebreska Public Power District, 88/12/12 Document Control Branch (Document Control Desk), 4pp. 47914;162-47914;183
- =8812220221 Proposed Tech Specs re detetion of proviously proposed changes to I m ting conditions for operation & surveillance requirements on fre barriers & pentration
- Nebraska Pub'ic Power District, 88/12/12, 18pp. 47914:166-47914:183,

J. Insurance & Indemnity Information

- 8812120256 Forwards schedular exemption from property insurance requirements of 100FR50 54(2)(1) Environ assessment also end: CALVOJ A Project Orectorate IV. 88/12/05. TREVORS,G A Nobraska Public Power District 4pp 4/1526/327-4/7826/336.
- =8812120261 Exemption from 10CFR50.54(w)(1) extending date for acquiring full amount of properly insurance required by Commission regulations to no later than 18 months from 681205 Licenson exempt from purchasing insurance in excess of ANI/
- HOLAHAN G.M. Project Directorate IV. 88/11/30 Nebraska Public Power District. 4pp. 47826 331-47826 334.
- -8812140259 Environ assessment & Ending of no significant impact rul partial exemption from requirements of 100FR50.54(w)(1) from 801205-900804 requiring licensee to have property demang insurence in amount latted OCONNOR,P.W Project Directorate IV. 88/11/30. 2pp. 47626:335.47826:336.
- 8812160137 Advisos that State of NE Supreme Court denied rehearing on 881116 re request for declaratory judgment Meoting held to discuss stated insurance company
- requirements VO:GT,H.H. LeBoauf, Lemb, Leiby & MacRae. 88/12/06. TREBY,S.A. Assistant General Course! for Rulemaking & Fuel Cycle. 2pp. 47833-081-47833-092
- 8812140049 Forwards Endorsements 80 & 81 to NELIA Policy NF-200 & Endorsements 64 & 65 to MAELU Policy MF-70, reflecting increase in facility form fiability insurance limit from \$160,000,000 to \$200,000,000 effective 881013 TREVORS,G.A. Nobrato \$200,000,000 effective 881013 TREVORS,G.A. Nobrato Power District. 89/12/07. Document Control Branch (Document Control Desk). 9pp. 47798:344-47798.352.

P. Operating license stage documents & correspondence

- 8811290209 Ack receipt of 680817 response to NRC evaluation of changes to plant off
 - of CONNOR,P.W. Project Directorate IV. 88/11/17. TREVORS,G.A. Nebraska Public Power District. 4pp. 47651;262-47651:265.
- 8811300063 Forwards requests for addline re util 831104 & 650701 responses to Go-netic Ltr 63-28 Itoms 2 1 8 2 2. O'CONNOR,P.W. Project Directorate IV 88/11/21, TREVORS,G.A. Nebraska Public Power District, 5pp. 47671:008-47671.010
- 8811280048 Genoric Ltr 88:20 to all licensees holding OLs & CPs for nuclear power reactor families re individual plant exam for severe accident vulnerabilities. Svc list

- 8812150097 Documents 081317 meetings w/util in Region IV to discuss general issues of interest to aceutine & NBC including overall performance of plant & other issues of regionality interest Agendanist of artendeds & more oling summary end. CALLANT 1. Region 4. Of of the Director 1887(2709 TREVORS)G A. Nobraska Public Fower District. Spp. 47623-050 (7823-054)
- 8812160020 Forwards SER supporting util response to Generic Ltr 83-28, flem 21 [Parts - 8-2], "Egyprion: Classisk dom & Vondur Interface (Peactor Trip Sys & Composition Cooper Nuclear Station" CCCNNOR W Project Directorize IV 88/12/12 TREVORS,G A Nebraska Pub c Power District 4pp 47835-139-47835 145
- -8612160021 SED supporting thit response to Seneric Child 28, item 2.1 (Paris 1.8.2). "Equipment Class Francin A Venuer Interface (Boacter Trip Sys. & Components)." Cooper Nuclear Station Office of Nuclear Roadfor Regulation, Director (Post 976411), 88/12/12, 265 47835 143 47835 145
- 8812zz0208 Revito 870610-8-850304 applications for amount to License DPR-46,consisting of Tech Spec Change Request 32,do/oling changes to limiting conditions for operation 8 surveit and or requirements on fire barners 8-ponetration seats RUNCLL G. Notraska Pable Flower District 55,17712. Forciment Central Brench (Document Classel Test): 4pp. 47913-162-47634-199.
- -8812220221 Proposed Tech Space to deletion of previously proposed changes to mile ing conditions for operation of surveillance requirements on the barners & pentration
 - Netraska Public Power Distret, 85/12/12, 18pp, 37914-106-37914,183

- 881300239 Forwards Insp Rept 50 258788:31 on 581631 J1 & notice of violation CALANLI 31 Region 4, ONL of the Director 98713710 TREVUNS,G A Noticeska Public Power District 2 pp. 47617251-47677 260
- -8811300246 Notes of violation from ursplan 881003-31 Violation noted on 881023-8 24 Incesses did not temporarily identificate burge of individual withtraining regime ments not accomplished & individual way anower unescorted accoss to protected. eroas * Region 4, Ofciolitho Director, 88/11/18, 1µ, 47677-253,47677-253
- -8811300248 Insp. Rept. 50-298785-31 on 801001-31 Violetions noted.Major areas inspected followup of plant overils operational safety verification access council monthly survertance & niant observations & emergency excurcise PICK, G.A., RENNETT, W.P., CONSTABLE G.L. Requir. 4, Orc. of the Director 88/11/ 15 7pp 47677 254 47677 260
- 8811380483 Responds to NRC 881019 ltr ru violations noted in Insp. Rept 50:298/89 26 Corrective actions now splcing using Over-tin must be in accordance w/Maint 7.3.26.1 or 7.3.26.2 in comparison w/F.O.DP.224.

 TREVORS,GIA. Nebraska Public Power District 887/11/18. Document Control Branch (Document Control Desk), 3pp. 47695-357-47695-359
- 8811300488 Provides addlinito on status of Open Itum 8614-07 of Insp Rept 50 2867-86-14-Spent fael contingency plan would be revised into two separate vots, A. & B.Vol. A. wit contain parts of plan which od contain soft-guards into.

 IREVORS,G.A. Nebraska Public Power Ostrict 80/11/21. Document Central Branch. (Document Central Desk), 1p. 47676 206-47676 206
- 8811300498 Respond: U NRC 881021 ftr re-violations noted in Insp. Rept 50-298/88 28 Corrective actions Nuclear Performance Proceedure 10.27 revised to clearly defined that deficient steps require signals prior to proceeding to next step.

 TREVORS G.A. Notraska Public Power District. 88/11/21 Document Control Branch (Document Control Dosk) 2pp 47677 285-47677 289
- 8811180211 NRC Into Notice 88 C90, "Unauthorized Removal of Industrial Nuclear Gauges" Syc hist erct. CUNNINGHAM, R. Division of Industrial & Modicel Nuclear Safety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 98pp. 47708.255-47708.255.
- 0811160467 NRC Info Notice 88-001, "Improper Administration & Control of Psychological Tosto "Svc list and ROSSI,CE. Division of Operational Events Assessment (Post 870411), 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.
- 8811290459 Forwards Insp. Rept. 50:298/88:20 on 881017:20.No violations or deviations noted.

 GALLANIL J. Rogion. 4. Ofc. of the Director. 88/11/23. TREVORS.G.A. Nobreska.

 Public Painer District. 2pp. 47657.326. 47657.336.
- --8811299460 http://Rept.50.208/88-29 on 881017-20 No violations or deviations noted Major areas inspected licensee performance & capabilities during annual exercise of emergency plan & precedings. TERC, N.M., 2. VERETT, R.J., Rugson 4, Otc. of the Cheetic 88/11/14, 9pp. 47657-028-47647-026. 47657,336
- 8811300229 Reafirms util need for extension to respond to notice of violation & pro-posed imposition of civil penalty concerning environ qualification issues in Gunenc Ltt 88-07.
 - BB'07. TREVORS.G.A. Nebraska Public Power District. 88/11/23. Old of Enforcement (Post 870413). 1p. 47670:359-47670:359
- 8811290030 NRC Info Notice 88.093, "Telotherapy Events" Svc Let oncl. CUNNINGHAM.R.E. Devision of Industriat 8 Medical fluctoar Safety (Post 870723), 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103:47811:216. 8811290538 NAC Into Notice 88-094, "Potentially Undersized Valve Actuators." Svc list
- eric. POSSI,C.C. Division of Operational Events Assossment (Post 870411) 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254.

- -8812050194 Notice of violation from inspiren 881024-28 Violation noted, semiannual PASS operator requalification training not conducted & documented by training dept during the period of May 1997 - June 1998 - Region 4, Oto of the Director 89/12/02 1p. 47731 003-47731.003
- -8812050196 Insp Rept 50:299/88-27 on 881024-28 Violation noted Major areas inspected licensee chamistry/radiochemistry program & water chemistry & radioche-
- mistry confirmatory measurements NICHOLAS, J.B., WISE, R., BAER, R.E. Hegien 4, Ofc of the Director 88/11/30, 21pp 47731.004-47731-024
- 8812090328 Ack receipt of 801121 ftr informing NRC of steps taken to correct violations noted in Insp Repl 50 299/MB 20. CALLANL J. Region 4, Oic of the Director 88/12/02 TREVORS,G A Nebraska Public Power District 2pp 4/781.131-47761.134
- 8812140207 Forwards Exam Rept 50-298/OL-88-03 of exam administered during wk of
- BB1017. CALLAN, J. Region 4, Ofc of the Director, 88/12/07, THEVORS,G.A. Nebraska Public Power District. 2pp. 47814.125-47814.174 -8812140209 Exam Rept 50:298/OL-88:03 on 881017.Exam results all candidates passed exams & issued appropriate licenses GRAVESD N., PELLET, J.L. Region 4, Ofc of the Director 88/12/02 3pp. 47814 127-4741-100 N.,
- 47814:129 -8812140213 Forwards commente on questions & answers associated w/exams admin-
- istored on 861018-20. DUTTON,J.W., KUNCL,L.G. Nobraska Public Power District 88/10/20. GRAVES,D. Region 4, Ofc of the Director. 45pp. 47814:130-47814-174
- 8812020287 NRC Into Notice 88:095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" Svc list onci ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302
- 8812160049 Responds to NRC 881108 ltr re violations noted in Insp Rept 50-298/88 24. Violation of plant Tech Spec 6.2.1.B.4 a did not occur Reconsideration of violation requested Existing procedural requirements need to be clarified.

 TRE VORS, G.A. Nobraska Public Power District 88/12/08. Document Control Branch (Document Control Desk). 3pp. 47832.352-47832.354
- 8812200128 Responds to notice of vicintion & proposed imposition of civil penalty in amount of \$150,000 resulting from First Round Special Team Environ Qualification insp 50-258786-28 on 881103-07 Fee paid KUNCL, I.G. Nebraska Public Power District 88/12/08. Ofc of Enforcement (Post 870413) 25pp 47860 269-47880-283.
- R. Periodic operating reports & related correspondence
- 8812140038 Monthly operating rept for Nov 1988 for Cooper Nuclear Station W/881205 Itr. SCHEUERMAN,J.T., HORN,G.R. Nebraska Public Power District. 88/11/30. 5pp.
- 47796:140-47796:144.
- S. Reportable occurrences, LERs & related correspondence
- 8812130014 LER 88-027-00 on 881108, lound sotpoint of two switches in excess of allowable setpoints prescribed in Table 3.2.8 of Tech Speca. Trip setpoints resolt to within 1cth Spec tolerances & re-verify switch operability W/881208 lift. REEVES.D.L., HORN, G.R. Netraska Public Power District 86/12/08. 5pp. 47702.276. 47702:280

V. Operator Examinations

- 8812060230 Requests that encl ref mall be updated prior to administering operator li-conse axams during wk of 890227. Encl approved ref mall should be updated in order for NRC to meet schedule. CALLAN,L.J. Region 4, Oic of the Director. 88/11/30. TREVORS,G.A. Nebraska Public Power District. 10pp. 47735:027-47735.036
- 8812050192 Forwards Insp. Rept 60-298/88-27 on 881024-28 & notice of violation CALLAN, L.J. Region 4, Old of the Director. 88/12/02. TREVORS, G.A. Nebraske Public Power District. 2pp. 47731:001-47731.024.
- -8812050194 Notice of violation from insp on 881024-28.Violation noted semiannual PASS operator requalification training not conducted & documented by training dept during time period of May 1987 June 1988
 * Region 4, Ofc of the Director. 88/12/02. 1p. 47731 003-47731:003.
- -6812050196 Insp Rept 50-288/88-27 on 881024-28 Violation noted Mejor areas inspected licensed chemistry/radiochemistry program & water chemistry & radiochemistry confirmatory measurements. NICHOLAS, J.B., WISE,R., BAER,R.E. Region 4, Ofc of the Director, 88/11/30, 21pp. 47731:004-47731:024.
- 8812140207 Forwards Exam Rept 50-298/OL-88-03 of exam administered during wk of
- BB1017. CALLANIL J. Region 4, Ofc of the Director, 88/12/07, TREVORS,G.A. Nebraska Public Power District, 2pp. 47814:125-47814:174.
- --8812140209 Exam Rept 60:298/OL-88:03 on 861017.Exam results all candidates passed exams & issued appropriate licenses GRAVES.D.N., PELLET.J L. Region 4, Ofc of the Director. 88/12/02. 3pp. 47814:127-47814:129.
- --9812140213 Forwards comments on quostions & answers associated w/exams administered on 881018-20.
 DUTTON,J.W., KUNCL,L.G. Nebraska Public Power District. 88/10/20. GRAVES,D. Region 4, Ofc of the Director. 45pp. 47814.130-47814:174.
- 8812220128 Concurs w/use of licensed operator certificate of medical history to determine 8 certify applicant history.per 881117 request.
 CALLAN,L.J. Region 4, Otc. of the Director. 88/12/14, TREVORS,G A Nebraska Public Power District. 2pp. 47892:358-47892:359.

- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2
- P. Operating license stage documents & correspondence
- 8811280206 Mottleation of 881201 meeting w/util in Rockvilla,MD to discuss containment liner leak chaso channel vonting SWENSON,W.H. Project Directorate III-3 BB/11/22. HANNON,J.N. Project Directorate III-3. 3pp. 47662-318-47662 200.
- 8811280048 Genoric Ltr 88-20 to all Tecnseus holding Otis & CPs for nuclear power reactor facilities to Individual plant exam for severe accident vulnerabilities. Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 89/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729 024
- 8812050188 Advises that util has no plans to further attempt ultrasonic testing of reactor coolant pump casing we'ds for p'ant due to unset stactory results per tili0125 & 0531 requests for reflet from ASME Code Section XI. FAY,C.W. Wisconsin Efective Power Co. 88711728 Decument Control Branch (Document Control Dosk). 2pp. 47731:353-47731.354.
- 8812050121 Requests higher review pronty for WCAP-11394, "Mothorhogy for Analysis of Dropped Rod Event," to allow iconsee to take advantage of methodology to reduce number of turbine runbacks." Reactor Regulation, Director (Post 870411) 2pp 47733 290 47733 291.
- 8812090090 Responds to Generic Ltr 88-11, "Analysis at Embrittement of Reactor Vessel Bettine Matts." Impact of Reg Guide 1 99, Rev 2,on pressure temp limits low temp overpressure protective setponts & PTS secreming calculations ericl. FAY,C.W. Wisconsin Electric Power Co. 88/11/29. Document Centrol Branch (Document Control Desk) 33pp. 47761:081-47761:113
- 8812050059 Forwards rollco of consideration of issuance of amend to Licenses OPR-24 & DPR-27 & opportunity for hearing to 880826 application. SWENSON,W.H. Project Directorate III-3, 88/11/30, FAY,C.W. Wisconsin. Electric Power Co. 2pp. 47734:013-47734.019.
- -8812050061 Notice of consideration of issuance of amond to Licenses DPR-24 & DPR-27 & opportunity for hearing to 880826 application Amends revise Tech Speciconcerning design & operation of fuel cycle w/upgraded core WAMBACH,T.V. Project Directorate III-3 (08/11/30, 5pp. 4/734.015-47734.019)
- 8812090281 Forwards proprietary Addendum 2 to Rov 1 to WCAP-10924-P & nonpro-priotary WCAP-12071, "Westinghouse Large-Break LOCA Best Estimate Methodolo-gy," In support of 880028 request for Tech Spec change Proprietary rept withhold (ref 10CFR2 780). FAY,C W Wisconski Electric Power Co. 88/11/30. Decument Control Branch (Docu-ment Control Desk). 3pp. 47781.121-47781:327.
- 8812070195 Requests that util address Generic Ltr 88-17 ro loss of DHR during nen-power operation Industry response to Generic Ltr 87-12 deticient in areas of preven-tion of accident Initiation 8 miligation of accidents MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 670411), 88/12/ 02 MCNEER,C. Wisconsin Electric Power Co. 2pp. 47749 224-47749 225

- 8811160211 NRC Into Notice 88-000, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list and: CUNNINGHAM,RE Division of Industrial & Modical Nuclear Safety (Post 870729), 88/11/22. Consolidated Edison Co. of New York, Inc. 90pp 47708/255-47708/257
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tosts" Svc 1st end ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708.142.
- 8811290030 NRC Info Notice 88-093, "Toletherapy Events." Svc Lst encl CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729), 88/12/02. Consolidated Ed.son Co. of New York, Inc. 112pp. 47611:103-47811:215
- 8811290538 NRC Info Notice 68-094, "Potentially Undersized Valve Actuators." Syc Lst ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254
- 8812060221 Forwards response to request for Info re NRC Bulletin 88-09, "Thimb's Tube Thinning in Westingtrouse Reactors." Rept reflects incore neutron flux thimble tube inspe conducted during Fall 1998 Unit 2 reflecting outage. FAY,C.W. Wisconsin Electric Power Co. 88/12/02. Decument Control Branch (Document Control Oesk). 7pp. 47734.345-47734.351.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurament Requirements Imposed by Licensees on Vendors" Svc list encl. ROSSI.CE. Division of Operational Events Assessment (Post 870411), 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302.
- 8812200173 Requests NRC Region III & NRH attendence at 890110 formal demonstra-tion of reactor vessel flaw sizing techniques. Flaws Identified in reactor vessel safety injection nozzle welds during inservice inspe FAY,CW. Wisconsin Electric Power Co. 88/12/14. Document Control Branch (Docu-ment Control Desk). 3pp. 47868:171-47668:173.
- 8912270136 Ack receipt of 881020 ftr informing NRC of steps taken to correct violations noted in Allegation filli-88-A-0126. MORELIUS.CE. Region 3, Oto of the Director. 88/12/18. FAY,C.W. Wisconsin Electric Power Co. 2pp. 47926.214-47926:215

R. Periodic operating reports & related correspondence

8812190218 Monthly operating ropts for Nov 1998 for Point Beach Nuclear Plant Units 1 8 2 W/881208 in KRAUSE,C.W., FAY,C.W. Wisconsvir Electric Power Co. 89/11/30 Spp. 47840 130.

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8812070172 Rev. 15 to Emergency Plan Implementing Procedure EtA-216, "Outles of Nuclear Prent Fire Brigade STEPHENSON, J.D. Florida Power Corp. (a.c.a. of Florida Progress Corp.). 88/11/21 8pp 47749 303-47749 310
- 8812090288 Forwards Insp. Rept. 50.002789-29.09.880918.1021 & notice of violation. WiLSON,B A. Rugion 2, Ofc. of the Director. 88/11/21, WiLGUS,W.S. Florida Power Corp. (aubs. of Florida Progress Corp.). 2pp. 47762-084-47762
- -8612090296 Insp. Rept. 50:302/89:29 on 880916:1021 Vigitations noted Major areas inspected ptant operations, security red ological controls, LERs. & nonconforming operations repts, facility mods & review of plant rown wicommittee. HOLMES-RAY, P. TERROWJ., CRUENIJAK R. Region 2, Otc of the Director. 89/11/21. 18pp. 47762 098:47762. 105.
- 8812070176 Rev 7 to Emergency Plan Implementing Procedure AP-460, "Steam Genereter Isolation Actuation."

 BANDHAW,W K. Florida Power Corp. (subs. of Florida Progress Corp.) 88/11/30-26pp. 47748-323-47748-348.
- 8812190243 Forwards Insp. Rept 50:302788-30 on 881110 No violations or deviations noted
 DECKER,T.R. Region 2, Ofciol the Director 88/12/08 WILGUS,W.S. Florida Power
 Corp. (subs. of Florida Progress Corp.), 2pp. 47853-318-47853:322.
- -6612199245 Insp Ropt 50:302/83:30 on 861110 Major areas inspected supplemental dose assessment drift conducted by Lewise to demonstrate corrective action in response to concerns identified during annual amerigancy exercise on 880608 SARTOR,W.M., RANKIII,W.H., Region 2, Old oil the Director, 88/12/07, 3pp 47853 320-47853 322
- 8812190268 Forwards FEMA analysis of prompt alort & not fication sys test on 860807 for plant FEMA determination that say installed around plant satisfies requirements of NUREQ-0854/FEMA-ITEP-1, Ray 1 & FEMA REP-10 noted.

 DECKER, TR. Region 2, Otto of the Director, 69/12/09, WILGUSWS Florida Power Corp. (subs. of Florida Progress Corp.), 2pp. 47852 178-47853 083
- 8812200159 Advises that 880226 Rev 7 to radiological emergency response plan meets alds of 10CFR50 47(b) & App E & acceptatio.
 DECKER,T.R. Rag on 2, Old of the Director, 88/12/12, WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Ccrp.), 2pp. 47850 249 47860 250
- 8812210166 Rev. 10 to Procedure AR-403, "PSA H Annunciator Response." MARSHALLW Florida Powor Corp. (subs. of Florida Progress Corp.), 88/12/12 13pp 47881:334-47881:348
- 8812200245 Advises that 890825 Rev 8 to radiological emergency response plan meets planning stids of F0CFR50, 47(b) & App E to 10CFR50 DECKER, F R Report 2, Otto the Directic 88/12/13, WILGUS,W S. Florida Power Corp. (subs. of Florida Progress Corp.) 2pp. 47868:169 47868 170.
- 8812210076 Roy 8 to Procedure EF-399, "Steam Generator Tube Leak."
 MARSHALL,W. Florida Power Corp. (subs. of Florida Progress Corp.) 88/12/13
 36pp. 47880.114-47880.149.
- 8812200171 Forwards Insp. Rept. 50:302/86-31 on 881022-1118 No. violations willSON,8 A Region 2, Ofci of the Director B8/12/15, WILGUS,W.S. Florida Power Corp. (subsi of Florida Progress Corp.) 2pp. 47860/223-47860/236.
- -8812200176 Insp. Rept. 50:302/88:31 on 881022-1118.No violations noted. Major areas Inspected plant operations, security, achological controls, LERs & nonconforming operations repts, facility mode, followup of onsite events & confirmatory action lins. HOLMES-INAY, P., TEDROW, J., CRLENJAK, R., Region 2, Otc of the Director, 88/12/14, 12pp. 47860, 225 47860, 236.

H. General correspondence

- 8812090041 Requests that comment period be extended from 60 days to 120 days on proposed rule 10CFR50 to maint in nuclear power plants WILSON,KR. Florida Power Corp. (subs of Florida Progress Corp.) 88/12/02. CHILK,S.J. Office of the Secretary of the Commission. 1p. 47700 087-47780.087.
- P. Operating ficense stage documents & correspondence
- 8811290300 Identifies facrity as lead plant for B&W Owners Group Tech Specs Committee for refocation of containment isolation valves table.

 SMYTH,C.W. Babcock & Wilcox Operating Plants Owners Group, 88/11/17, Office of Nuclear Reactor Regulation, Director (Post 870411), 1p. 47665-238-47685-238.
- 8811300130 Forwards safety evaluation accepting ust 861021 submittal re operation w/ deficiency in pressuritor heater power supply until restart from next scheduled retuel-Ing outage.
 SILVER H. Project Directorate N-2, 88/11/22 WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.), 2pp. 47676 302-47676 308.
- -9811300134 Safety evaluation accopting operation w/existing pressurizer heater power supply design until next refueling outage.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/22, 3pp. 47676 304-47676 308

- 8811300157 Forwards additinfo on ATWS mitigation design per 881013 miseting 8 665 sequent locons UN working to resolve remarking issues in bireframe to support or statistion in upcoming refuel in ordinary for oversize figure WIDELLIRIC Florida Power Corp. (subs. of Florida Progress Corp.). 88/11/22 Decument Coultol Branch (Document Control Desk). 17pp. 4769/ 125-47697:141.
- 8811280048 Generic Ltr 88 20 to 91 licensees holding CLs & CPs for nuclear power reactor faculties no included plant exam for severe accident vulnerabilities Szc list
 - CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 37728 303 47729 024
- 8811290333 Responds to Generic Ur 88-11, "NRC Pusition on Nadiation Emiliational Reactor Vossel Matts & Impact on Piant Operations." Current 8 EFPY pressure tempternt currest will be adequate boundary protection until 1ech Specs changed WiLSON KR. Florida Power Corp. (s.tb.s. of Fford a Progress Corp.) 88/11/23. Coc. a ment Control Branch (Document Control Casts). 2pp. 47656,018-47656 (199.).
- 8812010007 Provides update on status of high energy line break (HELB) rose star-program Util unable to locate sufficient documentation to rely on as permaner trescle tion & therefore recestableshing compliance white the design basis. WILSON,K. Florida Power Corp. (subs. of Florida Progress Corp.) 88/11/25. Docu-ment Control Branch (Document Control Desk), Spp. 17698 052-4/698 056.
- 8012020060 Application for amend to License DFR-72 consisting of Rev. 1, contamined isolation valves to Toch Spec Change Request 161 revising Limiting Condition to Operation 36.3.1.3 a acting Surveillance 4.6.3.1.3 WILGUSW.S. Florida Power Carp (subs. of Florida Progress Corp.) 88/11/20, Document Control Branch (Document Control Desk). 5pp. 47718-039-47718-055.
- -8812020071 Proposed Tech Specs revising Limiting Condition for Operation 3.6.3.1 re-containment isolation valves
 *Florda Power Corp. (subs. of Florida Progress Corp.). 68/11/28. http://doi.org/10.345-
- 8812020268 Application for ement to License DPR-72, consisting of Tech Spec Change Request 163 increasing containment leakage test pressure to 53.3 psg Feo paid will GDSWS Florida Power Corp (subsidial Progress Curp.) 86/11/28 Document Control Brunch (Document Control Dask) 7pp 47718.250-47718.262
- -8812020270 Proposed Tech Specs, ncreasing contaminent leakage test pression to 53.3 psig Florida Power Corp. (subs. of Florida Progruss Corp.) 88/11/28, 6pp. 47718-257-
- 8812120123 Requests that util addressos Garreno Util 88-17 to less of BHR during conpower operation
 MURICEY TE Office of Nuclear Reactor Regulation, Director (Post 8704.1.1) (94/12/
 02. KEESLER,A. Ffortida Power Corp. (subs. of Florida Progress Corp.). 2pp.
 47798.051-47798.052.
- 88 (2090252 Summary of 861 (29 meeting w/us) to discuss open ATWS issues at forthy in attempt to reach agreement on conceptual design List of attendeds, agond a & states SILVER,H. Project Directorate II-2, 08/12/07 Project Cirectorate II-2 (Spp. 47/86/332-47/86-350)
- 8812190125 Forwards summary of 801109 menting religious personnel performance & status of equipment qualification program. ERNST.M.L. Region 2, Ofc. of the Director 88/12/08 WILGUSW'S Florida Power Corp. (eubs of Florida Progress Corp.) 25pp. 47854-349-47855-013.
- 8812160112 Notification of 881221 meeting w/uril in Rockvilla,MD to discuss recent high energy into break submittal & questions on final resolution of emergency dissurgenceator pressure.

 SILVERIP, Project Directorate (I-2, 89/12/13, BERIKOW,HIN, Project Directorate II-2, 3pp. 47873,356-47873,359.
- 8812210079 Forwards safety evaluation accepting util 831104 8, 848731 responsible flam 2.1 (Parts 1-8-2) of Genoric Lik 83-28 re-equipment classification 8, vendor interface programs EGG-NTA-7243 also encl. SILVER,H. Project Directorate Inc. 88/12/15 WILGUS,W.S. Fforda Power Corp. (subs-of-Florida Progress Corp.) 2pp. 47877.327-47877-343.
- --0812210086 Safety evaluation accepting util responses to Item 2.1 (Parts 1 & 2) of Generic Ltr 63-28 religional class licition & vondor interface programs

 **Office of Nuclear Teactor Regulation, Director (Post 870411), 88/12/15 6pp 47877-338-47877-343

- 8811230033 Ack receipt of 881101 ftr informing NRC of stops taken to correct violations noted in Insp Rept 50:302/88-26. WiLSON,B.A. Region 2, Old of the Owester, BB/11/10, WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.) 1p. 47652-091-47652-091.
- 8812090288 Forwards Insp. Rept. 50:302/58/29 on 680916-1021 & notice of victation WILSON 8 A. Ragion 2, Ofc at the Director, 68/11/21 WILGUS,W.S. Florida Power Corp. (subs. of Florida Pragress Corp.), 2pp. 47762-084-47762-105.
- --8812090291 Notice of violation from inspirence 880916-1021. Violation noted: Procedure MP-101 inadequate in that procedure did not require sys leak test be conducted at normal operating pressure following replacement of thermowell in RCS WILSON,B A. Region 2, Oic of the Director, 88/11/21, 2pp. 47762.086-47762.087
- -8812090298 Insp. Rept. 50-302/88-29 on 880916-1021. Violations noted Major a:eas Inspected plant opporations, security radiological controls, LEHs & noncontorining operations repls, facility mods & review of plant review committee.

 HOLMES-RAY.P., TEDROW, J., CRI, ENJAK, R. Region 2, Orciof the Olirector. 88/11/21, 18pp. 47762-089-47762-105.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." See his onct. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/31/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708.257.

8811160467 NRC Info Notice 88 091, "Improper Administration & Control of Psychological Tesls." Svc list end.

ROSI,C E. Division of Operational Events Assessment (Post 870411), 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142

- 8811290101 Remits payment for civil penalties in amount of \$25,000. WIDELL, R.C. Florida Power Corp. (s.ths. of Florida Progress Corp.), 88/11/22. Ofc of Enforcement (Post 8/0413), 1p. 47648 169-47648 169.
- 8811300065 Forwards signed original of 881117 order imposing civil monetary penalty issued to Econson for transmittal to Ofc of FR W/o stated and LIEBERMAN,J. Ofc of Enforcement (Post 870413), 88/11/25 LESAR,M.T. Regulatory Publications Branch Tp. 47697.360-47697.360.
- 8812090100 Ack receipt of 881019 & 1114 his informing NRC of steps taken to correct BN2090100 Ack racego to activity a 114 ms anothing trace of steps taken to confect v.c) along a noted in lasp Ropt 50-302/86-24 ERNST,M L Region 2, Ofic of the Director, 88/11/30, WILGUS,W.S. Florida Power Corp (subs of Florida Progress Corp.) 1p. 47783.322-47783-322.
- 881129030 NRC Info Notice 88-093, "Telatherapy Events." Svc. fist enct. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811.103-47811.215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valvo Actuators." Svc list
 - ROSSICE, Division of Operational Events Assessment (Post 870411) 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254.
- 8812090312 Forwards Insp Ropt 50-302/88-32 on 881031-1102 No violations or devi-
- ations noted
 DECKER,T.R. Region 2, Ofc of the Director, 88/12/02, WILGUS,W.S. Florida Power
 Corp. (subs. of Florida Progress Corp.), 2pp. 47761:150-47761:158
- --8612090316 Insp. Rept. 50-302/88-32 on 881031-1102.No violations or deviations
- Identified Major areas inspected followup on a legations COLLINS,T.R., HOSEY,C.M. Region 2, Ofc of the Director, 88/11/30, 5pp. 47761.152-
- 47761:156.
- 8812130008 Ack receipt of payment for civil panalty imposed by NRC on 881031 in amount of \$25,000. Corrective actions will be examined during future insp.
 LIEBERMAN,J. Ofc. of Enforcement (Post 870413) 88/12/06. WILGUS,W.S. Florida
 Power Corp. (subs. of Florida Progress Corp.), 1p. 47792 132-47792.132.
- 8812190411 Ack receipt of 881114 ftr Informing NRC of steps taken to correct violations noted in Insp Rept 50:302/88-27.
 HERDT,A.R. Region 2, Ofc of the Director. 88/12/06. WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.) 1p. 47035-173-47835:173.
- 8812020287 NRC Info Notice 88 095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" Svo list enct ROSSI, CE. Division of Operational Events Assessment (Post 870411), 88/12/08, Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302
- 8812190243 Forwards Insp Rept 50:302/88:30 on 881110.No violations or deviations
- DECKER,T.A. Region 2, Ofc of the Director. 88/12/08. WILGUS,W.S. Florida Power Corp (sibs. of Florida Progress Corp.) 2pp. 47853.318-47853.322
- --8812190245 Insp Hopt 50:302/88:30 on 881110 Major areas Inspected supplemental dose assessment drill conducted by licensee to demonstrate corrective action in response to concerns identified during annual emergency exercise on 880608 SARTOR,WM, RANKIN,W.H. Region 2, Ofc of the Director 88/12/07, 3pp. 47853:320-47853:322.
- 8812130215 Requests listed Into for properation of 880206-09 Audit to venty resolution of IE Bullotin 79-27.
 SILVER,H. Project Directorate 11-2, 88/12/09, WILGI/S,W.S. Florida Power Corp. (subs. of Florida Progress Corp.), 3pp. 47792.118-47792:120
- 8812160078 Forwards supplemental response to Bulletin 88-004 re-potential safety-ro-lated pump loss.Util anticipates that addl info will be available to NRC by 890415. WIDELL.R.C. Florida Power Corp. (subs. of Florida Progress Corp.) 88/12/99. Docu-ment Control Branch (Document Control Dosk). 10pp. 47825.028-47825:037.
- 8812200171 Forwards Insp. Rept. 50:302/88:31 on 881022-1118.No violations noted.Unresolved item tidentified: WtLSON,B.A. Region 2, Oic of the Director. 88/12/15. WtLGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.) 2pp. 47850.223-47860:236.
- ~8812200176 Insp Rept 50-302/88-31 on 881022-1118.No violations noted Major areas inspected plent operations, security, rediological controls, LERs & nonconforming operations ropts, lability mods, followup of unsite events & confirmatory action tits. HOLMES-RAY.P., TeDROW.J., CRI, ENJAK,R. Region 2, Ofc of the Director. 88/12/14, 12pp. 47860:225-47860-236.
- 8812210179 Flemits payment in amount of \$50,000 for civil penalty imposed by NRC WIDELLR C. Florida Power Corp. (subs. of Florida Progress Corp.). 88/12/15. Document Control Branch (Document Control Desk). 1p. 47877.093-47877:105.
- 8812220299 Ack receipt of 881215 lir & payment for civil panalty in amount of \$50,000 Imposed by NRC in 881117 order. LIEBERMANJ. OIG of Enforcement (Post 870413). 89/12/21. WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 1p. 47900:217-47800:217.

R. Periodic operating reports & related correspondence

8812200206 Monthly operating rept for Nov 1988 for Crystal River Unit 3.W/881213 ltr. STEWART, S.A., WIDELL, R.C. Florida Power Corp. (subs. of Florida Progress Corp.). 88/11/30. 5pp. 47860.344.47860:348.

- S. Reportable occurrences, 1.ERs & related correspondence
- 8811280062 LER 88 020-00 on 881012 hydrauric snutber RCH-81 found disconnected at pping end Scubber removed to allow maint on adjacent valve on 871119. Snubber roinstalled Procedure revised for tracking purpose W/881110 tr.
 MOFFATT, W., WiDELL, R.C. Florida Power Corp. Isobs. of Florida Progress Corp.).
 88/11/10, 4pp. 47653 273-47653 276
 - 8811280157 LER 89:022:00 on 881023,DHR dropline isolation valve DHV-3 actuated during plant startup Caused by administrative personnel error Personnel involved counseled & operating procedures rev planned W/88121 lir.
 MOFFATT, L.W., WIDELL, R.C., Florida Power Corp. (6ubs. of Florida Progress Corp.)
 - 88/11/21 4pp. 47656 331-47656 334
 - 8812010 153 LER 89-924-00 on 881028 reactor trapped following main steam & main feedwater isolation due to excessive steam pressure itercease Caused by increased main turbine governor valve (GV) control setting GV limit setting reduced W/881128 MOFFATT, L.W., WILSON, K.R. Florida Power Corμ. (subs. of Florida Progress Corp.). 88/11/28, 4pp. 47703 160-47703 163.
 - 8812050182 I.ER 88-025 C0 on 881101.telluro of mactor protection sys channel B to meet all acceptance critoria of survollance procedure unrecognized since 880920 Caussod by personnet error Porsonnet counsolled W/881201 ltr. MOFFATT,t, W., WIDELL,R.C., Florida Power Corp. (subs. of Florida Progress Corp.), 88/12/02, 5pp. 47733 280-47733.284
 - 8812190371 LER 88:006 02 on 880228,unit experienced reactor trip during power de-crease due to feedwater frans ant Caused by broken stem ruit in feedwater B main block valvo Stem nutturbine ling scienci d & circuit fuso replaced W7881213 ltr. MOFFATT,L.W., WIDELL,R.C. Florida Power Corp. (subs. of Florida Progress Corp.) 88/12/13. 9pp. 47850-318-47850-326
 - 8812190381 LER 88-026-00 on 881014 personnel discovered Liquid reliused from evaporator condensate storage tanks before required sampling & analysis performed Caused by failure to sample Tiquid before release Valves evafuated W/881214 III.

 MOFFATT, L. W., WIDELL, R.C. Florida Power Corp. (subs. of Florida Progress Corp.), 88/12/14 4pp. 47849-133-4/849-136.

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8812090267 Requests submitted of allogation invostigation results & disposition of allogation within 45 days of its receipt Enct withheld NORELUS,CE Region 3, Ote of the Director 80/12/02, REEO,C Commonwealth Edison Co. 2pp. 47781 359-47781 360.
- 8812270051 Responds to exercise weaknesses noted in Insp Repts 50-295/68-18 & 50-304/88-18 on 880927-29. Corrective actions, accident mgt course for enshift personnel doveloped by Part Itaning dept in conjunction w/Westinghouse. TRZYNA,G.E. Commonwealth Edison Co. 88/12/06. DAVIS,A.B. Region 3, Ofc of the Director. 3pp. 47926-178-47926:180.

P. Operating license stage documents & correspondence

- 8811280048 Genoric Utr 88-20 to all liconsoes holding OLs & CPs for nuclear power reactor facilities no individual plant exam for severe accident vulnerabilities Svc list oncl CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consoli-dated Edison Co. of New York, Inc. 81pp 47728 303-47729 024.
- 8812010305 Provides analysis of Reg Guido 1 99,Rev 2, "Rathation Embrittlement of Reactor Vessel Malfs" for Impact on pressure-temp horitip & cooldown curves contained in Tach Space per Generic Lir 88-11 RICHTER,MH. Commonwealth Edison Co. 88/11/28 Document Control Branch (Document Control Dask). 2pp. 47703 049-47703 050
- 8812070061 Advisos NRC of 880824 meeting to address issue of Initial ref temp points for WF-70 weld metal in plant reactor vessels W/oncl. TRZYNA,G.E. Commonwealth Edison Co. 80/11/29, Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47737:323-47737-324.
- 8812070035 Forwards safety evaluation supporting util 831105,880822 & 1031 responses to Generic Ltr 83-28,Items 3.1.3 & 3.2.3 re Tech Spocs for post-maint testing
- MULLER,D R. Project Directorate III 2 88/12/02 BLISS,H.E. Caminonwealth Edison Co. 3pp. 47748 086-47748.093.
- -8812070038 Safety evaluation supporting util responses to Generic Ltr 83-28, Items 3.1.3.8.3.2.3 re post-maint testing requirements.
 * NRC - No Detailed Affiliation Given 88/12/02 3pp 47748.089 47748.083
- 8812220206 Forwards proprietary & nonproprietary NFSR-0033, "VIPRE/ WR8-1 DNBR Thermal Limit for Westinghouse OFA Fuel." Allidavit & application for withholding proprietary rept also enci. Proprietary version withhold (ref. 10CFR2-790) TRZYNA,G.E. Commonwastith Edison Co. 88/12/15, Office of Nuclear Reactor Regulation, Director (Post 870411), 4pp. 47892-257-47892-330.

- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list encl. CUNNINGHAM,RE Division of Industrial & Medical Nuclear Safety (Post 870729). 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708/257.
- 8811180467 NHC Info Notice 88-991, "Impropor Administration & Control of Psychological Tosts." Svc list onct.
 ROSSI,C.E. Divis'on of Operational Events Assessment (Post 870411). 88/11/22
 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708:142.

noted P_{3,21} areas, inspected chemistry program, including procedures against training 8 p. in any 8 secondary syst water QC programs. HCLT2VAPA B. SCHUMACHER M.C. Region 3, Ofc. of the Director 68/11/22, 12pp. 47654,039,47654,059.

- 8812140063 Lints in Tiber of tubes prugged in each steam generator as result of most reconting per Tech Speci4 31 8 5 A 6 ECK,T Al Convior wealth Edison Coll 69/11723 DAVISIA Bli Region 3, Ofci of the Director 2pp 47798 341 47799 342
- 8811300442 Formards Safety Insp. Repts 50:235/68-19 & 50:304/88-19 on 880824-1110 & notice of vicin to the Director 68/11/25 REED.C. Commonwealth Edison Co. 2pt. 47671 171-47671 195
- ~8811300445 Notice of violation from inspirer 890824-1110 Violations holed no program displacements of a scalar trial surveillance testing of svolvater pumps performed & con-displacements of the surveillance testing of svolvater pumps performed & con-displacements of the surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of svolvater pumps performed & con-displacements of surveillance testing of surveillan
- -8811300449 Insp. Reprs. 59:295/88-19 & 50:004/89-19 on 850824-1110. Violations noted Major, areas, inspected censee, action on provious insp. (indings, summary of operations Unit 2 topion 881005 & 12 & 681019 Unit 2 valve block shippage. His DS J.M. Pegion 3, Orciot the Director. 88/11/25, 21pp. 47671-175-47671-195.
- 8812010188 Formaids addendum to Insp. Repts 50-295/88.04 & 50-304/88-05 on e80210.coms.strg of comparisons of results of liquid spike sent to plant & criteria for comparing analytical measurements Conservative disagreement in this notad GREGERIA R. Roy on 3. Onto of the Director 88/11/28. REED.C. Commonwealth Edison Co. 1p. 47722.09.47722.092
- -8812020214 Addardum to Insp. Repts 50:295/89.04 & 50:304/88-05, consisting of companies of results of I guid spike sent to plant & criteria for companing enalytical measurements
 - Ofcic! Enforcement (Post 870413), 88/11/28, 2pp. 47722.091-47722.092.
- 8812120024 Informs that investigation of Allegation RIIII-A-88 0086 to afleged door problems discussed in end una 660929 til sufficient. HORELIUS CE Regelon 3, Oto of the Orector 88/12/01 REED,C Commonwoalth Edison Co. 2pp. 47760 151-47780 161.
- -8812120026 Provides response to Allegation Rtd-A-88 0086 re operation of vital area BLISS.H.E. Commonwealth Edison Co. 58/09/29. DAVIS.A.B. Region 3, Ofc of the Director, 9pp. 47780 153 47780 161.
- 8811290030 NRC into Notice 88 093, "Tatetherapy Events." Syc List enct. CUNTINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88 094, "Potentially Undersized Valva Actuators" Svc list ROSSICE Dw.son of Operational Events Assessment (Post 870411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254.
- 8612270051 Responds to exercise weaknesses noted in Insp Repts 50:295/89-18 & 50:394/88-18 on 890927-29 Corrective actions: accident mgt course for onshift porsonnel developed by plant training dept in conjunction w/Westinghouse. TRZYHA, DE Commonwealth Edison Co. 88/12/06 DAVIS.A.B. Region 3, Ofc of the Director. 3pp. 47926-178-47926:180
- 8812020287 NRC Info Nobice 88-095, "Inadequate Procurement Requirements Imposed by Logistos on Yendors" Svot 1st and.
 ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807-191-47807-302.

no reports & related correspondence

ov 1988 for Zion Generating Station Oct 1988 Document Control Branch (Docu-

¹ Zion Units 1 & 2. p. 47911:316-47911:324.

or Zion Generating Station Units 1

325-47911:325

pandence

or three main steam safety valves is Table 4.7-1 Caused by maint

Co. 88/04/11, 6pp. 47649.273-

pump 28 inoperable due to loose improper installation & post-mod

20 88/12/09. Spp. 47826.278-

ator A exhibited teakage. Caused f greater plugged as result of test-e W/681212 lit 1 Co. 88/12/18, 5pp 47871:3056916 "SALP"

69171EH,J.G. Project Dructerale III-3 88/12/13 GRFENMAN,E.G. Region 3, Only the Director 7pp. 47873 343-47873:349.

H. General correspondence

MACH LI EANLYMING COMMUNICATION ACCOUNTS

8812010413 Comment supporting proposed rule 10CFR26 to Fitness to 07, Program,per NUMARC comments Artid comments provided STEINHARDT,CR. Wisconsin Public Service Corp. 88711721. Dockuling & Service Branch 7pp 47678,269-47679,275.

P. Operating license stage documents & correspondence

- 8811280048 Genoric Ltr 88-20 to all licensines holding Obs & CPs for nuclear power reactor facilities re individual plant exam for sovere accident vulnerabilities ${\sf Sec}(x)$
 - CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 89/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47729.303-47729.024
- 8812090107 Application for Proposed Amend 96 to Liconso DPR-43,changing Teo-Spec Section 6 re personnel changes at facility Fee pald HINTZ,D.C. Wisconsin Public Service Corp. 88711/29 Document Centrol Brash (Document Control Dosk) 10pp. 47762-207-47762-235
- -8812090109 Proposed Tech Specsincluding Pages TS 3.10-1,3 10-2 & 316 48.consisting of Proposed Amend 86,reflecting personnel changes at facility *Wisconsin Public Service Corp. 88/11/29, 100p. 47762 217-47762-235
- 8812080030 Forwards revised Tech Specs pages inadvertently emitted from 891123 application for proposed Amend 86 to License DPR-43.
 HINTZ.D.C. Wisconsin Public Sorvice Corp. 88/11/30. Document Centrol Branch (Document Centrol Dosk). 1p. 47755-166 47765.171.
- -8812090146 Revised Tech Spacs to organization, alternates, authority, records 8 reportable events inadvertently omitted from 881129 application for proposed Amend 66 to
- License DPR-43.

 * Wisconsin Public Service Corp. 88/11/29. Document Control Branch (Document Control Desk) 5pp. 47755.167-47755.171.
- 8812070122 Requests that util address Generic Ltr 88-17 re toss of DHR accord.rgytt issued because of potential serious consequence of loss of shutdown cooling conversit w/ significant core decay host. MURLEY,T.E. Office of Nuclear Reactor Rugulation, Director (Post 870411) 88/12/02. STOLL,L. Wisconsin Public Service Corp. 2pp. 47745-244-47745.245
- 8812220132 Forwards proposed schedu's for completion of Gononic Ltr 88-14, "Instrument Air Supply Sys Problems Attacting Sofety-Rotated Equipment." Ltr Littable to complete plant sys review within 180-day deadline Response expected by 890526 STEINHARDT.C.R. Wisconstin Public Sorvice Corp. 88/12/16. Document Control Dask). 10pp. 47014:184-47914:193.

- 8811300487 Forwards Salety Insp Rept 50-305/88-21 on 881017-21140 violations GREGERIL.R. Region 3, Oto of the Director, 88/11/18, HINTZ,D.C. Wisconsin Public Service Corp. 2pp. 47678 032-47678.043
- -8811300494 Insp Rept 50-305/88-21 on 881017-21.No violations nutnd Major aleas Inspected confirmatory measurements & environ monitoring programs including audits, OA & confirmatory measurements of In-plant rachochomical analyses.

 JAHUSKA A G., SCHUMACHER, M. Rogion 3, Ofc of the Director, 88/11/16 47678 034-47678,043
- 8811280102 Forwards Safety Insp Rupt 50-305/88-22 on 881024-28 No violations GREGER,L.A. Region 3, Ofc of the Director, 86/11/21, HINT2,D.C. Wisconsin Public Service Corp. 2pp. 47662.304-47682.317.
- -8811280105 insp Rept 50:305/88-22 on 881024-28 No violations noted. Major 81653 inspected operational radiation protection & radwaste mgt programs.including organization & mgt controls, internal exposure controls & training & qualifications. PAUL.R.A. MILLER,D.E.. GREGER,L.R. Region 3, Old of the Director. 88/11/21 12pp. 47682-306-47662-317.
- 8811290038 Responds to NRC 881021 ltr re violations noted in Insp Rept 50-305/88-16 on 880816-0930.Corrective actions reinstalled jumpers on R-16,reopened steam generator blowdown & blowdown sampling valves & calibr procedure compilated. STEINHARDT.C.R. Wisconsin Public Service Corp. 86/11/21. Document Control Desk). 7pp 47649:178-47649.184.
- 8811180211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges," Svc list enci CUNNINGHAMR E. Division of Industrial & Medical Nuclear Safety (Post 870729, 88/11/22, Consolidated Edison Co. of New York, Inc. 90pp. 47708:255-47708:257.
- 8811160467 NRC Into Notice 68-091, "Improper Administration & Control of Psycholog-cal Tests." Svc list enc). ROSSI,C E. Division of Operational Events Assessment (Post 870411). 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47700:142
- 8811290030 NRC Info Notice 88-083, "Telethorapy Events" Svc list enct. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 89/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811215

- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Sychist
- encl ROSSI,C.E. Division of Operational Events Assessment (Post B78411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708.143-47709.254
- 8812020287 NRC Into Notice 88 095, "Inadequate Procurement Requirements Imposed by Licensoes on Voridos". Svc 1st enct. ROSSI,C E. Division of Operational Events. Assessment (Post 870411). 88/12/08 Conscilidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812160001 Forwards NRFI input for SALP board meeting re-plant, scheduled for 890111 Evaluation conducted in accordance w/890606 rev of NRC Manual Chapter U516, "SALP."
- GIITTER, J.G. Project Directorate III.3 88/12/13 GREENMAN, E.G. Region 3, Old of the Director, 7pp. 47873 343-47873 349.
- A. Periodic operating reports & related correspondence
- 8812140040 Monthly operating rept for Nov 1988 for Kowaunee Nuclear Power Plant.W/881209 ftr.
 RUITER,G.H., STEINHARDT,C.R. Wisconsin Public Service Corp. 88/11/30 5pp.
- 47799 232 47799 236

DOCKET 50-308 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 8812210232 Forwards Physical Socurity Insp. Repts 50-282/88-23 & 50-306/88-23 on 881108-18 No walations includ NORELIUS,C E. Region 3, Otc. of the Director 88/12/08. LARSON,C E. Northern States Power Co. 2pp. 47881-183-47881-186
- -8812210244 Partially withheld Physical Security Insp. Repts. 50:282/88:23 & 50:306/ 88:23 on 881108:18 Violations noted Major areas inspected myt support, security pro-gram plans & audits, protucted & vital area physical barriers. FUNK,D.E. Region 3, Oto of the Director. 88712768.2pp. 47881:165-47881:166.
- 8812210198 Forwards sot of F3 tabs for omergency plan implementing procedures FEY,F.L. Northern States Power Co. 88/12/14. Document Control Branch (Document Control Dosk). 2pp. 47006 299-47006 300.
- P. Operating license stage documents & correspondence
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities to individual plant exam for severe accident vulnerabilities Svc list ond. CRUTCHFIELD.D. Associate Director for Projects (Post 870411): 88/11/23. Consolidated Edison Co. of New York, Inc. 8 (pp. 47728-303-47728.024.
- 8812080122 Requesty that util address Generic Ltr 88-17 re toss of DHR during non-power operation Industry response to Ganeric Ltr 87-12 deficient in areas of preven-tion of accident initiation & initigation of accidents. MIGHEYT.E. Office of Nuclear Reactor Regulation, Director (Post 370411) 88/12/ 02. HOWARD,J J. Northern States Power Co. 3pp. 47755-184-47755.186
- Q. Inspection reports, IE Bulletins & correspondence
- 8612190396 Responds to NRC 880527 & 0607 ltrs ro violation noted in Insp Repts 50-282/88-05 & 50-306/88 495.Corrective actions blown fuse for Bus 16 voltage restoring schemo replaced & bus doctared operable within 20 minutes LARSON,C E. Northam States Power Co. 88/06/27. GULDEMOND,W.G. Region 3. Old of the Director. 2pp. 47851:330-47851:331.
- 8811300508 Forwards Safety Insp Repts 50-282/88-16 & 50-306/88-16 on 880916-1028 & notice of violation. WRIGHT,G.C. Region 3, Otc of the Director, 68/11/21 LARSON,C.E. Northern States Power Co. 2pp. 47877:303-47677.321.
- --8811300512 Notice of violation from insp. on 880916-1026 Violations noted procurement documents which requisition callur of flowmaters did not require that as-found condition be determined WRIGHT,G.C. Region 3, Old of the Director. 88/11/21, 3pp. 47677:305-47677.307.
- -8811300517 Insp Repts 50-282/88-18 & 50-306/88-16 on 880916-1026. Violations noted Major areas inspected becases action on provious insp findings containment integrated loak rate test (CILRT) & CILRT performance witnessing & results review. MENOEZ,R., PHILLIPS,M.P., Rogion 3, Ofc. of the Director 88/11/17, 14pp 47677:308-47677:321.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list encl.
 CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729).
 88/11/22, Consolidated Edison Co. of New York, Inc. 99pp. 47708.255-47708.257.
- 8811150467 NRC Info Notice 88-001, "Impropor Administration & Control of Psychological Tests." Svc list onci.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/11/22.
 Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708:142.
- 8812020213 Forwards Safety Insp Ropts 50-282/88-19 & 50-306/88-19 on 860925-1105 & notice of violation.
 AXELSON,W.L. Region 3, Ofc. of the Director, 68/11/23, LARSON,C.E. Northern States Power Co. 2pp. 47707;182-47707;194.
- -8812020215 Notice of violation from insplon 680925-1105 Violation noted unit person-nol airlock door used but not subsequently tested AXELSON,W.L. Region 3, Ofc. of the Director, 88/11/23, 1p. 47707:184-47707:184.
- -8812020216 Insp Repts 50-282/88-19 & 50-306/88-19 on 880925-1105 Violations noted Major areas Inspected previous insp findings.plant operational

- 8812060149 Forwards Insp Repts 50-282/88-18 & 50-306/88-18 on 880919-22 No vio lations noted GREGER, L.R. Region 3, Ofc of the Circolor, 88/11/30, LARSON, C.E. Northern States Power Co. 2pp. 47740 326-47740 333
- ~8812060151 Insp. Ropts 50-282788-18 8 50-306788-18 on #86/31%-02 No violations roted Major areas inspected concerns associated w/Allegation Rill-A 0111. JANUSKA A , FUNK D , SCHUMACHER,M. Ropton 3, Old of the Director 88/11/30 8pp. 47740-328-47740-333.
- 8811290030 NRC Info Notice 86-993, "To'etherapy Events." Svc 1st en.1 CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Surfly (Post 870729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811 103-47811:215.
- 8811290538 NRC Into Notice 88-004, "Potentially Undersized Valve Adjusters." Syc Lst ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consulidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254
- 8812120118 Forwards addit response to NRC IE Bulletin 89-08 re exam of containment Inter ponditation welds Util believes that inability to radiograph waus not of cuncern MUSQLE,D Nothern States Power Co. 88712705. Office of Nuclear Relator Regulation, Director (Post 870411), 7pp. 47789.086-47789.074.
- 8812140237 Forwards Safety Insp. Repls. 50-282/88/21 8: 50-306/88/21 on 881114-18 No violations noted GREGERLER Rep on 3, Otc of the Orestor, 88/12/06 LARSON,CE, Northern States Power Co. 2pp. 47800 344-47860/351.
- -8812140239 Insp. Repts 50:282/88:21 & 50:306/88:21 on 881114-18 No violations noted Major areas inspected action on previously identified items,emorgency plan activations & operational status of emergency proparedness program SMITH,M.J., SNELL,W. Region 3, Otc of the Director 88/12/05, 6pp. 47000.346-3200.25. 47BD0 351.
- 8812020287 NRC Info Notice 88 095, "Inadequate Procurement Registements Imposed by Licansees on Verdors" Svc hist encl.
 ROSSLC E. Division of Operational Events Assossment (Post 870411) 88/12/08
 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47407:192
- 8812120005 Forwards proproducy & conproprietary safety evaluation of NRC Bullotin 88 002, "Rapidity Propagating Faliguo Cracks in Steam Generator Tubes." Finding subj to adoption of additionalizative controls. DIMANI,D.C. Project Directorate III-1. 88/12/08 MUSOLF,D.M. Northern States Power Co. 4pp. 47787,193-47787 199
- -8812120009 Safety evaluation accepting licenside analyses documented in WCAP-11787.Based on satisfactory resolution of Item C 2 of Bulletin 88 002 Tempsed may terminate commitment to enhanced leak rate monitoring program.

 **Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/08. 3pp 47787:197-47787 199
- 8812210232 Forwards Physical Sucurity Insp Ropts 50:282/88:23 & 50:306/88:23 on 881108:18 No violations noted NORELINIS,C.E. Rogion 3, Otc. of the Director 88/12/09 LARSON,C.E. Northern States Power Co. 2pp. 47881:163-47881:166
- -8812210244 Partially withhold Physical Security Insp. Ropts 50-262/88-23 & 50-306/88-23 on 881108-18. Violations noted Major areas inspected.mgt support, security program plans & nuffls, protected & vital area physical barners. FUNK.D.E., PIRTLEGIL, CREED, J.R. Rogion 3, Otc of the Director 88/12/08, 2pp. 47881:165-47881:166.

R. Periodic operating reports & related correspondence

8812140263 Monthly operating ropts for Nov 1988 for Prairio Island Nuclear Generating Plant W7681207 ftr. DUGSTAD, D., MUSOLF, D. Northern States Power Co. 88/11/30 9pp. 47821 061-47821:069

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

- F. Security, medical, emergency & fire protection plans
- 8812120031 Forwards Insp. Rept. 50:309/88-16 on 881006-1119.No violations noted.NRC concerns about number of wiring discrepancies Identified during outage & Interest in understanding root cause/causes of problems & resolution of discrepan-
- cies. WIGGINS, J.T. Region 1, Olc of the Director, 88/12/05 RANDAZZA, J.B. Maine Yankee Atomic Power Co. 2pp. 47785.188-47785-203
- --8812120032 Insp Rept 50-309/88-16 on 881006-1109.No violations noted Major areas inspected plant operations & outage activities, including followup on previous insp findings,roview of special ropts,ficonsee event followup,maint & surve liance. TRIPPLE. Region 1, Ofc of the Director. 88/12/01. 14pp. 47785.190-47785.203.
- 8812230030 Forwards Physical Security Insp. Rept 50:309/68:20 on 881114:18 Violations noted Enforcement conference scheduled on 881220 to discuss violation involving missing security & vital area keys.

 EBNETER.S.D. Region 1, Ofc. of the Director, 88/12/08. HANDAZZA,J.B. Maine Yankee Atomic Power Co. 3pp. 47911:008-47911:013
- --8812230032 Parually withheld Physical Security Instr Rept 50:309/88:20 on 881114-18 (rel 1905/R2.790). Noncompliance noted in areas of vital area key control access control & protected area lighting Major greas inspected access control & verticus.

- P. Operating license stage documents & correspondence
- 8811300165 Requests NRC permission to dispose of slightly contaminated chemical cleaning solution used in cleaning of secondary side of steam generators per 10CFR20 302(a) Fee paid.
 WHITTLER.G.D. Maine Yankee Atomic Pawer Co. 83/11/22 Decument Centrol Branch (Document Centrol Dask). 26pp. 47880 175, 47680 200.

- 8812060291 Application for amend to License DPR-34,consisting of Proposed Change 134 to main steam excess flow check valve. Amend modifies Tech Spec 4 6 to partiodic losting by extending specified surveillance testing interval RANDAZZA, J.B. Maine, Yankee, Atomic, Power, Co., 89/11/22, Document, Control Branch (Document Control Desk) 8pp 47734 239-47734 249
- -8812060292 Proposed Tech Specs supporting Change 134 re-main steam excess flow check valve & furbing valve losting frequency.
 * Maine Yankse Atomic Power Co. 88/11/22 3pp 47734 247-47734 249
- 8811280048 Generic Ltr 88:20 to all licensees holding QLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list endi CRUTCHF:ELD.D. Associate Director for Projects (Post 870411) 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729-024.
- 8812120231 Requests assurance that util addresss Generic Ltr 68-17 re loss of DPA during responds operation.
 MURLEY,T.E. Offica of Nuclear Reactor Regulation, Director (Post 870411). 88/12/02. RANDAZZAJB Maina Yankee Atomic Power Co. 2pp. 47786 199-47786 200
- 8812150092 Application for amend to License DPR-36 consisting of Proposed Change 145 to combined healtip, cool-lown, pressure 8 temp limitations Fee paid RANDAZZAUS Mairio Yankee Alomic Power Co. 88/12/02 Document Control Branch (Document Control Branch (Document Control Desk) 9pp. 47808/330-47807-180.
- -8812150096 Proposed Tech Specs consisting of Proposed Change 145 in combined heatup.cooldown & pressure lemp I m taj ons
 * Maine Yankge Atomic Power Co. 88/12/02, 22pp. 47806 339:47806.360
- -8812150107 "Summary of Fast Neutron Exposure Evaluations for Maine Yankee Re-ANDERSON'S L., LIPPINCOTT,E P., LAU,F L. Westinghouse Electing Corp. 88/11/30 81pp. 47807.001-47807.082.
- --8812150110 "Reactor Pressure Vessel Betino Matis Assessment Maine Yankee Atomic Power Plant Byrnesing, Inc. JONES,H.F., PLANTE,P.J. Maine Yankee Atomic Power Co. 88/09/30, 50pp. 47807.093.47807.132
- -8812150113 "Final Rept on Pressure Temp Limits for Maine Yankee Nuclear Power * Combuston Engineering, Inc. 88/07/31 Maine Yankee Atomic Power Co. 48p. 47807:133-47807:180.
- 8812150012 Forwards updated assessment of fracture toughness for protection against PTS.In accordance w/10CFR50.61 WHITTIER.G.D. Man e. Yankee Atomic Power Co. 88/12/08. Document Control Branch (Document Control Desk). 5pp. 47829.211-47629.216.
- 8612130121 Advises that certein tests required by 1980 ASME Code, Section XI.defermined to be impractical per 10CFR50 55a(g). Bases for determination de-
- scribed enci WHITTIER G.D. Maira Yankee Atomic Power Co. 88/12/05. Document Control Branch (Document Control Desk), 3pp. 47794.073-47794.075

Q. Inspection reports, IE Bulletins & correspondence

- 8811290220 Informs that additime will be required to respond to 870729 request for additinfo re Action Item e of IE Bufletin 85-003.Response within addit 30 days expect-
- 8811290115 Forwards status rept for IE Buttetin 85-003, "Motor-Operated Valve Common Mode Failures Dunng Plant Transients Due to Improper Switch Settings," Info in rept prosented in accordance w/Act on Item f of bulletin RANDAZZA, J.B. Maine Yankee Atomic Power Co. 87/12/15. RUSSELL,W.T. Region 1, Ofc of the Director. 3pp. 47664-008-47664-088.
- -8811290122 "Maine Yankee Atomic Power Co Program for Selected Motor- Operated Valves, Status Rept. Connecticut Yankee Atomic Power Co 87/12/15, 52pp 47864 010-47684:088.
- 8811290208 Forwards corrected page to util 880115 response to NRC Compliance Bul-

letin grade. WhitTIER,G.D. Ma'ne Yankee Atonic Powar Co. 88/01/29. RUSSELL,W.T. Region 1, Old of the Director. 1p. 47651:113.47651.113.

- 8811290056 Forwards updated response to NRC Bulletin 87-001 re thinning of pipe waits including consol dated into re past pipe Insps FRIZZLE,C.D. Maine Yankee Atomic Power Co. 68/02/11. RUSSELL,W.T. Region 1, Ofc of the Director. 5pp. 47650/252-47650:255.
- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list end. CUNNINGHAM,R.E. Dission of Industrial & Modical Nuclear Safety (Post 870729), 88/11/22 Consolidated Edison Co. of New York, Inc. 09ap. 47708 255.47708 257.
- 8811160487 NRC Info Notice 98-991, "Improper Administration & Control of Psychological Tests " Svc list enc! ROSSICE Division of Operational Events Assessment (Post 870411). 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708.142.
- 8811290030 NRC Info Notice 88-993, "Teletherapy Events." Svc l'et anci. CUNNINGHAM,R.E. Division of Industrial & Madical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.

- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators," Synty-ROSSICE Division of Operational Events Assessment (Post 870411) 68/12/22 Consolidated Edison Collaboration (New York, Inc. 121pp 47708:143-47708:254.
- 8812120048 Forwards Meeting Rept 50:309/88:163 on 881018
 MARTIN,T.T. Region 1, Old of the Director, 08/12/04, RANDAZZA,J.B. Mainu Yerkib
 Atomic Power Co. 2pp. 47769 127-47789.147.
- ~8812120049 Mgt Meeting 50-309/88-163 on 881018 Mejor areas discussed clieby power issues & breaker interrupting capacity at plant.Meeting agenda & handomic of DURRU Region 1, Ofc of the Director 88/11/28 (19pp. 47789-129-4778) 147
- 8812120031 Forwards Insp. Rept. 50:309/88-16 on 881006-1119 No violence noted NRC concerns about number of wiring discrepancies identified during 0.1838 & interest in understanding roof cause/causes of problems & resolution of discrepancies. WIGGINSUIT, Region 1, Oto of the Director, 88/12/05 | HANOAZZAJIB | North Yankee Alcinic Power Co. 2pp. 47785-188-47785-203.
- --8812120032 Insp. Rept. 50-309/88-16 on 881006-1109 No violations nate: Major areas inspected plant operations 8 outage activities, including following on previous insp. Indings.review of special repts. Censee event following.natint 8 survice listone. TRIPP,LLE Region 1, Ofc of the Director. 88/12/01. 14pp. 47785-190 47785-203
- 8812020287 NRC Info Notice 88 095, "Inadequate Procurement Requirements imposed by Licensees on Vendors" Svc list enct. ROSSIC 6 Division of Operational Events Assessment (Post 870411). 88/12/6-Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302
- 8812230030 Forwards Physical Security Insp. Rept. 50:309788-20 on 881114-18 Vio.1 tions noted Enforcement conference scheduled on 881220 to discuss violation lines. ing missing security & vital area keys.
 EBNETER.S.D. Region 1, Ofc of the Director. 88/12/08 RANDAZZA,J.D. Mane Yankee Atomic Power Co. 3pp. 47911.009-47911.013.
- -8812230032 Partially withhold Physical Security Insp Rept 50:309/88:20 on 881114-18 (ref 10CFR2.790) Noncompliance noted in areas of vital area key control access control & protected area legistry Mayor areas inspected access control & vehicles LANCASTER,W.K., OLSEN,W.P., SYLVESTER,E.D. Region 1, Ofc of the Director £3/12/07. 2pp. 47911.012-47011:013.

S. Reportable occurrences, LERs & related correspondence

8812130091 LER 88-009-00:on 881108 two excere neutron flux monitor cable asserbles laired mits pressure test & developed leaks in cable assembly Affected cable assembly Affec 47791:358-47791:360.

V. Operator Examinations

8812090152 Advises that simulator operating exam scheduled for 890118. Util request ed to provide ref malls usted in encl by 881219. ESELBROTHE-W. Region 1, Dic of the Director, 88/11/30. RANDAZZA.1B. We to Yankee Alomic Power Co. 6pp. 47754:233-47754:238.

DOCKET 60-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8812020133 Rev 7 to Artificial Island Emergency Plan Station Procedure EPiP-2025 "Operations Support Ctr (OSC) Activation & Operations."

 * Public Service Electric & Gas Co. of New Jersey. 89/12/02. 26pp. 47722 IS8
- 8812150264 "Artificial Island Emergency Plan, Annual Exercise," conducted on 001123-
 - Public Service Electric & Gas Co. of New Jersey, 88/12/31, 450pp. 47615:138 47818:296

P. Operating license stage documents & correspondence

- 8811280024 Informs that all postulated events re Cycle 5 reload analysis within allowable limits & no unroviewed safety questions involved.

 MILTENBERGER,S. Public Service Electric & Gas Co. of New Jorsey. 88/11/15. Document Control Desk). 5pp. 47644:340-47644:344
- 8811280048 Generic Lir 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities to individual plant exam for severe accident vulnerabilities. Svc list and CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729:024.
- 8811360303 Summary of 881116 meeting w/util in Rockville,MD re util long-range pro-grams at plants & NRC long-range efforts STONE,J.C. Project Directorate I-2, 88/11/25, Project Directorate I-2, 4pp. 47677.132-
- 8812050041 Forwards response to Generic Ltr 88-11, "Radiation Embritifement of Ric actor Vessel Matis." Util will submit license amend requests to incorporate new heatup & cooldown curves in Tech Specs for Salem Units 1 & 2 by Dec 1988. MILTEMBERGER,S. Public Service Electric & Gas Co. of New Jorsey. 88/11/28. Document Control Branch (Document Control Desk). 7pp. 47732-021-47732-027.
- 8812050222 Summary of 881122 meeting w/util in Rockville,MD re preparation of teological assessment of sea turtle occurrences at plant. Agenda encl. STONE, J.C. Project Directorate I-2, 88/12/01, Project Directorate I-2, 6pp. 47745 009-2245 (Agenda et al., 2009-2245). 47745.013.

Region Lole to discuss design basis reconstitution. SWETLAND.P.D. Region 1, Otc of the Director 88/12/01. Region 1, Otc of the Director 2pp. 47788.118-47788.119.

- 8612150094 Documents agreement between util & J Stone & G Riverbark of NRC re-extending response submittal date for Generic Ltr 88-14 concerning instrument air supply sys MILTENBERGER,S Public Service Electric & Gas Co. of New Jersey. 88/12/06. Document Control Branch (Document Control Desk). 2pp. 47835-001-47835-002.
- 8812150004 Requests withdrawal of util 851119 application for amonds to Licenses DPA-70 & DPR-75 consisting of License Change Request 84-23 deleting App 8 of environ Tech Spacs & substituting withorizon protection plan MILTENBERGERS Public Service Electric & Gas Co. of New Jursey 88/12/09 Document Control Branch (Document Control Desk). 2pp. 47823-013-47823-014
- 8812210025 Approves 881022 milline of biological assessment re-sea turtles, subj. to in-cluding description of tresh bar cleaning process & dutails of operational aspects to minimize capture of sea turtles STONEUC Project Directorate 1-2 88/12/14 MILTENBERGER,S Public Service Electric & Gas Co. of New Jersey 4pp. 47881.157-47881:160.

Q. Inspection reports, IE Bulletins & correspondence

- 8812090076 Forwards response to NRC Bulletin 88-002 re-potential for rapidly propogaining fatigue cracks in steam generator tubes.
 MILTENDERGER,S. Public Service Electric & Gas. Co. of New Jersey. 88/03/28.
 RUSSELL,W.T. Region 1, Ofc of the Director. 21pp. 47757:318-47757:338
- 8811300351 Responds to NRC 881013 ltr re-violations noted in Insp Repts 50-272/88-17 & 50 311/88-17 Short term actions have been developed to quickly establish nec-
- ossary controls to effectively prevent future surveillance problems.
 MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey, 88/11/18. Document Control Branch (Document Control Desk). Spp. 47674:136-47674. 140.
- 8811290404 Forwards Safety Insp Repts 50-272/88-19 & 50-311/88-20 on 880927-
- 1107.No violations noted. WENZINGER,E.C. Region 1, Old of the Director, 88/11/21, MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 2pp. 47657:305-47657:324.
- -8811290412 Insp Repts 50:272/80-19 & 50:311/88-20 on 880927-1107 No violations noted Major areas inspected; plant operations including operational safety verification, mainti, LERs review, surveillance, Unit 2 outage activities & inspiritens follows:
- up SWETLAND,P.D., BROCHARDT,R.W., GIBSON,K11 Region 1, Oic of the Director. 68/11/21, 18pp 47657.307-47657:324.
- 8812020018 Advises that util 180811 response to NRC Bullotin 88:094 adequately provided 13fo requested in Items a,b,c,8 d of subjibullotin.Min recrecibition flow results requested within 30 days of completion of evaluation.

 STONEUJ C Project Directorials 12: 88/11/21 MILTENBERGER,S. Public Survice Electric & Gas Co. of New Jorsey. 4pp. 47707.184-47707.187.
- 8811160211 NRC Into Notice 88-080, "Unauthorized Removal of Industrial Nuclear Grugos," Svc list end CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729), 88711722; Consolidated Edison Co. of New York, Inc. 98pp. 47708 255-47708:257.
- 89 11160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests." Svc list and ROSSI, C.E. Division of Operational Events Assessment (Post 870411) 88/11/22. Consol dated Edison Co. of New York, Inc. 101pp. 47708.042-47708 142.

- 8811290034 Forwards Rethological Controls Insp Ropts 50-272/88-18 & 50-311/88-18 on 880326-1006 & not co of violation BELLAMY.R.R. Rogion 1, Otc of the Director. 88/11/22. MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 3pp. 47650:256-47650:280.
- -9811290035 Notice of violation from inspient 880926-1006 Violation noted rolling tool withdrawn from reactor cavity pool w/o required dose rate survey performed & work crow allowed to work in restricted seal table room.
 * Region 1, Otc of the Director, 88/11/22 2pp. 47850 259-47650:260.
- --8811290040 Insp. Repts 50:272/88-18 & 50:311/88-18 on 880926-1008. Violation noted Mejor areas inspected radiological controls organization & staffing personnel queflications & training, corrective action sys & performance monitoring & ALARA. NIMITZ.R.L., O'CONNELL,P.V., SHANBAKY,M.M. Region 1, Ofc of the Director. 88/11/16, 20pp. 47650.261-47650-260.
- 8811290364 Forwards Mgt Mooting Repts 50-272/88-18 & 50-311/88-18 on 681020 Meoting repts summarize discussion on NRC Identified weeknesses in area of industrial safety, radiological controls & fell of worker into reactor cavity on 881018. EBNETER,S.D. Region 1, Otc of the Director. 88/11/22. MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 3pp. 47665-049-47665.078.
- --8811290365 Mgt Meeting Ropts 50-272/88-18 & 50-311/88-18 on 881020. Major aroas discussed recent NRC identified weaknesses in aroa of industrial safety & radio-logical controls & fall of worker into Unit 2 reactor cavity on 881018. NIMITZ.R.L. Region 1, Otc of the Director. 88/11/18, 27pp. 47865-052-47665-078.
- 8811290030 NRC Info Notice 88:093, "Teletherapy Events." Svc list encl. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103
- 8811290538 NRC Into Notice 88-094, "Potentially Undersized Valve Actuators" Svc list enci ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02 Consol dated Edison Co. of New York, Inc. 121pp. 47708-143-47708-254.

celerated steam generator tube insps Util will have to comply w/1 bch. Spec. 4.4.6.3 b. 8. increase steam generator insp frequency to max 20 months for facility. STONE, JC. Project Directorate I-2. 88/12/05. NICHOLLS,G.P. New Jorsey, State of 5pp. 47754-134-47754-143.

- 8812020287 NRC Into Notice 89:095, "Inadequate Procurement Requirements Imposed by Liconseps on Vendors" Svc list oncl.

 ROSSI,C E Division of Operational Events Assessment (Post 870411) 88/12/08. Consolidated Edison Co. of Now York, Inc. 11/2pp. 47807-1191-47807-302

R. Periodic operating reports & related correspondence

- 8811290465 "NFDES Discharge Monitoring Ropt for Cct 1988 " W/881123 itr TREJOJ. Public Service Electric & Gas Co. of New Jersey, 88/10/31 CAPORALE New Jersey, State of, 25pp. 47650 053-47650 077
- 8812190256 Monthly operating ropt for Nov 1988 for Salom Generating Station Unit 2 W/881211 lift ORTICELLE A, WHITE.P., MILLER,L K. Public Service Electric & Gas Co. of New Jersey, 88/11/30 13pp 47860 045 47860 060

S. Reportable occurrences, LEAs & related correspondence

- 8811290494 Special Rept 88-8 on 881031,pressurizer overpressure protection sys (POPS) actuated Caused by equipment problem due to sotting of Channel II selpoint for POPS above Toch Spec 3.4.10.3 a POPS channels recarb.

 MILLER,L K. Public Service Electric 8 Gas Co. of New Jorsey 88/11/16. Document Control Branch (Document Control Desk). 3pp. 47665.173-47665-175.
- 8811290550 LER 88 021-00 on 861031, hourly roving fire watch patrol for soveral areas not comploted within 1h.Gaused by personnel error Personnel given modical litness for duty exam 8 site protection deptingt reviewed event W/881116 lir. POLLACK,M J. MILLER,L.K. Public Service Electric & Gas Co. of New Jersey. 88/11/16. 4pp. 47850.210-47850.21
- 8811290554 LER 88-022-00 on 881022 & 23 visual exem of containment spray valves 21 & 22CS8 revealed cracks in valve cashing Course attributed to transgranular stress corresion cracking Valves temperarily replaced w/p.ping species W/881116 ltr. POLLACK,M.J., MILERI, K. Public Service Electric & Gas Co. of New Jersey, 88/11/18, 5pp. 47865-084-47665-088.
- 8812070069 Supplemental Special Rept 88:5-1 on 800817, fire barrier penetrations impaired for greater than 7 days Complete review of line protection program initiated Impaired penetrations resealed utilizing existing procedures MILLER, L.K. Public Service Electric 8 Gas Co. of Now Jersey, 88/11/30 Document Control Branch (Document Control Desk) 3pp 47/46 083-47746 085.
- 8812220165 PNO-1-88-125 on 881209.tac.lity removed from svc dud to high combustible gas (accitylone) concentrations on Phase C of main power transformer Licensee plans to replace freeformer w/spare.

 GIBSON,K., SWETLAND,P. Rog on 1, Ofc of the Director 88/12/12, 1p. 47892:242-47092 242
- 8812190306 LER 88-023-00 on 860912,discovered that soveral radiation monitoring sys monitors were cally low due to use of incorrect cally source response info.Caused by inadequate admin strative controls Monitors call br W/881214 ltr. POLLACK,M.J., MILLER,L.K. Public Service Electric & Gas Co. of New Jersey. 88/12/14, 7pp. 47852.145-47852.151.

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

F. Security, medical, emergency & fire protection plans

- 8811280091 Forwards forty-five day submittal for "Rancho Seco 1988 Annual Exercise 8 Dross Rehearsels "
 FIRLIT.J.F. Sacramento Municipal Utility District. 88/08/17. MARTIN.J.B. Region 5, Oic of the Director. 2pp. 47659.057-47662:159.
- --8811260095 "Rencho Soco 1086 Annual Exercise & Dress Rehearsals."

 * Secremento Municipal Utility District. 88/08/17, 1,000pp, 47659 059 47662:159.
- 8811290347 Advises that Rov 13A to plant physical security plan consistent w/provisions of 10CFR50 54(p) & acceptation
 SCARANO,R A. Region 5, Ofc of the Director, 88/11/15, FIRLIT,J.F. Sacramento Municipal Utility District. 2pp. 47665:271-47665:272.
- 8812050110 Forwards rev to physical security plan reflecting administration changes within security dopt. Rev withheld (ref. 10CFR2.790).
 SHETLERJ.R. Secremento Municipal Utility District. 88/11/29. Document Control Branch (Document Control Desk). 1p. 47731.201-47731:201
- 8812190334 Forwards Insp Ropt 50:312/88:31 on 880907-1021 & notice of violation.Program for monitoring pipe wall thinning in response to IE Builetin 87-001 Inadequate.
 ZIMMERMAN.R.P. Region 5, Old of the Director, 88/12/06, FIRLIT, J.F. Sacramento Municipal Utility District. 2pp. 47860:026-47860.044.
- --0812190342 Insp Rept 50-312/68-31 on 880907-1021 Violations noted. Major ereas inspected operational safety verification health physics. & security observations, ESF sys walkdown, maint, surveillence & testing, OA & followup items. Dr.ANGELO.A.J., MYERS.C.J., OUALLS.P.M. Region 5, Otc of the Director. 88/12/06. 16pp. 47860:029-47860.044.
- 8812210058 Advises that 880906 Change 2 to emergency plan consistent w/ provisions of 10CFR50.47(b) & App E. & acceptable. FISH.R.F. Region 6, Ofc of the Director. 88/12/09 FIRLIT, J.F. Sacramento Municipal Utility District. 3pp. 47875.358.47875:358.

8812210141 Advises that raceway used as part of facility security sys upgrada will pro-vide projection opusitio App R exemption per discussion windin CHOLEY, B.G. Sarramono Municipal City District 88/12/15 Khighton, G. Docu-ment Control Branch (Document Control Desk), 2pp. 47861-142-47881,143

N. General Correspondence

8812010130. Comment supporting proposed rule 10CFR26 re INRC fitness for duty program Recommendations issed. FiRITILE Secrementations used by the Destrict 88/11/18. KNIGHTON,G. Document Control Branch (Document Control Bosts). 40pp. 47678 164-47678 203.

P. Operating license stage documents & correspondence

- 6811110019 Forwards NRC assessment of environ radioactive contamination in vicinity of plant 8 NUREG CR-4256, "Evaluation of Radioactive Liquid Effuent Refeases from Rancho Seco." Evaluations concluded offsite environ confaminated STOLZU, PWR Project Discovate 6-88/11/11 RODRIQUEZR J. Sacramento Mu-Gopal Utility District 7pp 47682 086 47682 092
- 8811290346 Forwards rept summarizing status of procurement engineering assossment plan as of 981031 CROLEY,B.G. Sacramento Afuncipal Ublity District 88/11/18 Document Control Branch (Document Centrol Desk) 20pp 47684 340 47664 359.
- 6811290343 Summarizes CU positions & commitments re leaf repair of pfant components per 881027 telcon w/NRC Analysis of chemical characteristics of scalant used on Vativos RCS-510 & HV 21510 encl. FIRELTILE Secremento Municipal Unity District 88/11/22, XM GHTCN,G. NRC No Detailed Affiliation Green. 4pp. 47665 265-47665 268.
- 8811280048 Generic Etri 88:20 to all licensees holding CLs & CPs for nuclear power reactor facilities as individual plant exam for sevare accident vulnorabilities Svo tist
- CRUTCHF,ELD,n Asso ate Director for Projects (Post 870411) 88/11/23 Consol-dated Edison Co. of New York, Inc. 81pp. 47728 303-47729 024
- 8811300244 informs that due to extended drought in Stato of CA unit plans to operate plant at nominal 92-94% power level Encl procedures identified for performance at 100% power level more of Municipal US/Ny District 88/11/23 Document Control Branch (Document Control Branch (Document Control Branch (Document Control Branch)
- 8812060009 Requests that SER for Amend 92 be revised to extend refusing intorvat for reactor, vessel, vent, valves, to Cycle, 8 refueing outage, but no later than Sept, 1969 Safety analysis enci. FIRLIT.J.F. Sacramanto Municipat Utility District, 88/111/29, KNIGHTON,G. NRC No Detailed Alfination Green, 7pp. 47753,007-47753,013.
- 6812150139 Requests response to Generic Ltr 88-17 re loss of DHR. Industry response 472150139 Requests response to Generic Liv 88-17 re-loss of DHH. Industry response to Generic Liv 87-12 deficient in areas of prevention of accident inclation & mitigation of accidents before progressing to core damage. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/02. FIRLIT, J. Sacramento Municipal Uti ty District, 3pp. 47830-181-47830, 183.
- 8812190408 Forwards Rev 0 to 69031-01, "Phase 1 Independent Performance Evalua-tion of Rancho Seco Nuclear Generating Station" Public hearing will be held on 881215 to discuss rept Second rept scheduled for completion in May 1989. FIRILIT, IS Sectamento Manicipal Unity District 88/12/09 MARTIN, J.B. Region 5, Ofc of the Orector 1p. 47855-125-47855-193.
- -8812190409 "Phase 1 Independent Performance Evaluation of Rancho Seco Nuclear 8812190409 Priess - Independent - Congressing State - Christophile - Christophile
- 8812200124 Forwards revised pages to "Rencho Seco Quality Menual"
 CRUNK S.L. Sacramento Municipal Udity District 887/2712 Document Control Branch (Document Control Desk). 20pp. 47861:217-47861.313
- --8812200130 Revised "Rancho Seco Quality Manual." FIRLITLE Secremento Municipal Utility District 88/11/18, 78pp. 47861 236-47881.31
- 8812210383 Forwards Director Decision DD-88-20 under 10CFR2 206,draft rule dtd 880922 & FR notice reidrug testing program at plant.

 MURLEY,T E. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/
 14 MOLLER,B. Affiliation Not Assigned 4pp 47889.090-47889.200.
- -8812210394 Director's Decision DD 88.20 under 10CFR2 206 re drug testing of all individuals at plant Petition demed.

 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/
 14. 128pp 47889 097-47889 224.
- -8812210398 Notice of issuance of Director's Decision DD-68-20 re drug testing program at plant Patition under 10CFR2 206 denied. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/ 14 6pp 47889 225 47889 230

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list encl CUNNINGHAM R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811180467 NRC linfo Notice 88-091, "Improper Administration & Control of Psychologi-
- cal Tests." Svc list encl. ROSSICE Division of Operational Eventa Assessment (Post 870411). 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708:142.
- 8812070068 Forwards Mgt Meeting Rept 50:312/88:35 on 881114 Since restart.util has operated plant successfully.Commitments to NRC to be completed after restart not yet met.

 Yet met.

 KIRSCH,D.F. Region 5, Orc of the Director, 88/11/22 FIRUT,J.F. Sacramento Municipal Utility District. 1p. 47746 322-47747.030.

- -8812070070 Mgt Mediknji Richt 50.312/88/35 on 881114 Major areas discussed licensed operational performance function testart in Mar 1988 & progress represent communication areas of originization operational & alliumni systems, MILLER, E. F. ZIMMERMAN, E.P. Region 5, Ofc. of the Director 88/11/21 65g. 47746.323-47747.030
- 8811300013 Responds to violations includ in linip Hopt 50:312788.32 Correctly actions (ICCF)50.59 dutermination resisted to include impact of USAR Figure 9.5.1 FIRLIF, J.F. Secramento Micropal Bibly District 188/11723 Document Control Branch (Occument Control Branch 1994) 47673.109.47673.112
- 8812150098 Forwards list of red purchase order curetiers & dates of purchases by lac by from Planned Maint Systinc, for review, per ISHC Into Notice 89 019, "Questionable Cortification of Class IE Composents" KN GHTON, G.W. Project Directorate V BB/11723 FIRLIT, it Secremento Mucicial UNIty District, 5pp. 47823-045-47823-049
- 8812150152 Discusses refineling cavity soil per Bulletin 84-03 Fletheling cavity shallow sists of metal ordular plate formed to span, gray technique metal ordular visits a following sists of metal, citcum prato, control of span god control of statem version of the least KALMAN, G. Project Deoctorate V 88/11/39 HOUGE, V. Gonene Communicates Branch 2pp 47825 011-47825 012.
- 8811290030 NRC Into Notice 88-093, "Tetallianary Events," Svc list oncl CRNNINGHAM,R.E. Division of Invitatinal & Modrial Nuclear Salety (Post 87072s) 88/12/02, Consolidated Edison Co. of New York, Inc. 112pp. 47811.103-47811.215
- 8811290538 NRC Info Notice 88-034, "Potentially Undersized Valva Actuators" Syr. 4 ROSSICE, Division of Operational Events, Assessment (Post 870411), 88/12/02 Consolidated Edison Co. of New York, Inc., 121pp, 47/708, 143-47/08, 254
- 8812130182 Fewards Ofc of Investigation Summary rept to Caso 5-87-011 concerning activities authorized by Licenso DPFI-54 No violations noted. KIRSCH, O.F. Region 5, Ofc of the Director 46712766 FIRCH, J. Sacramonio Municipal Utiny District 2pp. 47795.335-47795.397.
- 6812190334 Forwards tosp Rept 53.312780-31 on 683007-1021 & notice the violation Program for monitoring pipe wall thinning in response to IE Butletin 87-67 ZIMMERMAN, R.P. Region 5, Old of the Director, 88712706 FIRLIT, J.F. Sacramen's Municipal Utility District, 2pp. 47866 028-47860 044
- -8812190339 Notice of violation from inspiron 880007-1021 Violation noted design basis of safety-related sys not correctly translated into procedures & Instructions, ZIMMERIMAN,R.P. Region 5, Oic of the Director 80/12/06 to 47660 028 47860 02A
- -8812190342 Insp. Rept 50-312789-31 on 880907-1021 Violations holod. Major areas inspected operational safety vertication, hualth physics & socially observations, ESF sys walkdown, meant, surviviance & testing, OA & following turns D'ANGELOA J., MYERS.C.J., GUALLS, P.M. Region 5. Ofc of the Director 88/12/06 10pp. 47860 029-47860 044
- 8812020287 NRC Info Notice 88-095, "Inarrequeste Procurement Requirements Imposed
- by Licensees on Vendors "Svc list and Research (Post 870411) 88/12/83 ROSSICE, Division of Operational Events Assessment (Post 870411) 88/12/83 Consolidated Edicon Co. of New York, Inc. 112pp. 47807, 191-47897 302.
- 8812210245 Ack receipt of 881123 ftr informing NRC of stops taken to correct violations noted in Insp Rept 80-312788-32 on 681026 ZIMMERMAR P. Roglon 5, Otc of the Director. 68712714. FIREIT, J.F. Sacramen's Municipal Utility District. 19. 47881-311-47881-315

S. Reportable occurrences, LERs & related correspondence

- 8811300019 LER 88 016 00 on 881027 sample flow to radiation monitor R-15546A lost rendering notice gas monator 8 perfectate & charcoal samplers inoperatio Cause unknown Sample flow to monator restored W/861123 ftr. SOWSER.R.W., FIRLIT.,I.F. Sacramento Municipal Utility District. 88/11/23 4pp. 47673 245-47673 249.
- 8811300020 LER 88-014-00 on 881025.Tech Spec required shutdown due to RCS lakkage Cassed by degradation of two valves due to sec in RCS RCS repaired by sea welding body to bonnet joint, then injecting valvo w/loak sociant W/881123 for RUTTER.S., FRUTT.J.F. Sacramento Municipal Utility District 88/11/23. 5pp 47871:001-47871:005.
- 8811300256 Special Ropt 88-18.on 881025 8 26.ftt.luro to mpintain specific activity of primary sys within administrative limits occurred Afternate lobdown sys punheation deminerative placed in size KEUTER, D.R. Sacramanio Municipal Ubity District 88/11/23, MARTIN, J.B. Region 5, Orc of the Director, 5pp. 47671;225-47671,228
- 8812070002 PNS-V-88-006-on 881125, I can see received to Icon alloging that nonlineared equipment operator observed using illegal drugs inchvidual submitted to urically sets & showed positive for manipuana individual terminated on 881130. SCHUSTER, D. Region 5, Ofc of the Director 88/11/30. 1p. 47748-237-47748-237.
- 8812140017 Special Ropt 88-19.on 881109 & 11 fire barriers breached more than 7 days Caused by fire doors not restored to operable status Fire doors restored to operable status in 881111.

 KEUTER.D.R. Sacramento Municipal Ut his District 88/12/08 MARTIN.J.B. Region 5, Ole of the Director, 2pp. 47789-294-47799-295.
- 8812200088 Confirmatory action litring actions taken in response to 881212 reactor trip NRC understands that util actions will include but not limited to listed actions MARTINJB. Region 5, Old of the Director, 88/12/13 FIRLIT, J.F. Sacramento Municipal Utility District, 2pp. 47860:197-47860.198
- 8812200275 PNO-V-88-066 on 881212.feedwater flow sign-licently reduced due to steam pressure fluctuations to main feedwater pump 8 (MFP) Fluctuations caused by operator actions. Uni located unexpected steam demand from auxiliary steam supply MILLERL, D'ANGELO,A. Region 5, Otc of the Director. 88712713 2pp. 47860-3334.

8612200180 Suppl to Special Rept 88-13 Completion of restoration of penetration soals for floor slots reschoduled for phor to end of Cycle 8 refueling oblage because work would involve 4,160 volt Nuclear Svcs Bus 8 REUTER, DR Spreamento Municipal Unity District 88/12/14 MARTIN, J.B. Region 5, Oic of the Director. 1p. 47867 313-47867 319

V. Operator Examinations

8812140052 Forwards revised agenda for annual operator Louising mooting on 690110 W/o oncl PATER J. Region 5, Ofc of the Director, 80/12/05. HERRELL,M. Sacramonto Municipal Utity District. 1p. 47799-243-47799.243.

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811280183 Rev 6 to Emergency Plan Implementing Procedure 1903.04, "Administration & Maint of Emergency Plan & Implementing Procedures"

 * Arkensas Power & Light Co. 88709723, 6pp. 47654;029-47654.034.
- 8811300435 Rev 9 to Emergency Plan Implementing Procedure 1903.01, "Organization & Use of Emergency Plan Implementing Procedures."

 * Arkansas Power & Light Co. 88/10/27, 3pp. 47676;207-47676;209.

- 6611300429 Rev 10 to Emergency Plan Implementing Procedure 1903.51, "Turnover of Responsibility **
 * Arkansas Power & Light Co. 88/10/28, 11pp 47677.012-47677.022.
- 8811290503 Rev. 16 to Emergency Plan Implementing Procedure 1903.023, "Personnal Arkansas Power & Light Co. 88/11/18, 14pp. 47657.337-47657.350
- 8811300115 Advises that 881027 request for extension in submittal of response to dev-ations noted in Insp Repts 50:313787-14 & 50:368787-14 until 881216 acceptable. CALLAN,L.J. Region 4, Ofc of the Director, 88/11/16 CAMPBELL,G. Arkansas Power & Light Co. 2pp. 47673 239:47673.242.
- ⇒8811300119 Requests extension until 881216 to submit revised response to Insp Repts 50:313/87-14 & 50:368/87-14. LEVINE,J.M. Arkansas Power & Light Co. 88/10/27. CALLAN,L.J. Region 4, Ofc of the Director, 2pp. 476/3:241-47673:242.
- 8811280021 Forwards response to Safeguards Insp Ropts 50:313/86-34 & 50:368/86-34 Encl withhold (ref 10CF973 21). LEVINE,J M. Arkansas Power & Light Co. 88/11/18. CALLAN,L.J. Region 4, Old of the Director. 2pp. 47709 001-47709 002.
- 8812010004 Advises that 860021 changes to emergency plan acceptable. CALLAN,L.J. Region 4, Ofc of the Director. 88711718. CAMPBELL,G. Arkansas Power & Light Co. 2pp. 47709.250-47709.251
- 8812160163 Forwards Amends 114 & 88 to License DPR-51 & NIF-6, respectively. Amends modify Paragraphs 2.C(4) & 2.D of licenses to require complance w/revised physical security plan per 10CFR73.55. Safeguards evaluation rept also encl.
 HARBUCK, C.C. Project Directorate IV. 88/12/06. CAMPBELL, T.G. Arkansas Power & Light Co. 4pp. 47830.301-47830.311.
- -8812160155 Amends 114 & 88 to Licensos DPR-51 & NPF-6, respectively, modifying Paragraphs 2.C(4) & 2.D of licenses to require compliance w/revised physical security plan per 10CFR73.55.

CALVO, J.A. Project Directorate IV. 88/12/06, 4pp. 47830.305-47830.308

- -8812160167 Safeguards evaluation rept supporting Amonds 114 & 88 to Liconsos DPR-51 & NPF-6, respectively.

 Office of Nuclear Regulation, Director (Post 870411) 88/12/06 3pp. 47830.309 47830.311.
- 8812210301 Forwards Insp Repts 50:313/88:39 & 50:368/88:39 on 881031-1104 No violations or deviations noted CALLAN, L.J. Region 4, Old of the Director, 88/12/13, CAMPBELL, G Arkansas Power & Light Co. 2pp. 47877:115-47877:120.

→8812210304 Insp. Ropts 50:313/88:39 & 50:368/88:39 on 881031:1104.No violations or deviations noted Major areas inspected: physical security program including mgl support security program plan & audits & alarm stations & communications KELLY,J.A., EVERETT,R.J. Region 4, Ofc of the Director. 88/12/08. 4pp. 47877.117-47877:120

H. General correspondence

8812010155 Comment supporting proposed rule 10CFR26 to NRC rulemaking on litness for duty programs Endorses NUMARC 881118 comments on subj proposed rule & suggests incorporation of NUMARC suggested changes.

CAMPBELL, T.G. Arkansas Power & Light Co. 88/11/17, CHILK,S.J. Office of the Socretary of the Commission. 8pp. 47678:223-47678:230.

P. Operating license stage documents & correspondence

- 8811290182 Discusses NRC position on radiation embrittlement of reactor vessel matts & impact on plant operations to Gonoric Ltr 89-11.

 HOWARD,D.R. Arkansas Power & Light Co. 88/11/21. Document Control Brench (Document Control Desk). 2pp. 47648:198-47648:199
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list encl.
 CRUICHFIELD.D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303.47729.024.

- 8812020173 Summary of 881118 meeting w/ut/l in Rockville,MD re four plant startup issues including DHR sys shuddown cooling mode of operation,operability of penetration room vertilation sys & operability of nozzles in safety-related piping sys. HARBUCK,C.C. Project Directorate IV. 7pp. 47734 C86 47734 141
- --8812020176 Confirms 881107 conversation to operability of DHR sys during both long term cooling 8 shall down cooling modes of operation 8 operability of containment penotration ventilation sys MARTIN,R.D. Region 4, Ofc. of the Director 88/11/07. CAMPBELL,G. Arkansas Power & Light Co. 47pp. 47734 095-47734:141.

8812020239 Requests justification for inturing operation of facility based on assumed Lake Dardanelle terrini of 70 F,svc water flow of 1700 gpm through each decay HX & only one reactor bidg cooling unit operable in each trein HARBIUCK, C. Project Directorate IV. 88/11/29 CAMPBELL, T.G. Arkensas Power & Light Co. 5pp. 47711:112-47711:116

- 8812090220 Hoquest: that util address Generic Ltr 88-17 re tass of DHR during nonpower operation industry response to Generic Ltr 87-12 deficient in areas of prevention of accident initiation & mitigation of accidents. MURILEY, T.F. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/02. MAUJ.DEN.J.L. Arkensas Power & Light Co. 4pp. 47762-317-47762-320.
- 8812200252 Discusses addl into relieve water degradations per 881118 meeting w/ NRC Prior to warm weathur in Spring 1999, discrepancies will be resolved HOWARD B. Arkansas Power & Eight Co. 88712705. CALVOJ A. Project Directorate IV 4pp. 47863 064-47863 067
- 8812160153 Forwards Amends 114 & 98 to Libense DPR-51 & NPF-6, respectively Amends modify Paragraphs 2 C(4) & 2 D of licenses to require compliance wirevised physical security plan per 10CFR73 55 Saleguards evaluation rept HAHBLICK,C.C. Project Directorato IV. 88/12/06 CAMPBELL,T.G. Arkenses Power & Light Co. 4pp. 47833-301-47830-311
- -8812160155 Americk 114 & 85 to Liconsus DPR-51 & NPF-6, respectively, modifying Peragraphs 2.C(4) & 2.D of licenses to require compliance w/revised physical security plan per IOCFR73.55 CALVO,J A Project Directorate IV 88/12/06 4pp 47830:305-47830:308
- -9812160157 Saleguards evaluation rept supporting Amends 114 & 88 to Liconses OPR-51 & NPF-6,respectively.

 **Office of Nuclear Reactor Regulation, Director (Post 870411). 88/12/06. 3pp.
- 8812210005 Summary of 881013 moeting w/util ro long-standing safety Issues,Including Genonic Ltr 83-28 items,SPDS,Rog Guido 1.97 safety ovaluation open Itoms & TMI Action Item ILN 2.16
 HARBUCK,C.C. Project Directorate IV. 88/12/13 CAMPBELL,T.G. Arkansas Power & Elght Co. 17pp. 47889.035-47889.051
- 8812230104 Forwards Amend 115 to License DPR-51 & safety evaluation. Amend pro-
- vides 1 gpm Imition primary to secondary loak rate (total steam generator lube leakego) HARBUKK,C C. Project Directorate IV. 88/12/15. CAMPBELL,T.G. Arkansas Power & Light Co. 3pp. 47921 343-47921 352
- -8812230109 Amend 115 to License DPR-51,revising Tech Specs to specifically provide for 1 gpm lim1 on primary-to-secondary feek rate (total steam generator tube loakege) CALVO,J.A. Project Directorato IV. 88/12/15. Spp. 47921:346-47921:350.
- -8812230111 Safety gva'ualion supporting Amond 116 to License DPR-51
 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/12/15. 2pp. 47021:351-47921:352.
- Q. Inspection reports, IE Bulletins & correspondence

47830.309-47830 311.

- 8811180280 Forwards risk-based inspiguides described in mode to insp Manual Chapter 2515 W/o encis LONG,S.M. Risk Applications Branch 88/11/16, LANHAM,D. Document Control Branch (Document Control Dosk), 1p. 47597:114-47801:019.
- 8811300115 Adwisos that 881027 request for extension in submittal of response to deviations noted in Insp Repts 50:313/87-14 & 50:368/87-14 until 881216 acceptable. CALLAN,L.J. Region 4, Ofc of the Director, 88/11/16, CAMPBELL,G. Arkansas Power & Light Co. 2pp 47673.239-47673 242
- --8811300119 Requests extension until 881216 to submit revised response to Insp. Repts 50:313/67-14 & 50:368/67-14 LEVINE,J M Arkansas Power & Light Co. 88/10/27. CALLAN,L J Region 4, Ofc of the Director. 2pp. 47673:241-47673:242
- 8812010009 Ack receipt of 881026 ftr informing NRC of steps taken to correct violations noted in Insp Ropts 50:313/88-28 & 50:368/88-28.

 CALLAN,L J. Region 4, Ofc of the Director, 88/11/17. CAMPBELL,G. Arkansas Power & Light Co. 2pp 47709:310-47709:316.
- ~8812010012 Responds to violations noted in Insp Repts 50-313/88-28 & 50-368/88-28 Corrective actions RCS leakage rate determination in Procedure 1103.13 will be revised to climinate discrepancy of timing. LEVINE, JM. Arkansas Power & Light Co. 88/10/26. CALLAN,L.J. Region 4, Otc of the Director. 4pp. 47709:312-47709:315.
- 8811280021 Forwards response to Sateguards Insp Repts 50:313/86:34 & 60:368/86-34 Enct withheld (ref 100FR73 2!) LEVINE_JM. Arkansas Power & Light Co. 88/11/18. CALLAN,L.J. Region 4, Oic of the Director. 2pp. 47709 001-47709 002.
- 8811290271 Forwards Insp Repts 50-313/88-32 & 50-368/88-32 on 880916-1023 & notice of violation CALLAN,L J. Region 4, Ofc of the Directo: 86/11/18. CAMPBELL,G. Arkansas Power 8 Light Co. 2pp. 47650 035-47650 050.

- #8811290276 Notice of violation from inspiren 880915-1023 Violation noted controls for
- temporary supports not suitable
 * Region 4. Ote of the Director, 68/11/18, ip. 47650 037-47650 037
- -8811290278 insp. Repts. 50.313788.32.8. 50.368788.32 on .880316-1023. Violations noted Majur areas inspected maint, surveillance, operational safety verification followup on LBns.8. events.

 JOHNSON WOLHAAGERG. CHAMBERLAIN D. Region. 4. Ofc. of the Director. 887

11/15 13pp 47650 038-47650 050

8811300161 Forwards Insp. Repls 50:313/88-35 & 50-368/88 35 on 881030:1104 De 139 of U 3350n d scussed in tept. Preplation to discuss at aspects of community and the scuss at aspects of community at the scuss of the scuss o

- -8511300166 irisp Repts 50:313/88:35 & 50:368/88:35 on 881030:1104 Violation noted Major areas inspected Unit 1 containment integrated leak rate test AZUARY SEIDLE, W.C. Region 4, Cfc of the Director 88/11/17, 5pp. 47698-003
- 8811160211 NRC Info Notice 88 090, "Unauthorized Removal of Industrial Nuclear Gauges "S.c. list onci CUNIX CHAM.R E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psycholog
- cal Tests: Sic Island ROSSIC E. Division of Operational Events Assessment (Post 870411) 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142.
- 8811300159 Forwards Insp. Repts 50:313/88:37 & 50:368/88:37 on 881017:1104 No CALLANI, J. Region 4, Old of the Director 88/11/22 CAMPBELL,G. Arkansas Power & Light Co. 2pp. 47673 058-47873 108

- -8813300160 Insp. Repts 50:313/88:37 & 50:368/88:37 on 881017:1104 No violations or deviations noted Major areas inspected licenses capability for self-assessment & compliance w/ respective OL Tech Specifical rements
 TAYLOR, R.G., BARNES, I. Region 4, Old of the Director, 88/11/22, 9pp. 47673:100-47673 1CB
- 8811300254 Forwards Insp Repts 50 313/88-41 & 50-368/88-41 on 881103-04 Viola Lors noted for force render to should be shoul
- -8811300257 Insp. Repts. 50-313/88-41 & 50-368/88-41 on 881103-04 Violations antious27 ...sp. hepis 30-13768-41 5 50-300708-41 for antious4 Vigid and in moted Major a reas respected events surfounding apparent overoxposure of one worker performing maint work during reflueting outage RICKETSON.T., MURRAY.B., PEDERSON.R.L. Region 4, Ofci of the Director, 887 11/16 Epp. 47674 118 47674 125
- 8812020306 Forwards Environ Qualification Insp. Repts 50:313/88-29 & 50:368/88-29 on 880222-26,0312-29 & 1003-13 & notice of violation CALLANUJ Region 4, Oto of the Director 88/11/28 CAMPBELLIG Arkansas Power & Light Co. 2pp. 47718-290-47718-306
- -8812020307 Notice of violation from inspiring 860714-18 & 680229-0610 Violations noted equipment qualification files did not adequately address instrument accuracy & maint procedures marcoquate in performing maint on cooling unifiam motors. Region 4, Ofc of the Director 88/11/28, 3pp. 47718-292-47716-294.
- -8812020309 Insp Repis 50-313/88-29 & 50-368/88-29 on 880822-26,0912-29 & 1003-47718 295 47718 306
- 8811290030 NRC Info Notice 88-093, "Tetatherapy Events." Svc List encl. CUNN NGHAM,R.E. Omision of Industrial & Medical Nuclea: Safety (Post 870729) 68/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811.103.47811.215
- 8811290538 NRC Info Notice 65 094, "Potentially Undersized Valve Actuators." Svc list
- enci ROSSICE Division of Operational Events Assessment [Post 870411]. 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708.143-47708.254.
- 8812050305 Informs that Insps 50-313788-46 & 50-368788-46 cancelled & no insp repts will be issued for repli rumbers CALLANLU Region 4, Otc of the Oirector, 88/12/02 CAMPBELL,G. Arkensas Power & Light Co. 1p. 47740-055-47740-055
- 8812020287 NRC Info Notice 88 095, 'Inadequate Procurement Requirements Imposed by Licenseas on Vendors. Svc list encl.

 ROSSI,C E. Drvis on of Operational Events. Assessment (Post 870411). 89/12/08.

 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812150102 Forwards Insp. Repts 50:313/88:34 & 50:368/88:34 on 881004-07 & 17-21 No violations or deviations noted CALLANU, J. Regon. 4, Olic of the Director, 88/12/08, CAMPBELL,G. Arkansas Power & Light Co. 2pp. 47830
- -8812150109 Insp Repla 50-313/88-34 & 50-368/88-34 on 881004-07 & 17-12. No vislations or deviations noted Major areas inspected. Inservice insp activities & welding activities associated w/design changes. MCNEILL,W.M., ELLERSHAW,L.E., BARNES,I. Region 4, Ofc of the Director, 88/12/07. 8pp 47830 273-47830 281.
- 8812210187 Forwards steam generator tubing inservice inspirely for eighth refueling outage per Tech Spec 4.18 6.
 HOWARDS DR. Arkansas Power & Light Co. 88/12/09 CALVO,J.A. Project Orectorate IV 14pp 47875 001-47875 014.
- 8812210301 Forwards Insp Repts 50:313/88:39 & 50:368/88:39 on 881031-1104.No violations or day ations noted
 CALLANIL J. Region 4, Ofc of the Director, 88/12/13, CAMPBELLIG, Arkansas Power
 8 Light Co. 2pp. 47877, 115-47877, 120

- -8812219364 lines Rogis 50:313788:39 & 50:368780-39 on 881031.1104 tio √√√2015 of deviations insted Major areas inspected, physical security program in √2019 π₂ support security program plan 8 audits & altern stations & communications KELLY, JA, EVERETT, R.J. Region 4, Otc. of the Director 88712708 4pp. 47877 tr.
- 8812210346 Forwards Insp. Repts 50 313788-48 & 50 368788-48 on 881128 29 Entyte ment confurence scheduled on 881221 to discuss understanding of apparent vicilities ref to rept 8 violations in Insp. Repts 50 313788-41 & 50 368788-41 CALLANT, J. Regan 4, Office the Director, 88712714. CAMPBELL,G. Arransas Poses & Light Co. 2pp. 47877-119-47877-114
- -8812210347 tosp Repts 50/313788/48 & 50/368788/48 on 881128/29 Victorials noted Major ereas inspected events surrounding apparent overexposure to skin clica-BAERRE, FICKETSONL T., MURRAY, B. Region 4, Ofc of the Director 88/12/13 4pp 47877 111-47877 114
- 8812220010 Advisos that Insp. Hopts 50/313/88/40 & 50/368/88/40 cancolled No reg. อาธะเลยนาย กษณะของ และ และ เกตุก สมุทธ (ค.ศ. 1370) 40 & เกษายยยยย 40 Cancoled Relieg numbers will be issued CALLARL J. Region 4, Orc of the Director 88/12/14. CAMPBELL,G. Arkansas Power & Light Co. 1p. 47903 038-47903 038

R. Periodic operating reports & related correspondence

- 8812190247 Monthly operating ropt for Nov 1988 for Arkansas Nuclinar One,Una 1 W.
- SCHAUBROECK,D., HOWARD,DR. Arkansas Power & Light Co. 88711730 660 47849 137 47849 142

S. Reportable occurrences, LERs & related correspondence

- 8811300331 Summary of Operating Reactors Events Meeting #8-45 on #81115 List of atlendens & handouts ercl LANNING,W.D. Evants Assessment British 88/11/25, ROSSI,C.E. Division of Operational Evants Assessment (Post 870411), 16pp. 47674 141-47674 156
- 8812130043 LER 88 008 00 on 880026 inspiral emergency diasel generators A exists: pining rever'ed cracked wold at multer discharge. Caused by fallure to portoim cos stress analysis Cracked wold on multer discharge repaired W/801202 th JACKSJID., LEVINEJ M. Arkaneas. Power & Light Co. 88/12/02. Spp. 47792.33 47792 309
- 8812210043 Forwards LER 50-313788-013-00 re-potential failure of high pressure nec tion pump to start on anginumed saleguards signal disc to breaker wining cred LEVINE, J.M. Arkansas Power & Light Co. 88/12/12. Document Control Branch (Document Control Dask). 2pp. 47876 031-47876 003
- -8812210193 LER 88-013-00 on 880924-potential failure of high pressure injection pump to start on engineered saleguards signal due to breaker wining error Wing environmented & circuit lested to vorify proper operation. J
- 8812210085 Forwards LER 50:313/88-009-00 re Inoperable mechanical snebbtrs of satety-related piping sys Only abstract of LERI direct. LEVINE,J.M. Arkansas Power & Light Co. 88/12/12, Document Control Branch (Dec. ment Control Desk). 2pp. 47892 001-47882 003.
- -8812210088 LER 88-009-00 on 8A0022 throo inoposition muchanical solubias discoered on salety-related plying sys Caused by ovurload & use of undorsized shutter of spec Extension tube kit modified & shim plated installed JACKS,JD Arkansas Power & Light Ca. 88/12/12. 1p. 47882 G03-47882 003
- 8812210211 Notifies that due to peak work load conditions associated w/ refusing outagoutil unable to submit dutailed LERs within 30 day time period Solected repts to be submitted including end in abstract form to assure 1 mely notification LEVINE_J.M. Arkansas Power & Light Co. #8/12/12. Document Control Branch (Occoment Control Desk) 2pp. 47906 301-47906 303
- -8812210278 LER 88-015 01 on 880928 resulting from rowew of follow-up calculations during reanalysis of RCS loop model increased support foads identified on two hydion in shubbers purformance conducted. TAYLOR,L A. Arkansas Power & Light Co. 88/12/12 1p. 47908:303-47906:303
- 8812220243 LER 88-011-00 on 881115,coro flood tank inoperable due to favire of vertine to most seismic design qualification. Caused by missing solamic support Vertine dosign deficency corrected by adding rost an WA81212 Till 1971 (1971) and 1971 (1971) a
- 8812210166 LER 85-001-01 on 850107, steam-driven emergency feedwater purp nop-erable following refueling outage Caused by hand indicating controller incorrectly set on direct acting vs reviews acting Procedure rovised W/881215 ltr. TAYLORL A. LEVINE, J.M. Arkansas Power & Light Co. 88/12/15. 6pp. 47880 353 47890-365.

DOCKET 50-315 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811290533 Change Sheet 4 to Rev 0 to Emergency Plan Implementing Procedure PMP 2080 EPP.108, "In tial Offsite Notification" * Indiana Michigan Power Co. (formerly Indiana & Michigan Etectric Co.) 89/11/14 11pp. 47802.304-47802.314.
- 8811300480 Chango Sheet 3 to Rev 0 to Emergency Plan Implementing Procedure PMP 2081 EPP.102, "Technical Support Cir Emergency Communication." Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.) 86/11/15

- 8812010011 Change Sheet 4 to flow 0 to Emergency Plan Implementing Procedure PMP 2080 EPP 106, "Initial Offside Notification."

 Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.): 88/11/23 2pp 47702:308-47702.309
- 8812010014 Change Sheet 3 to Roy 3 to Emergency Plan Implementing Procedure PMP 2981 EPP 102, "TSC Emergency Communication."
 **Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.), 88/11/23, 2pp. 47702 312-47702 313.
- 8812140240 Forwards Safety Insp Ropts 50-315/88-24 & 50-316/88-28 on 881020-1116 & 0022-1116 & notice of violation AXELSON,W.L. Region 3, Ofc of the Director, 88/12/01 ALEXICH,M.P. Indiene Michi-gan Power Co. (formerly Indiana & Michigan Electric Co.), 2pp. 47802-238-47802-259.
- -8812140244 Insp. Repts 50-315/88-24 & 50-316/88-28 on 881020-1116 Violations noted Major areas inspected operational safety, radiological noted Major areas inspected operational safety, radiological controls, maint, surveillance, fire protection, innergency preparedness, security & out
 - agos BUHGESS,B.L. Region 3, Ofc of the Director, 88/11/29, 19pp, 47802:241-47802:259
- 8812210369 Advises that 881010 Rev 7 to amergency plan consistent w/ provisions of 10CFR50.54(g) & acceptable GREGEH,L. R. Region 3, Ofc of the Director. 88/12/14. ALEXICH,M.P. Indiana Michi-gan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 47875.286-47875.287
- 8612210322 Rev 3 to Emergency Plan Implementing Procedure PMP-2080 EPP.107. Not feat on of Plant Porsonial.

 SMITH.W. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/12/19, 59pp. 47877-268-47877:326

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 88-20 to all Leonsoes holding OLs & CPs for nuclear power reactor facilities to Individual plant exam for severe accident vulnerabilities Svc 1st
 - CRUICHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 8B12050036 Application for amend to Licenses DPR-58 & DPR-316, increasing trip sotreported Application of the Individual Control of Contr
- 47732.028 47732 043 -8612050037 Proposed Toch Space rullengineered safety feature actuation sys instru-
- * Indiana M.chigan Power Co. (formerly Indiana & Michigan Electric Co.), 88/11/29 3pp. 47732-041-47732-043.
- 8812070158 Requests that util addresses Generic Lir 88-17 re-loss of DHR during non-power operation accordingly NRC believes that industry has not aggressively respond-ed to resolve concern following Identification in Generic Lir 67-12. MURLEY,T.E. Office of Nuclear Reactor Hugulation, Diructor (Post 670411), 86/12/ 02. WHITE,W.S. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.), 3pp. 47746-272-47748-274
- 8812090036 Responds to Generic Lir 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Malls & Impact on Plant Operations."

 ALEXICH, Mr., Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88712/05. MURLEY,T.E. Document Control Branch (Document Control Desk). 8pp. 47775 321-47775.351.
- --8612090060 "Assessment of Roy Guide 1.99,Rov 2 Upon D.C. Cook Units 1 & 2 Adjusted Rof Temps & Prossure Temp Curvos." IDDINGS,F.A., CROSS,B.T. American Efectric Power Service Corp. 88/11/30, 23pp. 47775-320,47775-351.
- 8812130204 Forwards Anunds 119 & 105 to Liconses DPR-58 & DPR-74, respectively & safety evaluation. Amends revise radiological environ Tech Specs to be consistent w/NRC guidefines re obtaining milk samples for analysis SCOTT,W Project Directorate III-1, 88/12/06, ALEXICH,M.P. Indiana Michigan Power Co. (formarly Indiana & Michigan Electric Co.), ALEXICH,M.P. American Electric Power Co., Inc. 4pp. 47796 035-47790-054.
- -8812130206 Amonds 119 & 105 to Licenses DPR-58 & DPR-74, respectively, revising
- Tech Space to be more consistent w/NRC guidelines for obtaining milk samples for analysis & Westinghouse STS ro thyroid release pathway for child. QUAY,T. Project Directorate III-1, 88/12/06, 11pp. 47796:039-47796.049.
- ~8812130209 Safety evaluation supporting Amends 119 & 105 to Licenses DPR-58 &
- DPR-74-raspectively.
 * Office of Nuclear Reactor Ragulation, Director (Past 870411). 88/12/06 3pp. 47796 050-47796052.
- -8812150265 Notice of Issuance of Amonds 110 & 105 to Licenses DPR-58 & DPR-74,respectively. Amends ravise Tech Specs to be more consistent w/NRC guidelines re-obtaining milk eamples for analysis. SCOTT,W Project Directorate III-1. 88/12/06. 2pp. 47796.053-47796.054.
- 8812130032 Submits plan of action for resolving concerns associated w/Copes-Vulcan valves installed at plant Doscription of actions taken also provided. ALEXICH,M.P. Inclina Michigan Power Co. (formetly Indiana & Michigan Electric Co.). 88/12/03. DAVIS.A.B. Document Control Branch (Document Control Desk). 4pp 47799,181-47799,167.
- --8812130083 "Interim Acceptance Criteria for Safety-Related Piping Sys." WILLIAMS.J.L. American Electric Power Service Corp. 88/12/09. 3pp. 47799:165-47790.167

- 8811160467 NRC Info Natice 88-091, "Improper Administration & Control of Psychological Control of Control of Control of Control Control Control of Control Contr cal Tosts " Svc list enci ROSSI,C E. Division of Operational Events Assessment (Post 870411) 88/11/22 Conso'dated Edison Co. of New York, Inc. 101pp 47708 042-47708.142
- 8812140240 Forwards Safety Insp Repts 50:315/88:24 & 50:316/88:28 on 881020-1116 & 0922-1116 & notice of violation AXELSON,W.I., Region 3, Ofci of the Director, 88/12/01, ALEXICIT,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 47802:238-47802.259.
- -8812140242 Notice of violation from inspirence on 881020-1116 Violation noted fire watch covering welding of Unistrut attachment on Steam Generator 21 specified under Hot Work Permit 1247 not present. AXELSON,W.L. Region 3, Ofc of the Oxector, 88/12/01, 1p. 47802 240-47802-240
- -8812140244 Insp Repts 50-315/88-24 & 50-316/88-28 on 881020-1116, Violations inspected operational safety, radiological aroas
 - controls,maint,surveillance,fire protection, emergency preparedness, security & outages BURGESS,B.L. Region 3, Ofc of the Director, 88/11/29, 19pp, 47802 241-47802 259
- 8811290030 NRC Info Natice 88:093, "Telethorapy Events" Svc list encl CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 670729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811.103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list
- ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254
- 8812130002 Forwards Safety Insp Repts 50-315/88-26 & 50-316/88-30 on 881107-29 No violations noted WRIGHT, G.C. Region 3, Ofc of the Director. 88/12/02 ALEXICH, M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.) 2pp. 47792/316-47792/330
- -8812130005 Safety Insp Repts 50-315/88-26 & 50-316/88-30 on 881107-29. No violations noted Major ereas inspected Loosee action on previous insp finding recurring problems w/es/imated critical position & calibr of nuclear instrumentation sys. PHILLIPS.M.P., WETZEL.B.A. Region 3, Ofc of the Director. 88/12/02. 13pp. 47792:318-47792:318-47792:308
- 8812120240 Responds to NRC 881205 lit re violations noted in Insp Repts 50-315/88-23 & 50-316/88-27 Corrective action taken damper timeup conducted using Procedure 01-OHP 4021-028-008 to reposition four dampers to correct position.

 ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.) 867/12/05 DAVIS,A.B. Document Control Branch (Document Control Dosk). 4pp. 47785-356-47785-359.
- 8812020287 NRC Inio Notice 89:005, "Inadequate Procurement Requirements Imposed by Licansees on Vandors" Svc 1st encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/08. Consordated Edson Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812190336 Forwards Insp Repts 50:315/88-25 & 50:316/88-29 on 881031-1104.No violations noted.insp team conclusion that util meeting commitments to Improve re-
- qualification training program noted.

 WRIGHT,G.C. Region 3, Ofc. of the Director. 88/12/14. ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 47853:231-47853:249.
- --8812190340 Insp Repts 50-315/88-25 & 50-316/88-29 on 881031-1104.No violations or deviations noted Major areas inspected. Ilcensed operator requalification fraining, including evaluation of commitments to improve program. HOPKINS, JA, DAMON, D.J., BURDICK, T.M. Region 3, Otc of the Director. 88/12/14. 17pp. 47853 233-47853.249.

S. Reportable occurrences, LERs & related correspondence

- 8811300572 NPDES noncompliance notification on 881114.sample of profilter backwesh offluent (Outfall 00F) analyzod for suspended solids & Indicated 171 mg/1.Rqugh lake conditions sitired bottom sed-ments coming Into plant Intake water. MENGE.R.C. Indiana Michigan Power Co. (formarly Indiana & Michigan Electric Co) 88/11/18. ZUGGER.P.D. Michigan, State of. 2pp. 47674:193-47674:194.
- 8812210379 LER 88 012-03 on 881111, turbino room sump not sampfed & analyzed in accordance w/Tech Spacs. Caused by personnel error Procedures updated to list required sampling frequencies & analysis for sys W/881212 ftr. WOJCIK, J.T., SMITH, W.G. Indigen Michigen Power Co. (formerly Indiana & Michigan Electric Co.). 88/12/12, 4pp. 47875/038-47875/041.

V. Operator Examinations

- 8812190336 Forwards Insp Repts 50-315/88-25 & 50-316/88-29 on 881031-1104.No violations noted insp team conclusion that util meeting commitments to improve re qualification training program notod. WRIGHT,G.C. Rogion 3, Oto of the Director. 88/12/14. ALEXICH.M.P. Indiana Michi-gan Power Co. (tormerly Indiana & Michigan Electric Co.). 2pp. 47853:231-47853:249.
- -8812190340 Insp Repts 50-315/88-25 & 50-316/88-29 on 881031-1104.No violations

or deviations noted Major areas inspected licensed operator requalification training,including evaluation of commitments to improve program. HOPKINS,JA., DAMON,DJ., BURDICK,T.M. Region 3, Oic of the Director, 88/12/14 17pp. 47853.233-47853.249.

DOCKET 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8812010011 Change Sheet 4 to Rev 0 to Emergency Plan Implementing Procedure PMP 2080 EPP 108, "Initial Olfsite Not floation."
Indiana Michigan Power Co. (termorly Indiana & Michigan Electric Co.). 88/11/23 2pp. 47702 308-47702 309

- 8812010014 Change Shoet 3 to Rev 3 to Emergency Flan Implementing Procedure PMP 2081 EPP-102, "TSC Emergency Communication".

 *Indiana Michigan Power Co. (formerly Indiana & Michigen Electric Co.). 88/11/23. 2pp. 47702 312-47702 313.
- 8812140240 Forwards Setety Insp. Repts 50-315/88-24 & 50-316/88-28 on 881020-1116 & 0922-1116 & notice of volation AXELSON,WIL Region 3, Ofc of the Circetor 88/12/01, ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.) 2pp 4/802.238-4/802.259

-8812140242 Notice of violation from inspiron 681020-1116 Violation noted fire watch covering welding of Unishut attachment on Steam Guneralor 21 specified under Hot Work Permit 1247 not present AXELSON,W L Region 3, Ofc of the Director 88/12/01. 1p. 47802 240 47802 240.

-8812140244 Insp Repls 50-315/68-24 & 50-316/68-28 on 881020-1116 Viotations noted.Major areas inspected operational safety, radiological controls,maint survertance,fire protection, emergency preparedness, security & outfacigoloibas 8ges -BURGESS,B.L. Region 3, O'c of the Director, 88/11/29, 19pp. 47802 241-47802:259.

8812210322 Rev 3 to Emergency Plan Implementing Procedure FMP-2080 EPP.107, "Notification of Plant Personne". "Notification of Plant Personne" (formetty Indiana & Michigan Electric Co.). 887 12/19, 59pp. 47877.268-47877.326

P. Operating license stage documents & correspondence

- 8811280148 Forwards notice of consideration of issuance of amend to License DPR-74
- Scoportunity for Fearing to 880915 (optication to amend SCOTT,W. Project Directorata III-1, 88/11/21, ALEXICH,M.P. Indigna Michigan Power Co. (formatily indigna. & Michigan Electric Co.). ALEXICH,M.P. American Electric Power Service Corp. 3pp. 47652 240-47652:249
- --8811260152 Notice of consideration of Issuance of amend to Legense DPA-74-8 op-porturity for hearing re-890815 application Amend revises Tech Spac 3/4-1, "Peactiv-ty Control Sys."

 QUAY,T. Project Directorate III-1, 89/11/18, 5pp. 47652-240-47652-247.
- 881128004B Genoric Ltr 68-20 to all liconsees holding OLs & CPs for nuclear power reactor facilities to individual plant exam for severe accident vulnerabilities Svc fist CRUTCHFIELD.D. Associate Director for Projects (Post 870411) 88/11/23. Consol-deted Ed.son Co. of New York, Inc. 81pp. 47728 303 47720 024
- 8812050036 Application for amond to Licenses OPR-58 & DPR-316, Increasing top serpoint & distribution values for 4 KV Bus foss of vollege & 4 KV Bus degraded voltage engineered safety feature actuation instrumentation Fee paid ALEXICH, M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.) 88/11/20, MURILEY,T.E. Document Control Branch (Document Control Desk). 13pp. 47730-303, 47730-303.

47732.023 47732 043

- -8812050037 Proposed Tech Specs relengineered safety feature actuation sys instru-
- meniation trip salpoints

 * Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 68/11/29.
 3pp. 47732:041-47732-043
- 8812070158 Requests that util addresses Generic Ltr 80.17 to loss of DHR during non-power operation accordingly MRC believes that industry has not aggressively respond-ed to resolve concern following identification in Generic Ltr 87-12. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02. WHITE,W.S. Indiana Michigan Power Co. (formorly Indiana & Michigan Electric Co.), 3pp. 47748 272-47748 274.

- 8812090038 Rosponds to Generic Ltr 88-11, "NRC Position on Radiation Embrittement of Reactor Vessel Mails & Impact on Plant Operations."
 ALEXICH.M.P. Indiana Mchigan Power Co. (formerly Indiana & Michigan Electric Co.).
 88/12/05. MURLEY.T.E. Document Control Branch (Document Control Desk.). 8pp 47775:321-47775 351
- 8812130204 Forwards Amends 110 & 105 to Licenses DPH-58 & DPR-74, respectively 8 safety avaivation Amends 110 kg to Licenses DPH-518 8 DPH-74, respectively 8 safety avaivation Amends revise radiological environ Toch Specs to be consistent w/NRC guidefinos re obtaining milk samples for analysis. SCOTT,W. Project Directorate III-1. 8B/12/06. ALEXICH,M.P. Indiana Michigan Power Co. (formally Indiana & Michigan Electric Co.) ALEXICH,M.P. American Electric Power Co., Inc. 4pp. 47796 035-47796.054.
- -8812130206 Amends 119 & 105 to Licenses DPR-58 & DPR-74,respectively, rev.sing Tech Specs to be more consistent w/NRC guidelines for obtaining milk samples for enalysis & Wostinghouse STS or thyrotid coles o pathway for child. QUAY,T. Project Directorate III-1. 88/12/06 11pp. 4708.039-47796:049.
- -8812130209 Sately evaluation supporting Amends 119 & 105 to Licenses DPR-58 & DPR-74 respectively.

 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/06, 3pp. 47798:050-47796:052
- -8812150285 Notice of issuance of Amends 119 & 105 to Licenses DPR-58 & DPR-74, respectively Amends raylso Tech Specs to be more consistent w/NRC guide.inea to obtaining mike samples for analysis.

 SCOTT, W. Project Directorate III-1, 88/12/06, 2pp. 47796.053-47796.054.

- --8812130083 "Interim Acceptance Criteria for Safety-Related Piping Sys WILLIAMS.J.L. American Electric Power Service Corp. 88/12/09 (3pp. 47/9) 165 47790-167

Q. Inspection reports, IE Bulletins & correspondence

47799 161-47799 167

- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industriel facility Gauges." Syc fist and CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 87)223-88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47768 256-47709 251.
- 8811160467 NRC Info Notice 68 031, "Improper Administration & Central of Psyctotop cal Tosts" Sveilst end: ROSSI, C.E. Dwisson of Operational Events Assessment (Post 870411), 4877722 Consolidated Edison Co. of New York, Inc. 101pp, 47708-042-47708-142
- 8812140240 Forwards Safety Insp. Repts 50 315788:24 8 50:316788:28 on 38:020 1116 8 0922-1116 8 notice of violation AXELSON,W.L. Region 3, Citic of the Director 08/12/01 ALEXICH,M.P., Inst and Idea gan Power Co. (formerly Indiana & Michigan Electric Co.), 2pp. 47802:238:47692259
- -9812140242 Notice of wolation from inspiron 881020-1116.Violation culled the watch covering wording of Unistrut attachment on Steam Generator 21 specified under the Work Portrat 1247 not present AXELSON,W L. Region 3, Ofc of the Director, 88/12/01, 1p. 47802 240 47632 240
- -8812140244 Insp. Repts 50-015/85-24 & 50-016/88-28 on 881020-1116 Violations noted Major areas inspected operational safety, radialogs controls maint, surveillance, fire protection, limiting on prepared noss security & cut

8368 BURGESS,B.L. Region 3, Old of the Director 88/11/29 19pp 47802:241-4/ii:22:19

- 8811290030 NRC Into Notice 89-993, "Tolutherapy Events." Svc 1st engl CUNNINGHAM,R E. Civision of Industrial & Medical Nuclear Safety (Post 8/0/25) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811,103 4/(II) 215 8811290538 NRC Info Notice 88-094, "Potentially Unifersized Valvo Actuators" Sec Est
- HOSSI.C.E. D.v.ston of Operational Events Assussment (Post 870411) 88/19/02 Consolidated Edison Co. of New York, Inc. 121pp 47708:143-47708:254
- 8812130002 Forwards Safety Insp. Repts 50-315/88-26 & 50-316/88-30 en 661107-23 No violations noted WRIGHT, G.C. Rogion 3, Oic of the Director 88/12/02, ALEXICH,M.P. Indiana Matagan Power Co. (formarly Indiana & Michigan Electric Co.), 2pp. 47792.316-4778235)
- -8812130005 Safety Insp Ropts 50/315/88/26 8 50/316/88/30 on 881107/29, No reds tions noted Major areas inspected licensee action on previous insplintable all recording weather than the provided with the provided section of previous insplintable and provided weather than the provided weather the provided weather than the provided weather than the provided
- 8812090051 Responds to NRC 691103 ftr re-violations noted in Insu Rept 50-316/e924 on 880905-15 Corrective action reviews of rediographic film Indiated on steam (in the of substants from the following words.

 ALEXICH, M.P. Inclains Michigan Power Co. (formorly Indiana & Michigan Efective Cot. 84/12/05). DAVIS, A.B. Decument Central Branch (Document Control Desk). 559, 47762-287-47762-291.
- 8812120240 Responds to NRC 881205 ftr re-violations noted in Instr Repts 50 315/89 23 & 50-316/88-27-Corrective action taken damper lineup conducted using Procedure 01-01P 4021 028-008 to reposition four dampers to correct position.

 ALEXICH, M.P. Indiana Michigan Power Co. (formarly Indiana & Michigan Frech : Co.) 86/12/05. DAVIS.A.B. Document Centrol Branch (Document Control Desk) 4pp 47785:356-47785:359
- 8812020287 NRC Info Notice 88 095, "Inadequate Procurement Requirements in possibly technisors on Verstors." Svc 1st and ROSSICE Division of Operational Events Assessment (Post 870411) 89/12/C3 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 0812190011 Provides final rept of evaluation of acceptability of wolds made in partialities the provided sys using ER308L wold mall.per Insp Rept 50-316/88-12 Rosults of lowers & engineering evaluations completed subsequent to 880817 transmittal and ALEXICHEM P. Indiana M.chigan Power Co. (formerly Indiana & Michigan Etodino Co) 88712/09. DAVIS.A.B. NRC No Detailed Affiliation Given 8pp. 47859277-47859284.
- 8812200108 Forwards Safety Insp Rept 50-316/88-26 on 880907-1129 & safety evaluation No violations noted HARRISON, J. Reg on 3, OIC of the Director 98/12/09 ALEXICH, M.P. Indiana Vite. gan Power Co. (termerly Indiana & Michigan Electric Co.), 2pp. 47871 324-47671:344
- ~8812200109 Safety Insp. Rept. 50-316/88-26 on 880907-1129 No violatoral noted Major arroas inspected provious Insp. findings re-welding issues, raway of procedures, quelifications & in-process work activities. JACOBSON, J.M., LIU, W.C., WESTBERG, R.A., Region 3, Ofc. of the Director, 88/12/08, 6pp. 47871:326-47871:331.
- --8811170057 Forwards safety evaluation to crecking of reactor coolant piping to 61333 generator nozzle wolds at plant.Cracking considered significant event due to number 8 depth of repairs.Findings 8 conclusions listed CHENG.C.Y. Materialings Engineering Branch 88/11/09. SCOTT.W.E. Project Directivate III-1, 2pp. 47871:332-47871.333
- -8812200120 Safety evaluation re-cracking of steam generator nozzle to reactor cost ant piping welds.
 Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/09 11pp
- 47871:334-47871:344

- 8812190336 Forwards Insp Repta 50:315/88-25 & 50:316/98-29 on 881031-1104 No violations noted they team conclusion that left meeting commitments to improve requalification training program noted WRIGHT,G.C. Region 3, Ofc of the Director B8/12/14 ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 47853 231-47853 249
- --8812190340 thsp Repts 50:315/88-25 & 50:316/88-29 on 891031-1104 No violations or deviations noted Major areas inspected accessed operator requalification training reducting evaluation of commitments to improve program POPKINS, J.A., DAMON, D.J., BURDICK, T.M. Region 3, Otc. of the Director 68/12/14

S. Reportable occurrences, LERs & related correspondence

- 8811300572 NPCES moncompliance notification on 881114, sample of prefitur backwash efficient (Ostfall ODF) analyzed for suspended softins a redicated 171 mg/1.Rough lake conditions stirred bottom sedments coming linto prant Intake water MENGE.RC Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.) 89/11/18 ZUGGER.P.D. Michigan. State of 2pp. 47674-193 47674-194
- 8612080146 Supplemental RO offsite location found that yields higher calculated dose through milk palliway,per tand use consus. Calculations will be based on assumption that mik an mal located 3,800 motors from plant in each tand sector ALEXICH.M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.) 88/12/05 DAVISA B. Document Control Branch (Document Control Desk). 2pp 47753.343-47753.344

V. Operator Examinations

- 8812190336 Forwards Insp Repts 50-315/88-25 & 50-316/88-29 on 881031-1104 No violations noted inspitiesm conclusion that util meeting commitments to improve requalification training program noted WRIGHT, G.C. Region 3, Ofc of the Director 88/12/14. ALEXICH, M.P. Indiana M.ch. gan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 47853.231-47853.249.
- -8812190340 Insp. Ropts 50:315/88-25 & 50:316/88-29 on 881031-1104 No violations or devations noted Major areas inspected. I consed operator requalification training-rounding availabilities occimilities to improve program HOPKINS,J.A. Region 3, Ofc of the Director 88/12/14, 17pp. 47853-233-47853-240

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812060131 Changes 20 & 21 to Rov 12 to Emergency Plan Implementing Procedure, ERPIP 3.0, "Personnel Injury."
 * Baltimore Gas & Electric Co. 88/11/09, 8pp. 47742 308-47742 315
- 8812060141 Rovised unorgancy response plan implemention procedures, including Change 8 to Rev 11 to ERPIP 4.1.6, "Offsite Monitoring Team" & Change 14 to Rev 9 to ERPIP 4.1.76, Change 15 to Rov 0 to ERPIP 4.1.82.

 * Balumoro Gas & Electric Co 88/11/22 28pp 47741.107-47741.134.
- 8812080136 Revised emergency response plan implemention procedures, including Change 10 to Rev 9 to ERPIP 4.1.15, "Deposition Calculations" & Change 4 to Rev 9 to ERPIP C.1, "Reactor Core Major Radiolsotopes Inventory."

 * Balt more Gas & Floctice Co. 88/11/23, 8pp. 47741:186-47741:203.
- 8812060143 Rov 12 to Emergency Plan Implementing Procedure ERPIP 5.1, "Communications Equipmont."

 * Baltimore Gas & Electric Co. 88/11/20, 24pp. 47742:316-47742:339
- 8812120160 Change 6 to Roy 5 to Emergency Response Plan Implementing Procedure ERPIP 4.1.22.1. Baltimoro Gas & Electric Co. 88/12/02, 10pp. 47785.346-47785.355
- 8812120166 Rev. 11 to Emergency Rosponso Plan Implementing Procedure ERPIP 4.1.25, "Environ Svcs."

 * Baltimore Gas & Electric Co. 88/12/03 16pp. 47788 025-47788 040

H. General correspondence

8812010170 Comment on proposed rule 10CFR26 to Fitness for Outy Program Supports NUMARC proposal that entire linal rule be made effective 190 days after publication & redefication of drug abuse.Requires Commission justify rule per 10CFR50.109. TIERNANUA Baltimore Gas & Electric Co. 88/11/18. Docketing & Services Branch. 11pp. 47679:065-47679 075.

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 88-20 to all ticonsoos holding OLs & CPs for nuclear power reactor facilities no individual plant exam for severe accident vulnerabilities Svc list encl CRUTCHFIELD.D. Associate Director for Projects (Post 670411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729-024.
- 8812060213 Forwards final typed Tech Spec pages discussed in Chango 1 to 880616 application for amend to Licenses DPR-53 & DPR-69. OSBORNE_J.M. Bullmore Gas. & Electic Co. 88/11/29. Document Control Branch (Document Control Desk). Ip. 47752:200-47752:202.
- --8812080216 Proposed Tech Specs discussed in Change 1 to 880616 application for amond to Licenses DPR-53 & DPR-69.
 * Baltimore Ges & Electric Co. 88/11/29, 2pp. 47752;201-47752;202.
- 8812070099 Forwards proposed change to FSAR QA program description & QA policy. Proposed change would reduce, by one level of mgt, position at which senior reactor operator ficense must be held.

 TIERNAN, J.A. Battimore Gas & Electric Co 88/12/01. Document Control Branch (Document Control Desk). 13pp. 47745-285-47745-297.

- 8812070220 Requests that util address Generic Ltr 88-17 re toss of DHR during non-power operation Industry response to Generic Ltr 87-12 deficient in areas of preven-tion of accident initiation & mitigation of accidents prior to core damage MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 8704.11) 88/12/ 02 MCGOWAN,G.V. Beltimore Gas & Electric Co. 4pp. 47746-107-47746-110
- 8812120245 Rov to 890315 application for amends to Licenses DPR-53 & DPR-89,replacing Pages 6-3,6-6 & 6-7 w/Pages 6-1a,6-6 & 6-7 re plant operations & safety review committee membership.
 RUSSELL,L.B. Baltimore Gas & Electric Co. 88/12/02. Document Control Brench (Document Control Desk). 2pp. 47788.007-47788:014
- Balt more Gas & Electric Co. 88/12/02, 6pp. 47788 009-47788 014
- 8812070110 Forwards notice of consideration of issuance of amonds to Licenses DPR-53 & DPR-69 & opportunity for hoaring on 890315 application to modify Tech Spec 6.2. "Organization." MCNEIL,S.A. Project Directorate 1-1, 88/12/05. TIEHNAN,J.A. Baltimore Gas & Elec-
- -8812070112 Notice of consideration of Issuance of amend to Licenses DPR-53 & OPH-69 & apportunity for hearing on 880315 request re-reviol requirement of Tech Spec 6-2.2 concerning organization CAPRA,R A Project Directorate I-1 88/12/05 5pp 47745-267-47745-278.
- 8812080128 Forwards modified notice of consideration of Issuance of amends to Li-censes DPR-53 & DPR-69 & opportunity for hoaring relutil 891025 request to modify 880609 application to reduce max limit for Kuff to 0.95. MCNEIL, S.A. Project Directorate 1-1, 88/12/05 T.ERNAN, J.A. Balt more Gas & Elec-tric Co. 2pp. 47753 211-47753 224.
- --9812080130 Modified notice of consideration of issuance of amends to Licenses DPR-53 & DPR-69 & opportunity for hearing on 881025 request to modify 880609 application to reduce max I mit for Kelf from 0.98 to 0.95.

 CAPRA,B.A. Project Directorate I-1, 88/12/05, 5pp. 47753:213-47763:224
- 8812210314 Application for amonds to Licenses DPH-53 & DPH-69,changing Tech Specs to provide for extension of Type B & C tests w/ gas at 50 ps/g until Spring 1989 schedu/od reliabing cutage Fee µ at TIERNAN, JA Hattmare Gas & Electric Co 88/12/14, Document Control Branch (Document Control Desk), 12pp. 47874.311-47874:334.
- --8812210315 Proposed Toch Specs to survailance requirements for offsite transmission network & ensite Class 1E distribution sys

 * Beltimore Gas & Electric Co | 86/12/14 | 12pp | 47874/323-47874/334

- 8811180288 "PRA Applications Program for Insp at Calvert Cliffs Unit 1 Nuclear Power VO.T.V., HARRIS,M.S., GORE,B.F. Datto'le Memorial Institute, Pacific Northwest Laboratory. FtN: B-26t/2: 88/05/31. Office of Nuclear Reactor Regulation, Director (Post 870411), 88pp. 47597-115-47597-202.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Romoval of Industrial Nuclear Gauges" Svc 1st uncl CUNNINGHAM,RE Division of Industrial & Medical Nuclear Safety (Post 870729) 88/117/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708:257.
- 6811160467 NRC Info Notice 68 091, "Improper Administration & Control of Psychological Tosts." Svc list end. ROSSI.C E Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co of New York, Inc. 101pp. 47708.042-47708.142.
- 8812090188 Forwards still into re-util response to NRC Bullatin 88-901 re-datects in Wostlinghouse circuit breakers Thirty breakers will have pole shafts replaced during nest normal proventive maint or by and of nest Unit 2 refueling outage. TIERNANJA Baltimore Gas & Electric Co. 88712701. Document Control Branch (Document Control Dask). 2pp. 47786-356-47786-357.
- 8811290030 NRC Inlo Notice 88-093, "Telotherapy Events." Svc list encl. CUNNINGHAM, R.E. Division of Industrial & Modical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp 47011:103-47811-215.
- 8811290538 NRC Info Notice 88 094, "Potentially Undersized Valve Actuators" Svc list encl ROSSLCE. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708-254.
- 8812020287 NRC Info Notice 88-095, "Inadequato Procurement Requirements Imposed by Licensees on Vendors" "Svc 1st end. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/12/06. Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302.
- 8812210013 Forwards Safety Insp Repts 50:317/88-29 & 50-318/88-29 on 881031-1104 & notice of violation. Independent measurements taken to vonly util capability for analyzing radioactive effluents Data will be reported in subsequent Inspirept. BELLAMY, R.R. Region 1, Oic of the Director, 88/12/13, TIERNAN, J.A. Beltimore Gas & Electric Co. 2pp. 47875-329-47875-349.
- -8812210018 Notice of violation from insp on 881031-1104. Violations noted scaling fac-tors used to determine radwastic concentrations not evaluated semiannually & two shipments of radioactive mails improperly classified. * Region 1, Ofc of the Director. 88/12/13 2pp. 478/75:331-47875:332
- -8812210022 Insp Repts 50/317/88-29 & 50/318/88-29 on 881031-1104. Violations noted Mejor areas inspected norradiological chemistry program, including confirmatory measurements, radwaste sys & radiological environ monitoring program FURIAJ., DAVIDSON,B., JANG,J. Region 1, Ofc. of the Director. 88/12/08. 17pp. 47875.333-47875.349.

R. Period's operating reports & related correspondence

8812200201 Monthly operating repts for Nov 1998 for Calvert Ciffs Units 1 & 2 W/ BEHMAKEIC, RUSSELLL & Baltimore Gas & Electric Co. 89/11/30, 12pp, 47867-301-

S. Reportable occurrences, LERs & related correspondence

- 8812020258 LERI BB:011 GO on 851026,dscovered that pressurizer code safety valve performing pressure relict function above may value arowed by Tech Specs Caused by discretize in temp profile conditions of safety relief valves W/881128 ltr. SLYCID_RUSSELL LB. Baltmore Gas. & Electric Co. 85/11/28 6pp. 47721.087-47721 592
- 8812120258 LER 68 010 01 on 880628 containment personnel air lock interlock discov ered indigitable during portormance of solver lands test procedure Caused by improper solver procedure which of clarry fra ning provided W/881202 in LARRASQUIFELS. RUSSELL, L.B. Batimore Gas. 8. Electric. Co. 68/12/02. 9pp. 47/86.023.47/86.034.
- 8812220138 LER 88 012 00 on 681114 furbine runback actuated due to low stator cool-ing water pressure alarm Caused by incorrectly calibriatarm switch Selpoint fire revised to correct design set point for low stator cooling pressure W/881213 ftr FUROIP, RUSSELL WIT Baltimore Gas & Electric Co. 88/12/13 Spp. 47916 168-47916 172
- 8812270228 LER 65 012 01 on 881114 lumbne runback actualed by fow stator coolant pressure Caused by reduction in generator hydrogen pressure during hydrogen feed & tied procedure Setpoint fla revised W/881222 ltr. FURS.0P. RUSSELL, B. Baltimore Gas & Electric Co. 88/12/22 Spp. 47927.125-47927.129

V. Operator Examinations

8812070099 Forwards proposed change to FSAR OA program description & QA policy Proposed change would reduce by one level of mgt, position at which sen'or reactor operator license must be he'd TIERRIANULA Battmore Gas & Elective Co. 88/12/01 Document Control Branch (Document Control Desk) 13pp. 47745/235-47745/237

DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8812060131 Changes 20 & 21 to Rev 12 to Emergancy Pian Implementing Procedure, ERP.P 3.0. Personnel Injury." Baltimora Gas & Electric Co. 88/11/09 8pp. 47742 308 47742 315
- 8812060141 Revised Emergency response plan implemention procedures, including Change 8 to Rev 11 to ERPIP 4.1.6 "Offsite Monitoring Team" & Change 14 to Rev 9 to ERPIP 4.1.8 Change 15 to Rev 0 to ERPIP 4.1.8 2.

 * Baltimoro Gas & Electric Co. 88/11/22, 28pp. 47741, i07-47741:134
- 8812060136 Revised emorgency response plan implemention procedures, including Change 10 to Rev 9 to ERP.P 4 1.15. "Deposition Calculations" & Change 4 to Rev 9 to ERPIP C 1, "Reactor Core Major Rad disolopes Inventory"

 * Baltimore Gas & Electric Co. 86/11/23. 8pp. 47741:196-47741:203
- 8812060143 Flev 12 to Emergency Plan Implementing Procedure ERPiP 5.1, "Communications Equipment."

 Bail more Gas & Electric Co. 88/11/29, 24pp. 47/42, 316, 47742, 339
- 8812120160 Change 6 to Rev 5 to Emergency Response Plan Implementing Procedure Batt more Gas & Electric Co. 88/12/02, 10pp, 47785, 346-47785, 355
- 8812120156 Fjev 11 to Emergency Response Plan Implementing Procedure ERPIP 4.1 25, "Environ Sycs." 4.1 25, "Environ Sycs." * Baltimora Gas & Electric Co. 88/12/03, 16pp. 47768-025-47788-040

H. General correspondence

8812010170 Comment on proposed rule 10CFR26 re Filness for Duly Program Supports NUMARC proposed that entire final rule be made effective 180 days after publication & redefinition of drug abuse Requires Commission justify rule per 10CFR50.109. TERNAN JA Ballmore Gas & Electric Co. 88/11/18. Docketing & Services Branch. 11pp. 47679.065-47679.075.

P. Operating license stage documents & correspondence

- 8811280048 Genenc Lir 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnerabilities Svc list ents CRUTCHFIELD.D Associato Director for Projects (Post 870411): 88/11/23. Consoli-dated Edison Co. of New York, Inc. 81pp. 47728 303-47729.024
- 8812060213 Forwards final typed Tech Spec pages discussed in Change 1 to 880616 application for amend to Licenses DPR-53 & DPR-59 OSBORNE_J.M. Bat more Gas & Electric Co. 88/11/29. Document Control Branch (Document Control Desk). Ip. 47752 200-47752 202.
- --8812060216 Proposed Tech Specs discussed in Change 1 to 880616 application for amend to Licenses DPR-53 & DPR-69.

 * Ba'imnore Gas & Electric Co. 88/11/29 2pp. 47752.201-47752.202.

8812070099 Forwards proposed change to FSAR QA program di policy Proposed change would reduce, by cro-level of mgt, position reactor operator Loerse must be held. TIERNAN, A. Ballmorre Gas & Electric Co. 08712701 Decimi

- 8812070220 Requests that uh address Generic Ltr 88 t7 re loss of power operation Industry response to Generic Ltr 87-12 defection as then detected in taken & intigation of accounts prior to coro dana, MURLEY,T.E. Otice of Nuclear Reactor Regulation, Director (Post of MCGOWAN,G.V. Ballimore Gas & Electric Co. App. 47746-107-47
- 8812120245 Rev to 880315 application for animids to Licensus (1994) pacing Pages 6-3,6-6-8, 6-7 w/Pages 6-1a,6-6-8, 6-7 re-plact cubreway committee membership RUSSELL, 8-89t more Gas 8-Floatio Co. 88712702 Document (Document Control Dosk), 2pp. 47788-007-47788-014
- -8812120248 Proposed Tech Spics Pages 6-18,6-6-8,6-7,Cparent, 3-6-3,6-6-8-6-7 in 880315 amend application to troopanization.in:Latassistant general supervisors operations to organization chart 3-8 Baltimore Gas & Electric Co. 68712702. Gap. 47789 009-47789 009-
- 8812070110 Forwards notice of consideration of assumed of animals to 53 & EPR-69 & opportunity for bosing on 880.415 application to re-6.2. "Organization" MCNEIL, S.A. Project Directorale E1 88712705 - Till PINAN, EA. Bellin. Inc Co. 2pp. 47745-255-47745-278
- ~8812070112 Notice of consideration of resonance of amond to bire. DPR 69-8 opportunity for Learning on 880315 request to reviol requirements of control of the control of
- 8812080128 Ferwards modified notice of consideration of issuance of conses DPR-53 & DPR-69 & opportunity for treating roll of 881625 re 880609 application to reduce maximul for Kelf to 0.95.
 WONEL SIA Project Directorate 11 88712705 TIERMAN SIA Batter to CO 2pp 47753 211-47753 224
- --8812080130 Modified notice of consideration of issuance of amends to 53 & DPR-69 & opportunity for treating on 8018025 request to modify tool to reduce may hart for Kuff from 0.98 to 0.85 CAPRAIR A Project Directorate 1-1 08/12/05 5pp 47763 213-47/53
- 8812210314 Application for amends to Licenses DPR-59 & DPR-69 Specs to provide for extension of Type 8 & Citests w/ gas nt for 1969 scheduled refisching catego Fee paid TIERNAN, J.A. Ballimore Gas & Efectino Co. 88/12/14 Decument (Document Control Nesk), 12pp. 47874-311-47874-334
- #8812210316 Proposed Tech Specs in Surveillance requirements for commonwork & onsite Class 1E distribution sys.
 * Batamore Gas & Electric Co. 68712734, 12pp. 47874-320-47874-334.

- 8811180211_NRC Into Notice 88-090, "Unauthorized Remova" of his Gauges," Svc hist enct. CUNNINGHAM,R E. Division of Industrial & Monteal Nucleur Salety 89/11/22 Consolidated Edison Co. of New York, Inc. 80pp. 47/00/255
- 8611160467 NRC Info Notice 86-091, "Improper Administration & Centro cal Tosts" Svollist end ROSSI,C E. Division of Operational Events. Assessment (Post 8704 Consolidated Edison Co. of Now York, Inc. 101pp. 47708-042-47708
- 8812080196 Forwards addlinto rolutt response to NRIC Ruhatin 88 to Westinghouse circuit breakers. Thirty breakers will have pote status riest commat reventive maint or by end of nost Unit 2 refricting outage TIERNAN, J.A. Batt more Gas. 8 Electric Co. 98712701. Document (Occument Control Dosk). 2pp. 47786:356-47788.357.
- 8811290030 NRC Into Notice 88 093, "To'otherapy Events." Svc. Ist onct CUNNINGHAM,R.E. Division of Industriat & Mudical Nuclear Safety 88/12/02, Consolidated Edison Co. of New York, Inc. 112pp. 47811
- 8811290538 NRC Info Notice 88:094, "Potentially Undersized Valve Act. enci.

 ROSSI,C E Division of Operational Events Assessment (Post 8704 Consolidated Edison Co. of New York, Inc. 121pp. 47709 14:3 47708 25
- 8812020287 NRC Info Notice 88-095. "Inadequate Procurement Required by Licensees on Vendors." Svc list unct. ROSSI,C.E. Division of Operational Events. Assessment (Post 8704 Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.30
- 8812210013 Forwards Safety Insp Ropus 50:317789:20 & 50:318789:1 1104 & notice of violation Independent measurements taken to verify it analyzing radioactive officients bala will be reported in subsequent insp BELLAMY, R.R. Region 1, Olf of the Director, 88712713, TIERNAN, J.A. & Electric Co. 2pp. 47875-329-47875-349
- 8812210018 Notice of violation from msp on 881031-1104 Violations not fors used to determine radwaste concentrations not evaluated sentic shipments of radioactive matts improperly classified.
 Region 1, Oto of the Director. 88/12/13. 2pp. 47875.331-47875.332
- -8812210022 Insp Repts 50-317/88-29 & 50-318/88-29 on 681031-1 noted Mejor areas inspected norwald ological chumistry program including measurements, redwaste sys & red/ological environ monitoring program FURIA_J_DAVIOSON_B_JANG_J_Region 1, Old of the Director, 88 47875 333-47875:349.

- 8\$12270055 Responds to NRC request for inforum West phouse. Type DS circuit breaker failure per NRC Info Nation 88:044 Cosing coll burned out & shorted Norbinding of Legaker mechanism found hasps performed on 20 add, therakers. LIPPOLDW J. Baltimore Gas & Electric Co. 88/12/19, Document Control Branch (Occument Control Desk). 2pp. 47927 062-47927 063.
- R. Periodic operating reports & related correspondence
- 8812200201 Monthly operating repts for Nov 1988 for Calvert Cliffs Units 1 & 2 W/ 681214 Pr BEHNICE C., RUSSELLI, L.B. Ballimaro Gas & Electric Co. 88711730 (12pp. 47867.30).

V. Operator Examinations

- 8812070099 Furwards proposed change to FSAR QA program description & QA policy Proposed change would reflece by one level of migl, position at which serior made operator license must be held
 - HERNAN JA Baltimoro Gas & Flectric Co. 88/12/01 Document Control Branch (Document Control Desk). 13pp. 47745-285-47745-297

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 8812210168 Forwards FEMA & Regional Assistance Committee final exercise rept of offsital emergency preparedness plans for facilities Deliciencies noted nonparticipation of Lower Paxton Township & distribution of desimptry kits. KRIMMIR.W Furferal Emergency Management Agency 88/12/12 CONGELE J Divisor of Radiation Protection & Emergency Preparedness (Post 870411) to 47888:120-47889 212
- -8812210173 "FEMA & Regional Assistance Committee Exercise Rept of 871022 Exerc se. * Federal Emorgoncy Management Agoncy 88/11/04 92pp 47808 121-47888.212
- 8812220400 Forwards partially defended Physical Subgulards Insp Repts 50-289/88/31 & 50-320/88/18 on 881114-17 (ref. 10CFR/3/21) No waliabons observed Steps taken to correct waliations noted to NRC 841213,850603 & 18 lits arise venified BELLAMY, B.R. Region 1, Oto of the Director 887/27/21 HUKILL, B.D. Genera' Priblic Lit it os Corp. GPU Service Corp. 3pp. 47903/298-47903/308
- --8812220401 Partially withheld Physical Security Insp. Hepts 50-209/06-31. 8, 50-3297 88-18 on 881114-17 No violations noted Major group inspected unrusofized items & inspected following items, mgt. support & security program plans. SMITH, G.C. Region 1, Ofc. of the breeder, 08/12/09. 8(p): 47903-301-47993-308.

G. Adjudicatory correspondence

- 8812190138 Discusses now info re proceedings on preliminary tost of evaporator portion of accident-generated water disposal sys showing that decontain nation factor for soid in measured greater than 1,000 for all fost samples Svc 1st unct.

 BAXTERI,T.A. General Public Utilities Corp. GPU Sorvice Corp. BAXTERI,T.A. Shew, Priman, Potts. & Trowbridge, #488-7632-88/12/06. BLOCH,P.B., BRIGHT,G.O., PARIS,O.H. Atomic Safety and Licensing Board Panet. 5pp. 47801-187-47001.171.
- 8812190107 Liconsee proposed transcript corrections.* Certificate of Svc encl. BAXTER,T.A. General Public Utilines Cerp. GPU Service Corp. BAXTER,T.A. Shaw, P.timan, Potts & Trowbridge. #488.7656. 88/12/08. 18pp. 47802.188-47802.285.
- 8812190121 Licensoo proposed findings of fact & conclusions of law in form of pro-posed initial decision.* See list onet BAXTER.T.A. General Public Utilities Corp. GPU Servico Corp. BAXTER.T.A. Shaw, Pitman, Polts & Trowbridge. #408-7658-88/12/08-102pp. 47801-218-47801.319
- 8812270077 Joint Intervenors motion for extension of time to file proposed Endings of fact & canchisions of law.* Extension of time requested until 890116 Svc Lst encl. SKOLNICK,F. Throo Mile Island Alort. SKOLNICK,F. Susquehanna Valley Albance, Lancaster, PA #488 7682 88/12/12. Alomic Safety and Licensing Board Panel 4pp. 47872:306-47872:309.
- 8812270037 Licensod enswer to Jorni Intervenors motion for extension of time to file proposed findings of fact 8 conclusions of law.* Joint Intervenors have failed to show good cause for extension Hollated into 8 Certificate of 5vc ond.
 BAXTER.T.A. General Public Utilities Corp. GPU Service Corp. BAXTER.T.A. Shaw, Pitman. Potts 8. Irowbr.dgo. #488.7590. 88/12/14. Atomic Safety and Licensing Doard Panel. 9pp. 4/873-084-47873.092.
- 8812280250 NRC Staff response to Joint Interveners motion for extension of time to tile proposed lindings.* Joint Interveners have not established good cause for extension.W/Certificate of Svc.
- Self-Use State General Counsel for Hearings, #488-7755, 88/12/15, Atomic Safety and Licensing Board Penul. 5pp. 47884:203-47884:297.
- 88 12270044 Suppls #81206 ftr reporting on proliminary lest of evaporator portion of accident-generated water disposal sys. Vendor has implemented one of two piping configuration mods to improve boron removal efficiency. W/Svc list. BAXTER,T.A. General Public Utilities Corp. GPU Service Corp. BAXTER,T.A. Shaw, Pitman, Polts & Trowbridge. #488 7702, 88/12/16 BLOCH,P.B., BRIGHT,G.O., PARIS,O.H. Atomic Safety and Liconsing Board Panel. 3pp. 47873.080-47873.082
- 8812270167 Motion for extension of time * Grants Intervenors 1.wk extension until 881230 to file proposed findings of fact & conclusion of law,per 881212 request Served on 881220 BLOCH P.B. Atomic Safety and Licensing Board Panel #488 7713, 88/12/19, Susquehenna Vetey Alliance, Lancaster, PA. 1p. 47872.082-47872.082.

II. General correspondence

- 8811300222 Forwards L Drey Itir re-defay which has occurred in connection w/shipment of nuclear to wants a crisy in 18 or ay which i as occurred at connection Wishproant Offucer five Inch Net rolls from TMI CLAY.W.L. House of Rep. 88/10/31. ZECH,L.W. Commissioners. 1p. 47769.011-47709 011
- --8811300224 Regiosts into about invidents that have occurred during four month detay our rapozza mejmosis iniu adant no denis mat navo occurred during four month defay in shipment of TMI fiel & about related concerns DREY,K. Affikalion Not Assigned. 88709729. COWG/LL,C.J. Region. 1, Old of the Di-rector. 6pp. 47709.012-47709.019

P. Operating license stage documents & correspondence

- 8811280048 Generic 1.tr 89:20 to all Leanseas holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulcerabilities Svc list CRUTCHF(ELD,D: Associate Director for Projects (Post 870411), 88711723. Consolidated Edison Co. of New York, Inc. 81cp. 47720 303-47729 024
- 8812010090 Forwards application for amond to License DPR-73,consisting of Tech Spot Change Request 61 Amend will consolidate TMI-1 & TMI-2 radiological controls depts into site prograzation ROCHE, MB. General Public Utilities Corp. (3PU Service Corp. 88/11/23. Document Control Branch (Document Cantrol Desk), 2pp. 47698-272-47698-280.

- --8812010091 Application for amond to License OPR-73 consisting of Tech Spoc Change Request 61 consolidating TMI-1 & TMI-2 radiological controls depts into site organization HOCHE,M.B. Goderat Public Utilities Corp. - GPU Service Corp. 88/11/23, 4pp 47698 274 47698 277
- -8812010092 Proposed Tech Specs re-ringt position responsible for radiological controls
 * General Public Utilities Corp - GPU Service Corp 88/11/23 3pp 47698 278-
- 8812080014 Forwards charter for Advisory Panel for Decontamination of TMI-2,extending committee He until 901128 HOYLE,J.C. Office of the Socretary of the Commission 88/11/28 DEAN,J.L. General Survices Administration, 4pp, 47757 102-47757:117.
- --8812080015 Forwards updated charter by NHC on 881128 to extend life of Advisory Panel for Decontamination of TMr2 until 931128. HOYLEJIC Office of the Secretary of the Commission 80711720 Library of Congress 1p 47757
- --8012080019 Forwards charter for Advisory Panel for Decontamination of TMI-2 BHADBURNE, J.C. NRC No Cotellot Albiation Given, 80/11/28 SHARP,P.R. House of Rep., Interior & Insular Affairs BHEAUX,J. Senato, Environment & Public Works 5pp. 47757 107-47757:111.
- --8812080021 Continus proposal to renew Avisory Panel for the Decontamination of TMI-2 for 2 yrs DEAN, J.L. General Serv.cos Administration 88/11/09 HOYLE, J.C. NRC - No Detailed Afficiation Given 1p. 47757:112-47757 112
- --8812080022 Informs of NRC determination to renewal of Advisory Panel for TMI-2 for add: 2 yr ponoil HOYLE,J C. Office of the Secretary of the Commission 88/11/01, DEAN,J L. General Services Administration. 5pp. 47757.113-47757:117
- 9812060239 Forwards safety evaluation supporting approval of lower core support assentitly defueling STOLZ,FF Project Directorate I.4, 88712701, ROCHE,M.B. General Public Utilities Corp - GPU Service Corp. 3pp. 47734-184-47734-188
- -8812080241 Safety evaluation supporting approval of lower core support assembly & lower head defusing "Olice of Nuclear Reactor Regulation, Director (Post 870411) 88/12/01 2pp 47734:197-4773.198
- 8812190408 Approves Flev 19 to TMI-2 organizational planuncorporating decontamina-tion section into wasto migl section Encl Figure 1-2, Flev 19 should be substituted for existing organization plan Figure 1.1. STOLZ-JF. Project Directorate 1-4. 88/12/15. ROCHE, M.B. General Public Utrillus Corp. GPU Service Corp. 4pp. 47851:276-47851.279.

- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list end CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708.255-47708.257
- 8811160467 NHC Into Notice 88-091, "Improper Administration & Control of Psychological Tests. Svc 1st oncl ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708-042-47708-142.
- 8811290024 Forwards Safety Insp Rept 50:320/88-16 on 881009-1109.No violations noted BETTENHAUSEN,L. Region 1, Oic of the Director, 88/11/23, ROCHE,M.B. General Public Utdities Corp. - GPU Service Corp. 2pp. 47648.201-47648.213.
- --8811290026 Insp. Ropt. 50:320/88:16 on 881009-1109 No violations noted. Major areas inspected defueling. 8 decontamination activities including proper implementation of radiological controls & housekeeping measures. COWGILL, C., CONTE, R., JOHNSON, D. Rogion 1, Old of the Director. 88/11/23. 11p. 47648:203-47648:213.
- 8811290030 NRC Into Notice 88-093, "Telethorapy Events." Svc list encl. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729), 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.

- 8311290538 NRC info Notice 88 031. Potentially Undersized Valve Actuators. Svc 1st enci RONSSICE Division of Operational Events Assessment (Post 870411) 88/12/02 Consolitati filed ton Collect Naw York, Inc. 121pp 477C6 143-47706 254
- 8812020281 ft/PIC into fterice 68 625 Ticrasequate Procurement Requiremental Imposed by techniques on Vendors ("Size ist end I ROSSICIE (Ites on ict Operation)) Events Assessment (Post 870411), 88712705 Conto dat J Edison Collaboration Pork, Inc. 112pp. 47807, 191-47807, 302
- 8812220400 Forwards partially deleted Physical Sategoards Insp. Repts 60-289/88:31-8 59-220/68:13 on 861114-17 ref. 10CFR/3-211 No whatens observed Steps taken to correct voostons netwine hard 841213,950601-8 18 insiable verified 6ELCAAW R.R. Regan 1. Onlet Insi Director 88/12/12 HJKKILL H.D. General Public Utitios Corp. 1 GPU Service Corp. 3pp. 47503-299-47903-398
- #812220401 Panally withing Physical Security Insp. Repts. 50 289788-31. 8: 50-3207 88-18 on 881114-17 No void: ons noted Major areas inspected unresolved items. 8: Inspect in follows pictals and support 8 security program plans. SM THIGG CAMERON D.F., KEIMIG R.R., Region. 1, Orci of the Director. 88712709. 8pp. 47903-301-47903-308.

R. Periodic operating reports & related correspondence

- 8812050087 TMH 2 Effluent & Offsite Dose Rept for Jul-Sept 1988 " W/881129 ttr. ROCHE M 9 General Public Unities Corp GPU Service Corp 88/09/30 12pp. 47731 147 47731 158
- 881130519 Forwards TMI monthly status rept for 881007-1105 COMGLECU Region 1, Ofcief the Director 88/11/15 BETTENHAUSEN,E. Region 1, Ofcief the Director. 7pp. 47676 111-47676 117

T. Hearing transcripts on non-antitrust matters

8812270037 Licensee answer to Joint Intervenors inclination for extension of time to fife proposed findings of fact & conclusions of few I Joint Intervenors have failed to show good causo for extension Rolated into & Certificate of Sice and EAXTER, TA General Public Unities Corp. GPU Service Corp. BAXTER, TA Shaw, Priman, Polits & Trowbridge. #488 7690; 88/12/14. Atomic Safety and Licensing Board Fanel. 9pp. 47873 084-47873 092.

DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- \$412090102 Revised emergency plan implementing procedures including Rays 0 to 63EP-EIP-012-OS-63EP-EIP-018-OS-63EP-EIP-021-OS-63EP-EIP-022-OS-63EP-EIP-022-OS-73EP-RAD-005-OS-6 63EP-EIP-022-OS-W881205 III. SUMMERIT Georga Power Co. 88/11/07 48pp 47762 020 47762 068
- 8812200112 Rev 0 to Emergency Plan Implementing Procedure 63EP-EIP-067-OS, "Ac-bors for All Plant Personnel During Security Alert." W/881214 ltr SUMMERJ, HAIRSTON,W.G. Georgia Power Co. 88/11/17, 3pp. 47658-266-47858 269
- 8812120011 Confirms annual emergency preparedness exercise on 891025.

 MARSTON,W G. Georgia Power Co. 88712705. Document Control Branch (Document Control Desk). 2pp. 47780.164-47769.165.

H. General correspondence

8812120059 Comment opposing proposed rule 10CFR2 re records related to licensing high level radwaste geologic repository. Ut1 endorsos EEI comments to be submitted to NRC. DAMASTON,W.G. Georgia Power Co. 88/12/05. CHILK,S.J. Office of the Secretary of the Commission. 2pp. 47798 087-47798 086.

P. Operating license atage documents & correspondence

- 8811290309 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Mail & Impact on Plant Operations," per Rev 2 to Reg Guide 1.99 Pessure-temp will be revised by end of second refueling outage for Unit 2 HA/RSTON-W.G Georgia Power Co. 88/11/22 Document Control Brench (Document Control Desk), 25pp. 47864:159-47664.183.
- 6811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclnar power reactor facilities re individual plant exam for severe accident vulnorabilities Svc list enci. CRUTCHFIELD,O Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 8811300096 Notification of 881201 meeting w/util in Rockwile MD for util presentation of evaluation of bent rockbotis observed on Unit 1 Proposed agenda enci. CROCKER,L.P. Project Directorate II-3 88/11/23 MATTHEWS,D.8. Project Directorate II-3 4pp. 47697-356-47697:359
- 6812160035 Summary of 881201 meeting w/wtil in Rockville,MD re present status of investigation re bent rockbolts anchoring torus. List of attendees & related into enct. CROCKER,L.P. Project Directorate II-3: 68/12/08 MATTHEWS,D.B. Project Directorate II-3: 89pp. 47835:008-47835:095
- 8812200037 Forwards questions re contamment integrity of bent rockbolts in plant forus anchorage, for ongoing evaluation CROCKERILP. Project Directorate II-3. 68/12/14. HAIRSTON,W.G. Georg'a Power Co. 3pp. 47962.187-47862
- 8812220032 Forwards safety evaluation re compliance w/ATWS rule (10CFR50 82) Util complies w/requirements except for open item re testability of atternate rod injection system at power.

 CROCKER,L.P Project Dwectorate II-3 88/12/14. HAIRSTON,W.G Georgia Power Co 4pp. 47886 286-47886 301

- -881222036 Safety evaluation supporting util actions to comp (10CFB56 62),specifically alternate rod injection 8 recirculation pu-tern noted at establish of alternate rod injection sys while at power. * NRC No Detailed Attination Given: 88/12/14 12pp. 47885/293-47
- 8812200180 Forwards additinfo to orwinon offects attributable to transfuel softwars outlined in 10CFRS1 52 per Nov 1988 request for nod fy OLs to 40 yrs from date of issuance. HARRSTCN,W.G. Georgia Power Co. 88/12/15. Document Control E. Control Desk). 3pp. 47860 248-47860 248.
- 8812270071 Forwards updated listing of outstanding licensing submitt proval requested for certain priority items, including proposed ficans, yrs from Ct. vice CP. HAIRSTON,W.G. Georgia Power Co. 88/12/20. Document Control E. Control Desk). 3cp. 47927.12247927.124

- 8811160211 NRC Info Notice 88.090, "Unauthorized Removal of Gauges." Svc list end: CUNNINGHAM, B. Division of Industrial & Morfical Nuclear Sate 88/11/22, Consolidated Edison Co. of New York, Inc. 99pp. 47708.2
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Conf cal Tosts " Svc list enci. ROSSI,C E. D:vision of Operational Events Assessment (Post 87 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.
- 8811290030 NRC Into Notice 88-093, "Teletherapy Events." Svc list or CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safet 88/12/02. Consordated Edison Co. of New York, Inc. 112pp. 4781
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve A ROSSI.C.E Division of Operational Events Assessment (Post 87) Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708
- 8812050063 Advises that util 680711 response to NRC Bullotin 88-004 CROCKER,t.P. Project Directorate II-3, 88/12/02, HAIRSTON,W.G Co 4pp 47731:162-47731:165.
- 8812050069 Advises that ubl 880705 response to NRC Bulletin 88-Hatch Engagement in HFA Type Latching Relays Mile by GE," accep CROCKER,L.P. Project Directorate II-3, 88/12/02 HAIRSTON,W G Co. 3pp 47/31:202-47731:204
- 8812190303 Forwards Insp Repts 50-321/88-36 & 50-366/88-36 on 86 febions or deviations noted. JULYAN,CA. Region 2, Olic of the Director. 68/12/05. HAIRSTO Power Co. 2pp. 4/850-242-47850.254.
- -8812190305 Insp Repts 50-321/88-36 & 50-366/88-36 on 861101-0-devations noted Major gross inspected. follow-up to operational permon conducted on 880509-20,per Insp Ropts 50-321/88-15 & 50-36 STARKEY,D., SHYMLOCK,M Rogion 2, Ofc. of the Director. (47850.244-47850.254.
- 8812180171 Forwards Insp Repts 60-321/68-33 & 50-366/86-33 on 88 lations or deviations noted. DECKER,1.1. Region 2, Otc of the Director. 88/12/06. HAIRSTO Power Co. 2pp. 47832:245-47832 257.
- -8812160174 Insp Repts 50-321/88-33 & 50-366/88-33 on B81024-2t deviations noted Major areas inspected insp Procedure 84750 rac chemistry, confirmatory measurements & radiological environ monitoring MARSTONIRS, KAHLE, J.B. Region 2, Ofc of the Orector 847832 247-47632:257.
- 8812120193 Responds to NRC 891108 litr ra violations noted in Insp. F 30 & 50-368788-30. Corrective action.limiting condition for operation is Spec. 3.7. A.8. & involved personnel counselled. HAIRSTON,W.G. Georgia Power Co. 88/12/07. Document Control B Control Desk). 6pp. 47788:294-47786.299.
- 8812020267 NRC Into Notice 88-095, "Inadequate Procurement Requible Licensees on Vendors." Svc list end.
 ROSSICE Division of Operational Events Assessment (Post 870 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807.
- 8812210059 Confirms 881219 mgl meeting w/util in Birmingham,AL to plant oversight responsibilities,technical support responsibilities & at rate organization,per 881205 telcon re listed Intsp repts. ERNST.M.L. Region 2, Otc of the Director. 88/12/13. HAIRSTO Power Co. 3pp. 47886.101-47888:103.
- 8812200233 Forwards Insp Repts 50-321/88-34 & 50-366/88-34 on notice of violation.

 BROWNLEE,V.L. Region 2, Ofc of the Director, 88/12/14. HAIRSTO
 Power Co. 2pp. 47855-210-47855-231.
- -8812200238 Notice of violation from insp. on 881022-1125.Violation take initial corrective action w/knowledge that automatic depressurit such that loss of automatic sys operation could result from single fails BROWNLEE,V.L. Region 2, Oic of the Director, 88/12/14, 2pp. 4785
- -8812200242 Insp Repts 50-321/88-34 & 50-386/88-34 on 881022 observations, surveillance testing observations, Ros & NAC Bulletin 88 MENN:NG.J.E., MUSSER,R.A., SINKULE,M.V. Region 2, Otc of the 15, 18pp. 47855:214-47855:231.

- 8812200348 Forwards summary of 881123 mgt maeling ro mgt contro's of we'd ng pro-gram at plant w/emphas's on adequacy of we'ding on RWCU sys,per Insp Repts 50-321/88-31,50-366/88-31, 50-321/88-35,50-366/88-35,50-321/88-38 & 50-366/88-38 ERNST.ML. Region 2, Oft of the Director 88/12/14. HAIRSTON,W.G. Georgia Power Co. 6pp. 47867:264-47867.269.
- R. Periodic operating reports & related correspondence
- 8812190260 Monthly operating repts for Nov 1988 for El Hatch Units 1 & 2 W/881214 TUCKER JE., HAIRSTON W.G. Georgia Power Co. 88/11/30. 12pp 47850-285-47050 296
- S. Reportable occurrences, LERs & related correspondence
- 8812010342 LER 88-015-00.on 881026.informed that automatic depressurization systems as such that single failure (battery) could cause sys to be unable to perform safety function.Caused by inadequate design review W/801122 Its. TIPPS.S.B., HAIRSTON.W.G. Georgie Power Co. 88/11/22 8pp 47703.175-47703 182
- 8812120180 Special Rept 88:008:on 881101, fire watch not established & fire rated asembly not restored to operable condition within 14 days as required Event had no adverse impact on plant safety Poisonnel counseled & cable tray end modified. HAIRSTON,W.G. Georga Power Co. 88/12/07. Document Control Branch (Document Control Branch (Document Control Desk). 7pp. 47786-016-47786-022.
- 8812150081 LER 88-006-01:on 880809,RWCU primary containment isolation sys valves closed on Group 5 isolation signal whitch was unanlicipated actuation of ESF.Caused by excessive pump whallon due to deteriorated bearings W/881209 it.

 TIPPS.S.B. HAIRSTON.W.G. Georgia Power Co. 88/12/09. 7pp 47826 026-47826 033

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

- F. Security, medical, emergency & fire protection plans
- 8811300001 Forwards response to FEMA post-exercise assessment for 880607-09 exe причинг полнатиз темритви то пемя рознохегова assessment for 880607-09 ох-ercise of local offsile radiological amergancy response plan & response to FEMA re-plonal assistance committee review commont for Rev 10 of plan. LEONARD, JD. Long Is'and Lighting Co. 88/11/21. Document Control Branch (Docu-ment Control Dask). 14pp. 47701:333-47701:346.
- 8812210291 FOIA request for records identified in onci GC Peterson 880818 fir re-offsite emorgency plans & proparedness. BELAIR,R.R. Kirkpatrick & Lockhart, BELAIR,R.R. Suffolk County, NY, 88/11/21, NRC No Detailed Attriation Given, 4pp. 47874:045-47874:048
- 881208089 Forwards Rov 2 to updated FSAR for Shergham Nuclear Power Station Unit 1 & Rov 4 to Fire Hazard Analysis Ropt for 870608 800607.pgr 10CFR50.59. LEONARD.J.D. Long Island Lighting Co. 89/12/05. Document Control Branch (Document Control Dosk). 2pp. 47751.078-47752:157.
- -8812080091 "Rev 4 to Fire Hazard Analysis Rept."
 * Long Island Lighting Co. 88/06/07, 9pp. 47751:080-47751:089
- 8812130257 Staff requirements memo ro 881201 affirmation/discussion & vote in Rockvile,MD on SECY-88-201A concerning facility exercise. CHILK,S.J. Office of the Secretary of the Commission 88/12/08. Office of the Secretary of the Commission. 1p. 47795:357-47795.357.
- 8812160273 Vol I to "Shoreham Nuclear Power Statton Local Offsite Emergency Response Plan,App B." W/881208 Itr.
 LEONARD,J.D. Long Island Lighting Co. 88/12/08. 736pp. 47818.213-47820:320.
- 8812200110 Forwards Safety Insp Rept 50-322/68-08 on 880916-1118.No violations noted. WIGGINS,J.T. Rogion 1, Ofc of the Director. 88/12/12. LEONARD,J.D. Long Island Lighting Co. 4pp. 47863 050-47863 092.
- --8812200114 Insp Rept 50-322/88-08 on 880916-1118.No violations nated. Major aroas inspected.plant operations, radiation protection, security.plant events, maint surveillance & ropts to NRC.
 BLOUGH.A.R. Region 1, Oic of the Director. 89/12/12. 9pp. 47863 054-47803.062. security.plant
- 8612730086 Forwards chart of state & local resources relied upon in plant offsite radio-logical emergency response plan.Related Info.including radiological detense advisory manual & Suffolk County resource manual also enct. CALLK. Long Island Lighting Co. 88/12/17. PODOLAK,E. NRC No Detailed Athil-ation Given. 3pp. 47918:001-47921:102.
- -8812230089 Radiological Defense Advisory Manual RDAM 2-5, "Radiological Intelligence Annex K to Emergency Operations Plan of New York State." New York, State of, 76/08/31, 160pp. 47918:004-47918:165.
- -8812230092 "Suffolk County Emergency Operations Plan."
 * Suffolk County, NY, 86/12/17, 800pp, 47918.166-47920.088.
- --8812230094 "Sulfolk County Resource Manual."
 * Sulfolk County, NY, 88/12/17, 400pp, 47020.089-47921:102.
- 8812280002 LILCO response to Intervenors motion for reconsideration of CLI-88-9.* Motion should be denied on basis of no good reason offered & motion on wrong premise that Intervenors should be permitted to use 2-yr exercise regulation. IRWIN_DP. Long island Lighting Co. IRWIN_DP. Hunton & Williams #488 7717. 88/12/19. Commissioners. 25pp. 47885:001-47885:077.
- -8812280012 Requests factual & logistical Info necessary to enable govts to participate bit 1290012 Hequests lactual & logistical into facebash to analist govis to participate in plant 880607-09 exercise Supporting documentation enci.

 MILLER,M.S. Sutfolk County, NY. MILLER,M.S. New York, State of MILLER,M.S. Southempton, NY. 88/05/31. BACHMANN,R.J. Assistant Ceneral Counsel for Hearings. IRWIN,D.P. Hunton & Williams. CUMMING,W.R. Federal Emergency Management Agency. 24pp. 47885:046-47885:069.

- 8812210294 Final response to FOIA request for records App A records encl & available
- in PDH
 GRIMSLEY,D.H. Division of Freedom of Information & Publications Services (Post 880515) 88712/20. BELAIR,R.R. Kirkpatrick & Lockhart BELAIR,R.R. Sulfolk County,
- --8812210298 "Shoreham-Seabrook Exercise History" * NRC No Detailed Affiliation Given 88/12/20 4pp. 47874 051-47874 056

G. Adjudicatory correspondence

- 8812020017 Mumorandum & order (granting in part & denying in part LILCO request for immediate authorization to operate at 25% power).* Director of NFIR authorized to make findings re LILCO motion & to issue Foenso Served on 881121.
 GLEASON,J.P., KLINE,J.R. Atomic Safety and Licensing Board Panel. #488-7545-88/11/21. Long Island Lighting Co. 12pp. 47643-031-47643-042.
- 8812020024 Order * Donies Intervonors request for disqualification of Judges Gleason & Kine in QL-6 proceeding on basis that no NRC authority supports Intervenors views for disqualification Screed on 601121. GLEASON,JP, KLINE,JR Atomic Safety and Licensing Board Panel #488 7546 88/11/21. New York, State of. 10pp 47643.074-47643 083
- 8812020031 Order.* Postpones conference of counset scheduled for 881122 until 881206 in order to accompdate schedules of members of Board Served on 881121. FRYE,J.H. Atomic Safety and Licensing Board Panel #488 7547. 88/11/21. Office of the General Counsel. 1p. 47643.126.47643.126.
- 8812020032 Expresses disappointment re-postponoment of 881122 prehearing conference until 881202.LILCO motion to dismiss Exercise Contentions 4-20 on basis of ALAB-993 encl.
 IRWIN,D.P. Suffolk County, NY. IRWIN,D.P. Hunton & Williams #498 7556, 88/11/21.
 FRYE,J.H., SIKON,F.J., PARIS,O.H. Atomic Safety and Licensing Board Panel 1p

- ~8812020038 LILCO motion to dismiss Exercise Contentions 4-20 on basis of ALAB-903.* Contentions should be rejected & Interveners should not be permitted to modify contentions to account for ALAB-003 W/Cortificate of Svc. IRWIN,D.P. Long Island Lighting Co. IRWIN,D.P. Hunton & Williams. 88/11/21. Atomic Safety and Liconsing Board Panol. 22pp. 47643.128-47643.149.
- 8812020037 Order* Extends time within which Commission may review Decisions ALAB-900 ALAB-901 & ALAB-902 until 861202 Served on 881121. CHILK,S.J. Office of the Secretary of the Commission. #488 7548. 68/11/21. Commissioners. Ip. 47643 150-47643 50.
- 8812140092 Errata to Board Docision LBP-88-24, changing yr on Page III, Line 8 from 1988 to 1986 Served on 881205 GLEASON, J.P. Atomic Safety and Licensing Board Panel. #488 7611, 88/11/21 1p. 47770:186-47770:186
- 8812020050 Memorandum & crder.* Board 881121 memorandum & order authorizing issuance of 25% power OL cunsidered appealable, per 10CFR2 762 & govis motion socking disqual fication of judges wil be reviewed promptly Served on 881123. HAGINS,E.E. Atomic Selety and Liconsing Appeal Panel #488 7549. 88/11/22. Office of the General Counsol. 4pp. 47643 174-47643.177.
- 8812020046 Govts motion for reversal of Commission order of 881109 * Appeal Board Appear Books and the complete review of Govis pending appeal of LBP-88-24 Certificate of Syc and NoRTON,CL Sulfo's County, NY. NORTON,CL Sulfo's County, NY. NORTON,CL Sulfo's County, Syc and 47843:159-47643:173
- 8812020052 Notice of appearance.* Author enters appearance in proceeding on behalf of Suffolk County Certificate of Svc encl. NIELSON,B.H. Suffolk County, NY. NIELSON,B.H. Kirkpatrick & Lockhart. #488 7559. 86/11/23. 4pp. 47643.178-47643 181.
- 8812020061 LILCO comments on immediate effectiveness of Board 881121 memorandum & order.* Urgos Commission to make 881121 decision offective & authorize issuance of 25% power OL for plant Certhicate of 5xc oncil IRWIN.DP. Long Island Lighting Co. IRWIN.DP. Hunton & Williams. #488 7560. 88/11/23. Commissioners. 9pp. 47643 193-47643 201.
- 8812020083 LILCO motion for certification of Licensing Board 881121 memorandum & ordor & request for expedited disposition.* Requests that Appeal Board certify Commission order authorizing 25% power operation.W/Certificate of Svc IRWIN,D.P. Long Isrand Lighting Co. IRWIN,D.P. Hunton & Wildems. #488 7588. 88/ 11/23. Atomic Safety and Licensing Appeal Panel. 8pp. 47643 233-47643 240.
- 8812020104 Govts motion for page extension.' Requests leave to tild stay motions in excess of 10 pages

 LANPHER,L.C. Suffolk County, NY, LANPHER,L.C. Kirkpatrick & Lockhart.

 ZAHNLEUTER,R.J. New York, State of. #488 7570. 88/11/23. Atomic Safety and Licensing Appeal Panel. 6pp. 47643.268-47644 074.
- -8812020113 Govts motion for stay of 881121 Licensing Board order.* Board should maintain status quo by granting requested stay.

 LANPHER, L.C. Suffolk County, NY LANPHER, L.C. Kirkpatrick & Lockhart.

 ZAHNLEUTER, R.J. New York, State of 88/11/23. Atomic Safety and Licansing Appeal Panel. 15pp. 47643:275-47643:289.
- --8612020121 Affidavit of LC Lenpher.* Affidavit re govts 861123 motion to stay 881121 Licensing Board memorandum & order authorizing NRC to make nacessary Indings on 25% power issues & to issue 25% power icones to util. LANPHER,L C. Kirkpatrick & Lockhart. 08/11/22. 2pp. 47643 280-47643 201.
- -8812020123 Alfidavit of GC Minor in support of motion for stay.* Supports govts motion to stay ASLB 881121 order authorizing Issuance of 25% power OL for plant MINOR,G.C. Sulfolk County, NY MINOR,G.C. New York, State of MINOR,G.C. Southampton, NY. 88/11/22. 6pp. 47643/292-47643/297.

- -8812020130 Affiday to fEJ Greason discolor of planning State of NY energy of c." Provides data on whether supply of electric power to Long Island would be adversely impacted if plant did not operate W/re aled info & Centricate of Svc GLEASON,EJ Swiftisk County, NY GLEASON,EJ Southampton, NY 88/11/03 137pp 47643 295-47644 074
- 8812140050 Forwards sense of legislature utging rejection of LfLCO request to operate Shortham rucked power plant at 25% power approved at 881122 meeting TAIBBLE Suffer County, NY #488 7595 E8/11/25 Afficiation Not Assigned 2pp 47770 081-47770 082
- 8812020120 Memorandum & crider." Replies to govis motion for stay of Soard 881121 order authorizing issuance of 25% power Ot & LILCO motion for certification of Board order should be submitted by 881205 Served on 881128. SHOEMAKERICJ Affords Safety and Licensing Appeal Panel. #488 7577 88/11/28 Office of the General Course: 2pp. 47644 104 47644 105.
- 8812020134 Decision * Affums Board findings in LBP-88-13 re quostons of locally unwanted land use & UtLCO registration procedures & denies portion of Intervenors appear charlenging Board findings w/o obtaining FEMA findings first Served on B81129 SHOEMAKER C.J. Atomic Safety and Licensing Appeal Panel. #488 7579, 88/11/29 42pp 47644 116-47644 157
- 8812140035 NRC Staff response to intervenors motion for page extension. Staff has no objection to extending page that from ten pages to tourteen pages filed by Intervenors Certificate of Sicc end.

 BACHMAN RG. Assistant General Counsel for Hearings. #488, 7593, 88/11/29.

 Atomic Safety and Licensing Appeal Panet, 3pp. 47770,073-47770,075.
- 8812140041 NRC Staff motion for reconsideration of Appeal Board order of 881128 & for enlargement of response time.* Requests extension of time period for NRC to fife responses to both follervenor stay motion & LILCO motion W/Certificate of Svc YOUNG MA. Assistant General Counsel for Hearings. #488 7594.88/11/29. Atomic Safety and Licersing Appeal Pariet. Spp. 47770.076-47770.080.
- 8812140058 Motion for leave to fife amended exercise contentions. Board should accept goods amended contentions Certificate of Sivic encl. MCMURRAY, C.M. Sulfock County, NY MCMURRAY, C.M. Kirkpatrick & Lockhert ZAHNILEUTER R. J. New York, State of #488 7608, 88/11/29. Atomic Safety and Licensing Board Panel. 10pp. 47770.248-47771.021.
- ~8812140068 Amended emergency planning contentions to 880607-09 Shoreham exer-OSE
 MCMURRAY, C.M. Suffork County, NY MCMURRAY, C.M. Krikpatrick & Lockhart ZAHNLEUTER, R.J. New York, State of 88/11/29. Atomic Safety and Licensing Board Panel 124pp 47770 256-47771 021.
- 8812020079 NRC Staff comments on immediate effectiveness of ASLB 891121 memorandum & order.* Recommends that Commission initially decide ments of LBP-86 24 Certificate of Svc encl YOUNG,M.A. Assistant General Coursel for Hearings. #488,7582, 88/11/30, Commissioners 7pp 47643 218-47643 224.
- 8812020168 Advises that govts do not object to ASLAB granting NRC motion for reconsideration of ASLAB 881128 order & enlargement of response time on caveal that if govts stay motion needs to be acted on decision will be made w/o NRC. LANPHERILC Suffolk County, NY. LANPHERILC New York, State of LANPHERILC Southerplon, NY. #488 7584 89/11/20 KOHLC N, ROSENTHALLAS, WILBERIHA Alomic Safety and Licensing Appeal Panel 1p. 47644 337-47644 337
- 8612140080 Memorandum & order.* Commission grants staff motion only in part Staff responses to both govt & LILCO motions requested by 881207 Repries of other parties remain due as specified in 881128 memorandum & order. Sorved on 881201 SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panol. #488 7597, 88/11/30. Office of the General Counsel. 4pp. 47770.233-47770.236
- 8812140087 Order CLI-88-09.* Commission believes prudent to establish procedures & go forward wi/any necessary proceedings on 1988 express Parties encouraged to negiciate to reduce actual number of issues to be highered Served on 881/201. CHILLES J. Office of the Sectiating of the Commission. #488-7598-88/12/01. Office of the General Counsel. 7pp. 47770-201-47770-207.
- 8812140070 Answers to Intervenors brief on school bus driver role conflict & emergency broadcast sys * ASLAB should affirm ASLB decision on emergency broadcast sys & school bus driver rote conflict Issues Certificate of Size encil.

 CHRISTMANJ.N. Long Isrand Ughting Co. CHRISTMANJ.N. Hunton & Williams #488 7618 68/12/01. Atomic Safety and Licensing Appeal Panel. \$7pp. 47769.322-47270.118
- 8812140071 Comments of Suffolk County, State of NY & town of Southampton concerning immediate effectiveness of 881121 Licensing Board order.* Commission should stay effectiveness of 881121 order W/Certificate of Svc. LETSCHE.K.J. Suffolk County, NY LETSCHE.K.J. Kirkpatrick & Lockhert PALOMIANGE G. New York, State of #488 7596 88/12/01. Commissioners. 11pp 47770:019-47770.039.
- 8812140113 Advises that 881121 order should be stayed pending full appolate raview of merits in light of ALAB-905 & for other reasons sell forth in govts stay motion. LETSCHE,K J. Kirkpatrick & Lockhart #468 7601. 88712701. KOHL,C.N., ROSENTHALAS, JÖHNSON,W.R. Atomic Safety and Licensing Appeal Panal. 2pp. 47769 225-47769 226
- 8612140115 LILCO birel in opposition to intervenors appeal from Licensing Board con-cluding initial decision (sanctions/ realism issues). *Commission should affirm Licens-ing Board decision Certificate of Svc & Vols 1 & II of app enct. IRWIND P. Long Island Lighting Co. IRWIND P. Hunton & Williams. #468 7614, 667 12/01. Commissioners. 1,258pp. 47766 047-47769.224
- 8812140121 LILCO reply to intervenors motion for reversal of Commission 881109 order 1 intervenors motion should be defield. Certificate of Syc encl. IRWIND.P. Long 154and Uphing Co. IRWIND.P. Hunton & Widiams. #468 7802.

- 8812140139 Govis opposition to LICCO motion to dismiss Exercise Contentions 4-K y basis of ALAB 903 * LICCO motion should be doned Conflicate of Svc encl MCMURRAY,C M. Solfolk County. NY MCMURRAY,C M. Kirkpainsk & Locket ZAHMEUTERRIJ I New York, State of #480 7615 //18/12/01. Atomic Salety avg. censing Board Panel. 31pp. 47771.022-47771.053
- 8812140032 Order * Period in which Commission may review ALAB 900 ALAB 5: 1 ALAB-802 extended until 881222 Served on 881202 CHILK,S.J. Office of the Secretary of the Commission, #488, 7605, 88/12/02 1: 47770 241 47770 241
- 8812140054 Forwards corrected cover page to LICCO answer to interveners beet of school bus driver role conluct & emergency broadcast sys, tital 881201 LEUGERS.M.J. Hunton & Williams. #488.7623. 88/12/02. NRC No Deta ed &**, alton G ven. tp. 47769.274.47769.275
- -8812140064 Corrected cover page to LILCO answer to intervenor hind on school 55 driver rete conflict & emergency broadcast sys (EBS).

 * Long Island Lighting Co. * Hunton & Wilhams 88/12/01 Atomic Safety and Liversing Board Panel. 1p. 47769.275-47769.275
- 8812080004 Ack 881122 fir to plant licensing producting Commission discussion dis-Conselect Action of recipient admissing producting Commission discussion (its conselection not appropriate MALSCH,MIG. Deputy General Counsel 88/12/05 HOCHBRUECKNER House of Rep. 19. 47754.145-47754.147
- -8812080005 Requests that Commission take steps to consider disqual fication of the Greason from further involvement in any proceedings to licensing of facility Series. HOCHBRUECKNER House of Rep. 88/11/22 ZECHA W. Commissioners 250
- 47754 146-47754-147
- 8612140073 Govis response to LILCO motion for conflication of 861121 order to Commission * LILCO motion for certification should be denied Certificate of Swelenc' LETSCHE K.J. Suffolk County, NY LETSCHE K.J. Krikipatrick & Lockber PALOMINO,F.G. Now York, Statio of #488-7616-88/12/05 Alomic Safety and Liconsing Appeal Panet 8pp. 47770 178-47770 185.
- 8812140089 Memorandum & order * Order of Glusson & Klino,dtd 881121, decising a rescue themselves from further participation in procouding affirmed Served or
- TOMPRINS B.A. Alonic Safety and Licensing Appeal Panel #488 7610, 88/12/5 Suffelix County, NY 10pp 47770 191-47770:200
- 8812140099 Forwards corrected Page 2 of CLI-86-9.Date changed to 870310 fra 870513 Served on 881205 JULIAN EL Docketting & Services Brench #488 7612 88712705 Atomic Safety ac Licensing Board Panel 2pp 47770 187-47770 188
- 8812190103 LILCO response to Intervences motion for stay of 881121 Board order* Motion should be donad Roteled into encl IRWINDP Long Island England Co. IRWINDP Hunton & Williams #488 7831 68/ 12/05 Atomic Safety and Liconsing Appeal Panul 20pp 47801.172-47801 202
- -8812190117 Affidavit of AM Madsen in support of LLCO rusponse to Intervetor motion for stay of 981121 Board order * W/ Combicate of Svc. MADSEN.A.M. Long Island Eighting Co. 88/12/05 11pp 47001.192-47891.202
- 8812190112 Correction.* Forwards Page 29 to LiLCO answer to Intervenors birefice school bus driver role conflict & emergency broadcast sysuifid 881201 Certificate of
 - TEUGERS.M.J. Long Island Lighting Co. LEUGERS.M.J. Hunton & Williams #482 7657. 88/12/05. KOHL, C.N., ROSENTHAL, A.S., WILLBURLH & Atomic Safety and U-censing Appeal Panel. 4pp. 47802 184-47802 187
- 8812190143 NRC Staff responses to LILCO metion to demiss Exercise Contention 4-20 on basis of ALAB-903* Board should reject interveners contentions as latelfied Certificate of Svc and CLARKL B. Assistant General Counsel for Hearings. #488-7643, 88/12/06. Atomic Safety and Licensing Roard Panel. 18pp. 47801;105-47801.122
- 8812190008 NRC Staff response to intervener motion for stay of 881121 order." Inferveners show no good Issue for stay of decision involving 25% full power license & motion should be denicid. W/Certificate of Svc. REIS.E. J. Assistant General Courset for Hearings. #498-7646-88/12/07 Atoms Safety and Licensing Appeal Panel. 14pp. 47801-320-47801-333
- 8812198013 NRC Staff response to LILCO motion for certification of 881121 Board order * Motion should be granted W/Certificatio of Svc YOUNG, MA Assistant Gonzeal Councel for Naturings #488 7847 88/12/07 Atches Safety and Licensing Appeal Panel 7pp. 47802.042-47802.048
- 8812190178 Advises that due to LILCO OL application for plant being sub) of pending formal adjudication, discussion by NRC adjudicatory personnel deemed inappropriate per recipient 881130 ftr. Served on 881209 MALSCH, M.G. Deputy General Counsel for Licensing & Regulation #488 7634 65/12/07. TODOROVICH, M.M. Scientists & Engineers for Socure Energy. 10, 47601 082 47601 082 47801.09R
- -8812190182 Forwards itre expressing concern re-costly consequences of not licensing plant Commission requisited to grant full power Leenso TODOROVICH.M.M. Scientists & Engineers for Secure Energy, 88/11/30, ZECH,L.W. Commissioners, 13pp. 47801:084-47801:096.
- 8812190016 NRC Staff response to govts mollon for reversal of Commission order cf 881103.* Hotion should be denied W. Certificate of Svc. BERRY.GA Assistant General Counsel for Hearings. #488 7649. 88/12/08. Commissioners
- 8812190220 Forwards sense of legislature resolution demanding NRC to stop consideration of OL for plant & to evaluate salety & financial implications of LfLCO Racketer Influenced & Corrupt Organizations Act fieldity, Served on 881214. TAIBBLE, Soffolk County, NY #488 7674, 88/12/08, Alhikation Not Assigned 4pp 47801.001-47801.004.

- 881219069 Memorandum & order * Grants LILCO 881123 motion & certifies to Com-mission LBP-88-30 re issuance of 25% power license, govts 881123 appeals from LBP-88-30 & govts motion for stay of LBP-88-30 Served on 881209. TOMPKINS,B A Atomic Safety and Licensing Appeal Panel. #488 7653 88/12/09 Long Island Lighting Co. 16pp 47802 067-47802 082
- 8812190168 Govts motion for reconsideration of CLI-88-9 * Commission allockly rescind CLI-88-9 & grant ASLB authority to substitute schedule & procedures which take govts due process rights into account MCMURRAY,CM Suffo'k County, NY. MCMURRAY,CM Kirkpatrick & Lockharl ZAHNLEUTERRJ, New York, State of #488-7667-88/12/09. Commissioners 35pp

47801 035-47801:082

- -8812190172 Affidavit of CM McMurray * Discusses issuance of CLI-88-9 & 880607-09 exercise of LILCO emergency plan for plant MCMURRAY,C M. Suffolk County, NY, MCMURRAY,C M. Kirkpatrick & Lockhart 88/12709, 6pp. 47801-070-47801-075
- -8812190179 Affidavit of RJ Zahnfontor* Supports govts motion for reconsideration of CLI-88-9 Certificate of Svc encl ZAHNLEUTER, R.J. Massachusotts, Commonwealth of 88/12/09 7pp. 47801 076-47801082
- 8812190024 NRC Staff response in opposition to Intervenors appeal of sanctions imposed in LBP-88-24.* W/Contribicate of Svc. YOUNG,M.A. Assistant General Counsel for Hearings. #488-7675-88/12/12. Commissioners, 68pp. 47801:334-47802-041
- 8612270090 NRC Stall response in opposition to Intervenors appeal of 880923 concluding initial decision." LBP-88-24 should be atturned on emergency broadcast sys & school bus driver rote conflict issues Certificate of Svc and BACHMANN,R.G., BARTH.C.A. Assistant General Counsel for Huannys #488 7685. 88/12/12. Atomic Safety and Licensing Appeal Partet 33pp 47872-233-47972-265.
- 8812270033 Govts motion for ruling for reversal & for hearing & opportunity to respond to LILCO & NRC briefs to Commission, on Issue Identified in Commission 081109 order.' Reversal motion should be granted Certificate of Svc encl. LETSCHE.K.J. Suffolk County, NY LETSCHE.K.J. Kirkpatrick & Lockhart PALOMINO,F.G. New York, State of. #488 7679 88/12/14. Commissioners 10pp. 47873 093-47873 102.
- 8812270049 Polition for review of ALAB-905 * Commission should reverse ALAB-905 & B12270049 Polition for roving of ALAB-905* Commission should roverse ALAB-905 to Hold that LILCO has more than mot NRC requirements based on 20% nati policy guidance from FEMA.W/ Contificate of Svc.
 CHRISTMAN.J.N. Long Island Lighting Co. CHRISTMAN.J.N. Hunton & Williams. #488.7692. 86/12/14. Commissionars 13pp. 47873.067-47873.079.
- 8812270052 Govts motion for oral argument on issue identified in 881109 order.* Govts request that Commission reschedule oral argument on issues identified in order profit oracting any decision on issues-Certificate of Svc end LETSCHE,K.J. Suffolk County, NY. LETSCHE,K.J. Kirkpatrick & Lockhart PALOMNO,F.G. New York, State of #488 7680 00/12/14. Commissioners 7pp 47873:060-47873:066.
- A812270088 Govts motion for brioling schodule on matters certified in ALAB-908.* Govts propose that Commission establish brighting along lines of Issted schodule & request that Commission act expeditiously on motion.Certificate of Svc and: LETSCHE,K.J. Surfolk County, NY, LETSCHE,K.J. Kirkpatrick & Lockhart. PALOMINO,F.G. New York, State of. #488-7681-88/12/14. Commissioners. 8pp. 47823-318-47823-318-4782 47872 319-47872 326
- 8812270094 Order.* Parties should provide to Board by Itr mailed no later than 890110,name of Individual presenting argument on 890125 Served on 881215. TOMPKINS,B A. Atomic Safety and Licensing Appeal Panel. #488 7087. 88/12/14. Office of the General Council. 2pp. 47872.218-47872.219.
- 8812280084 Advises that FEMA evaluation forms, including forms prepared by NRC employabs, should be disclosed to all parties in proceeding Related correspondence. REIS,EJ. Office of the General Counset. #488 7747, 86/12/14. CUMMING,W.R. Federal Emergency Management Agency. 1p. 47884:333-47884:333
- 8812270014 Mollon for leave to file govte reply brief in support of appeal of emergency broadcast sys & role conflict of school bus drivure issues of 880923 concluding initial decision. Brief should be accepted on basis of good cause.

 TAYLOR,J.L. Suffolk County, NY, TAYLOR,J.L. Kirkpatrick & Lockhart. ZAHNLEUTER,R.J. New York, Statio of, #488.7701, 88/12/15, Atomic Safety and Licenses and the second systems.

censing Appeal Panel. 4pp. 47873.132-47873.170.

-8812270024 Govts reply brief in support of appeal of emurgency broaticast sys & roto conflict of school bus driver issues of 880923 concluding initial decision. W/Certificate of Svc.
TAYLOR, J.L. Suffolk County, NY. TAYLOR, J.L. Kirkpatrick & Lockhart ZAHNLEUTER, R.H. Now York, State of .86/12/15 Atomic Safety and Licensing Appeal Panel. 34pp. 47873:136-47873-170.

- 8812270069 LILCO pre'iminary responses to interveriers 881214 motions.* Interveners motion for briefling schedule on matters certified in ALAB-908 should be dealed W/
 - Certificate of Svc.
 IRWIN,D.P. Long Island Lighting Co. IRWIN,D.P. Hunton & Writems #488 7694. 88/12/15 Commissioners. 8pp. 47872:313-47872:318.
- 8612280088 Certificate of Syc.* Cortiflos syc of motion for leave to file govts reply bitef in support of appeal of emergency broadcast sys & role conflict of school bus driver issues of 880923 concluding initial decision on 881215
 MILLER,M.S. Suffolk County, NY. MILLER,M.S. New York, State of MILLER,M.S. Southampton, NY. #488 7720. 88/12/16. 3pp. 47884:344:47884:346.
- 8812280002 LILCO response to Intervenors motion for reconsideration of CLI-88.9.* Motion should be deried on basis of no good reason offered & motion on wrong premise that Intervenors should be permitted to use 2-yr exercise regulation. IRWIN.D.P. Long Island Lighting Co. IRWIN.D.P Hunton & Williams. #488 7717. 88/12/19. Commissioners. 25pp. 47885-001-47885-077.
- --8612280003 Alfidavit of DM Crocker in support of LILCO response to Interveners motion for reconsideration of CLI-88-9.* CROCKER,D.M. Long Island Lighting Co. 88/12/19, 4pp. 47895-026-47885:029.

- --8812280005 Affidavit of DP Irwin in support of LILCO response to Intervenors motion for reconsideration of CLI-88-9.*
 IRWIN.D.P. Long Island Lighting Co. IRWIN,D.P. Hunton & Williams 88/12/19. 4pp 47885 030-47885 033
- -8812280006 Affidavit of JA Monaghan in support of LILCO response to Intervenoral motion for reconsideration of CLI-88-9 * MONAGHAN, JA Long Island Lighting Co. MONAGHAN, JA Hunton & Williams. 88/ 12/19. 4pp 47885-034-47885-037.
- --8812280007 Affidavit of SD Metchett in support of LILCO response to Intervenors motion for reconsideration of CLI-88-9 * MATCHETT,SD Long Island Lighting Co MAATCHETT,SD Hunton & Williams. 88/12/19 4pp 47805-038-47805-041.
- -8812280008 Affidawt of DS Harlow in support of LILCO rasponso to Intervenors motion for reconsideration of CLI-88 9.* HARLOW,D S Long Island Lighting Co HARLOW,D S Hunter & Williams 88/12/19, 4pp 47865-042-47865-045.
- --8812280012 Requests factual & log stical into necessary to enable govis to participate in plant 880607-09 exercise. Supporting documentation and.
 MILLER,M.S. Suffork County, NY. MILLER,M.S. Now York, State of MILLER,M.S. Southampton, NY. 88/05/31. BACHMANN,R.J. Assistant General Counsel for Hearings. IRWIN,D.P. Hunton & Williams. CUMMING,W.R. Federal Emergency Management Agency. 24pp. 47885-046-47885-069.
- --8812280021 Advises that NRC has arranged for state or county representative to be present in emergency operation facility for two observers to be at staying area & re-ciplent to receive controller messages per request REIS,E.J. Office of the General Counsel 88/06/00. BROWN,H.H. Suffelk County, NY BROWN,H.H. Kirkpatrick & Lockhart 1p. 47885-070-47885.070.
- -8812280026 Requests that recipient sand atty, for Suffolk County, NY, FEMA controller mossages 8.7or free play mossages used in recent plant exercise REIS, E.J. Office of the General Counsel. 88/06/17. CUMMING, W.R. Federal Emergency Management Agency 1p. 47885.071-4785-071.
- -8812280028 Advises that NRC will ask FEMA counsel to send recipient controllor messages used during plant exercise, per request
 REIS,E.J. Office of the General Coursel 88/06/17 BROWN,H.H. Suffelk County, NY.
 BROWN,H.H. Kirkpatrick & Lockhart 1p 47885.072-47885:072
- -8812280033 Requests that NRC arrange to have all of FEMA controllar massages &/ or free play messages sent to author, promptly W/ Certificate of Svc BROWN,H.H. Suffolk County, NY. BROWN,H.H. Kirkpatrick & Lockhart 88/08/15. REIS. J. Othice of the General Counset. Spp. 47885-073-47885-077.
- 8812280070 LILCO supplemental response to Intervenor 881214 mollons * LILCO urgos that stay of ALAB-908 not be granted-schedule not be extended & ASLAB advisory const of 10CFR50.57(c) be reversed & LBP-89-30 left in effect Certificate of Svc encl. IRWIN.D P. Long Island Lighting Co. IRWIN,D P. Hunton & Williams #488 7740. 88/12/20. Commissioners 12pp 47886.150-47886 161
- 8812280075 NRC Staff response to Intervenors motion for briefing schedule on matters certified in ALAB 908.1 Intervenors have not shown good cause to extend briefing schedule & motion should be denied W/Certificate of Svc BACHMANN,R.C. Assistant General Courset for Hearings #488 7719 88/12/20. Commissioners. 8pp 47884:338-47884.343.
- 8812280078 Floquests that encl corrected Page 6 to LILCO 881220 supplemental response to Intervenors 881214 motions be inserted into document Cartificate of Svo encl HARLOW,D.S. Long Island Lighting Co. HARLOW,D.S. Hunton & Williams. #488 7741. BB/12/21. ZECH,L.W., ROBERTS,T.M., CARR,K.M. Commissioners 5pp 47886:162-47886.166.
- 8812280190 Order CLI-88-11.* Dan es poblion for review of ALAB-900 & ALAB-901. Applicant may conduct remedial exercise sufficient in scope to address deficiency in original scope of exercise Served on 881121.

 HÖYLE, J.C. Office of the Secretary of the Commission #488 7733 88/12/21. Office of the General Counsel. 3pp. 47886 092-47886 094
- 8912280129 NRC Staff response to Interveners motion for oral argument on issue identified in 891109 order.* NRC does not object to oral argument if Commission determines that argument will assist in consideration of issues W/Cert*cate of Svc. YOUNG, M.A. Assistant General Counsel for Hearings #488 7745, 68/12/22, Commissioners, 7pp. 47884:309-47884:315

H. General correspondence

8812070103 Informs that RM Kascaack appointed to position of acting manager of nuclear engineering dept.effective on 881101. LEONARD,J.D. Long Island Lighting Co. 88/12/05 Document Control Branch (Document Control Dest). 2pp. 47746.090-47748.091.

- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8812080089 Forwards Rov 2 to updated FSAR for Shoreham Nuclear Power Station Unit 1 & Rev 4 to Fire Hazard Analysis Rept for 870808 880607.per 10CFR50.59. LEONARD.J.D. Long Island Lighting Co. 88/12/05 Document Control Branch (Occument Control Desh.) 2pp. 47751.078-47752.157.
- --8812080091 "Rev 4 to Fire Hozard Analysis Rept" *Long Island Lighting Co. 88/08/07, 9pp. 47751:089-47761:089
- --8812080094 "Rev 2 to Updated Safety Analysis Rept."
 * Long Island Lighting Co. 88/12/31, 428pp. 47751:090-47752:157.

P. Operating license stage documents & correspondence

- 8812050109 FC1A inquest for records to 681109 decision to certify to Commission appeal of CL 3 decision to distuis gords in Leansing proceeding. BELLAR RR R in practice & Lockhard BELLAR R Surful County, NY 68711717 INRC No Octated Afficiation County 200 47729 085-47729 086.
- 8812150259 Forwards: Ucersa Readiness Assessment:" Rept confirms that util prepared for above 5% thermal power During 881017 ingt meeting/icensee informed NRC that each functional area would be self-assessed LECHARO JO Long Stand Lighting Co. 88/11/18 RUSSELL W.T. Region 1, Ofc of the Director 2pp 47817-001-47818-212
- --8812150260 | Littensee Readnass Astessment."
 * Long Island Lighting Co. 68/11/30, 500pp, 47817,003,47818:212
- 8811280048 Gerand Ltr. 98.20 to at Licensees holding Ots & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnorabilities Svo list end.
- CRUTCHFIELD D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729-024.
- **8812060335** Forwards Amend 9 to License NFF-36 & safety evaluation Amend revises Attachment 3 to plant ocensalise maint & surveillance for TDI emergency diesel generators.
- BUTLER,WIR Project Errectorate 1/2 69/11/30 LECNARD, J.D. Long Island Lighting Co 6pp. 47744 341-47744 358
- -8812060338 Amend 9 to License NPF-36,revising Attachment 3 to plant ficense remaint 8 surver lance program for TDI diesel generations ButfletR WR Project Directorials 12: 881/1739 Spp. 47744-347-47744-355.
- -8812060340 Safety evaluation supporting Amend 9 to License NPF-36 10 Ninco of Nuclear Reactor Regulation, Director (Post 870411) 88/11/30 3pp 47744 355-47744 356
- 8812120037 Forwards Amend 10 to License NPF-95 & sefety evaluation Amend changes definition of core afteration in Toch Specs to include certain exceptions & changes footnotes in Tech Specs to be consistent withew definition. BUTLER, W.R. Project Directorate 1-2 88/11/30, LEONARD, J.D. Long Island Lighting Co. 5pp. 47760-174-47780-197.
- -8812120040 Amend 10 to License NPF.36,changing definition of core alteration in Tech Specs to include certain exceptions & foolinates in Tech Specs to be consistent when definition.
- BUTLER,W.R. Project Directorale I-2, 88/11/30, 15pp, 47780,179-47780, 193
- -8812120043 Salety evaluation supporting Amend 10 to Liconso NPF-36 Office of Nuclear Reactor Pegulation, Director (Post 870411) 88/11/30, 4pp 47783.194.47760.197.
- 8812050113 Final response to FOIA request to agency records subj to request located licersing. Board decision not certified to Commission Commission chose, through exercise of discretionary authority to take junisd-ction avair senctions. GRIMSLEY, D.H. Division of Freedom of Information & Publications Services (Post 880515). 88/12/01. BELAIR, Richards & Lockhart BELAIR, R. Sutto'k County, NY. 19, 47729.067-47729.087
- 8812140059 Forwards changes to initial test program described in Chapter 14 of updated SAR Changes include deletions/fevs of startup test procedures & station procedure LEONARD.J.D. Long Island Lighting Co. 58/12/09. Document Control Branch (Document Control Desk). 13pp. 47796.094-47796.106
- 8812200290 Ack receipt of 881118 to requesting exemption from FY89 fee requirements per 10CFR171 Review of request will be completed as soon as possible WOLLOWAY, C.J. License Fise Management Branch 88/12/14, LEONARD, J.D. Long Island Lighting Co. 1p. 47906.294-47906.296
- -8812200294 Requests extension of exemption from payment of annual fee under 10CFR171 for part of FY89 that plant restricted to no more than 5% rated thermal power.

 LEONAROUD Long Island Lighting Co. 88/11/16. STELLO.V. Ofc of the Executive Director for Operations. 2pp. 47906.295-47906.296.

Q. Inspection reports, IE Bulletins & correspondence

- 8811210080 Rev O to "Shoreham Nuclear Power Station PRA Based Sys Insp Plans." FRESCO.A. H:GGINS.J. GUNTHER.W Brookhaven National Laboratory FIN A:3453 A:3453:3-87(-3) R00 82703731 Region 1, Old of the Director 76pp 47599
- 8812090157 Requests 30 day extension to complete response to NRC Compliance Bulletin 87-002 is fastener testing to determine conformance w/applicable matt spec requirements
 LEONARDJO Long Island Lighting Co. 88/01/15 RUSSELLW. Region 1, Otc of the
 Director. 1p 47782 306-47782 306
- 8804210209 Forwards response to Items 1-6 of NRC Compliance Builetin 67-002 re fastener resting to determine conformance w/ applicable matil specs, including data sheets & results of mechanical & chemical testing LEONARD, JD. Long Island Liphiling Co. 88/02/18. RUSSELL,W. Region 1, Otc of the Director. 59pp. 45194-177-45194-235
- 8812140188 Responds to NRC Bulletin 88-001, "Detects in Westinghouse Circuit Breakers." Westinghouse Breakers DS-206,DSL-206, DS-416,DSL-416 & DS-420 not utikzed at plant/per review of plant by listed spacs. LEONARD J. D. Long Island Ughting Co. 88/04/06. RUSSELL,W.T. Region 1, Otc of the Director. 3pp. 47800:161-47800 163.
- 8811180211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svo list enci.
 CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729).
 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708:257.

- 8811150467 NRC Into Notice 88:091, "Impreptir Administration & Control of cal Tests." Size tist enct. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.
- 8811290007 Forwards Radiological Safety Insp. Rupt 50-322/88-09 on 88 violations noted BELLAMY, R.R. Region 1, Ofc. of the Director 88/11/23 LEONARO, J.C. Lighlag Co. Spp. 47640-204-47649-222
- -8811290011 Insp Rept 50:322/8H-09 on 861017-21 No violations nated inspected radiation protection program areas including previously items organization & stating training & qualification of personnel & ALARA MARKEY, M. DRAGOUN, T., SHANBAKY, M. Region 1, Ofc of the Director 14pp, 47649-209-47649-222
- 8811290030 NRC Into Notice 88 093, "Teletherapy Events" Svc Est enci CUNNINGHAM,R E. Division of Industrial & Modical Nuclear Safety (Pot 88/12/02, Consolidated Edison Co. of New York, Inc., 112pp, 47811-103-
- 8811290538 NRC Info Notice 88-094, "Polontially Undersized Valvo Actuator end. ROSSIC E. Division of Operational Events Assessinant (Post 870411), Consol dated Edison Co. of New York, Inc. 121pp 47708 143-47708 254
- 8812020287 NRC Info Notice 86:095, "Inadequate Procurement Requiremently Licensees on Vendors". Svc list end. ROSSICE Dx-sten of Operational Events Assessment (Post 870411). Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302
- 8812200110 Forwards Safety thep Rept 50:322/88:08 on 880016-1118 Nonoted MIGDINS, JT Region 1, Ofc of the Director, 88/12/12 LEONARD, JD. Lighting Co. 4pp 47863 050-47863 062
- -8812200114 http://doi.org/10.000114 http://do
- 8812230015 Informs that review of Loresco roudiness assessment to thereby, of high quality & adequately reflects reathness for power operative percent thermal power Concerned w/stelling vacancies in several areas WIGGIN, J.T. Ragion 1, Offic of the Director 88/12/15 LEONARD, J.D. Lighting Co. 4pp 47811:086-47911:080

S. Reportable occurrences, LERs & related correspondence

- 8811300012 LER 88-017-00.on 891025,eoismic monitoring instrumentation for greater than 30 days w/o issuance of spucial rept Caused by personn procedural deficiency. Survoisiance engineer has been roassigned W788112 GRWNSEICH,R.W. STEIGER,W.E. Long Island Lighting Co. 88/1147688 298-47668 302
- 8812060046 LER 88:018 00 on 881101,RWCU isolation occurred Caused by job briefing between watch angineer 8 operating crow Operators actions d performance of Feston tab installations will be procedurated W7881130 ling GNUNSECHARW. STEIGER,R.W. Long Island Lighting Co. 88/114743.023-47743.027.
- 8812080335 Forwards Amend 9 to License NPF-36 & safety evaluation Am Attachment 3 to plant license re-maint & surveillance for TOI emorgency erators. BUTLERW.R. Project Directorate I-2, 88/11/30 LEONARD,J.D. Long Isla Co. 8pp. 47744,341-47744:358.
- -8812069338 Amend 9 to License NPF-36,revising Attactment 3 to plant maint 8 surveillance program for TDI diesel generators. BUTLER,W.R. Project Directorate I-2, 88711730, 9pp. 47744;347-47744;359
- -8812060340 Safety evaluation supporting Amend 9 to License NPF-36.

 **Office of Nuclear Reactor Regulation, Director (Post 870411), 68/147744:358-47744:358.
- 8812090054 LER 88-019-00 on 881108 reactor building closed loop cooling on to to head tenk level during placement of HX Into evo due to hiting problem Procedure identifying deficiencies performed W/081205 ftr. GRUNSEICH.R.W., STEIGER.W.E. Long Island Lighting Co 88/1247782:308-47782:314.

T. Hearing transcripts on non-antitrust matters

8812120252 Transcript of 881206 hearing In Bethesda,MD re plant. Pp. 1-122
* Atomic Safety and Licensing Board Panel 88/12/06, 123pp. 47786.082

U. Congressional/Executive Correspondence

- 8811300078 Forwards NRC quarterly status rept covering Third Quarter C sponse to direction given in House Rept 97-850. ZECHLW. Commissionars. 88/11/10. BEVILL,T. House of Rep., Apr. 12pp. 47733 001-47733.012.
- 8811300081 Forwards quarterly watus rept on emergency preparedness power plants for Jul-Sept 1988 Inability of Commission to forecast licensific Shoreham & Seabrook noted.

 ZECH,L.W. Commissioners. 88/11/10. BREAUX,J B. Senate, Environme Works 5pp. 47764:227-47754;231.

F. Security, medical, emergency & fire protection plans

- 8811300077 Roy 6 to "San Luis Obispo County/Cities Nuclear Power Plant Emergency Response Plan " W/881122 ltr. SHIFFER,J.D. Pacific Gas & Electric Co. 88/10/31, 348pp. 476/1;317-47672 302
- 8812130244 Forwards Insp Repts 50-275/88-28 & 50-323/88-24 on 880804-1022 No violations noted Discusses events. KIASCH,D.F. Region 5, Ofc of the Director 88/11/23 SHIFFER,J.D. Pacific Gas & Electric Co. 3pp. 47788 107-47798 128
- --8812130245 Insp. Repts 50:275/88-26 & 50:323/88-26 on 880904-1022 No violations or deviations noted Major areas inspected plant operations,maint & surveirlance activities,onsite events, open items,LERs & selected independent insp activities. WAGNERW., MENDONCA,M.M. Region 5, Otc. of the Director. 88/11/22 16pp 47798:110-47798.128.
- 812090334 Revised corporate emergency response plan implementing procedures including Rev 4 to 1.2, "Activation of Corporate Includent Respose Cir" & Rev 5 to 48, "Computer & Telecommunications Svcs" W/8812061r; SHIFFER.J.D. Pacific Gas & Electric Co 88/12/08 7pp 47/61/170-47761 176. 8812090334

G. Adjudicatory correspondence

- 8812190078 Establishment of ASLB * Board comprised of PB Bloch,charman & GA Limenberger & J Harbour,members Served on 881209. LAZO,R-M Atomic Safety and Licensing Board Panel #488 7654 88/12/07 2pp 47801,209-47801,210.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8812050183 Forwards proposed change to Chapter 17 of updated FSAR for Diable Canyon Units 1 & 2,for review & approvel SHIFFER J.D Pacific Gas & Electric Co. 86/11/29, Document Control Branch (Document Control Desk), 5pp 47733:285-47733:289
- P. Operating license stage documents & correspondence
- 8812210107 FOIA request for all closed sessions &/or meetings of Commissioners held between Jan 1980 & Dec 1086 re plant SCHMEGE, P.A. O'Molveny & Myors 88/04/06 NRC No Detailed Attitution Given 2pp. 47874,057-47874358.
- 8811230225 Forwards notice of issuance of withdrawal of applications for amends to Licenses DPR-80 & DPR-82. ROODJH Project Directorate V. 88/10/31 SHIFFER,J.D. Pacific Gas & Electric Co 4pp. 47822:275-47822:280.
- --8811230227 Notice of withdrawal of 971030 & 0924 applications for amonds to Licenses DPR-80 & DPR-82.
 ROOD,H. Project Directorate V 88/10/31, 2pp 47622 278-47622 280
- 8811280048 Generic Ltr 88-20 to all Leensovs holding OLs & CPs for nuclear power reactor facilities re individual plant exem for sovere accident vulnerabilihes Svc list
- CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728-303-47729-024.
- 881205006\$ Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Resctor Vassel Matils & Impact On Plant Operations." SHIFFER, JD. Pactic Gas & Electric Co. 88/11/28. Document Control Branch (Document Control Desk). 1p. 47733:294-47733:294.
- 8812080117 Forwards diagrams re high pressure injection sys erroneously emitted from 881028 lit re long-term seismic program & PRA documentation for LPIS Auxiliery salt-water sys documentation will be submitted by 881209,
- 8812070167 Forwards application for amonds to Licenses DPR-80 & DPR-82, consisting of License Amond Request 88-08, authorizing use of 17X17 VANTAGE 5 fuel assembles to the Amond Region of the Amond Region o
 - biles at plant. Fee paid.

 SHIFFER, J.D., Pacific Gas & Electric Co. 88/11/29, Document Control Branch (Document Control Desk). 2pp. 47738:180-47739:331.
- -8812070188 Application for amends to Licenses OPR-80 & DPR-82, consisting of License Amend Request 88-08, changing Tech Spocs to reflect use of 17X17 VANTAGE 5 fuel assemblies.
- SHIFFER,J.D. Pacific Gas & Electric Co 88/11/29 42pp. 47738:182-47738:233
- -8812070189 Proposed Tech Specs, reliecting use at 17X17 VANTAGE 5 fuel assem-
- Pacific Gas & Electric Co. 88/11/29, 458pp. 47738:234-47739.331.
- 8812220348 Requests that licensee address concerns in Generic Lir 88-17 re loss of DHR during nonpower operation.NRC considers issue to be of high priority as result of 870410 Incident. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 05. CLARKE,R.A. Pacific Ges & Electric Co. 6pp. 47892:244-47892 249.
- \$612090313 Forwards list of completed second refueling outage activities SHIFFER, J.D. Pacific Gas & Electric Co. 88/12/06. Document Control Branch (Document Control Desk). 3pp. 47762:070-47762-072.
- 8812160268 Forwards proprietary WCAP-11594 & nonproprietary WCAP-11595 "Westinghouse Improved Thermal Design Procedure Instrument Uncertaintly Celculations for Diablo Caryon Units 1 & 2" & application for withholding proprietary into. SHIFFER_J.D. Pacific Gas & Electric Co. 88/12/09. Document Control Branch (Document Control Desk). 3pp. 47816:297-47816:354.

- proved Thormal Design Procedure Instrument Uncertainty Calminions for Eable Canyon Units 1.8.2. WIESEMANN R A Wostinghouse Electric Corp. 88/11/17. Office of Nuclear Reactor Regulation, Director (Post 870411): 10pp. 47816:300-47816.309
- -8812150270 "Westinghouse Improved Thermal Design Procedure Instrument Uncerlainity Calculations for Dubb Cangor Units 1.8.2."

 TULEY, C.R. Westinghouse Electric Corp. WCAP-11595. 87/00/30, 44pp. 47816.310-47816 354
- 8812160011 Responds to NRC 881031 request for this re Generic Ltr 83:28, Item 4.3, "Reactor Trip Sys Reliability." Surveillance Tost Procedure STP I-18C moets Tech Spec requirement to venify undervollage ting 8 should tip every 18 months SHIFFER.J.D. Pacific Gas 8 Electric Co 88/12/09 Document Control Branch (Document Control Desk). 3pp. 47834:271-47834.273
- 8812190072 Forwards PRA for auxiliary saltivator sys.per util 881129 commitment re long term solsmic program. SHIFFER,J.D. Pacific Gas & Electric Co. 88/12/09. Document Control Branch (Documant Control Desk). 85pp. 47848 241-47848-327
- 8912160014 Forwards proprietary WCAP-11312,Rov 1 & nonproprietary WCAP-11966, "Westinghouse Owners Group Toch Spec Subcommittee Reactor Trip Broaker Maint/ Surveillance Optimization." WCAP-1312,Rov 1 withhold (rol 10CFR2 790) SHIFFEH.J.D. Pacilic Gas & Electric Co. 88/12/12 Document Control Branch (Document Control Branch (Branch (Document Control Branch (Document Control Branch (Document Control Branch (Branch (B
- ment Cantrol Dosk). 3pp. 47834 276-47834.336
- 8812160026 Forwards proprietary WCAP-12064 & nonpreprietary WCAP-12065 repts in support of utilitraview of steam generator tuning at plant for susceptibility to fatigue induced cracking SHFFERIA D Pacific Gas & Electric Co. 88/12/12 Document Control Branch (Document Control Desk). 4pp. 47869-125-47869-332.
- --8812160027 Submits application withholding proprietary rept WCAP-12004, "Diable Caryon 1 & 2 Evaluation For Tube Vibration Induced Fatigue," from public disclosure (ref. 10CFR2 790(b)[4])
- WIESEMANN, H.A. Westinghouse Electric Corp. 88/12/02, MURLEY, T. Office of Nuclear Reactor Regulation, Director (Post 870411), 10pp, 47869, 129, 47869, 138. --8812160029 "Diable Canyon 1 & 2 Evaluation For Tube Vibration Induced Fatigue." CONVORIS.H.J., FRICK,1 M., HALLJ.M. Westinghouse Electric Corp. WCAP-12065. 88/11/20, 194pp. 47869.139.47869.332
- 8812200230 Forwards request for addl into re-plant long-term selsmic program final rept Response to PHA questions should be submitted by 890115 & response to other
 - questions by 890130 FPK questions should be stabilised by 890113 & Repoile to differ Questions by 890130 ROOD, IL Project Directorate V. 88/12/13. SHIFFER, J.D. Pacific Gas & Electric Co. 14pp. 47868-148-47868-161.
- Q. Inspection reports, IR Bulletins & correspondence
- 8812050200 Forwards SALP Mgt Meeting Repts 50:275/88-30 & 50:323/88:28 on 881028 KIRSCH.D.F. Rog on 5, Ofc of the Director, 88/11/10, SHIFFER.J.D. Pacific Gas & Eluctric Co. 2pp. 47731:138-47731.144.
- --8612050201 Mgt Meeting Repts 50-275/88-30 & 50-323/88-28 on 881026. Major areas discussed SALP rept for plant & recent plant events developed since linst mgt meetings hold on 880722 & 0428 O'BRIEN,J.P., MENDONCA,M.M. Region 5, Ofc of the Director. 88/11/00, 5pp. 47731.140-47731:144
- 8811160211 NRC Into Notice 88 090, "Unauthorized Romoval of Industrial Nuclear Gauges." Svc list encl. CUNNINGHAM.R.F. Division of Industrial & Medical Nuclear Safety (Post 870720). 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologic cal Tests" Svc list and ROSSIC E. Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142
- 8812130244 Forwards Insp. Ropts 50-275/88-26 & 50 323/88-24 on 880904-1022 No. violations noted Discussns events
 KIRSCH,D.F. Region 5, Ofc of the Director, 88/11/23 SHIFFER,J.D. Pacific Gas & Electric Co. 3pp. 47798:107-47798:128.
- -8612130245 Insp Repts 50 275/88-26 & 50-323/88-26 on 880904-1022 No violations or deviations noted Major areas inspected plant operations, maint & surveillance activities, unsite events, open Items, LFRs & selected independent insp activities. WAGNER, W., JOHNSTON, K. E., NARBUT, P. P. Region 5, Otc of the Director, 88/11/22, 18pp. 47/98.110-47798:128.
- 8812010259 Ack receipt of 881005 ftr informing NRC of steps taken to correct violations noted in Insp Repts 50-275/88-15 & 50-323/88-14.Response to encl list of questions
- requested within 30 days.

 KIRSCH.D.F. Region 5, Ofc of the Director. 88/11/25. SHIFFER,J.D. Pacific Gas & Electric Co. 3pp. 47709.075-47709.144.
- 8812080094 Forwards proprietary WCAP-12064, "Diable Canyon 1 & 2 Evaluation for Tube Vibration Induced Fatigue" All five tubes requiring corrective action removed from sec during Unit 2 refueling outage Rept withheld (rol 10CFR2.790). SHIFFER, J. D. Pacific Gas & Electric Co 88/11/730. Document Control Branch (Document Control Dask) 2pp. 47736.221-47736:222.
- 8811290030 NRC Info Notice 88-093, "Taletherapy Events," Svc list enci CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02, Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc tist encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254

- 8812150093 Ack recriptiof 881107 thin forming NRC of steps taken to correct deviation rousd in thrup Repsis 25 275/65/25 & 50/323/48/23 PATERU, Repsis 5, Ots of the Director 68712/02 SMIFFER,UID Pacific Gas & Elected Coll pt 475/35/03/47935/5077
- 8812130131 Informs that per R61130 relocal agreement reached botween ftRC & utilitiat regenre reciponse dato to iguistichis contained in ftRC 881125 thine worklichs solded in ftsp Repts 50 275768-115 & 50 323748 11,4 mild to 840103 SHEFER, DD Pack Gods & Fectivic Co. 86/12/05 MENDORCA MIM. Region 5, Dio ctittle Orector: 1p. 47794-130 47794-130
- 8812020287 NEC Info Notice 88 095, "Inadequate Procurement Requirements Imposed by Licensces or Vendors" Swiftstend in OSSICE Drisson of Operational Events Assessment (Post 870411) 88/12/09 Conscripting Edward Notice 40
- 8812230121 Forwards safety evaluation accepting first 10 yr interval inservice firsp program pran for of an Technical Evaruation Reprisional.

 ACCOM Project Directorate VI 88/12/14 StiffER.J.D. Pacific Gas & Electric Co. Spp. 47315 221 47916 021.
- #8812230155 SEA accepting plant first 10 yr inferval insonuce inspip program plan per 16CFR50 55a(q) 8 Tech Spec 4 0.5 1 Otroe of Nuclear Readlor Regulation, Director (Post 870411) 88/12/14 12cp 47415 304 47215 304 47215
- 8812270203 Responds to NRC Bulletin 89-008, "Thermal Stresses in Piping Connected to RCS" Radiographic exam of weldscheat affected zones & high stress locations including geometric discontinuities found no endence of as sting traws SHFFERUD Radio Gas & Electric Co. 85/12/19 Document Control Branch (Document Control Drisk) 4pp. 47925 300-47925 303

R. Periodic operating reports & related correspondence

- 8811290426 "Rept on Discharge Monitoring at Diablo Campon Power Plant During Month of Oct 1985 W/851121 tr. TOW/19570.0 Pack Gas & Electric Co. 88/10/31, 81pp. 47651,118,47651198.
- 8812190233 Monthly operating repts for Nov 1989 for Distric Caryon Units 1 & 2 W/ 881214 ftr. BEDESEMP, MOLANUJ, TOWNSENDUD Pacific Gas & Electric Co. 88711730 11pp 47851127-47854 137

S. Reportable occurrences, LERs & related correspondence

- 8812130172 LER 88 014-00 on 881009 lound beministraining block studs for each check value RHP 2 8740A to be broken Caused by migliacorrect heat treatment of check valve Seatch made to locate valves wybotensatil for stud fazire W0811118 tt. MOLARIJIC. SIFFERIJID Pacific Gas & Electric Co. 88/11/18 11pp 47794 240 47794 250.
- 8812150248 Special Repl 88-03 on 681112 diesel generator 1-3 did not start on second level undervollage Caused by contact fature in second felio undervollage relays Contacts on relay cleaned & second felial undervollage portion completed SHEFERJ Di Pacific Gas & Electric Co. 88/12/09 Cocument Control Branch (Document Control Desk). 8pp. 47830-282-47830-287.
- 8812270205 LER 88-018-00 on 881121,unintentional automatic start of two motor-driven autolary sections occurred Caused by Inadequate fest procedure Administrative Test Procedure C-1 S1, "Onsite Plant Mod" being revised W/881220 it.

 GREBEL, TL. SH.FFER J.D. Pacific Gas & Electric Co. 88/12/20, 6pp. 47927 055

T. Hearing transcripts on non-antitrust matters

- 8812210118 Partial response to FOIA request for closed Commission meeting transcripts between Jan 1980 & Dec 1985 re plant App A documents available in PDR App B partially withheld & App C documents completely withheld per Subshitte Act
 GRIMSLEY,DH- Division of Freedom of Information & Publications Services (Post 880515), 88/12/19 SCHMIEGE,P.A. O'Melveny & Myers, 7pp. 47874 059-47874 127.
- -8812210120 Partially withheld transcript of 810331 closed Commission intenting in Washington,DC to discuss plant order Pp 1.16 . Commissioners 81/03/31 13pp 47874 066-47874 078
- --8812210122 Partially withheld transcript of 810825 closed Commission breaking in Washington DC re-pending adjudicatory proceedings Pp 1-83 * Commissioners 81/08/25, 16pp 47874-079-47874-123
- -8812210128 Partially withheld transcript of 821021 closed Commission briefing in Washington,DC religional Investigations Pp 1-71 1 Commissioners 82/10/21, 4pp. 47874-124-47874-127.

U. Congressional/Executive Correspondence

- 6811300421 Responds to 981020 ftr to Charman Zech urging NRC to study util rept reevaluating sessinc deelign basis for plant. Concludes that plant design seismically adoquete.

 STELLO,V. Otc of the Executive Director for Operations 68/11/18. BOXER,8 House of Rep 9pp 47755:012-47755 021.
- -8811300423 Requests studying of seismology rept which reassesses seismic design base of facility recently released by PG&E. BOXER,B. House of Rep. 88710/20. ZECH,L.W. Commissioners. 1p. 47755.021-47755.021.

V. Operator Examinations

8812140046 Forwards revised agenda for annual operator Learsin 090110 W/o etic! PATE,R.J. Region 5, Oto of the Oxentor 88712795 IMARDIN 1, Partic Co. 2pp. 47800 165-47800 166

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8811230004 Forwards inner ded flew 5 to security transleg 8 geoder plant Rev withheld (ref. 1005FR2 790). LOFUNUT Carefina Power 8 Light Ca. 88731738. Domained Control Desk). 1p. 47652-135-47652-135.
- 8612050273 Forwards toop Repts 50-324788 JR 8-50-325784 JR Gr. Figure of violation Uniteselved items noted

of violation Unresolved itams noted VERRELLI,D.M. Region 2, Otc of the Caracter (897) 1723 (1711-Y), E & Light Co. 2pp. 47723-153-47723 167

- #8812050274 Notice of violation from hispitich 131 Viellation role: Procedure FPP-014 not implemented in that rachine interfal water talgerestrated area 8 no roles will threshold braits conducted VERRELUID M. Region 2. Ofc. of the Orienter 188711721 (sp. 4772).
- 8812090273 Forwards Insp Rinpts 50 024789:07 8 50:025788:07 on 88 not so of world on DECKERT R. Rigg on 2, Ofc of the Director INB/11725. UTLEY,ETE C. Light Co. 2pp. 47785-014-47785-032

-8812090278 Notice of violation from inspiror 881017-19 8-27 Violation provide tracky follow up messages to offeate auditorians. DECKER, TR. Region 2, Ofci of the Director 188111725-2pp. 47785 nife

- --8812090284 Insp. Repts 50 324788-37 & 50-325788-37 on 891017-19 noted Major areas inspectual energency papilaredniuss invocuse BANKIN,WHI, SARTOR,W.W., KAMVOR,F. Brigon 2, Oh. of the Pre-1spp 47785-018-47785-032
- 8812090112 Forwards 1st of rove to plant umorgonity procedures, per Eirclading Rev 012 to PEP-02-3, "Emirigency Control - Alert" HARNESS, J.L. Carcton Power & Light Co. (18711728 GHACE, J.N. Rithe Croctor 2pp. 47775.093-47775.094
- 8812220278 Approves 830415 requests for approval of use of alternaplace of backup emergency operations facilities for plants. LORH Project Directorate (I.1. 88/12/16) UTLEY, E.E. Carolina Pos. 4pp. 47902 283-47902 281.

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 89:20 to all trensces holding Otts 8 CPs for reactor facilities re-individual plant evant for severe accident vulner encl.

 CRUTCHFIELD,D. Associate Director for Projects (Post 8704111) 087 dated Edison Co. of New York, Inc. 81pp. 47720 303 47729 024.
- 8812130169 Notification of 881209 meeting whith to Rickwise MD to distration of 8 Teansees proposed corrective actions for pipe cracks in injection nozzla.

 LENB, Project Directorate II-1 88/12/07, MURLEY T., SNIEZERC, NRC No Data lod Affiliation Given, 3pp. 47704, 113-47/94-115.
- 8812140082 Advises that l'stort project managers reassigned to plan 881205 ADENSAM,E.G. Project Directorate III. 88712708 UTILEY,E.F. Ca Light Co. 3pp. 47799 240-47799 242.
- 8812190407 Advisos that urt has adopted BWR Owners Group, "Interdutions for Stability Actions," by issuance of Standing Instruction 88-114 NRC 981207 request for add into re-Euol Cycle 7 reford LOPLIN,L I Carotina Power & Light Co. 88/12/14. Document Control ment Control Desk). 1p. 47851:313-47851-313
- 8812200172 Summary of 881122 theoling would in Rockvilln,MD to providing myllion activities undertaken at site to improve portall operation to end.

 MOZAFARI,B. Project Directorate II-1 88/12/19 Project Directorate 47870 341-47870,347.

- 8811230294 Supplemental response to violations moted in Irisp Ropts 50.325788.14.Corrective actions requirements, established to in on ito: tempon 30 mirrule ponodicity when in shuldown cooling HARNESS.J.L. Carolina Power & Light Co. 88711718 | Document Control umant Control Desk). 3pp. 47652.122-47652.124
- 8811280209 Ack receipt of 881013 fit informing NRC of ships taken to concled in linsp Ropts 55 324/86-21 8 55 325/88-21 VERRELLIO M. Region 2, Oto of the Director 88/11/21 UTLEY,E F & Light Co. 2pp. 47654 069-47854 070
- 8611160211 NRC Into Notice 88 090, "Unauthorized Removal of In Gauges" Sychistienci. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety 88/11/22 Consolidated Edison Co. of New York, Inc. 99(p) 4/7/08/25/

- ROSSICE Division of Operational Events Assessment (Post 870411) 88/11/22 Consciidated Edison Co. of New York Inc. 101pp 47708 042-47708 142.
- 1812050225 Informs that reactor & turtine bldg ventilation flow rate measurement devices will be completed by 690393 instead of 900113 Plant mods required to correct design problems w/sys can bu expended HAFNESS II. Carolina Power & Light Co. 88/11/23. Document Control Branch (Document Ontrol Drsh.). 1p. 47733-155-47733-155
- 3812050273 Forwards Insp Repts 50 324/88-38 & 50-325/88-38 on 881001-31 & notice
- of wellaton Uniosolived ilems indied VEHAELLI D.M. Rey on 2, Ok. of the Director 88/11/23 UTLEY,E.E. Carolina Power & Light Co. 2pp. 47723-154-47723-167
- -8912050274 Natice of violation from inspiring 881001-31 Violation noted. Fire Protection Procedure FPP-014 not implemented in that nontire retordant wood used inside syc water bidg restricted area & no review of threshold limits conducted VERRELLIDM Region 2, Old of the Director 88/11/23, 1p. 47723-155-47723-155
- -8812050275 Insp. Repts. 50.324/88/38 & 50/325/00/38 on 881001/31. Violations co'ed Major areas Inspected maint observation, surveillance observation operational safety vertication & crisite followup of events
 RULAND,WHI, LEVIS,W., MADDEN,P.M. Region 2, Ofc of the Director, 88/11/23
 12pp 47/23 155-47/23 167
- 3812050043 Confirms dates of 881213-16 for meeting at plant in preparation for maint team risp of plant on 893109-13 & 23-27,per 881122 teleon List of insp mails encl HERDT,A.R Region 2, Ole of the Director: 88/11/25 UTLEY,E E. Carcina Power & Light Co. 4pp. 47/43-085 17743-088
- 3812090273 Forwards hisp Rents 50 324/88/37 & 50-325/88/37 on 881017-19 & 27 & notice of violation DECKER,TR Ruglion 2, Old of the Director, 88/11/25, UTLEY,E.E. Carolina Power & Tight Co. 2pp. 47785-014-47785-032
- -8812090278 Notice of violation from this on 881017-19 & 27.Violation noted fature to provide 1 mely follow-up messages to offsite authorities BECKER,T.R. Region 2, Old of the Director, 88/11/25, 2pp. 47785-018-47785-017
- -8812090284 hisp Hopts 50 324/88/37 8 50/325/88/37 on 881017/19 & 27, Violation noted Major arous hispocted critirgrincy proparednoss exercise RANKIN,W.H., SARTOR,W.M., KANTOR,F. Region 2, Otc of the Director, 88/11/25 15pp 47785 018-47785.032
- 9812060157 Responds to NRC 881130 ltr re-violations noted in Insp Repts 50-324788-34 & 50-325/88-34 Corrective action review conducted of administrative & engineering procedures in place at tiral of in tuition 8 approval
 HARNESS, I.C. Carolina Power & Light Co. BR711/30. Document Control Branch (Document Control Dosk), app. 47741-237.
- 8812190221 Forwards Exam Rept 50-324/OL-BB 01 of exams administered on 880829-
- 0909 Rept for both Inchter; 100 A. Region 2, Olc of the Director 80/11/39, UTLEY,E.E. Carolina Power & Light Co. 2pp. 47/149 080-47849.005
- -8812190222 Exam Rept 50-324/OL-89 01 on 880829-0908.Exam results:17 cendidates passed operating tests, 18 candidates passed written exams & one candidate passed written exam of Calegory 8 Rept for both facilities PAYNE D.C., BROCKMAN,K.E. Region 2, Ofc of the Director, 88/11/22, 4pp. 47840,082-47840,085
- 8811290030 NRC Info Notice 86:093, "Telotherapy Events." Svc list encl CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729) 89/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list
 - erct ROSSI,C E. D.vision of Operational Events Assessment (Post 870411), 88/12/02, Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812090027 Ack receipt of 881118 ftr Informing NRC of steps taken to correct violations noted in Insp. Rept 50-324/88-14. & 50-325/88-14. REYES,L A. Region 2, Ofc of the Director. 88/12/02. UTLEY,E E. Carolina Power & Light Co. 2pp. 47761-066-47761-066
- 8812180119 Forwards Insp. Repts 50:324/88:40 & 50:325/88:40 on 881031-1104 &
- rot co of violation.
 JNN.C.A. Region 2, Ofc of the Director. 88/12/06, UTLEY,E.E. Carolina Power & Light Co. 2pp. 4/893-326-4/932-337.
- -8812160126 Notice of violation from insp on 881031-1104. Violation noted original unreviewed safety question determination for PM 67-226 drd not provide sufficient justification for add 15 field reys that substantially expanded scope.
 JULIAN,C.A. Region 2, Ofc of the Director. 86/12/06 2pp. 47632:328-47632:329.
- 47632:337.
- 8812020287 NRC Info Notice 88 095, "Inadequate Procurement Requirements Imposed by Liconsess on Vendors" Svc list encl.
 ROSSICE. Division of Operational Events Assessment (Past 870411). 88/12/08.
 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812210009 Ack receipt of 881130 ftr Informing NRC of stops taken to correct violations roted in Insp Repts 50-324/88-34 & 50-325/88-34. VERRELLI,D M. Region 2, Otc of the Director. 88/12/16. UTLEY,E.E. Carolina Power & Light Co. 1p. 47888-099-47888-099
- 8812270199 Responds to violations noted in Insp Repts 50-324/88-38 & 50-325/88-38 Corrective actions personnel indoctrination training of plant const craft supervisors & foreign will be conducted to cover use of fire referred wood.

 HARNESS JL. Carolina Power & Light Co 88/12/21. Document Control Branch (Document Control Desk). 3pp. 47926:263-47926:265.

- 8811300193 Summary of Operating Reactor Events Meeting 88-46 on 881122 LANNING,W.D. Events Assessment Brench 88/11/25 ROSSIC E. Division of Operational Events Assessment (Post 870411) 11pp. 47680 201-47680 211.
- 8B12140247 Monthly operating repts for Brunswick Steam Electric Plant Units 1 & 2 for 912190497 Actions Operating Topics to Community Operation Nov 1998 W7881286 HTML Nov 1998 W7881286 HTML Nov 1988 Topics Operation Operat 47799 270-47799 280

S. Reportable occurrences, LERs & related correspondence

- 8812130161 LER 88:001:02 on 880102;manual roactor protection sys trip initiated Caused by decreasing contenser vacuum interim corrective measure will be compreted by 8906:30.W/881201 tit. PASTVA,M J. HARNESS,J L. Carolina Power & Light Co. 80/12/01. 10pp. 47794.251-47794-260
- 8812130137 LER 88-014-00:on 881107.primary containment isolation sys (PCIS) Group 5 isolation signal received w/closure of RCIC E51-F007 Caused by personnel error Personnel involved field for a ring sessions discussing event W1/881206 lift HARRIS.T., HARNESS.J.L. Caroline Power & Light Co. 88/12/06 5pp. 47795.343-47795.347
- 8812210111 LER 88-018-00 on 881116 reactor scramed due to bubbine controt valve fast closure on high fevel furbine trip Caused by feedwater logic inverter tripping on high input voltage due to limit switch problem Switch readjusted Wn881215 tr.
 JONES T.M., HARNESS J.L. Carotina Power & Light Co. 88/12/15 7pp. 47876:129-47876:135
- 8812210131 LER 88-019-00.on 881116,reactor low level 1 reactor protection sys trip oc-curred due to startup level control valve laring to feed vessal Valvo unable to open due to procedure inadequacy.Procedure revised W/881215 ltr. JONES,T.M., HARNESS,J.L. Carolina Power & Light Co. 88/12/15 5pp. 47881-013-47881-017
- 8812210409 LER 88-011-01:on 880725, discovered that shutdown cooling suction supply primary containment isolation sys inboard isolation vaive would not open Caused by in lure to close off electrical contacts in switch 1.W/881216 ttr
 PASTVA.M.J., HARNESS.J.L. Caroline Power & Light Co. 88/12/16 4pp. 47882 47882 059

V. Operator Examinations

- 8812190207 Forwards exam comments for exam given on 880829 at plant HOWE,P.W. Carolina Power & Light Co. 88/09/02 BHOCKMAN,K. Region 2, Ofc of the Director. 26pp. 47851;287-47851;312.
- 8812190221 Forwards Exam Rept 50 324/OL-88 01 of exams administered on 880929-0008 Rept for both feelilities JULIAN.C.A Region 2, Ofc of the Director, 88/11/30, UTLEY,E.E. Carolina Power & Light Co. 2pp. 47849,080-47849.085.
- -8812190222 Exam Rept 50:324/OL-88-01 on 880829-0908.Exam results 17 candidates passed operating tests, i6 candidates passed written exams & one candidate passed written roxem of Category 8 Rept for both facilities.

 PAYNEDC, BROCKMAN,KE Region 2, Ofc of the Director, 88/11/22, 4pp. 47849.082-47849.085.

DOCKET 50-326 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811230004 Forwards amended Rev 5 to security training 8 qualification plan for plant.Rev withhold (rof 10CFR2.780). LOFLIN.L.1. Carolina Power 8 Light Co. 88/11/18. Document Control Branch (Document Control Dosk). 1p. 47652 135-47652 135.
- 8812050273 Forwards Insp Repts 50-324/88-38 & 50-325/88-38 on 881001-31 & notice of widelign Unresolved Items nated. VERRELLI,D.M. Rogion 2, Olic of the Director. 68/11/23. UTLEY,E.E. Carolina Power & Light Co. 2pp. 47723-163-47723-167.
- -8812050274 Notice of violation from inspion 881001-31. Violation noted Fire Protection Procedure FPP-014 not implemented in that nonfire retardant wood used inside svowater bldg restricted area & no review of threshold limits conducted.

 VERRELLI,D.M. Region 2, Ofc of the Director, 88/11/23, 1p. 47723-155-47723.165.
- 8812090273 Forwards Insp Repts 50-324/88-37 & 50-325/88-37 on 831017-18 & 27 &
- notice of violation DECKEN,T.H. Region 2, Ofc of the Director, 88/11/25, UTLEY,E.E. Cerokna Power & Light Co. 2pp. 47765-014-47785-032.
- -8612090278 Notice of violation from insp on 8B1017-19 & 27 Violation noted failure to provide timely follow-up messages to offsite authorities. DECKER,T.R. Region 2, Ofc of the Director, 88/11/25, 2pp. 47785.016-47785.017.
- --8812090284 Insp Repts 60-324/88-37 & 50-326/88-37 on 881017-19 & 27. Violation noted Major areas inspected emergency preparedness exercise.
 RANKIN,W.H. Region 2, Ofc of the Director, 88/11/25, 16pp, 47785;018-47785.032.
- 8812090112 Forwards list of rays to plant emergency procedures.per 10CFR50.App E.ncluding Rev 012 to PEP-02.3, "Emergency Control Alort." HARNESS.J.L. Carolina Power & Light Co. 88/11/28. GRACE.J.N. Region 2, Olc of the Director. 2pp. 47775:093-47775.094.
- 8812220276 Approves 830415 requests for approval of use of alternate locations in place of backup emergency operations facilities for plants. LO.R.H. Project Directorate II-1. 88/12/16. UTLEY,E.E. Carolina Power & Light Co. 4pp 47902:288-47802:291.

P. Operating ticense stage documents & correspondence

- 8811280048 Generic Ltr 68/20 to all licensees holding Ots & CPs for nuclear power reactor lachities re-individual plant exam for severe accident vulnerabilities Svc list
 - CRUTCHFIELD, D. Associato Director for Projects (Post 870411), 88/11/21. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303 47729 324.
- 8812130169 /hot/sellon of 881209 meeting w/utr in Rockwite,MD to discuss character-tizion of & licensees proposed corrective actions for pipe cracks in U-1 core spray
- registro no 219 registro no 219 LE NB Project Directorale III-1 88/12/07 MURLEYT, SNIEZEK,J, MIRAGUA,F INGC NO Destred Affilason Given 3pp. 47784 113 47794 115
- 8812140082 Advises that I sted project managers leassigned to plants, effective on 881/25 ADENSAMEG Project Directorate (III. 88/12/08 UTLEY,E.E. Carolina Power & Light Co. 3pp. 47799 240 47799 242
- 8812190407 Advises that util has adopted BWR Owners Group, interim Recommendations for Stability Actions," by issuance of Standing Instruction 88-114 on 881104, per NRC 681207 request for add info its Fuel Cycle 7 reload. LOFLINLL I Carolina Power & Hight Co. 681/12/14. Document Control Branch (Document Control Desk) 1p. 47851 313 47851 313.
- 8812200172 Summary of 861122 meeting w/u/l in Rocky lie,MD to provide update to NRC mgt on activities undertaken at site to improve overall operation List of attendees
- enci MOZAFARI B Project Directorate III-1 88/12/19 Project Directorate III-1 7pp 478/10341-47870347

Q. inspection reports, iE Bulletins & correspondence

- 8811230294 Supplemental response to violations noted in losp Replis 50:324/88:14 & 50:325/88:14 Corrective actions requirements established to monitor reactor vessel temp on 30 manute pendectify when in shutdown cooling HARNESSUL Carolina Power & Light Co. 88/11/18. Document Control Branch (Document Control Desk). 3pp. 47652122-47652.124.
- 8811280209 Ack receipt of 681013 ltr intorming NRC of steps taken to correct violations noted in Insp. Repts 50-324/88-21 & 50-325/88-21 VERRELLID M Report 2. Off of the Director 88/11/21, UTLEY,E.E. Carofina Power & Light CO 2pp. 47654 069-47854 070
- 8811160211 NRC Info Natice 88-090, "Unauthorized Roinozal of Industrial Nuclear Gauges " Svc list encl CURTHINGHAM R.E. Drivision of Industral & Medica' Nuclear Salaty (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 89pp. 47708.255-47708.257.
- 8811160487 NRC Into Notice 88-091, "Improper Admin stration & Control of Psychologicel Tests" Svc list encl ROSSICE Division of Operational Events Assessment (Post 870411), 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47709.042-47708.142.
- 8812050225 Informs that reactor 8 turbine bldg versilation flow rate measurement do vices will be completed by 890303 instead of 900113. Plant mode required to correct design problems w/sys can be expedited. HARNESS, J.L. Carolina Power & Light Co. 88/11/23 Document Control Branch (Document Control Dask). 1p. 47733.155-47733.155.
- 8812050273 Forwards Insp Repts 50-324/88-38 & 50-325/88-38 on 881001-31 & notice of violation threesofved itams noted VERRELLI,D.M. Region 2, Ofc of the Director, 88/11/23, UTLEY,E.E. Carolina Power & Ught Co. 2pp. 47723153-47723167.
- -8812050274 Notice of violation from inspirence 881001-31. Violation nated Fire Protection Procedure FPP-014 not implemented in that nonfire relardent wood used triside svo-water blog restricted area & no review of threshold limits conducted VERRELLI, D.M., Region 2, Ofc of the Director, 88/11/23, 1p. 47723.155-47723.156.
- -8812050275 Insp Repls 50-324/88-38 & 50-325/88-38 on 881001-31. Violations noted Major areas inspected maint observation, surveillance observation, operational salety verification & onsist followup of events. RULAND, W., LEVISW, MADDEN,P.M. Region 2, Ofc of the Director, 88/11/23 12pp, 47723.156-47723.167.
- 8812060043 Confirms dates of 881213-16 for meeting at plant in preparation for maint learn hisp of plant on 890109-13 & 23-27.per 881122 refcon Ust of Insp maits encl. HERDIT AR Region 2, Otc of the Director. 68/11/25 UTLEY,E.E. Carolina Power & Ught Co. 4pp. 47743-085-47743-088.
- 8812090273 Forwards Insp Repis 50-324/88-37 & 50-325/88-37 on 881017-19 & 27 & notice of violation.

 DECKER,T.R. Region 2, Otc of the Director, 88/11/25, UTLEY,E.E. Cerolina Power & Light Co. 2pp. 47785-014-47785-032.
- -8812090278 Notice of violation from inspirence 881017-19 & 27.Violation noted.failure to provide timely follow-up messages to offsite authorities. DECKER,T.R. Region 2, Otc of the Director. 88/11/25, 2pp. 47785 016-47785.017.
- -8812090284 Insp Repts 50-324/88:37 & 50-325/68-37 on 681017-19 & 27. Violation noted Major areas inspected emergency preparedness exercise. RANKIN,W.H., SARTOR,W.M., KANTOR,F. Region 2, Otc of the Director. 88/11/25. 15pp. 47785-018-47785-032.
- 8812060167 Responds to NRC 881130 ftr re-violations noted in Insp. Repts 50:324/88-34 & 50:325/88-34 Corrective action review conducted of administrative & engineering procedures in place at time of initiation & approval. HARNESS, J. L. Carolina Power & Ugnt Co. 89/11/30. Document Control Branch (Document Control Desk). 4pp. 47741:234-47741.237.
- 8812190221 Forwards Exam Rept 50:324/OL-88-01 of exams administered on 880829-0908 Rept for both facilities. JULIAN CA. Region 2, Ofic of the Director. 88/11/30. UTLEY,E.E. Carolina Power & Light Co. 2pp. 47849 080 47849 085.

- -8812190222 Exam Rept 50:324/Ot.:88:01 on :880829:0908.Exam dator passed operating leats.16 carefulatus pressed written exam of Category 8 Rept for both factives PAYNE D.C. Region 2, Oto of the Director. 88/11/22 4pp. 47849 682
- 8811200030 NRC Into Natice 88-093, "Toletherapy Events" Svc list en CUNNINGHAM,R.E. Division of Industrial & Modreal Nuclear Safet 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 4781
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Ad ROSSLCE, Division of Operational Events Assassment (Post 870 Consolidated Edison Co. of New York, Inc. 121pp. 47708-143-47708.
- 8812090027 Ack receipt at 881118 lic informing NRC of steps taken to noted in Insp. Rept 50, 324788-14 & 50-325788-14. REYES, A. Region 2, Oto of the Director, 88712702, UTLEY,E.E. Clight Co. 2pp. 47761 066-47761 066.
- 8812160119 Forwards Insp. Flopts 50-324788-40 & 50-325788-40 on notice of violation JULIAN,CA Region 2, Ofc of the Director 88/12/06, UTLEY,E.E. (Light Co. 2pp. 47832-326-47832.337
- --8812160126 Notice of violation from hisp on 881031-1104. Violation a reviewed satory quest on determination for PM 87-226 did not provide the notice of the first substantially explanted scope JULIAN, C.A. Region 2, Ofc of the Director. 89/12/06, 2pp. 47832-326.
- -9812160127 Insp. Repts 50 324/68 40 & 50 325/08 40 on 881031 noted Major areas inspected design design control & mode. COOPER, T., BELISLE, G.A. Region 2, Ofc of the Ovector 88/12/05 47832 337
- 8812020287 NRC Info Notice 88:095, "Inadequate Procurement Requi-by Liconseps on Yenticis" Svc list end: ROSSICE Division of Operational Events Assessment (Post 87 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807
- 8812210009 Ack receipt of 881130 ftr informing NRC of stups taken to noted in Insp Regis 50-324/88-34 & 50-325/88-34. VERRELLIO M. Region 2, Otc of the Overtor 80/12/16. UTLEY.E.S & Light Co. 1p. 47680-099-47888-099.
- 8812276199 Respands to wolations noted in thisp Ricpis 50-324/88-38.Corrective actions, personnel Indoctionation training of plant const 8 foremen will be conducted to cover use of file relatedant wood. HARNESS, J. C. Caroba, Power & Light Co. 86/12/21, Decument Con-ument Control Desk). 3pp. 47026 263-47926 265.

R. Periodic operating reports & related correspondence

- 8811300193 Summary of Operating Reactor Events Moeting 88:46 on LANNING,W D. Events Assessment Branch, 86/11/25, ROSSI,C.E. abonal Events Assessment (Post 870411), 11pp. 47680.201-47680.2
- 8812140247 Monthly operating repts for Brunswick Steam Efectric Plan Nov 1988 W/881266 ftr. HARRISONF., HARNESS,J.L. Carolina Power & Light Co. (47799.270-47799.280.

S. Reportable occurrences, LERs & related correspondence

- 8811290031 LER 88-023-00: on 881021,Unit automatically scrammed bine trip/furbine step vs/ve closure Caused by high electrical resist facts 3.7.4 in fuedwards control transfer relay Relay replaced W/8811 PASTVAMJ, HARNESS,J.L. Carolina Power 8 Light Co. 88/11/18
- 8812060242 LER 88-011-02 on 880420,HPCI pump suction from supp F0A1 would not opon during instrument channel callor & functio caused by breakdown of motor-winding insulation.W/8811123 ltr. PASTVA,MJ., HARNESS,J.L. Caroline Power & Light Co. 88/11/23
- 8812050219 Special Rept 1-SR-88-003 on 881120,7-day time frame for its operation exceeded Caused by fire Door 211 being out-of-sec to possible damage to locking seals & interlocks.

 HARNESS.J.L. Carolina Power & Light Co. 88/11/28. Document Corument Control Desk). 2pp. 47733:278-47733:279.
- 8812220059 Summary of Operating Reactors Events Meeting 88-48 o å list of attendees encl. LANNING,W.D. Events Assussment Branch. 88/12/07. ROSSI,C E. attenal Events Assessment (Post 870411). 15pp. 47922.001-47922.0
- 8812130017 LER 88-024-09:on 881110,TCV feet closure reactor acre power/load unbalanced testing Caused by assumed alectrical fault of rious trip. Control rods scheduled to be rebuilt W/881208 ftr. JUNESSAULT ARRIVESSAUL. Carolina Power & Light Co. 88/12/08. 47797:132.
- 8812210090 LER 88-027-00 on 881118 discovered that reactor bidg a lock doors were ted open but did not have proper associated fire is a hourly hiewatch Caused by personnel error W/881214 ftr. HARRIST, HARNESS,J.L. Carolina Power & Light Co. 88/12/14-47888-293.
- 8812210103 LER 88-025-00 on 881115.outboard MSIVe B21-F028B meet Tech Spec local leak rate requirement.Root cause under introntinung Followup rept will be submitted by 890324.W/881215 ftr. PASTVA.M J. HARNESS.J.L. Carolina Power & Light Co. 86/12/15 47877:108

- 8812210097 LER 88:028:00:on 881123.coro spray subsys B p/po crack indication re-veated through Generic Lir 88:01 testing Preliminary cause indicates IGSCC of weld inconnel buttering Overlay approved W/801216 Iff. PASTVA M J., HARNESS J.L. Carolina Power & Light Co 88/12/16. 2pp. 47877-125.
- 8812210395 LER 88-026-00 on 881116.unplanned isolations occurred due to momentary toss of power to common emergency bus E-2. Appropriate real-lime training will be conducted to stress importance of proper test lead during testing.W/681218 tir. PASTVA.M.J., HARNESS.J.L. Carolina Power & Light Co. 86712716. 7pp. 47882-044. 47882 050

V. Operator Examinations

- 8812190207 Forwards exam commonts for exam given on 880829 at plant HOWE,P.W. Carolina Power & Light Co. 88709702 BROCKMAN,K. Reg on 2, Ofc of the Director, 26pp. 47851:287-47851:312.
- 8812190221 Forwards Exam Flept 50-324/OL-88-01 of exams administered on 880829-0908.Rept for both facilities
 JULIAN,CA. Region 2, Ofc of the Director, 89/11/30 UTLEY,E.E. Carolina Power & Light Co. 2pp. 47848.080 47849.085
- -8812190222 Exam Rept 50:324/OL-88-01 on 880829-0008 Exam requits:17 candidates passed operating tests,18 candidates passed written exams & one candidate passed written exams & one candidate passed written exam of Category 8-Rept for both facrities PAYNE.O.C. BROCKMAN.K.E. Region 2, Ofc of the Director. 88/11/22, 4pp.
- 47849 082-47849 085

DOCKET 50-328 UNIV. OF CALIFORNIA AT IRVINE RESEARCH REACTOR

V. Operator Examinations

47793:077

8812140143 Forwards revised agenda for annual operator ticensing mooting on 890110 W/o encl PATE,R.J. Region 5, Olc of the Director 89/12/05, MILLER,G. California, Univ. of, In/na, CA. 1p. 47811:270-47811:270.

DOCKET 60-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812220115 Forwards Insp Repts 50-327/88-37 & 50-328/88-37 on 880725-28 One unrosolved film 8 three inspector follows: items noted finspense requested within 30 days of three-pt. Respector follows: items noted finspense requested within 30 days of three-pt. Respector follows: 88/10/28. WHITE,S.A. Tannessee Valley Authority. 3pp. 47900,180-47800.197.
- -8812220119 Insp Repts 60-327/88-37 & 60-328/88-37 on 880725-28 Unresolved & Tollowup Itams noted Major argas inspected.fire protection & implementation of incCFR50.pp R. incCFR50.pp R. WESCOTT, R.G., PIERSON,R.C. Otc of Special Projects 88/10/21, 15pp. 47900.183-47900 197.
- 8812010359 Roy 0 to Emergency Implementing Procedure EPIP-17, "Emergency Equipmont & Supplies" NOBLET, FORDJR, CAT,N. Tonnossee Valley Authority. 88/11/05. 30pp. 47703:130-47703:159.
- 8812020022 Forwards Rev 20 to physical security/contingoncy ptan.Rev withheld (ref 10CFR73.21). GRBDE-Y,R.L. Tennossoo Valley Authority. 88/11/28. Pocument Control Branch (Document Control Desk). 2pp. 47/21.095.47721:096.
- 8812080167 Forwards Insp Repts 50:327/88-48 & 50:328/88-48 on 881019-25 & notice of violation.Unresolved Item noted.
 MCCOY,F.R. Region 2, Ofc of the Director. 88/11/28. KINGSLEY,O.D. Tennossee
 Valley Authority. 2pp. 47793.053-47793.077.
- -8812080170 Insp Repts 60-327/88-48 & 50-328/88-48 on 881019-25. Violations noted Major areas inspected extended control room observation & operational safety ventication including operations performance sys lineups & safeguards JENISON,K., WATSON,L. Region 2, Ofc of the Director, 88/11/28, 22pp. 47703 056-
- 8812080189 Forwards Insp Ropts 50 327/88-47 & 50-328/88-47 on 881012- 18 Two IIconsee Identified violations & seven unresolved Items Identified.
 MCCOY,F.R. Region 2. Dio of the Director. 88/11/28. KINGSLEY,O.D. Tennessee
 Valley Authority. 2pp. 47755 275-47755 309.
- -8812080190 Insp. Repts 50-327/88-47 & 50-328/88-47 on 881012-19 No violations noted Major areas inspected operations partormance, cys kneups, radiation protection & safeguards & housekeeping inspections. POERTNER, W. Rogion 2, Ofc or the Director. 88/11/28, 24pp. 47755:277-47765:300.
- 8812090046 Ack receipt of 881027 ftr transmitting 1988 plant radiological emergency
- exercise controllers package. MCCOV,F.R. Ote of Special Projects. 88/11/30. KINGSLEY,O.D. Tennessee Valley Authority, 2pp. 47782:359-47782:360.
- 8812120271 Responds to NRC 881108 ltr re violations noted in Insp Repts 50-327/88-46 & 50-328/88-46 Corrective actions like operations personnel assigned to accompany liro watch personnel on patrols to provide requirement guidance. GRIOLEY,R Tennessee Valley Authority. 88/12/95. Document Control Branch (Document Control Desk). 4pp. 47760.193-47780 196.
- 8812120236 Instruction Change Form 88-1419 to Rev 0 to Emergency Plan Implement-ing Procedure EPIP-1, "Emergency Plan Classification Logic." W/881207 ltr. GRIDLEY,R. Tennossee Valley Authority. 88/12/07. 8pp 47785:243-47785:250.

- 8812150103 Responds to NRC 881028 ltr religion items noted in Insp Repts 50 327/ 88 02 & 50 328/68 37 No new util commitments provided to inspector Followup Item 50 327 328/68 37 02 & Unresolved Item 50 327 328/68 37 01 concerning high impodance faults
 GRIDLEY,H. Tennessee Va'ley Authority, 88/12/09, Document Control Branch (Document Control Desk), 3-pp. 47816-356.
- 8812210099 Forwards Int.n Repts 50:327/88 49 & 50:328/88-49 on 881026-1101 Vio-lations noted mot NRC enforcement policy critiqua & therefore no notice of violation MCCOY,F.R. Region 2, Ofc of the Director 88/12/13, KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47876 249-47876 279
- -8812210102 Insp. Repts 50:327/88:49 & 50:328/88:49 on 681028:1101. Violations noted Major areas inspected control room observation & operational safety ventication including operations partormance, satinguards, housekeeping & sys lineup. JENISON, K., WATSON, L. Region 2, Ofc. of the Director. 88/12/08, 29pp. 47876.251-47976.230
- 8912210195 Revised central energency control cir emergency plan implementing procedures including Rev 1 to CECC-EPIP-1,Rov 2 to CECC-EPIP-2,Rev 2 to CECC-EPIP-3,Rev 3 to CECC-EPIP-4, Rev 2 to CECC-EPIP-5 & Rev 2 to CECC-EPIP-7,W/ 881216 Ur MCANALLY, J.L. Tennessee Valley Authority 88/12/16 88pp 47908 304-47907.053.

- 8811300355 Submits followup to 881025 ltr re EPA condensing cooling water intake trash sluce & strainer backwash All samples analyzed contained less than min detectabba amount of total residual chromo SCHMIERBACH,M. Tonnessoe Valley Authority. 88/11/22. SINCLAIR,R.M. Tennessoe, State of 4pp. 47709 003-47709.006
- 8811280048 Generic Ltr 88:20 to all Icansees holding OLs & CPs for nuclear power reactor facilities no individual plant event for suvere accident vulnerabilities Svc list CRUTCHFIELD,D Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47720.024
- 8811300243 Advises that util will shorn t proposed change to Tech Spec Table 3.3-4 to
 - Include logic time delays associated w/ suction transfer of turbine-driven & motor-driven auxiliary fuodwator pumps by 890601,per NRC determination. GRIDLEY,R. Tonnasseo Valley Author ty 88/11/23. Document Control Branch (Docu-ment Control Desk). 3pp. 47677:136-47677.138.
- 8812010240 Forwards salety evaluation supporting titl 881019 response to Generic Lir 83-28 Items 4.2.1 & 4.2.2 re reactor trip sys rehability (preventive maint & surveillance program for reactor trip byteskers) Program for plant acceptable BLACK, S.C. Oft. of Spirical Projects 68/11/28. KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47703 306-47703 312.
- -9812010246 Sefety avaluation accepting program for plant in response to items 4.2.1.
 4.2.2 of Generic Ltr 83-28 no reactor trip systratiophrity
 Ofc of Special Projects 88/11/28 Spp. 47703.308-47703.312.
- 8812010330 Advisos that mods to engineering units,per NRC audit of post-implementa-tion of plant SPOS,may be completed as early as bypassed inoperable status indica-tion sys upgrade,but no later than CRDR clinings. GRIDLEY,R. Tennessee Valley Authority #8711720 Document Control Branch (Docu-ment Control Deak). 2pp. 47710.092-47710.093.
- 8812020177 Summary of 081024 meeting w/ut4 in Hockville,MD ro status of TVA fulfilling commitments made to NRC during restart of plant.Including Phese II programs & Status of next update of plant FSAR.

 DONDHEW,J.N. Old of Special Projects 88/11/29. Old of Special Projects. 21pp. 47722.180-47722.210.
- 8812080088 Advises that Reg Gulde 1.99,Rev 2 methodology has no immediate impact on plant operations per end evaluation of plants for Generic Ltr 88-11, "NRC Position on Radiation Embrittermant of Reactor Vossel Mattle 8 Impact on Plant..."
 GRIDLEYR. Tennossee Varya Authority. 88/11/30 Document Control Branch (Document Control Dosk). 20pp. 47752 203-47752.222
- 8812050198 Application for amonds to Liconsos DPR-77 & DPR-79, consisting of TS Change 88-14, revising Table 3.3-12, "Radioactive Liquid Effluent Monitoring Instrumentation."
 RAY,M.J. Tennesses Valley Authority 88/12/02. Document Control Branch (Document Control Desk). 2pp 47731:205-47731.213
- -8812050203 Proposed Tech Spacs consisting of Tech Spac Change 88:14, changing Table 3.3-12 to clarify essential raw cooling water min channels operable column.

 * Tennossae Velley Authority, 88/12/02, 7pp. 47731:207-47731:213.
- 8812050242 Application for amends to Licenses DPR-77 & DPR-79, consisting of Tech Spec Change 88-42 modifying trip sotpoint & allowable value units for intermediate range nuclear flux detector. Few paid RAY,MJ. Tennesses Valley Authority, 88/12/02. Document Control Branch (Document Control Desk), 3pp. 47731,268-47731,350.
- --8812050247 Proposed Toch Specs Pages 2-8,8 2-4,9/4 3-2 & 3/4 3-5, modifying trip setpoint & allowable value units for intermed-ato range nuclear flux dotector & revising applicability requirements for source range flux dotector.

 *Tonnessee Valley Authority. 88/12/02. 80pp. 47731:271-47731:350
- 8812060055 Application for amends to Licensos DPR-77 & DPR-79, consisting of Tech Spec Change 88-25 Amend modifies action statements for pressure control relief valves to ensure availability for pressure control. Fee paid RAY,M.J. Tennossen Valley Authority. 88/12/02. Document Control Branch (Document Control Desk). 2pp. 47743:144-47743:154.
- -8812060058 Proposed Tech Specs, modifying action statements for pressurzer power
 - operated relief valves Tennessee Valley Authority 88/12/02, 9pp. 47743;146-47743;154.

- 8812060072 Application for amends to Licenses DPR-77 & DPR-79, consisting of Tech Spec Change 88.32 requesting exemption from 10CFR50 App J to allow use of mass point mapped for cardisting containment leakage rates Fee paid RAYM J. Tennessee, Valley Authority, 88/12/02. Document Control Branch (Document Control Desh), 6pp. 47743-048-47743-063.
- -8812060019 Proposed Tech Specs,allowing use of mass point method for calculating containment leakage ratios
 - Tennossee Valley Authority 88/12/02 10pg 47743 054-47743 063
- 8812080145 Provides add into the 881103 request for temporary exemption from administrative provisions of 10CFR50 46 Recommends that util discretionary resources be bottler utilized in directed at operation/maint improvements. GRIDLEY,R. Tennessee Valley Authority, 88/12/05. Document Control Branch (Document Control Desk), 3pp. 47755-238-47755-240.
- 8812080227 Application for amends to Licenses DPR-77 & DPR-79, consisting of Tech Spec Change 85-08 re leak rate test frequency for containment purge supply & exhaust isolation valves Fee paid RAYMJ Tennessee Valley Authority 88/12/05 Document Control Branch (Document Control Osks) 3pp. 47750-283-47751-038
- -8812080229 Proposed Tech Spacs.consisting at Tech Spac Change 88-08 re leak rate test frequency for containment purge supply 8 exhaust isolation valves.

 * Tennessee Valley Authority 88/12/05 75pp 47750 286-47751 038
- 8812120016 Requests us assurance that Generic Lit 88-17 relioss of Dirth during non-power operation being addiessed accordingly unlike response to Generic Lit 87-12 re loss of RHR with a RCS part 4th filted RICHARDSOLIS O
- 8812139279 Forwards Amends 91 & 81 to Licenses DPR-77 & DPR-79, respectively & safety evaluation Amends revise Tech Spec 3/4 9 7 re crane travel over sport fuel pit
- BLACK,S. Of al Special Projects. 88/12/05. WHITE,S.A. Tennessee Valley Authority. 2pp. 47797-298-47797-313.
- -8812130281 Amends 91 & 81 to Licenses DPR-77 & DPR-79, aspectively, fevrsing Tech Spec 3/4 9 7 re crane travel over spent fuel p.t area BLACK, S. Ofc of Special Projects 88/12/05, 9cp. 47797 300-47797 308.
- -8812130282 Safety evaluation supporting Amends 91 & 81 to Licenses DPR-77 &
 - Ofc of Special Projects 88/12/05. Spp. 47797-309-47797.313
- 8912190193 Forwards corrected Amends 91 & 81 to Licenses DPR-77 & DPR-79,re-spectively & safety evaluation.Amends revise Tech Spec Section 3/4.9.7 re crane traval in spart fuel pit area BLACK,5 Ofc of Special Projects. 88/12/05 KINGSLEY,O.D. Tennessee Valley Au-thority 2pp 47855.051-47655.066
- -8812190199 Corrected Amends 91 8 81 to Licenses DPR-77 & DPR-79, respectively, revising Tech Spec Section 3/4 9.7 raicrana travel in spont fue! prl area @LACK_S. Otc of Special Projects 88/12/05. 9pp 47865.053-47855-061.
- -8812190202 Safety evaluation supporting Amends 91 & 81 to Licenses DPR-77 &
- Ofc of Special Projects 88/12/05, 5pp. 47855 062-47865,066
- 8812070237 Application for amends to Licenses DPR-77 & DPR-79, consisting of Tachi Spec Change 88-29-deleting surveillance requirement to demonstrate operability of emergency power supply for pressurtzer PORV & block valves Fee paid RAY_MJ_Tennessee Valley Authority, 86/12/08. Document Control Branch (Docu-ment Control DesN.) 2pp. 47745-333-47745.342
- -8812010240 Proposed Tech Specs re limiting conditions & surve l'anco requirements for RCS relief valves & block valves 1 Tennessee Valley Authority, 88/12/08, 9pp. 47745-335-47745-342.
- 8812070256 Application for amends to Licenses DPR-77 & DPR-79, consisting of Tech Spec Change 88 26,adding tootnote to Spec 3.4.2 for RCS safety valves Fee paid RAY,M.J. Tennessee Valley Authority, 88/12/06. Document Control Branch (Docu-ment Control Desk). 2pp. 47747-63-47747/072
- -8812070267 Pronosed Tech Specs, adding footnote to Spec 3.4.2 for RCS safety 12/06. Spp. 47747.085-47747.072.

- 8811160467 NRC Into Notice 88-091, "Impropor Administration & Control of cal Tests." Such stienct. ROSSIC E. Division of Operational Events Assussment (Post 870411) Consolidated Edison Ca. of New York, Inc. 101pp. 47708.042-47709 142
- 8812010186 Forwards V Stello 881117 ftr to all tall executives re-presence spector at plants,rev to enforcement policy & proposed enforcement action afor mattentiveness at Peach Bottom BLACK, SC Otc of Special Projects. 88711/23 KINGSLEY,O D Tenno-Authority 3pp 47709 258-47709.309
- 8812080139 Ack receipt of 871106.690513 & 1020 lins informing NRC of ste correct violations noted in linsp Repts 50.327787.56 & 50.328767.56 Violated term records per addit info provided in 881020 ft. RICHARDSON,S D. Olic of Special Projects 88711725 KINGS; EY,O () Valloy Authority. 2pp. 47734.358.47734.359
- 8812080167 Forwards Insp Repts 50 327/86-48 & 50-328/88-48 on 881019 of violation Unresolved Item noted. MCCOY,F.R. Ragion 2, Ofc of the Director, 88/11/28. KINGSLEY,O.D. Valley Authority. 2pp. 47793-053-47793-077.
- ~8812080168 Notice of violation from insp. on 881005-11.Violation note landed two electrical leads & portermed test of pump w/o procedures of
 - MCCOY, F.R. Region 2, Olicial the Director, 88/11/28, 1p. 47793 055 47/9
- --6812080176 Insp. Ropis 50:327/88-48 & 50:328/88-48 on 881019-25 noted Major areas inspected extended control room observation & opera vertication including operations performance, sys intopys & Satispiands JENISONIK, WATSONIL Region 2, Ofc of the Director (88/11/28) 22pp 47793 077
- 8812080189 Forwards Insp Repts 50-327/88-47 & 50-328/88-47 on 88101: consec identified violations & soven unresolved items identified MCCOY,F.R. Region 2, Otc. of the Director #8/11/28. KINGSLEY,O D Valley Authority. 2pp 47755-275-47755-300
- -8812080190 Insp. Repts. 50-327/88-47; 8: 50-328/88-47; on: 891012-19.0 noted Major areas inspected operations performance, syst Innups, radialical sategoards. 8: housekeeping insps. JENISON, HUMPHERY, P. POERTNER, W. Region 2, Old of the Directe 24pp. 47755-277-47755-300.
- 8812020265 Forwards not purchase order numbers & dates for suspected p ulti of Class 1E components or sics from Planned Maint System to action ar NRC Into Notice 89-019, "Questionable Confriction of Class 1I BLACK S.C. Ofc of Special Projects 89/11/29, KINGSLEY,O.D. Ferrid Authority, 5pp. 47722 089 47722.073
- 8812080194 Forwards Insp. Repts 50:327/88:45 & 50:328/88:45 on 89092 Islans or deviations noted MCCOY,F.R. Region 2, Ofc of the Director 88/11/30 KINGSLEY.O.D Valley Authority. 2pp. 47754 086-47754 080
- -8812080195 Insp. Repts 50:327788:45 & 50:328788:45 on 880920 28 & 2 talions or deviations noted Major areas inspected shoulder survivaling 6 censee action on previous Insp. Indings. LENARAN, J.J., JAPE, F. Region 2, Old of the Director, 88711722 (8PP 2254-003). 47754 083
- 8811290930 NRC Info Notice 88-993. Telethorapy Events." Svc list oncl CUNNINGHAM,R E. Division of fertustrial & Modical Nuclear Safety (P 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811.10
- 8811290538 NRC Info Notice 88-094, "Potentially Unitorsized Valve Actual ROSSI.C.E. Division of Operational Events Assessment (Post 87041) Consolidated Edison Co. of New York, Inc. 121pp 47708:143-47708:254
- 8812120271 Responds to NRC 881103 ltr to violations noted in Insp. Rept. 46 & 50-328/88-46.Corrective actions for operations personnel assigned
- ny fire watch personnel on patrols to provide requirement girdinice. GRIDLEY, fl. Tennessee Valley Authority, 88/12/05. Document Connot B ment Control Dask), 4pp. 47789:193-47790.199
- 8812020287 NRC Info Notice 80-085, "Insulaquate Procurement Requirem by Ucensees on Vendors". Svc. list end. ROSSIC C. Division of Operational Events, Assessment (Post 670411 Consolidated Edison Co. of Now York, Inc. 112pp. 47807-191-47807.302.
- 8812200347 Ack receipt of 881114 fit informing NRC of steps 185cm to complete fining Repts 50-327788-39 & 50-328788-39.
 MCCOYF.R. Ote of Special Projects 88/12708 KINGSLEY,O.D. Tent Authority. 2pp. 47868-300-47868-301.
- 8812200369 Ack receipt of 881117 itr informing NRC of steps taken to connoted in Insp Repts 65-327/88-40 & 60-328/88-40.
 MCCOV.F R. Olic of Special Projects 88/12/08. KINGSLEY,O.D. Tens Authority. 2pp. 47871.040-47871-041
- 8812210047 Forwards Insp Repts 50-327/88-53 & 50-328/88-53 on 89 ion re failure to follow procedures concerning test procedure caution sinotice issued aince discretionary onforcement criteria met MCCOYF. R. Region 2, Otto of the Director. 88/12/08. KINGSLEY.O. Valley Authority. 2pp. 47876-197-47876-214.
- -8812210053 Insp Repts 50-327/88-53 & 50-328/88-53 on 881104 noted Major areas inspected reactor physics testing LONG AR, WATSON L. Region 2, Dic of the Director 88/12/08, 18p. 478/6-214

88 127 10293 Rocky to MO to discuss apparent deficiencies in actions to prevent &/or mitigate ef-tects of excessive post-trip RCS cooldowns,both past & present.Proposed agenda

enci MCCOY, F.R. Oic of Special Projects. 88/12/08. KINGSLEY, O.D. Tennossee Valuy. Authority. 3pp. 47881,326-47881,328.

- 8812220228 Ack roce pt of 881111 ftr informing NRC of steps taken to correct violations noted in Insp Ropts 50:327788.44 & 50:328788-44 MCCOY, F.R. Otc. of Special Projects. 88712708 KINGSLEY,O.D. Tennessee Valey Authority. 2pp. 47903.041-47003.044
- 8812150103 Responds to NRC 881028 ftr religious noted in Insp Repts 50:3277
 88:02 & 50:328788:37 No new util commitments provided to Inspuctor Followup Item
 50:327,328788:37:02 & Unresolved Item 50:327,328788:37:01 concerning high impedanco fau'is GRIDLEY,fi. Turinosseo Valley Authority. 88/12/09. Document Control Branch (Docu-ment Control Disk.). 3pp. 47816-358-47816-360.
- 8812210099 Forwards hisp Ropts 50-327/88-49 & 50-328/88-49 on 881026- 1101.Volations noted met NRC enforcement policy criteria & therefore no notice of violation will be ssued
- W.B. 98. SSR00 MCCOY,F.R. Region 2, Old of the Director 88/12/13. KINGSLEY,O.D. Tannessee Valley Authority. 2pp. 47876-249-47876-279.
- -6812210102 Insp. Roots 50:327/88:49 & 50:320/88:49 on 081029:1101 Violations roted Major areas Inspected control room observation & operational safety verification, Including operations performance, safety transfeoding & sys Indup JENISON,K., WATSON,I. Reg on 2, Otc. of the Director 88/12/08 29pp 478/76.251-47876.279

R. Periodic operating reports & related correspondence

- 8812080200 "Annual Environ Operating Rept for (I/0915-869914." W/881205 ttr. GRIDLEY,R. Tennossee Valley Authority 88/09/14 9pp 47756:199-47756 205.
- 8811290082 Monthly operating repts for Oct 1988 for Sequeyah Nuclear PlantW/ 881114 Ur. SMITH,S.F. DUPREE,D.C. Tennossed Valley Authority, 80/10/31, 46pp, 47664-286-47664:339

S. Reportable occurrences, LERs & related correspondence

- 8811290110 LER 88-043-00 on 880928 inadequacy of Fro watch patrols, rusulting in noncomptance w/Tech Spec 3.7.12 occurred Caused by tack of adequate mgt oversty's Individual relevand of line watch patrol duty W/881123 ifr NAIK JA, SMITH, SJ Tonnessee Valley Authority 88/11/23 6pp 47667.098-47667.093
- 8811300486 Confirms 881117 conversation on actions taken re-detection of polychlorruted biplionyls in low yol waste treatment pend Suggestion to treat pend contents who chemicals to facilitate collegial and ministron offers promise SCHMERBACH,M. Tomossoc Verloy Authority 88/11/23. STEWART,9.L. Tennessoc, State of .2pp. 47671:310-47671:311.
- 8612070207 LER 89.046-00.ca 881110,Un1.1 containment ventilation isolation occurred due to incateguate test recorder ground strap configuration Containment ventilation isolation resot WRB1201 für RILGORE.B.E. SMITH.S.J. Tonninssie Vallay Authority (18/12/01 6pp. 47746-075-
- 47746.080 • IZVIVIZZE THERE BR 044-00 on BB F10B autostart of turbino driven aux liary fourtwater pump occurred Caused by Irise of seaf injection pressure due to hotwell pumps 1B & 1C tripping. Main feedwater pump trip represent W/B8 (201 tt. LONG, J. L., SMITH, S. J., Tormusson, Valley, Authority, BB/12/01, 6pp. 47745-230-47745-235. 8812070227 LEFF 88 044-99 on 881108 autostart of turbino drivon auxliary foedwater
- 8812200144 LER 88-044-00-on 881100 bulcaratic auxiliary foodwater pump stort signal generated. & auxiliary foodwater pump started. Caused by both mount foodwater pump tripping Main foodwater pump trip signals reset W7881201 ltr.
 LONGJL , SM11H,S.J. Foonossiae Valley Authority, 88712701 Spp. 47862-158-47862-162.
- 8812140248 LER 88-043-04 on 880930 inadequate fire watch patrol resulted in noncom
 - plance w/Tech Spuc 3.7.12 Chased by lack of adequate right oversight for tire watch person of Fire witch patrol recurved warning it W/881208 IIr. NAIK.J.A. SMITH,S.J. Tennossen Valley Authority 88/12/09. 6pp. 47800 318-47800 323.
- 8812210143 LER 89-045-00.on 881118, reactor tripped due to actuation of furbare gen-orator neutral everyolitage protective rolay. Stater bar removed & transported to Wes-traplecise for analysis W7881216 ftr P14:ER,T.K., SMITH,S.J. Termissee Valley Authority 88/12/15 9pp 47877:127-

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8612220116 Forwards Insp Repts 50:327/88-37 & 50:328/88-37 on 880725-28 One un resolved item & three inspector followup items noted Response requested within 30 days of Hr receipt RICHARDSON,S.D. Cir. of Special Projects 88/10/28. WHITE,S.A. Tennessee Valley Authority. 3pp. 47800-180-47800-197.
- --8812220119 Insp Repls 50-327/88-37 & 50-328/88-37 on 880725-28 Unresolved & followup items noted Major areas inspected fire protection & implementation of 10CFR50.App R WESCOTT,RIG Ofc of Special Projects 88/10/21 15pp 47900 183-47900 197.
- 8812010359 Rev 0 to Emergency Implementing Procedure EPIP-17, "Emergency Equipment & Supplies."
 NOBLET, FORD, J.R., CAT,N. Tennessee Valley Authority. 88/11/05 30pp. 47703-130-47703-150

- Forwards nev 20 to physical secunity continuency citin nev with new 10CFR/3 21). GRIOLEY,R.L. Tennossee Valley Authority, 88/11/28. Document Control Branch (Document Control Desk), 2pp. 47721:095-47721.095
 - 8812080167 Forwards Insp Repis 50:327/88-48 & 50:328/88-48 on 881019-25 & notice of violation Unresolved flom noted MCCOY, F.R. Region 2, Olic of the Director, 88/11/28 KINGSLEY,O.D. Tennossia Valloy Authority. 2pp. 47703
 - -8812080170 Insp. Ropts 50-327/88-48 & 50-328/88-48 on 881019-25. Violations noted Major areas inspected extended control room observation & operational safety ventication, including operations performence systimoups & salleguerds. JENISON,K. Region 2, Otc of the Director 88/11/28 22pp 47793 556-47793 077
 - 8812080189 Forwards Insp. Repts 50:327/88-47 & 50:328/88-47 on 881012- 18 Two I-
 - censee identified violations & seven unresolved items identified MCCOY.F.R. Region 2, Otto of the Divector. 88/11/28 KINGSLEY,O.D. Tonnossea Valley Authority. 2pp. 47755-275-47755-300 -8812080190 Insp Repts 50:327/88:47 8 50:328/88:47 on 881012:19 No violations
 - noted Major areas inspected operations performance, sys lineups, radiation protection & safeguards & housekeeping insps JENISON, K., WATSON, I. Reg.on 2, Ofc of the Director 88/11/28, 24pp, 47755 277-47755,300. 8812090046 Ack receipt of 881027 ltr transmitting 1988 plant radiological emergency
 - exercise controllers package:
 MCCOY,F.R. Old of Spackal Projects 88/11/30 KINGSLEY,O.D. Tennessee Valley
 Authority, 2pp. 47782.359-47782.360 8812120271 Responds to NRC 881108 ltr re-violations noted in Insp Repts 50-327/88-
 - 46 & 50 328/88-46 Corrective actions fire operations personnel assigned to accompany fire watch persennel on patrols to provide requirement guidance GRIDLEY,R Tennesseo Valley Authorly 88/12/05 Document Control Branch (Docu-ment Control Dosk) 4pp 47789 193-47789 196.
 - 8812120236 Instruction Change Form 88-1419 to Rev 0 to Emergency Plan Implementing Procedure EPIP-1, "Emergency Plan Classification Logic " W/881207 ltr GRIDLEY,R. Tennessee Valley Authorsy 88/12/07 8pp 47785 243-47785 250.
 - 8812150103 Responds to NRC 881028 ftr re-open items noted in Insp Repts 50-327/ 88-02 & 50-328/88-37 No new util commitments provided to Inspector Followup Item 50-327,328/88-37-02 & Unresolved Item 50-327,328/88-37-01 concerning high Impodance faults.
 GRIDLEY,R. Tennessee Valley Authority. 88/12/09. Document Control Branch (Document Control Dask). 3pp. 47816-358-47816-360.
 - 8812210099 Forwards Insp Repts 50-327/68-49 & 50-328/68-49 on 881026- 1101 Vio lations noted met NRC enforcement policy criteria & therefore no notice of violation
 - will be issued. WCCOY, F.R. Region 2, Ofc of the Director, 88/12/13 KINGSLEY, O.D. Termessee Valley Authority: 2pp. 47876, 249-47876-279
 - --8812210102 Insp. Repts 50:327/88:49 & 50:328/88:49 on 881029-f101. Violations noted Major preas inspected control room observation. & operational safety verification,including operations performance,safegrards,housekeeping & syst...neu JENISON, K. Region 2, Otc. of the Director 88712/08, 28pp. 47870 251-47870 279
 - 8812210195 Revised central emergency control cit emergency plan implementing procedures including Rev 1 to CECC-EPIP-1,Rev 2 to CECC-EPIP-2,Rev 2 to CECC-EPIP-3,Rev 3 to CECC-EPIP-4, Rev 2 to CECC-EPIP-5 & Rriv 2 to CECC-EPIP-7 W/ 881216 Hr. MCANALLY, J.L. Tonnossee Valley Authority. 88/12/16 86pp. 47906 304-47907.053

- 8811300355 Submits followup to 881025 ltr re EPA contlansing cooling water Intake trash sluce & strainer backwash All sumples analyzed contained less than min detectable amount of total residual chilomes. SCHMIERRACH.M. Tennessee Valley Authority. 88/11/22 SINCLAIR.R M. Tennessee, State of. 4pp. 47708 003-47709 006.
- B811280048 Generic Ltr B8:20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident virinerabilities Svc list
- GRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 4/728.303-47729.024
- 8811300243 Advisos that util will submit proposed change to Tech Spec Table 3.3-4 to include togic time delays associated w/ suction transfer of turbne driven & motor-driven auxiliary feedwater pumps by 990601,per NRC determination GRIDLEY,IT Tennessee Valley Authority 86/11/23 Document Control Branch (Document Control Dask) 3pp. 47677:138-47877:138
- 8612010240 Forwards safety evaluation supporting util 861019 response to Gondric Ltr 83-28,floms 4.2.1 & 4.2.2 to reactor trip sys reliability (proventive maint & surveillance program for reactor trip breakers). Program for plant acceptable. BLACK,S.C. Otto 15 Special Projects. 88/11/28 KINGSLEY,O.D Tonnessed Valley Authority. 2pp. 47703-306-47703-312
- -8812010245 Safety evaluation accepting program for plant in response to Items 4.2.1 8.4.2.2 of Generic Ltr 83-28 re reactor trip sys reliability. Ofc of Special Projects. 88/11/28. 5pp. 47703-386-47703.312.
- 8812020244 Forwards Amunid 80 to License DPR-79 & safety evaluation. Amend rolling Surveillance Requirement 4 6 5 1 b.2 to allow one-time extension to next refuel-
- Ing outage for weighing of ice.
 BLACK,S. Ofc of Special Projects 88/11/28 KINGSLEY,O.D. Tecnessou Valley Au thority, 3pp. 47717:184-47717.194.
- -8812020245 Amend 80 to License DPR-79 revising Survollance Requiremen 4.6.5.1.b.2 to allow one time extension to next refueling outage for weighting of Ice BLACK,S. Ofc of Special Projects 88/11/28 5pp 47717:187-47717 191.

- -8812020246 Salety evaluation supporting Amend 80 to License DPR-79
 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/11/28 3pp
- 8812010330 Advises that mode to engineering units per NRC audit of post-implementa-tion of prant SPDS may be completed as early as opposed inoperable status indica-tion sys upgrade but no tarch than CROR changes. GRIDELY H. Ternessee Valley Authority 88/11/29. Document Control Branch (Docu-ment Control Desk). 2pp. 47710.092-47710.093.
- 8812020177 Summary of 881024 meeting w/util in Rock / fo.MD to status of TVA fulfilting commitments made to finite during restant of plantic during Phase II programs 8 status of next update of plant FSAR DONONEMUS NO for of Special Projects 88/11/29 Otc of Special Projects, 21pp 47722190 47722 210
- 8812060086 Advises that Reg Guide 1 93 Rev 2 methodology bas no immediate impact on grant operations per encil evaluation of plants for Generic Ltr 68-11, "NRC Position on Registion Embritishment of Reactor Vessel Matts & Impact on Plant GRIDLEY, Fliennesse Valley Authority 89/11/1/30 Document Centrol Branch (Document Control Dask) 20pp 47/52/203/47752/222
- 8812050198 Application for amends to Licenses DPR-77 & DPR-79, consisting of TS Change 88 14 revising Table 3.3-12, "Radioactive Liquid Efficient Monitoring Instru-
- MAY,M.J. Tennessee Valley Authority, 68/12/02, Document Control Branch (Document Control Desk), 2pp. 47731-205, 47731-213
- -8812050203 Proposed Toch Spocs consisting of Tech Spec Change 88-14, changing Table 3.3-12 to clary, essect at raw cooling water minichannels operable column.
 * Tennessee Valley Authority, 88/12/02, 7pp, 47731.207-47731.213.
- 8812050242 Application for amends to Econises DPR-77 & DPR-79, consisting of Tech 81/200242 Approaches the amoustic compass between a between control recording 88-42 modifying this serious it all above the value units for intermediate range nuclear flux detector Fee pad.

 RAY,M. J. Tennessee Valley Authority 88/12/02 Document Control Branch (Document Control Boss), 350-47731-258-47731-350.
- -8812050247 Proposed Tech Specs Pagos 2-6.8 2-4.3/4 3-2 & 3/4 3-5, modifying Inp selpoint & allowable value units for intermediate range nuclear flux defector & revising applicability requirements for source range flux defector. *Tennessee Vatrey Authority 88/12/02 80pp 47731-271-47731:350.
- 8812050289 Application for amend to License OPR-78,consisting of Tech Spec Change 88-33 revsing upper head injection level switch setpoint & tolorances of survollance requirement Foe paid
- RAY,M.J. Faceasse Valley Authority 89/12/02 Document Control Brench (Document Control Dask) 3cp 47730 243-47730 260.
- -8812050291 Proposed Tech Specs consisting at Tech Spec Change 88-03, revising upper head injection level switch setupint 8 follerances of survertance requirement 8 heat flux hot channel factor of firmting condition for operation. *Tennessee Valley Authority 68/12/02, 15pp. 47730,246-47730,260
- 8812060055 Application for amends to Licenses DPR-77 8 DPR-79, consisting of Tech Spec Change 88-25 Amend modifies action statements for pressunzer power-operated telies valves to ensure availability for pressure control Fee pard RAY.M.J. Tennesses Valley Authority, 88/12/202 Document Control Branch (Document Control Desk), 2pp. 47743-144-47743-154.
- -8812060058 Proposed Tech Speca modifying action statements for pressurizor poweroperated relief valves
 Tennessee Valley Authority, 88/12/02, 9pp. 47743,148-47743,154
- 8812060072 Application for amends to Liconses DPR-77 & DPR-79, consisting of Tech Spec Change 88-32 requesting exemption from 10CFR50,App J to allow use of mass port method for calculating containment leakage rates Fee paid RAY,M J Tennessee Verlay Authority 88/12/02 Document Control Brench (Document Control Besk) 6p. 47743 048-17743 059
- -8812060079 Proposed Tech Specse uwing use of mass point method for calculating containment ladkage ratas. *Tennessee Valley Authority 89/12/02, 10pp 47743-054-47743-080.
- 8812080145 Provides add, into re 891103 request for temporary exemption from administrative provisions of 10CFR50 46 Recommends that util discretionary resources be better utilized if directed at operation/maint improvements.

 GRIDLEY, R. Tennesse Valloy Authority, 88/12/05. Document Control Branch (Document Control Desk), 3pp. 47755-238-47755-240.
- 8812080227 Application for amends to Licenses DPR-77 & DPR-79, consisting of Tech Spec Change 88-06 re leak rate test frequency for containment purge supply & exhaust isolation varies Fee paid.

 RAY.M.J. Tennessee Valley Authority 88/12/05 Document Control Branch (Document Control Desk) 3pp. 47750 283-47751 038
- -8812080229 Proposed Tech Space consisting of Tech Spec Change 88-06 re leak rate test frequency for containment purge supply & chaust isolation viewes. * Tennessee Valley Authority 88/12/05 75pp 47750 296 47751-038
- 8812120016 Requests util assurance that Generic Ltr 88-17 re loss of DHR duting non-power operation being addressed accordingly unline response to Generic Ltr 87-12 re loss of RHR white RCS partially filled. RICHARDSON.S.D. Of of Special Projects 88/12/05 KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47789 153-47789 154.
- 8812130279 Forward's Amends 91 & 81 to Licenses DPR-77 & DPR-79, respectively & safety evaluation Amenda revise Tech Spec 3/4 9.7 re crane travel over spent fuel cit BLACK,S Ofc of Special Projects 88/12/05 WHITE,S A. Tennessee Valley Authority. 2pp. 47797:298-47797.313
- -8812190281 Amends 91 8 81 to Licenses DPR-77 8 DPR-79 respectively, revising Tech Spec 3/4 9 7 re crane travel over spent fuel pit area BLACKS Ofc of Special Projects 88/12/05 9pp. 47797.300 47797:308.
- -8812130282 Salary evaluation supporting Amends 91 8 81 to Licenses CPR-77 8 DPR-78 respectively.

 ' Ote of Special Projects 88/12/05 5pp. 47797:309-47797:313.

- 8812190193 Forwards corrected Amends 91 & 81 to Licensos DPR-77 & DPR-781e, specially 8 safety evaluation Amends revise Tech Spec Section 3/4.9.7 to crangitive! In spent fuel bit area BLACK, 5 Ofc of Special Projects 88/12/05 KINGSLEY,O D. Tonnessee Valley A; thority 2pp 47855 051-47855 086
- -8812190199 Corrected Amends 91 & 81 to Licenses DPR-77 & GPR-76, respectively, revising Tech Spec Section 374.9.7 to crains travel in spent first pit sits BLACK.S Otc of Special Projects 88/12/05 9pp 47855-053-47855.061.
- -8812190202 Safety evaluation supporting Amends 01 & 01 to Licenses DPR-77 & CPR-79 respectively.
 **Ofc of Special Projects 88/12/05 Spp. 47855.062-47855.066
- 8812070237 Application for amends to Licensus DPR-77 & UPR-79, consisting of lack Spec Change 88-29,dotoring surveillance requirement to identifiate operating of emergency power supply for pressuriser PORV & block valives. Fee paid RAY,M.J. Tennessee Valley Authority 89/12/26 Document Control Branch (Decument Control Desk) 2pp. 47745-333-47745-342.
- -8812070240 Proposed Tech Specs re limiting conditions & surveillance requirements for ACS rollef valves & block valves Ternesses Valley Authority, 88/12/08, 9pp. 47745-335-47745-342
- 8812070256 Application for amends to Uconsos DPR-77 & DPR-79, consisting of face Spec Change 88-26.adding foolnote to Spec 3.4.2 for RCS safety valves Fee ps4 RAY,M.J. Tennessee Valley Authority 88/17/06 Document Control Branch (Document Control Dask) 2pp 4/747-063-4/747-072.
- -8612070257 Proposed Tech Specs, adding footnote to Spec 3.4.2 for RCS safety valves * Tennessee Valley Authority, 88/12/06, 8pp. 47747-065-47747-072
- 8812140165 Responds to Generic Ltr 89-11 re-radiation ombrittloment of reactor vessel matis & impact on plant operations using methodology in flev 2 to Reg Guide 103 GRIDLEY,R Tennessee Valley Authority 88/12/09 Document Control Branch (Document Control Desk), 6pp. 47800 206 47800 212.
- 8812270210 Summarizes NRC sentor mgt 881200.07 ineetings to rewow of performance of operating nuclear power plants Econsed by NRC Public monthing schoolured for 881221 to review results of tatest mooting of MMR managers.

 STELLOY. Of of the Executive Director for Operations. 88/12/18. KINGSLEY,OD Technossee Valley Authority. 3pp. 47926;273:47926;275.
- Q. Inspection reports, IE Bulletins & correspondence

47900 197

- 8912220116 Forwards Insp Repts 50-327/88-37 & 50-328/88-37 on 860725-28 One unresolved item & three inspector followup Items inotal Response requested within 30 days of it roce pt. RICHARDSON 5.D. Ofc of Special Projects. 88/10/28 WHITE,S.A. Tennessee Valley Authority. 3pp. 47800:180-47800.197.
- ~8812220119 Insp Ropis 50:327/88:37 & 50:328/88:37 on 880725:28. Unresolved & followup idems noted Major areas inspected fire protection & implementation of IOCFRSO App R. WESCOTT, R.G., PIERSON, R.C. Otc. of Special Projects. 88/10/21. 15pp. 47800:183-
- 8811160211 NAC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear " Svc list encl Gauges Svc list entit CUNNINGHAM.R.E. Division of Industrial & Modical Nuclear Safety (Post 870729) 68/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255 47708:257
- 8811180467 NAC Info Notice 88-091, "Improper Administration & Control of Psycholog
- cal Tests." Svc list and ROSSICE Dwiston of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, inc. 101pp. 47708 042-47708:142
- 8812010188 Forwards V Stello 881117 ftr to all util executives re-presence of NRC in spector at plants, revito enforcement policy & proposed enforcement actions for operator inattentiveness at Paach Bottom.

 BLACK, S.C. Ofte of Special Projects 88/11/23 KINGSLEY, O.D. Tonnessee Valley Authority. 3pp. 47708.268-47709:309.
- 8812060139 Ack recorpt of 871106,880513 & 1020 litrs informing NRC of steps taken to correct violations noted in Insp. Repts 50:327/87-56 & 50:328/87-56 Vrotation B deleted from records.per add into provided in 881020 lfr.
 RICHARDSON,S.D. Ofc of Spacral Projects. 88/11/25 KINGSLEY,O.D. Termessod Valley Authority. 2pp. 47734:358-47734.358.
- 8812080167 Forwards Insp Repts 50-327/88-48 & 50-328/88-48 on 881019-25 & notice of violation Unresolved itom noted.

 MCCOY.F.R. Region 2, Ofc of the Director, 88/11/28, KINGSLEY,O.D. Tennessee
 Veiley Authority, 2pp. 47793-053-47793.077.
- -8812090168 Notice of violation from map on 881005.11.Violation noted transcet landed two electrical teads & performed test of pump w/o procedures or adequate MCCOY,F.R. Region 2, Ofc of the Director, 88/11/28, 1p. 47793.055-47793.055.
- -8812080170 Insp Repts 50.327/88-48 & 50.328/88-48 on 881019-25. Violations noted Major areas Inspected extended control room observation & operational safety vortification.including operations portormance, sys tineups & safeguards. JENISON K., WATSON,L. Region 2, Oic of the Director. 88/11/28, 22pp. 47793-056-47793-077.
- 6012080169 Forwards Insp Repts 50:327/88-47 & 50:328/88-47 on 861012-18 Two fi-censor Identified Violations & seven unresolved items Identified MCCQV_FR. Region 2. Oit. of the Director. 88/11/28. KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47755:275-47755:300.

-8812080190 Insp Repts 50-327/88-47 & 50-328/88-47 on 881012-19.No violations noted Major areas inspected operations performance, sys lineups, radiation protection & sateguards & housekeeping inspa. JENISON,K., HUMPHREY,P., POFRINER,W. Region 2, Cit. of the Oractor 88/11/28, 24pp. 47755 277-47755 3tio.

- 8812020255 Forwards ref purchase order numbers & dates for suspected purchases by util of Class, 1E components or sixes from Planned Maint Systinc for appropriate action per NRC into Notice 88,019, "Questionable Certification of Class 1E...." BLACK,S.C. Ofc. of Special Projects, 88/11/29, KINGSLEY,O.D. Tennossee Valley Authority, 5pp. 47722,069,47722,073.
- 8812080194 Forwards Insp Ropts 50-327/88-45 & 50-328/88-45 on 880920- 28 No vio *at nns or deviations noted MCCOY,F.R. Royion 2, Otc of the Director, 88/11/30, KINGSLEY,O.D. Termassee Velley Authority, 2pp. 47754 086-47754 093.
- ~8812080195 Insp Fiepts 50-327788-45 & 50-328788-45 on 800920-28 & 27-28. No vio Tations or deviations noted Major areas inspected, studber surveillance program & In-cersee action on previous insp. findings. LERIAHENJJ., JAPE,F. Region 2, Ote on the Director 88/11/22 6pp. 47754-088-

47764.093

- 8611290030 NRC Info Notice 86:093, "Teletherapy Events" Svc list encl. CUNNINGFRAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list
- enct ROSSLC E Division of Operational Events Assessment (Post 870411): 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708-143-47708-254).
- 8612120271 Responds to NRC 881108 ftr re-violations noted in Insp Repts 50:322786-46 & 50:328788-46 Corrective actions fire operations personal assigned to accompany fre-watch personal on patients to provide produtement guidance GRIDLEY,R Terriossee Valley Authority, 88712705 Decument Control Branch (Document Control Dosk), 4pp. 47789:198-47789:198
- 8812020287 NRC Info Notice (18-095, "Inadequate Promitement Requirements Imposed by Licensens on Venders" Svollist encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302
- 8812200347 Ack recept of 8811.14 fir Informing NRC of steps taken to correct violations noted in Irisp Repts 50:327788:39 & 50:328788:39.

 MCCOY,F.R. Ofe of Special Projects 88712708 KINGSLEY,O.D. Innressee Valley Authority, 2pp. 47868:300-47868:301.
- 8812200369 Ack receipt of 881117 fir informing NRC of steps taken to correct violations noted in Insp. Repris 55:327788-40 & 50-328788-40. MCCOY,F.T. Oto. of. Special Projects. 88712708. KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47871.040-47871.041.
- 8812210047 Forwards Insp. Repts 60:327/88-53 & 50:328/88-53 on 881104-12.Violation re-feture to follow procedures concerning tost procedure cantion steps noted No notice issued since discretionary enforcement critina met MCCOY,F.R. Regent 2, Oto of the Director, 88/12/08. KINGSLEY,O D. Fonnessee Valloy Authority, 2pp. 47876:197-47876.214.
- -6812210053 Insp Repts 50:327/88:53 & 50:328/88:53 on 881104:12, Violation noted Major gross inspected reactor physics testing
 LONG,A.R., WATSON,L. Region 2, Otc of the Director 88/12/08, 16pp. 47876.199-47876 214.
- 8812210293 Confirms 881206 telcon re-enforcement conference on 881219 in Rockvillo,MD to discuss apparent deficiencies in actions to provent &/or mitigate effocts of excessive post-trip RCS controwns,both pest & present.

MCCOY,F.R. Ofc of Special Projects 88/12/08. KINGSLEY,O.D. Tennossae Valley Authority. 3pp. 47881-326-47881-328

- 8812220226 Ack receipt of 881111 ftr informing NRC of steps taken to correct violations noted in Insp Repts 50-327788-44 & 50-328788-44 MCCOY,F.R. Ofc of Special Projects 88712708 KINGSLEY,O.D. Tennassee Valley Authority. 2pp. 47903-041-47903-044.
- 8812150103 Responds to NRC 881028 lit re open liems noted in Insp Repts 50:3277 88:02 & 50:326/88:37 No now util commitments provided to Inspector Followup liem 50:327,328/89:37-02 & Unrosolived item 50:327,328/89:37-01 concerning high lim-

pedance faults. GRIDLEY,R. Tennessee Valley Authority. 88/12/09. Document Control Branch (Document Control Desk.) 3pp. 47816.358-47816.360.

- 8812210099 Forwards Irisp Repts 50-327/88-49 & 50-328/88-49 on 881026- 1101.Violations noted met NRC enforcement policy criteria & therefore no notice of violation wi'l be issued
- MCCOY,F.R. Region 2, Ofc of the Director, 88/12/13, KINGSLEY,O.D. Tennessoo Valley Authority, 2pp. 47876;249-47876;279.
- -8812210102 Insp Repts 50-327/88-49 & 50-328/88-49 on 881029-1101, Violations noted Major areas inspected control room observation & operational safety varification including operations performance safeguards housekeeping & sys fineup. JENISON,K. WATSON,L Region 2, Otc of the Director 86/12/08. 29pp 47876:251-47876:279

Fl. Periodic operating reports & related correspondence

- 8812080200 "Annual Environ Operating Rept for 870915-880914." W/881205 ltr. GRIDLEY,R. Tennessee Valloy Authority. 88/09/14. Bpp. 47756.190-47756.205.
- 8811290082 Monthly operating repts for Oct 1988 for Sequoyah Nuclear Plant W/ 881114 Nr. SMITH, S.J., DUPREE, D.C. Tonnessee Valley Authority, 88/10/31, 46pp. 47684.286-47664 339

S. Reportable occurrences, LERs & related correspondence

- 8811380486 Confirms 681117 conversation on actions taken re-detection of polychlorinated by heavis in low yol waste treatment point. Suggestion to treat point contents who cliomicals to facilitate colloidal sed monitation offers promise SCHMERBACH MITCHMESSON Valloy Authority 88/11/23 STEWART, PL Tennesson, State of 2pp 47671/310 47671/311.
- 8812070223 LER 88 010 02 on 871221,electroinagnetic interference caused spurious high rad at on spikes resulting in two containment ventilation isolations Caused by electromagnetic interference in rad ation monitor cables W/881201 ltr.
- SMITH,S.J. Tennessee Valley Authority. 8B/12/01 8pp 47746:001-47746.006
- 8812070226 LER 87-003-02 on 871205,etectromagnetic interference caused spurious high radiation spikes resulting in two contaminent ventilation isolations Sampte gas profilter replacement increased from crico every 24 h to every 4 h W/881201 ftr. NAIK, J. S. SMITH, S. J. Ternessee Valley Authority. 88/12/01. Spp. 47747:117-47747:121
- 8812070230 LER 67-008-03 on 871127 containment ventilation isolation occurred due to spurious high radiation spike Caused by efectromagnets into lenerce in cab'es Design changes to todine & particulate alaim circuit implemented W/881201 ltr.
 NAIK.J.A., SMITH,S.J., Tennessee Valley Authority 88/12/01, 7pp 47746:256-47746 262
- 8812200061 LER 87-010-02 on 881221,two containment ventilation (solutions occurred due to spurious high radiation spikos Caused by electromagnetic interference generated. Design charigos implemented W/881201 ltr. NAIK.J.A., SMITH.S.J. Tennesseo Valley Authority. 88/12/01. 6pp. 47862-190-47862-195.
- 8812200151 LER 87-009-02 on 871205,two containment ventilation isolations occurred Caused by electromagnetic interference induced to radiation monitor delector cable Design changes implemented W/881201 ltr.
 NAIK_JA, SMITH.S J. Fennessee Valley Authurity. 68/12/01. 5pp. 47864:311-47864:315
- 8812140246 LEB 88-040-00 on 881117.containment vontilation Isolation (CVI) occurred Cause attributed to power failure to lower containment air monitor gaseous channel Operations personnel verified that CVI not result of high radiation W7881208 NAIK.J.A., SMITH,S.J. Tennossee Valley Authority 88/12/08 5pp 47814:176-47814:180.
- 8812140250 LER 88-039-00 on 881109, Train B containment ventilation isolation occurred Caused by Incomplete labeling of terminals & wires on terminal block Design change to rowing forminations in panel O-M-12 to be important of W/88128 if FENNIKY. SMITH, SJ Tannessee Varioy Authority 88/12/08 6pp 47602.270-

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8811280048 Generic Ltr 88-20 to all licensons holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Syc list CHUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.

Q. Inspection reports, IE Bullatins & correspondence

- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Suc list onct CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729): 88111722 Consolidated Edison Co. of New York, Inc. 99pp. 47708.255-47708.257.
- 8811160467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Tests" Svc list and.
 ROSSIC.E. Division of Operational Events Assessment (Post 870411), 88/11/22, Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708.142.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Evants" Svc list encl. CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 670729), 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Svc list
- enct.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02.

 Consolidated Edison Co. of New York, Inc. 121pp 47708 143-47708.254.
- 6812020287 NRC Into Notice 88-005, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svo list enct.

 ROSSI,C E. Division of Operational Events Assessment (Post 870411) 88/12/08.

 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.

S. Reportable occurrences, LERs & related correspondence

8812200139 PNO-III 88-101 on 881207 util & Bechtel announced signing of agroements for jointly owned company to acquire facility & to resolve outstanding claims associated w/Midland Nuclear Plant const project State of MI will be informed. BURGESS,B., AXELSON,W. Region 3, Old of the Director, 88, 12/08, 1p. 47870 340-47870 340.

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8811280048 Genero Ltt 83 20 to attiliconsees holding OLs & CPs for nuclear power reactor fact tes ra individual plant exam for severe accident vulnerabilities Svo I st CRUTCHFIELD.D. Associate Director for Projects (Post 870411) 88/11/23. Consolidated Edison Co. of flew York, Inc. 81pp. 47728 303 47729 024.

O. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Syc List enct CUNNINGHAM R.E. Dryson of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22 Conscidated Edison Co of New York, Inc. 99cp. 47708 255-47708 257
- 8811160467 NRC Into Notice 88 091, "Improper Administration & Control of Psychological Control of Control of Control of Psychological Control of Control of Control of Control of Control of Control cal Tests: Swithst end: RCSSICE Dinsion of Operational Events Assessment (Post 870411) 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47/08.042-47/08.142
- 8811290030 NRC Into Notice 88:093 "To'etherapy Events " Svc list encl CUNNINGHAMIRE Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811 103:47811:215
- 8811290538 NRC Into Notice 88:094, "Potentially Undersized Valve Actuators." Svc 1st ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143 47708 254
- 8812020287 NRC Into Notice 88:095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" Svollist end. ROSSICE Division of Operational Events Assossment (Post 870411) 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807.302

8. Reportable occurrences, LERs & related correspondence

8812200139 PNO-III-68-101 on 881207 unit & Bechtel announced signing of agraements for jonity owned company to accure facility & to resolve outstanding claims associated with dand Nuclear Plant const project State of Mil will be informed BURGESS,B Region 3, Otc of the Director, 88/12/08, 1p. 47870,349-47870,340

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F. Security, medical, emergency & fire protection plans

- 8812020224 Rev 13 to Emergency Plan Implementing Procedure EPiP 1.2 & revised corpotate plan implementing procedures/including Rev 8 to CPIP 1.2 Rev 4 to CPIP 1.4 Revs 3 to CPIP 4.3 & 5.1 & Rev 7 to CPIP 5.2 W/881114 ltr. SWAILS.S.L. Iowa Electric Light & Power Co 88/11/14 136pp 47718.071
- 8812130044 Forwards Emergency Operating Procedure (EOP) Insp Rept 50:331/89:200 on 890801-12 Executive summary encligiving overview of insp findings in each area reviewed Response w/ firm commitment for issuing revised EOPs requested HOLAHANIG, Division of Reactor Projects IdJV, V & Special Projects | Post 870411), 88/12/02, UIU, L. Iowa Electric Light & Power Co. 6pp | 47792 159 47792:192
- -8812130046 Emergency Operating Procedure Insp. Rept. 50-331/88 20 on. 880801-12 No. violations inoted Major lareas inspected licensee program for implementing emergency operating procedures as required by NUREG-0737, Suppl. 1. DYER, E., SMITH, D. HALL, JP. Division of Reactor Inspection & Safeguards (Post 870411), 88/11/22, 28pp. 47792,165-47792,192.
- 8812210387 Ack receipt of 880923 Rev 8 to Duana Arnold Energy Ctr emergency plan Rev consistent w/10CFR50 54(g) & acceptable. GREGER,LR Region 3, Oft of the Director. 88/12/14, LIU,L towa Electric Light & Power Co. 2pp. 47881-324-47881-325.

H. General correspondence

8812050089 Comment on proposed rule 10CFR26 relitiness for duty program Detailed comments on rule encl.

ROTHERT, W.C. Iowa Electric Light & Power Co. 88/11/29, CHILK, S.J. Office of the Secretary of the Commission. 4pp. 47695 335-47695 338.

P. Operating ficense stage documents & correspondence

- 8812010123 Forwards Amend 154 to License OPR-49 & safety evaluation. Amend revises Tech Spec to reflect new core loading for Cycle 10 operation. HALLJR. Project Directorate III-3: 88/11/22; LTD,L. Iowa Electric Light & Power Co. 3pp. 47699;340-47699 356.
- -8812010124 Amend 154 to License DPR-49, revising Tech Specs to reliect new core loading Cycle 10 operation HANNON,J N. Project Directorate (II-3 88/11/22, 9pp. 47699 343-47699.351.
- -8812010127 Sately evaluation supporting Amend 154 to Ucense DPR-48.
 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/11/22. 5pp. 47699 352-47699 358.
- 8811260048 Generic Ltr 68-20 to all Icensees holding OLs & CPs for nuclear power reactor facilities in individual plant exam for severe accident vulnerabilities Svc list enci. CRUTCHFIELD.D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729-024.

- 8811290424 Responds to WC Rothert 881031 Ltrito AB Davis relatingation by utilemployees Concurs w/Leenson findings that offergations unsubstan GREENMANLE G. Region 3, Oto 01 the Dilector, 88/117/3 LtD.L. loward Co. 1p. 47657:325-47657-325
- 8812010211 Forwards Aircoid 155 to License DPR-49 8 shfety evaluated vises Tech Spots to reflect improvements in accident monitoring in made as part of util DCRDR program long term enhancements. HALL 18 Project Drectorate III-3 89/11/30 LIU/L lowe Electric Light 2pp 47702 328-47702 342
- -8812010213 Amend 155 to License DPR 49 revising Tables 3.2-F,3.2-I Tech Specia to reflect proper ranges suiver/ance requirements & nomeno tainment water level & pressure/tunis water level & pressure/tunis water level & lemp instrumentation HANNON, IN Project Directorate III-3 89/11/30 0pp 47/02 330-4/702
- -8812010216 Safety evaluation supporting Amond 155 to Dictinse DFR-49
 * Office of Nuclear Reactor Regulation, Director (Post 870411) 89
 47702 339 47702 342
- 8812090164 Forwards Amond 156 to Liconse OPR-49 & safety evaluation vises Tech Specs by changing selpoint for uninterrupt blocine. & instrume devoltage relays to reliect mod of power supplies per Roy Guide 1 97 HALL J.R. Project Directorate III-3, 89/12/07, LIU,L. towar Efective Light 3pp. 47781-332-47781-344.
- -8812090167 Amend 156 to License DPR-49, revising Tech Spacs by points for uninterruphible ac & instrument ac sys undervoltage relays to sys power supplies to conform to Reg Giddle 1.97
 HANKON, J N Project Directorate III-3. 88/12/07, 7pp. 47781 335-47781
- -8812090169 Safety evaluation supporting Amond 156 to License DPR-49
 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88 47781.342-47781 344.

Q. Inspection reports, IE Builetins & correspondence

- 8812020182 Forwards Safety Insp. Rept. 50:331/88-19 on 880906-10. AXELSON W.L. Region 3, Ofc of the Orector, 88/11/17, LIU,L. lowe & Power Co. 2pp. 47722 093-47722:113
- -8812020183 Insp. Rept. 50. 331788-19 on 880306-1031 Violation indial Inspected followop of core insp. modula, corrective actions for develors, onsite followup of events at operating power reacture. & m. JACKIW,I N. Region 3, Ofc of the Director, 88/11/16, 19pp. 47722 095-4
- 8811300502 Responds to notice of violation & proposed triposition of o amount of \$50,000 Corrective actions util has taken steps to proclude: too of unqualitied butt spices in circuits per 10CFH50.49

 ROTHERT W.C lowe Electric Light & Power Co. 88/11/21 LIEBERMAN forcement (Post 870413). 8pp. 47676-105-47670.110.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Indu Gauges" Svc fist enct. CUNNINGHAMR E. Division of Industrial 8 Medical Nuclear Safety (88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708.255
- 8811180467 NRC Into Notice 88-091, "Improper Administration & Control cal Tests." Svc list encl.
 ROSSICE Division of Operational Events Assessment (Post 87041 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708:142
- 8811300007 Forwards "Duane Arnold Energy Ctr Safety Sys Functional In MOTHERT,W.C. lowa Electric Light & Power Co. 88/11/22 DAVIS,A.B. of the Director. 2pp. 47681.065-47681;122.
- -8811300009 "Duane Arnold Energy Cir Safety Sys Functional Insp HPCI ERC International, Inc. 88/10/03, 56pp. 47681:067-47681.122.
- 8812020145 Forwards Safety Insp Rept 50-331/88-25 on 881010-13 & 24 tions noted. AXELSON,W.L. Region 3, Ofc of the Director, 88/11/22, LIU,L. towa E Power Co. 2pp. 47710.338-47710.344.
- -8812020148 Insp. Rept. 50-331/88-25 on #81010-13 & 1024-28 noted Major areas Inspected QA program implementation & Licensee 81 capabiliy. SCHRUM,D.L., JACKIW,I.N. Region 3, Ofc of the Director, 88/11/22, 7; 47710.344
- 8812010017 Documents results of visual exam of core spray spargers po current refueling outage,per IE Bulletin 80-13. ROTHERT,W.C. lowa Electric Light 8 Power Co 68/11/23. DAVIS,A.B. of the Director. 2pp. 47702:306-47702:307.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc fist encl. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety e 88/12/02, Consolidated Edison Co. of New York, Inc. 112pp. 47611:1
- 8811290538 NRC Info Notice 86-094, "Potentially Undersized Valve Actu enci. ROSSI.C.E. Division of Operational Events Assessment (Post 8704) Consolidated Edison Co. of New York, Inc. 121pp 47708:143-47708.25
- 8812130044 Forwards Emergency Operating Procedure (EOP) Insp Rept on 880801-12 Executive summary encl giving overview of insp finding reviewed Response w/ firm commitments for Issuing reviewed EOPs requ HOLAHAN,G Division of Reactor Projects III,VV, V & Special Projects 88/12/02. LIUL, towa Electric Light & Power Co. 6pp. 47792-159-4779:

12 No. violations indeed Major larges inspection. Consolo program for implementing emergency operating procedures as required by NUREG-0737, Suppl. 1. DYER, J.E., SMITH, J.D., HALL, J.R. Division of Reactor Inspection & Safeguards (Post 870411) 88/11/22 28pp. 47792-165-47792-192

- 8812130011 Ack recept of paymont for civil penalty imposed by NRC on 881021 in amount of \$50,000 Corrective actions will be examined during future insp. LIEBERMANUL Oft. of Enforcement (Post 670413) 88/12/06. LULL lower Electric Light & Power Co. Ip. 47792 133-47792 133
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensess on Vendors" Svc list encl POSSI, CE. Dusich of Operational Events Assessment (Post 870411), 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807-302.
- 8612200215 Concludes that Cycle 9/10 refueling outage wolld insps performed to meet guidelines of Gonoric Lir 88:01 & other applicable NRC acceptance cutoria Finding contingent upon approval of request for deterral of msp of addit RWCU we'ds HALL JR Project Directorate III:3 88/12/15. LIU,L Towa Electric Light & Power Co 4pp. 47868.356.47868.359
- 8812210032 Approves util 881021 request for relief from inspecting 92 RCWU wolds for IGSCC during Cycle 9/10 refueling outage thisp can be deferred until next refueling HANNON, J.N. Project Directorate III-3, 88/12/15, LtU,L. Iowa Electric Light & Power Co. 3pp. 47880.266-47880.268

S. Reportable occurrences, LERs & related correspondence

- 8812230153 LER 80:007:00 on 880706, difficulty experienced when attempt made to re-calibr standby emergency deset generator sys. Caused by high 8 low switches being improperly assembled by milg. Personnel corrected assembly deliciency. W/880817 lir SMITH, B.K., TIANNEN, R.L. towa Electric Light & Power Co. 88/08/17. 8pp. 47911:078 47911.085
- 8811290564 LER 88-016-00 on 881018, discovered several ESF actuations occurred when one 4160 essential bus was inadvertently de-energized Cause by matioquate dosign of degraded voltage delection circuit Automatic actuations reset W/881118 ltr SMITH, BK, HANNEN, RL towa Etectric Light & Power Co. 88/11/16 DAVIS, A.B. Region 3, Otc of the Director 8pp 47683.046-47663.053.
- 8812020210 LER 88-013-00 on 881026, spurious actuation of Yanway level switch com-trined w/actuation of second level switch resulting in actuation of core spray & emer-goncy diesel generator. Caused by improper sealing of switch.W/861125 ltr. PRO8ST,J.R., HANNEN,R.L. lowe Electric Hight & Power Co. 88/11/25. DAVIS,A & Region 3, Old of the Director. 11pp. 47718:350-47718-360
- 8812070250 LER 88-018-01 on 881017,ESF actuation & loss of assential bus due to imadequate degraded voltage detection logic design. Caused by incorrect operator action & inadequate design of degraded voltage detection crewt. W/881129 ltr. SMITILB K., HANNEN,R C. lowa Electric Light & Power Co. 89/11/29. 8pp 47745-222-47745-229.
- 8812140232 LER 88-017-00.on 881106,plant shut down for Cycle 9/10 refuel outage when primary containment isolation sys half Group III ("B" side) isolation recorded Caused by fative of normally energized refay (GE CR120A) W/881205 III AXLINE, J.S., IANNEN, R.L. lowa Electric Light & Power Co 88/12/05. 4pp. 47800.330-47800.333
- 8812140044 PNO-III-88-998 on 881121,pinholo leaks in control rod drive hydrautic tries identified.Caused by chloride externally induced stress corrosion cracking Leaking hydrautic tries removed & repracements planned.

 DANIELSON,D. HARRISON,J. Region 3, Otc of the Director. 88/12/06. 1p. 47797:220-47797:220.
- 8812140254 LER 88-018-00 on 881018 teactor protection sys Imp & Group I through V so alions received Casued by apparent spurious signed within electrical protection assembly breaker concurrent w/survariance testing W/881207 ltr. AXLINE_US, HANKEN,RL. Iowa Electric Light & Power Co. 88/12/07. DAVIS,A B Roglon 3, Old of the Director. 4pp. 47821-057-47821-060.

DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

8812200073 Forwards response to NRC 881116 ftr re violations noted in insp on 880026-30 Enct withheld (ref IOCFR73.21). CONVERSE, R.J. New York Power Authority (formerly Power Authority of the State of New York). 88712714. Document Control Branch (Document Control Dosk). 1p. 47801:058 47861:058

H. General correspondence

8812010423 Comment on proposed rule 10CFR26 re Fitness for Duty Program Util has constitutional concerns re proposed random tosting which shou'd be fully addressed prior to rule being promulgated Endorses NUMARC & EEI comments. BRONS_JC. Now York Power Authority (formerly Power Authority of the State of New York). 88/11/18. Docketing & Services Branch. 12pp. 47679:292-47679:303.

P. Operating license stage documents & correspondence

- 8811230192 Grants temporary waiver of compliance from Tech Spec Surveillance Tests 4.7.A.2.a (10) & 4.7.A.2.per 881109 request re integrated leak rate tests. BOGER, B.A. Assistant Director for Region I Heactors. 88/11/18. BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 6pp. 47657:243-47657:248.
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024.

termination & opportunity to hearing to ast trus frequents to eliminate primary containment leak rate less required by Tech Speec during 1988 refueing outlage. LABARGE, D.E. Project Directorate 1-1. 88/11/29. BRICNS, J.C. New York Power Authority of the State of New York, 2pp. 47754-094-47754-119.

- --8812080099 Notice of consideration of issuance of amend to Licenso DPH-59 & proposed NSHC determination & opportunity for boaring re-881109 request to amend primary contemperate leak rate requirements per Tech Specs 4.7 A 2410) & 4.7 A 2.1 LABARGE, D.E. Project Directorate I-1, 88/11/29, 10pp. 47754 096-47754:117.
- 8812090097 Forwards SER re util 831109 & 840629 responses to Generic Ltr 83-DIZUBUDBY Forwards SER re util 831109 & 840629 responses to Generic Lir 83-28,tom 2 r (Part 2) which involves confirmation of vanctor interface program w/NSSS vendro for components required for reactor fing function Responses acceptable LABARGE.D.F. Project Directorate I-1 88/12/06. BRONS,J.C. New York Power Authority formerly Power Authority of the State of New York) 3pp. 47762,244-47762,255
- --8812090098 SER supporting util response to Generic Ltr 83-28,tiem 2.1 (Part 2) re-confirmation that vender interface program exists w/NSSS vender for components that are required for performance of reactor trip function.

 * NRC Na Data led Affiliation Given 88/12/06 3pp 47762 247-47762 255
- 8812220062 Forwards corrected 881129 notice of consideration of Issuance of Amend to License DPR-59 & proposed NSHC changing data in second column from 890108 LEBARGE, D.E. Project Directorate 1-1 88/12/14 BRONS J.C. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 47903 191-47903:196
- --8812220067 Corrected notice of consideration of issuance of amend to License DPR-59,changing date in second column from 890106 to 881222 LESAR,M.T. Regulatory Publications Branch 88/12/08 4pp 47803.193-47903 196.

Q. Inspection reports, IE Bulletins & correspondence

- 8811290039 Corrects typos in 870918 response to IE Bullotin 87-001, "Thinning of Pipe Walls in Nuclear Power Plants" CONVERSE, R.J. Now York Power Authority (formally Power Authority of the State of New York). 87/10/05 Region 1, Ofc of the Director 2pp. 47649 243-47649 243
- 8811290392 Forwards Sateguards Insp. Rept. 50-333/48-19 on 880926-30. Noncompli-ence noted Partially withheld App A uncl. BELLAMY, R.H. Reg on 1, Otc of the Director 88/11/15, CONVERSE,R.J. Now York Power Authority (formerly Power Authority of the State of Now York). 2pp. 47668-080-
- --8812160130 Paris: y defeted notice of v.ofation from Irisp on 880926-30 Violation noted access control to containment for authorized personnel & mail not maintened whom frequent access permitted Safeguerd info withlived per 10CFR73.21.
 * Region 1, Oic of the Director 88/11/15 2pp 47668-082-47668-093
- -8811290398 Safeguards Insp Rept 50:333788-19 on 880926-30 Violations noted Major areas inspected security plan & procedures, records & replications & maintiocks,keys & combinations & barriers protected area Portions deleted (ref 10CFR73 21) MASNYK,O.M., MAUDEN,J., KEIMIG,R.R. Region 1, Orc of the Director. 88/11/15 10pp. 47668:084-47668:093.
- 8811300317 Forwards Insp Ropt 50:333/88-28 on 881011 & notice of violation. RUSSELL,W.T. Region 1, Old of the Director 88/11/18 CONVERSE,R.J. New York Power Authority (formarly Power Authority of the State of New York). 2pp. 47701:326-47701:332.
- -8811300323 Notice of violation from insp on 881011. Violation noted waste shipment of solidified resin transferred for disposal, but not completely solidified & contained 7.6% pical nic scid Region 1, Ofc of the Director, 88/11/16, 1p. 47701:320-47701:328
- -8811300326 Insp. Ropt. 50-333/88-28 on 881107.Violation noted.Major areas Inspected.Cham-Nuclear Sys.Inc.tiurial site at Barnwoll,SC. FURIA.J., PASCIAK.W. Rog on 1, Oic of the Director. 88/11/09. 4pp. 47701.328-47701:332
- 8811230192 Grants temporary waiver of compliance from Tech Spec Surveillance Tests 4.7.A.2.a.(10) & 4.7.A.2.i.per 861109 request re integrated leak rate tests. BOGER,B.A. Assistant Director for Region I Reactors 88/11/18 BRONS,J.C. New York Power Authority (formerly Power Authority of the State of New York). 6pp 47657:243-47657:248
- 8811290548 Forwards Safety Insp. Rept 50-333/88-25 on 881011-14 & notice of violation.
 DURR.J.P. Region 1, Olc of the Director. 86/11/21. CONVERSE,R.J. New York
 Powor Authority (formarly Power Authority of the State of New York). 2pp. 47650.18547650.196.
- --8811290551 Notice of violation from irisp on 881011-14. Violation noted, noted Installed half-tapped layers of Okonito cable splices loss than 3/8-1/2 inch half-tapped layer required per qualified configuration.

 * Region 1, Old of the Director, 88/11/21, 1p. 47650:187-47650.187.
- --8611290553 Insp Rept 50:333/88-25 on 881011-14. Violation noted. Major areas inspected status of previously identified open items & adequacy of licensee response In resolving Issues.
 PAOLINO,R.J., LARA,J., ANDERSON,C.J. Region 1, Otc of the Director 88/11/01.
 9pp. 47850:188-47650:188
- 8811160211 NRC Into Notice 88-090, "Unauthorized Romoval of Industrial Nuclear Gauges." Svc list enct. CUNNINGHAM.RE Division of Industrial & Medical Nuclear Safety (Post 670729). 88711722. Consolidated Edison Co. of New York, Inc. 99pp. 47708.255-47708.257.

- 8811160457 MiC H to Notice 88 091. Emproper Administration & Control of Psychologcal Tots: Scollstand: ROSSIGE (www.nord.com/order) before the ROSSIGE (www.norder) before the
- 8812060260 Forwards thep Rept 50 303768 22 on 651031-1104 No vicitions noted 65LLAM the R. Rey to 1. O'c of the Director 88/11/50 CONVERSE R.J. New York Page: Authority (forming Fower Authority of the State of New York) 2pp. 47735 015
- -8812060261 Insp. Frot 50 332189-22 on 881031-1104145 violations noted. Major STEAST OF THE PARTY OF STEETS AND BUILDING NO WARDERS NOTED MAJOR AREAS INSPECTED CARRY AND AREAS INSPECTED AND AREAS AR
- 8811290030 NRC Info Notice 88-093. Teletinerapy Events II Svolust and CURN NGHAMIR E. Drisson of Industrial & Medical Nuclear Safety (Post 870720) 63/12/02. Consolitated Edison Co. of New York, Inc. 112pp. 47811 103-47811
- 8811290538 NR-C Into Notice 88 694. "Potentially Undersized Valve Actuators." Svc list ROSSICE Civisor of Operational Events Assessment (Post 870411) 88/12/02 Conscluded Edison Co. of New York, Inc. 121pp. 47768 143 47708 251
- 8812050058 Advisors that Planned Marti Systinc indicated that the purchased Class 1E components or sizes for plant Util should lake appropriate action to ensure that components in compliance with AC requirements. CAPRA RIA Project Directorale 11, 88/12/02, BRONS J.C. New York Power Authority (formerly Power Authority of the State of New York). 7pp. 47732,063-47732,071.
- 8812120066 Forwalds Safety Insp. Rept. 50-333/88 27 on 891031-1104 No violations ngred
 MARTIN,T.T. Region 1, Oto of the Director 88/12/04 CONVERSE,R.J. New York
 Power Authority (formerly Power Authority of the State of New York). 2pp. 47780-16647780-173
- -8812120069 Insp. Rept. 50:333788.27 on 881031-1104 No violations noted. Major areas inspective exam of IGSCC conducted during 1988 outage & repair of in-vessel Core screy pipe crack
 MCBREARTY:R.A., STROSNIDER,J.R. Region 1, Ofc of the Director, 89/12/01, 6pp
 47/8G 168 47/83 173
- 8812130001 Responds to NRC 881103 ft/re violations noted in trisp Rept 50.333/88 17 Corrective autions fuel reloading stopped & chique hold when maduentent rod inreceived as 2-ons 39 reliabling stoched & critique hald when madvertent rod in-sertion occurred. Only Power Authority (tornerly Power Authority of the State of New York, 88/12/05. Document Control Branch (Document Control Dask). 4pp. 47792 339.47792 332.
- 8812150126 Responds to NRC 581020 liting including another in Insp. Rept 50:333768-15 Corrective actions formal training to be conducted w/personnal involved in pipe utilisation, testing example CONVERSE, if J. New York Power Authority (formerly Power Authority of the State of New York) 88/12/05 Document Control Branch (Document Control Desk). 7pp. 47878-96-748795-96-96. 47826 257 47826 263
- 6812090007 Forwards SER re uit 831109 & 840529 responses to Generic Ltr 83-28.liem 2.1 (Part 2) which involves confirmation of wonder interface program w/NSSS vender for components required for reactor fing function Responses acceptable LABARGE DE Project Directorate Int. 88/12/06 BRONS.J.C. New York Power Authority (formerly Power Authority of the State of New York) 3pp. 47762-244-47762-255.
- 8812020287 IARC (n/s Notice 88 035, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svc list encil ROSSIC C. Dirsion of Operational Events Assessment (Post 870411) 88/12/03 Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302.
- 8812210262 Responds to NRC 881116 ftr te violation noted in Insp Rept 50:333/88-28 Corrective action wherever abnomalises experienced during solid.fication.positive method of ventication with be used to verify billers condition CONVERSE.RJ. New York Power Authority (formerly Power Authority of the State of New York, 88/12/09 Document Control Branch (Document Control Dack) 2pp 47882 051-47882 052
- 8812200155 Responds to NRC 881213 ftr re-volutions noted in Insp Rept 50-333/88-25 Corrective actions training program being upgraded to ensure contract electricians properly trained in type of splice CONVERSER J. Now York Power Authority (formerly Power Authority of the State of New York) 58/121/13. Document Control Branch (Document Control Desk) 2pp.
- 8812200073 Forwards response to NRC 881115 ftr re violations noted in insp on 880928-30 Encl withhold (ref 10CFR73.21) CONVERSERJ. New York Power Authority (formerly Power Authority of the State of New York) 88/12/14 Document Control Branch (Document Control flask), 1p. 47881-058-47881-058
- 8812270249 Forwards Insp. Rept. 50:333/88-23 on 881006-1125 & notice of deviation Concerns expressed re adequacy of surveillance testing for operability of reactor bidg crescent area unit coolers Enforcement conference will be scheduled. KANE,WF, Region 1, Ofc of the Ciractor, 887/12/20 BRONS,J.C. New York Power Authority (formerly Power Authority of the State of New York) 3pp. 47927.076, 47927.096.
- -8812270250 Notice of deviation from insp on 881006-1125 Deviation noted on 881031 Control room operators were not aware of unavailability of one 115 kV offsite reserve ac power source
- Region 1, Ofc of the Director 88/12/20, 1p. 47927.078-47927.078.
- --8812270251 Insp Rept 50-333/88-23 on 881006-1125 Deviation noted Major areas inspected refueling 8 plant restart, operational safety ventication, surviveillance observations, angithering battery sys walkdown & hydrogen water chemistry review JOHNSON, J. Region 1, Ofc. of the Director 88/12/15, 17pp. 47927-080-47927-096

R. Periodic operating reports & related correspondence

88121#0J10 Monthly operating rept for Nov 1988 for JA Fitzpatrick plan CCDK J. CONVENSE, A J. New York Power Authority (furmorly Power State of New York) 88/11/30 6pp. 47849 159-47849 164

5. Peporlable occurrences, LERs & related correspondence

- 8611300503 LER 86,009,00.00 881021,inopintable ECCS area cocking equate procedures Other causes to be determined during evaluations coolers rustered to operable status by cleaning flushing & testing flushing and the causes Coolers rustered to operable status by cleaning flushing & testing flushing CHILDS.W.V., CONVERSE, P.J. New York Power Authority (formerly F of the State of New York), 88/11/22, 10pp, 47676-189-47676,197
- 8612010145 LER bill C10 00.on 881029, reactor safety rolled valva discovered Cause cinknown No corrective action necessary W/8811281 CHILDS, WY., CONVERSERJ. Now York Power Authority (formerly Fofthe State of New York). 88/11/28. 4pp. 47703 273-47703-278.
- 8812080013 .ER 88:011-00.on 88:1031,top of operating 115 kV offs to the resulted in short loss of allernating current power Caused by more 115 kV tibe Sys restored to normal W788.1130 In: CHILDS,WV., CONVERSE,RJ, New York Power Authority (formerly P of the State of New York) 88/11/30 5pp 47757 162-47757:168
- 8812080053 PNO-I-88-122 on 881202,commencement of reactor shulde main turbine generator delurring planned to correct resonant frequency erating speed of low pressive furting rotor Rotor will be detuned. SCHV.DT,W. JOHNSON J. Region 1, Olc of the Director. 88/12/02. 47783.225
- 8812130301 CER 88-012-00 on 881109,ESF actuation during transfer of occurred Duo- to-procedural delicting isolation signal reset & shu reestablished W// 881207 ftr. feesiachsner v7 651201 tt. CHILDS, W., CONVERSE,R.J. New York Power Authority (formorly P of the State of New York). 88/12/07. 4pp. 47796.248-47796.251.

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812120003 Forwards summary of util efforts to date & projected school too re line damper qualification status SIEBER.J.D. Dequason Light Co. 88/11/30. Document Control Bran Control Deski 3pp. 47780-115.47780.117.
- 8812090192 Advises that 980427 Rev 4 to physical socurity plan consistent of 10CFR50.54(p) & acceptable BELLAWIA R Region 1, Otc of the Director 88/12/01, SIEBER,J D. Co 3ρρ. 47785 033-47785 035.
- 8812090272 Forwards Revs 6 to Issue 4 to physical security plan.Rev 10CFR2 780(d) & 73 21). SIEBERJ D Duquasne Light Co. 88/12/06. Document Control Bran Control Desk). 2pp. 4//85 001-47785 002.
- 8812150006 Forwards Safety Insp Repts 50:334/88-28 & 50-412/88-2 1115 & notice of violation
 WIGGINS J.T. Region 1, Old of the Director 88/12/07, SIEBEH, J.D. D.
 Co. 2pp. 47823.019-47823.044
- -8812150011 Insp. Repts 50-334/88-28 & 50-412/88-22 on 881001-11 noted Major areas inspected plant operations, security,radiological housekeeping & fire protection matrix & surventance testing. TRIPP, LE Region 1, Ofc of the Director #8/12/08, 23pp. 47823:022-47

H. General correspondence

- 8812010421 Comment opposing proposed rule 10CFR26 re random drug sion in Funess for Duty Program Local 142 members can accept & work for Duty Program that contents only just cause drug testing provision. SPEAKMAN,R.J. International Brottleribod of Electrical Workers. 88/1 r.g. & Services Branch. 1p. 47679 291.47679.291.
- 8812020030 Comment opposing proposed rule 10CFR26 ro random testing fitness for Duty Program Mombers of Local 142 at plant can accept Fitness for Duty Program that contains only just cause drug tosting providing SINGER, W.J. International Brotharhood of Electrical Workers 8871 ing & Services Branch. 1p. 47680.019.47680.019.
- 8812020077 Comment on proposed rule 10CFR28 re Fitness for Duty 142 members opposed to proposed random drug testing Supports jud lesting provision NOWAK, J.M. Witernational Brotherhood of Electrical Workers 88/11/28 Services Branch, 1p. 47680.026-47680.028.

- 8812010248 Responds to request for additinto re Tech Spec Change Resulbbers at plant Revised Tech Specs encl.
 SIEBER.J.O. Ovquesne Light Co. 88/11/17. Document Control Brand Control Desk) 4pp. 47708 221-47709.231.
- ~8812010253 Proposed Tech Specs 3/4.7 12 re snubbers. * Duquesne Light Co. 88/11/17, 7pp. 47708 225-47709:231.

- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list
 - CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consoldated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024.
- 8812010021 Responds to Generic Ltr 88-11, "NRC Position on Fladiation Embritillement of Reactor Vessel Mails & Impact on Plant Operations." Util currently evaluating new heatup & cooldown curves Technical analysis and SIEBERJ D. Duquesne Light Co. 88/11/23 Document Control Branch (Document Control Desk). 29pp. 47702.345-47703.013
- 8812120083 Forwards summary of util efforts to date & projected schedule for completion re fire damper qua'il calion status SIEBERJ D. Duquesne Light Co. 88/11/30. Document Control Branch (Document Control Desk), 3pp. 47780.115-47780.117.
- 8812080103 Forwards anviron assessment & finding of no significant impact re 880622 request to axclude all containment Isolation weight. & spring-baded check valves not sub; to Type-C testing from lift test requirements of Spac 4.6.3.1.
 TAMPS. Project Directorate 1-4, 88/12/01 SIEBER, J.O. Duquesno Light Co. 2pp. 47766-178-47755-183.
- --8812080107 Environ assessment & finding of no significant impact supporting amend application changing Tech Spec 4.6.3.1 which would exclude containment isolation spring-loaded & weight-loaded check valves from lift test requirements STOLZ,J.F. Project Directorate I-4, 88/12/01 4pp. 47755 180-47755:183.
- 8812080109 Requests that util address Generic Ltr 88-17 re loss of DHR during non-power operation accordingly.Believes that industry did not aggressively respond to Generic Ltr 97-12. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02 VON SCHACK,W. Duquesno Light Co. 3pp. 47754 221-47754:223
- 8812130216 Requests addl into re 871112 Amend Request 144 to revise applicable ESF response times in Tech Spec Table 3.5-5.Into requested within 45 days of itr re
 - celpt TAM.P.S. Project Directorate I-4, 88/12/08, SIEBER,J.D. Duquasna Light Co. 2pp 47792-105-47792-106.
- 8812220268 Forwards Amends 133 & 9 to Licenses DPR-66 & NPF-73, respectively & safety evaluation.Amonds exclude all containment isolation weight & spring loaded check valves not subjict Type C testing from Tech Spec 4.6.3.1.
 TAM.P.S. Project Directorate I-4. 88/12/13. SIEBER.J.D. Duquesno Light Co. 3pp. 47901:093-47801:115.
- --8812220272 Amends 133 & 9 to Licenses DPR-66 & NPF-73 respectively, excluding all containment isolation weight & spring loaded check valves not subj to Type C testing from Tech Spec 4 6 3.1 requirements STO1.7,J.F. Project Directorate 1-4, 88/12/13, 15pp 4/901-096-47901:110.
- -9812220273 Safety ovaluation supporting Amends 133 & 9 to Licenses DPR-66 & NPF-73,respectively.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 86/12/13 3pp. 47901.111-47901:113.
- -8812220276 Notice of Issuance of Amends 133 & 9 to Licenses DPR-66 & NPF-73,respectively-Amends exclude all containment Isolation weight & spring loaded check valves not subj to Type C tosting from Tech Spec 4.6.3.1 requirements TAM,P.S. Project Directorate 1-4. 88/12/13. 2pp. 47801:114-47901:115.
- 8812220199 Forwards Amends 134 & 11 to Licenses DPR-66 & NPF-73, respectively &
- safety evaluation.Amonds clarify several action statements to reactor trip breakers in Table 3.3-1 of Tech Specs.
 TAM P.S. Project Directorate I-4. 88/12/19. SIEBER,J.D. Duquesno Light Co. 3pp. 47892:166-47892.180.
- --8612220202 Amerids 134 & 11 to License DPR-66 & NPF-73,respectively, clarifying several action statements re reactor trip broakers in Table 3.3-1 of Tech Specs. STOLZ,J.F. Project Directorate I-4, 86/12/19, 10pp. 47892:169-47892:178.
- -8812220204 Safety evaluation supporting Amends 134 & 11 to Licenses DPR-66 &
 - NPF-73 respectively.

 Office of Nuclear Reactor Regulation, Diractor (Past 870411). 88/12/19. 2pp. 47892:179-47892:180.

Q. Inspection reports, IE Bulletins & correspondence

- 8811300061 Responds to NRC 881020 ltr re violations noted in Insp Repts 50-334/86 12 & 50-334/86-21,por 880812 enforcement conference.Corrective action fully qualified cabling 8 containment penetration mod to enhance HRRM sys installed. SIEBER, J.D. Duquesne Light Co. 88/11/18. Document Control Branch (Document Control Dosk). 5pp. 47880.307-47880-311.
- 8612080232 Forwards results of facility sixth refuoling outage steam generator tube in-service Inspirapt.Rept contains number & extent of tubes inspected & identification of
- tubes plugged.

 SIEBER, J.D. Duquesne Light Co. 88/11/21. Document Control Branch (Document Control Desk). 1p. 47755:241-47755:268.
- ~8812080234 "Sixth Refuelling Steam Generator Tube Inservice Insp Special Rept." Duquesne Light Co. 88/11/21, 27pp. 47765;242-47755;268.
- 6811180211 NRC Into Notice 86-090, "Unauthorized Removal of Industrial Nuclear
- Gauges: Svc list encl.
 GuNNINGHAMRE. Division of Industrial & Medical Nuclear Safety (Post 870729).
 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:265-47708:257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests." Svc list encl.

 ROSSI,C E. Division of Operational Events Assessment (Post 870411) 88/11/22.

 Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708.142.
- 8812050045 Forwards supplemental response to NRC Bulletin 88-008, "Thermal Stresses in Piping Connected to RCS." SIEBER,J.D. Duquesne Light Co. 88/11/28 Document Control Branch (Document Control Desk). 5pp. 47732:340-47732

- 8812060023 Forwards Insp. Repts 60-334/88-27 & 50-412/88-21 on 881017- 21.No violations noted BELLAMY,R.R. Region 1, Otc of the Director. 88/11/28. SIEBER,J.D. Duquesne Light Co. 2pp. 47743.028.47743.040
- -8812080027 Insp Repts 50-334/88-27 & 50-412/88-21 on 881017-21 No violations noted Major areas inspected licenses radioactive officent controls radwaste & transportation & radiological environ monitoring programs

 PASCIAK W.J. DAVIDSON B.S., KOTTAN J.J. Region 1, Otc at the Director 68/11/ 28 11pp 47743 030-47743 040
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events" Svc list encl. CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 670729). 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Svc fist enct. ROSSt,C.E. Division of Operational Events Assessment (Post 870411), 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708.254.
- 8812150006 Forwards Safety Insp Repts 50:334/88-28 & 50:412/88-22 on 881001-1115 & notice of violation WIGGINS, J.T. Regon 1, Old of the Director 88/12/07. SIEBER, J.D. Duquesne Light Co. 2pp. 47823:019-47823:044
- -8812150009 Notice of violation from insp on 881001-1115. Violations noted Icensea corrective actions in response to insp findings found inadequate to preclude repetition in that inaccurate into shown on control room status prints Region 1, Olc of the Director, 89/12/07, 1p. 47823.021-47823.021.
- -9812150011 Insp Repts 50:334/88:28 & 50:412/88:22 on 881001-1115. Violations noted. Major areas inspected plant operations, security, radiological controts, plant housekeeping & fire protection, ment 8 surveillance testing TRIPP, L.E. Region 1, Otc of the Director: 88/12/06 23pp. 47823.022-47823.044.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Liconeses on Vandors" Svc list end: ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47897.302.

R. Periodic operating reports & related correspondence

- 8811300509 Discharge monitoring rept for Oct 1988 for Beaver Valley Units 1 & 2.W/ 881122 ltr DRUGA,R J. Duquesne Light Co. 88/10/31, 21pp. 47680:262-47680.282
- 8812140267 Monthly operating repts for Nov 1988 for Boaver Valley Units 1 & 2 W/ WINGER, SIEBER, J.D. Duquesno Light Co. 88/11/30, 11pp. 47812 069-47812 079.

S. Reportable occurrences, LERs & related correspondence

8812210201 LER 88-011-01:on 880103,one of twolve tofts which secure thermal shield to lower core barrel found severed Caused by transgranular fracture Ultrasonic testing performed W7891216 It. NOONAN,T.P. Duquesne Light Co. 88/12/16. Spp. 47881:277-47881:281.

DOCKET 60-335 ST. LUCIE PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812080241 Advises that 880921 Rev 5 to safeguards contingency plan consistent w/ provisions of 10CFR50.54(p) & scceptable. CLINE,W.E. Region 2, Ofc of this Director. 88/11/23. WOODY,C.O. Florida Power & Light Co. 3pp. 47783:319-47783-321.
- 8812090319 Forwards Insp. Repts 50:335/88:27 & 50:389/88:27 on 881002- 1105 No violations or deviations identified WILSON,B.A. Region 2, Ofc. of the Director, 88/12/01, CONWAY,W.F. Florida Power & Light Co. 2pp. 47761:069-47781:080.
- --0812090322 Insp Repts 50-335/88-27 & 50-389/68-27 on 881002-1105 No violations or deviations identified Major areas Inspected. Tech Spec compilance, operator performance, QA practices, side security procedures & radiation control activities. CRLENJAK, RV. PAULK, GL., BIBB.H.E. Region 2, Ofc of the Director. 88/11/30. 10pp. 47761:071-47761:080.
- 8812160045 Informs that safeguards regulatory effectiveness review scheduled for which of 881212-16. Review conducted to ensure that safeguards, required by NRC regulations, provide intended level of protection w/o compromising safety of operations.

 CLINE,W.E. Region 2, Ofc of the Director, 88/12/02, CONWAY,W.F. Florida Power & Light Co. 3pp. 47830:345-47830.347.
- 8812080149 Forwards response to violations noted in Insp Repts 60-335/68-20 & 60-389/68-20.Response withheld (ref 100FR73.21 & 2.790(a)(3)). CONWAY W.F. Florida Power & Light Co. 88/12/08. Document Control Branch (Occument Control Dosk). 1p. 47757.101-47757:101.
- 8812190129 Forwards Rev 18 to physical security plan Rev withhald (ref 10CFR73.21 & 2790).

 CONWAY,W.F. Florida Powor & Light Co. 88/12/13. Document Control Branch (Document Control Desk). 2pp. 47853.355-47853.356.

G. Adjudicatory correspondence

Sic Retited correspondence BAUSER,MIA Fini Ja Power 8 Light Co. BAUSER,MIA Newman 8. Hotzinger. #488 7554, 891-1721. RC:HiC. Hich. C. 4pp. 47643,265,47843,268

- 8812190150 Notice of hearing! Notices of evidentary hearing on 890124-26 in Straft FL Served on 681208 COTTER B.P. Atomic Safety and truending Board Panel, #488,7633, 88/12/06, 2pp 47801 165 47801 166
- 8812270080 Notice of appearance." Advises that author will enter appearance in pro-ceeding on behalf of NRC Centificate of Sudjenct JEHLEIP A. Assistant. General. Coursel for Hearings. #468, 7693, 88/12/13, 3pp. 47872,284,47872,778.
- 8812280257 Forwards indoments describing Borathax panel degradation at Grand Gulf Patwication techniques used in Grand Gulf Patwication techniques used in Grand Gulf Speni fuel racks also used in const of Quad Cuber racks Petals discretely decide. JEMEP A. Assistant General Coursel for Hearings. #489,7753, 88/12/16. RICH,C. Rich, C. 11pp. 47684,233,47684,338
- 8812280128 Forwards test many of J Wing EG Tourigry & U Kopp on Contentions 3.6 & 7 per issues that remain in proceeding. Related correspondence. JEHLE PA: Assistant General Counsol for Pearings: #488-7752-88/12/19 COTTER B P., ERIGHT GO., COLE, R.F., Atomic Salisty and Licensing Board Panel 1p. 47884 195 47884 220
- ~8812280131 Testimory of JW WingleG Tourighy & LI Kopp on Contentions 3, 6 & 7 * Certificate of Svir end Related correspondence wins G. TOURIGN IS Office of the General Counset WING J. Chemical Engineering Branch 88/12/19

I. Financial Intermation

8812220136 Forwards financial disclosure informationing 1967 abruel 10-X Sept. 1998 10-O & util statement of internal cash flow excluding retained earnings for 12 months anding Sept. 1969, por 100FR140-21 & Reg Golda 9-4 CORMAY, W.F. Florida Folwer & Light Co. 89/12/14 Document Control Branch (Document Control Desk). 91pp. 47856 (95.47886.785).

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor faculties re-individual plant examillor severe accident vulnerabilities Svc List enci CRUTCHFEED,D. Associate Director for Projects (Post 870411) 88/11/23. Consoldated Ed-son Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 8811290335 Pesponds to Generic Liu 88.01. NPC Posuon on Radiation Embrittlement of Reactor Vessel Mails & Impact on Plant Operations." Util determined that neither unit wit exceed criteria per Reg Guide 1.93/Rev 2.through end of Irig CONWAY, W.F. Flonds Power & Light Co. 887/11/23. Document Control Branch (Document Control Desk). 2pp. 47655.273.47655.275.
- 8812120137 Requests that u.l. agdresses Generic Ltr 88-17 reitors of OHR during non-power operation Industry has not aggress-vely responded to resolve concern to bining dentification in Generic Ltr 87-12 MURILEY T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 68/12/ 02. HUDIBURG J.J. Florida Power & Light Co. 3pp. 47780-139-47780.141.
- 8812150042 Informs that new infoire Monument 80 B installed to replace missing monument does not change continuous of done suncy, per end CONWAY.W.F. Florad Power & Light Co. 864/12/08. Document Control Branch (Document Control Desk). 4pp. 47823.015-47823.018
- 8812150185 Informs that effective 831201, JA floring assigned as new project manager for facilities
 BERKOW,H.N. Project Directorate II-2, 88/12/13, CONWAY,W.F. Florida Power & Ught Co. 2pp. 47626-293 47826-294

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 69 090. Unauthorized Removal of Industrial Nucleur Gauges" Svc hist enci CUNNINGHAMR E Drisson of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811180467 NRC tota Notice 68 091. Improper Administration & Control of Psychological Tests." Svc I stienci. ROSSI.C.E. Drusson of Operational Events Assessment (Post 870411). 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.
- 8812050320 Ack recept of 881017 Itr informing NRC of steps taken to correct violations noted in Insp Repts 50, 335/68.21 & 50,339/88.21 WILSON, B.A. Region 2, O'c, of the Director 88/11/22 CONWAY,W.F. Florida Power & Light Co. 1p. 47740,100-47740,100
- 8612060001 Ack receipt of 880912 & 1117 firs informing NRC of steps taken to correct deviation noted in lasp Ropt 50 335/89 16.

 HERDT,A.R. Region 2, Ofc of the Director, 88/11/23 CONWAY,W.F. Florida Power & Light Co. Ep. 47743 064-47743 084.
- 8812080233 Forwards owner data rept for inservice inspiper ASME Code, Section XI for facility
 CONWAY, W.F. Florida Power & Light Co. 88/11/30. Document Control Branch (Document Control Desk). 1p. 47753 225 47753 342.
- -8812080235 inservice inspirept for second 10 yr interval Florida Power & Light Co. 88/11/30, 117pp, 47753 226-47753 342.
- 8812090319 Forwards Insp Repts 50:335/88:27 & 50:389/88:27 on 881002: 1105.No violations or deviations identified. WILSON 8 A. Region 2, Ofc of the Director. 88/12/01. CONWAY,W.F. Florida Power 1: 069 47761 080

- -8812090322 Insp. Repts 50:335/68:27 & 50:389/88:27 on 881002:110 or devations Identified Major areas inspected Toch Spac compartormance, OA practices, sie security procedures & radiation control a CRLENJAK RV., PAUK GEL., BIBB, HE Region 2, Ofc of the Direct 10pp, 47761-071-47781-080
- 8811290030 NRC Into Notice 88:093, "Teletherapy Events." Svc hat uncl CUNNINGHAM,R.E. Dusion of Industrial & Medical Nuclear Safety 88/12/02 Consolidated Erison Co. of New York, Inc. 112pp. 47811
- 8811290538 NRC Info Notice 88-004, "Potentially Undersized Valve Actu ROSSICE, Division of Operational Events Assessment (Post 9704 Consolidated Edison Co. of New York, Inc. 121pp. 47708.143-47708.25
- 8812090069 Ack recept of 880922 response & 881220 supplited deviating Repts 50:335/88/08 & 50:389/88/08 Response & supplihage sponse requested following planned meeting to discuss emerginity of dues program ERNST.M.L. Region 2, Old of the Director 88/12/02 CONWAY,W.F. F. Light Co. 1p. 47762:307-47762:307.

8812220343 Forwards Exam Ropt 50.335/OL-88-01 administered during 8 0912 Exam ropt Indiags in conjunction w/Insp Repts 50.335/88 08 8 Indiags indicate weakness in omergency optinating procedures GIBSON.A F. Rogen 2, Otc. of the Birector. 88/12/05. CONWAY,W.S. & Light Co. 2pp. 47881 140-47892 087.

- ~8812220352 Exam Rept 50:335/OL-83-01 on 880725 & 0912 Exam rescued operators & 12 reactor operators passod examp & three rea failed evams

 CASTO,C. MUNRO,J.F. Region 2, Old oil the Director, 88/11/30, 228, 47892 097
- 8812020287 NRC Into Notice 88 095, "Inadequate Procuroment Required by Licensees on Vondors". Svc hist encl.
 ROSSICE Division of Opurational Events Assessment (Post 8704). Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.30
- 8812980149 Forwards response to violations noted in Irisp Repts 50:33 389/68/20 Response withhold (rd. 10CFR73 21.8, 2.790(a)(3)) CONWAY.W.F. Flonds Power 8, Light Co. 89/12/09 Document Control ment Control Dask): 1p. 47757-101-47757:101.
- 8812270272 Forwards "Owners Ropt for Repairs or Replacements," 881130 submittel of owner data for inservice integral CONWAY.WF Florida Power & Light Co. 88/12/20 Pocument Control mont Control 109sty 1p. 47926-151-47926-167.
- -8812270276 Eriala to 881130 Inservice Insp. rept.consisting of Forms I "Owners Rept for Repairs or Replacements" "Fronda Power & Light Co. 88/12/14, 18pp. 47928 152 47926 167

R. Periodic operating reports & related correspondence

- 8812200008 Forwards monthly operating status ropts for Nov 1988 for Units 3 & 4 & 51 Lucte Units 1 & 2 & corrected unit shuldown & power for Turkey Point Unit 3 for Oct 1988. CONWAY,W.F. Floada Power & Light Co. 88/12/13 (Document Control mont Centrol Desk). 1p. 47868.333.47869.349
- ~8812200013 Monthly operating repts for Nov 1988 for Turkey Point Un Lucle Units 1 & 2 BONETT, D.M. Florida Power & Light Co. 88/11/30, 16pp. 47866 334-47

S. Reportable occurrences, LERs & related correspondence

8812200382 NPDES noncompliance notification on 881021,10,000 gallo water released into intake canal Caused by pipe broak in valve pit. Plaresuce to repet pipe.

CONWAY, W.F. Floords Power & Light Co. 88/11/14. Document Control ment Control Dask). 3pp. 47862.216-47862.218.

T. Hearing transcripts on non-antitrust matters

- 8812280009 Forwards testmony of KP Singh,SE Turner & EJ Weinkam 3.6 & 7,for tiling EPRI NP-6159, "Assessment of Borallex Performance clear Fuel Storage Racks," also end W/Cortflicate of Svc Related corre BAUSER M.A. Florida Power & Light Co. BAUSER,M.A. Newman & Ho 7725, 88/12/19, COTTER,B.P., COLE,R.F., BRIGHT,G.O. Atomic Safeing Board Panel. 2pp. 47885.173-47886.072
- -8812280040 Testimony of KP Singh on Contentions 3 & 6* Related co SINGH, KP. Florida Power & Light Co SINGH, K.P. Holtec Internation 26pp. 47885.175.47895.200.
- -8812280086 Testimony of SE Turner on Contentions 3 & 6.º Rolated oc TURNER, S. Flonda Power & Light Co TURNER, S.E. Holtec Internatio 25pp. 47865 201-47885, 225.
- ~8812280103 Testimony of SE Turner on Contention 7.* Rolated correspond TURNER,S.E. Florida Power & Light Co. TURNER,S.E. Holtec Internation 26pp. 47885/226-47885/251
- -8812280116 Testimony of EJ Weinkam on Contentions 3 & 6.1 Relate WEINKAM,E J. Florida Power & Light Co. 88/12/19, 8pp. 47885-252-47.
- -8812280124 Testimony of EJ Weinkern on Contention 7.* Supporting Betzzouter resimbly of the second service of

101

8812280128 Forwards tustimony of J Wing EG Tourigny & LI Kopp on Contentions 3.6 & 7.per issues that remain in proceeding. Related correspondence. JEHLE,PA. Assistant General Counset for Hearings. #488 7752, 88/12/19 COTTER,B.P., BRIGHT,GO., COLE,R.F. Atomic Safety and Licensing Board Panel 1p. 47884-198-47684-220.

--8812280131 Testimony of JW Wing,EG Tourigny & LI Kopp on Contentions 3, 6 & 7.1 Certificate of Svc encil Related correspondence. WING,J., TOURIGNY,E, Office of the General Counsel WING,J. Chemical Engineering Brench 88/12/19 22pp 47884.199-47884.220

V. Operator Examinations

8812220343 Forwards Exam Ropt 50:335/OL-88-01 administered during wks of 880725 & 0912 Exam ropt findings in conjunction w/Insp Ropts 50:335/88-08 & 50:389/08-08 findings indicate weakness in emergency operating procedures GrBSON,A.F. Region 2, Oto of the Director, 88/12/05, CONWAY,W.S. Florida Power & Light Co. 2pp. 47891:140-47892.097.

--8812220352 Exam Rept 50 335/OL-88-01 on 880/25 & 0912 Exam results live serior reactor operators & 12 reactor operators passed exams & three reactor operators CASTO,C., MUNRO,J.F. Heg.an. 2, Olc. of the Director, 88/11/30, 228pp. 47891:142-47892:097.

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8811300298 Forwards Safeguards Insp Repts 50-213/88-21,50-245/88-22, 50-338/88-25 & 50-423/88-21 on 891017-21.No violations noted BELLAW/RR. Region 1, Off of the Director 88/11/15. MROCZKAE J. Northeast Nuclear Energy Co. (subs. of Northeast Utdites). 2pp. 47678-019-47678-024.

-8811300298 Physical Socurity Insp Ropts 50-213/88-21,50-245/88-22, 50-336/88-25

& 50-423/88-21 on 681017-21.No noncompliance noted Mejor areas inspected/safeguerds into program - corporate ofcs.

LANCASTER,W.K. Region 1, Otc of the Director. 88/11/15 4pp 47678:021-

47676:024 8811280068 "Millstone Nuclear Power Station Emergency Response Exercise, Nov

Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 88/11/30, 395pp 47856:052-47659 056

8812070178 Rov 13 to Emergency Plan Implementing Procedure EPIP-4304, "Emergency Response Factities Operating Instructions." SCACE, SE. Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 88/12/01. 35pp. 47745/298-47745/332

6612236020 Forwards hisp Hopt 50-336/88-24 on 881013-1123.No violations

noted Expresses concern to temporary loss of access to certain spaces & open items re effegations concerning Metrology Lab ability to cal br Simpson multimoters BETTENHAUSEN,I. Region 1, Olc of the Director, 88/12/15, MROCZKA,E.J. Northeast Nuclear Energy Co (subs. of Northeast Utilities). 2pp. 47811.090-47811:122.

--8812230022 Insp. Rept. 50:336/88:24 on 881013-1123.No violations noted. Major areas Inspected survo llanco, maint, proviously identified items, reactor trip, plant incident repts, security, allegations, periodic repts & see water leak. MCCABE, E.C. Region 1, Ote of the Director, 88/12/14. 31pp. 47911:092-47911:122

H. General correspondence

8812010055 Comment supporting proposed rule 10CFR26 to litrose-for-duty program MROC2KA,E.J. Northeast Utilities. 8B/11/21. CHILK,S.J. Office of the Secretary of the Commission. 9pp. 47679.046-47679.054.

8812130299 Forwards ANF-88-127, "Millstone Unit 2 Steam Line Break Analysis."

P. Operating license stage documents & correspondence

MRQCZKA.E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MRQCZKA.E.J. Northeast Utilities. 88/10/27. Document Control Branch (Document Control Desk). 3pp. 47796:154-47796:206.

-8812130302 "Millstone Unit 2 Steam Line Break Analysis."
WAGONER,S.R. Advanced Nucloar Fuels Corp. (formorly Exxon Nuclear Co., Inc.)
88/10/31. 50pp. 47706:157-47796 206.

8811280101 Application for amend to License DPR-65, revising Tech Specs re Cycle 10 reload operation & entry into Mode 4 after Feb 1989 refuelling outage. MROCZKA,E.J., ROMBERG,W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA,E.J. Northeast Utilities). MROCZKA,E.J. Northeast Utilities. 88/11/11/5. Document Control Branch (Document Control Desk). 16pp. 47653:933-47654:026.

--8811280103 Proposed Tech Specs re Cycle 10 refoad operation & entry into Mode 4 after Feb 1989 refueling outage.

Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 88/11/15 38pp. 47653:350-47654-026.

8811280048 Generic Lir 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severo accident vulnerabilities. Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729:024.

8812080089 Requests that util address Goneric Lir 88-17 re loss of CHR during non-power operation Issue of high priority 8 should be addressed accordingly MURLEY T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02. ELLIS,W.B. Northeast Utilities 3pp 47757-008-47757-010

8812090163 Forwards Amend 135 to License CPR-65 8 sufety evaluation, Amend revises Tech Spec 47.8c to decrease sample size, for subsequent tosts of snubbers, from 10% to 5% of snubber tost population.

JAFFE,D.H. Project Directorate 1-4 88/12/06, MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 47761:114-47761.122

~8812090165 Amend 135 to License DPR-65,revising Tech Spec 4.7.8 c to decrease sample size,for subsequent tests of snubbors,from 10% to 5% of snubbor test population.

STOLZ, J.F. Project Directorate 1-4 88/12/08 5pp. 47761.116-47761 120

--8812090166 Safety evaluation supporting Amend 135 to License DPR-65
* Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/06 2pp
47761:121-47761.122

8812120214 Forwards Rev 1 to "Rad ological Efficient Monitoring & Offsile Doso Calculation Menual & Process Control Program" Attachment 1 provides detailed list of proposed changes for NRC approval. Fee paid MROCZKA, E. J., SEARS, C. F., Northeast Nuclear Energy Co. (subs. of Northeast Utilies) MROCZKA, E. J., Northeast Utilities 88/12/09, Document Control Branch (Document Control Dosk), 11pp. 47788 120-47788 167.

--9812120250 Rev 1 to, "Rathological Elithont Monitoring & Offsite Dose Calculation Manuel & Process Control Program."

* Northoast Nuclear Energy Co (subs of Northeast Utilities) 89/01/31, 37pp 47788-131-47788-167.

8812160089 Forwards safety evaluation concluding that util in compliance w/ATWS rule 10CFR50.62 requirements re design of diverse scrain sys, diverse circuitry to Inisate turbine trip & circuitry for initiation of auxiliary feedwater. JAFFE_DH. Project Directorate I-4 88/12/13, MROCZKA_E_J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 47873:309-47873:328.

 -8812180090 Safety evaluation concluding that util compiles w/ATWS rule 10CFR50.62 requirements for reduction of risk from ATWS events for light-water-cooled nuclear power plants. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/13. 18pp. 47873 311-47073 328.

8812220328 Forwards nanproprietary ANF-88-88(NP), "Dosign Rept for Millistone Point Unit 2 Refoad ANF-1," Rept includes description of fuel design, analytical basis, design critoria, drawings & results of fuel design analyses.

MROCZKA,E J. Northeast Nuclear Encryo Co (subs. of Northeast Utilities) MROCZKA,E J. Northeast Utilities, 86712716. Document Control Branch (Document Control Branch (Document Control Branch) 3pp. 47901-230-47901-283.

-8812220341 Rev 0 to "Dosign Rupt for Milistone Point Unit 2 Relead ANF-1."
WARLOUIST,K.J., BRYAN,K.A., ODELL,L.D. Advanced Nuclear Fuels Corp. (formerly Exxon Nuclear Co., Inc.). ANF-88-88(NP) R00. 88/11/30. 52pp. 47901:233-47901:283.

Q. Inspection reports, IE Bulletins & correspondence

8811290027 Clarihas schedule for completion of Itoms b,c & d of IE Buildtin 85:003 & submission at final repts (Itom f),per discussions wNRC.
MROCZKA,E J. Connocticut Yankea Atomic Power Co. MROCZKA,E J. Northeast Nuclear Energy Co. (eubs. of Northeast Utilities). MROCZKA,E J. Northeast Utilities. 87/12/30. RUSSELL,W.T. Region 1, Ofc of the Director 5pp. 47667:108-47667:201.

8611300296 Forwards Safoguards Insp. Repts. 50-213/88-21,50-245/88-22, 50-336/88-25-8-50-423/88-21 on 881017-21.No violations noted.

BELLAMY,R.R. Region 1, Oic of the Director. 88/11/15. MROCZKA,E.J. Northeast Nuclear Energy Co., (subs. of Northeast Utilities). 2pp. 47678-019-47678-024.

-8811300298 Physical Socurity Insp Repts 50-213/88-21,50-245/88-22, 50-336/88-25 8 60-423/88-21 on 881017-21.No noncomplance noted.Mejor areas inspected:safeguards info program corporate sites. LANCASTER,W.K., CAMERON,D.F., KEIMIG,R.R. Region 1, Oic of the Director. 88/11/15, 4pp. 47678-021-47678-024.

8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear

Gauges." Svc list enct CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Salety (Post 670729). 68/11/22. Consolidated Edison Co. of New York, Inc. 00pp. 47708.255-47708.257.

8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests." Svc list encl. ROSSICE. Division of Operational Events Assessment (Past 870411). 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708-042-47708:142.

8811290030 NRC Info Notice 68-093, "Te'etherapy Events." Svc list oncl. CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:216.

8811290538 NRC Info Notice 86-094, "Potentially Undersized Valvo Actuators." Svc fist encl ROSSI.C.E. Division of Operational Events Assessment (Post 670411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp 47708 143 47708 254.

8812130113 Responds to NRC 881108 ftr re violations noted in Insp Rept 50-336/88-22.Corrective action:shift supervisor notified & test/operate switches placed in operate

position.
MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
MROCZKA,E.J. Northeast Utilities. 88/12/07. RUSSELL,W.T. Region 1, Ofc of the Director. 3pp. 47792:129-47792:131.

- 8812230020 Forwards Insp. Rept. 50:336/68-24 on 881013-1123 No. violations noted Expresses concern to temporary loss of access to certain spaces & open items to a Legations concerning Networdy Lab ability to call by Smpson multimeters.

 BETTENHAUSEN,L. Region 1, Old of the Orector 88/12/15 MROCZKA,E J. Northeast Nutrear Energy Co. (subs. of Northeast Villus). 2pp. 47911 030 47911:122
- -8812230022 Insp. Rept. 50-305/88-24 on 68/013-1123 No violations noted. Mejor areas inspected sub-enance, maint proviously identified items, reactor trip plant incident repts security, a logations periodic repts & six water leash. MCCABEEC Region 1, Oto of the Director. 88/12/14, 31pp. 47911.092-47911.122.

R. Periodic operating reports & related correspondence

8812190412 Monthly operating rept for Nov 1988 for Mitistene Unit 2, W/881212 tt: NERON G., SCACE S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) SCACE,S.E. Northeast Utilities, 88/11/30, 5pp. 47850 297-47850 301.

S. Reportable occurrences, LERs & related correspondence

8811280136 LER 88-011-00 on 881025 loss of normal power due to improper connec-tion of grounding device to bus side of 4,160 volt breaker Caused by personnel error Vertication that all equipment responding as required done W1881122 I MAP/DAY/H, SCACE,SE Northeast Nuclear Energy CO (subs. of Northeast Utitues) SCACE,SE, Northeast Utitues 88/11/22, Spp. 47657-055-47657-059.

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811300438 Ack receipt of 881028 ftr informing NRC of steps taken to correct violations noted in linsp Repts 50-338/88-24 & 50-339/88-24 Ack util Intent to submit emergency plan rev by 881120 which will address violation reliating Limb COLLITIS,DIM Region 2, Otto of the Director 88/11/18, CARTWRIGHT,WIR. Virgina Power (Virginia Electric & Power Co.). 1p. 47681-042-47681-042
- 8812220080 Requests approval of encl proposed revs to augmentation times in Table 5.1 of emergency plan in response to Insp Repts 50 338/88-24 & 50-339/88-24 Justification for proposed rays also enci CARTWRISHT,W R. Virginia Power (Virginia Electric & Power Co.) 88/11/30 Docu-ment Control Branch (Document Control Desk). 14pp. 47903 022-47903 035
- 8812190244 Advises that 881001 revito corporate emergency plans meets requirements of 10CFR50 47(b) & App E & acceptable DECKERJ R. Region 2. Othor the Director. 88/12/05 CARTWRIGHT, W.R. Virgin a Power (Virgina Electric & Power Co.). 1p. 47851:270-47851:270
- 8812200339 Forwards Insp. Regts 50-338/88-32 & 50-339/88-32 on 881114-18.No violations or deviations noted HERDT A.R. Region 2, Ofc. of the Director. 88/12/12. CARTWRIGHT, W.R. Virginia Power (Virginia Electric & Power Co.). 2pp. 47906 280-47906 292
- -8812200341 Insp Repts 50:338/68:32 & 50:339/88:32 on 881114-18 No violations or danations noted Major grees inspected fire protection & JCO 68-30, "Buried Svc Water/Header Leakage" No weakness in Fire protection program identified. HARRISJR. CONLON.T.E. Region 2, Otc of the Director. 88/12/08 11pp. 47906 282-47906 292

- 8811280048 Genenc Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities. Svc list
- encr CRUTCHFIELD,D Associate Director for Projects (Post 870411): 88/11/23 Consoli-dated Edison Co. of New York, Inc. 81pp. 47/28 303-47/29 024.
- 8812010031 Forwards correction to util 880920 & 1006 requests for change to Tech Specs re-containment integrated leak test schedulo-Current Interval for Unit 2 is second interval w/ Type A test scheduled for 1989 refuséing outage CARTIWRIGHT, W.R. Virgina Power (Virgina Electric & Power CO) 1 88/11/23. Document Control Branch (Document Control Desk) 3pp. 47703:185-47703:188.
- -8812010032 Corrected proposed Tech Spec 3.6.1.2 re-containment integrated leakage rate test schedule
 * Virginia Power (Virginia Electric & Power Co.). 88/11/23. 1p. 47703:188-47703 188.
- 8812060085 Responds to Generic Ltr 88.11 re details of implementation of Reg Guide 1.99 Rev 2 in analyses other than PTS Util implementing methodology of reg guido into heatup & cooldown curves for unit-Proposed Tech Specs on subj being prepared. CARTWRIGHT, W.R. Viginia Power (Viginia Electric & Power Co.) 87/11/30 Document Control Branch (Document Control Desk). 2pp. 47743.068-47743.069.
- 8812070084 Application for amend to License NPF-4 supporting operation w/revised heatup & cooldown curves velid to 10 EFPY, WCAP-11791, "North Anna Umit 1 Reactor Vessel Heatup & Cooldown Limit Curves for Normal Operation," enct. Fee paid CARTWRIGHT, WT Virginia Power (Virginia Electric & Power Co.) 88/11/130. Document Control Branch (Document Control Desk) 3pp. 47748:187-47748:275.
- -8812070089 Proposed Tech Specs, supporting operation of plant w/revised heatup & cooldown curve's valid to 10 EFPY.

 'Virginia Powor (Virginia Electric & Power Co.). 88/11/30. 50pp. 47748:190-47748:2190-47748:2190-47748
- -8812070182 "North Anna Unit 1 Reactor Vessel Heatup & Cooldown Limit Curves for Normal Operation SCHMERTZ, C., YANICHKO,S.E., PALUSAMY,S.S., Westinghouse Electric Corp. WCAP-11791, 88/05/31, 38pp. 47748-240-47748-275.
- 8812120079 Requests that util address Generic Ltr 88-17 re loss of DHR during non-power operation Ltr issued due to potentially serious consequences resulting from In-adequacy of Industry response to Generic Ltr 87-12. MURLEY.T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02 FERGUSON.J.H. Virginia Power (Virginia Electric & Power Co.), 3pp. 47789:119-47780-121.

- 8812070116 Forwards notice of environ essessment & finding of no significant world in 880930 application for amend concerning use of two fuel assembles containing to code clad whatwanced zircontum-hased alloy.

 ENGLE, B. Project Directorate In2 88/12/05 CARTWRIGHT,W.R. Virging Poly (Virging Electric & Power Co.) 2pp. 47745-279-47745-284
- -9812070120 Notice of issuance of environ assessment & Ending of no sectors impactive 880930 application for amount to use of two lead test assembles. BERKOW,H.N. Project Directorate 31-2, 887.12705 4pp. 47745;281-47745
- 8812080032 Forwards environ assessment & finding of no significant Impact to applications ten for amends concerning confidentiant air tump ENGLE,L.B. Project Directorate II-2 88/12/05. CARTWRIGHT,W.R. Vicgina Pong (Virginia Electric & Power Co.). 2pp. 47/53:203-47/53.208.
- -8812080034 Environ assessment & finding of no significant impact revising Tech. Specsiae containment air temp upper limit to 120 F & increasing required contactnet test pressure for integrated & facel look rate tests from current value. BERKOW,H.N. Project Directorate II-2 88/12/05. 4pp 47753:205-47753:208.
- 8812080038 Forwards Amends 107 & 93 to Licenses NPF-4 & NPF-7, respectiely 5 safety evaluation Amends permit rodos gri of reactor coolant pump & steam generative supports. ENGLE, B Project Directorate II-2, 88/12/05, CARTWRIGHT, W.R. Virginia Power (Virginia Electric & Power Co.), 2pp. 47789.003-47780-106
- -8612080041 Aniends 107 & 93 to Licenses NPF-4 & NPF-7, respectively, permitting to
- design of reactor coolant pump & steam generator supports since dynamic effects of posturated primary foop ruptures would be eliminated from design basis BERKOW,H N. Project Directorale II-2 88/12/05. 4pp 47780 095-47780 095
- -8812080043 Safety evaluation supporting Amonds 107 & 93 to Licenses NPF-4 & NPF-7, respectively.
 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/05 8;e
- 47780 009-47760 108
- 8812130119 Forwards Amends 108_8 94 to Licenses NPF-4 & NPF-7, respectively 8 safety evaluation Amonds modify Section 3/4.6, "Containment Sys," to reflect use of mass point method for calculating containment leakage rates ENGLEL 8. Assistant Director for Region II Reactors, 88/12/07, CARWRIGHT.WA Virginia Power (Virginia Electric & Power Co.) 4pp 47794.310-47794.330
- ~8812130120 Amends 108 & 94 to Liconsos NPF-1 & NPF-7, respectively, modifying Section 3/4 6, "Containment Sys," to reflect use of mass point method for calculating containment leakage rates described in ANSIANS 56 8-187.

 BERKOW H N. Assistant Director for Region II Heactors 88/12/07, 15pp 47794314
- -8812130122 Salety evaluation supporting Amends 108 & 84 to Licenses NFF.4 & NPF-7, respectively.

 Office of Nuclear Reactor Regulation, Director (Post 870411). 88/12/07. 3:5
- 8812130144 Notification of 881208 meeting w/uFl in Rockville,MD to discuss slabs/sd DNB topical & moderator temp coefficient. ENGEL Project Directorate II-2 88/12/07. MURLEY,T. NRC No Detailed Affiliation Given. 3pp. 47797.122-47797.124.
- 8812160092 Forwards Amends 109 & 05 to Liconses NPF-1 & NPF-7, respectively & safety evaluation Amends implement more stringent primary to secondary coolant sis leakage Imits & establish survaillance requirements to assure operability ENGLE,L.B. Project Directorate II-2, 88/12/12, CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.), 3pp. 47873 266 47873 308.
- -8812160093 Amonds 109 & 95 to Licenses NPF-4 & NPF-7, respectively, implement 's stringent primery to secondary coolant sys leakage limits & ostablishing surva. 'ance requirements to assure operability of existing instrumentation.

 BERKOW,H.N. Project Directorials III.2. 98/12/12. 34pp. 47873:269-47873:302
- -8812160094 Safety evaluation supporting Amends 109 & 95 to Licenses NPF 4 & NPF-7,respectively.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/12 600 47873:303-47873.308
- 8812230275 Summarizes 881129 meeting re proposed extension of Cycle 7. Evel. > Wons performed to support extended fuel burnup also summarized.Cycle 7 will reach and of full power reactivity in mid-Jan 1989.

 CARTWRIGHT.W.R. Virginia Power (Virginia Electric & Power Co.). 88/12/13. Document Control Branch (Document Control Dosk). 4pp. 47918:137-47918:140.
- 8812220222 Forwards Amends 110 & 36 to Licenses NPF-4 & NPF-7, respectively & safety evaluation Amends revise Tech Spacs re containment air temp upper limit & vol of water available from refueling water storage tank for quench spray bys. ENGLE, I.B. Project Directorate II-2. 88/12/14. CARTWRIGHT, W.R. Virginia Power (Virginia Etectric & Power Co.). 3pp. 47900:130-47900:176.
- -8812220224 Amends 110 & 96 to Liconses NPF-4 & NPF-7,respectively, revising Tech Specs re-contenment at temp upper timit & vol of water available from refusing water storage tank for quench spray sys. BERKOW,H N. Project Directorate (I-2, 88/12/14, 32pp. 47900:133-47800:163
- -8812220227 Salety evaluation supporting Amends 110 & 96 to Licenses NPF-4 & NPF-7/respectively.
 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/14 11pp 47900:164-47900:174.
- ~8812220228 Natice of Issuance of Amends 110 & 96 to Licenses NPF-4 & NPF-7,respectively,Amends revise Tech Specs re-containment air temp upper limit & vol of water waitable from returning water storage tank for quench spray sys. ENGLE,LB Project Directorate II-2, 88/12/14, 2pp. 47900, 175-47900, 176.

- 8811290018 Supplemental response to notice of violation from Insp. Repts 50:339/88-16 & 50:339/88-16,providing addl info & status on entericements to operating expen-ence review program for facility. CARTWRIGHT,W F. Virginia Power (Virginia Electric & Power Co.). 85/11/16. Docu-ment Cantrol Branch (Occument Control Desk). 3ep. 47651-271-47651-273
- 8811300438 Ack receipt of 881028 ftr informing NRC of steps taken to correct violations noted in Insp. Repts 50:338788:24 & 50:339789:24 Ack util Intent to submit onlargen cy plan rov by 881120 which will address violation to stalling Ling COLLINS,D.M. Region 2, Otc of the Director 88711718 CARTWRIGHT W.R. Virginia Power (Virginia Electric & Power Co.). 1p. 47681.042-47681.042
- 8811280210 Ack receipt of 860323 submitted of revised officioncy callbridge for three high purity germanium detectors located in count room of plant, our hispited 50-338789-26 & 50-339789-28 Carlbridge currently being reviewed DECKER, T.R. Region 2, Otc of the Director 88713721 CARTWRIGHT, W.R. Virgin a Power (Virgina Efectic & Power Co.) 1p. 47655-343-47655-343
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear
- Gauges "Svc list encl CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870/29) 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708-255-47709-257
- 8811180467 NRC Info Notice 88-081, "Improper Administration & Control of Psychological Tests," Svc list onct.
 ROSSI, CE. Division of Operational Events. Assessment (Post 67041s) -88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 4/708/042-47708.142
- 8812080033 Forwards Insp. Ropts 50-280/88-40,50-281/88-40,50-338/88-28 & 50-339/ 88-28 on 880926-30.No violations or dovations noted COLLINS.O.M. Region 2, Oic of the Dractor 88/11/23 CARTWRIGHT,W.R. Virgina Power (Virginia Efectric & Power Co.). 2pp. 47750-119-47750-132
- ~8812080039 Insp. Repts 50:280788:40,50:281788:40,50:338768:28 & 50:339768:28 on 880928:30 No violations or deviations noted. Major areas inspected.control from habitability & Insp following items. GLOERSEN,W.B., MARSTON,R.R., KAHLE,J.B. Region 2, Ofc of the Director. 887107.26, 12pp. 47750:121-47750.132
- 6812010164 Forwards safety evaluation accepting util actions to resolve listing identified in NRC Bullotin 88 092, "Reputly Propagating Futigue Cracks in Steam Generator Tubes," subj. to util adopting aidd administrative controls ENGLE, I.B. Project Directorator III.2, 88/11/20, CARTWRIGHT,W.R. Virgina Power (Virgina Electric & Power Co.), 2pp. 47703 040 47703 045
- -8812010166 Safety evaluation supporting financial responses to NRC Bullotin 88-002, "Rapidly Propagating Fatique Cracks In Steam Generator Tubes," sub; to util adopt og add administrative controls.
- Office of Nuclear Resolar Regulation, Orector (Post 870411) 98/11/20 4pp 47703.042-47703.045
- 8812220090 Requests approval of oncl proposed rovs to augmontation times in Table 5.1 of amorgancy plan in response to Insp Rupts 50:338/08-24 & 50:339/08-24 Justification for proposed rovs also encl CARTWRIGHT,W.R. Vignila Power (Virginia Electric & Power Co.) 88/11/30 Decument Control Branch (Document Control Desk.) 14pp. 4/903.022-47903.035
- 8811290030 NRC Info Notice 88-993, "Toletherapy Events." Svc list and CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870/29) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list
- enct. ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708-143-47708-254
- 8812020287 NRC Info Notice 88-005, "Inadequate Procurement Requirements Imposed by Licensees on Vandors" Svc list enci.
 ROSSI, CE. Division of Operational Eventy Assessment (Post 870411) 88/12/08 Consolidated Edison Co. of New York, Inc. 112(pt. 47807.19) 47807.302
- 6812200339 Forwards Insp Ropts 50-338/88 32 & 50-339/88-32 on 881114-18 No vio-
- HERDT,A.R. Region 2, Otc of the Director, 86/12/12 CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.) 2pp. 47006;280-47906 292
- --8812200341 Insp Repts 50-338/88/32 & 50-338/88/32 on 881114/18 No violations or deviations noted Major areas inspected fire protection & JCO 88/30, "Buried Svc Water/Header Leakage." No weakness in fire protection program identified. HARRIS.J.R., CONLON,T.E. Region 2, Old of the Oriecter 88/12/08 11pp 47906/262/47906/292
- 88 12210237 Ack receipt of 881116 supplemental response to violations noted in Insp. Repts 50-339/88-16 & 50-339/88-16. ERNST,M.L. Replon 2, Ofc of the Director, 88712714, CARTWRIGHT,W.R. Virgin's Power (Virginia Electric & Power Co.). 1p. 47876 232-47876 232.

R. Periodic operating reports & related correspondence

- 8812200157 Monthly operating repts for Nov 1988 for North Anna Power Station Units 1
 - 42 W/891213 Itr.
 GARNER,B., CARTWRIGHT,W.R. Virginia Powor (Virginia Electric & Power Co.) 88/11/30. 13pp. 47867:251-47867:263.

S. Reportable occurrences, LERs & related correspondence

8812060025 LER 88-025-00.on 881101.Tech Spec 3-6-2-2 violated Caused by one recruitation spray subsystem whose casing cooling subsystem inoperable Functional testing on casing cooling tank level transmitters stopped W/881201 ftr. KANE.G.E. Virginia Power (Virginia Electric & Power Co.) 88/12/01. 4pp. 47753.014-47753.017.

ad 2 augus LER 88-027-00 on 88111/inconsistency between updated FSAR & Tech Specs for surveillance requirements of soft state protection sys slave relays discovered Cause undutermined. Review of ESF testing program initiated W/881215 KANE,G.E. Virgin a Power (Virginia Electric & Power Co.) 88/12/15 App. 47855.014 47855 022.

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8811390438 Ack recept of 881028 lir informing NRC of steps taken to correct violations noted in Insp Ropis 50-338/88-24 & 50-339/88-24 Ack util Intent to subtruit emergency plan rev by 881120 which will address violation re-staffing time COLLINS,D M. Region 2, Ofci of the Director, 88/11/18 CARTW/IIGHT,W.R. Virgnia Power (Virgnia Electric & Power Co.). 1p. 47681-042-47681-042
- 8812220080 Requests approval of encl proposed revs to augmentation times in Table 5.1 of emergency plan in response to Insp Repts 50.338788-24. & 50.339788-24 Justification for proposed revs also encl. CARTWHIGHT, WR. Virginia Power (Virginia Electric & Power Co.). 88711730. Document Control Branch (Document Centrol Desk). 14pp. 47903.022.47903.035

- 8812180244 Advisos that 881001 rev to corporate emergency plans mades requirements of 10CFH50.47(b) & App E & acceptable DECKERJ.F. Regen 2. Of cill the Director. 88/12/05 CARTWRIGHT,W R Virginia Power (Virginia Electric & Power Co.). 1p. 47851.270-47851.270.
- 8812200339 Forwards Insp Ropts 50 330/88/32 & 50 339/88/32 on 881114-18 No violations or deviations noted HERDT,A.R. Region 2, Ofc of the Director, 88/12/12, CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.), 2pp. 47905/280-47906.292
- --8812200341 Insp Repts 50-338/88.32 & 50-339/88.32 on 881114-18.No violations or dividitions noted Major areas inspected line protection & JCO 88-39, "Buried Svc Water/Header Leakage." No weakings in fine protection program identified HARRIS,J.R. Region 2, Otc of the Director. 88/12/08, 11pp 47906-282-47906-292

P. Operating license stage documents & correspondence

- 8811280040 Gonoric Ltr 86:20 to all Feonsoes holding Otis & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vurnorabilities Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024.
- 8812010031 Forwards correction to tall 880920 & 1006 requests for change to Tuch Specs to containment integrated feek test schedule Current interval for Unit 2 ls second interval w/ Type A test scheduled for 1980 refueling outlage CARTWRIGHT,WR Virginia Power (Virginia Electric & Power Co.) 88/11/23 Documunt Central Branch (Document Control Dosk) 3pp. 47703:185-47703:188
- -88 120 10032 Corrected proposed Tech Spec 3 6.1.2 re-containment integrated leakage rate test schedule. Virginia Power (Virginia Electric & Power Co.) 88/11/23 1p. 47703:188-47703:188
- 8812080085 Responds to Generic Lir 88-11 to details of implementation of Reg Guide 812080085 Responds to Genoric Lif 85+11 to deliass of implomentation or freq source 199,Rev 2 In analyses, other than PTS ULI Implamenting methodology of reg guide into hoating & confidewn curves for unit Proposed Tech Spocs on subj being prepared. CARTWRIGHT WR. Virginia Power (Virginia Electric & Power Co.) 88/11/30. Occiment Control Branch (Document Control Dosk). 2pp. 47743.069-47743.069.
- 8812120079 Requests that util address Generic Ltr 88-17 re loss of DHR during non-power operation Ltr Issued due to potentially serious consequences resulting from In-adequacy of industry response to Generic Ltr 87-12 MURLEY, T.E. Office of Nuclear Reactor Hegulation, Director (Post 870411) 88/12/ 02 FERGUSON, J.H. Virginia Power (Virginia Efectic & Power Co.) 3pp. 47789.119-47789-121.
- 6812080032 Forwards environ assessment & finding of no significant Impact re applica-Ilon for amonds concerning containment air temp ENGLE,I. B. Project Directorate II-2. 88/12/05. CARTWRIGHT,W.R. Virginia Powor (Virginia Electric & Power Co.). 2pp. 47753:203-47753:208.
- -9812080034 Environ assossment & finding of no significant impact revising Tech Specs re-containment air temp upper limit to 120 F & increasing required containment test pressure for integrated & focal leak rate tests pressure for current value BERKOW,H.N. Project Directorate II-2. 88/12/05. 4pp 47753-205-47753-208.
- 8812080038 Forwards Amonds 107 & 93 to Licenses NPF-4 & NPF-7, respectively & selety evaluation Amonde permit redesign of reactor coolent pump & steam generator

supports.
ENGLE.L.B. Project Directorate II.2. 88/12/05. CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 2pp. 47780.093.47780.106.

- -8812080041 Amonds 107 & 93 to Licenses NPF-4 & NPF-7 respectively, parmitting redesign of reactor coelant pump & steam generator supports since dynamic effects of postulated primary loop ruptures would be eliminated from design basis BERKOW,H.N. Project Directorate II-2 88/12/05. 4pp. 47780 085-47780.088
- ~8812080043 Safety evaluation supporting Amends 107 & 93 to Licenses NPF-4 & NPF-7,respectively.

 *Office of Nuclear Reactor Regulation, Director (Post 870411). 88/12/05. 8pp. 47780.099-47780.108.
- 8812120078 Forwards corrected Page 3/4 6-2 to Amend 92 to License NPF-7, changing ref from third lest to second test & delate ref to 10-yr ISI outage is footnote ENGLE.L.B. Project Directorate II.2. 88/12/06 CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 2pp. 47786:216-47766-220.
- -8812120088 Errata to Amend 92 to License NPF-7,changing raf from third tost to second test & deleting raf to 10-yr ISI outago in lootnote.
 * NRC No Detailed Affiliation Given. 88/12/06. 3pp. 47786-218-47785-220

- 8812130119 Forwards Amen'ts 108 8 94 to Licenses NPF-4 & NPF-7, respectively & salicty unablasticin Amends modify Section 3/4 6, "Contaminent Sys," to reflect use of mass point method for calculating containment leakage rates. ENGLEL B. Assistant Oxidotor Tor Region II Reactors 88/12/07. CARWAIGHT, W.R. Virginia Power (Virginia Electric & Power Co.). App. 47794-310-47794-339.
- #8812130120 Amends 108 & 94 to Licenses hPF-4 & NPF-7 respectively, modifying Section 374 6. "Containment Sys." to reflect use of mass point method for calculating containment teakage rates described in ANSI/ANS 55.8-187

 BERKOWHIN Assistant Ovector for Region II Reactors 88/12/07 15pp 47794/314-47794 327
- -8812130122 Safety evaluation supporting Amends 108 & 94 to Licenses NPF-4 & NEF-7, respectively
 Offices of Phylical Reactor Regulation, Director (Post 670411) 68/12/07 3pp.
 47784-326-47784-339
- 8812130144 Notification of 881208 meeting w/util in Rocky/lie,MD to discuss statistical DNB topical & moderator temp coefficient.
 ENGLEL Project Directorate II-2 88/12/07, MURKEY,TI NRC - No Detailed Afficiation.
 Given 3pp. 47797 122-47797 124
- 8812160092 Forwards Amends 109 & 95 to Licenses NPF-4 & NPF-7, respectively & salicty explaints a melement more stringent primary to secondary contant system that age I.m.s. & establish sunk l'ance requirements to assure operability. ENGLE LB Project Overchoste L. 2. 88/12/12. CARTWRIGHT, W.R. Virginia Power (Virginia Electric & Power Co.). 3pp. 47673-266-47873-308
- -8812160093 Amends 103 & 95 to Licenses NPF-4 & NPF-7 respectively, implementing straigent primary to secondary coolant sys leakage firmts & estatt-shing survollance requirements to assure operability of eurising instrumentation. BEAROW, ITN Project Directorate It 2: 88/12/12, 34pp. 47873, 269-47873, 302.
- -8812160094 Satisty evaluation supporting Amends 109 & 95 to Licenses NPF-4 & NPF-7 respectively.

 **Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/12 6pp 47873 303 47873 303 47873 303
- 8812220222 Forwards Amends 110 & 98 to Licenses NPF-4 & NPF-7, respectively &
- -8812220224 Amends 110 8 98 to Licenses NPF-4 & NPF-7 respectively, rewising Tech Specs re-containment air temp upper limit 8 vol of water available from refueling water storage tank for Quench specy sys. BERKOW,HIN Project Orectorale II-2 86/12/14 32pp 47900 133-47900 163
- -8812220227 Safety evaluation supporting Amends 110 & 96 to Licenses NPF-4 & NPF-7, respectively
 Office of Hudear Reactor Regulation, Director (Post 870411), 88/12/14, 11pp
 47900 164-47900 174
- -8812220228 Notice of issuance of Amerids 110 & 98 to Licenses NPF-4 & NPF-7. isspectively Amerids revise Tech Specs to confariment at temp upper limit & vol of water and able from refueling water storage tank for guench spray sys ENGLE, B Project Orectorate II-2, 68/12/14 2pp 47900-175-47900.176

Q. Inspection reports, IE Bulletins & correspondence

- 8811290019 Supplemental response to notice of violation from Insp. Repts. 50.338/88-16 & 50-339/88-16 providing additinto & status on enhancements to operating experience review program for facility. CARTWHIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 88/11/16. Document Control Brench (Document Control Dosk). 3pp. 47651:271-47651:273.
- 8811300438 Ack receipt of 881023 ftr informing NRC of steps taken to correct violations noted in Insp Repts 50-338/88-24 & 50-339/88-24 Ack util intent to submit amergency plan rev by 881120 which will address violation re staffing time. COLLINS,D.M. Region 2, Olic of the Director. 88/11/18. CARTWRIGHT,W.R. Virginia Power (Virginia Electric & Power Co.). 1p. 47681.042-47681.042
- 8811280210 Ack receipt of 880923 submittal of revised efficiency calibr data for three high purity germentum detectors located in count room of plant,per Insp. Repts 50-338/68-26 & 50-339/88-26 Caribr data currently being reviewed DECKER, F.R. Region 2, Otc. of the Director, 88/11/21, CARTWRIGHT,W.R. Virginia Power (Virginia Efection & Power Co.), 1p. 47655-343-47655-343.
- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list encl CUNNINGHAM,R E. Omision of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708.255-47708.257.
- 8811180467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests" Svc list enct.
 ROSSIC E. Division of Operational Events Assessment (Post 870411) 68/11/22.
- - p Repts 50 280/88 40.50 281/88 40.50-338/88 28 & 50-339/
 - violations or deviations noted. , Otc of the Director 68/11/23 CARTWRIGHT,W.R. Virginia Power Co.) 2pp 47750:119-47750:132.
 - 30/88-40,50-281/88-40,50-338/88-28 & 50-339/89-28 on eviations noted. Major areas inspected control room hab-
 - -a--- 2. Old of the Director. 88/10/26. 12pp. 47750.121-
- 8812010164 Forwards safety evaluation accepting ubit actions to resolve issues identified in NRC Buffetin 88-002, "Rapidly Propagating Fatigue Cracks in Steam Generator Tubes," subj to thit adopting addit administrative controls ENGLEL, B. Project Directorate II-2, 88/11/29 CARTWRIGHT, W.R. Virgina Power (Virgina Electric & Power Co.) 2pp. 47703.040-47703.045.

47750:132.

- -8812010166 Safety evaluation supporting I censor responses to NRC B "Rapidly Propagating Fatigue Cracks in Steam Generator Tubes," sub, I add admirestrative controls
 - agui acri in similiya controls

 "Office of Nuclear Reactor Regulation, Director (Post 870411) 8i
 47703.042-47703.045
- 8812220080 Requests approval of enct proposed revs to augmentation 5.1 of emergency plan in response to Insp Ropts 50.338/86.24 & 50.33 feet on for proposed revs also encl CARTWRIGHT, WR. Vrighta Power (Virgina Electric & Power Co.). 88 ment Control Branch (Document Control Disk). 14pp. 47903-022-47903
- 8811290030 NRC Into Notice 88:003, "Telatherapy Evants." Svc list enci CUNNINGHAM R.E. Division of Industrial & Medical Nuclear Sately (88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:1
- 8611290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actu NOSSI,CE Division of Operational Events Assessment (Post 8704) Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 25
- 8812070287 NRC Into Notice 88:095, "Inadequate Procurement Required by Licensees on Vendors". Svc list end:
 ROSSI,CE: Division of Opportational Events. Assessment (Post 8704; Consol dated Edison Co. of New York, Inc. 112pp. 47807:191-47897.30.
- 8812200339 Forwards Insp Repts 50-338/88-32 8 50-339/88-32 on 881 Intions or deviations noted
 HEADT, A.R. Region 2, Otc. of the Director 88/12/12 CARTWRIGH
 Power (Virginia Electric & Priver Co.) 2pp. 47906.280.47906.292.
- -8812200341 insp Repts 50:338/88:32 & 50:339/88:32 on 081114-18 h devations noted Major areas inspectatifier protection & JCO 88:30 Water/Header Leakage "No weakness in tire protection program identification, J. C. CONLON, T.E. Rog on 2, Ofc of the Director 88 47906 282-47906 292.
- 8812210237 Ack receipt of 881116 supplemental response to violations Repts 50:338788-16 & 50:339788-16 ERNST,ML, Region 2, Oto of the Director, 88712714, CARTWRIGH Power (Virginia Electric & Power Co.) 1p. 47876-232-47876

R. Periodic operating reports & related correspondence

- 8812200157 Month'y operating ropts for Nov 1088 for North Anna Power & 2 W/881213 ltr. GARNER, B., CAHTWHIGHT, W.R. Virgiria Powor (Virginia Electric & P 11/30 13pp. 47867:251-47867:263.

S. Reportable occurrences, LERs & related correspondence

8812010187 LEH 88:001:00 on 881104, steam driven auxiliary foedwater entry started while being removed from size for prophannod maint Causc error Steam supply isolated Humann performance evaluation underway Y KANE G.E. Virginia Power (Virginia Electric & Power Co.): 80/11/22: 5 47703.111.

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 8812070083 Rev 3 to Emergency Plan Implementing Procedure EP-54 mate of Core/Fuel Damage Based on Containment High Range Rad * Detrol Edison Co. 88/11/29, 8pp. 47930/2664-47930/273.
- 8812150160 Revised emergency plan implementing procedures.includin 301-02, "Technical Support Cir.Support Functions," Rev 4 to EP.301 Support Cir.' & Rev 4 to EP.110, "Organization & Responsibilities" FOLANO,M. Delroit Edison Co. 88/11/30, 21pp. 47830;189-47830;209
- 8812190082 Rev 7 to Radiological Emergency Rosponsa Planning Pla Procedure EP-102, "Unusual Event." ROLAND,M. Detroit Edison Co. 88/12/08, 7pp. 47840;140-47840;146
- 8812200088 Forwards Safety Insp Rept 50 341/88-32 on 801114-1
- GREGER, L.R. Region 3, Ofc of the Director, 88/12/08, SYLVIA, B.R. Co. 2pp. 47864:181-47864:191.
- -8812200076 Insp. Rept. 50-341/88-32 on 881114-17 No violation: noted Major areas inspected emergency preparedness program. FOSTER J. SNELL, W. Region 3, Otc. of the Director. 88/12/08 47864:191
- 8812200366 Forwards upgraded procedures generation peckage.includi ministrative Procedure NPP-PR1-03, "Emergency Operating Procedure Process" & WG-APP-E, "Fermi Writers Guide App E:Emergency Committee of the Co SYLVIA,B.R. Detroit Edison Co. 88/12/12 Document Control Branch (vol Desk), 4pp. 47863;081-47864;172.
- -8612200372 Rev 1 to Administrative Procedure NPP-PH1 03, "Emer Procedure Development Process" & Rev 0 to WG-APP-E, "Formi W E-Emergancy Operating Procedures" Detroit Edison Co. 88/11/29, 62pp. 47863.085-47863:145.
- -8812200374 Rev 0 to emergency operating procedure plan.
 * Detroit Edwan Co. 86/12/09, 350pp. 47863;146-47884;172.

H. General correspondence

8812010404 Comment on proposed rule 10CFH26 re Fitness for Duty Program including random drug testing Util endorses NUMARC comments on rule

* Detroit Edison Co. 88/11/17 Docketing & Services Branch. 10pp. 47679.209-

I Financial Information

8812090249 Forwards cortilind cash flow statement per 10CFR140.21 US. Dept of Agriculture 760429 & 0528 memos, which constitute Wolvering response to secondary limited protection requirements also encl. SYLVIA,B.R. Detroit Edison Co. 88/12/02. DINITZ,LP. NRC - No. Detailed Affination Given. 10pp. 47762-321-47762-333.

P. Operating license stage documents & correspondence

8811230336 Discusses Tech Spec changes for single loop operation Industry events involving BWR thormal hydraulic instability & associated activities indicated further Tech Spec changes be required as result of events & activities SYLVIA,8 Pt. Detroit Edison Co. 88/11/16 Document Control Desk). 1p. 47632-342-47632-342.

- 8811290525 Forwards AEOD diagnostic evaluation team rept for plant Rept documents toam Indings & conclusions STELLO,V. Oic of the Executive Director for Operations, 88/11/22, ZECH, ROBERTS, CARR Commissioners, 1p. 47662-250-47662-250
- 8811280048 Generic Ltr 88-20 to all licensees he'ding OLs & CPs for nuclear power reactor facilities re individual plant evam for severe accident vulnerabilities Svc 1st
 - oncl CRUICHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729.024.
- 8811300458 Responds to Generic Lir 88-11, "NRC Position on Radiation Embrittlement of Reactor Vissel Mally & Impact on Plant Operations." SYLVIA.8 R. Detroit Edison Co. 88/11/28. Document Control Dash. 20pp. 47676:158-47676.177
- 812090293 Confirms 881216 moeting in Newport,MI to discuss plant status schedules,Improvement programs & NRC commitments.
 GREENMAN.E.G. Rogion 3, Otc of the Director 80/12/05 SYLVIA,BIR Detroit Edison Co. 2pp. 47781:357-47781:358
- 8812120100 Nothins of change in startup tost program described in Chapter 14 of facility updated FSAR Change involves detelling flow-induced vibration test of RHR sys reactor vossel head spray piping within primary containment SYLVIA,8-R. Defroit Edison Co. 88112705 Document Control Branch (Document Control Branch (Docu trol Dusk) 3pp 47789 061-47789 063
- 8812090208 Forwards revised Rebet Request VR-46-R2 to insurvice testing program for pumps & valves. Isolation valves listed on encil reflect request cannot be individually
- leak rate tested. SYLVA.B.R. Douroit Edson Co. 88/12/06. Document Central Branch (Document Centrol Desk). 6pp. 47785-059-47785-064.
- 8612270214 Forwards Amond 29 to License NPF-43 & safety evaluation. Amend revises Tech Specs to clarify hitting condition for operation of 480 voll MCC 72CF swing bus STANGU, Project Directorate III-1, 88/12/15, SYLVIA,B.R. Detroit Edison Co. 3pp. 47925 398-47925 324.
- --8812270218 Amend 29 to License NPF-43,revising Tech Specs to clarify limiting condition for operation of 480 volt MCC 72CF swing bus CUAY,T. Project Directorate III-1, 88/12/15, 10pp. 47925,312-47925,321.
- --8812270219 Safoty evaluation supporting Amend 20 to Liconso NPF-43.

 * Office of Nuclear Resider Hegulation, Director (Post 870411), 88/12/15 3pp. 47925/322-17925/324.
- 8812270300 Application for amend to License NPF-43, changing Tech Spec 3/433 re ECCS actuation instrumentation Fee paid ORSER, W.S. Detroit Edison Co. 88/12/22. Document Control Branch (Document Control Desk). 26pp. 47926.216-47926:259.
- --8812270302 Proposed Tech Specs 3/4.3.3 ro ECCS actuation instrumentation Detroit Edison Co. 88/12/22, 18pp. 47926;242-47926;259.
- 8612270303 Application for amend to License NPF-43, revising Toch Spec Table 3.3.2-2 re condunser pressure-high containment isolation setpoint & allowable value. Fee pald. ORSER.W.S. Detroit Edson Co. 88/12/22. Document Control Branch (Document Control Dask). 7pp. 47927.026-47927.034.
- --8812270304 Proposed Tech Spec Table 3.3.2-2 re condenser pressure-high contament isolation setpoint & allowable value
 Dotroit Edison Co. 68/12/22, 2pp. 47827;033-47927;034.

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear
 - Gauges" Svc list encl
 CUNNINGHAM.R.E. Division of Industrial & Modical Nuclear Safety (Post 870729)
 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257.
- 8811180487 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tosts." Svc list end: ROSSIC.E. Division of Operational Events Assessment (Post 870411). 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708:142
- 8811300058 Forwards Insp. Ropt 50-341/88-08 on 880308-0920 & notice of violation. KNOP,R.C. Region 3, Olc of the Director, 88/11/23, SYLVIA,B.R. Detroit Edison Co. 2pp. 47675:219-47675 276
- --8811300060 Notice of violation from Insp. on 880308-0920. Violation noted engineering evaluations used to select diodes, valves & grains that were not safety-related for applications did not ensure critical characteristics satisfied requirements. KNOP,R.C. Region 3, Otc of the Director. 88/11/23. 1p. 47675:221-47675:221.

- -8811300062 Insp Rept 50-341/88-08 on 880308-0920.Violations noted Major areas Inspected circumstances relicensee actions in response to mail control allegations re-ported to NRC in Jan & Fob 1989 COOPER,R W. Region 3, Olic of the Director, 88/11/23 20pp, 47675 222-47675.241.
- --8804250252 Forwards results of util & S&W invastigations of elegations re-control practices discussed in NRC 880125 & 0212 ltrs.
 SYLVIA,B.R. Dotrott Edison Co. 88/04/19. Document Control Branch (Document Control Branch) trol Desk) 6np 47675 242 47675 276
- 8812060286 Ack receipt of 880429 ltr informing NRC of actions taken re allegations noted in NRC 880222 ltr concerning safeteam practices & hiring practices GREENMAN,E.G. Region 3, Otc of the Director 88/11/30 SYLVIA,B.R. Detroit Edison Co. 2pp. 47734 160-47734:161
- 8811290030 NRC Info Notice 88-093. "Teletherapy Events" Svc 1st encl. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811.103-47811:216
- 8811290538 NRC Info Notico 88-094, "Potentially Undersized Valve Actuators." Svc list ROSSI, G.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708:254
- 8812090260 Forwards Enforcement Conference Rept 50-341/88-34 on 881118 re viola-Tigors noted in Insp Rept 50:341/88-25.

 MILLER, HJ Rog on 3, Otc of the Director 88/12/05 SYLVIA, B.R. Detroit Edison Co.

 2pp 47762.106.47762.111.
- --8812090262 Enforcement Conforence Rept 50-341/88-34 on 881118 Major grees discussed apparent violations to 10CFR50,App B identified & infor pertnent to cause,extent,treatment & corrective action to provent recurrence of problems EICK,S.,SMITHJF, HARRISON,JJ Region 3, Ofc of the Director 88/12/05 4pp. 47762.108-47762.111.
- 8812120085 Forwards Safety Insp Rept 50-341/88-29 on 881018-20, 1031-1103 & 1109 No violations noted HARRISON,J.J. Ragion 3, Otc of the Director, 88/12/06, SYLVIA,R.B. Detroit Edison Co 2pp 47791:341-47791:350
- --8812120087 Insp Rept 50:341/88:29 on 881018:20,1031-1103 & 09 No violations or deviations Identified Major areas Inspected I.censee compliance w/ATWS deviations Identified Major areas Inspected Leensee compliance w/ATWS rule, 10CFR50.62 WESTBERG,R.A., GARDNER,R.N. Region 3, Old of the Director. 88/12/05. 8pp. 47791.343-47791:350.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svc list and ROSSLC E Division of Operational Events Assessment (Post 870411), 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807-191-47807-302
- 8812200068 Forwards Safety Insp Rept 50:341/89:32 on 881114-17 No violations noted. GREGEH,L. R. Reg on 3, Ofc of the Director. 88/12/08. SYLVIA.B.R. Defroit Edison. Co. 2pp. 47864-181-47864-191.
- -9812200075 Insp Repl 50:341/88:32 on 9B1114:17.No violations or deviations noted.Major areas inspected emergency preparedness program. FOSTER,J., SNELL,W. Rog on 3, Oic of the Director. 88/12/08. 9pp. 47864:183-47864:101.
- 8812130026 Responds to NRC 681104 ltr ra violations noted in Insp Rept 50-341/88-17.Corrective actions:new administrative procedure developed & improvements being made to surverlance scheduling & tracking data base SYLVIA,B.R. Dotroit Edison Co. 88/12/09. Document Control Branch (Document Control Desk). 12pp. 47794:116-47794.127.

R. Periodic operating reports & related correspondence

- 8812270091 Forwards monthly operating rept for Nov 1988 & rev to Oct monthly operating rept for Fermi 2.
 ORSER,W.S. Detroit Edison Co. 88/12/15. Document Control Branch (Document Control Dosk), 2pp. 47924 197-47924:204.
- -8812200300 Monthly operating rept for Nov 1988 for Fermi 2 ANTHONY,P.M. Detroit Edison Co. 88/11/30, 3pp. 47924:198-47924:201.
- --8812270098 Revised monthly operating rept for Oct 1988 for Fermi 2. ANTHONY, P.M. Detroit Ed.son Co. 88/10/31, 1p. 47924:202-47924:202.

S. Reportable occurrences, LERs & related correspondence

- 8811290087 LER 87-010-01:on 870403,discrepancies in reactor operator regulatication training discovered.Caused by inadequate administration of pest requalification pro-gram. Requalification administrator guidet rovised W/881118 ltr. ANTHONY,P., ORSER,W.S. Detroit Edison Co. 88/181/1/18. 4pp. 47864:087-47884:070.
- 8812140266 LER 88-036-01:on 881108,off-duty operations shift feiled to properly per-form startup checklist & daily plant surveillances per Tech Spec 3 8.4.1. Supervisor de-energized breakers & personnel disciplined W/881208 Ler ANTHONY,P., ORSER,W.S. Detroit Edison Co. 88/12/08. 5pp 47813:331-47813:335.
- 8812140265 LER 88-026-01:on 880720,increase in unidentified leakage in drywell noticed Caused by valves w/scored stems Both valves had their stems replaced & both valves repacked W/881208 ltr.
 ANTHONY,P., ORSER,W.S. Detroit Edison Co. 88/12/09. 4pp. 47621:044-47821:047.
- 8812200285 LER 87-048-09:on 971008,svc,turbine & radwaste bldg ventilation radiation monitoring sys channol functional test surveillance procedures did not specify testing of nonrunning exhaust fans.Procedures revised W/881215 ltr. NADER,G., ORSER,W.S. Datroit Edison Co. 88/12/15. 28pp. 47881:020-47861:047.

U. Congressional/Executive Correspondence

- 8811170122 Responds to 880927 request for review & commant of R Mand of rept NRC reviewed tept & concludes that no new safety concerns known or not being adequately addressed by ficensee improvement program.UTI committed to correct deficiences ZECHL.W. Commissioners 88/11/10 DINGSULJ.D. Poiss of Rep. Energy & Commerce 4pp 47567;180 47567.168
- --8812080064 " Fermi II Problem Introduction." HUTCHINSON,W B. Nor Research Institute -88708/12, 75pp. 47792 339-47793 052

DOCKET 50-344 TROJAN NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

- 8812050021 Rev 4 to Red ological Emergency Response Plan Implementing Procedure EP-130, "Emergency Operations Facility."
 * Portland General Electric Co. 88/11/11, 140pp. 47733 013-47733 152
- 8811230237 Raylsed emergency plan implementing procedures including Ray 2 to Figure 003 6 of EP-002,Roy 2 to Figure 003 1 to EP-003,Roy 3 to Figure 100-3 of EP-100 & Roy 3 to Figure 101-8 of EP-101.
 *Portland General Electric Co. 89/11/15, 16pp. 47631 204-47631.218.
- 8811280044 Forwards final ropt for 871014 exercise of offsite radicity callemonguing response plans for plant Nineteen deficiencies observed in exercise FEMA resorves right to invoke 44CFR350.13 pending results of 881116 exercise KRIMMRW. Federal Emergency Wanegement Agency 88/11/16 CONGEL.F.J. D.w. son of Rediation Protection & Emergency Preparedness (Post 870411) 2pp. 47652-305-476512-67.
- -8811280051 Forwards memoire status of corrective actions for 871014 exercise of off-Ste plans & preparadnoss for plant KRIMMA W. Federal Emergency Management Agency 88/04/19 Division of Rad-align Protection & Emergency Preparadness (Post 870411). 4pp. 47652/307-47652.310.
- ~8811280059 Final rept of 871014 exercise of offsite radiological emergency response Plans for plant.
 Federal Emergency Management Agency 88/06/30 313pp 47652 311-47653 2e7
- 8812090177 Forwards results re-review of fire protection mods per Amend 22 to 11-cense NPF-1 & violations noted in Insp Rept 50:344/88-17 concerning fire protection program implementation COCKF:ELD.D.W. Portland General Electric Co. 88/11/30. Document Control Branch

H. General correspondence

- \$12020023 Commants on proposed rule 10CFR28 to Fitness for Duty Program NUMARC recommondation that proposed 300% sample size occassive & that 100% annual sample size will be sufficient supported COCKFIELD, W. Portland General Electric Co. 88/11/21. Docketing & Services Branch 4pp 47679,352-47679;355.
- P. Operating license stage documents & correspondence

(Document Control Desk), 6pp. 47761:279-47761:284.

- 8811380253 Forwards notice of withdrawal of portion of 861219 application for amend changing Tech Space 3.3.5, "Remote Shutdown Instrumentation." BEVAN,R. Project Directorate V 88/11/18 COCKFIELD.D.W. Portland General Electric Co. 3pp. 47678:118-47876;121.
- -8811300258 Notice of withdrawal of partion of 861218 application for amond to incense change Tech Spec 3.3.3.5 or remote shutdown instrumentation BEVAN,R. Project Directorate V. 88/11/16 [p. 47676.121-47676.121.
- 8811260048 Generic Ltr 88:20 to all tidensees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnerabilities Syc list

enct.
CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consoldated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024.

- 8812050302 Forwards response to Generic Ly 88-11, "NRC Position on Radiation Era-brittlement of Reactor Vessel Matis & Impact on Plant Operations" using methodology DRIGHT 10 Reg Guide 1.99.

 COCKFIELD,D.W. Portland General Electric Co. 88/11/30 Document Control Branch (Document Control Desk), 14pp. 47740:263-47740-278
- 8812070234 Summary of 881110 meeting w/ulil & B&W to discuss use of B&W m/g fuel at facility Handouts from meeting & list of attendees enci.
 BEVANIR B. Project Directorate V. 88/11/30. Project Directorate V. 23pp. 47748:276-
- 8812070068 Requests extension for Installation of ATWS mitigating systactions circuit-ry (AMSAC). Util proposes to complete installation of AMSAC during 1990 refueling outage (approx Jul 1990). COCKFEED.D. W. Portland General Electric Co. 88/12/02 Document Control Branch (Document Control Desk). 2pp. 47745-240-47745:241.
- 8812140174 Documents vorbal responses to NRC re handing of SNM associated w/
- repair of fuel assemblies.

 COCKFIELD,D.W. Portland General Electric Co. 88/12/02. MARTIN,J 0. Region 5, Otc of the Director. 2pp. 47600:204-47800 205.
- 8812150229 Requests response to Generic Ltr 88-17 re foss of DHR. Deliciency of in-dustry response to Generic Ltr 87-12 in areas including prevention of accident initi-ation & mitigation of accidents before core fragulation, Director (Post 870411) 88/12/ 02. SHORT,R H. Portland General Electric Co. Spp. 47829:206-47829.208.
- 6812130196 Informs that tentative date of 881215 scheduled for presentation of license cardicates and 130 totoon.

 PATE,R.J. Region 5, Ofc of the Director. 88/12/05 NICHOLS,S. Portland General Electric Co. 2pp. 47794;079-47794;080.

- 8612190209 Responds to 880914 requestive transcends of commercial grada tensin safety-related applications Finding given in thisp. Rept. 50:344768-39 a; poars to be repeat of they conflucted in 1995 Escalated office or more action recommended VIRIGILIO,M.J. Assistant Oracter for Region III. & Region V. Reactors. 8971272 KIRSCH,D. Region 5, Otc. of the Director. 3pp. 47852-093-47852-095.
- 8812210349 Advises that submittal of Ciconin. Change Application 161 re upgrade the design reschinduled from 881215 to 890215 Debuy necessitated by contractor id/ficult, in completing analysis of locked rethrovent on schedule COCKFIELD,D.W. Perittand General Electric Co. 8912/16. Document Control Braich (Document Control Dask), 1p. 47876 022-47876 022.
- 8812270163 Amond 2 to PGE-1043, "Accident Monitoring Instrumentation Review"

 * Portland General Electric Co. PGE-1043, A 02, 88712731, 195pp. 47823 (4) 47923.345

Q. Inspection reports, IE Bulletins & correspondence

- 8811290023 Rosponds to NRC 881020 fit re-violations noticed in Insp. Rept. 59 (4478) 34 Corrective actions weatherized portable lanterns w/6 in power supplies provided in dodicated indoor storage locations & plant procedures revised COCKFIELD,D.W. Porlland General Electric Co. 88/11/18. Document Control Branch (Document Control Dusk), 3pp. 47650.136-47650.138
- 8811160211 NRC Info Notice 88 090, "Unauthorized Removal of Industria" Nucleur Gaugos: Svc list encl CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Satety (Post 670720): 88/11722. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255 47708 257.
- 8811160467 NRC Info Notice 88-891, "Improper Administration & Control of Psychological cal Tests," Svc list encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 80/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142
- 8812050176 Forwards "Inscrivice trisp Rept Trojan Unit 1 Nuclear Generating Plant's: First Panod Second Interval NDE ASME Section XI Regulated Exams," Vol 1-4, COCKFIELD.D.W. Portland General Electric Co. 88/11/39. Document Control Branch (Document Control Dask) 2pp. 47724-010-47728-302.
- -8812050178 "Inservice Insp. Rept. Trojen Unit 1 Nuclear Generating Flent for Feel Period Second Interval NDE ASME Section XI Regulated Exems" on 880413-071015; consisted of exam of components piping & supports Rept consists of four vols. * Portland General Electric Co. 88/10/31, 1,731pp, 47724-012-47728-302.
- 8812050313 Informs that roy to Topical Rept PGE-1049, "Trojan Nuclear Plant Inserved Insp Program for Second 19-Yr Inforwal" detayed until 890131 due to extensive roy COCKFELD,DW Portland General Efection Co. 88/11/30 Document Control Branch (Document Control Dosk), 1p. 47740 186-47740 186
- 8812090177 Forwards results re-review of fire protection mods,pur Amenial 22 to to cense NPF-1 & violations noted in Irisp Ropt 50-344/88-17 concerning fire protection program implementation COCKFIELD,D.W. Portland Genural Electric Co. 88/11/30. Document Control Braic' (Document Control Dosk). 6pp. 47761 279-47761 284
- 8811290830 NRC Info Notice 88-093, "Tolothorapy Events." Svc. list encl. CUNN'NGHAM,R.E. Division of Industrial & Modical Nuclear Saloty (Post 870720) 88/12702 Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47011:213
- 9811290538 NRC Into Notice 88 984, "Potentially Undersized Valve Adicators" Svc list encl. ROSSICE Division of Operational Events Assessment (Post 870411), 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708.143-47708.254
- 8812200089 Forwards Insp. Rept. 50-344/88-30 on 880926-1007 & notice of violation Maint process for plant improved & reflects continuing organizational & program improvements, but program could be further strongthened.

 MARTIN,J.B. Reg. on 5, Offic of the Director, 88/12/02 COCKFIELD,D.W. Portland General Electric Co. 6pp. 47862-246-47862-318.
- -8812200094 Notice of violation from inspirent 880926-1007.Violation noted flow Indicators for see water pump bearing water not call to prior to performance of any Inservice teating of see water pumps
 MARTIN,J.B. Region 5, Otc of the Director, 88/12/02, 4pp. 47862:252-47862:255
- -8812200098 Insp Rept 50:344/88:30 on 880928:1007.Violations incled.Major areas Inspoted that it program & impfementation of related activities MCLAUGHLINP, HOCKER,C., BURDOIN,J. Region 5, Ofc of the Director, 88/11/25 57pp. 47862:256-47882:318.
- 8812190209 Responds to 880914 request relicensee use of commercial grade items in safety-related applications Finding given in Insp. Rept. 50-344/88-39 appears to be repeat of insp conducted in 1995. Escalated enforcement action recommended. VIRGILLO,M.J. Assistant Director for Region III. & Region V. Roactors. 88/12/07. KIRSCH,D. Region 5, Ofc of the Director. 3pp. 47852-093-47852-095.
- 8812020287 NRC Info Notice 88:095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" Svc list encl. ROSSI, CE. Division of Operational Events Assessment (Post 870411) 88/12/08. Consolidated Edison Cn. of New York, Inc. 112pp. 47807;191-47807;302.
- 8812180046 Responds to NRC 881103 ltr re violations noted in Insp Rept 50-344/88-40.Corrective actions ladder in control bldg switchgear room removed & returned to tool issue room & plant surveyed for ladders not meeting requirements. COCKFEED.D.W. Portland General Electric Co. 88/12/12. Document Control Branch (Document Control Desk). 9pp. 47830:312-47830:320.

S. Reportable occurrences, LERs & related correspondence

8811290581 LER 88:040:00 on 881024.contritugal charging pump mechanical shall seal discovered leaking at rate of 2400 cubic cantimoters/ii Causo unknown Seal replaced & pump returned to svc Action plan influeted W/881123 tr
KERSIKUL.8. OLMSTEAD.C.A. Portland General Electric Co. 88/11/23 4pp 47667:194-47667:197.

- Tech Spec 3.0.3 entered Caused by intentional closure of valve MO-8813 due to loose metal plate attached to stem of valve W/881128 ltr.
 KERSHUL,B., OLMSTEAD,C.A. Portland General Electric Co. 88/11/28 4pp.
 47740 178-47740
- 8812050210 LER 88.042-00 on 881029,instrument air pressure 98 psig 8 decreasing white containment air pressure increasing Caused by poor workmanship on soldered joint Temporary repair made to rupture joint using nylon strap & tile wire.W/881128 ftr BOWMAN,S.W. OLMSTEAD,C.A. Portland General Electric Co. 88/11/28. 4pp. 47730.261-47730.264.
- 8812210365 LER 88-043-00 on 881113,reactor Impood this to turbine trip on highlisteam generator fevel Caused by main feedwater regulating valve controller fature following power supply failure Emergency Instruction 0 performed.W/881213 ling GUBERSKI,J.D., OLMSTEAD,C.A. Portland General Electric Co. 88/12/13 Rpp 47875.042-47875-049
- 8812210061 LER 88-044-03 on 881114,auxiliary feedwater sys actuation occurred on to for steam generator fevel w/plant in Mode 3. Caused by personnel error in lutting steam generator level got too low.Plant procedures revised.W/881214 ftr. GUBERSKI,J., OLMSTEAD,C.A. Portland General Electric Co. 80/12/14, 4pp 47881:349-47881:352.

V. Operator Examinations

- 8812140056 Forwards revised agends for annual operator licensing miceting on
 - PATE R.J. Region 5, Oic of the Director 88/12/05, NICHOLS,S. Portland General Electric Co. 1p. 47798.093-47706.003.
- 8812210286 Advises that written & oral operator exams scherfuled for 890620 & 0621-23,respectively. List of ref mall requirements for reactor/senior reactor operator Bronsсоинарусство от ген man requirements for reactor/senior reactor operator Econs-ing exams & related into enct BICHAROS,S A. Region 5, Otc of the Director, 88/12/15, COCKFIELD,D.W. Pertland General Efective Co. 9pp. 47876

DOCKET 50-346 DAVIS-DESSE NUCLEAR POWER STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8811300122 Change C-1 to Rev 2 to Emergency Ptan Implementing Procedure HS-EP-02520, "Assembly & Accountabliny." * Toledo Edison Co. 88/10/28, 36pp. 47675:277-47675:312.
- 8811300125 Change C-1 to Rev 3 to Emergency Plan Implementing Procedure HS-EP-02010, "Emergency Mgt." W/Rev 31 to table of contents. WASILK,J.S. Tolado Edison Co. 88/11/20. 35pp. 4767/:344-47678:018.
- 8811300525 Forwards Safety Insp. Rept. 50-346/88-34 on 881101-03 No violations noted GREGER,L.R. Region 3, Ofc of the Orrector. 88/11/21, SHELFON,D. Toledo Edison Co. 2pp 47676:239-47676-262.
- --8011300531 Insp Rept 50:346/88:34 on 881101-03:No violations nate: Major great inspected 1988 emergency proparetiness exercise (IP 82301);motiving observations of four NRC insps on most of facilities, equipment & personnel Involved in exercise PLOSKI,T., PATTERSON,J., SNELL,W. Roglon 3, Ofc of the Director. 88/11/18, 22pp 47676:241-47676:202.
- 8812120192 Discusses schedule to complete fire protection corrective actions Util does not consider sale operation of plant to be gooperfized pending completions Util does not consider sale operation of plant to be gooperfized pending completion of necessary corrective actions resulting from NFPA Code review.

 SHELTON,D.C. Toledo Edison Co. 88/12/02. Document Control Branch (Document Control Dosk). 5pp. 47786:309-47786.304.
- 8812070088 Rev 12 to emergency plan Sections 5 & 9.
 * Tolado Edison Co. 88/12/16 57pp 47748:019-47748.075.

- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities.Svc 1st
- CRUTCHFIELD,D. Associate Director for Projects (Past 870411) 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47/28 303-47729:024.
- 8811290428 Advisos that 881005 Rev 8 to QA program description most requirements of 10CFR50,App. 8.Contirms 881108 telcon to 881021 proposal to reduce commitments concerning restructure of anginearing assurance function.

 MILLER,11.3. Region 3, Dic of the Director. 88/11/25, SHELTON,D. Toledo Edison Co. 2pp. 47648;170-47648;171.
- 8811300098 Forwards signed original order modifying license issued to util on 881121 for transmittal to FR for publication W/o encl. LIEBERMAN,J. OIc of Enforcement (Post 870413), 88/11/25, LESAR,M.T. Regulatory Publications Branch, 1p. 47701:347-47701:347.
- 8812050307 Responds to Generic Lir 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Matts & Impact on Plant Operations." Temp limits revised in Amend 118 to License NPF-3 based on draft Rev 2 to Rog Guido 1.99. SHELTON, D.C. Toldob Edsaor Co. 88/11/28. Document Control Branch (Document Control Desk). 1p. 47734:152-47734:152.
- 8812120249 Forwards application for amend to License NPF-3, revising Tech Specs to
- rouwards appreciation for amend to License Ni/f--3,/evising 10ch Specs to reduce reactor protection sys reactor coolant low pressure trip setpoint & modifying variable low pressure setpoint Fee paid.

 SHELTON,D.C. Toledo Edison Co. 88/12/01. Document Control Branch (Occument Control Dask). 2pp. 47798.009-47798:046.
- --9812120251 Application for amend to License NPF-3 revising Tech Spacs to reduce reactor protection sys reactor coolant low pressure trip setpoint & modifying variable low pressure setpoint. SHELTON,D.C. Toledo Edison Co. 88/12/01. Document Control Branch (Document Control Desk). 27pp. 47798 011-47798.036.

- pressure trip salpoint & correspondingly modifying reactor protection sys variable low pressuro setpoint * Toledo Edison Co. 88/12/01, 10pp 47798 037-47798 046
- 8812070116 Requests that util address concerns in Generic Ltr 88-17 re loss of DRR during nonpower operation NRC belief is that industry as whole has not aggressively responded to resolve concern following identification in Generic Ltr 87-12. MRREY.T.E. Office of Nucloar Reactor Regulation, Director (Post 870411), 88/12/02. EDELMAN,M. Toletlo Edison Co. 2pp. 47749 226-47749-227.
- 8812120028 Requests NRC concurrence w/approach of performing Cycle 7 LOCA max Linear heat ratio calculations using TACO3 in fluur of purforming confirmatory calculation for Cycle 6 by 881230.
 SHELTON,DC. Toletto Edison Co. 88/12/02, Document Control Branch (Document Control Dusk), 2pp. 47780,162-47780.183
- 8812120030 Provides status of corrective actions taken & planned for auxiliary feed-water sys components.Governor valve parts will be replaced every 5 yrs SHELTON,D.C. Toteth Edison Co. 88/12/02 Document Control Branch (Document Control Desk). 3pp. 47789 155-47780.157.
- 8812130277 Forwards environ assessment & finding of no significant impactine 880220 application for amond to Licensh NPF-3 to revise steam & feedwater rupture control sys main steam tow pressure block permit suppoint DE AGAZIO.A.W. Project (Trectorate III.3 88/12/02, SHELTON,D.C. Toledo Edison Co. 2pp. 47796:007-47706.012.
- --8812130278 Environ assossment & finding of no algorithm and impact supporting amend to License NPF-3. DE AGAZIO,A W. Project Directorate til 3: 88/12/02: 4pp. 47796 009-47796.012.
- 8812140010 Provides into to history & resolution of discrepancy concerning 100% rated thermal power fived parameter usual in BAW-10075, "Multimode Analysis of Small Breaks for B&W 177. Fuel Assumbly Nuclear Plants W/Haised Loop Arrangement." SHELTON,D.C. Tollede Edison Co. 88/12/05, Document Control Branch (Document Control Dosk), 3pp. 47799,298-47799.298 8812090201 Provides addl into re 880304 request to revise main steam safety valve ca-
- pacity/high flux trip solpoint rolationship SHELTON,D.C. Tolodo Edison Co. 88/12/88, Document Contro! Branch (Document Control Desk), 2pp. 47785-965-47785-966 8812130159 Forwards Amend 125 to Liconso NPF-3.Amend revises Tech Spec
- 3.3.2.2, Table 3.3-13 ro steam & feedwater rupture control sys, turbing step valve closure time & associated bases sections.
 DE AGAZIO,A.W. Project Directorate III-3. 88/12/07. SHELTON,D.C. Toledo Ed son Co. 4pp. 47792 089-47792.100.
- -8812130165 Amond 125 to License NPF-3,changing Tech Spoc 3.3.2.2,Table 3.3-13 re steam 8 feedwater replace control sys response times HANNON,J.N. Project Directorate III-3. 88/12/07, 9pp. 47792 093-47792.100.
- 8812090239 Forwards safety evaluation re-util 870403 rehability analysis for auxiliary feedwater sys UN should ghours that sys mode do not result in net reduction in sys
- толирину. DE AGAZIO,A.W. Project Directoralo III-3. 88/12/08. SHELTON,D.C. Tolodo Edison Co. 3pp. 47762:256-47782.273.
- -8812090240 Salety evaluation re util response concerning auxiliary foodwater sys reli-ability study.Util should ensure that sys mode do not result in nat reduction in sys reliability.
 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/12/08. 15pp.
- 47762:259-47762.273.
- 8812130200 Forwards environ essessment & finding of no significant impact re 880201 application for amend to License NFF-3, changing setpoints for reactor high pressure trip, PORV trip & antic pationy reactor trip sys arming DEAGAZIO,A W. Project Directorate III-3, 88/12/08, SHELTON,O.C. Toledo Edison Co. 2pp. 47797:224-47797:229.
- --8612130202 Environ assessment & finding of no significant impact in amond to Li-cense NPF-3, changing satpoints for reactor high pressure trip, PORV trip & anticipatory
- reactor trip sys arming COLBURN.T.G. Project Directorate III-3, 88/12/08, 4pp. 47797:226-47797:229. 8812160089 Notification of 881221 meeting w/util,Quadrex HPS,Inc & listed others in Rockville,MD to discuss proposed approach to disposal of PCB contaminated,very low
- FIGURATION TO INSCREEN INTRODUCTION OF THE BOOK OF THE CONTRIBITION OF THE BOOK OF THE CONTRIBITION OF THE BOOK OF THE CONTRIBITION OF THE CONTRIB
- 8812220326 Forwards Amend 126 to License NPF-3.safety evaluation & notice of Issuance Amend revises Table 3.3-11.Section 3.3-2.2, "Steam & Feedwater Rupture Control Sys Instrumentation" DEAGAZIO,A.W. Project Directorate III-3. 88/12/19. SHELTON,D.C. Toledo Ed.son Co. 2pp. 47918-173-47916-185
- -8812220330 Amend 126 to License NPF-3, revising Tech Spec Table 3.3-11, Section 3.3.2.2 re steam & feedwater rupture control sys instrumentation. HANNON, J.N. Project Directorate III-3, 88/12/19, 5pp. 47916:175-47916.179.
- -8812220335 Safety evaluation supporting Amend 126 to License NPF-3.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/19, 4pp 47916:180-47916:183.
- -8812220337 Notice of issuance of Amend 126 to License NPF-3, revising Tech Spec Table 3.3-11 re steam & feedwater rupturo control sys instrumentation. DE AGAZIO,A.W. Project Directorate III-3, 88/12/19, 2pp. 47916.184-47916-185

Q. Inspection reports, IE Bulletins & correspondence

- 8811300352 Forwards All egation Insp.Rept 50 346/58-17 on 880412-0916 file violations noised MORELUISICE Region 3, Ofci of the Director 88/11/17, SHELTON,D. Toledo Edison Co. 26p. 47676 210-47676 220
- #8811300357 Inspilent 50 346/88.17 on 880412-0916 No violations noted. Allegation respectively additional duals inappropriately placed in util employee assistance program 8/or placed on prantial energy access list for continuing mgt policies. NYCELEY_JR_CREED_JR_Region_1, Ordio III the Director 88/10/27 9pp 47676.212-47676.220
- 8811290342 Forwards Safety Insp. Rept. 50-346/88.32 on 880312-1103 No. violations incled. NIOD-RIC Region 5, O'c of the (Mector 88/11/21 SHELTONIO To'edo Edison Co. 200. 47664.233 47664.254
- -8811290344 Insp. Rept. 50:346788-32 on 880912-1103 No violations or deviations noted Major areas inspected bleensee actions on previous insp. findings. & review of series of all egations religion of facility.

 DEFAYETTE, R.W. Region. 3. Ord of the Director. 68/11/10 12pp. 69425-114-69425-116.
- -8808020344 Responds to NRC 680614 ltr containing a legations reliablemente to painting/coatings procedures 8 use of knives 8 hacksaw blades in installation of electrical conduit sealant. SHET0NDIC Totedo Edison Co. 88/07/22 Document Control Branch (Document Control Dosk), 3pp. 47664 249-47664 254.
- 8811300525 Forwards Safety Insp. Rept. 50-348/68/34 on 881101-03 No violations noted. GREGER,L.R. Region 3, Otc of the Director, 88/11/21 SHELTON,D Toledo Edison Co. 2pp. 47676 239 47676 262
- -8811300531 (nsp Rept 50-346/88.34 on 681101-03 No violations noted Major areas inspected 1958 emergency preparedness exercise (IP 82301), involving observations of four NRC interps on most of fact test equipment & personnel involved in exercise PLOSKLT, PATTERSON, J., SNELL, W. Region 3, Ofciof the Director 88/11/18, 22pp 47676 241-47676 262.
- 8811300553 Forwards Safety Irisp Rept 50:346/88/24 on 880804-1020 & notice of viotation WRIGHT.G.C. Pegron 3, Otc of the Director 88/11/21, SHELTON,O. Toledo Edison Co. 2pp. 47676 124-47676 154
- -8811300555 Notice of violation from inspiron 680804-1020 Violation noted ticensed failed to document or resign three refests consisting of Steps 6.4.1-6.4.17 of Procedure DB PF-10050 WRIGHT.G.C. Region 3, Ofcicil the Director 68/11/21, 3pp. 47676-126-47676-128
- -8811300558 Insp Rept 50-346/68/24 on 880804-1020 volations noted. Major areas inspected post mod procedure review 8 tests witnessing containment integrated feak rate test (CLRT). CLRT procedure review test witnessing 8 evaluation. MENDEZR. PriLLLPS M.P. Region 3, Old of the Director 88/11/18 19pp. 47676-129-47676-13.
- 8811160211 NRC Into Notice 88:090. 'Unauthorized Removal of Industrial Nuclear Gauges' Size list enct. CUNNINGHAM RE. Drivis on of Industrial 8 Medical Nuclear Safety (Post 870729). 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257.
- 8811160467 NRC Info Notice 68-091, "Improper Administration & Control of Psychological Tests" Suc 1st end: ROSSIGE Division of Operational Events Assessment (Post 870411), 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.
- 8811290373 Forwards Safety Insp Rept 50:346/88:26 on 880816-0930 No violations noted Little progress in implementing requalification training program for simulator scenario development & exercise evaluation noted GREENMAN,E.G. Region 3, Otc. of the Director, 88/11/23, SHELTON,O. Toledo Edison Co. 2pp. 47664-215-47664-232
- --8811290374 Insp. Rept. 50:346/88:26 on 880816-0930 No violations or deviations noted Unresolved items. & weakness noted Major areas inspected operational safety verfications, maint, surverlance, LERs, Icensee events & quality verification.

 DEFAYETTE, R. W. Region. 3. Oic of the Director. 68/11/10. 16pp. 47684:217-47664:232
- 8811290376 Forwards Safety Insp. Rept. 50-346/88-35 on 881003-28.No violations noted on the Communication of the Director Ref. 11/23. SHELTON, D.C. Toledo Edison Co. 2pg. 47665-176-47665-188.
- -8811290377 Insp Rept 50:348/88:35 on 881003-28 No violations noted. Major areas inspected allegation reloperation of facility. DEFAYETTERW FARBER,M J. Region. 3, Ofc. of the Director. 88/11/16, 6pp. 47665-176-47665-189.
- 8812050140 Confirms NRC Reg Guide 1.97 insp on 881212-16 te post-accident monitoring instrumentation established during telcon between B Shingleton & MJ Kopp Requests to submit documents listed HARRISON.J.J. Region 3, Otc of the Oirector. 88/11/29. SHELTON.D. To'edo Edison Co. 2pp. 47733 292-47733 293.
- 8812050209 Submits hated documents to support audit of implementation of IE Bulletin 79:27, "Loss of Non-Class 1E instrumentation & Control Power Sys Bus During Operation" SHELTON 0 C Toledo Edison Co. 88/11/30. Document Control Branch (Document Control Desk). 4pp. 47733-158-47733.161.
- 8812060308 Forwards altegations re activities at plant for review & followup. Response requested should investigation identify potential safety or regulatory issue Encl withheld (ref. 10CFR2 789).

 GREENMAN.E.G. Region 3, Dic of the Director. 88/11/30. SHELTON,D. Toledo Edison Co. 1p. 47743.162-47743.162

- 8811290030 NRC Into Notice 88:093, "Telethorapy Events." Svc tist enci CUNNINGHAM.R.E. Dursion of Industrial & Medical Nuclear Safety 88/12/02. Conscidated Edison Co. of New York, Inc. 112pp. 47811
- 8811290538 NRC Info Notice 88-894, "Potentially Undersized Valve Actuant ROSSIC E Division of Operational Events Assessment (Post 8704 Consocidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 25
- 8812020287 NRC Into Notice 88-085, "Inadequate Procurement Required by Licensess on Vendors." Svc list onci.
 ROSSLC E. Dwisten of Operational Events Assessment (Post 8704 Conscidated Edison Co. of New York, Inc. 112pp. 47807-191-47807-30
- 8812160062 Forwards Safety Insp Rept 50:346/R8:36 on R81116:21 or operating procedures technically correct & operators trained to use pro-approved issue. WRIGHT, G.C. Region 3, Ofc. of the Orector, 68/12/12, SHELTON,D. Co. 2pp. 47830:356:47831:009.
- -8812160087 Insp Rept 50-346/88/36 on 881110-21 No violations note inspected heansee varidation & verification of operating procedures, we procedures & witnessing of procedure reval/dation WRIGHT,G.C. Region 3, Otc of the Director 887/12/12 12pp 47830:
- 8812270040 Forwards Insp. Ropt. 50:346788-29 on 880912-23,1003-07 & v.o'ation Concerns relievel of mgt altontion to woaknesses including trement la lures,root cause analysos & problem Identification exprussed MILLER, MJ. Rogion 3, Otc of the Oirector. 88712716. EDELMAN,M. Co. 3pp. 47945-187-47945-230.
- --8812270045 Notice of violation from insp. on 880912-1019 Violation in maint records inaccurate/incomplote & in some cases nonrotrievable MILLER,BJ Region 3, Ofc of the Director, U8/12/16 1p. 47945 190-47
- -8812270048 Insp Rept 50:346/88:29 on 880912:23,1003:07 & 19 Victor & weeknesses identified Major Breas inspected imaint support of maint activities. WALKER H.A., BONGIOVANNI, A., CARTER, T.H., Region 3, Ofc of the 12/16, 40pp. 47945:191-47945:230.

R. Periodic operating reports & related correspondence

- 8812200272 Monthly operating rept for Nov 1988 for Davia-Basse Nitch tion Unit 1 W/881214 lif. SARSOUR,B., STORZ,L.F. Toledo Edison Co. 88/11/30 6pp. 47860 3
- S. Reportable occurrences, LERs & related correspondence
- 8812150059 Revised special raption 870718,hru didlection z inoperable Caused by failed detactor in zone Addl administrative contributions supervisors reviewed incident to butter understand procedures to STOR2, F. Toledo Edison Co. 88/11/29, Document Central Branch (titrol Desk) 2pp. 47830;141-47930,142.
- 8812140195 LER 88-023-00 on 881206,16 Inch ITT Hammel (Jahl Corvelve found deliciont after review to Improve operation of size will 1434 Station Mod 88-0142 Initiated to modify valves SW 1424,1429 & 1 ft.
 - STOTZ,J.C., STORZ,L.F. Telado Edison Co. 88/12/10, 4pp. 47813.318

V. Operator Examinations

- 8811290373 Forwards Safety Insp. Ropt 50:346/88/26 on 880816-093 noted Little progress in implementing requalification training program for narto development & usercise evaluation noted GREENMAN.E.G. Regon 3, Ofc. of the Director 88/11/23. SHEL Edison Co. 2pp. 47684:215-47664-232
- ~8811290374 Insp. Rept. 50-346/88-26 on 880816-0930 No violations noted Unresolved Items & weakness noted Major areas inspected op ventications, maint, surveillance, LERs, I censee events & quality ventications PAYETTE, R.W. Region 3, Otc. of the Director. 88/11/10. 16(47864-232).

DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 6812060115 Forwards General Ofc Emergency Implementing Procedure document transmittal ack form.W/o and HARRIS,R. Alabama Power Co. 88/11/21. Region 2, Ofc of the 47741.163.47741-163.
- 8812050286 Forwards Insp Ropts 50-348/88-29 & 50-364/40-29 on 86 violations or deviations noted. VERRELLI,0 M. Region 2, Otc of the Director, 88/11/25, HAIRSTON Power Co. 2pp. 47731:251-47731:260.
- ~8812050290 Insp Repts 59:348/88:29 & 50:364/88:29 on 881011-11: or deviations noted. Major areas inspected review of oper verification, monthly surveillance observation, into meeting w/officials & ercise MAXWELL.G.F., MILLER,W.H., DANCE,H.C. Region 2, Ofc of the Dire 8pp. 47731 253:47731:260.
- 8812120227 Revised emergency plan implementing procedures includ FNP-0-EIP-16, "Emergency Equipment Supplies" & Rev 14 to FNP-0-1 gency Pian." W/881207 II/. HUDSPETH,J.B. Alabama Power Co. 88/12/07, 18pp. 47786.276-4778

109

8812200033 Flov 0 to Procedure GO-EIP-138. Procedure For ROLM Sys Reprogram m ng: 8 temporary chango review approval to Draft 1,Ruv 5A to Procedure GO-EIP-116, "Emergency Operations Facility Shift Turnover." W/881214 lir HAIRSTON,W.G. Alabama Power Co. 88/12/14, 16pp. 47858 269-47858 284.

H. General correspondence

- 8B12128050 Comment opposing proposed rule 10CFR2 re-submission & mgt of records & documents related to licensing of high level radwaste geologic repository.Ut.I supports EEI comments to be submitted to NRC.
 HAIRSTON,W.G. Alabama Power Co. 88/12/05. CHILK,S.J. Office of the Secretary of
 - the Commission 1p 47798 086-47798 086

P. Operating license stage documents & correspondence

- 8811280048 Genero Lifr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re-individual plant examillor sovera accident vulnerabilities Svc List CRUTCHFIELD.O Associate Director for Projects (Post 870411) 88/11/23 Consolidated Edison Colof New York, Inc. 81pp. 47728 303-47729 024.
- 8811290103 Advises that new heatup & cooldown curves will be generated after analysis of next surveillance capsule data at approx 6 EFPY.per Generic Ltr 88-11.Ref temps for all plant reactor vessel mails at end-of-tife and below screening cyteria HAIRSTON,W G. Alahama Power Co. 98/11/23. Document Control Branch (Document Control Dosk). 2pp. 47649-253-47649-254.
- 8812070105 Requests that util addresses concerns noted in Generic Lir 88-17 re loss of OHR during nonpower operation industry response as whole has not aggressively responded to resolve concern following identification in Generic Lir 87-12.

 WCRLEY, T.E. Ollico of Nuclear Reactor Regulation, Director (Post 870411), 88/12/02 FARLEY, J.M. Alabama Power Co. 3pp. 47749.230-47749.232
- 8812210033 Application for amonds to Licenses NPF-2 & NPF-8, incorporating provisions for reactor vossol level indicating system Generic Ltr 82-28 & NUREG-0737, Item II F 2 Feb paid HARISTON,W G. Alabaina Power Co. 88/12/14. Document Centrol Branch (Document Centrol Desk). 2pp. 47881-082-47881:099.
- --8812210038 Proposed Tech Spacs, incorporating provisions for reactor vessel level in it cating sys,per Generic Ltr 82-28 & NUREG-0737, Item II.F.2.

 * Aletiama Power Co. 88/12/14, 18pp. 47881 084-47881:099

O. Inspection reports, IE Bulletins & correspondence

- 8811180211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." See list encl. CL.NNINGHAM,R E. Division of Industrial & Modical Nuclear Safety (Post 870/29). 88/11/22 Consciteded Edison Co. of New York, Inc. 99pp. 47708-255-47708:257.
- 8811160467 NRC Info Notice 88 001, "Improper Administration & Control of Psychological Tests: "Svc list oncl HOSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/11/22 Conscidented Edison Co. of New York, Inc. 101pp. 47708 042-47708:142.
- 6812050266 Forwards Insp Ropts 50-348/88-29 & 50-364/88-29 on 881011- 1110.No
 - violations or deviations roled VEHRELLI,DM. Region 2, Otc of the D.recter, 88/11/25, HAIRSTON,W.G. Alabama Power Co. 2pp. 47731:251-47731:260
- -8812050290 Insp Repts 50:349/88-29 & 50:364/88-29 on 881011-1110 No violations or deviations noted. Major areas inspected review of operational safety verification, monthly surveillance observation, into meeting w/officials & emergency ex-
 - MAXWELL,G.F., MILLER,W.H., DANCE,H.C. Region 2, Ofc of the Director, 68/11/23, 8pp. 47731 253-47731 260.
- 8812020241 Forwards results of evaluations on safety-related pumps & justification for continued operation.per NRC Bulletin 88-004, "Potential Safety-Related Pump Loss." Final evaluation will not be completed until early 1989. HAPSTON,W G. Alabams Power Co. 88/11/30. Document Control Branch (Document Control Desk) 9pp. 47722:130-47722:138.
- 8811290030 NFIC Info Notice 88-093, "Teletherapy Events," Svc list enci. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02 Connected Edison Co. of New York, Inc. 112pp. 47811:103-47811:215. 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc 1st
 - ROSSICE: Division of Operational Events Assessment (Post 870411), 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8912020287 NFIC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licenseos on Vandors" Svc list encl. ROSSI, GE. Drivision of Operational Evants Assassment (Post 870411), 88/12/08. Consol dated Edison Co. of New York, Inc. 112pp. 47807:101-47807:302.
- 8812200071 Agrees w/881026 interpretation of Tech Spec re snubber visual insp schodule. Next snubber visual insp period is 16 months as stated in Table 4.7-3. REEVES,E.A. Project Directorate II-1, 88/12/11, HAIRSTON,W.G. Alebama Power Co 3pp 47868 304-47868:308.
- 8812210059 Confirms 861219 mgt meeting w/util in BirmIngham,AL to discuss nuclear plant oversight responsibilities,technical support responsibilities & activities of corporate organization,per 981295 telcon re-lated insp-repts. ERNST,M.L. Region 2, Otc. of the Director. 88/12/13. HAIRSTON,W.G. Georgia Power Co. 3pp. 47888:101-47888:103.

R. Periodic operating reports & related correspondence

8812190266 Monthly operating rept for Nov 1988 for Joseph M Farley Unit 1.W/881214

S. Reportable occurrences, LERs & related correspondence

- LER 88-022-00.on 881011,ESF actuation due to 8812130263 defective jumper Appropriate guidance will be provided to ensure that jumpers are checked prior to their use W/881202 tir. MOREY, D.N., HAIRSTON, W.G. Alabama Power Co. 88/12/02. 4pp. 47798:185-4779B-188
- 8812220269 LER 88-023-00 on 881207, radiation monitor R-60A (main steam reliof & atmospheric steam dump discharge) declared inoperable for greater than 7 day period specified in Tech Spec 3.3.1.Monitor will be repaired W/881216 ltr MOREY, D.N., HAIRSTON, W.G. Alabama Power Co. 88/12/16 2pp 47903.050-47903 051.

U. Congressional/Executiva Correspondence

8812070259 Informs that Ofc of Invostigations reviewed all info (laveloped during investigation of ellogations & concluded that no addl field work required Rept of investigations out ning findings expected in Jan 1989 ZECHLIV Commissioners 88/11/28. SHARP,P. House of Rept, Energy & Commisce 1p 47739.354-47739.354.

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811020184 Forwards public version of revised emergency plan implementing procedures. Including Rev 5 to Procedure EP-211, "Field Survey Group" & Rev 4 to EP-251, "Plant Survey Group" W/DH Grimsley release memo GALLAGHER, J.W. Philadelphia Electric Co. 88/10/21, RUSSELL, W.T. Region 1, Oto of the Director. 3pp 47721.053-47721.083.
- --8811020187 Revised emergency p'an Implementing procedures, including Rev 5 to EP.
 211, "Field Survey Group" & Rev 4 EP.251, "Plant Survey Group"
 Philade/phia Electric Co. 88/10/21, 28pp. 47721.086-47721.083
- 8812130018 Forwards Insp. Rept. 50-352/88-20 on 880925-1106 & notice of violation. WENZINGER, E.C. Region 1, Ofc of the Director. 88/11/30 MCNEILL, C.A. Philadelphia Electric Co. 2pp. 47794-291-47794.308.
- -8812130020 Notice of violation from insp on 880925-1106 Violation noted remote shutdown method R for safe shutdown of reactor not accomplished, due to inoperable reactor vossel & level
 - Region 1, Ofc of the Director, 88/11/30, 1p. 47794:293-47794:293
- -8812130021 Insp Rept 50:352/88:20 on 880925:1106.Violations noted Major areas Inspected daylimo & backshift/hol day insp on plant tours, observations of maint & survaillance teating, review of LETI & penodic rept, operational events & sys walkdowns. WILLIAMS.J.H. LINVILLE.J. Region 1, Ofc of the Director. 88/11/30. 15pp 47794 294 47794 308.
- 8812120033 Forwards request for etidl into re util 880930 Intention to combine emergency operations facrities for plants at single Coataville see bidg facrity Straight line direct & driving distances between plants & Coatsville see bidg requested BUTLER.W.R. Project Directorate I-2: 88/12/96. HUNGER.G.A. Philadelphia Electric Co. 4pp. 47785:184-47785:187.
- 8812200009 Discusses issue involving min source range monitor count rate requirement for control rod withdrawal specified in Tech Specs.Util preparing Tech Specs change request.
 FOGARTY,E.P., Philadelphia Electric Co. 88/12/13. Document Control Branch (Document Control Desk). 2pp. 47864:356-47864:357.

H. General correspondence

8812210292 Comments on rev to 10CFR2,App C, "Policy & Procedure for Enforcement Action." Util agreus w/pub ravs in that these changes will provide more reasoned basis for determining whether enforcement action necessary & appropriate levels. GALLAGHER,J.W, Philadelphia Electric Co. 88/12/14. CHILK,S.J. Office of the Secretary of the Commission. 3pp. 47882 060-47882.062.

- 8811280048 Generic Ltr 88-20 to all licensees holding Ol.s & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities.Svc list CRUTCHFIELD.D. Associate Director for Projects (Post 970411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729:024.
- 8811290350 Responds to Generic Ltr 88-11, "NRC Position on Red-ation Embrittlement of Reactor Vessal Matls & Impact on Plant Operations." Submittal dates for Tech Spec amends & results of fractive toughness analyses for plants stated. GALLAGHER,J.W. Philadelphia Electric Co. 88/11/23. MURLEY,T. Office of Nuclear Reactor Regulation, Director (Post 870411). 3pp. 47685-276-47665.322.
- -8811290357 Roy 1 to "Impact of Reg Guide 1.99, Roy 2 on Limerick Generating Sta-
- Ton Unit 1."
 PAPANDREA,C.J., CAINE,T.A., RANGANATH,S. General Electric Co. SASR 88-82-801-88/10/31-25pp. 47885:298-47685:322.
- 8811300432 Forwards Rev 0 to "Pump & Valve Inservice Testing Program, First 10 Yr FOGARTY, E.P. Philadelphia Electric Co. 88/11/23. Document Control Branch (Document Control Desk). 2pp. 47674:185-47675:178.
- -8811300466 Rev 0 to "Pump & Valve Inservice Testing (IST) Program, First 10 Yr Inter-Cilhart (Cam

- 8812160104 Forwards Amend 12 to License NPF.39 & safety evaluation. Amend modifies reactor end; recirculation sys. & common plant standby gas treatment sys to remove cooldown mode of operation for charcoal beds. CLARK, P. Project Directorate (2) 89/12/07. HUNSEH,G.A. Philadelphia Electric Co. 6pp. 47834.251-47834.269.
- -8812160105 Amend 12 to License NPF.G9,modifying reactor end reproblement sys & common plant standby gas freatment sys to remove cooldown mode of operation for chargost bods. BUTLER, W.R. Project Directorate 1-2 88/12/07 7pp 47634 257-47834 263
- -8812160106 Safety evaluation supporting Amend #2 to Lecense N2F-39 1 Office of Nuclear Reactor Regulation, Credior (Post 870411), 89/12/07 5pp 4/834264-47634261
- 8812160121 Advisos that methodology described in Rev 5 to offsite doso calculation manual within guidelines of NUREG-0133 & acceptable EG&G commonts encl. CLARK, R.J. Project Directorale N2 88/12/09 HUNGER, G.A. Philadolphia Electric Co. 4pp 47823 004-47823 012
- -8811280118 Discusses avaitation of Rev. 5 to offsite dose calcidation manual for plant Methodology considered within guide has of NUREG 0103,but listed discrepanclas noted Cles folials stated than the (subs. of EGSC, Inc.) SIMPSON,F.B. Idaho National Engineering Laboratory 88/07/06 POLK,H.E. NRC - No Dolased Afficient Green Spp. 47823 008-47823 012
- 8812200000 Ciscusses Issue Involving miniscurce range monitor count rate requirement for control rod withdrawal specified in Tech Specs Ustipreparing Tech Specs change **FOCUES!** FOGARTY, E.P. Philadelphia Electric Co. 88/12/13. Document Control Branch (Document Control Dask). 2pp. 47664.356-47864;357.
- 8812220086 Application for amend to License NPF-39,consisting of Tech Spec Change Request 86-10 relited sequence control sys & rod worth minimizer low power setpoint Fee paid GALLAGHER, J.W. Phrindelphia Electric Col. 68/12/14, Document Control Branch (Document Control Ousk). 22pp. 47994-001-47904.036.
- -8812220058 Proposed Tech Specs Including Pages 3/4 1-4,3/4 1-11 & 3/4 1-13,re sequence control sys & fed worth min mixer low power setup in 1 Philadelphia Electric Co. 88/12/14, 14pp, 47504 023 47904 035
- 8812270180 Informs of change in address for NRC resident Inspectors of LINVILLE, J.C. Rogion 1, Ofci of the Director, 88/12/14 MCNEILL, C.A. Philadelphia Electric Co. 2pp. 47826:211-47926.212
- 8012270165 Forwards marked up FSAR pages to clarify areas of electrical power distribution system common systematic diosel generator start signals & trypassing of diesel generator trip's grants Clarifications with be included in future amond KEMPERJ S. Philadelphia Etrictic Co. 88/12/22 Document Control Branch (Document Control Desk), 30pp. 47926 181-47926:210

Q. Inspection reports, IE Bullatina & correspondence

- 8811180341 Rev 0 to "Limerick Generating Station Unit 1, PRA-Based Sys Insp Plans." FRESCOA, HIGGINS.1, COPPOLAA Brookhavea National Laboratory Fin A.3453 A.3453-3.87(-2) R00 (17/03/31 NRC No Cotaled Alfabetica Gwen 109pp 47598:081-47598 189
- 8811160211 NRC Into Notice 88 090, "Unauthorized Removal of Industrial Nuclear Gauges," Sve List end CUMNINGHAMR E. Division of Industrial & Medical Nuclear Safety (Post 870729), 88/11/22, Consolidated Edison Co. of New York, Ind. 99pp. 47708.255-47708.257.
- 8811160467 NRC Info Notice 88 091, "Improper Administration & Control of Psychological Tests. Svc ist and ROSSLCE Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708:142.
- 8811290238 Advises that NRC will perform insplict mainliprogram on 890130-0210 & requests assistance in accomplishing task. Facility should furnish refinal listed in encitio enable NRC to prepare for insplicting anximize onsite time spent CALLOR Region 1. Oto of the Director, 88711722 MCNEILL,C A. Philadelphia Electric Co. 15pp. 47684:255-47684:265.
- 8812130018 Forwards Insp Hept 50:352/89-20 on 880925-1108 & notice of violation WENZINGER, E.C. Region 1, Old oil the Director, 69/11/30 MCNEILL, C.A. Philadel-phila Electric Co. 2pp. 47794-291-47794-308
- -8812130020 Notice of violation from inspiron 880925-1105. Violation hoted remote shutdown method R for safe shutdown of reactor not accomplished due to Inoperable re-actor vessel & lave!
 * Region 1, Otc of the Director. 88/11/30 1p. 47793-203-47794:293.
- →8812130021 http:// Rept. 50-352/88-20 on 880925-1108 Violations noted Major areas inspector/daytime & backshift/hot.day inspiror ptant tours, observations of maint & surval fance testing, roview of LER & periodic rept, operational events & sys walkdowns. WILLIAMS.J.H. LINVILLEJ. Region 1, Ofc. of the Director 88/11/30, 15pp. 47784.294-47794.308.
- 8811290030 NRC Info Notice 88-093, "Terotherapy Events" Syc list end CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp 47811:103-47811.215
- 8811290538 NRC Into Notice 88-094, "Potentially Undarsized Valve Actualors." Svc list enci ROSSI,CE Division of Operational Events Assessment (Post 870411), 88/12/02. Consolidated Edison Co. of New York, Inc. 12 tpp. 47708.143-47708.254
- 8812020287 NRC Info Notice 88:095. "Inadoquate Produrement Requirements Imposed by Uccesses on Vendors." Svc hist end. ROSSI.CE. Division of Operational Events Assessment (Post 870411). 88/12/08. Consolidated Edison Coll

S. Reportable occurrences, LERs & related correspondence

- 8811300528 Forwards Part 21 rept to breaker trip causing sponous undervoltage relatip 5 gnat RHOADS.E.W. Brown Boveri Corp. (subs. of Brown Roven & Co., Ltd.). 87/12/23. RUSSELL.W.T. Region 1, Ofc of the Director. 1p. 47696 307-47698 330.
- 8812050046 LER 88-012-01 on 890409, actuation of reactor protection sys. 8 ESF occurred Caused by reactor operator error Operator cautioned to be constantly aware of conditions which affect core reactivity Widelit28 its KRICH,RIM, FOGARTY, EP Philadelphia Electric Co. 88/11/28, 5pp. 4723107.
- 8812080295 LER 08:003:60 on 881101 discovered unacceptable electrical isolaten between facility Class 1E D.v II do power source & D22 bus did circuit Caused by pessonnel earl All non-Class 1E circuits removed from D.v II do source W/88120:11 GALLAGHER,J W. Philadelphia Electric Co 88/12/01. 7pp. 47735:099-47735:018
- 8812120080 LER 88:034:00 on 981105 isolation of reactor end secondary contact red occurred on low differential pressure Causod by sovered instrument at tine serving reactor oncl exhaust fan blade pitch positioner B.W/881206 ttr KRICH.R.M., GALLAGHER,J. Philadelphia Electric Co. 98/12/66, 5pp. 47780 34 47780 138
- 8812210357 LER 88-033-01 on 881101,cornaction of Unit 2 non-Class #€ circuits to Unit 1 de source w/o acceptable isolation found Caused by personnel error.All not class iE circuits removed from D.v. II de power source W/881202 IV.
 KRICHAM., FOGARTY,E.P. Philadelpha Electric Co. 88/12/66 (0cp. 47882034-
- 8812150090 Special reption 881107.diesel generator D13 manually shuftown & de-clared inoparable Caused by lared component within rectifier A bank components Rectifier banks thoroughly tested Cause sitt under investigation. MCCORMICK.M.J. Philadelph & Electric Co. 88/12/07. Document Control Branch (Document Control Desk). 4pp. 47828-082-47828-085.
- 8812200195 LER 88-035-00 on 881109 discovered 18 past-LOCA hydrogen recomblect intel valve inoperable Caused by Inadequate communication between operations personnel Memo written to remind shift personnel of responsibilities W/881213 v KRICH R.M., FOGARTY, E.P. Philadelphia Electric Co. 08/12/13 7pp 47862 tes-47682 168

V. Operator Examinations

8812050098 Forwards summary of 881102 mosting reiplan & schedule for firmfed serior reactor operator incense exams for fuel handler candidates on 890103.05 GALLO,R M Region 1, Offic of the Director 88/11/28. MCNEILL,C A Philadelpha Electric Co 39pp 47731.092-47731-130.

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

- 6811290360 Forwards, "Limorick Generating Station Unit 2 Summary Description of CA Program" Revised document provides update reflecting organizational name & vie channag Changas. KEMPERJ.S. Philadelphia Electric Co. 88/10/24, RUSSELL,W.T. Region 1, O'c of the Director, 1p. 47680.050, 47680.092.
- --8811290382 "Summary Description of OA Program." W/one oversize figure 'Ph/ade/ph/a Electric Co. 86/10/08, 43pp. 47880-051-47680-092.
- 8811280139 Provides supplemental info re 880506 application for amend to License SNM-1077,per D McCaughy request during 881015 telcon. KOWALSKI,S J Philaderphia Eloctric Co. 88/10/28 MURLEY,T.E. Office of Nuclear Regulation, Director (Post 870411). 2pp. 47652/232-47652/233
- 8811280048 Generic Lir 88-20 to all ficensoes holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list ance. CRUTCHFIELD.D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024
- 8811290350 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Matte & Impact on Plant Operations." Submitted dates for Tech Spec emonds & results of fracture toughness enalyses for plants stated CALLAGREN.J.W. Philadelphia Electric Co. 88/11/23. MURLEY.T. Office of Nuclear Reactor Regulation, Director (Post 870411). 3pp. 47865.278-47865.322
- 8811300432 Forwards Rev 0 to "Pump & Valve Inservice Testing Program, First 10 Yr FOGARTY,E.P. Philadelphia Electric Co. 88/11/23. Document Control Branch (Document Control Desk). 2pp. 47674;195-47675;178.
- ~8811300466 Rov 0 to "Pump & Valve Inservice Testing (IST) Program, First 10 Yr Interval."
 * Gilbert/Commonwealth, Inc. (formerly Gilbert Associates, Inc.). 88/11/18. 200pp
- 8812090143 Forwards S&W 881028 ftr providing summary description of independent design const assessment performed for unit per verbal request HELWIG.D.R. Philadelphia Electric Co. 88711729. IMBRO.E.V. NRC No Detailed Affiliation Given. 3pp. 47782.004-47782.006.
- 8812090219 Requests that facility be allowed to complete SPDS & emergency response facility display sys verification during power ascension test program & declare plant data sys operable within 30 days of completion of 100 h warranty run. KEMPERJUS. Philadelphia Electric Co. 88/12/05 MURLEYTE. Office of Nuclear Reactor Regulation, Director (Post 870411) 2pp. 47785.038 47785.039.

- 8812090232 Requests exemption from 10CFR50 44(c)(3)(i) to extend time of operation will non-morted containment to accommodate completion of power assersion test
 - program Justifications encl KEMPER J.S. Philadelphia Electric Co. 68/12/05, MURLEY,T.E. Office of Nucleon Re actor Regulation, Cirector (Post 070411), 4pp. 47795 139-47785,142
- 8812150121 Advises that moltodology described in Rev 5 to offsite dose calculation manual within guidelines of NUREG-0133 & acceptable EG&G comments and CLARK, R.J. Project Directorate I-2 88/12/09. HUNGER, G.A. Philadolphia Electric Co 4pp. 47823-004-47823-012
- -8911280118 Discusses evaluation of Rev 5 to Offsite dose calculation manual for plant.Methodology considered within guidelines of NUREG-0133,but listed discrepancies noted
- SEMPSON,F.B. EG&G Ideho, Inc. (subs. of EG&G, Inc.). SIMPSON,F.B. Ideho National Engineering Laboratory. 88/07/06. POLK,H.E. NRC No Detnilud Affiliation Given-6/pp. 47823;008-47823-012
- 8812270180 Informs of change in address for NRC resident inspectors of C NVIELE,J.C. Region 1, Ofe of the Director, 88/12/14 MCNEILL,C.A. Philadelphia Efecting Co. 2pp. 47926 211-47926 212
- 8812270185 Forwards marked-up FSAR pages to clarify areas of electrical power distri-bilition sys for common sys automatic diesel generator start signels & bypassing of classification of the signals Clarifications will be included in future amend KEMPER.J.S. Philadelphila Electric Co. 88/12/22. Document Control Branch (Docu-ment Control Deck). 30pp. 47926-181-47928-210

F. Security, medical, emergency & fire protection plans

- 8811020184 Forwards public version of revised emergency plan implementing procedures, notwing Rev 5 to Procedure EP-211, "Field Survey Group" & Rev 4 to EP-251, "Plant Survey Group" W/DH Grimsky release memo. GALLAGHERJ W Philadelphia Electric Co. 88/10/21, RUSSELL,W.T. Region 1, Ofc of the Director, 3pp. 47721:053-47721:083.
- -8811020187 Revised emergency plan implementing procedures including Rev 5 to EP-211, "Field Survey Group" & Rev 4 EP-251, "Plant Survey Group" * Philadelphia Electric Co. 88/10/21, 28pp. 47721:056-47721:083
- 8612120033 Forwards request for addlinto relubilities 0 Intention to combine emor-gancy operations facilities for plants at single Coatsville svc blug facility Straight I ne direct & driving distances between plants & Coatsville svc blug requested BUTLER,W.R. Project Directorate 1-2 88/12/06. HUNGER,G.A. Phylodelphia Electric Co. 4pp 47785 184 47785 187

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 88-090, "Unauthorized Romoval of Industrial Nuclear Gauges " Svc list encl CUNN.NQ1AM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870720). 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 4770tl 255-4770tl 257.
- 8811160487 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests," Svc list enci.
 ROSSI, CE. Division of Operational Events Assessment (Post 870411), 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47700.142.
- 8812020193 Forwards Insp Rept 50:353/88-201 on 881003.07 ra Implementation of Independent dosign assessment per util "Program for Independent Design & Const Assessment of Plant."

 WARIGA,S.A. Division of Reactor Projects I/II (Post 870411). 88/11/29

 HUNGER,G.A. Philadelphia Electric Co. 6pp. 47707.248-47707.264.
- -8812020196 Insp. Rept 50-353/88-201 on 881003-07 No violations noted. Major areas inspected insp. of Independent design assessment implementation. PARKHILL,R.W., IMBRO,E.V., HAUGHINEY,C.J. Division of Reactor Inspection & Sateguards (Post 870411), 88/11/21, 10pp. 47707:254-47707.264.
- 8811290030 NRC Info Notice 88-093, "Telathorapy Events" Svc 4st enck. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp 47611:103-47811.215
- 8811290538 NRC Into Notice 88-004, "Potentially Undersized Valve Actuators." Svc list encl.

 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/12/02.

 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708-254.
- 8812090137 Responds to NRC 881103 ltr re violations noted in finsp Ropt 50:353/68-25 Corrective action GE reviewed 3,500 Unit 1 floid deviation disposition request in 1894 for applicability to Unit 2. KEMPER, J.S. Philadelphia Electric Co. 68/12/05. WENZINGER, E.C. Occument Control Branch (Document Control Desk). 3pp. 47784:002-47784.004.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" Syc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/08.
- Consol dated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302
- 8812220398 Forwards Safety Insp Rept 50-353/88-28 on 881024-1104.No violations
- noted.
 DURR.J.P. Region 1, Ofc of the Director. 88/12/15. MCNEILL,C.A. Philadelphia Elec-inic Co. 2pp. 47903.052-47903:060.
- -8812220397 Insp Rept 50:353/88-28 on 881024-1104.No violations noted Major areas inspected preoperational test program, including review of preoperational test program implementation requirements prooperational test procedures. VAN KESSEL,H.F., EAPEN,P.K. Region 1, Ofc of the Director, 88/11/30, 7pp. 47903 054-47903 060.
- 8812290126 Requests that licensee provide NRC w/current schedule, including dates 8 topics for self-assessment activities KANE.W.F. Region 1, Ofc of the Director. 88/12/15. MCNEILL,C.A. Philadelphia Electric Co. 2pp. 47946

S. Reportable occurrences, LERs & related correspondence

8812070044 Final Significant Deficiency Richt 250-2 roluse of insulated wire by Westinghouse in safety-related motor starters. Initially reported on 881020 Defective componants reworked 8 corrected Action to provent recurrence not incessary. KOWALSKI,S.J. Philade/phia Electric Co. 887/12/02 RUSSELL,W.T. Document Control Branch (Document Control Dask). 3pp. 47746.269-47746:271.

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812020133 Rev 7 to Artificial Island Emergency Plan Station Procedura EPIP-202S, "Operations Support Cir (OSC) Activistion & Operations."

 1 Public Service Electric & Gas Co. of New Jersey 88/12/02, 26pp. 47722 158-
- 8812150264 "Artificial Island Emergency Plan, Annual Exercise," conducted on 881123-1202 Public Service Electric & Gas Co. of New Jersey, 88/12/31, 450pp, 47815.138

- 8811300537 Accepts util response to Part 2 of Item 2.1 to Generic Lir 93-28 re-estab-Isting Interface w/either NSSS or vendors of each of components of util reactor trip sys SER encl.
 - BIVENBARK,G. Project Directorate 1-2 88/11/22. MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 3pp. 47701.309-47701.313.
- -8811300543 Safety Evaluation re Part 2 at Item 2.1 to Generic Lir 83-28, "Vendor Interface Programs Reactor Trip Sys Components."
 * Project Directorate I-2: 88/11/22, 2pp. 47701:312-47701:313.
- 8811280048 Generic Lir 68-20 to all ficensees holding OLs & CPs for nuclear power reactor facilities individual plant exam for severe accident vulnorabilities. Svc 1st
 - CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729 024.
- 8611300303 Summary of 881116 meeting w/util in Rockvillo,MD re util long-range pro-grams at plants & NRC long-range offorts STONE,J.C. Project Directorate I-2, 88/11/25, Project Directorate I-2, 4pp, 47877:132-47877:135
- 8812010202 Application for amend to License NPF-57 revising Tech Space Surveillance Requirement 4.8.1.1.2.1 updating ASTM std ref in specification for diesol fuel oil
- sampling Fee paid
 MILTENDERGER,S Public Service Electric & Gas Co. of New Jersey, 88/11/28 Document Control Branch (Occument Control Desk), 6pp. 47709 194-47709:207.
- -8812010296 Rovised Tech Spec pages re surveillance requirements * Public Service Electric & Gas Co. of New Jersey, 88/11/28 app. 47709.200-47709.207.
- 8812050041 Forwards response to Generic Ltr 88-t1, "Radiation Embritllement of Re-actor Vessel Matts" Ubl will submit Leense amend requests to incorporate new heatup & cooldown curves in Tech Specs for Safem Unite 1 & 2 by Dec 1988. MILTENDERIGERS Public Service Electric & Gas Co. of New Jersey. 88/11/28 Doc-ument Control Branch (Document Control Desk). 7pp. 47732-021-47732-027.
- 8812120241 Forwards notice of consideration of issuance of amend to Licenso NPF-57 & proposed NSHC determination & opportunity for hearing re 881026 application BUTLER,W.R. Project Directorate 1-2 88/12/05 MILTENBERGER,S. Public Service Electric & Gas Co. of Now Jersey. 4pp. 47786 201-47786.213
- -9812120242 Notice of consideration of Issuance of amend to License NPF-57 & proposed NSFIC determination & opportunity for hearing re 881026 application Amend revises spont fuel storage capacity imitation in Toch Spec 5.6.3.
 BUTLER,W.R. Project Directorate I-2 88/12/05. 9pp 47786 205-47786 213.
- 8812140012 Application for amond to License NPF-57, consisting of Rev 1 to License Change Request 88.04,revising Section 6 of administrative controls by detering Fig. MILTENBERGER, S. Public Service Electric & Gas Co. of New Jersey. 88/12/05 Document Control Branch (Document Control Desk). 7pp. 47796:108-47796:130.
- --8812140014 Proposed Tech Speca re-administrative controls

 * Public Service Electric & Gas Co. of New Jersey, 88/12/05, 18pp. 47796.115-
- 8812150094 Documents agreement between util & J Stone & G Rivenbark of NRC re extending response submittel date for Generic Ltr 88-14 concerning instrument air supply sys MILTENBERGER,S Public Service Electric & Gas Co. of New Jersey, 68/12/06. Document Control Branch (Occument Control Dosk). 2pp. 47835.001-47835.002.
- 8812190026 Forwards Vols I & II to Rov 0 to PSE-03-103, "Safety Relief Valve Dis-charge Test Hope Creek Generaling Station," final test rept Confarment structures deemed adequate for hydrodynamic loads resulting from valve actuation. MILTENBERGEHS, Public Service Electric & Gas Co. of New Jersey, 88/12/09. Doc-ument Control Branch (Document Control Dosk), 2pp. 47838:189-47839.121.
- --8812190031 Vots I & II to Rev 0 to "Safety Relief Valve Discharge Test Hope Crook Generating Station," final test rop! MCINNES.I D., YOSHIDA,D.K., LEHNERT,R A. NU*TEC PSE-03-103 R00, 87/09/28 300pp. 47838:191-47838.121.

- 8812220055 Centres that Hope Creek Generating Station simulation facility.comsisting solely of plant-ref simulation as defined in 10CFR65 4,meets Commission regulations UII Procedures 206.205.8.203.8 related into end. LABRUNAS, Public Service Electric & Gas Co. of New Jersey 88712114 MURLEY, T. E. Office of Nuclear Reactor Regulation. Director (Post 870411), 14pp. 47934-025-47926-333.
- -8812220057 Rev 4 to Hope Crock Procedura HCSP-206, "ANS 3-5 Validation"
 Public Service Electric & Gas Co. of New Jersey, 88/11/23, 1,200pp, 47934-034-47936-277.
- -8812220061 Rev 4 to Hope Creek Simulation Procedure HCSP-205, "Hope Creek Simu'alor Configuration Mgt."
 Public Service Electric 8 Gas Co. of New Jersey 88/11/29, 56pp. 47936-278.
- 47936 333
- --8812220063 Rev 4 to Hope Creek Simulator Procedure HCSP-203, "Hope Creek Simulator Portermance Discrepancies."

 **Public Service Electric & Gas Co. of New Jersey 68/11/26 450pp 47936:334-
- 47936 147.

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear
- Gauges "Svollstiend" CUNNINGHAM,R.E. Drzision of Industrial & Medical Nuclear Safety (Post 870729) 66/11/22 Consolidated Edison Co. of New York, Inc. 995p. 47708-255-47708-257
- 8811160467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Tesis." Svc list encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142
- 8812010302 Advises that 880331 response to NRC Bullatin 88:001, "Defects in Wes-tingliouse Circuit Breakers" satisfactory. Response continued that Westinghouse DS series circuit breakers and used in safety-related applications. RWENBARK,G.W., Project Directorate 1/2, 881/11/22, MitTENBERGER,S. Public Service Effecting & Gas Co. of New Jersey. 3pp. 47703;324-47703;326.
- 8812020036 Artrises that util 890712 response to NRC Buketin 88:004, "Potential for Safety-Related Pump Loss," full-us requirements. RIVENBARK, G. Project Directorale 1-2 88/11/12 MITENBERGER, S. Public Service Electing & Gas Co. of New Jersey. Spp. 47707.156.47707.160.
- 8811300484 Informs that recent insplict records indicated that uit may have purchased Class. IE components from Planned Maint Sys, Inc.Unit should review records for period from Jan 1935 to present BUTER, W.R. Project Directorate 1-2, 80/11/23, MILTENBERGER, Public Service Electric & Gas Co. of New Jersey. 6pp. 47676 (48-47675 (53)
- 8811290030 NRC Info Notice 88 993. "Telathorepy Events." Svc Lst encl. CUNNINGHAM,R.E. Division of Industrial & Mod cal Nuclear Safety (Post 870729) 88/12/02 Consolidated Edison Co. of New York, Inc., 112pp. 47811:103-47811:215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators," Svc 1.st Brids ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02. Censelidated Edison Co. of New York, Inc. 121pp. 47708:143 47708:254.
- 8812020287 NRC Into Notice 88-095, "Inadequato Procurement Requirements Imposed by Licensess on Vendors" Svc list ercl. ROSSIC & Division of Operational Events Assessment (Post 870411), 86/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807.302.

R. Periodic operating reports & related correspondence

- 8812190398 Monthly operating rapt for Nov 1998 for Hope Creek Generating Station Unit 1.W/881215 kr.
 JENSEN,H. BRENNAN,C., HAGAN,J. Public Service Electric & Gas Co. of New Jersey 88/11/30, 16pp 47851:314-47851.329
- S. Reportable occurrences, LERs & related correspondence
- 8811290237 Special Rept 88-008-00 on 880826, HPC/I injection occurred. Caused by low seactor vessel level signal following reactor acram described in LER 88-022-00 HPCI injection notate usage factor not calculated. HAGAN JJ. Public Service Electric & Gas Co. of New Jersey. 88/11/21. Document Control Branch (Occument Control Desk). 1p. 47862-357-47662:357.
- 8812080047 LER 88-029-00 on 881101, manticipated turbine generator top & reactor scram occurred. Caused by failure of exciter brush collector ring assembly. Excitor brush explaced & new procedure to replace weekly insp implemented. W/881201 ttr. MERRELLA, HAGAM, J. Public Service Electric & Ges Co of New Jersey, 88/12/01.5pp 47750-114-47750.118
- 8812090304 LER 88-030-00.on 881104, pinhole loak observed on recirculation pump B discharge valve-On 881108, pinhole loak observed on recirculation pump A suction valve dran tine cap weld caused by vitration induced stress W/881205 ltr. WERRELL,A., HAGAN,J. Public Service Electric & Gas Co of New Jersey. 88/12/02 5pp. 47762.115-47762 119.
- 8812130178 LER 88-032-00.on B81113.surveillance test on svc water stray pump not performed as required by Tech Space 8 Section XI of ASME Boller & Pressure Vessel Codo Caused by personnel error Responsibilities re testing reemphasized.W/881213
- MERRELL, A.M., HAGAN, J. Public Service Electric & Gas Co. of New Jersey, 88/12/ 08. 5pp. 47794 356-47794.360
- 86 12130239 LER 88-931-00.on 881108. discovered that isolation of RWCU sys occurred Caused by air pockets induced by steam flashing in cleanup sys during reactor cookdown. Design change pursued to compensate subj instrumentation. W/881207 MERRELL, A.M., HAGAN, J. Public Service Electric & Gas Co. of New Jersey, 88/12/ 08. 5pp. 47798:195-47798:199.

DOCKET 50-356 UNIV. OF ILLINOIS RESEARCH REACTOR

P. Operating license stage documents & correspondence

8812190249 Advisos that License R-117 scheduled to expire on 801101. Applicationly renowal must be submitted 30 days prior to expiration Guidanco for preparing aso ta tion for renewal provided ADAMS,A. Standardization & Non-Power Heactor Project 12 rectorali 86/12-65 JCNES,B.G. Phos. Univ. of Urbana, IL. Epp. 47826-298-47826-003

DOCKET 50-368 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8811280048 Generic Lir 88-20 to all ficenseus holding Olis & CPs for nuclear power reactor facilities to individual plant examitor severe accident vulnerabilities Svc. it rect CRUTCHFIELD,D. Associate Director for Projects (Pest 870411). #8711725. Crisedated Edison Co. of New York, Inc. 81pp. 47728 303-47120 024

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 88 000, "Unauthorized Removal of Industrial Nacian Bauges "See list and County of the County Number States, 4 ost 8/3/24 88/11/22 Consolidated Edison Collaboration Work, Inc. 99pp. 47708-255-4770a-257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Control of Censol dated Edison Co. of New York, Inc. 101pp. 47709.042-47708.142
- 8811290030 NRC Info Natice 88:093, "Teletherapy Events." Syc list excit. CUNNINGHAM.R E. Division of Industrial & Mortical Nuclear Safety (Fost 87072), 89712702, Consolidated Edison Co. of New York, Inc. 112pp. 47811, 103, 47811,215
- 8811290538 NRC Into Notice 88-094, Polentially Undersized Valve Actual bis " Svc 'sl enci ROSSI,C E Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254
- 8812020287 NRC Into Notice 88:095, "Inadequate Producement Regulations imposed by Licensees on Vendors." See list end.
 ROSSICE Division of Operational Events Assessment (Phys. 876411) 86712766
 Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8811290025 Forwards thisp Repts 50:206/88:26.50:361/88:27 K 51:362/88:29 C 881025/28 No dolictonicies or violations noted YUHAS/GP Region 5, Ofc of the Director 88/11/10 BASKIN,K.P. Southern Callonia Edison Co. 2pp. 47651:088-47651:099.
- -8811290032 Insp Repls 50-206/88-26,50-081/88-27 & 50-082/88-20 un 881025 28 No deficiencies of violations noted Major areas inspected open interts intertified during 1987 exercise & associated chilque GOOD.6 M. Region 5, Otc of the Director 88/11/10 10pp 47651 080-47651.090
- 8811300057 Provides clarification of info previously submitted re App Rilcomp rance as sessment rept for plant
 MEDFORD,M O. Southern Cantornia Edison Co. 88/11/21. Document Control Branch
 (Document Control Desk). 46pp. 47870 312-47870 357
- 8812160133 Forwards SALP Board Repts 50.203/88.25.50.361/88.26 & 50.362/89 28 for period Oct 1987 Sept 1988 Need to Improve mgt involvement in მოგის ხურე ვის Critical attitude at all tevels of util organization noted MARTINUS Region 5, Offic at the Director 88/11/25 BASKINUK P. Southern California Edison Co. 3pp. 47820.321-47820.360.
- -8812150141 SALP Repts 50:206/88:25,50:361/88:26 & 50:362/88:28 for Cct 1987 Sept 1988 Category 1 assigned in areas of radiological controls & security. * Region 5, Oto of the Director 88/11/25 37pp. 47820 324-47820:360.
- 8612060124 Provides addl info re App R fire protection audit open items,gor 891017 add. Requests NRC reflect resolution of App R audit open items in final safety evaluation for util Units 2.6.3 fire protection program.

 MEDPORD,M.O. Southern Californa Edison Co. 88712701 | Document Control Branch (Document Control Desk) | 10pp | 47741.204.47741.213.
- 8812190321 Forwards Insp Repts 50 361/88 22 & 50 362/88 24 on 081017-21 No viotations noted Concerns noted, including adequacy of procedures that implement alternate shutdown methodology.

 KIRSCH, D.F. Region S. Olic of the Director, 88/12/06, BASKIN,K.P. Southern Callerna Edwan Co. 3pp. 47854.318-47854.348
- -8812190323 Insp. Repts 50-361/08-22 & 50-362/88-24 on 881017-1021 No violations of deviations noted Major areas inspected adequacy of mods implemented to achieve compliance w/10CFRS0,App R.
 RAMSEY,C, QUALLS,P. Region 5, Olc of the Director KUBICKID. Office of fuceter Reaclor Regulation, Director (Post 870411). 88/12/06, 28pp. 47854.321.47854.348
- 8812130286 Forwards revised Tech Spec 3.3.3.7, "Fire Detection Instrumentation," per roview of updated fire hazards analysis MEDFORD,M.O. Southern California Edison Co. 88/12/07. Document Control Branch (Occument Control Desk). 2pp. 47784-261-47784-290.

- -3812130269 Proposed Tech Spec 3 3 3 7, "Fire Detection Instrumentation." Southern Cattorna Edison Co. 88/12/07, 28pp. 47794 263-47794:290
- H. General correspondence
- 8911290018 Informs that 861108 request for extension of public comment puriod on proposed threes for duty rule doned Ampte response time provided GRIMES,B K. Division of Reactor Inspection & Safeguerds (Post 870411), 88/11/16 CINTRON,J A. Southern Celifornia Edison Co. 1p. 47668 668-47668 069
- 8911300539 Responds to 881112 request for Commission to extend public comment period on proposed Filness for Duty rule Commonts received effer 881121 will be considered if practical GR-MES, BK Division of Reactor Inspection & Safeguards (Post 870411) 88711728 UNATO, J. Southern California Edison Co., 1p. 47689,172-47680,174
- 8811300558 Cerries 881112 request for Commission to extend public comment period on proposed Filiness for Duty Program GR.MES,8 K. Division of Reactor Inspection & Safaguerds (Post 870411), 88/11/26 BARBRE,G L. Solthern Catterna Edison Co. 2pp. 47676-155-47676-157
- 8811300583 Danies 881112 regiest for Commission to extend public comments period
- on proposed threes for duty me GRIMES,B.K. Dwision of Header Inspection & Saleguards (Post 870411) 88/11/28 tVATSON,P.C. Southern California Edison Co. 1p. 47709.069-47709.071
- P. Operating license stage documents & correspondence
- 8811230311 Discusses changes made to improve use of acculerated maint processes for uttifications discussion w/NRC on changes made to Superintendent accelerated
 - maint process duming next visit
 MCCARTHY.C.B. Southern Celifornia Edison Co. 88/06/20. ZIMMERMAN,R. Region
 5, Ofc of the Director 3pp. 47632.350-47632.352.
- 8911230271 Provides prioritized monthly listing of pending ficunsing actions to assist in reviewing matters re-plant Encl identifies profitized list of proposed Tech Specichanges re-util 18 month surveillance interval extension efforts. changes to this 18 month surveillance Interval extension efforts.
 MEDFORD MIO: Southern Carifornia Edison Co. 88/11/22. Decument Control Branch (Document Control Dosk). 4pp. 47631:348-47631.351.
- 8811290263 Forwards addlinfo re design details pertaining to emergency dusel genera-tor start circustry mods per 880927 request. Encl includes Proposed Facility Change 2-85 6324,Rev 1 & Design Change Peckage 2-6324-0J.W/13 eversize drawings MEDFORO,MIO Southern Carlorina Ed son Co. 86/11/22. Document Control Branch (Document Centrol Dosk). 380pp. 47704.001-47705.020
- 8811290389 Provides additinto on 860806 proposal relidiverse scram sys (DSS) & diverse luthano trip (DTT), per 880825 request find clarifies how proposed DSS & DTT hardware diversity & other features medit ATWS ruto criteria.W/19 oversize figures MELFCRD, M.O. Southern Canterials Edison Co. 88/11/22. Document Control Branch (Document Control Desk). 39pp. 47680.083-47680.112.
- 8811300233 Informs that review of Chango Notice 29 to Topical Ropt SCE-1-A, "QA Program," Amond 11 will require more than 60 days to complete review & evaluation KIRSCH.D.F. Region 5. Old of the Director, 89/11/22 BASKIN,K.P. Southurn Calforna Edison Co. 1p. 47677:139-47677:139.
- 8811300270 Discusses extension of matt irradiation surveillance specimen test results
- repl Immediate attent on requested on matter.

 H.CKMAN,D.E. Project Oractorato V. 88/11/22. BASKIN,K.P. Southern California Edison Co. COTTON,G.D. Son Diago Gas & Electric Co. 3pp. 47676.299-47676.301
- 8811280048 Gunoric Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list
- CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024.
- 8812050111 Notification of 881207 meeting w/util in Rockville,MD to discuss reracking 61203011 Regime and Bat207 mosting wroth in Receiving to a scoss relativing cf spent fire! pool at plan!
 HICKMAN,D.E., Project Directorate V. 88/11/29. KNIGHTON,G.W. Project Directorate V. 4pp. 47733 353-47733.356.
- 8812070001 Requests additinfoline 881107 proposed change to Tech Specs, revising RCS pressure-temp limit curves,low temp overpressure protection temps & bases to the effective up to 10 EFPY of operation to complete rowow by Mar 1989. HICKMAN, DE. Project Directorate V. 88/11/30. BASKIN,K.P. Southern California Edison Co. 3pp. 47748:116-47748:118.
- 6812070007 Requests details of event re-control element assemblies exceeding Tech Spoc I mile, including assemblles in quosition & calculated drop times using onginal & rawsed processing times within 30 days.

 HICKMAN D.E. Project Directorate V. 88/11/30. BASKIN,K.P. Southorn California Edison Co. COTTON,G.O. San Diego Gas & Electric Co. 4pp. 47748 112-47748.115.
- 8812060073 Forwards Amend 116 to Liconse DPR-13 & safety evaluation. Amend authorizes transin pment of spent fuel from Unit 1 spent fuel pool to store in Units 2 & 3 spent fuel pools.
 TRAMMELL,C.M. Project Directorate V. 88/12/02. BASKIN,K.P. Southern California
- Edison Co. 3pp 47743:128-47743:141. --8812060074 Amond 116 to License DPR-13,authorizing transshipment of spent fuel from Unit 1 spent fuel pool & w/Amands 63 & 52 to Licenses NPF-10 & NPF-15,respectively,authorizes to store Unit 1 spent fuel in Units 2 & 3 spent fuel pools. KNIGHTON,G.W. Project Directorate V. 88/12/02 2pp. 47743:131-47743:132.
- B812160134 Requests response to Generic Ltr 88-17 re loss of DHR. Industry response to Generic Ltr 87-12 deficient in areas of prevention of accident Initiation & mitigation of accidents before progressing to coro demago.

 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/02. ALLEN,H P. Southern Carifornia Edison Co. 5pp. 47830.184-47830:188.
- 8812130268 Forwards revised Tech Spec 3.3.3.7, "Fire Detection Instrumentation," per review of updated fire hexards analysis.
 MEDFORD,M O. Southern California Edison Co. 88/12/07. Document Control Branch (Document Control Dosk), 2pp. 47794:261-47794:290.

- -8812130269 Proposed Tech Spec 3 3 3.7, "Fire Detection Instrumentation" Southern California Edison Co. 88712707, 28pp. 47794 263-47794 290
- 8812160095 Forwards salety evaluation denying 880811 application for amends to Li-censes NPF-10 & NPF-15 changing Tech Specs 6.5.3.4.8.6.5.3.4.g ru review by nu-cloar safety group of events requiring 24 h written not fication to NRC HICKMANDE Project Directorate V 88/12/09. BASKINJK P. Southern California Edison Co. COTTONIG D. San Diego Gas & Electric Co. 3pp. 47835.134-47835.138
- -8812160100 Safety evaluation denying utl 880811 application to amend Licenses NPF-10 & NPF-15,ttebuling Tech Spec Sections 6.5.3.48 & 6.5.3.4 g re-requirement that nucleus safety group invition events requiring 24 in oblication to NRC.

 * Cifice of Nucleus Reactor Regulation, Director (Post 870411) 88/12/09, 2pp
 - 47835 137-47835 138
- 8812190081 Responds to Guiteric Lit 89-11 ru roovaluation of effects of radiation on reactor vessel matts UIJ in process of updating Tech SPecs based on Reg. Guide 1.99,Rev 2 to be offective through 10 EFPY MEDFORD,MO Southern Gal Forms Edison Co. 88/12/12. Document Control Branch (Document Control Desk). 2pp. 47849,189-47840 190.
- 8812210065 Second partial response to FOIA request for records App C documents end & available in PDR. PHILLERS, J Division of Freedom of Information & Publications Services (Post 880515) 88/12/14 PARRISH,O Afficiation Not Assigned 2pp 47874 128/47874,190
- --8812210080 Forwards precedures per teleon w/K Baskin MEDFORD,M Southern California Edison Co. 88/09/20, ZWOLINSKI,J. NRC No De-tared Affiliation Given, 4pp. 47874,142-47874,145.
- --8812210087 Flev 1 to Site Directive f(GS-D-006, "Attentiof & Drug Use " RAY,HB Southern California Edison Co-86/11/14, 9pp. 47874;146-47874;1\$4
- -8812210091 Rev. 1 to General Administrative Procedure SO123-XV-69, "Fitness for
- Southorn California Edisen Co. 86/11/14, 12pp. 47874.155-47874:166
- --8812210096 Temporary Change Notice TCN 1-2 to Rev 1 to General Administrative Procedure SO123-XV-70, "Drug Testing Program for Protected Area Access." Southern California Edison Co. 86/11/14 16pp. 47874.169-47874 190.
- -8812210185 Toirpurary Cliarup Nolice TCN 1-3 to Rov 1 to General Administrative Proceduro SO123-XV-70, "Drug Tashing Program for Protected Arioa Access" Scutteuri Catifornia Erison Co. 88708/19, 2pp. 47874-1674-168
- 8812210323 Forwards application for amends to Licenses NPF-10 & NPF-15. Amends revise Tech Specs re-motor-operated valve thermal overload protection bypass & conlainment penetration conductor overcurront protection devices Fee pald
 BASKIN,K P. Southorn California Edison Co. 88/12/16. Document Control Branch
 [Document Control Desk]. 1p. 47875 218-47875 242
- -8812210325 Application for amends to Licenses NPF-10 & NPF-15 changing Toch Specs to confiderment penalitation conductor geocurrent protection device 8 motor-operated valve thermal overload protection typess. BASKIN,K.P. Southern California Edison Co. 88/12/16 12pp. 478/5/219-47875/230
- -8812210327 Proposed Tech Space re-conterment penetration conductor evercurrent protective driving 8 motor operated valve thormal evertead protection bypass
 Southern California Edison Co. 88/12/16, 12pp. 47875-231-47875-242
- 8812210216 Requests extension of submittal date of test rept for first Unit 2 matte survui lanco capsulo lo 881231 MEDFORD,M.O. Southern California Edison Co. 88/12/19. Document Control Branch (Document Control Desk) 1p. 47881.211-47881.211.
- 8812230044 Forwards Amend Applications 74 & 60 to Licensos NPF-10 & NPF-15,respectively. Amends would revise Tech Spec re-position indication channel shut-down & 18-menth surveillance intervals to support fuel cycle operation Fee paid. BASKIN,K P. Southern California Edson Co. 88/12/19. Document Control Branch (Document Control Desk). 1p. 47911:123-47911:138
- -8812230048 Application for amonds to Licenses NPF-10 & NPF-15 revising Tech Spec re position indication channel shutdown & 18-month surveillance intervals to support riumnal 24-month fuel cycle operation * Southern California Erison Co. 88/12/19: 9pp. 47911:124-47911.132
- 8812230067 Proposed Tech Specs re-position indicator channel shutdown
 Southern California Edison Co. 88/12/19, 5pp. 47911:133-47911-138.
- 8812270112 Forwards application, for amonds to Licenses NPF-10 & NPF-15, consisting of Amond Applications 71 & 57,rospectively. Amonds would revise Tech Spoc 3/4.4.5 to chango 18-month survel*lance intervals to refueling intervals Fee paid. BASKIN, K.P. Southern Caltornia Edson Co. 88/12/19. Document Control Branch (Document Control Dask) 1p. 47927.192-47927.207.
- --8812270117 Amond Applications 71 & 57 for Licenses NPF-10 & NPF-15, aspectwoly,revising Tach Spec 3/4.4.5.1 to change 18-month surveillance intervals to returning intervals to support normal 24-month fuel cycle operation. BASKINK.P. Southern California Ed son Co. 88/12/10, 9pp. 47927:193-47927:201.
- --8612270186 Proposed changes to Tech Spec 3/4.4.5 I revising 18-month surveillance intervals to refueling intervals to support nominal 24-month fuel cycle operation.
 Southern California Edison Cp. 88/12/19 Spp. 47927:202-47927:207.
- Q. Inspection reports, IE Bulletins & correspondence
- 8811290025 Forwards Insp. Repts 50-206/88-26,50-361/88-27 & 50-362/88-29 on 881025-28 No deliclencies or violations noted. YUHAS,G.P. Region 5, Old of the Director, 88/11/10, BASKIN,K.P. Southern California Edison Co. 2pp. 47651 088-47651:003.

- -8811290032 Insp. Repts. 50.206/88-26.50.361/88-27. 8. 50:562/88-29. on. 881025-20 No deficiences or volations noted Major areas inspected open items identified during 1987 exercise & emergency preparedness exercise & associated childude GOOD GM FISH FIF TATUMUE Region 5, Oto of the Director 88/11/10
- 8311230221 Requests results of C.E. Owners Group efforts to address truw require ments to NRC Burstin 88 004. Potential Safety-Rolated Pump Loss."

 HCKMANDE Project Directorals V 88/11/17. RASKINK P. Southern Californa Edison Co. COTTON G.D. San Diego Gas & Electric Co. 5pp. 47622.270.47622.274
- 8811160211 NRC Info Notice 89:050, "Unauthorized Removal of Industrial Nuclear Gauges "Sub-statert" CUNN NSHAM R.E. Division of Industrial & Medical Neclear Safety (Post 870729) 68/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257
- 8811160457 NRC Info Notice 88 091, "Improper Administration & Control of Psychologic ROSSI, C.E. Division of Operational Events Assessment (Post 870411) 88/11/22 Conscillate Edison Co. of New York, Inc. 101pp. 47708.042-47/08.142
- 8812150193 Forwards SALP Board Repts 50-205/88-25,50-361/88-26 & 50-362/88-28 for period Oct 1987 Sept 1988 Neud to improve mgt involvement in developing self-critical attitude at a lilevels of ust organization noted MARTIN 19 Region 5, Offic of the Director 68/11/25 BASKIN,K.P. Southern Cellfornia Edison Co. 3pp. 47820-321-47820-360.
- -8812150141 SALP Repts 50-206/88-25,50-361/86-26-8-50-362/88-28 for Oct 1987 -Sept 1988 Calegory 1 assigned in areas of radiological controls & security Region 5, Ord of the Ozector 68/11/25, 37pp, 47820,324,47820,360
- 8812150159 Forwards Meeting Repts 50:206/88:30.50:361/88:31 & 50:362/88:33 on 681102 Principal areas of current NRC concern emphasized at meeting & listed, richding missed opportunities to vidertify & correct observed profilems MARTIRU B Region 5, 0ffs of the Director, 88/11/25, FOGARTY,D J Southern Callforna Edison Co. 2pp. 47833 066:47633 072
- 8812070021 Requests info explaining how 8 h battery performance test demonstrates that battery can meet two design requirements, based on review of unit 860624 response to Insp Repris 50.361/88-10 8-50.362/88-10

 HICHMAN, DE Project Directoral V-88/11/128 BASKIN, K.P. Southern California Edison Co. COTTON, G.D. San Diego Ges & Electric Co. 4pp. 47748-082-47748-085.
- 8812130142 Discusses component cooling water sys review to 880502-0610 safety sys functional risp of activities authorized by NRC. Util will comprete evaluation & submit component cooling water sys phase two design review rept by 881216 MEDFORD, M.O. Southern California Edison Co. 86/11/30. MARTIN, J.B. Region 5, Otc. of the Director. 2pp. 47784, 158-47794, 159.
- 8812200087 Forwards Insp. Repts 50:206/68:27.50:361/88:28 8 50:362/68:30 on 881031:1104 No votations noted NRC encourages util to adopt more conservative approach toward reportability determinations per 881102 mgt meeting. ZIMMERIMANIR P. Region 5. Oic of the Director. 88/12/01 BASKINIK.P. Southern California Edison Co. 2pp. 47864 213-47864 224
- ~8812200090 Insp. Repts. 50:206/88:27.50:361/88:28 & 50:362/88:30 on 981031-1114 No violations noted Major areas inspected. Multiplant Action Item A-15,evaluation of plant trips & events/review of QA audits & surveillances & Part 21 repts. CALD/WELLC W. JOHNSON,P.H. Region 5, Otc. of the Director. 88/12/01. 10pp. 47864.215.47864.224
- 8811290030 NRC Into Notice 88.093, "Teletherapy Events." Svc Ist encl. CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870728), 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811 103-47811:215
- 8811290538 NRC Into Notice 88-094, "Potentally Undersized Valve Actuators." Svc List encl ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254.
- 8812070071 Requests that util notify NRC of date of next boroscopic exam re WKM MSIV root cause analysis NRC withholds comment on acceptability of util recommend-
- ed Inspician HICKMAN,DE Project Directorate V. 68/12/02. BASKIN,K.P. Southern California Edison Co. 3pp. 47746.111.47746.113
- 8812120185 Confirms 881213 mgt meeting w/u/u in Rosemead.CA to discuss SALP for Oct 1997 Sept 1988 per 881130 telcon Notice of meeting encl W/o erict KIRSCH Q.F. Region 5, Ofc of the Director 88/12/05 BASKIN.K.P. Southern California Edison Co. 2pp. 47/88/015-47788/016.
- 8812120188 Notification of 881213 meeting w/util in Rosemead,CA to discuss SALP for Oct 1987 Sept 1908 K/RSCH,D.F. Region 5, Otc of the Director, 88/12/05, Region 5, Otc of the Director, 3pp. 47788.021-47788.023.
- 8812190321 Forwards Insp Repts 50:351/68:22 & 50:362/88:24 on 881017-21 No vio-tations noted Concerns noted including adequacy of procedures that implement after-nate shutdown methodology KIRSCH,D.F. Region 5, Drc of the Director, 88/12/06. BASKIN,K.P., Southern Califor-nal Edison Co. 3pp. 47854.318-47854.348
- -8812190323 Insp. Repts 50-361/88-22 & 50-362/88-24 on 881017-1021. No violations of deviations noted Major areas inspected: adequacy of mods implemented to schieve compliance w/10CFR50. App. R. RAMSEY, C., OUALLS, P. Region 5, Otc of the Director, KUBICKLD, Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/06, 28pp. 47854.321-47854.348.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Ucensees on Vendors" Svc list enc!
 ROSSICE Division of Operational Events Assessment (Post 870411), 88/12/08, Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302

- 8012210065 Second partial response to FOIA request for records Allero & available in PDA.
- anci & ava-actio in Publ. PHILLIPS, J. Division of Freedom of Information & Publications 860515). 88/12/14 PARRISH, D. AlHiation Not Assigned. 2pp. 4787/
- -8812210077 Forwards Acosta response to 880715 order suspending i renewal due to drug use Related Infolinc'urding press release encl W/c LIERERYANJ. Of ce Enforcement (Post 870413), 88/07/11, MIRAG O rector for Projects (Post 870411), 13pp. 47674;131-47674,141

R. Periodic operating reports & related correspondence

- 8812200152 Monthly operating repts for Nov 1988 for San Onofre Nur Station Units 2 & 3 W/881215 ftr. SIACOR.E.R., MORGAN,H.E., Southern California Edison Co. 8 47860 349 47860 359
- 8812220128 Forwards Oct 1988 monthly NPDES rept summary for fac volations noted at Unil 3 during reporting portiod MORGANHE Southern California Edison Co. 88/12/12. Document (Occument Control Bask) 3pp. 47802 356-47802 350.

S. Reportable occurrences, LERs & related correspondence

- 8812060290 RO determined that redundant safe shutdown cables loca 2-YD-30-200 not separated 8/or protected in accordance w/10CFR5/III G Unit involved in expanding use of nenconformance rept process MORGAN,H.E. Southern California Edison Co. 88/11/15. MARTIN,J. 6 of the Director. 2pp. 47742 359-47742 360.
- 81:280110 LER 88:024:00 on 881021,control room isolation actuated Possibly caused by unsuitable plastic housing to tost jack equate support for Internal components Detector cable replaced W/88 MORGAN,HE, Southern California Edison Co. 88/11/21, Spp. 47655
- 8811300176 PNO-V-88-062 on 881119,earthquake occurred 30 miles Clamente CA Earthquake tott by personnel in Unit 1 control room & no mentation afarms recoved. Licensee found no damage after visual inst JOHNSON,P., HUEY,R. Region 5, Ofc of the Director. 88/11/21. 47678 846
- 8812020242 LER 88 027-00 on 880806, deliciency w/inverter 3Y-006 for HV-9377 Identified Caused by vender error & util preoperational testing to identify deficiency Design mods will be availated W/881128 ftr. MORGAN, HE Southern Caffornia Edison Co. 88/11/28, 7pp. 47722. 8812130258 Followup to Oct 1988 RO rept to Inoperable fire doors Fire lished per Toch Spec 3.7.9. Action Statement a & will remain in effect
- stored to operable status MORGAN.H.E. Southern California Edison Co. 89/11/29, MARTIN,J.B of the Director. 4pp. 47799 168-47799.171.
- 8812070265 PNS-V-88-007 on 881130 sentor resident informed of pos-events Caused by cleaning person not being able to completely sec-valving after work activities. Enhanced walkdown performed. SCHUSTER,M. MCQUEEN,A. Region 5, Ofc of the Director. 8 47749 228-47749 229
- 8812120007 LER 88 029 00 on 880921, handling machine operated w/handling isolation sys monitors. Caused by embiguity of Tech requirements Personnol reinstructed on followup on reportability. W/881: MORGAN, HE. Southern California Edison Co. 88/12/02. 6pp. 47780:
- 8812140055 PNS-V-88-007A on 881201, actuation alarm received from a pump fire protection deluge sys at Unit 2. Caused by contract watchmany intent to cause damage to plant. Two watchman terminated. SCHUSTER,M.D. Region 5, Olc of the Director. 88/12/07, 1p. 47800.0
- 8812210146 LER 88-028-00.on 881031, determined that plant operated at in excess of 100% between 880827 & 881021. Caused by apperent def water flow venturis following outages Sensing lines inspected.W/881212 MORGAN,H E. Southern California Edison Co. 88/12/12. 8pp. 47881:3

V. Operator Examinations

- 8812140090 Forwards revised agenda for annual operator ficonsing 890110 W/o enct.
 PATE,RJ, Region 5, Otc of the Director, 88/12/05, REEDER,J, Soutl Edison Co. 1p. 47796;149-47796;149.
- 8812150227 Ack receipt of 881021 litr re expiration of senior operator littion of Unit 1 plant superintendent Requests identification of Individuals three units responsible for drocting activities of licensed operators. KNIGHTON,G W. Project Directorate V. 88/12/08. BASKIN,K.P. Soutt

DOCKET 50-382 SAN ONOFRE NUCLEAR STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 9811290025 Forwards Insp. Repts 50-206/88-26,50-361/88-27 & 50-381025-28 No deficiencies or violations noted YUHAS,G.P. Region 5, Otc. of the Director 88/11/10. BASKIN,K.P. Sornia Edison Co. 2pp. 47651 088-47651.099.
- ~8811290032 Insp. Repts. 50-206/88-26,50-361/88-27. & 50-362/88-28 No. deficiencies or violations noted Major areas inspected open it during 1987 exercise & emergency preparedness exercise & associated GOOD,G.M. Region 5, Ofc of the Director. 88/11/10, 10pp. 47651:090-4

- 8811300057 Provides clarification of info previously submitted re App R compliance as-
- sessment rept for plant. VEDFORD,MC Southern California Edison Co. 88/11/21. Document Control Branch (Document Control Desk). 45pp. 47670/312-47670/357.
- 8812150133 Forwards SALP Board Repts 50-206/88-25,50-361/88-26 & 50-362/88-28 for period Oct 1987 - Sept 1988. Need to Priprove mgt involvement in developing self-chical attitude at all levols of util organization noted WARTINJ B. Region 5, Old of the Director, 88/11/25. BASKIN, K.P. Southern Califor-nia Edison Co. 3pp. 47820 321-47820-360.

- -8812150141 SALP Repts 50:206/88:25,50:361/88:26 & 50:362/88:28 for Oct 1987 Sept 1986 Category 1 assigned in areas of radiological controls & security 1 Region 5, Old of the Director, 88/11/25, 37pp. 47820:324-47820:360.
- 8812060124 Provides addl into re App R fire protection audit open items.per 881017 and tiRequests NRC reflect resolution of App R audit open items in final safety ovaluation (or ut1 Units 2 & 3 fire protection program.

 MEDFCRD,M O Southern California Edison Co. 88/12/01. Document Control Branch (Oocument Control Oosk). 10pp. 47741:204-47741:213
- 8812190321 Forwards Insp Repts 50-361/88-22 & 50-362/88-24 on 881017-21.No vio-lations noted Concerns noted,including adequacy of procedures that implement alter
 - nate shutdown methodology K-RSCH,D.F. Region 5, Old of the Director, 88/12/08, BASKIN,K.P. Southern Californta Ed son Co. 3pp. 47854:318-47854:348.
- -3612190323 Insp. Repts 50:361/88-22 & 50:362/88-24 on 881017-1021. No wolstions or deviations noted Major areas inspected: adequacy of mods implemented to achieve compriance w/10CFR50.App R.
 RAMSEY,C. Region 5, Oic of the Director. BALL,J., BRADFUTE,J. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/06, 28pp. 47854.321-47854:348.
- 8812130266 Forwards revised Toch Spec 3 3 3.7, "Fire Detection Instrumentation," per review of updated fire hexards analysis MEDFORD,M.O. Southern Coll forms Edison Co. 88/12/07. Document Control Branch (Occument Control Desk). 2pp. 47794:261-47794-290
- -8812130269 Proposed Tech Spec 3.3.3.7, "Fire Doloction Instrumentation" Southern California Edison Co. 88/12/07, 28pp. 47794:263-47794:290.

H. General correspondence

- 8811290018 Informs that 881108 request for extension of public comment period on groposed filmss for duty rule denied Ampte response time provided.
 GRIMES.B.K. Division of Reactor Inspection & Sateguards (Post 870411). 88/11/16. CINTRON.J.A. Southorn California Edison Co. 1p. 47688.068-47688.069
- 8811300539 Responds to 881112 request for Commission to extend public comment period on proposed Filness for Duty rule.Comments received after 881121 will be considered if practical.

 GR:MES,B.K. Division of Reactor Inspection & Safeguards (Post 870411). 88/11/28. JOKUMATO,J. Southern California Edison Co. 1p. 47880,172-47680.174.
- 881;300658 Denios 881112 request for Commission to extend public comment period on proposed Frinces for Duty Program. GRIMES.B.K. Division of Reactor Inspection & Saleguards (Post 870411). 88/11/28. BARBRE,G.L. Southern California Edison Co. 2pp. 47678;155-47676.167.
- 8811300583 Denies 881112 request for Commission to extend public comments period
- on proposed litness for duly rule.

 GRIMES,B K. Division of Reactor Inspection & Safeguards (Post 870411). 88/11/28.

 WATSON,R.C. Southern California Edison Co. 1p. 47708-089-47700.071.

- 8811230311 Discusses changes made to improve use of accelerated maint processos for util Requests discussion w/NRC on changes made to Superintendent accelerated maint process during next visit.

 MCCARTHY, C.B. Southern California Edison Co. 68/06/20. ZIMMERMAN,R. Reg on 5, Ofe of the Director. 3pp. 47632:350-47632.352.
- 8811230271 Provides prioritized monthly listing of pending licensing actions to assist in reviewing matters re plant End Identifies prioritized list of proposed Tech Specichanges ro util 18-month surveillance Interval extension efforts MEDFORD, M.O. Southern California Edison Co. 89/11/22, Document Control Branch (Document Control Desk), 4pp. 47631;348-47631;351.
- 8811290263 Forwards additinto re design dotalls portaining to emergency dioset genera-tor start circultry mods.per 880927 request. Encl includes Proposed Facility Change 2-85-6324.Rev 1 & Design Change Package 2-8324-0
- 8811290369 Provides additinto on 860606 proposal re diverse scram sys (DSS) & diverse turbine trip (DTT),per 880625 request into clarifies how proposed DSS & DTT hardware diversity & other features meet ATWS rule criteria.W/19 oversize figures. MEDFORD,M.O. Southern California Edison Co. 88/11/22. Document Control Branch (Document Control Desk). 39pp. 47680.093-47680.112.
- 8811300233 Informs that review of Change Notice 29 to Topical Rept SCE-1-A, "QA Program," Amend 11 will require more than 60 days to complete review & evaluation KIRSCH,D.F. Region 6, Ofc of the Director. 88/11/22. BASKIN,K.P. Southern Celiforna Edison Co. 1p. 47877:139-47677:139.
- 8611300270 Discusses extension of matti tradiation surveillance specimen test results repl immediate attention requested on matter.

 HICKMAN,D.E. Project Directorate V. 88/11/22. BASKIN,K.P. Southern California Edison Co. COTTON,G.D. San Diego Gas & Electric Co. 3pp. 47676 299-47676 301.
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities.Svc list
- encl CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024.

- 8812050111 Notification of 881207 meeting w/util in Rockville,MO to discuss reracking of spont fuel pool at plant HICKMAN,D E. Project Directorate V. 88/11/29. KN/GHTON,G W. Project Directorate V. 4pp. 47733-353-47733-356
- 8812070001 Requests addl into re 881107 proposed change to Tech Spacs, revising RCS pressure-temp limit curvos,low temp overpressure protection temps & bases to be offective up to 10 EPPY of operation to complete review by Mar 1989 HICKMAN,D.E. Project Directorate V 88/11/30. BASKIN,K.P. Southern Cantorna Edison Co. 3pp. 47748.118.47748.118.
- 8812070007 Requests dotai's of event in control element assemblies exceeding Tech Spec Imits, including assemblies in question & calculated drop times using original & revised processing times within 30 days HICKMAN, D.E. Project Directorate V. 88/11/30. BASKIN, K.P. Southern California Edison Co. COTTON, G.D. San Ciago Gas & Electric Co. 4pp. 47748 112-47748 115
- 8812060073 Forwards Amend 116 to License DPR-13 & safety evaluation Amend authorizes transshipment of spont fuel from Unit 1 spent fuel pool to store in Units 2 & 3 Robert fuel pools.

 TRAMMELL,C M. Project Directorate V. 88/12/02 BASKIN,K P. Scuthern California Edison Co. 3pp. 47743:128-47743:141

- -8812060074 Amend 116 to License OPR-13,authonzing transshipment of spent fucl from Unit 1 spent fucl pool & w/Amonds 63 & 52 to Licenses NPF-10 & NPF-15-raspectively-guithorizes to store Unit 1 spent fucl in Units 2 & 3 spent fuel pools KNIGHTON,G.W. Project Directorate V. 88/12/02 2pp. 47743-131-47743.132.
- 8812150134 Requests response to Generic Lir 88-17 re loss of DHR. Industry response to Generic Lir 87-12 deficient in areas of prevention of accident initiation & mitigation of accidents before progressing to core damage.

 MURICEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 887127-02 ALLEN,H.P. Southern California Edison Co. 5pp. 47830:184-47830.188
- 8812130266 Forwards revised Tech Spot 3 3.3.7, "Fire Detection Instrumentation," per review of updated fire hazards analysis MEDFORD.M.O. Southern Catiforna Edison Co. 88/12/07. Document Control Branch (Document Control Dask). 2pp. 47794.281.47794.280.
- --8812130269 Proposed Tech Spoc 3 3 3 7, "Fire Dataction Instrumentation."

 * Southern California Edison Co. 88/12/07, 28pp. 47794:263-47794:290
- 8812160095 Forwards safety evaluation donying 880811 application for amends to Li-censes NPF-10 & NPF-15, changing Tech Specs 6.5.3.4.a. & 6.5.3.4.g re review by nu-clear safety group of events requiring 24 h written ne
- --8812160100 Safety evaluation denying util 880811 application to amend Licenses NPF-10 & NPF-15, doleting Tech Spoc Sections 6.5.3.4a & 6.5.3.4g re requirement that nuclous selety group review events requiring 24 in bot 47835 137-47835 138.
- 8812190001 Responds to Generic Lir 88-11 re reevaluation of effects of radiation on reactor vessel matts. Util in process of updating Tech SPecs based on Rog Guide 1.99,Rov 2 to be effective through 10 EFPY.
 MEDFORD,MO. Southern Cattleria Edson Co. 88/12/12. Document Control Branch (Document Control Dask) 2pp. 47840.189.47840:190.
- 8812210065 Second partial response to FOIA request for records App C documents oncl & available in PDR. PHILLIPS, J. Division of Freedom of Information & Publications Services (Post 880515), 88712714, PARRISH,D Affiliation Not Assigned 2pp. 47874:128-47874.180.
- -8812210080 Forwards procedures per telcon w/K Baskin MEDFORD,M Southern California Edison Co. 88/09/20, ZWOLINSKI,J NRC No Detailed Affiliation Given 4pp. 47874:142-47874:145
- --8812210087 Rev 1 to Site Directive NGS-D-006, "Alcohol & Drug Use " RAY,H.B. Southern Carlornia Edison Co. 86/11/14 Spp. 47874 148-47874:154.
- -8812210091 Roy 1 to Goneral Administrative Procedure SQ123-XV-6.0, "Fitness for Southorn California Edison Co. 86/11/14 12pp. 47874.155-47874-186
- -8812210096 Temporary Change Notice TCN 1-2 to Rov 1 to Goneral Administrativo Proceduro SQ123:XV-7.0, "Drug Testing Program for Protected Area Access." Southern California Edison Co. 86/11/14, 18pp. 47874:189-47874:190.
- --8812210185 Temporary Change Notice TCN 1-3 to Rev 1 to General Administrative Procedure SO 123.XV-7.0 "Drug Tosting Program for Protected Area Access." Southern California Edison Co. 88/08/18. 2pp. 47874-187-47874-188.
- 8812210323 Forwards application for amends to Licenses NPF-10 & NPF-15. Amends revise Tech Spacs re motor oporated valvo thermal ovorload protection bypass & containment penetration conductor ovorcurrent protection devices. Fee paid.

 BASKIN.K.P. Southern Celifornia Edison Co. 88/12/16. Document Control Branch (Document Control Desk). 1p. 47875 218-47875 242
- --9812210325 Application for amonds to Licenses NPF-10 & NPF-15, changing Tech Spocs of containment periodration conductor overcurrent protection device & motor-operated valve thermal overload protection bypass. BASKIN, K.P. Southern California Ed.son Co. 80/12/16 12pp. 47875 219-47875 230.
- -8812210327 Proposed Tech Specs re-containment ponetration conductor overcurrent protective device & motor operated valve thermal overload protection bypass.
 * Southern California Edison Co. 88/12/16, 12pp. 47875:231-47875:242.
- 8812230044 Forwards Amend Applications 74 & 60 to Licenses NPF-10 & NPF-15,respectively, Amends would revise Tech Specine position indication channel shuldown & 18-month surveillance intovals to support fuel cyclo operation Fee paid BASKIN, K.P. Southern Californs Etiesn Co. 88/12/19. Document Control Branch (Document Control Dosk). 1p. 47911:123-47911:138

- -8812230948 Application for amends to Licenses NPF-10 & NPF-15, revising Tech Spec re position indication channel shutdown & 18-month surveillance intervals to support nominal 24-month fuel cycle operation.
 Southern California Edison Co. 88/12/19. 9pp. 47911:124-479f1:132.
- -8812230067 Proposed Tech Spacs re position indicator channel shutdown.
 * Southern California Edison Co. 88/12/19. 5pp. 47911:133-47911:138.
- 8812270112 Forwards application for amends to Licenses NPF-10 & NPF-15, consisting of Amend Applications 71 & 57,respectively. Amends would revise Tech Spec 37 4.4.5.1 to change 18-month surveillance intervals to refueling intervals Fee paid. BASKIN.K.P. Southern California Edison Co. 88/12/19. Document Control Branch (Document Control Desk). 1p. 47927:192-47927:207.
- -8812270117 Amend Applications 71 & 57 for Licenses NPF-10 & NPF-15, respectively,revising Tech Spec 3/4.4.5.1 to change 18-month surveillance intervals to refueling intervals to support nominal 24-month fuel cycle operation. BASKIN,K.P. Southern California Edison Co. 88/12/19. 9pp. 47927:193-47927:201.
- -8812270186 Proposed changes to Tech Spec 3/4.4.5.1 revising 18-month surveillance intervals to refueling intervals to support nominal 24-month fuel cycle operation.
 Southern California Edison Co. 88/12/19. 6pp. 47927;202-47927;207.

Q. Inspection reports, IE Bulletins & correspondence

- 8811290025 Forwards Insp. Repts. 50-206/88-26,50-361/88-27 & 50-362/88-29 on 881025-28.No deficiencies or violations noted. YUHAS.G.P. Region 5, Oit of the Director. 88/11/10. BASKIN,K.P. Southern California. nia Edison Co. 2pp. 47651:088-47651:099.
- -8811290032 Insp Repts 50-206/88-26,50-361/88-27 & 50-362/88-29 on 881025-28 No deficiencies or violations noted Major areas inspected:open items identified during 1987 exercise & emergency preparedness exercise & associated critique. GOOD,6.M., FISH,9.F., TATUM,J.E. Region 5, Ofc of the Director, 88/11/10, 10pp.
- 8811230221 Requests results of C-E Owners Group efforts to address flow requirements re NRC Bulletin 86-004, "Potential Safety-Related Pump Loss."
 HICKMAN,D.E. Project Directorate V. 88/11/17. BASKIN,K.P. Southern California Edison Co. COTTON,G.D. San Diego Gas & Electric Co. 5pp. 47622:270-47622:274.
- 88_111602 11 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear 817160211 NHO IND NUIDE GO-USU, CHAURINIZED FRONTON OF REPORT OF R
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologi-811160467 NRC Into Notice 88-091, "Improper Administration & Control of Psychologi-cal Tests." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708:142.
- 8812150133 Forwards SALP Board Repts 50-208/88-25,50-361/88-28 & 50-362/88-28 for period Oct 1987 Sept 1988 Need to improve mgt involvement in developing self-discal attitude at all levels of util organization noted. MARTIN, J.B. Region 5, Otc of the Director. 88/11/25. BASKIN,K.P. Southern California Edison Co. 3pp. 47820:321-47820:380.
- --8812150141 SALP Repts 50-206/88-25,50-361/88-26 & 50-362/88-28 for Oct 1987 Sept 1988 Category 1 assigned in areas of radiological controls & security.

 * Region 5, Ofc of the Director. 88/11/25, 37pp. 47820:324-47820:360.
- 8812150158 Forwards Meeting Repts 50-206/88-30,50-361/88-31 & 50-362/88-33 on 881102.Principal areas of current NRC concern emphasized at meeting & listed including missed apportunities to identify & correct observed problems. MARTIN.J.B. Region 5, Ofc of the Director, 88/11/25, FOGARTY,D.J. Southern California Edison Co. 2pp. 47833:066-47833:072.
- -8812150159 Mgt Meeting Repts 50-206/88-30,50-361/88-31 & 50-362/88-33 on 881102.Major areas discussed issues of current interest re plant. HUEY,F.R., JOHNSON,P.H. Region 5, Ofe of the Director, 88/11/23, 5pp. 47833:068-
- 8812070021 Requests info explaining how 8 h battery performance test demonstrates that battery can meet two design requirements, based on review of util 880624 response to Insp Repts 50-361/88-10 & 50-362/88-10.
 HICKMAN, D.E. Project Directorate V. B8/11/29. BASKIN,K.P. Southern California Edison Co. COTTON,G.D. San Diego Gas & Electric Co. 4pp. 47748:082-47748:085.
- 8812130142 Discusses component cooling water sys review re 880502-0610 safety sys functional insp of activities authorized by NRC. Util will complete evaluation & submit component cooling water sys phase two design review rept by 881216. MEDFORD,M.O. Southern California Edison Co. 86/11/30. MARTIN,J.B. Region 5, Ofc of the Director. 2pp. 47794:158-47794:159.
- 8812200087 Forwards Insp Repts 50-206/88-27,50-361/88-28 & 50-362/88-30 on 861031-1104.No violations noted NRC encourages util to adopt more conservative eproach toward reportability determinations,per 881102 mglt meeting
- --8812200090 Insp Repts 50-206/88-27,50-361/88-28 & 50-362/88-30 on 881031-1114.No violations noted Major areas Inspected: Multiplant Action Item A-15,evaluation of plant trips & events,review of QA audits & surveillances & Part 21 repts.

 A7864:215-47864:224.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Sve list encl. CUNN/NGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 881129053B NRC Info Notice 88-084, "Potentially Undersized Valve Actuators." Svc list encl.

 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/12/02.

 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.

- 8812070071 Requests that util notify NRC of date of next boroscopic exam re Wiki MSIV root cause analysis.NRC withholds comment on acceptability of util recommend.
- ed Insp plan.

 ed Insp plan.

 ed Insp plan.

 HICKMAN,D.E. Project Directorate V. 88/12/02. BASKIN,K.P. Southern California

 Edison Co. 3pp. 47746:111-47746:113.
- 8812140241 Ack receipt of 881011 response to violations noted in Insp Rept 50:382/ 88-22.Corrective actions will be verified during future insp. PATE,R. Region 5, Ofc of the Director. 88/12/02. BASKIN,K.P. Southern California Edison Co. 1p. 47802:219-47802:223.
- 8812120185 Confirms 881213 mgt meeting w/util In Rosemead,CA to discuss SALP for Oct 1987 Sept 1988,per 881130 telcon.Notice of meeting encl.W/o encl. KIRSCH,D.F. Region 5, Otc of the Director. 88/12/05, BASKIN,K.P. Southern California Edison Co. 2pp. 47768:015-47788:015.
- 8812120188 Notification of 881213 meeting w/util in Rosemead,CA to discuss SALP for Oct 1987 Sept 1988.
 KIRSCH,D.F. Region 5, Ofc of the Director, 88/12/05, Region 5, Ofc of the Director, 3pp. 47788:021-47788:023.
- 8812190321 Forwards Insp Repts 50-361/88-22 & 50-362/88-24 on 881017-21.No vio-lations noted.Concerns noted,including adequacy of procedures that implement alter-nate shutdown methodology. KIRSCH,D.F. Region 5, Ofc of the Director, 88/12/06. BASKIN,K.P. Southern Califor-nia Edison Co. 3pp. 47854:318-47854:348.
- -8812190323 Insp Repts 50-361/68-22 & 50-362/88-24 on 881017-1021.No violations or deviations noted.Major areas inspected: adequacy of mods implemented to achieve compliance w/10CFR50,App R. RAMSEY,C., QUALLS,P. Region 5, Ofc of the Director. KUBICKI,D. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/06, 28pp. 47854:321-47854:348.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svc list encl.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 68/12/08.
 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812210065 Second partial response to FOIA request for records.App C documents encl & available in PDR. PHILIPS,J. Division of Freedom of Information & Publications Services (Post 880515), 88/12/14, PARRISH,D. Affiliation Not Assigned, 2pp. 47874:128-47874:190.
- --8812210077 Forwards Acosta response to 880715 order suspending license & denying renewal due to drug use. Related Info,including press release encl.W/o response. LIEBERMAN,J. Ofc of Enforcement (Post 870413), 88/07/11, MIRAGLIA,F. Associate Director for Projects (Post 870411), 11pp. 47874:131-47874:141.

R. Periodic operating reports & related correspondence

- 8812200152 Monthly operating repts for Nov 1986 for San Onofre Nuclear Generating Station Units 2 & 3.W/881215 ltr, SIACOR,E.R., MORGAN,H.E. Southern California Edison Co. 88/11/30. 11pp. 47860:349-47860:359.
- S. Reportable occurrences, LERs & related correspondence
- 8812060290 RO:determined that redundant safe shutdown cables tocated in Fire Area 2-YD-30-200 not separated & for protected in accordance w/10CFR50,App R,Section III.Q.Util Involved in expanding use of nonconformance rept process, MORGAN,H.E. Southern California Edison Co. 88/11/15, MARTIN,J.B. Region 5, Ofc of the Director. 2pp. 47742:359-47742:360.
- 8811300176 PND-V-88-062:on 881119,earthquake occurred 30 miles west of San Clemento,CA.Earthquake felt by personnel in Unit 1 control room & no seismic instrumentation alarms received. Licensee found no damage after visual insp of Unit 1. JOHNSON,P. Region 5, Ofc of the Director. 88/11/21. 1p. 47678:046-47678:046.
- 8812130258 Followup to Oct 1988 RO rept re inoperable fire doors.Fire watches established per Tech Spec 3.7.9, Action Statement a & will remain in effect until doors restored to operable status.

 MORGAN,H.E. Southern California Edison Co. 86/11/29. MARTIN,J.B. Region 5, Otc of the Director. 4pp. 47799:168-47799:171.
- 8812070265 PNS-V-88-007:on 881130,senior resident informed of possible tampering events.Caused by cleaning person not being able to completely secure associated valving after work activities. Enhanced walkdown performed.

 SCHUSTER,M. Region 5, Ofc of the Director. 88/12/01. 2pp. 47749:228-47749:228.
- 8812140055 PNS-V-88-007A:on 881201,actuation alarm received from reactor coolant pump fire protection deluge sys at Unit 2. Caused by contract watchman who denied any intent to cause damage to plant.Two watchman terminated. SCHUSTER,M.D. Region 5, Ofc of the Director. 88/12/07. 1p. 47800:329-47800:329.
- 8812220130 LER 88-010-00:on 881114,steam generator blowdown liquid composite sample lost.Caused by personnet error resulting in inadvertent disposal.Administrative controls on sample labeling,storage & segregation enhanced.W/881114 ltr. MORGAN,H.E. Southern California Edison Co. 88/12/12. 2pp. 47903:296-47903:297.

V. Operator Examinations

- 8812140090 Forwards revised agenda for annual operator licensing meeting on 990110,W/o encl.
 PATE,R.J. Region 5, Ofc of the Director. 88/12/05. REEDER,J. Southern California Edison Co. 1p. 47798:149-47796:149.
- 8812150227 Ack receipt of 881021 ltr re expiration of senior operator license for posi-tion of Unit 1 plant superintendent.Requests identification of Individuals & titles at all kniGHTON,G.W. Project Directorate V. 88/12/08. BASKIN,K.P. Southern California Edison Co. COTTON,G.D., San Diego Gas & Electric Co. 5pp. 47825:056-47825:060.

DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8812060115 Forwards General Old Emergency Implementing Procedure G0-EIP-138 & document transmittal ack form W/o enct.
 HARRIS.R. Alabana Power Co. 88/11/21 Region 2, Old of the Director 1p.
- 47741 163-47741 163
- 8812050286 Forwards Insp Repts 50-348/88-29 & 50-364/88-29 on 881011- 1110 No violations or deviations noted
 VERRELLI,D.M. Region 2, Ofc of the Director, 88/11/25 HAIRSTON,W.G. Alabama
 Power Co. 2pp. 47731:251-47731:260.
- -8812050290 Insp. Repts 50:348788:29 & 50:364788:29 on 881011-1110 No violations or deviations noted Major areas Inspected review of operational safety verification, monthly surveillance observation, informating whether is 8 emergency ex-
 - MAXWELL G.F. Region 2, Ofc of the Director, 88/11/23, 8pp. 47731 253 47731 260
- 8812120227 Revised omergency plan implementing procedures including Rev 21 to FNP-0-EIP-16, "Emergency Equipment Supplies" & Rev 14 to FNP-0-EP-090, "Emergency Plan" W/881207 ltr. HUDSPETH,J.B. Alabama Power Co. 88/12/07
- 8812200033 Rev 0 to Procedure GO-EIP-138, "Procedure For ROLM Sys Reprogramming" & temporary change review approval to Draft 1,Rov SA to Procedure GO-EIP-118, "Emergency Operations Facility Shift Turnover" W/891214 ltr HARISTON,W G Alabama Power Co. 88/12/14, 16pp 47858/269-47856/284

H. General correspondence

- 6812120050 Commont opposing proposed rule 10CFR2 re submission & rigt of records & documents related to Leonsing of high lovel radwaste goodsgic repository Util sup-ports EEI comments to be submitted to NRC HAIRSTON,W.G. Alabama Power Co. 88/12/05 CHILK,S.J. Office of the Secretary of the Commission.

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnerabilities Svc list
 - CRUTCHFIELD,D. Associate Director for Projects (Post 970411) 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729:024.
- 8811290103 Advises that now heatup & cooldown curves will be generated after analysis of next surveillance capsule data at approx 6 EFPY,per Generic Lir 88-11.Rel temps for all plant reactor vessel matts at not-brille are below screening criteria. HalfiSTON,W.G. Alabama Power Co. 88/11/23, Document Centrel Branch (Decument Centrel Basel), 2pp. 47649:253-47849:254.
- 8812070105 Requests that util addresses concerns noted in Generic Ltr 88-17 reliess of DHR during nonpower operation Industry responso,as whole has not aggressively re-sponded to resolve concorn following Identification in Generic Ltr 87-12. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02. FARLEY,J.M. Alabama Power Co. 3pp. 47749,230-47749,232.
- 8812210033 Application for amonds to Licenses NPF-2 & NPF-8, incorporating provisions for reactor vossel level indicating sysper Generic Ltr 82-28 & NUREG-0737, Item ILF 2.Fob paid HAMBSTON,W.G. Alabama Power Co. 88/12/14, Document Control Branch (Document Control Desk), 2pp. 47881.082-47881.099.
- 8812210038 Proposed Tech Space Incorporating provisions for reactor vessel level indicating sys.per Generic Ltr 82:28 & NUREG-0737, Item II F.2.
 Alabama Power Co. 88/12/14. 16pp. 47881:084-47881.099
- 8812190292 Forwards Rov 0 to FNP-2-M-067, "Second 10-Yr Pump & Valve Inservice Testing Program..." Beginning on 890401, program will be utilized for completion of pump & valve tests performed on Unit 2 during first 10-yr Interval Fee paid HAIRSTON,W.G. Alabama Power Co. 88/12/15. Document Control Branch (Document Control Desk), 12pp. 47870.005-47870.310.
- -8812190299 Rev 0 to FNP-2-M-067, "Second 10-Yr Pump & Valve Inservice Tosking Program of JM Farloy Unit 2 Nuclear Generaling Plant."

 *Aflabama Power Co. 89/03/24, 500pp, 47870,017-47870,311.

Q. Inspection reports, IE Builetins & correspondence

- 8811180211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear
- Gauges." Svc list enct. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 86111B0467 NRC Into Notice 88-091, "Improper Administration & Control of Psychologi-ROSSI,C E. Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708.142.
- 8812050288 Forwards Insp Repts 50:348/88:29 & 50:364/88:29 on 881011- 1110 No violations or deviations noted.

 WERRELLI, D.M. Region 2, Otc of the Director. 88/11/26, HARSTON,W.G. Alabama Power Co. 2pp. 47731:251-47731:260.
- --8812050290 Insp Repts 50:348/88-29 & 50:364/88-29 on 881011-1110.No violations or deviations noted.Major areas inspected review of operational safety verification,monthly surveillance observation,info meeting w/officials & emergency ex-

- 8812020241 Forwards results of evaluations on safety-related pumps & justification for continued operation, per NRC Bullotin 88 004, "Potential Safety-Related Pump Loss" Final evaluation wit not be completed with early 1989 HAIRSTON, W.G. Alabama Power Co. 88711/30 Document Control Branch (Document Control Desk) 9pp. 47722 130-47722.138
- 8811290030 NRC Info Notice 88 093, "Te'ethorapy Events." Svc Ist end CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811 103-47811 215
- 8811290538 NRC Info Notice 88 094, "Potentially Undersized Valve Actuators." Svc list onci ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254.
- 8812020287 NRC Into Notice 884095, "Inadequate Procurement Requirements Imposed by Licenseos on Verdors" "Suc 1st end. ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302
- 8812200071 Agrees w/881026 interpretation of Tech Spec re snutber visual inspisionadule Next snutber visual inspisionad is 18 months as stated in Talus 4.7-3 REEVESE A Project 0 rectorate II-1. 88/12/11 HAIRSTON,W.G. Alatiama Power Co 3pp. 47868 304-47868 308
- 8812210059 Confirms 881219 mgt incebing w/util in Birmingham,AL to discuss nuclear plant oversight responsibilities,technical support responsibilities & activities of corporate organization.por 881205 talcon to listori inspirepts ERNST,M.L. Region 2, Ofc. of the Director. 88/12/13 HAIRSTON,W.G. Georgia Power Co. 3pp. 47808 101-47888 103
- 8812160138 Forwards Rev 0 to FNP-2-M-068, "Second 10 Yr Inservice Insp. Program for ASME Code Class 1.2 & 3 Correponents of JM Farley Unit 2 Nuclear Generating
- Plant' & requests relief by 890324.
 HAIRSTON,W.G. Alabama Power Co. 88/12/16 [Document Centre] Branch (Documont Control Desk). 7pp 47833 318-47831 225.
- -8812160139 Rev 0 to FNP-2-M-068 to "Second 10 Yr Inservice hisp Program for ASME Codo Class 1,2 & 3 Components of JM Failey Unit 2 Nuclear Generating Plant"
- Alabama Power Co. 89/03/24, 300pp. 47833:325-47834,225

R. Periodic operating reports & related correspondence

- 8812190275 Monthly operating rept for Nov. 1988 for JM Farley Nuclear Plant, Unit 2.W/ MOREY,D.N., HAIRSTON,W.G. Alabama Power Co. 88/11/30. 8pp. 47869.007-
- S. Reportable occurrences, LERs & related correspondence
- 8812130055 LER 88 007-00 on 881104 fire watches not established within 1 h of ineporability of fire protection sys Caused by switch improperly repositioned Switch properly positioned to main bank bottles flow lag placed on selector switch W/881202 fir MOREY, D.N., HAIRSTON, W.G., Alabaina, Power Co., 88/12/02, 4pp. 47798 200-47708 203
- 8812220266 LER 88 008-00 on 881118,fire damper 139-118-03 failed to close w/air flow New damper will be installed with ninext yr,thus oxceeding Toch Spec 3.7.12 requirement that damper be retuined to operable status within 30 days W/881216 fz. MOTEY D.N., HAIRSTON, W.G. Alnbama Power Co. 88/12/10. 2pp. 47914-230-47914 231.

U. Congressional/Executive Correspondence

8812070259 Informs that Ofc of Investigations reviewed all Into developed during Investigation of allicigations & concluded that no addit field work required Rupt of Investigations cultining findings expected in Jan 1989. ZECH,L.W. Commissioners. 88/11/28. SHARP,P. House of Rep., Energy & Commerca. 1p. 47739-354-47739-354.

DOCKET 50-366 EDWIN I. HATCH NUCLEAR PLANT, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 8812090102 Revised emergoncy plan implementing procedures,including Revs 0 to 63EP-EIP-012-0S,63EP-EIP-018-0S,63EP-EIP-012-0S 63EP-EIP-022-0S,63EP-EIP-029-0S,83EP-EIP-029-0S,
- 8812200112 Rev 0 to Emergency Plan Implementing Procedure 63EP-EIP-067-OS, "Actions for All Plant Personnot During Security Alert." W/881214 ltr.
 SUMMER.J., HAIRSTON,W.G. Georgia Power Co. 89/11/17 3pp 47858/266-47858:268.
- 8812120011 Confirms annual omergency preparadness oxercine on 891025. HAIRSTON,W.G. Georgia Power Co. 88/12/05. Document Control Branch (Document Control Desk). 2pp. 47780:164-47780.165.

H. General correspondence

8812120059 Comment opposing proposed rule 10CFR2 re records related to licensing high level radwaste geologic repository. Util endorses EEI comme: its to be submitted to NRC

P. Operating license stage documents & correspondence

- 8811290309 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Matt & Impact on Plant Operations," per Rev 2 to Reg Guide 1.99 Pressure-temp will be revised by end of second refueling outage for Unit 2. HAIRSTON,W.G. Georgia Power Co. 88/11/22. Document Control Branch (Document Control Desk). 25pp. 47684:159-47684:183.
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities.Svc list anci. CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729:024.
- 8811300096 Notification of 881201 meeting w/util in Rockville,MD for util presentation of evaluation of bent rockbolts observed on Unit 1.Proposed agenda encl. CROCKER,L.P. Project Directorate II-3, 88/11/23, MATTHEWS,D.B. Project Directorate II-3, 4pp. 47697:356-47697:359.
- 8812220032 Forwards safety evaluation re compliance w/ATWS rule (10CFR50.62).Util complies w/requirements except for open item re testability of alternate rod injection sys while at power.
 CROCKER L.P. Project Directorate (i-3, 88/12/14, HAIRSTON,W.G. Georgia Power
 Co. 4pp. 47886:286-47886:301.
- -8812220038 Safety evaluation supporting util actions to comply w/ATWS rute (10CFR50.62), specifically alternate rod injection & recirculation pump trip sys. Open item noted re tostability of alternate rod injection sys white at power.
 NRC No Detaited Affiliation Given. 88/12/14, 12pp. 47896:290-47886:301.
- 8812200160 Forwards addl into re environ effects attributable to transportation of spent fuel solid waste outlined in 10CFR61.52.per Nov 1988 request.Info follows util 860228 request to modify OLs to 40 yrs from date of issuance.

 HAIRSTON,W.G. Georgia Power Co. 68/12/15. Document Control Branch (Document Control Desk). 3pp. 47850:246-47860:248.
- 8812270971 Forwards updated listing of outstanding licensing submittels. Early NRC approval requested for certain priority items, including proposed license extension to 40 HAIRSTON, WG. Georgia Power Co. 68/12/20, Document Control Branch (Document Control Desk). 3pp. 47827:122-47927:124.

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear 811160211 NHC Into Notice de-usy, Chaptilotzed Noticear Safety (Post 870729).

 Gauges "Syclist encl.

 CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729).

 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257.
- 8811180467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708:142.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc fist enct. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of Naw York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list encl.

 encl.

 BOSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/12/02.

 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708;254.
- 8812050063 Advises that util 880711 response to NRC Bulletin 88-004, acceptable. CROCKER,L.P. Project Directorate il-3, 88/12/02, HAIRSTON,W.G. Georgia Power Co, 4pp. 47731:162-47731:185.
- 8812050069 Advises that util 880705 response to NRC Bulletin 88-003, "Inadequate Hatch Engagement in HFA Type Latching Relays Mig by GE," acceptable, no Living TON,W.G. Georgia Power

- 8812210059 Confirms 881219 mgt meeting w/utili in Birmingham,AL to discuss nuclear plant oversight responsibilities,technical support responsibilities & activities of corporate organization,per 881205 telcon re listed insp repts. ERNST,M.L. Region 2, Ofc of the Director. 88/12/13. HAIRSTON,W.G. Georgia Power Co. 3pp. 47868:101-47888:103.
- 8812200233 Forwards Insp. Repts 50-321/88-34 & 50-366/88-34 on 881022-1125 & notice of violation.

 BROWNLEE, V.L. Region 2, Ofc of the Director. 88/12/14, HAIRSTON, W.G. Georga Power Co. 2pp. 47855:210-47855:231.
- --8812200238 Notice of violation from insp on 881022-1125. Violation noted failure to take initial corrective action w/knowledge that automatic depressurization sys design such that loss of automatic sys operation could result from single failure.

 BROWNLEE, V.L. Region 2, Ofc of the Director. 88/12/14. 2pp. 47855:212-47855:213.
- -8812200242 Insp Repts 50-321/88-34 & 50-366/88-34 on 881022-1125, Violations noted Major areas inspected: operational safety verification, maint MENNING, J.E., MUSSER, R.A., SINKULE, M.V. Region 2, Old of the Director. 69/12/15, 18pp. 47855:214-47855:231.
- 8812200348 Forwards summary of 881123 mgt moeting re mgt controls of welding program at plant w/emphasis on adequacy of welding on RWCU sys.per Insp. Repts 50-321/88-31,50-3369/88-31, 50-321/88-35,50-321/88-35,50-321/88-38 & 50-366/88-38. ERNST,M.L. Region 2, Otc of the Director. 88/12/14. HAIRSTON,W.G. Georgia Power Co. Spp. 47867:264-47867:269.

A. Periodic operating reports & related correspondence

8812190280 Monthly operating repts for Nov 1988 for El Hatch Units 1 & 2.W/881214 TUCKER, J.E., HAIRSTON, W.G. Georgia Power Co. 88/11/30. 12pp. 47850:285-

S. Reportable occurrences, LERs & related correspondence

8812120004 Special Rept 88-005:on 881105 omergency light Inoperable for longer than 24 h period.Caused by deploted/doad battery. Maint personnel replaced dead battery under MWO-2-88-4353. under myrv-c-ou-4355. HAIRSTON,W.G. Georgia Power Co. 88/12/02. Document Control Branch (Document Control Dosk). 6pp. 47789:113-47789:118.

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8811280183 Rev 6 to Emergency Plan Implementing Procedure 1903.04, "Administra-tion & Maint of Emergency Plan & Implementing Procedures." "Arkansas Power & Light Co. 88/09/23, 6pp. 47654:029-47654:034.
- 8811300435 Rev 9 to Emergency Plan Implementing Procedure 1903.01, "Organization & Use of Emergency Plan Implementing Procedures."

 * Arkansas Power & Light Co. 88/10/27, 3pp. 47876;207-47876;209.
- 8811300429 Rev 10 to Emergency Plan Implementing Procedure 1903.51, "Turnover of Responsibility."
 * Arkansas Power & Light Co. 88/10/28. 11pp. 47677:012-47677:022.
- 8611290503 Rev 16 to Emergency Plan Implementing Procedure 1903.023, "Personnel
 - Emergency."

 * Arkansas Power & Light Co. 88/11/16, 14pp. 47657:337-47657:350.
- 8811300115 Advises that 881027 request for extension in submittal of response to devi-ations noted in insp Repts 50-313/87-14 & 50-368/87-14 until 881216 acceptable. CALLAN,LJ. Region 4, Ofc of the Director. 88/11/16. CAMPBELL,G. Arkansas Power & Light Co. 2pp. 47673:239-47673:242.
- --8811300119 Requests extension until 881216 to submit revised response to Insp. Repts 50-312/87-14 & 50-368/87-14, LEVINE,J.M. Arkansas Power & Light Co. 88/10/27, CALLAN,L.J. Region 4, Otc of the Director, 2pp. 47873:241-47873:242.
- 8811280021 Forwards response to Safeguards insp Repts 50-313/86-34 & 50-368/86-34. Encl withheld (ref 10CFR73,21). LEVINE, J.M. Arkansas Power & Light Co. 88/11/18. CALLAN, L.J. Region 4, Oic of the Director, 2pp. 47709:001-47709:002.
- 8812010004 Advises that 880921 changes to emergency plan acceptable. CALLAN,L.J. Region 4, Ofc of the Director, 88/11/16, CAMPBELL,G, Arkansas Power & Light Co. 2pp. 47708:250-47709:251.
- 8812160153 Forwards Amends 114 & 88 to License DPR-51 & NPF-6, respectively.Amends modify Paragraphs 2.C(4) & 2.D of licenses to require compliance w/revised physical security plan per 10CFR73.55.Safeguards evaluation rept alice myteriseu priyancar accents pear pear pear selso anci.
 HARBUCK,C.C. Project Directorate IV. 88/12/06. CAMPBELL,T.G. Arkansas Power & Light Co. 4pp. 47830:301-47830:311.
- -8812160155 Amends 114 & 88 to Licenses DPR-51 & NPF-8, respectively, modifying Paragraphs 2.C(4) & 2.D of licenses to require compliance w/revised physical security plan per 10CFR73.55.
 CALVO,J.A. Project Directorate IV. 88/12/06, 4pp, 47830:305-47830:308.
- -8812180157 Sateguards evaluation rept supporting Amends 114 & 88 to Licenses DPR-51 & NPF-8,respectively.
 Office of Nuclear Reactor Regulation, Director (Post 870411), 86/12/06. 3pp. 47830:309-47830:311.

8812210301 Forwards Insp. Repts 50-313/88-39 & 50-368/88-39 on 881031-1104 No

violations or deviations noted.

CALLAN,L.J. Region 4, Old of the Director 88/12/13 CAMFBELL,G. Arkansas Power & Light Co. 2pp. 47877:115-47877:120.

-8812210304 Insp. Repts 50:313/88:39 & 50:360/88:39 on 881031-1104 No violations or developes noted Major areas inspected, physical security program life discounty support, security program life & audits & alarm stations & communications KELLY,J.A. Region 4, Ofc of the Director, 88/12/08, 4pp, 47877.117, 47877, 120.

P. Operating license stage documents & correspondence

- 8812190295 Provides add into re-response time tosting on plant for ESF sys Actual re-sponse for three of four containment bldg cooling units measured at approx 27 sec-onds & considered slightly greater than safety analysis assumption LEVINEUM, Arkansas Power & Light Co. 89/11/03. MARTIN,FLD. Region 4, Old of the Director. 2pp. 47851:271-47851.272.
- 8811290182 Discusses NRC position on radiation embrillement of reactor vessel matts & Impact on plant operations to Generic Lit 88-11 HOWARD,D.R. Arkansas Power & Light Co. 08/11/21 Document Control Branch (Document Control Desk). 2pp. 47648:198-47648 199
- 5811280049 Goneric Ltr 88-20 to all liconsees holding Otis & CPs for nuclear power reactor facilities re Individual plant exam for severe accident vidinerabilities Svc list encl CRUTCHFIELD.D. Associate Director for Projects (Post 870411) 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729 024
- 8812090229 Requests that util address Generic Ltr 88-17 to loss of DHR dirting non power operation Industry response to Generic Lir 87-12 deferent in grees of provention of accident initiation 8 miligation of accidents. MURLEY, TE. Office of Nuclear Reactor Regulation. Director (Post 870411), 86/12/02. MAULDEN, J.L. Arkansas Power & Light Co. 4pp. 47762-317-47762-320.
- 8612160153 Forwards Amends 114 & 68 to Liconse CPR-51 & NFF 6, respectively. Amends modify Paragraphs 2 C(4) & 2 D of licenses to require compliance w/revised physical security plan por 10CFR73 55 Sateguards evaluation rept
 - HARBUCK,C.G. Project Directorate IV. 88/12/06 CAMPBELL,T.G. Arkenses Power & Light Co. 4pp. 47830:301-47830:311.
- -8812160155 Amends 114 & 88 to Licenses DPR-51 & NPI-6 respectively, modifying Peregraphs 2.C(4) 8 2.D of licenses to require compliance w/revised physical security plan per 10CFR73.55.
 CALVOU A. Project Directorate IV. 88/12/06. 4pp. 47830-305-47830-308
- -8612180157 Safeguards evaluation rept supporting Amends 114 & 88 to Licenses DPR-51 & NPF-6, respectively.

 * Office of Nuclear Reactor Regulation, Director (Post 670411) 88/12/06 3pp 47830:309-47830:311.
- 8812210005 Summary of 881013 monthing w/white forigistending safety issues; including Generic Ltr. 83:28 Items,SPDS,Rog. Guide 1.97 safety evaluation open items & TMI Action Item II.K.2.18.
 HARBUCK,C.C. Project Directorate IV 88/12/13, CAMPBELL,T.G. Arkensas Power & Light Co. 17pp. 47889.035.47889.051.

Q. Inspection reports, IE Bulletins & correspondence

- 8611300115 Advises that 861027 request for extension in submittal of response to deviations noted in Insp Replis 50:313/87-14 & 50 368/87-14 until 861216 acceptable CALLANLJ. Region 4, Oto of the Director. 88/11/16 CAMPBELL,G. Arkenses Power & Light Co. 2pp. 47873:239-47673:242
- -8811300119 Requests extension until 881216 to submit revised response to Insp. Ropts 50:313/87-14 & 50:368/87-14. LEVINE,J.M. Arkanses Power & Light Co. 88/10/27 CALLAN,L.J. Region 4, Otc of the Director. 2pp. 47673:241-47673:242.
- 8812010009 Ack receipt of 881026 fit informing NRC of stops taken to correct violations noted in Insp Repts 50:313/88-28 & 50:368/88-28. CALLAN, J. Region 4, Ofc of the Director, 88/11/17, CAMPBELL,G. Arkansas Power & Light Co. 2pp. 47709:316-47709:315.
- --8612010012 Responds to violations noted in Insp. Repts 50:313/88-28 & 50:368/88-28. Corrective actions:RCS leakage rate determination in Procedure 1103.13 will be revised to eliminate discrepancy of timing. LEVINE_J.M. Arkansas Power & Light Co. 88/10/26 CALLAN, U.J. Region 4, Ofc of the Director. 4pp. 47708:312-47709.315.
- 8811280021 Forwards response to Safeguards Insp. Repts 50:313/86-34 & 50:369/86-34, Encl withheld (ref. 10CFR73.21).
 LEVINE,J.M. Atkansas Power & Light Co. 88/11/18 CALLAN,L.J. Reg.on 4, Olc of the Director, 2pp. 47709.001-47709.002.
- 8811290271 Forwards Insp Repts 50-313/88-32 & 50-368/88-32 on 880916-1023 &
- notice of violation.
 CALLAN,L.J. Region 4, Olc of the Director, 88/11/18, CAMPBELL,G. Arkensas Power
 & Light Co. 2pp. 47650 035-47650.050
- -8811290278 Insp Repts 50-313/88-32 & 50-368/88-32 on 880916-1023. Violations noted Major areas inspected maint survoillance, operational safety verification following on LERs & events.

 JOHNSON,W.D., HAAG.R.C., CHAMBERLAIN,D. Region 4, Ofc of the Director. 88/11/15, 13pp. 47650.038-47650.050.
- 8811300161 Forwards Insp Repts 50-313/88-35 & 50-368/88-35 on 881030-1104.Details of violation discussed in tept. Preparation to discuss all aspects of item w/Region
- IV at future meeting requested.
 CALLAN,L.J. Region 4, Ofc of the Director. 8B/11/18. CAMPBELL,G. Arkansas Power & Light Co. 2pp. 47698.001-47698:007.
- -8811300166 Insp. Repls 50:313/88:35 & 50:368/68:35 on 881030:1104. Violation noted, Major areas inspected: Unit 1 containment integrated leak rate test AZUA,R.V., SEIDLE,W.C. Region 4, Old of the Director 88/11/17. 5pp 47698 003-47698:007.

- 8811180211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges "Svc list enri CUNNINGHAM R.E. Dv.son of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708-255-47708-257.
- 8811160467 NRC Into Notice 88 091, "Impropor Administration & Control of Psychology cal Tents "Svc list and Operational Events Assessment (Post 670411) 88/11/22 Consol Jated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142
- 8811300159 Forwards Insp. Hopts 50:313/R8:37 & 50:368/88:37 on 881017-1104/No viciations or deviations noted CALLAN_LJ Region 4, Old of the Director, 80/11/22 CAMPBELL,G Arkansas Power & Light Co. 2pp 47673-098-47673-108
- -8811300160 Insp Hopts 50-313/88:37 & 50-368/88:37 on 881017-1104 No violations or devaluers noted Major areas inspected licensee capitality for self-assessment & complaince w/ respect vo OL Foch Specific quiercerents TAYLORUE G. BARNES, Region 4, Otc of the Circotor 88/11/22, 8pp. 476/3 100 47673,108.
- 0811300264 Forwards Insp. Ropus 50:313/88-41 & 50:369/88-41 on 881103-04 Violations noted Enforcement conference scheduled on 881201 to discuss util understanding of apparent vicintions reason for occurrence & corrective actions CALLAN,L. J. Region 4, Old of the Director 88/11/23 CAMPBELL,G. Arkansas Power & Light Co. 2pp. 47674;118 47674.125
- -8811300257 Insp. Repts 50-313/88-41 & 50-368/88-41 on 881103-04 Violations noted Major areas inspected events surrounding apparent overexposure of one worker perforuncy maint work during follucting outlige. HICKETSON, L.T., MURRAY,B., PEDERSON,B.L. Region 4, Ofc. of the Director. 88/ 11716-8pp. 47874.118-47674.125
- 8812020306 Forwards Environ Qualification Insp. Repts 50:313788-29 & 50:368788-29 on 880822-26,0912-29 & 1003-13 & notice of violation. CALLAN, L.J. Region 4, Oic of the Director 88711/28 CAMPBELL,G. Arkansas Power & Light Co. 2pp. 47718-260-47718,306
- -8812020307 Notice of violation from hisp on 860714-18 & 880229 0610. Violations noted equipment qualification this did not adequately address instrument accuracy & maint procedures inadequate in pertaining maint on cooling unit ten motors.

 • Region 4, Otc of the Director, 88/11/28, Upp. 47/18, 292-47718, 294.
- -8812020309 Inap Repts 50-313/88-29 & 50-368/88 20 on 880822-28,0912-29 & 1003-13 Violations noted Major areas insported Langee actions on previously Identified items to equipment agrification as documented in Isated inspiration by STETIKA, T.F. Region 4, Otc. of the Director 188/11/21, 12pp. 47718 295-47718 306
- 8811290030 NHC Info Notice 88-093, "Talethorapy Events" Svc Lst end CUNNNGHAMR E. Division of Industrial & Medical Nuclorar Safety (Post 870729) 88/12/02 Consolidated Edison Co. of New York, Inc. 11209, 47811:103-47811
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list anci KOSSI.C.E. D.vision of Operational Events Assessment (Post 870411): 88/12/02 Consolidatert Edison Co. of Now York, Inc. 121pp. 47/08 143-47708 254
- 8812050305 Informs that Insps 50-313/88-46 & 50-36H/60-48 cancelled & no insp repts will be lesued for right numbers. CALLAN,L.J. Region 4, Ofc of the Director. 88/12/02 CAMPBELL,G. Arkandas Power & Light Co. 1p. 47740 055-47740,055
- 8812020287 NRC Into Notice 08:095, "Inadequate Procurement Requirements Imposed by Licanseus on Vendors" Svc list encl ROSSI.C.E. Division of Operational Events. Assessment (Post 870411) 88/12/08 Consolidated Edison Co. of Naw York, Inc. 112pp. 47807.191-47807.302
- 8812150102 Forwards Insp Repts 50-313/88-34 & 50-368/88-34 on 881004-07 & 17-21 No volations or dovations noted.

 CALLAN,L. J. Rogion 4, Ofc of the Director. 88/12/08. CAMPBELL,G. Arkensas Power & Light Co. 2pp. 47830:271-47830:281.
- -8812150109 Insp Ropts 50:313/88:34 & 50:368/88:34 on 881004:07 & 17:12. No vio-Table 18 to 18 to
- 8812210301 Forwards Insp Repts 50:313/88:39 & 50:368/88-39 on 661031-1104.No violations or deviations noted

 CALLAN,L. J. Region 4, Ofc of the Director 88/12/13, CAMPBELL,G. Arkanses Power & Light Co. 2pp. 47877:115-47877-120
- -8812210304 Insp Repts 50-313/88-39 & 50-368/88-39 on 881031-1104.No violations or deviations noted Major areas inspected physical security program, including mgt support, security program plan & audits & alarm stations & communications KELLYJA, EVERETT, RJ. Region 4, Ofc of the Director 88/12/08 4pp. 47877;117-47877:120
- 8812210346 Forwards Insp Ropus 50-313/88-48 & 50-368/88-48 on 881128-29 Enforceenactioner converge map rapple outstated 48 50,386/48 48 60 881128-29 Enforcement conference scheduled on 881221 to discuss understanding of apparent violations of in rept & violations in lnsp Repts 50,313/88-41 & 50-368/88-41.

 CALLAN,L J. Region 4, Otc of the Director, 88/12/14, CAMPBELL,G. Arkenses Power & Light Co. 2pp. 47877:109-47877:114.
- -8812210347 Insp. Repts. 50:313/88:48 & 50:388/88:48 on 881128:29. Violations noted Mejor areas inspected events surrounding apparent overexposure to skin of one. worker. BAEH,R.E., RICKETSON,L.T., MURRAY,B. Region 4, Otc of the Director. 88/12/13 4pp. 47877:111-47877:114.
- 8812220010 Advises that Insp Repts 50-313/88-40 & 50-368/68-40 concelled No repl numburs will be issued CALLAN,L J. Region 4, Olc of the Director. 88/12/14 CAMPBELL,G. Arkansas Power & Light Co. 1p. 47903 038-47903 038.

R. Periodic operating reports & related correspondence

8812190240 Monthly operating rept for Nov 1988 for Arkansas Nuclear One,Unit 2 W/ 681214 ftr.
SCHAUBROECKID., HOWARD,DIR Arkansas Power & Light Co. 88/11/30 6pp.
47849 966 47849 071.

S. Reportable occurrences, LERs & related correspondence

- 8811290452 PNO-IV-88 091 on 681123,hot particle was identified by portal monitor as worker was existing non-radicing call work area tocated on turbrie bldg roof turconsed conducting investigation to determine origin MURRAY,B. Region 4, Oto of the Oirector 88/11/25, p. 47648 200-47648 200
- 8811380331 Summary of Operating Peactors Events Meeting 88-45 on 881115 lust of attondees & handouls and:
 LANNING.W.D. Events Assessment Branch, 88/11/25 RCSSICE, Division of Operational Events Assessment (Post 970411), 16pp. 47674.141-47674, 156
- 8812210184 Forwards LER 58-368/88-019-00 re-corrosion & fallure of svc-water impeller snap rings Only abstract of LER submitted due to temporary increase in number of LERs to be submitted by 800228 LEVINEJ.M. Arkansas Power & Light Co. 88/12/12 Cocument Control Branch (Document Control Dask). 2pp. 47875-353-47875.355.
- -8812210281 LER 88 019:00 on 881111,corrosion & failure of sick water pumps imposer shap rings discovered Caused by hersh environ of take water.Pelinps repaired & returned to sick Evaluation continuing.
 TAYLOR L.A. Arkansas Power & Light Co. 88/12/12 1p. 4/875.355-47875.355.
- 8812230177 Forwards LER 88-018-00 re discovery of unseated fire barrier opening Util unable to submit all repts to desired fixed of detail within 20-day time period required by 10CFR50.73 Total of six repts submitted in abstract form only. LEVINE, J.M. Arkansas Power & Light Co. 89/12/12 Document Control Branch (Document Control Desk). 1p. 47811-312-47811-314.
- ~8812200211 LER 88-018-00 on 980922unsealed fire barrier opening discovered which results in operation prohibited by Toch Specs Caused by incorrect evaluation of condition when initially identified Opening sealed W/891212 lin. MICHALKE, LEVINE, J.M. Arkensas Power & Light Co. 88/12/12, 2pp. 47911:314-47911.314.

DOCKET 50-369 WILLIAM B. MCQUIRE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811230276 Informs that ench revs to emergency plan implementing procedures transmitted on 881107 W/o encls LEONARD,R. Duko Power Co. 88/11/14. Region 2, Ofc of the Director. 1p. 47852.090-47052.090.
- 8911300576 Advises that 860909 Rev 9 & 860929 corrected page to Rev 9 to guard training & qualification plan consistent w/ provisions of 10CFR50.54(p) & acceptable NRC 881017 act of receipt of corrected page to Rev 9 should be disre-
- garded CUNE,WE Region 2, Ofc of the Director 86/11/18 TUCKER,H.B. Duke Power Co. 2pp 47674:126-47674:127.
- 8812090029 Forwards public version of Rev 28 to "Crisis Mgt Plan" W/ DH Grimstoy undeted recesse memo. TUCKER.H B. Duke Power Co. 88/11/22. Document Control Branch (Document Control Deski, 4pp. 47757:171-47757:215
- ~8812990034 Pobit version of Flov 28 to "Crisis Mgt Pian for Nuclear Stations."

 * Duke Power Co. 88/12/01, 41pp. 47757;175-47757;215
- 8812060106 Forwards zevs to emergency plan implementing procedures mailed on 861122 W/o encl.
 LEONARD.R. Duke Power Co. 88/11/28. Region 2, Ofc of the Director. 1p. 47741,136-47741,135.
- 8812050103 Forwards response to NRC 881031 ltr re-violations in Insp Repts 50:3897-88-28 & 50:370768-28 Response withheld (ref (IQCFR73.21), TUCKER.H.B. Duke Power Co. 88/11/30. Document Control Branch (Document Control Oask), 2pp. 47731-222-47731-223
- 6812090162 Informing that oncl revs mailed to NRC on 881129 to update emergency plan implementing procedures.W/o encl. LEONARD.R. Duks Power Co. 88/12/02. Region 2, Olc of the Director. 1p. 47762303/47762303.
- 8812210386 Forwards revs to update amergency plan implementing procedures.W/o ancis. LEONARD,R. Duke Power Co. 88/12/13 Region 2, Q/a of the Oirector. 1p. 47875:131-47875:131.
- 8812270264 Responds to exercise weakness noted in Insp Rept 50:369/68:27 & 50:370/88-27.per 10CFR50.App E.Corrective actions emphasis will be placed on emergency action levels during senior reacts) operator requestication training. TUCKER.H.B. Duke Power Co. 88/12/16. Document Control Desk) 3pp. 47925:358-47925:360.

H. General correspondence

8812090335 Confirms meeting w/utif on 881209 at Region If ofcire reorganization.per 881121 telcon. ERNST,ML Region 2, Ofc of the Director, 88/12/01, TUCKER,H.B. Duke Power Co. 1p. 47782:231-47782:231.

P. Operating license stage documents & correspondence

- 8811900228 Responds to Generic Lir 88-11, "NRC Position on Radiation Eintraliered of Reactor Vessel Metis 8, Impact on Plant Operations," New pressure 1947 11:3 must be implemented on by June 1989. TUCKER-HIB, Duke Power Co. 88/141/21, Document Control Braidh (Counter) 10:3 trol Deski, 3pp. 47696-277-47696-279.
- 8811280048 Generic Ltr 88-20 to all transpess holding Otis 8 CPs for nuclear practices facilities no individual plant exam for severe accident vidurabilities Sic. 18 enc. CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88711723. Cascil dated Edison Co. of New York, Inc. 81pp. 47726:303-47729 024.
- 8811300152 Responds to request for additinfoire util request for extended entagency for VC/YC sys mod TUCKER, H.B. Duke Power Co. 88/11/23 | Document Control Branch (Document to India Desk) 29pp. 47673 069-47673 097
- 8812070025 Application for amends to Licenses NPF-35,NPF-52,NPF-9 8 NPF-47 (a lyng Tech Spec 6.2.3 re-safety rownw group Fee paid TUCKER HB. Duke Power Co. 89/11/28. Document Control Branch (Pocument for trol Desk). 11pp. 47746-050-47746-066.
- ~8812070027 Proposed Toch Spac 6.2.3 re satety review group.
 * Duke Power Co. 89/11/28 6pp. 47746:061-47746:066
- 8812080080 Requests that util address Ganoric Ur 88-17 te loss of UPR during repower operation issue of high priority 8 should be addressed accordingly MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 85/12/02. LEE,W.S. Duke Power Co. Spp. 47753:129-47753.133
- 8812120012 Forwards "Emergency Dose Assessment Manual" TUCKER,H.B. Duke Power Co. 88/12/07 Document Central Branch (Document Control Branch (Document Control Dosk), 3pp. 47780,219-47781,120.
- -8812120014 "Cuke Powor Co Emergency Dose Assessment Manual." TUCKER.H.B. Duke Power Co. 88/11/21 259pp 47780.222-47781:128

Q. Inspection reports, IE Bulletins & correspondence

- 8811290264 Provides comments re NRC SALP Repts 50 413/88-24, 50-414/68 24,56-369/88-21, 8 50-370/88-21, TUCKER,H.B. Duke Power Co. 88/11/21. Document Control Branch (Document Control Dask). 2pp. 47650 033-47650 034.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Initiation Nutries Gauges" Svc list enct.
 CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Pest 870725),
 88711722 Consolidated Edison Co. of New York, Inc. 99pp. 47709-255-47768-257
- 8811180467 NRC Info Natice 88 091, "Improper Administration & Control of Psychological Tasts," See list and ROSSICE Division of Operational Events Assessment (Post 870111) 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708:142
- 8812060008 Forwards 881027 onforcement conference summary re Insp Repts 50.3597 88.24.50 370788-24.50 389786-29 & 50.370788-29 Issues rollogorability of hydrogon skirmer sys & inoperability of sefety sys due to inadequate post-mod instead decreased. ERNST.M.L. Region 2, Otc of the Director, 88/11/25, TUCKER,H.B. Duke Power Co 62pp 47752 223-47752-283
- 8812020063 Forwards steam generator inspirept for little refuelling outage,por 1c.th Specs 4.4.5.5.8 & c.8.6.9.2.Lists quantities of generator tubes removed from svc by plugging 8 info on Fituhes w/locations 8 size of degradation. TUCKER,118. Outa-Power Co. 88/11/29. Document Control Branch (Document Control Desk) 16pp. 47716.296-47716:311.
- 8812020300 Revised response to violations noted to this Repts 50:369/87-04 & 50:370/87-04-Corrective actions:performance test procedures changed to require operations senior reactor operator sign off prior to beginning test TUCKER, I1 B. Duke Power Co. 98/11/29. Document Control Branch (Document Control Desk). 6pp. 47721:007-47721:012.
- 8812050103 Forwards response to NRC 881031 ltr re-violations in Insp Repts 50 3697 88-28 & 50-370788-28. Response withheld (ref 10CFR73.21) TUCKER,MB. Duke Power Co. 88/11/30 Document Control Branch (Document Control Desk). 2pp. 47731:222-47731:223.
- 8812050072 Advises that use of ASME Code Cases N-401,N-416,N-426 & N-427 in a service lasp program approved per 880302 request.
 MATHEWS.O.B. Project Directorate tt-3, 88/12/01, TUCKER,H.B. Duke Paint Co. 7pp. 47734.020-47734.028.
- 8812120118 Provides action status update re NRC Bulletin 88-004, "Potental Safety-Related Pump Loss." Migs contected re anticipated response time after 890601 TUCKER-NB Duke Power Co. 88/12/01. Document Control Branch (Document Control Desk). 2pp. 47791:339-47791:340.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc tist onct. CUNNING-IAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88:094, "Potentially Undersized Valve Actuators" Sva list encl. ROSSI,CE. Division of Operational Events Assessment (Post 870411), 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708.254.
- 8812120112 Responds to violation noted in Insp. Repts 50:369/88:30 & 50:370/08-30. Corrective action takentitatining package for all licensed operators reinterpretation of time finitis associated w/Toch Spec 3.0.3 initiated TUCKER,H.B. Duke Power Co. 68/12/05. Document Control Branch (Document Control Desk). 5op. 47787:001-47787:005.

- 1912160163 Forwards Insp. Repts. 50 069789/31 & 50 370788 31 on 881021-1121 &
- natice of violation BEDWNLEE,VIL Region 2, Old of the Director, 88/12/05, TUCKER,HIB, Duke Power Co 7pp 47632-265-47832 282
- 8812160167 Notice of visiation from inspiral on 881021-1121 Violation noted fling them by 8 particulous of retineing cavity impropedly implemented & procedures for performance test of fuel all transfer purity endoquate.

 BEOWILEE,VIL Region 2, Ote of the Orector, 88712705, 4pp. 47832,267-47832,270. -9812160167 Notice of
- umposived Liems political of 8 SU 370/68/31 on 88/1031/1121 Violations & umposived Liems potent Migur areas, inspected operations safety varification, surveillance testing mant activities & Part 21 followup VANDOOHN K., NELSON, D., CROTEAU, R. Region 2, Ofci of the Director 88/12/02, 12pp. 476/32/271-476/32/282 -8912160170 Trisp Repts 50/36978(Ltf. & 50/370788/31 on 801031/1121 Violations &
- 3812160162 Forwards Insp Repts 59 369/88 32 & 53 370/88/32 on 881114-18 & notice
- of violation FERDLARI, Region 2, Old of the Overter BB/12/US TUCKER,H.B. Duko Power Co 2pp. 47303 327-47830 344
- -8812160166 Notice of violation from one 6811114-18 Violation noted volumetric aram of lower head-to-shot well as pirt of preservice inspired performed 8 request for reservoir such mited to NHC HERDITATE. Region 2, Old of the Director 88712-36, 4pp. 47830-328-47830-332
- -8812160169 Insp. Repts 50:369/88/32 & 50:370/88/32 on 881114-18 Violations noted Major intens inspected inscrince inspiprogram. KLE 4SUHGE W.P. BLAKE, Lit. Begion 2, Old of the Director 88/11/30 12pp 47833 333-47830 344
- 3812020287 NHC Info Notice 08 095, "Inadequate Procurement Requirements Imposed by Licenseas on Vendors ROSSI,C.E. Division of C
- P) 20087 NHC into Notice to 0.55. In antiquam crossional insign entering imposed by Licenscop on Vendins." Svc 1st enc. ROSSICE: Division of Operational Events Assessment (Post 870411) 88/12/08. Consolidated Edison Co. of New York. Int: 112pp. 47807-191-47807.302
- 8812210257 Forwards summary of 181020 8, 21 SALP presentation meetings. List of reciscos 8 NRC altendoes 8 states used during presentation also end. ERNST.ML Triag on 2, Otc of the fure for 188712714, Tucker.H B. Duke Power Co. 84pp. 47877 162-47877-247.
- 8812270254 Responds to exercise weakness noted at lists Rept 50-369/88-27 & 50-370768 27 per 100ERS0.App. C. Corrective actions emphasis with the placed on omer-gency solich toyets during serior reactor operator requalification training. TUCKER H.B. Quite Power Co. 88712716. Document Control Branch (Document Contro" (Jesk) (3pp. 47925/358-47925/360)
- R. Periodic operating reports & related correspondence
- 8812200023 Forwards monthly operating rights for Nov 1989 for McOuire Units 1 & 2 & corrected Jan & Apr 1088 repts for Units 2 & 1 respectively.

 TUCKER FLB Duke Power Co. 88712715 | Document Control Branch (Document Contra! Desk) 1p 47861 059 47861 071
- -8812200146 Monthly operating ropts for Nov 1988 for McChiro Units 1 & 2. WILLIAMS,R.A. Duko Power Co. 88/11/30, 10pp. 47864 060-47861.071.
- --8812200150 Corrected monthly operating rept for Jan 1998 for McGuire Unit 2 MEAD,J.J. Duke Power Co. 68701731, 1p. 47861,070,47861,070.
- --8812200190 Corrected monthly operating upt for Apr 1989 for McGuire Unit 1 MEAD J.J. Duke Power Co. 88704730 [sp. 47861 071-47861 071.
- -8612200193 Monthly operating status rept re-personnal exposure for Oct 1986 for McGere Nuclear Station
 * Dike Power Co. 88/10/31, 1p. 47861-072-47861-072
- S. Reportable occurrences, LERs & related correspondence
- 8811300431 Special reption 831017,diosel generator 1A storted for operability tost & subsequently Impred Caused by loose wire on jucket pump discharge pressure switch the property of the pump discharge pressure switch calbr. TUCKER, H.B., Duke Power Co. 8II/11/16. Deciment Control Branch (Document Control Deck), 3pp. 47697 253-47697 255.
- 8811290560 LER 88-029-00 on 8B1005,Unit 1 & 2 fre barriers breached. Caused by mgt del ciencies. Fire/flood barrier perioditations properly sealed by Bahnson personnel W/ ARTLIA Hr LEROY, S.E., TUCKER, H.B. Duko Power Co. 1/8/11/18, 10pp. 47650-081-47650-090
- 8812020047 LER 88-010-01 on 880710 flow requirements not moliby some damper compartment flows on VX sys Classed by distactive procedure 8 design deficiency-Flow reless re-evaluated 8 mod of sys to activate sys flow balancing planned W7881125 ltr. LEROY,S.E., TUCKER,H B Duke Power Co 88/11/25 12pp 47711.035-47711.046
- 8812020237 Adv.sos that due to uniresolved concerns,881128 submittel of LER remissed fire watches deleyed Subj LER will be submitted to later than 881229. TC/XER/M.6. Dake Power Co. 88/11/29. Do. ument Confrol Branch (Document Control Dosk). 2pp. 47711:021-47711.022
- 8812060284 Special rept on 881030,(hiuse) Generator 1B experienced Invalid test falure during Start Attempt 602 Applicable procedures for diesel generator testing reviewed & revised if necessary.
 TUCKER,H B Duke Power Co. 88/11/29, Document Control Branch (Document Con-
- trel Desk) 3pp. 47734-336-47734.338
- 8812090247 LER 88-032-00.on 881012,annulus ventilation sys inoporatie due to door seal fallure resulting in Unit 1 romaining in hot standby for over required 7 h.Caused by personnel error & mgl deficiency Snals on doors repaired W1881130 ftr. LEROY,S.E., TUCKER,H.B. Duke Power Co. 88/11/30 9pp. 47783 347-47783.356.
- 8812120094 Special reption 881205,diesol generator 1B experienced invalid test fallure Caused by Improper adjustment of voltage regulator due to personnel error Operations mat will cover incident w/representative from each shift. TUCKER,H.B. Duke Power Ca. 88/12/105 Document Centrol Branch (Document Control Desk). 3pp. 47786-358-47786-360.

- 8812140252 Special reption 881015,vaire 1NV-238 failed to open Caused by loss of power to control cabinat 6 due to technician error during replacement of backup power supply Wiring reloated to proclude future occurrences
 Tube Power Co. 88/12/08 Document Control Branch (Document Control Desk) 4pp. 47848.284.47848.331
- 8812220059 Summary of Operating Reactors Events Meeting 88-48 on 881206 Agends & list of attendees each LANNING, WID Events Assessment Branch 88/12/07 ROSSI, C.E. Division of Operational Events Assessment (Post 870411) 15pp 47922 001-47922 015
- 8B12140233 LER R8 033-00 on 8B1031,6xhaust gases discovered loscaping from cylinder 1L exhaust manifold exapansion jornt of diseal generator 1B & on 8B1101,exhaust manifold feled tigen Caused by mig deficiency,W/R81208 ltr.
 LEROY,S E , TUCKER,H B | Duke Power Col 8B/12708 7pp | 47800 234-47800 240

DOCKET 60-370 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 6811230276 Informs that enci revs to emergency plan implementing procedures transmitted on 681107.W/o encis LEONARD,R Duke Power Co. 88/11/14 Region 2, Ofc of the Director. 1p 47652.090-47652.000
- 8811300576 Advises that 880909 Rev 9 & 860929 corrected page to flev 9 to guard training & qualification prant consistent w/ provisions of 10CFR50 54(n) & acceptable NRC 881017 ack of recept of corrected page to flev 9 should be discrete. garded CLINE.W.E. Region 2, Old of the Director, 88/11/18, TUCKER,H.B. Duke Power Co 2pp. 47674-125-47674-127
- 8812090029 Forwards public version of Rev 28 to "Crisis Mgt Plan" W/ DH Grimsley undated release memo TUCKER,H B. Duke Power Co. 88/11/22. Document Control Branch (Document Con trol Desk). 4pp 47757:171-47757 215
- -8812090034 Public version of Rev 28 to "Crisis Mgt Plan for Nuclear Stations." * Duke Power Co. 88/12/01, 41pp. 47757 175 47757:215
- 8812060106 Forwards revs to emurgency plan Implementing procedures mailed on 881122 W/o enci. LEONARD.R. Duke Power Co. 88/11/28. Region 2, Olc of the Director. 1p 47741:135-47741.135.
- 8812050103 Forwards response to NRC 881031 ltr re violations in Insp Repts 50:3697-88-28 & 50:370/88-28 Response withhold (ref 10CFR73.21). TUCKER, H.B. Diuke Power Co. 86/11/30. Document Control Branch (Document Control Disk). 2pp. 47731:223-47731:223
- 8812090162 Informing that encl rovs maind to NRC on 881129 to update emergency plan implementing procedures W/o occl LEONARD.R. Duke Power Co 86/12/02 Region 2, Ofc of the Director. 1p 47762 303:47762 303:
- 8812210386 Forwards revs to update emergency plan implementing procedures W/o LEONARD,R. Duke Power Co. 89/12/13. Region 2, Ofc at the Director 1p 47875:131-47875-131.
- 8812270254 Rasponds to exercise weakness noted in Insp Rept 50-369/88:27 & 50-370/88:27,per 10CFR50,App E Corrective actions amphasis will be placed on emergency action levels during senior reaction operator requalification training. TUCKER,H.B. Duke Power Co. 88/12/16 Document Control Desk). 3pp. 47925:358-47925.360

H. General correspondence

8812090335 Confirms meeting w/util on 881209 at Region II ofc re reorganization per 881121 telcon. ERNST.M.L. Region 2, Otc of the Director. 88/12/01. TUCKER,H B. Duke Power Co. 1p. 47782-231-47782-231.

- 8911280086 Understands that permanent mod of containment air return & hydrogen skinner sys will be installed by Jul 1980 refulbling outage based on 881131 request for relief from action statement of Tech Spec 3.5.5.6. ERNST,M.L. Region 2, Ofc of the Director, 88/11/10, TUCKER,H.B. Duke Power Co. 1p. 47854:147-47854:147.
- 8811300228 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Malls 8 Impact on Plant Operations." New pressure temp limits TUCKER,H B. Duke Power Co. 88/11/21. Document Centrol Branch (Document Control Desk). 3pp. 47696 277-47696:279.
- 8611280048 Generic Lit 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities to individual plant exam for severe accident vulnerabilities. Svc list CRUTCHFIELD,D Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47/28/303-47728.024.
- 8811300152 Responds to request for addl info re util request for extended outage time
- for VC/YC sys mod. TUCKER,H.B. Duke Power Co. 88/11/23. Document Control Branch (Document Control Dask). 29pp. 47673-069-47673.097.
- 8812070025 Application for amends to Licenses NPF-35,NPF-52,NPF-9 & NPF-17,clan-fying Tech Spec 6.2.3 re selfety roview group Fee paid TUCKER,H.B. Duke Power Co. 88/11/28. Document Control Branch (Document Con-trol Desk). 11pp. 47746.050-47746.066.

- 8812080080 Requests that util address General Lit 86-17 reliass of DHR during notepower operation issue of Figh prior ty & should be addressed accordingly.
 MURICRY TE Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/
 02. LEEWS Duke Power Co. Spp. 47753 129-47753 133
- 8812123012 Forwards "Emergency Dose Ascessment Manual"
 TUCKER,HIB Duke Power Co. 88712707 Document Control Branch (Cocument Control Desk). 3pp. 47760/219/47781.120.
- ~8812120014 "Duke Power Co Emergency Dose Assessment Manual" TUCKER,H.B. Duke Power Co. 88/11/21, 259pp. 47769 222-47781 120
- Q. Inspection reports, IE Bulletins & correspondence
- 8811290264 Provides comments re NRC SALP Repts 50:413/88:24, 50:414/88:24,50:369/86:21 & 50:370/88:21 369/86:21 & 50:370/88:21 TUCKER H B. Duke Power Co. 86/11/21. Document Control Branch (Document Control Dask) 2pp. 47650
- 8811160211 NRC Info Notice 88-090. 'Unauthorized Removal of Industrial Nuclear Geoges, Sculist encl CUNNINGHAM,R.E. Drvision of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708-255-47708 257
- 8811160487 NRC Info Notice 88 091, "Improper Administration & Control of Psycholog-
- cal Tests "Syc list encl ROSSICE Dynalon of Operational Events Assessment (Post 870411) 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47/09 042-47708 142.
- 8812060008 Forwards 881027 enforcement conference summary relinspifiepts 50:369/ 88:24,50:370/88:24,50:369/88:29 & 50:370/88:29 issues to operatually of hydrogen skimmer sys & inoporabity of selety sys due to inadequate post-mod teating discussed. ERNST,M.L. Region 2, Ofc of the Director, 88/11/25, TUCKER,H.B. Duke Power Co. 6209, 47752,223,47752,283
- 8812020300 Revised response to violations noted in Insp Repts 50-369/87-04 & 50-370/87-04 Corrective actions performance test procedures changed to require operations senior reactor operator sign off prior to beginning test TUCKER.H B. Duke Power Co. 86/11/29 Document Control Branch (Document Control Bosk) 6pp 47721-007-47721.012.
- 8812050103 Forwards response to NRC 881031 ftr to violations in Insp Repts 50.369/ 68 28 & 50-370/68-28 Response withheld (ref. 10CFR73.21) TUCKER, NR B. Ouke Power Co. 88/11/30. Document Control Branch (Document Con-trol Dosk). 2pp. 47731.222-47731:223
- 8812050072 Advises that use of ASME Code Cases N-401,N-416,N-426 & N-427 in Inservice insp program approved,per 880302 request MATTHEWS.D.B. Project Directorate II-3 88/12/01. TUCKER,H.B. Duke Power Co 7pp. 47734 020-47734
- 8812120118 Provides action status update re NRC Bulletin 93.004, "Potential Sefety-Related Pump Loss." Migs contacted re anticipated response time after 890801. TUCKER, HS. Duke Power Co. 89/12/01. Document Control Branch (Document Con-trol Desk). 2pp. 47791:339-47791.340.
- 8311290030 NRC Into Notice 88-093, "Teletherapy Evants." Svc list enct.
 CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729)
 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list enci.

 ROSSI,C E. Drylsion of Operational Events Assessment (Post 870411) 98/12/02
 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708-254
- 8812120112 Responds to violation noted in Insp. Regts 50:389/88-30 & 50:370/88-30 Corrective action taken training package for all scansed operators no interpretation of time limits associated without Special 30-3 initiated. TUCKER,H.B. Dute Power Co. 88/12/05 Document Control Branch (Document Control Desk), 5pp. 47787:001-47787:005
- 8812180163 Forwards Insp Repts 60-369/88-31 & 50-370/88-31 on 881021-1121 & notice of violation BROWNLEE,V.L. Region 2, Otc of the Director, 88/12/05, TUCKER,H B. Duke Power Co. 2pp. 47832 265-47832 282
- --9812180167 Notice of violation from Insp on 881021-1121. Violation noted filting draining & puniscation of refueling cavity Improperly implemented & procedures for performance test of fuel oil transfer pump inadequate. BROWNLEE, V.L. Region 2, Ofc of the Director. 88/12/05. 4pp. 47832.267-47832.270
- -8412180170 Insp Repts 50-369/88-31 & 50-370/88-31 on 881031-1121 Violations & unresolved items noted Major areas inspected operations safety verification, surveillance testing, maint activities & Part 21 followup VANDOORNIX., NELSON,D., CROTEAU,R. Region 2, Ofc of the Director. 88/12/02.12pp 47832:271-47832:282
- 1812180182 Forwards Insp Repts 50 369/88-32 & 50-370/88-32 on 881114-18 & notice of violation HERDT,A.R. Region 2. Ofc of the Director, 88/12/06, TUCKER,H.B. Duke Power Co 2pp. 47830,327-47830,344.
- 8812180166 Notice of violation from insp on 881114-18-Violation noted: volumetric exam of lower head-to-shell weld as part of preservice insp not performed & request for teller not submitted to NRC.

 HERDT_A.R. Region 2, Orc of the Director. 88/12/06. 4pp. 47630-329-47630-332.
- 8812180189 Insp. Repts 50-369/88-32 & 50-370/88-32 on 881114-18. Violations noted Major areas inspected inservice insp program.

 KLEINSORGEW P., BLAKE J.J. Region 2, Otc of the Director. 88/11/30. 12pp 47830-333-47830-348.

8812210257 Forwards summary of 881020 & 21 SALP prosentation along a Salph Albert Salph Sa

and Orall

Consolidated Edison Co. of New York, Inc. 112pp. 47807 191 47807

T VIIII

A PART OF THE PROPERTY OF THE

- 8812270254 Responds to exercise weakness noted in Insp. Rept 50 370789-27,per 10CFR50,App E.Corrective actions emphasis will be gency action levels during serior reactive operator requalification trail TUCKER,HIB: Diske Power Co. 88/12/16: Document Control Brand Irol Oesk). 3pp. 47825-338-4/925-360.
- R. Periodic operating reports & related correspondence
- 8812200023 Forwards monthly operating routs for Nov 1988 for McC corrected Jan 8 Apr 1998 repts for Units 2 8 1,respectively TUCKER HS Duby Power Co. 86/12/15 Cocurrent Control Branch for Desk). 1p. 47861 059-47861 071
- #8812200148 Monthly operating repts for New 1988 for Mr.Ohrie Units WILLIAMS,R A. Duke Power Co. 89/11/30 TUPP 47861 060 47861
- --8812209180 Corrected monthly operating rept for Jan 1988 for McGu MEAD, J.J. Duke Power Co. 88701731 1p. 17881 070 47861 070
- -8812200193 Monthly operating status ropt to personnel exposure McGu tu Nucinat Statio * Duko Power Co. 88/10/31, 1p. 47861 072-47861 072
- S. Reportable occurrences, LERs & related correspondence
- 9912020043 Notifies that due to unresolved concerns, LER refund en 3.0.3 will be delayed & submittee no later than 881216 TUCKER,H.6: Doke Power Co. 88711/25 Document Control Branch frol Dekkj. 2pp. 47718/336-47718/337
- 8812020237 Advisus that due to unresolved concerns,881128 sub-missed for whiches delayed SubJ LER wit be submitted no later than TUCKER HB. Duke Power Co. 88/11/29. Decument Control Brench trol Desk). 2pp. 47711.021.47711.022
- 8812220059 Surimary of Operating Reartors Events Meeting 88-48 o ANNING,W.D. Events Assessment (Pest 870411) 15pp 47922 001-47922 0
- 8812140270 LER 88 012 00.0n 881105 operations personnel duclared febion & challed water sys Train A insperable for med & main assigned On 881108, personnel signar received spurious alarm W/68 LERDY,S.E., TUCKER,H.B. Ouke Power Co. 88/12/08 9pp 478120

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

- F. Security, medical, emergency & tire protection plans
- 8812190194 Rev 15 to Emergency Pian Implementing Procedure LZP-tions." W/881202 procedure inclinication form * Commonwealth Edison Co. 88/10/01 18pp. 47853.336-47853.354
- 8811300536 Forwards Sateguards Insp Ropt 50 373/88-26 & 50 374/6 20 No walkings noted GREGER,LR Region 3, Old bit the Director, 88/11/17 REED.C Edison Co. 2pp 47676 044-47876 047
- —8811300542 Partially withhold Physical Security Insp Ropts 50:373/ 98:25 on 881011-20 (ret 10CFR73.21).Mojor areas inspected mgt suj gram plans & audits & protected & vital area physical barriers MADEDA,T.J. CHRISTOFFER,G., CREED,J.R. Region 3, Ofc of the 17 2pp. 47676.046-47676.047.
- P. Operating license stage documents & correspondence
- 8811280048 Ganeric Lit 88-20 to all licensees holding OLs & CPs t reactor facilities re individual plant exam for severe accident vuln end. CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88 dated Edison Co. of New York, Inc. 81pp. 47728 303-47729-024.
- 8812010305 Provides analysis of Reg Guide 1.99.Rev 2. "Rediation Reactor Vosset Matte" for impact on pressure-temp heatup & coold feined in Tech Specs.per Gengric Ltr 88.11 RICHTER.M.H. Commonwealth Edison Co 98/11/26 Document Con-ument Control Desk). 2pp. 47703.049-47703.050
- 6812070040 Application for amends to Licenses NPF-11 & NPF-18, foad profiles for each specific dc battory. Fee paid.
 MDRGAN.WE. Commonwealth Edison Co. 88/11/29 Document (Document Control Dask). 3pp. 47748.007-47746.015.
- -8812070042 Proposed Tech Specs,removing specific load profiles to:
 * Commonwealth Edison Co. 88/11/28. 6pp. 47748.010.47748.015.
- 8812180101 Requests meeting between NRC & util to discuss commoperability assessment criteria for piping sys SHEMANSKI.P.C. Project Directorate III-2, 88/12/12 BLISS.H.E. Edison Co. 1p. 47873.360-47873.360

20.No violations noted GREGER, R. Region 3, Old of the Director 88/11/17 REFD.C Commenwealth Edison Co. 2pp. 47676 044-47676 047

- -8811300542 Parhally will held Physical Security Insp Repts 50-373/88.26 & 50-374/88.26 on 881011-20 (rof 10CFR73 21) Major areas inspected right support security program plans & aud is & protected & vital area physical barriers MADEOA,T.J. CHRISTOFFER.G., CREED.J.R. Region 3, Old of the Director 88/41/17, 2pp. 47676.046-47676.047
- 8811160211 NRC Into Notice 88-090, "Unauthorized Flomovint of Industrial Nectear Gauges." Szc. Ist enci CURN NGHAMME D. Division of Industrial & Mindical Nuclear Safety (Post 870729) 08711722 Consolidated Edison Co. of New York, Inc. 89pp. 47708 255-47708 257

6811160467 NRC Info Notice 88 091, "Improper Administration & Control of Psychologi-

- cal Tosts "Svc list encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/11/22. Consciidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142
- 8811290030 NRC Info Notice 88-693, "To atheropy Events." Svc 1st end. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 670729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811-103-47811-215
- 8811290538 NRC Info Notice 88 094, "Potentially Undersized Valve Actuators." Svc list BOSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708.143 47/08.254.
- 8812130133 Forwards Safety Insp Repts 50 373/88-27 & 50-374/88-26 on 881017-24

8 notice of violation MILLER, H.J. Region 3, Ofc. of the Director 80/12/05 REED,C. Commanwealth Ed son Co. 2pp. 47797:100-4779/ 115

- -8812136134 Notice of violation from inspiren 881017-24 Violation nated lutil failed to electrical splice on we are in the responsibilities of the struck tubing & Okonto tapes used in electrical splice assemblies for 10CFR50 49.

 MILLER, H.J. Region 3, Old of the Director 88/12/05 1p. 47797:102-47797 102
- -8812130136 Safety Insp Repts 50-373/80-27 & 50-374/88-26 on 881017-24 Violation 8812130136 Satisf help replaced and instrumentation sys for inspecting plant conditions during & lettowing accident as specified in Reg Guide 197,Rev 2 GARDNER,RN, GAUTAMAS. Region 3, Ofc. of the Greater, 88/11/30 13pp 47787:103-47787.115
- 8812020287 NRC Info Notice 88 005, "fundaquate Procurement Requirements Imposed

Ey Licensees on Vendore." Svc 1st end.
ROSSI,C.E. Division of Operational Eventy, Assosprient (Post 870411) 88/12/08
Consolidated Edison Co. of New York, Inc. 112(p. 47807-191-47807-392)

R. Periodic operating reports & related correspondence

- 8812200049 Monthly operating ropts for Nov 1988 for LaShillu Units 1 & 2.W/881210 ftr THUNSTEDT,J.W., DIEDERICH,G.J., Commonwoolth, Edison, Co., 88/11/30 | 27pp. 47867:334-47867:360
- S. Reportable occurrences, LERs & related correspondence
- 881206002 LER 88-002-01 on 880316, Typo B & Typo C total lookage exconded 0.6 La during look rate testing Caused by excessive lookages Corrective actions include instal largert of new disc listed in Table 1 W/881130 ltr VRLAM_P_CREDERICH,G_J_Commonwealth Edison Co_88/11/30_8pp_47743.094-47743-101.
- 8812070211 LEFT 88-025-00 on 891103 spurious animon's diffector trip due to failure of Chamcassette tape drive motor Caused by design deficiency of chemcassette lape mechanism Drive motor assembly & this mension by prepared W/881201 lin ROUMELIOTIS,G. DIEDERICH,G.J. Commonwealth Edison Co. 88/12/02 Spp. 47747:112-47747:116
- 8812070214 I.ER 88-0/36-00.on 881105.spuncus amotonia dotector trip due to design def-ciency in Chomcassetto topo machanism Caused by Janimed chomcassetto topo in detector unit.Chomcassetto topo unhuund & realigned & detector resut W/081202 ftr. ROUMELIOTIS,G., DIEDERICH,G.J. Commonwealth Edison Co. 88/12/02 5pp 47745 353 47745 357
- 8812270237 LER 88-027-00 on 881128 operator performing plant daily surverlances re-ported drywoll circuits energized contrary to Tech Specs 3.8.3.1 Caused by personnel violating station policy. Circuits decirergized & broakers locked W7881221 lit TENNYSON,M. DIEDERICH,G.J. Commonwealth Enison Co. 88/12/21 5pp 47926 001-47926 005

DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 8812190194 Rov 15 to Emergency Plan Implementing Procedure LZP-1310-1, "Not/ications." W/881202 procedure notification form
 * Commonwealth Edison Co. 88/10/01, 19pp. 47653 336-47853 354
- 8811300536 Forwards Safeguards Insp Ropt 50:373/88-26 & 50:374/88-25 on 881011-

20 No violations noted GREGERLLR, Region 3, Ofc. of the Director, 88/11/17, REED,C. Commonwealth Edison Co., 2pp. 47878-044-47876-047.

-8811300542 Partially withheld Physical Socurity Insp. Repts 50:373/88:26 & 50:374/88:25 on 881011-20 (rof 10CFF73 21) Major steas inspected angl support security program plans & audits & protected & stall area physical barriors MADEDA,T J. Region 3, Otc of the Director 88/11/17, 2pp. 47676:046-47876.047.

reactor facilities re individual plant evant for severe accident vulnerabilities Svc list CRUTCHFIELD D. Associate Director for Projects (Post 870411), 88/11/23. Consoli dated Edison Co. of New York, Inc. 81pp. 47728 303-47729 024

BH112MUDGB GODERE LITERSZD TO BLITCHESEES HEIDIG OLS G CESTOL

- 8812010305 Provides analysis of Rug Gurdo 1,99,Rov 2, "Radiation Embrittlement of Reactor Vesser Matis Tor repaction pressure-temp heatury & cooldown curves con-tained in Touth Specs per Genone Util 08-11. RICHTER MTT Commonweight Ertisch Co. 88/11/28 (Document Control Branch (Dec-ument Control Desk). 2pp. 47703-049-47703-050.
- 88 12070040 Application for amounts to Licenses NPF-11 & NPF-18 removing specific load profiles for each specific de ballory Fig. paid.
 MORGAN,W.E. Communical th Forsian Co. 88/11/29 Occurrent Control Brench (Pocument Control Do.4) 3pp. 47746 c07-47746 015.
- -8812070042 Proposm1 Tech Spess removing specific load profiles for each do ballary *Commonwealth Edison Co. 80711729 -8pp -47746-010-47746-015.
- 8812070229 Application for amount to Flacense 142F-18 revising Table 3.8.3.2-1 to reflect new locations of breakers for Valva 2E12-F039,RHR shutdown cooling suction Isolation valve. Significant flactuids consideration ovaluation end Fue paid MORGAN,WE. Commentwealth Education Co. 28/12/02. Occument Control Branch (Document Control Dosk). 3pp. 47747-073-47747-080.
- -8612070231 Proposed Tech Spaces, vehig Table 3.8.3.2-1, "Printary Containment Proposed for ductor Cyrendent Protective Devices" to reflect revised breaker compartment Seat ons of revised seatons of part number rolls. "Commonwealth Edison Co. 18712702, 54p. 47747-076-47747.080.
- 8812160101 Ficquests most by botween NFIC & util to discuss community on alternate opmability issortiment interia for ping sys SHEMANSKI,P.C. Project Directorate III-2 88/12/12 BLISS,FLE Commonwealth Edison Co. 1p. 47873 360-47873 350
- Q. Inspection reports, IE Bulletins & correspondence
- 8811300536 Forwards Saleguards help Ropt 50/373/88 26 & 50/374/88/25 on 881011-20 No violations nated GREGERI, B. Region, 3, Ofc. of the Director, 89/11/17, REED,C. Commonwealth Edison Co. 2pp. 4767-6-044, 47676-047
- #811300542 Partistly withhold Physical Secondy http://doi.org/10.001374/88.25 on 881011-20 (ref.10CLR74.21) Major areas hispected mgt support, socially program plans & muldis & prefected & vital preaching the physical barriers MADEDA, TUT, CRRISTOFFER, G., CRRISTO, R. Region 3, Ofc. of the Director, 887117-17 (2pp. 47676.046-47676.047.)
- 8811160211 NRC Into Notice 88-090, "เป็นตสโท กระป flormaval of Industrial Nuclear Gringos" Svc list end CUNNINGHAM IT Division of Industrial & Moderal Nuclear Safuty (Post 870729) 88/11/22 Consolidated Edecin Co of New York, Inc. 09pp. 47708 255-47708 257.
- 8811160467 NRC Into Notice 88 091, "Incoroper Administration & Control of Psychologi-Cal Tuets," Svc. list erc. ROSSI,C.E. Division of Operational Evolute Assessment (Post 670411). 98/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142.
- 8811200030 NRC Into Nation 86 093, "Total orapy Events." Syc list encl. CUNNINGFIAM,R.E. Division of Influstral & Medical Nuclear Safety (Post 870729), 68/12/02, Consolidated Edition Co. of New York, Inc. 112pp. 47811:103-47811:216.
- 8811290538 NRC Into Notice 88 694, "Potentially Undersized Valve Actuators." Svc list ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 4/708 143-47709 254.
- 8812130133 Forwards Salety Insp Ropts 50:373/88-27 & 50:374/88-26 on 881017-24 8 notice of violation MILLER H.J. Region 3, Olic of the Director 80/12/05. REED,C. Commonwealth Edison Co. 2pp. 47:97 (1:0-4/797.115
- -0812130134 Notice of violation from linsp on 881017-24 Violation noted: util failed to quality various configurations of Raychom heat shrunk tubing & Okonite tapes used in electrical spice assembles for 10CFR50 49. MILLER, H.J. Region 3, Oic of the Director, 88/12/05 1p. 47797,102-47797.102.
- -8812130138 Safety Insp Repts 5th 373788-27 & 50-374788-28 on 881017-24. Violation during & following accident as - procted in Reg Guida 1.97,Rev 2.

 GARDNER R.N. GAUTAM A.S. Region 3, Oto of the Director. 88/11/30. 13pp. 47707.103-47797:115
- 8812020287 NRC Info Notice 88 095, "Inadequate Procurement Requirements Imposed by Licensons on Vondors." Svr. l-st onct ROSSICE: Division of Operational Evonts Assessment (Post 870411). 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302
- R. Periodic operating reports & reinted correspondence
- 8812200049 Monthly operating repts for Nov 1988 for LeSalfo Units 1 & 2 W/881210 lin THUNSTEDT,J W., D/EDERICH,G J. Commonwealth Edison Co. 88/11/30 2/pp. 47867-334-47867-360

S. Reportable occurrences, LERs & related correspondence

8811300427 Special rept on 881013 & 15,6re doors 406 & 393 blocked open, ospectively & made inaperable in excess of 7 days. Fixe door 400 blocked open to allow passage of security cable & door 393 to allow passage of in 3h voltage cable DIEDERICH, G.J. Commonweillh Edison Co. 8871177 DAVIS, A.B. Rogion 3. Oct. of the Director. 1p 47701 258-47701;258

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8812870143 Change 2 to Rev 11 to Entergency Plan Implementing Procedure EP-1-001, "Recognition & Classification of Emergency Conditions" W/881201 ltr. CAINS N.S., BURSKI,R.F. Louis and Power & Light Co. 86/12/01. 8pp. 47746:295-47746 302

8812270294 Responds to eight emergency preparedness program deficiencies ob-served during 1908 annual exercise noted in linsp Repi 50 382/89 24.Lessons tearned review session conducted w/supervisors by 881212. BURSKIR,F. Louisetae Power & Ught Co. 88/12/21. Document Control Branch (Doc-ument Control Desk). 11pp. 47924 091-47924-011.

K. Utility Final Safety Analysis Report (FSAR) & amends

8812200032 Rev 2 to updated FSAR for Waterford Steam Electric Station Unit 3.W/ DEWEASE.J.G. Louislana Power & Light Co. 86/12/31. 1,200pp. 47865;036-47867;237.

P. Operating license stage documents & correspondence

- 6811280046 Generic Lir 88:20 to all licensees holding Ots & CPs for nuclear power reactor facilities so individual plant exem for severe accident vulnerabilities Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23. Consolidated Edison Co. of New York, Inc. 81gp. 47728 303-47729 024.
- 8812010116 Forwards addit Info to support ut 1 880920 request for amend to License NPF-38 defeting line protection requirements from Tech Spec & adopting sid fire protection license condition.

 BARIKI (URST,R.P. Louisiana Power & Light Co. 89/11/28 Document Control Branch (Occurrent Control Desk), 4pp. 47698,295-47699 343
- -8812010119 Roy 0 to UNT-5 013, "Admin.strativo Procedure Fire Protection Program." * Louislane Power & Light Co. 88/11/18, 44pp, 47698,300-47698,343
- 8812090077 Advisos that util should address Generic Lir 89.17 re foss of DHR during nonpower operation. Lir issued due to potentially senous consequences of inadequacy of industry response to Generic Lir 87.12 MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/02 CARN, C.L. Louisiana Power & Eight Co. App. 47761.285-47761.288
- 8812090158 Forwards Amond 48 to License NPF-38 & safety evaluation Amend changes App A Tech Spec for reactor coolant flow-low trip to allow operator to bypass trip below 0.0001% of rated thormal power.
 WIGGINGTON, D.L. Project Directorate IV. 88/12/02 DEWEASE, J.G. Louisiana Power

8 Light Co. 4pp. 47782.095-47782:105.

- ~8812090159 Arriand 46 to Ucensa NPF-38,revising App A Tech Space for reactor coolant flow-low trip to office operator to bypass trip below 0,0001% of rated thermal Dower, CALVO, J.A. Project Directorate IV. 88/12/02 Spp. 47782.039-47782.103.
- -8812090180 Safety evaluation supporting Amend 46 to License NPF-38
 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/02 2pp
 47782:104-47782:105.
- 8812120105 Application for armend to License NPF-38 deleting motor-operated valve actuator compartment-heater circuit breakers from Table 3.8-f. Fee paid DEWEASE_JG_Louisiana Power & Light Co. 88/12/06. Document Control Branch (Document Control Desk). 7pp. 47707:038 47787:051.
- --8612120113 Proposed Trich Specs deteting motor-operated valve actuator compartment-heater circuit breakers from Table 3 θ·1.

 * Louislana Power & Light Co. 86/12/06. 9pp. 47787.042 47787.051.
- 8812220065 Forwards Amend 48 to License NPF-38 & safety evaluation. Amend changes Tech Space on boron distribution by adding Mode 4 requirements clarifying surveillance to verify systepolation only when sys to be isolated. WIGGINTON,DL. Project Directorate IV. 88/12/14. DEWEASE,J.G. Louis'ana Power & Light Co. 4pp. 47902.316-47902:332.
- --8812220068 Amend 48 to License NPF-38, changing Tech Space on boron dibition by suiding Mode 4 requirements, clarifying surveillance to verify sys Isolation only when sys to be isolated & revising backup dibition detection frequencies.
 APPOPCS Directorate IV. 88/12/14, 11pp. 47902:320-47902.330.
 - 2 Salety evaluation supporting Amond 48 to License NPF-38.

 1 Nuclear Reactor Regulation, Director (Post 870411). BB/12/14. 2pp 17902.332.
 - wards Amend 47 to Licensa NPF-38 & salety evaluation. Amend Space to ESFAS instrumentation as related to actions required for loss hannels that protect ageinst loss of voltage on emergency bus &
 - ofect Directorate IV. 88/12/14. DEWEASE,J.G. Louisiana Power 97-17892.211.
 - o Liconse NPF-38,changing Tech Specs on ESFAS instructions required for loss of one or more channels that protect degraded vollage on emergency bus & Circuits orato IV, 80/12/14, 8pp. 47892 201 47892.208.

-8812220092 Safety evaluation supporting Amend 47 to License NPF-38
* Office of Nuclear Reactor Regulation, Director (Post 870411) | 88/12/14 | 3pp 47892 209-47892 211

Q. Inspection reports, IE Bulletins & correspondence

8811300210 Forwards Insp. Rept. 50/382/88/26 on 881024/28 No violations of dest. allions noted CALLANUL J. Region 4, Otc. of the Director, 88/11/17 DEWFASE J.G. Louis 3, 3 Power & Light Co. 2pp. 47701:296-47701:308

47701 308.

8811300434 Advises of maint team insp scheduled for wks of 890117 & 30 at facility. Entrace inferview suggested for 890117 & axil interview on 890203. CALLANUL J. Region 4, Oftic of the Direction 88/11/21 DEWEASE J.G. Loisest Power & Light Co. 3pp. 47697 229-47697 231.

881116021F NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nursear Gauges" Svc list and CURNINGHAMAR E. Division of Industrial & Medical Nucleon Safety (Post 67073) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257

881160467 NRC Into Notice 88-031, "Improper Administration & Control of Psychological Fests" Svc fist end ROSSIC El Division of Operational Events Assessment (Post 870411) 887/17/2 Consolidated Edison Collaboration (101pp 47708 042-47708.142)

8811290483 Notification of SALP mgt meeting on 881201 w/ut3 in Rocke2io,NO to as cossissessment of utilifor period 870201-0731. CALLANUL Region 4, Old of the Director, 88711722 Region 4, Old of the Director, 88711722 Region 4, Old of the Director, 2004-0757, 302-47657, 302-47657, 303.

8811290474 Forwards Equipment Qualification Insp Rept 50-382/88-27 on 684017 27 & 8B1101-04 & notice of violation.
CALLAN,L.J. Region. 4, Ofc. of the Director. 88/11/23. DEWEASE,J.G. Louisera.
Power & Light Co. 3pp. 47665:112-47665.123.

~8811290476 Notice of violation from inspiron 881017-27 & 8811101-04, Violation noted iTT Barton,Model 763 & 764 pressure transmitters from the tradequate y install histogram of but not adequate y install histogram 4. Ofc of the Director, 88/11/23 2pp. 47665 115-47665:116

-8811290477 Insp Rept 50:382/88:27 on 881017:27 & 881101-07.Violations noted Major areas inspected licenses actions on previously identified items to major ment documented in NRC tiesp Rept 50 382786-32 on 870416 STETIKATE, JOHNSON,AH Region 4, Oto of the Director (87/11/22 Try 47665 117-47685 123

8812020027 Forwards response to violation noted in Irrep Rept 50-382/89 22 Newton - withheld (re) 10CFR73 21).
BURSKIR F. Lousland Power & Light Co. 88/11/28 | Document Control Branch (Encument Control Desk). 1p. 47721 097-47721 097

- 8812020303 Forwards Insp. Rept 50:382/88-25 on 880917-1031 & molice of violation CALLAN, L.J. Region 4, Ofc of the Director, 88/11/29 DFWEASE, LG Louissing Power & Light Co. 2pp. 47722:138-47722-157.
- -8812020304 Notice of violation from insp. on 880917-1031 Violation noted 51-2425 found closed but not focked. No documentation allowing deviation from regured 533'03 nor any procedure in progress requiring valve to be unlocked.
 * Region 4, Ofc of the Director, 88/11/29, 1p, 47722-141-47722,141
- -8812020305 Insp Rept 50:382/88-25 on 880917-1031 Violations noted. Major areas inspiring plant status, onsite followup of events, operational settity verification, more than make observation. STAKER, TR., CHAMBERLAIN, D. Region 4, Old of the Director, 46/11/17, 16pp, 47722:142-47722:157.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." See list end CXNNINGHAM, B. Division of Industrial & Medical Nuclear Safety (Post 870720) 88/12/02 Consolidated Edison Co. of New York, Inc. 12pp 47811:103 47811:215
- 68 11290536 NRC Into Notice 88-094, "Parantially Understred Valve Actuators." Svenist end: SICE Division of Operational Events Assessment (Post 870411) 88/12/02 Censolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812140216 Ack receipt of 881031 ftr informing NRC of steps taken to correct violatives noted in imsp. Rept. 50-382/88-23. Responsiveness to concerns in milico of violation,based on lif. & 881201 telecon,found. CALLAN,L.J. Region 4, Ofc. of the Disoctor, 88712/07, DEWEASE,J.G. Unit status. Power & Light Co. 2pp. 47814.057-47814.071.
- 8812020287 NRC Into Natice 88-095, "Inadequate Procurement Requirements Imposor by Licensees on Vendors." Svc 1st and ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/09 Consolidated Edison Co. of New York, Inc. 112pp. 47807-191-47807-302.
- 8812270294 Responds to eight emergency preparedness program deficiencies observed during 1888 annual exercise noted in Insp Rept 50-382/88-24 Lessons loarned review session conducted w/supervisors by 881212.

 BURSKIR.F. Louislana Power & Light Co. 88/12/21, Document Control Branch (Cosument Control Dask), 11pp. 47924:001-47924-011.

R. Periodic operating reports & related correspondence

8812210148 "Rept of Facility Changes, Tests & Experiments for 1988,per 10CFR50.59." covering 870819 880818.W/881216 ltr.
BURSKI,R.F. Louislane Power & Light Co. 88/06/18, 86pp. 47889.333-47893.058

125

- 8812200053 Monthly operating ropt for Nov 1988 for Waterford 3 W/881212 ltr CENTOLANZI,P., BURSKI,R.F., Louisians, Power & Light Co., 88/11/30, 7pp CENTOLANZIP. BU 47867 244 47867 250
- S. Reportable occurrences, LERs & related correspondence
- 8812010199 LER 88 026 00 on 870108 discovered that wrong piping class tubing installed for bond acid makeup tank level indicators Caused by personnel inadequate rower of design Supports inspected 8 bubing replaced W/681128 liz.

 DAVIS.GM. CARNS.N.S. Louisiania Power 8 Light Co. 88/11/28 7pp. 47709 238.

- 8812020233 LER 88-027-00 on 881012,Okon1o taped splice configurations declared indeterminate status & written operativity determination prepared Gaused by const design documentation not previously supported by documentation W/881130 ltr. HOWARD, J.E., CARNS,M.S. Louis-ana Power & Light Co. 88/11/30, 8pp. 47717 C65-
- 8812130013 LER 88-928-00 on 881103,discovered discrepancy in operating range for configuration purgo isolation radiation monitors. Caused by incorrect translation of range from Generic Ltt 82-16 & C.E. STS to plant Tech Spec W/681205 life GAINES,C.R., CARINS,N.S. Louisiana Power & Light Co. 88/12/05. Spp. 47798 130-
- 8812150035 LER 88-029-00 on 881109, fuel handling bildy vontilation sample enalysis not performed Caused by personnel error. Radiation monitoring tronds reviewed & Inc. Caldod involved counseled W7881212 in LABONTE W T., CARNS N S. Louisiana Power & Light Co. 88/12/12 Spp. 47830-235-
- 6812150039 LER 68-030 00 on 841218, fire barrier discrepancies dating from Initial plant const. Fig. watch patrols established for affected areas & inspire remaining ponetration seals expected to be completed by 881231 W/881212 ftr. FIGLOPHIA L., CARNS,N.S. Louisiana Power & Light Co. 88/12/12 11pp. 47802 281-47802:301.

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8811300066 Rovised emergency plan implementing procedures, including Rov 6 to EP-IP 001, "Classification of Emergency Conditions," Rev 3 to EP-IP-011, "Security Contingency & Emergency Access" & Rev 0 to EP-IP-055 W/881109 ftr KEISER.H W. Pennsylvania Pawar & Light Co. 88/11/09, 39pp. 47702.078-47702.115
- 8811300333 Forwards Safety Insp. Repts 50-367/88-17 & 50-368/68-20 on 880918-1029.Results decumented in entil rept WigGinNSJ F. Reglan 1, Ote at the Director. 88/11/14, KEISER,H.W. Punnsylvania Power & Ughi Co. 2pp. 47673
- --8811300336 Insp Ropts 50:387/88:17 & 50:398/88:20 on 880918:1029 No violations noted Mejor ereas Inspected plant events, surveillance & maint activities. operations, phys.cal BLOUGH,A.R. Rog on 1, Ofc of the Director 88/11/14, 16pp, 47673:135-47673:150.
- 8812120172 Forwards listed add: into re-plant hiro protection review rept W/18 oversize drawnigh KEISER H.W. Pennsylvania Powor & Light Co. 88/11/22, BUTLER,W.R. Project Direc-torato F.2, 36pp. 47827-183-47820.053
- ~8812120191 Roy 11 to EO-100-009, "Plant Shutdown From Outside Control Room" * Periosylven a Power & Light Co. 88/07/07, 43pp. 47827;223-47828.053
- 6812190122 Revised emergency plan implementing procedures including Rev. 11 to EP-IP-030, "Activation & Functional Operation of Emergency Operations Facility & Transfor "& Rev. 10 to EP-9-007, "Personnel Assembly...." W/881130 ftr.
 TABCR,W.F., KEISER,H.W. Pennsylvan'a Power & Light Co. 88/11/30. 68pp. 47651-333-47852.040
- 8812210384 Forwards Roy 11 to Susquohanna Units 1 & 2 oniergancy p'an KEISER H.W. Pennsylvania Power & Light Co. 98712715. BUTLEH.W.R. Project Directorate F2. 4pp. 4789-092-47900-032.
- --8812219368 Rev 11 to "Susqueharina Steam Electric Station Emergency Plan" W/
 - three oversize drawings.
 * Pernsylvania Power & Light Co. 88/10/31 306pp 47893 096-47900.032

H. General correspondence

- 8812050159 Informs of new making address of NRC rearrant inspectors at plant. YOUNG,F. Region 1, Old of the Director 88/12/01. MCKNIGHT,J. Dodument Control Branch (Oddument Control Desk). 1p. 47733 297-47733 297.
- J. Insurance & Indemnity Information
- 8811290375 Forwards Endorsements 1-3 to NELIA Certificate NW-157 & MAELU Certificate MW-77, respectively, Endorsements 7 & 5 to NELIA Certificates N-84 & N-96 & Endorsements 7 & 5 to MAELU Certificates MW-84 & MW-96, respectively Related into KEISER,H.W., Pennsylvania Power & Light Co. 88/11/21 SALTZMAN,J. NRC - No Duta led Affiliation Given: 48pp. 47667 094-47667.141.
- P. Operating license stage documents & correspondence
- 8811280215 Forwards Amends 85 & 52 to Licensus NPF-14 & NPF-22, respectively & safety evaluation Amends remove organization charts from Tech Spacs & make some changes to nomericiature of Section 6 8.2.

- --8811280217 Amends 85 & 52 to Licenses NPF-14 & NPF-22,respectively, removing organization charts from Tech Specs & making some charges to nomenciature of Section 6.8.2 BUTLER,W.R. Project Directorate 1-2, 88/11/16, 18pp, 47657 034-47657 051.
- -8811280218 Safety evaluation supporting Amends 85 & 52 to Licenses NPF-14 & NPF-22 rospectively

 Office of Nuclear Reactor Regulation, Director (Post 870411) (I8/11/16 3pp 47657052-47657054.
- 8811220341 Comment endorsing NUMARC comments on proposed rule 10CFR26 relfitness for duly fire KEISER,H.W. Pennsylvan a Power & Light Co. 88/11/17. CHILK,S.J. Office of the Secretary of the Commission. 3pp. 47721.053-47721.052
- 8811280048 Generic Ltr 88-20 to all liconsees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnerabilities Svc list

CRUTCHFIELD,D Associate Director for Projects (Post 870411) 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.

- 8812090282 Informs of intent to close Riverlands hiking traliper MC Thadant request Closing of hising trail does not have to be availuated as unreviewed environ question as identified in environ protection plan. REISER,H W. Pennsylvan a Power & Light Co. 88/12/05. BUTLER,W.R. Project Directorate 12. Tp. 47785-147-47785 148
- 8812190232 Forwards application for Proposed Amends 116 & 68 to Licenses NPF-14 & NPF-22, respectively, modifying Tech Spec 4 8 2 1 d 2 b to decrease load profites for Batteries 10610, 10620, 10630, 10640, 20610, 20620, 20630 & 20840 Fee paid KEISER, HW. Pennsylvania Power & Light Co. 88712712. BUTLER, W.R. Project Orectorate 1-2, 4pp. 47848 332-47848 342
- -8812190235 Application for Proposed Amerids 118 & 68 to Licenses NPF-14 & NPF-22,respectively,revising Tech Spec 4 8 2 1.d 2 bits decrease toad profiles for 125 volt do battery banks KEISER,H.W. Pennsylvania Power & Light Co. 88/12/12 | 2pp | 47848 335-47848 337
- -8812190237 Proposed Tech Specs, docreasing load profiles for 125 volt dc battery
- Ponnsylvania Power & Light Co. 88/12/12, 5pp. 47848 338-47848 342
- 0812190377 Hosponds to Generic Lir 89-11 re calculation of pressure- temp curves using equations prosented in Reg Guida 1.99.Rev 2.Technical evaluation purformed & new pressure-temp curves developed as result of analysis Technical evaluation encl KEISER, H.W. Pennsylvania Power & Light Co. 88712712 BUTLER, W.R. Project Directorate 1-2, 40pp. 47849-093-47849 132.

Q. Inspection reports, IE Bulletins & correspondence

- 8611300333 Forwards Safety Insp. Repts 50:387788-17 & 50:388788-20 on 880918-1029 Results documented in end rept WIGGINS_J.T. Region 1, Old of the Director, 98/11/14, KEISER,H.W. Pennsylvania Power & Light Co. 2pp. 47673
- --8811300338 Insp. Repts 50-387/88-17 & 50-388/88-20 on 880918-1029 No violations noted Major areas inspected plant operations, physical security, plant vents, surveillance & maint activities BLOUGH, A.R. Rag on 1, Old of the Director. 88/11/14 16pp 47673 135-47673 150.
- 8611300307 Forwards Insp Repts 50:387/89-18 & 60:388/88-21 on 898928-30 & notice of violation
 DURR,J.P. Region 1, Old of the Director, 98/11/17, KEISER,H.W. Pennsylvania,
 Power & Light Co. 2pp. 47676.022-47676.033
- ~8811300309 Notice of violation from insp. on ⇒6.0928-30 Violation noted receipt of
- dioset generator fuel w/o evidence of lesting for type & quality of fuel fure shird for all foregoing attributes of ASTM spaces
 * Region 1, Ofc of the Director 88/11/17, 1p. 47676.024.47676.024
- -8811300312 Insp Ropts 50:387/88-18 & 50:388/88 21 on 880928-30 Violation & unresolved item noted Major areas inspected. Unit 2 unplanned ESF actuations in which RWCU syst isolated when large Unit 1 pump stanced WOODARD,CH. LARA,J.F., ANDERSON,C.J. Region 1, Oic of the Director 88/11/16.9pp. 47676-025-47676-033.
- 8811180211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list enct.
 CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Safety (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 90pp 47708.255-47708 257.
- 8811180487 NRC Info Notice 88-001, *Improper Administration & Control of Psychological Tests." Svc list encl. ROSSI,C E D.vislan of Operational Events Assessment (Post 870411), 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708,042 47708.142
- 8812020097 Forwards Into re-qualification of Target Rock sciencid valves.per NRC re-quest re-linsp Repts 50-387/86-25 & 50-388/86-28 Info includes comment resolutions & qualification checkinst notes dating back to 1982. KEISER-IN-W. Ponnsylvania Power & Light Co. 88/11/28. RUSSELL,W.T. Region 1, Otc of the Director. 12pp. 47718-338-47718-349.
- 6611290030 NRC Info Notes 86:033, "Totalherapy Events." Svc I st and. CUNNINGHAM,R E. Division of Industrial & Modical Nuclear Safety (Post 870729) 86/12/02. Consolidated Edison Co. of New York, Inc. 112pp 47611:103-47811:215.
- 8811290536 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Svc list onci ROSSI,C.E. Division of Operational Events Assossment (Post 870411), 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp 47708:143-47708:254.
- 8812090202 Forwards MC Thedeni Insp Repts TI 2515/93 & TI 2515/95 on 881025.

- 8812120074 Advises that util 850711 & 1001 responses to fiRC Bulletin 89-004, "Polental Safety Related Pump Loss: acceptable Results of long-term evaluations & schodules of any resultant charges requested within 30 days of completion. THADANI,M.C. Project Directorate 1:2 88/12/06. KEISER,H.W. Pennsylvan a Power & Light Co. 4pp. 47780.146.47760.149.
- 8812020287 NRC into Notice 88 095, "Inadequate Procurement Requirements Imposed by Leansees on Vendors." Suchisheral ROSSICE Disconnot Operational Events Assassment (Post 870411) 88/12/08 Consolidated Edison Colif (New York, Inc. 112pp. 47807.191-47807.302

R. Periodic operating reports & related correspondence

- 8811230306 Monthly operating regis for Oct 1988 for Susquehanna Steam Electric Station Units 1 & 2 W/851111 ftr.
 HRT.J.A. KEISER,H.W. Ponnsylvania Power & Light Co. 88/10/31
 MCDONALD,W.G. Ottoe of Agrin stration & Resources Management, Director (Post 870413) 11pp 47652 109 47652 119
- 8811300321 * Oscharge Mor fonng Rept for Oct 1988 * W/681121 ltr. FIELCS LS Pennsylvania Power & Light Co. 88/10/01 BREZINSKI R. Pennsylvania, Commonwealth of 10pp. 47697 216-47697 228
- 8812200196 Monthly operating replie for Nov 1998 for Susquehanna Steam Electric Station Units 1 & 2 W/881215 fit:
 YOUNG,KIA, KEISER H.W. Pennsylvania Power & Light Co. 88/11/30, 9pp KEISER,HW. Parnsylvania Power & Light Co. 88/11/30. 9pp 47860 189-47860 207

S. Reportable occurrences, LERs & related correspondence

- 8812210008 LER 88-004 01.on 880203 discovered reactor bidg ventration boundary door blocked open to permit passage of temporary power cabre Caused by personnel error Cabre removed, door closed & train a provided W/881214 in WEHRY.R. BYRAM.R.G. Pennsylvana. Power & Light Co. 88/12/14. 5pp. 47888 115-47888 119
- 8812130053 LER 88-021-00 on 680922 discovered normal versus actual full closed in-deation limit switch positions used in insthodology for determining min MSIV stricks time acceptance criteria Caused by use of norminal settings W/681208 tz. RUSANOWKYPP, BYRAMRIG Pennsylvania Power & Light Co. 88/12/20 Spp. 47792 271-47792 275

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8811300068 Revised emerger by plan in promenting procedures including Rev 6 to EP-IP-001, "Class-lication of Emergency Conditions," April 3 to EP-IP-011, "Security Contingency & Emergency Access" & Rev 0 to EP-IP-055.W/681109 lir KEISER,H W. Pennsylvania Power & Light Co. 88/11/09, 39pp. 47702.078-47702.115
- 8811300333 Forwards Safety Insp. Repts 50:387/88-17 & 50:368/88-20 on 880918-1029 Results documented in engine rept. WiGGINS, J.T. Region 1, Ofc of tire, Director, 88/11/14, KEISER, H.W. Pennsylvania Power & Light Co. 2pp. 47673 133-47673 150
- -8611300338 Insp Repts 50:387/£8-17 & 50:388/88-20 on 880918-1029.No violations o'ed Major areas inspected vents surveil'ance & maint activities inspected plant operations, physical security plant BLOUGH,A R. Region 1, Ofc of the Director, 88/11/14, 16pp. 47673.135-47673.150
- 8812120172 Forwards listed additinfo re-plant fire protection review rept W/16 oversize drawings KEISER,H.W. Pennsylvania Power & Light Co. 88/11/22, BUTLER,W.R. Project Direc-
- --8812120191 Rev 11 to EO-100-009, "Plant Shutdown From Outside Control Room."
 Pennsylvania Power & Light Co. 68/07/07, 43pp. 47827,223-47828-053.
- 8612190122 Revised emergency plan implementing procedures including Rev 11 to EP. IP-030, "Activation & Functional Operation of Emergency Operations Facility & Transfer," & Rev 10 to EP-IP-007, "Personnel Assembly..." W/881130 ftr. TABOR, W.F., KEISER, H.W., Pennsylvania Power & Light Co. 89/11/30, 88pp. 47861232-47852040.
- 8812210364 Forwards Rev 11 to Susquehanna Units 1 & 2 emergancy plan KEISER.H.W. Pennsylvania Power & Light Co. 88/12/15. BUTLER.W.R. Project Direc-torate I-2. 4pp. 47899 092-47900.032
- -8812210366 Rev 11 to "Susquehanna Steam Electric Station Emergency Plan" W/ thee oversed drawings *Pennsylvania Power & Light Co. 88/10/31, 300pp. 47899 096 47900 032.

H. General correspondence

8812050159 Informs of new mailing address of NRC resident inspectors at plant YOUNG,F. Region 1, Otc of the Director, 88712701, WCKNIGHT,J. Document Control Branch (Document Control Dask) 1p. 47733 297-47733 297.

J. Insurance & Indemnity Information

8811290375 Forwards Endorsements 1-3 to NELIA Certificate NW-157 & MAELU Certs 8 11/29/03/79 FORWARDS Emporations 173 to RELAT Commission (WHITE & MARLIU Cent. cate MW-71/aspectively, Endorsoments 7 & 5 to NFLIA Continentes N.04 & 11:55 & Endorsements 7 & 6 to MARLIU Centificatios MW-84 & MW-98, respectively Related to KEISER,H.W. Pennsylvania Power & Light Co. 88/11/21. SALTZMAN,J 1.8C - Ho Dotaled Alt.Lation Given. 48pp. 47867.084.47667.141.

P. Operating license stage documents & correspondence

- 8811280215 Forwards Amendo 85 & 52 to Licenses NPF-14 & NPF-22, respective'; & safety, evaluation Amends remove organization charts from Tech Specs & niake some changes to comenciature of Section 6 & 2 BUTLER,WIR Project Directorate 1/2 8/3/11/16. KEISER,H W Perinsylvaria Power & March Control of the Cont Light Co 5pp 47657.029 47657.054.
- -8811280217 Amends 85 & 52 to Licensos NPF-14 & NPF-22,respectively, removing organization chairs from Tech Spocs & making some changes to nomenclature of Section 68 2 BUTLER,W.R. Project Directorate I-2, 88/11/16, 18pp, 47657-034-47657-051

- -9811280218 Satety evaluation supporting Amands 85 & 52 to Licenses NFF-14 & NPF-22-respectively.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/16 3pp 47657-052-47657-054
- 6811220341 Comment endorsing NUMARC comments on proposed rule 10CFR26 relative ness for duty rule KEISER,H W. Pennsylvania Powor & Light Co. 88/11/17 CHILK,S J. Office of the Secretary of the Commission 3pp. 47721 050 47721 052
- 8811280048 Generic Ltr 88:20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list GRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23. Conse dated Edison Co. of New York, Inc. 81pp. 47728/303-47729.024.
- 8812090282 Informs of Intent to close Rivertands hiking trailliper MC Thadam request Closing of hiking trail does not have to be evaluated as unreviewed environ question as identified in unwiron protection clan KEISER,H W. Pennsytvania Power & Light Co. 88/12/05. BUTLER,W R. Project Directorate L.2. 1p. 47785-147-47785.148
- 8812190232 Forwards application for Propused Amends 118 & 68 to Liconess NPF-14 & NPF-22 respectively, modifying Tech Spec 4 8 2 1. d 2 b to discrease load profiles for Batteries 10610, 10620, 10630, 10640, 20610, 20620, 20630, 8 20640 Fee paid Datables 10510, 10500, 10500, 10500, 20510, 20020, 20030 & 20540 Fee pa.d. KEISER, IV. M. Pennsylvaria Power & Light Co. 88/12/12, FUTLER, W.R. Project Directorate I-2, 4pp. 47848 332-47040, 342.
- -8812190235 Application for Proposed Amends 118 & 68 to Liconago NPF-14 & NPF-22,0spectively,ravising Tech Spec 4 8 2 1 d 2 h to decrease load profiles for 125 voil dc battery banks KEISER, H.W. Pennsylvania Power & Light Co. 88/12/12, 2pp. 47848-338-47849.337
- -6812190237 Proposed Tech Specs, decreasing load profiles for 125 volt do battery Pennsylvania Power & Light Co. 88/12/12 5pp. 47848:338-47848.342
- 8812190377 Responds to Genoric Liv 88-11 re calculation of pressure temp curves using equations presented in Reg Guide 1.99, Rev 2. Technical evaluation performed & new pressure temp curves developed as result of analysis Technical evaluation and, KEISEA, H.W. Pernsylvania Power & Light Co. 88/12/12, BUTLER, W.R. Project Oirectorate 1.2, 40pp. 47849,093,47849,132.

Q. Inspection reports, IE Bulletins & correspondence

- 8811300333 Forwards Safety Insp. Repts 50:387/88-17 & 50:388/88-20 on 880918-1029.Rosults documented in enci rept. WIGGINS,J.T. Region 1, Ofc of the Director. 88/11/14, KEISER,H.W. Pennsylvan a Power & Light Co. 2pp. 47673;133-47673;150.
- -8811300338 Insp Repts 50-387/88-17 & 50-388/88-20 on 880918-1029 No violations noted Major areas inspected plant operations, physical security.plant events, surveitlence & maint activities. BLOUGH, A.R. Region 1, Otc of the Director 88/11/14, 18pp. 47673:135-47673:150 security plant
- 8811300307 Forwards Insp Repts 50-387/88-18 & 50-388/88-21 on 880928-30 & notice of violation DURRUP, Region 1, Ofc of the Director 88/11/17, KEISER,H.W. Pennsylvania Power & Light Co. 2pp. 47676:022-47676:033.
- -\$811300309 Notice of violation from Insp on 880928-30 Violation noted receipt of deel generator fuel w/o evidence of testing for type & quelity of fuel furnished for all foregoing altibutes of ASTM specs. Region 1, Ofc of the Director, 88/11/17, 1p. 47676.024-47676.024.
- -8811300312 Insp Repts 50 387/88-18 & 50 388/88-21 on 880928-30. Violation & un-Tosolved filem noted Major stress respected: Unit 2 unplanned ESF actuations in which RWCU sys isolated when large Unit 1 pump started.

 WODDARD, CH, LARAJE, ANDERSON, CJ. Region 1, Otc of the Director, 88/11/18 Ppp, 47878 025-47878.033.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges: Svc list enc!
 CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729).
 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257
- 8811160467 NAC Info Notice 88-091, "Improper Administration & Control of Psycholog-Call Catal. Sec list end. Caperational Events Assassment (Post 870411). 88/11/22 Consaddated Edison Co. of New York, Inc. 101pp. 47708.042-47708:142.

85.11290038 NRC Info Notice 89-090, "Totalnurapy Events." Svc list enct CUNNINGHAM,R E. Division of Industrial & Modical Nuclear Safnty (Post 870729). 68/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811 103-47811 215

- 8811290538 NRC Info Notice 88 094, "Potentially Undersized Valve Actuators." Sve int ROSSIC E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, It.d. 121pp 67708 143-47708 254
- 8812090202 Forwards MC Thadant Insp Flepts TI 2515/93 & TI 2515/95 on 881025 BUTLER,WR Project Directorate I-2 887/12/06 V/IGGIRS J.F. Beginn 1, Oh of the Director 5pp 47785 003-47785 007.
- 8812128074 Advises that util 880711 & 1031 responses to NRC Bulletin 88-004, "Potential Safety-Related Pump Loss" acceptable. Results of long-term evaluations & schedules of any resultant changes requested within 30 days of completion. THADANI,MC Project Directorator 1-2, 88/12/06. KEISER,FLW Perinsylvania Power & Light Co. 4pp. 47780-146-47783-149.
- 8812020287 NRC Info Notice 80-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors' Svollist encl.

 ROSSICE Division of Operational Events Assessment (Post 870411), 88/12/08.

 Consolidated Edison Co. of New York Inc. 112pp. 47807-191-47807-392

R. Periodic operating reports & related correspondence

8811230306 Monthly operating repts for Oct 1988 for Susqueheina Steam Electric Station Units 1.8.2 W/881111 lik HIRT JA. KEISERHW. Pennsylvana Power & Light Co. 86/10/31. MCDONALD.W.G. Office of Administration & Resources Management, Director (Post 870413) 11pp 47652.109-47652-119

BB11300021 "Discharge Monitoring Rept for Cat 1995" W7881121 ftr FIELDS,J.S. Pennsylvania Power & Light Co. 68/10/31, BHEZINSKLA Pennsylvania, Commonwealth of, 13pp. 47697 216 47697 228

8812200196 Monthly operating ropts for Nov 1988 for Susquehamia Steam Electric Station Urds 1-8 2-W/851215 fit YCUNG.KA, KEISER.H.W. Ponnsylvania Power & Light Co. 88/11/30. 9pp 47860-199-47860-207.

S. Reportable occurrences, LERs & related correspondence

8812210010 LER 88-016-00.on 891114.applicable Toch Spec action statements not taken upon determination that two containment isolation valves inoportule Caused by mettent on to datable by personnel Personnel training planned W/881214 ltr. RYDER,T.S. BYRAM,R.G. Pomsylvarda Power 8 Light Co. 89/12/14 4pp 47876.007-47876.010

DOCKET 50-389 ST. LUCIE PLANT, UNIT 2

F. Security, modical, emergency & fire protection plans

- 8812090319 Forwards Insp Ropts 50:335/88-27 & 50:389/88-27 on 881002- 1105 No violations of deviations (Identified Wilson, B.A. Region 2, Ofc of the Director 88/12/01 CONWAY,W.F. Florida Power & Light Co. 2pp. 47781 069-47761.080
- -8812090322 Insp Repts 50:335/88.27 & 50:389/88.27 on 881002:1105 No violations of deviations identified Major areas inspected. Tech Spec compliance operator performance QA practices, site security procedures & radiation control activities. CRLENJAKRV. Region 2, Oto of the Director. 88/11/30 10pp 47761:071-47781 OBO
- 8812180045 Informs that safeguards regulatory affactiveness review scheduled for wk of 881212-16.Review conducted to ensure that safeguards.required by NRC regulations,provide intended level of protection w/o compromising safety of oper-

CLINE,W.E. Region 2, Old of the Director 88/12/02 CONWAY,W.F. Florida Power & Light Co. 3pp. 47830:345-47830:347.

- 8812080149 Forwards response to violations noted in Insp Repts 50:335/88-20 & 50:389/88-20.Response withheld (ref 10CFR73.21 & 2.790(a)(3))

 CONWAY.W.F. Florida Power & Light Ca. 80/12/08. Document Central Branch (Document Control Desk). 1p. 47757:101-47757:101.
- 9812190129 Forwards Rev 18 to physical security plan Rev withheld (rel 10CFR73 21 & 2 790). CONWAY,W.F. Florida Power & Light Co. 88/12/13. Document Control Branch (Document Control Dask). 2pp. 47853.355-47853.356

I. Financial Information

8612220136 Forwards (mancial disclosure into,including 1987 annual 10-K,Sept 1966 10-O & util statement of Internal cash flow oxcluding rotained earnings for 12 months and ng Sept 1989, per 10CFR140 21 & Reg Guida 9-4 CONWAY, W.F. Florida Power & Light Co. 88/12/14 Document Control Branch (Document Control Dask), 91pp. 47886 195-47886 285

P. Operating license stage documents & correspondence

8811280199 Resubmits inadvertently omitted Pages 18 & 19 of 881020 safety analysis of application for amend to Lecanso NPF-15. CONWAY,W.F. Florida Power & Light Co. #8/11/21. Document Centrol Beach. 20pp. 47652 285-47652:304.

- 8611290335 Responds to Generic Lir 80-01, "NRC Position on Radiation Embrittement of Reactor Vessel Matts & Impact on Plant Operations." Util determined that notifice unit will exceed critical point Reg Guide 1 99, Rev 2, through end of Mo CONWAY, W.F. Florida Power & Ught Co. 48/11/23. Document Centrol Branch (Decembert Control Dosk). 3pp. 47665 273-47665 275.

 - 8812120137 Requests that util addresses Generic Ltr 88-17 re loss of DHR during con-power operation Industry has not aggressively responded to resolve concern following identification in Generic Ltr 87-12 MUHLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/ 02. HUDIBURG, J.J. Florida Power & Light Co. 3pp. 47780-139-47780-141.
 - 8812150042 Informs that new Info re Monument 80 8 Installed to replace missing monuroom does not change conclusions of dane survey, per encil
 CONWAY, W.F. Florda Power & Light Co. 88/12/08 Document Control Branch (Docu-nent Control Desk). 4pp. 47823.015-47823.018
 - 8812150195 Informs that effective 881204,JA Norms assigned as new project manager for facilities
 BERIKOW,HIN Project Directorate II-2 88/12/13, CONWAY,W.F. Florida Power & Light Co 2pp. 17826 293-17826 294.
 - 8812220257 Forwards Amend 36 in License NPF-16 & safety evaluation. Amend changes value of Pa in Tech Spec 3/4 6.1, "Containment Sys."

 TOURIGNY,E.G. Project Directorate II-2 88/12/16. CONWAY,W.F. Florida Power & Light Co. 3pp 47900 115-47900 129.
 - -8812220258 Amend 36 to License NPF-16,changing value of Pa in Tech Specs 3/ 4.6 1, "Containment Sys" BERKOW,H.N. Project Directorate II-2 88/12/16 9pp 47900.118-47900 126.
 - --9812220260 Satoty evaluation supporting Amend 36 to License NPF-16.

 * Office of Nuclear fleector flegulation, Director (Post 870411) BB/12/16 3pp 47900-127-47900 129.
 - 8812200199 Forwards Amend 38 to License NPF-16 & safety evaluation, in response to 881020 application Amend changes control element assembly max drop time from 2.7 TOUHIGNY,E.G. Project Directorate II-2, 887/12/19, CONWAY,W.F. Florida Power & Light Co. 2pp. 47903-351-47903-362.
 - --8812200204 Anward 38 to Licenso NPF-16, changing control obscent assembly max drop line time from 2.7 to 3.1 s BERKOW,H.N. Project Directorate II-2 88/12/19 5pp 47803:354-47903:358
 - -8812200210 Safety evaluation supporting Amend 36 to License NPF-16
 * Officer of Nuclear Reactor Regulation, Director (Post 870411) 88/12/19 4pp. 47903 359-47903 362

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Into Notice 88 090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list encl. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88711722. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 6811160467 NRC Info Notice 89-091, "Improper Administration & Control of Psychological Tests." Svc list encl. ROSS), C.E. Division of Operalidaal Events Assessment (Post 370411). 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp 47708 042-47708 142
- 8812050320 Ack receipt of 881017 ftr informing NRC of steps taken to correct violations noted in Insp Repts 50:335788-21 & 50:389788-21 WILSON,B.A. Region 2, Otc of the Director, 88711722, CONWAY,W.F. Florida Power & Light Co. 1p. 47740-100-47740-100
- 8812090319 Forwards Insp Repts 50:335/88-27 & 60:389/88-27 on 881002- 1105 No Villations or deviations then the Director. 88/12/01. CONWAY,W.F. Florida Power & Light Co. 2pp. 47761:069-47761.080.
- -8812090322 Insp Repts 50:335/88:27 & 50:389/88:27 on 881002:1105 No violations or deviations identified Major areas Inspected Tech Spec compliance, operator performance, OA practices, site socurity procedures & radiation control activities. CRLENJAK,R.V. PAULK,G.L., BIDD,H.E. Reg.on 2, Ofc of the Director. 88/11/30 10pp. 47761:071-47761:080.
- 8811290030 NRC Into Notice 88-093, "Te'etherapy Events" Svollist encl CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc fist ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708 254.
- 8812090069 Ack receipt of 880922 response & 881220 suppl to deviations noted in Insp. Repts 50.335/88-08 & 50.389/88-08 Response & suppl inadequate Addl response requested following planned meeting to discuss emergency operating procedures program.

 ERNST,M.L. Region 2. Ofc of the Director. 88/12/02 CONWAY,W.F. Florida Power & Light Co. 1p. 47782 307-47762 307
- 8812220343 Forwards Exam Ropt 50:335/OL-88-01 administored during whis of 880725 & 0812 Exam rept findings in conjunction w/Insp Repts 50:335/88-08 & 50:389/88-08 findings indicate weakness in emergency operating procedures GIBSON,A F. Rogion 2, Otto of the Oractor, 88/12/05. CONWAY,W S. Florida Power & Light Co. 2pp. 47891:140-47892-097

- -8812220352 Exam Rept 50-335/OL-88-01 on 880725 & 0912.Exam results:five senior reactor operators & 12 reactor operators passed exams & three reactor operators
- CASTO,C. Region 2, Ofc of the Director, 88/11/30, 228pp, 47891:142-47892:097.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed 81202087 NRC Into Notice 88-095, "inadequate Procurement Requirements imposed by Licensees on Vendors." Svc list enct. ROSSI.CE. Drivision of Operational Events Assessment (Post 870411), 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812080148 Forwards response to violations noted in Insp Repts 50-335/88-20 & 50-385/88-20.Response withheld (ref 10CFR73.21 & 2.790(a)(3)).

 CONWAY,W.F. Florida Power & Light Co. 68/12/08. Document Control Branch (Document Control Desk). 1p. 47757:101-47757:101.

R. Periodic operating reports & related correspondence

- 881220008 Forwards monthly operating status repts for Nov 1988 for Turkey Point Units 3 & 4 & St Lucie Units 1 & 2 & corrected unit shutdown & power reductions rept for Turkey Point Unit 3 for Oct 1988.

 CONWAY,W.F. Florida Power & Light Co. 88/12/13. Document Control Branch (Document Control Desk). 1p. 47868:333-47868:349.
- -8812200013 Monthly operating repts for Nov 1988 for Turkey Point Units 3 & 4 & St EGGE UTILIS 1 & 2. BONETT, D.M. Florida Power & Light Co. 88/11/30, 15pp. 47868;334-47868;349.

S. Reportable occurrences, LERs & related correspondence

8812200362 NPDES noncompliance notification on 881021,10,000 gallons of pH 10.4 water released into intake canaf. Caused by pipe break in valve pit. Plant work order water released into strang Certain Control Branch (Document Control Branch (Document Control Desk). 3pp. 47862:216-47862:218.

V. Operator Examinations

- 8812220343 Forwards Exam Rept 50-335/OL-88-01 administered during wks of 860725 & 0912.Exam rept findings in conjunction w/Insp Repts 50-335/88-08 & 50-389/88-08 findings indicate weakness in emergency operating procedures. GIBSON.A.F. Region 2, Ofic of the Director. 88/12/05. CONWAY,W.S. Florida Power & Light Co. 2pp. 47891:140-47892:097.
- -8812220352 Exam Rept 50-335/OL-88-01 on 880725 & 0912.Exam results:five senior reactor operators & 12 reactor operators passed exams & three reactor operators Paners Skams. CASTO,C., MUNRO,J.F. Region 2, Otc of the Director, 88/11/30, 228pp. 47891:142-

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

- 8811230101 Forwards Rev 0 to corrective action program plan, "HVAC Duct & Duct Supports" & summary statement of commitments. WHITE,S.A. Tennessee Valley Authority, 88/11/18, Document Control Branch (Document Control Desk), 2pp. 47657:162-47657:179.
- --8811230104 Rev 0 to corrective action program plan, "HVAC Duct & Duct Supports." W/summary statement of commitments. RODDY,L., MCCALL,J.K. Tennessee Valley Authority. 88/11/18, 16pp. 47657:164-47657:179.
- 811280048 Generic Ltr 88-20 to all licenses holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities.Svc list
- GRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23, Consolidated Edison Co. of New York, Inc. 81pp. 47728;303-47729:024.
- 8812060086 Advises that Reg Guide 1.99.Rev 2 methodology has no immediate impact on plant operations,per encl evaluation of plants for Generic Ltr 88.11, "NRC Position on Radiation Embrittlement of Reactor Vessel Matis & Impact on Plant..." GRIDLEY,R. Tennessee Valley Authority, 88/11/30. Document Control Brench (Docu-ment Control Desk). 20pp. 47752:203-47752:222.
- 8812090222 Forwards environ assessment & finding of no significant impact re 880829 request for extension of const completion dates of CPs CPPR-91 & CPPR-92 to 910701 & 921231, respectively.

 BLACK,S. Ofc of Special Projects. 88/12/05. KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47785:050-47785:055.
- --8812090235 Environ assessment & finding of no significant impact re extension of const completion dates for CPs CPPR-91 & CPPR-92 to 910701 & 921231,respective-
- BLACK,S. O/c of Special Projects. 88/12/05. 4pp. 47785:052-47785:055.
- 3812120016 Requests util assurance that Generic Ltr 88-17 re loss of DHR during non-power operation being addressed accordingly unlike response to Generic Ltr 87-12 re loss of RHR while RCS partially filled. RICHARDSON.S.D. Ofc of Special Projects. 88/12/05. KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47789:153-47789:154.
- 86 12150222 Discusses Generic Ltr 83-28, "Required Actions Based on Generic Implica-tions of Salem ATWS Events" for listed plants.Reactor trip breaker maint & trending Issues should be addressed as plant-specific Issues. BRADFUTEJ.O. Project Directorate V. 88/12/06. AULUCK,R. Ofc of Special Projects. 3pp. 47825;073-47825;075.
- 8812140165 Responds to Generic Ltr 68-11 re radiation embrittlement of reactor vessel mails & Impact on plant operations using methodology in Rev 2 to Reg Guide 1.99. GRIDLEY,R. Tennessee Valley Authority. 88/12/09. Document Control Branch (Document Control Desk). 6pp. 47800:206-47800:212.

- 8812210217 Forwards Rev 1 to corrective action program plan for replacement items program (piece parts) at Unit 1 for NRC review & concurrence.Summary of commitments also encl.

 RingsLEY,O,D. Tennessee Valley Authority, 88/12/14. Document Control Branch (Document Control Desk), 2pp. 47875;185-47875;202.
- --8812210221 Rev 1 to "Watis Bar Nuclear Plant Replacement Hems Program (Piece Parts) Corrective Action Program Plan."

 MCKEEHAN,R.S., METCALF,P.D., LYONS,J.R. Tennessee Valley Authority. 68/12/14.
- 8812210297 Forwards Rev 1 to corrective action program plan for vendor info.Summary of committeents provided in Encl 2.

 KINGSLEY,O.D. Tennessee Valley Authority. 88/12/14. Document Control Branch (Document Control Desk). 3pp. 47881:122-47881:141.
- --8812210302 Rev 1 to "Watts Bar Nuclear Plant Corrective Action Program Plan, Vendor Info." Program LORE, S.D., BOYD, L.W., CHANDLEY, C.A. Tennessee Valley Authority. 88/12/14.
- 8812230012 Forwards Rev 0 to "Watts Bar Nucloar Plant Cable Issues Corrective Action Program Plan." Raview & concurrence requested. KINGSLEY,O.D. Tennessee Valley Authority, 08/12/10. Document Control Branch (Document Control Desk), 2pp. 47914;287-47914;349.
- -8812230014 Rev 0 to, "Watts Bar Nuclear Plant Cable Issues Corrective Action Pro-Tennessee Valley Authority. 88/12/16. 61pp. 47914:289-47914:349.
- 8812230198 Forwards "O-List Development Flowchart," inadvertently omitted from 881027 QC list for corrective action program, GRIDLEY,R. Tennessee Valley Authority, 88/12/16, Document Control Branch (Document Control Desk), 3pp. 47911:001-47911:003.

F. Security, medical, emergency & fire protection plans

- 8811280054 Forwards Insp Rept 50:390/88:07 on 881004.No violations or deviations MCCOY,F.R. Oic of Special Projects. 68/11/04. WHITE,S.A. Tennessee Valley Authority. 2pp. 47653:268-47653:272.
- -8811280057 Insp. Rept. 50-390/88-07 on 881004.No violations or deviations noted.Major areas inspected-protection of fuel storago facility.

 THOMPSON,D.H., MCGUIRE,D.R. Region 2, Ofc of the Director. 88/10/25. 3pp. 47653:270-47653:272.
- 8812190003 Forwards Insp Repts 50-390/88-05 & 50-391/88-05 on 880816-0920.No violations or deviations noted. Three unresolved items identified. MCCOY,F.R. Region 2, Ofc of the Director. 88/12/02. KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47852:154-47852:169.
- -8812190005 Insp Repts 50-390/88-05 & 50-391/88-05 on 880816-0920 No violations Tabuba insp. repris ou-serzite prevention & fire protection, testing of pipe supports & BARRIK.P., MCCOY,F.R. Old of Special Projects. WALTON,G.A. Region 2, Ofc of the Director, 88/12/02, 14pp. 47852:156-47852:169.
- 8812210195 Revised central emergency control ctr emergency plan implementing procedures including Rev 1 to CECC-EPIP-1, Rev 2 to CECC-EPIP-2, Rev 2 to CECC-EPIP-2, Rev 2 to CECC-EPIP-1, Rev 2 to CECC-EPIP-3, Rev 2 to CECC-EPIP-1, Rev 2 to CEC MCANALLY,J.L. Tennessee Valley Authority, 86/12/16, 86pp. 47906;304-47907;053,

H. General correspondence

8812010405 Comments on proposed rule 10CFR26 re Fitness for Duty Program for nuclear reactor operators.Opposes random drug screening of nuclear plant employees. WHITEHEAD,G.G. International Brotherhood of Electrical Workers. 88/11/21. Docketing & Services Branch. 2pp. 47679:250-47679:251.

Q. inspection reports, IE Bulletins & correspondence

- 8812050303 FOIA request for Oic of Enforcement 881003 proposal to Commissioners on QA. POWELSON, R. Scripps-Howard Newspapers. 88/10/25. GRIMSLEY, D. Division of Freedom of Information & Publications Services (Post 880515). 1p. 47729:079-47729:079
- 8811280054 Forwards Insp Rept 50-390/68-07 on 881004.No violations or deviations MCCOY,F.R. O/c of Special Projects, 88/11/04, WHITE,S.A. Tennessee Valley Authority, 2pp. 47653;268-47653;272.
- --8811280057 Insp Rept 50-39D/88-07 on 881004.No violations or deviations noted. Major areas inspected:protection of fuel storage facility. THOMPSON,D.H., MCGUIRE,D.R. Region 2, Ofc of the Director, 88/10/25. 3pp. 47653:270-47653:272.
- 8811300183 Responds to NRC 861021 notice of violation & Enforcement Action EA-88-253.Corrective actions:Procedure 0602.01 revised to establish responsibilities & procedure for dealing w/NRC & review & concurrence processs established.

 RUNYON,M. Tennessee Valley Authority, 88/11/21, LIEBERMAN,J. Ofc of Enforcement (Post 870413), 8pp. 47697;198-47697:205.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear 81119021) NRU INIO NORCE 68-090. CHRURINOIZEG TREINIO. Gauges: Syc list encl. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257.

- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologi
 - cal fests" Svc list encl ROSSIGE Cavisco of Operational Events Assessment (Post 870411) 88/11/22 Corsol dated Edison Col of New York, Inc. 101pp. 47708 042-47708 142
- 8812010186 Forwards V Stella 081117 ftr to all ottl executives re presence of NRC in-spector at plants revite enforcement policy & proposed enforcement actions for openator instead veness at Peach Bottom.

 BLACK, S.C. Olic of Special Projects 88/11/23 KINGSLEY, O.D. Tennessou Varey.

 Authority 3pp. 47709 258-47709 309
- 8812090002 Ack receipt of 880919 ftr Informing NRC of steps taken to correct violations incled in Insp Repts 50-390786-24 & 50-301786-24 MCCOY,FIR Oz. of Special Projects. 88711728. KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47783-328-47783-327.
- 8812990005 Ack receipt of 880825 fir Informing NRC of steps taken to correct violations noted in Insp Repts 50:390/86-24 & 50:391/86-24 No objections noted to packaging contributions in 10CFR50 55(a) rept MCCCY/FR Ofc of Special Projects 88/11/28. KINGSLEY,O D. Tennussee Valley Authority 2pp. 47783:324-47783-325

- 8812090014 Ack receipt of 880609 & 0823 litrs informing NRC of steps taken to correct violations rated in Insp Repts 50-390/88-01 & 50-391/88-01. MCCOY,FR. Olic of Special Projects 88/11/28 KINGSLEY,O D. Tennessoc Valley Authority, 2pp. 47762-304-47762-305.
- 8812090031 Ack recoipt of 880829 ftr Informing NRC of steps taken to correct violations noted in Insp Repts 50:390/87-11 8:50-391/87-11.

 MCCOY,F.R. Old of Special Projects 88/11/28 KINGSLEY,O.D. Tennossee Valloy Authority. 1p. 47781:125-47781-125.
- 8812090040 Ack receipt of 880915 ftr informing NRC of steps taken to correct violations noted in Insp Ropus 50:390/87-05 & 50:391/87-05.

 MCCOY,FR. Olic of Special Projects 88/11/28. KINGSLEY,O.D. Tennessoe Valley Authority. 2pp. 47762:297-47762-298
- 8812020255 Forwards rol purchase order numburs & dates for suspected purchases by U.1 of Class 1E components or svcs from Planned Meint Sys.Inc for appropriate action per NRC Info Notice 88-019, "Questionable Cartification of Class 1E...."
 BLACK,S.C. Ofc of Special Projects 88/11/29, KINGSLEY,O.D Tennessee Valley Authority, 5pp. 47722 069-47722 073.
- 8611290030 NRC Info Notice 88-093, "Teletherapy Events." Svc list encl. CUNNINGHAM,R.E. D.vision of Industrial & Medical Nuclear Safety (Post 870729). 86/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Understand Valve Actuators" Svc fist enct ROSSI,CE Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp 47708.143-47708.254.
- 8812050306 Final response to FOIA ruquest for records App A document enct & avai-able in PDR App B documents completely withhold (rel FDIA Exemption 5) GRIMSLEY,D.H. Division of Froadom of Information & Publications Services (Post 880515) 88/12/02. POWELSON,R. Scripps-Howard Nowspapers 4pp. 47729.080-47729.084
- -6812050311 Staff requirements memo on notice of violation & proposed imposition of ctyl penallies re communication
 CH/LK,SJ. Office of the Secretary of the Commission. 88/19/20 STELLO,V. Ofc of
 the Executive Director for Operations. 1p. 47729.084-47729.084.
- 8612190003 Forwards Insp. Ropts 50:390/68-05 & 50:391/68-05 on 680816 0920.No violations or deviations noted Three unrasolved items kidentified. MCCOY.F.R. Region 2. Ott. of the Director. 88/12/02. KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47852:154-47852:189.
- --8812190006 Insp Repts 50-380/88-05 & 50-381/88-05 on 880818-0920 No violations incled Major areas inspected lire provention & five protection testing of pipe supports & resitant sys, roviow of QA manual safety-rollated piping & welding BARRKP, MCCOY,F.f. Old of Special Projects WALTON,G.A. Region 2, Old of the Director 88/12/02, 14pp. 47852:158-47852:169.
- 8812130093 Responds to 881110 lit requesting into re Commission enforcement action concorning 860320 lit from tult. CARR,K M. Commissioners. 88/12/06. DINGELL,J. House of Rep., Energy & Commerce. 18pp. 47792:248-47792:270.
- -8812130098 Requests that NRC provide listed into re Commission dealings w/Iconsee
- 860320 lir concerning compliance w/Commission OA requirements.

 DINGELL,J.D. House of Rep., Energy & Commerce. 88/11/10. ZECH,L.W. Commissioners 5pp. 47792.266-47792:270.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" Svc list encl. ROSSI. CE. Division of Operational Events Assessment (Post 870411). 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.

S. Reportable occurrences, LERs & related correspondence

- 8812019042 Deliciency reptire welds for hanger lugs on ASME Code piping initially re-ported on 870127. Final reptiwill be submitted by 890227. Corrective action program
 - creparation in progress.
 GRIDLEY,R. Tennessee Valley Authority, 88/11/28. Document Control Branch (Document Control Desk). 2pp. 47703:078-47703:077.
- 8812140171 Part 21 & final deficiency rept re-potential failure of operator-to-valve en-gegement of Xomox supplied valves. Initially reported on 871204.On 880711,Xomox provided replacement parts for 24 valves identified. GRIDLEY,R. Tennessee Valley Authority, 88/12/09. Document Control Branch (Docu-ment Control Desk), 4pp. 47796:145-47796:148.

U. Congressional/Executive Correspondence

8811300078 Forwards NRC quarterly status rept covering Third Quarter CY88 in re-sponse to direction given in House Rept 97:860 ZECH,L.W. Commissioners 88/11/10 BEVILL,1 House of Rep, Appropriations 12pp 47733-001-47733

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

- 8811230101 Forwards Roy 0 to corrective action program plan, "HVAC Direct & Duct Supports: & summary statement of communents
 WHITE,S.A. Tennesseo Valley Authority, 88/11/18. Document Control Branch (Document Control Desk), 2pp. 47657-162-47657-179
- --8811230104 Rev 0 to corrective action program plan, "HVAC Duct & Duct Supports" Wisummary statement of commitments ROEDY, L. MCCALL, J.K. Tennesson Valley Authority 88/11/18 16pp 47657 184-47657 179.
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident viilnorabilities Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23. Consoli dated Edison Co. of New York, Inc. 81pp. 47729 303-47729 924.
- 8812080086 Advises that Reg Guido 1.99,Rev 2 methodology has no immediate impact on plant operations,per encil ovaluation of plants for Generic Ltr 88-11, "NRC Position on Radiation Embritishment of Reactor Vessol Matts & Impact on Plant."

 GRIDLEY,R Tennessee Valley Authority, 88/11/30, Document Control Branch (Document Control Desk) 20pp. 47752 203-47752 222
- 8812090222 Forwards onviron assessment & finding of no significant impact re 880629 request for extension of const completion dates of CPs CPPR-91 & CPPR-92 to 910701 & 921231, respectively.

 BLACK,S. Old of Special Projects 88/12/05. KINGSLEY,O.D. Tonnossee Valley Authority. 2pp. 47785-050-47785-055
- -8812090235 Environ assessment & finding of no significant impact rollextension of const completion dates for CPs CPPR-91 & CPPR-92 to 910701 & 921231, respective. BLACK,S. Ofc of Special Projects 68/12/05 4pp 47785.052-47785.055
- 8812150222 Discusses Generic Ltr 83-28, "Required Actions Based on Generic Implica-tions of Saferi ATWS Events" for Istod plants fleactor trip threaker meint & trending Issues should be addressed as plant-specific issues BRADFUTE_J.O Project Directorate V 88/12/06 AULUCK,R. Otc of Special Projects 3pp 47825-073-47825-075
- 8812140165 Rosponds to Ganaric Lir 88-11 re radiation embrittlement of reactor versel matts & impact on plant operations using methodology in Rev 2 to Reg Guide 1.99 GRIDLEY.P. Tennossee Valley Authority. 86/12/09. Document Control Branch (Document Control Desk). 6pp. 47800 205-47800 212.
- 8812210217 Forwards Rev 1 to corrective action program plan for replacement liems program (place parts) at Unit 1 for NRC review & concurrence Summary of commitments also end KINGSLEY,O.D Tennessee Valley Authority, 88/12/14. Document Control Branch (Document Control Desk), 2pp. 47875.185-47875.202.
- --8812210221 Rev 1 to "Wetts Bar Nuclear Plant Replacement Hems Program (Piece Parts) Corroctive Action Program Plan" MCKEEHAN,RS, METCALF,PD, LYONS,J.R. Tennessee Valley Authority. 88/12/14. 15pp. 47875;187-47875;202.
- 8812210297 Forwards Rev 1 to corrective action program plan for vendor into Summary of commitments provided in Encl 2 KINGSLEY,O.D. Tennessee Valley Authority, 88/12/14. Document Control Branch (Document Control Desk) 3pp. 47881:122-47881:141.
- -8812210302 Rev 1 to "Watts Bar Nuclear Plant Corrective Action Program Plan Vendor Info."

 LORE, S.D., BOYD, L.W., CHANDLEY, C.A. Tennessee Valley Authority. 88/12/14.

 17pp 47881:125-47881:141.
- 8812230012 Forwards Flov 0 to "Watts Bar Nuclear Plant Cable Issues Corrective Action Program Plan." Roview & concurrence requested KINGSLEY.O.D. Tennessee Valley Authority, 88/12/16 Document Control Branch (Document Control Desk). 2pp 47814:287-47914:349.
- -8812230014 Rev 0 to, "Watts Bar Nuclear Plant Cable Issues Corrective Action Program Ptan."
 Tennessee Valley Authority, 88/12/16, 61pp, 47914;289-47914;349.
- 8812230198 Forwards "Q-List Development Flowchart," inadvertontly omitted from 881027 QC list for corrective action program.
 GRIDLEY,R. Tennessoo Valloy Authority, 88/12/16 Document Control Branch (Document Control Dask), 3pp. 47011-001-47911.003.

F. Security, medical, emergency & fire protection plans

- 8812190003 Forwards Insp Repts 50-390/88-05 & 60-391/88-05 on 880816-0920.No violations or deviations noted. Three unresolved Items identified MCCOY, F.R. Region 2, Oic of the Director. 88/12/02. KINGSLEY, O.D. Tennessee Valley Authority. 2pp. 47852.154.47852.169.
- +8812190005 Insp Repts 50:390/88:05 & 50:391/88:05 on 880816:0920.No violations noted Major aroas inspected fire prevention & fire protection testing of pipe supports & costraint sys, roview of OA manual safety-rolated piping & welding BARRIK P. Dic of Special Projects. 88/12/02. 14pp. 47852:156-47852:169.

8012210195 Royased central emergency control cirl emergency plan implementing procedures including Rev 1 to CECC EP.P-1.Rev 2 to CECC-EP.P-2.Rev 2 to CECC-EP.P-4.Rev 2 to CECC-EP.P-5 & Rev 2 to CECC EP.P-7 W/

MCANALLY, JE Tennessee Valley Authority, 68/12/16, 86pp, 47:908:304-47:907-05/1

H. General correspondence

8812018405 Comments on proposed rule 10CFR26 te Filhess for Cuty Program for nuclear reactor operators Opposes random drug screening of nuclear plant employees WHITEHEAD,G.G. International Brotherhood of Electrical Workers, 88/11/21, Docketing & Services Branch 2pp 47679 250 47679 251

Q. Inspection reports, IE Bulletins & correspondence

- 8812050303 FOIA request for Ofc of Enforcement 881003 proposal to Commissioners recommending fines for TVA reiS White inaccurate written sworn statements to NAC
 - POWELSON:F. Scripps Howard Newspapers 88/10/25 GRIVSLEY D Division of Freedom of Information & Publications Services (Post 880515): 1p 47729 079-47729 079
- 8811300183 Responds to NRC 881021 notice of violation & Enforcement Action EA-88-253 Corrective actions Procedure 0502.01 revised to establish responsibilities & pro-cedures for dealing w/NRC & review & concurrence process established RUNYON,M Tennessee Valvoy Authority 88/11/21. LIEBERMAN,J. Otc. of Enforce-ment (Post 870413), 8pp. 47697 198.47697 205
- 8811160211_NRC Info Notice 88 690, "Unauthorized Removal of Industrial Nuclear Gauges." Svollst encl CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Satety (Post 870729) 88/11/22 Conscildated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257. Svc I st encl
- 8811180487 NRC Into Notice 88 091, "Improper Administration & Control of Psychological Tests." Svc 1st end ROSSICE Division of Operational Events Assessment (Post 870411) 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708:142.
- 8812010186 Forwards V Stello 861117 lb to all util executives re-presence of NRC inspector of plants ray to enforcement policy & proposed enforcement actions for operator ineffectiveness at Peach Bottom
 BLACK, SC. Otic of Special Projects 88/11/23. KINGSLEY,O.O. Tennossee Valley
 Authority, 3pp. 47709 258-47709 309.
- 8812090002 Ack receipt of 880919 fit informing NRC of steps taken to correct violations noted in hisp Rigits 50-390/88-24 & 50-391/88-24.

 MCCOY,F.R. Ofc of Special Projects 88/11/28. KINGSLEY,O.D. Tonnesseo Valley Authority 2pp 47783-326-47783-327.
- 0812090005 Ack rucelpt of 880825 ftr informing NRC of steps taken to correct violations noted in Insp Ropts 50:390/86:24 8 50:301/86:24 No objections noted to packaging commitments in 10CFR50 55(e) ropt. MCCOV.F.R. Of of Special Projects. 88/11/28 KINGSLEY,O.D. Tennessee Valley

Authority, 200, 47783,324-47783;325

- 8812090014 Ack receipt of 880609 & 0823 lirs informing NRC of steps taken to correct violations noted in firsp Repts 50-390/88 01 & 50-391/88-01. MCCOY, FR. Ofc. of. Special Projects. 88/11/28. KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47762:304-47762:305.
- 8812090031 Ack receipt of 860829 fir informing NRC of steps taken to correct violations noted in Insp Repts 50-390/87-11 & 50-391/87-11.

 MCCOY,F.R. Old of Special Projects 88/11/28 KINGSLEY,O.D. Tennassee Valley Authority. 1p. 47761:125-47701.125
- 8812090040 Ack receipt of 880915 ftr informing NRC of steps taken to correct violations noted in Insp Ripts 50:390/87-05 & 50:391/87-05 MINGSLEY,O.D. Tennessee Valley Authority. 2pp 47762 297-47782 298.
- 6812020255 Forwards ret purchase order numbers & dates for suspected purchases by util of Class 1E components or sixes from Planned Maint Systinc for appropriate action, per NRC Info Notice 88-019, "Questionable Cortification of Class 1E..."

 BLACK,S.C. Otc. of Special Projects. 88/11/29, KINGSLEY,O.D. Tennessee Valley Authority. 5pp. 47722,069-47722:073.
- 8811290030 NRC Info Notice 88-003, "Teletherapy Events" Svc List encl. CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Saloty (Post 970729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators," Svc list enci ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp, 47708.143-47708.254.
- 8812050306 Final response to FOIA request for records App A document and & available in PDR App B documents compiciory withheld (ref FOIA Exemption 5).
 GRIMSLEY, DH. Ohrston of Freedom of Information & Publications Services (Post 880515). 88/12/02. POWELSON,R. Scripps Howard Newspapers 4pp. 47729.080. 47729.084
- -8812050311 Staff requirements memo on notice of violation & proposed imposition of chil penaltias re-communication. CHILK.S.J. Office of the Secretary of the Commission. 88/10/20. STELLO,V. Otc of the Executive Director for Operations. 1p. 47728.084-47729.084.
- 8812190003 Forwards Insp. Repts 50:390/88.05 & 50:391/88-05 on 880816-0920.No violations or deviations noted. Three unresolved items Identified. MCCOY, F.A. Repton 2. Otc of the Orector, 88/12/02. KINGSLEY,O.D. Tennessee Valley Authority. 2pp. 47852:164-47852:169.
- -8812190005 Insp Repts 50:390/08-05 & 50:391/88-05 on 880816-0920.No violations noted Major areas inspected; the prevention & fire protection, testing of pipe supports & testiant sys, review of OA manual safety-related piping & welding. BARR KP, MCCOY, FR. Odd of Spoc & Projects, WALTON,G.A. Region 2, Ofc of the Director, 68/12/02, 14pp. 47852 168-47852 169.

- 6812130093 Responds to 881110 III requesting infoire Commission enforcement action concerning 860,320 lit from util:
 CAFIR,K.M. Colomosonora, 88/12/06, DINGELL J. House of Rep., Energy & Commerce, 18pp. 47792 248-47792 270
- -8812130096 Requests that NRC provide listed info to Commismon dealings witicensee 860320 III concerning comphance w/Commission QA requirements
 DINGFLL,J.D. Hause of Rep., Energy & Commerce 88711710. ZECH,L.W. Commissioners Spp. 47792 265 47792 270.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements imposed by Licensees on Vendors" Svc1st end: ROSSICE Division of Operational Events Assessment (Post 870411), 88/12/68. Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302.

S. Reportable occurrences, i.ERs & related correspondence

- 8812010042 Delicioncy reptire welds for hanger lugs on ASME Code plging initially re-ported on 870127.Final repti will be submitted by 690227.Corrective action program preparation in progress
 GRIDLEY,R. Tennessee Valley Authority. 88/11/28. Document Control Branch (Document Control Dask). 2pp. 47703.076-47703.077.
- 8812140171 Part 21.8 final deficiency rept re-potential failure of operator-to-valve en-gagement of Xomox supplied valves. Initially reported on 871204. On 880711, Xomox provided replacement parts for 24 valves identified. GRIDLEY-R Tennessaci Valley Authority. 88/12/09. Document Control Branch (Document Control Desk). 4pp. 47796.145-47796.148.

U. Congressional/Executive Correspondence

8811300078 Forwards NRC quarterly status rept covering Third Quarter CY86 in re-sponse to direction given in House Rept 97:850 ZECHLLW. Commissioners 88/11/10. BEVILL,T. House of Rep., Appropriations 12pp, 47733-001-47733-012

DOCKET 50-385 VIRGIL C. SUMMER NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811300271 Responds to NRC 881101 lir ro violation noted in Insp. Rept 50:395/88-19.Corrective actions util established position of lire protection officer on 880328. BRADILMA.O.S. South Carolina Electric & Gas Co. 88/11/18. Document Control Branch (Document Control Desk). 2pp. 47677:099-47677:105
- 8812660077 Rev 10 to Emergency Plan Implementing Procedure EPP-022, "Vertication of Communications Operability." W/881130 ltr
 BRADHAM,O.S. South Carolina Electric & Gas Co. 88/11/30, 22pp. 47741.136-47741-160

H. General correspondence

8812010408 Comment supporting proposed rule 10CFR26 re Fitness for Duty Program per NUMARC comments,w/listed exceptions. BRADI+M,O.S. South Carolina Electric & Gas Co. 88/11/21. Office of the Secretary of the Comm.ss'on.

- 8811300448 Forwards Tech Spec 3/4.8.1 re ac sources making corrections, per 880914 telcon w/NRC No significant hazards daturmination also included.

 BRADHAM,Q.S. South Carolina Electric & Ges. Co. 88/11/18. Document Control Branch (Document Control Branch (Document Control Desk). 2pp. 47680.145-47680.158.
- -8811300452 Proposed Tech Specs, identifying Surveillance Requirement 4.8 1.1.2 A.4 in note on Table 4.8-1.
 South Carolina Electric & Gas Co. 88/11/18, 12pp. 47680.147-47680:158.

- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnerabilities. Svc list enci. CRUTCHFIELD,D. Associate Director for Projects (Post 670411) 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024.
- 8812020316 Advises that replacement of new SPOS will necessitate complete re-review when Installed & operational NRC should be informed of new devolopments HAYES, J. Project Directorate in 1, 88/11/23, BRADHAM, O.S. South Cerolina Efectific & Gas Co. 2pp. 4771:122-47711-123.
- 8812070166 Requests util address Generic Ltr 88-17 re loss of DHR during nonpower operation due to Industry responding deficiently to Generic Ltr 87-12, "Loss of RHR While HCS Partially Filled."
 MURLEY T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/02, NICHOLS, T.C. South Carolina Electric & Gas Co. 2pp. 47753:079, 47753.080.
- 8812080092 Summary of 881129 meeting w/ufil in Atlanta,GA re status of licensing issues for facility.List of attendess encil & related into encil. HAYES,JJ. Project Directorate II-1. 88/12/05. Project Directorate II-1. 13pp. 47783.284-47783.296
- 8812130124 Forwards list detailing tubes in which F* criteria applied subsequent to fourth inservice addy current exam.

 BRADHAM,O.S. South Carolina Electric & Gas Co. 88/12/06. HAYES,J.J. Office of Nuclear Reactor Regulation, Director (Post 870411). 18pp. 47792:134-47792:152.

8812210044 Forwards corrected Amend 75 to License NPF-12 re VANTAGE 5 improved fuel design Pressurizer pressure itents for three loop operation should road greater man or equal to 2,236 ps/si. FrayES,JJ, Project Directorate II-1, 68/12/14 BRADHAM,O S. South Carolina Electric & Gas Co. 3pp. 47890-072-47890-075.

- -8812210050 Corrected Amend 75 to License NPF-12 re three topp ophration of RCS & pressurizer pressure
 * NRC - No Detailed Affination Given 88/12/14 1p 47890 075-47890 075

Q. Inspection reports, IE Bulletins & correspondence

- 8811300428 informs that completion rept scheduled to be provided within 30 days of fourth refueing outago will be submitted within 60 days as required by IEB-85-003 BRADHAM,O.S. South Caronna Etectric & Gas Cα 88/11/15 ERNS1,M.L. Region 2, O'c of the Director, 1p. 47701:257-47701.257.
- 8811300271 Responds to NRC 881101 lit re violation noted in Insp Rept 50-395/88-19 Corrective actions will established position of fire protection officer on 880328. BRADHAM,O.S. South Carelina Electric 8 Gas Co. 88/11/19. Document Control Branch (Document Control Dusk), 2pp. 47677:099-47677.105.
- 8812080017 Forwards Inso Boot 50-395/88-27 on 861031-1104 No violations or devi etions noted.

 HEADT,A R. Reg on 2, Oic of the Cirector, 88/11/21, RRADHAM,O S. South Carolina Electric & Gas Co. 2pp. 47750 106-47750 113
- -8812080020 Insp. Rept. 50-395/88-27 on R81031-1104.No violations of deviations noted Major areas inspected refueling activities, routine surveillance of core power distribution first & Shuddown margin & reactivity anomaly.

 JAPEE BURNETT.P.T. Region 2, Otc of the Director. 88/11/18. 6pp. 47750 108-
- 9811160211 NRC Info Notice 18-090, "Unauthorized Ramoval of Industrial Nuclear Gauges "Svc list end CUNNINGHAM.RE Division of Industrial & Medical Nuclear Safety (Past 870729). 88/11/22. Cansolidated Edison Co. of New York, Inc. 99pp. 47708 255 47708 257.
- 6811150467 NRC Info Notice 66-091, "Improper Administration & Control of Psychologi
 - cal Tests." Svc list encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708-042-47708.142
- 8812050259 Forwards Insp Rept 50-395/88-25 on Oct 1988 No violations or deviations
 - VERRELLI,D.M. Region 2, Ofc of the Dunctor, 88/11/22 BRADHAM,O.S. South Carolina Electric & Ges Co. 2pp. 47734.142-47734:151.
- -8612050262 Insp. Rept. 50:305/88:25 on 881001:31.No violations or deviations noted.Major areas inspected monthly surveillance observations, monthly maint observation operational safety vorification & crisical followup of events. PREVATTERIL, HOPKINS,P.C., DANCE,H.C. Region 2, Ofc of the Director, 88/11/22, 6pp. 47734:144-47734.151.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc list onci CUNNINGHAM,RE Division of Initiatrial & Medical Nuclear Safety (Post 870729) 68/12/02, Consolidated Edison Co. of New York, Inc. 112pp 47811:103-47811:215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Svc list
- GIGC.
 GOSSI,C E. Division of Operational Events Assessment (Post 870411). 88/12/02
 Consolidated Edison Co. of New York, Inc. 121pp. 47708-143-47708.254
- 8812090341 Forwards Insp Rept 50:395/88:23 on 881017:21 & notice of violation. HEROT,A R. Region 2, Ofc of the Director, 88/12/92, BRAUHAM,O.S. South Carolina Electric & Gas Co. 2pp. 47783.328-47783:348
- ~8812090342 Notice of violation from insp on 881017-21. Violation noted corrective actions taken re-potential for mixed grease in Limitorque operators required to be environmentally qualified, inadequate. ronmenially qualified inadequate.
 HERDT,A.R. Region 2, Ofc of the Director, 88/12/92, 1p. 47783 330-47783 330.
- -8812090343 Insp. Ropt 50-395/88-23 on 881017-21.Violation noted.Major eroas Inspected environ qualification of electrical equipment,including raview of tull Implicimentation of program to meet 10CFR50-49 requirements & followup on previous Insp. CONLON.T.E. MERRIWEATHER,N. Region 2, Otc of the Director. 88/12/01. 14pp. 47783 331-47783 346
- 8812120084 Advises that insps during fourth refueling outage have shown no thinning occurring & no replacement necessary,per util 870901 response to NRC Bulletin 87-01, "Thinning of Pipe Welfs in Nuclear Power Plants" BRADHAM.O.S. South Cerolina Electric & Gas Co. 88/12/02. Document Control Branch (Document Control Desk). 1p. 47785:204-47785-204.
- 8812150170 Ack receipt of util 880916 ltr denying violations noted in Insp Rept 50:3857 88-13 Violation occurred as stated in notice of violation Evaluations & conclusion encl. ERNST,M.L. Region 2, Oic of the Director, 88/12/07, BRADHAM,O.S. South Carolina Efecting & Gas Co. 5pp. 47822:349-47822:353
- 8812190102 Ack receipt of 881118 ftr informing NRC of stops taken to correct violations noted in Irsp Rept 50:395/88-19.
 REYES,L A. Region 2, Ofc of the Director, 88/12/07, BRADHAM,O.S. South Carolina Electric & Gas Co. 1p. 47849:165-47849.165.
- 8812020287 NPC Info Notice 88-005, "Inadequate Procurement Requirements Imposed by Licensees on Vendors," Svc list encl ROSSI.C E. Division of Operational Events Assessment (Post 870411) 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8612200291 Forwards Insp Ropt 50-395/88-28 on 881101-1207.No violations or deviations noted VERRELLI,D.M. Region 2, Otc of the Director, 88/12/13, BRADHAM,O.S. South Caro-lina Electric & Gas Co. 2pp. 47862:173-47862.182.

- -8812200296 Insp. Rept. 50:395/88:28 on 681101:1207.No violations or deviations noted Major largest inspected monthly survertance interval on monthly ment observation operational safety verification. ESF sys walknown & design changes &
 - mods.
 PREVATTE.R.L., HOPKINS.P.C., DANCE.H.C. Region 2, Old of the Director 88/12/ 13 8pg 47862:175-47862 182.
- 8812270271 Advises that current miniflow rates & operation of enlictgancy feedwater pumps acceptable for concerns of NRC Bulletin 88-04 until risp of pumps can be completed during fifth returing outage. Summary of into recommended miniflow encough and the second managed miniflow encough and the second managed miniflow encough the second managed miniflowers and second managed miniflowers. South Carolina Electric & Gas Co. 89/12/20 Eccument Control Desk) 3pp 4/924/205-4/924/207

R. Periodic operating reports & related correspondence

- 8812140026 Monthly operating rept for Nov 1998 for Virg1 C Summer Nuclear Station Unit 1.W/881207 fir HALTIWANGER,J. BRADHAM,O.S. Snuth Carolina Electric & Gas Co. 88/11/20 BARRY,L.W. Document Control Branch (Document Control Desk). 5pp. 47798-358-
- S. Reportable occurrences, LERs & related correspondence
- 8812010002 LER 88-011-00.on 891026.oddy current exam completed & results yielded insp. Category C-3 determination since more than 1% of inspected tubes were defective. Caused by primary water stress corroston cracking W/881123 ftr. HIGGINS,W.R., BRADHAM,O.S. South Carolina Electric & Gas. Co. 88/11/23 4pp. 47698 201 47695 204

V. Operator Examinations

8812010016 Requests that util turnish and list of ref mail for evaluation of requalifica-tion program & licensed pursonnol schoduled for FotzMar of 1969 JULIAN,CA Region 2, Ofc of the Director, 88/13/17, NAUMAN,DA South Carolina Efective & Gas Co. 6pp. 47709,145-47709.150

DOCKET 50-396 UNIV. OF VIRGINIA CAVALIER REACTOR

P. Operating (iconse stage documents & correspondence

- 8812010059 Application for amend to License R-123,adding Tech Spec 4.0, "Surveillance Requirements."
 MULDER,R.U. Virginia, Univ. of Charlottesville, VA 88/11/22 Decument Control Branch (Document Control Desk), 1p. 47702.343-47702:344
- -8812010079 Proposed Tech Spec 4.0 "Surveillance Requirements."

 Virginia, Univ. of, Charlottosville, VA 88/11/22, 1p 47702 344-47702 344
- 8812210183 Forwards request for addl into & clarification re 881122 application for amend to Liconse R-123,consisting of proposed Tech Spoc & status of survoil ance requirements for moving fuel or having partially loaded coro.

 ADAMS,A. Standgridzation & Non-Power Houctor Project Directurale 88/12/14.

 MULDER,R.U. Virginia, Univ. of, Charlottosvillo, VA. 4pp. 47881-282-47881-285.

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8812130130 Clarifies min staffing needed for safe shutdown to Insp Rept 50-397/88-16 dtd 880725. Util understands that any combination of personnel meeting 10CFR50.App
- R requirements acceptable. SORENSENG C. Washington Public Power Supply System. 88/11/28. MARTIN.J.B. Region S, Oic of the Director. 2pp. 47797:216-47797:217.
- 8812130138 Provides status rept update on Tasks 6 & 8 re facility fire protection re-evaluation rept W/exception of remaining actions necessary to complete Task 8 sub-sequent to NRC approval of Amend 37.Improvement initiatives completed SORENSEN.G.C. Washington Public Power Supply System. 88/11/30 MARTIN.J.B. Region 5, Ofc of the Orector. 2pp. 47797.214-47797.216

J. Insurance & Indemnity Information

8812010001 Submits guarantee of payment of deforred promium.per 10CFR140.21 requirements SORENSEN,G.C. Washington Public Power Supply System. 88/11/22. Document Control Branch (Document Control Dosk), 1p. 47703.101-47703.101.

- 8811230215 Informs that selpoint methodology for GE supplied protection sys instru-mentation acceptable on condition that licensee submits reptire results of reovalua-SAMWORTH,R.B. Project Directorate V. 88/11/03. SORENSEN.G.C. Washington Public Power Supply System. 4pp. 47622 252-47622 258.
- -8811230217 Safety evaluation of instrumentation setpoint methodology for util re safety-related instrument measuring sys in svc at plant *NRC No Dotalled Afficiation Given. 88/11/03 3pp 47622:256-47622:258
- 8812020098 Requests discretionary enforcement re-Toch Spec 3/4-3-3 re-ECCS actuation instrumentation & applicability Spec 3/0-3 for 24-th period bogaming 881121 POWERS,C.M. Washington Public Power Supply System. 88/11/21 Document Control Branch (Document Control Desk). 3pp. 47/07:235-47/07.237.

- 8811280048 Generic Etri88 20 to a hitemsees holding Ots & CPs for nuclear power reactor factions to estautual plant channing system accident witherabilities Svo list enci CRUTCHFIELD D. Associata Director for Projects (Post 870411), 88/11/23. Consoli-dated Edisch Co. of New York, Inc. 81pp. 47728 303 47729 024.
- 8812080120 laterns that 681024 application for amend cannot be reviowed due to still faiture to indicate need for changes faiture to provide NSMC analysis.

 SAMWORTH R.B. Project. Directorate: V 88711730 SORENSEN,G.C. Washington Public Power Supply System Spp. 47734-233-47734-235

- 8812080120 Forwards SEA supporting ub responses to Generic Lir 83-28, Item 2.1 (Part. 1), "Equipment Classification (Reactor Tup Sys)" Items 2.2.2 & 4.5.3 remain SAMWORTH RIB Froject Directorate V 69/11/30 SCHENSEN,GIC Washington Public Power Supply System App 4/756 236-47756 242
- -8812080121 Safety evaluation supporting util response to Generic Etr 63-28, Item 2-1 (Pair 1), "Edupment Classification (Reactor Trip Sys Components)."

 * NPC No Octared Affiliation Given -88/11/30 -3pp -47756-240-47756-242
- -8811170247 Conformance to Gordio Ltt 83/28 ltem 2/2/1 Equipment Classification for Att Other Safety Refaled Comporents Washington Nuclear Plant 2 "VANDERBEEK R GOSG Idaho, Inc. (subs. of EGSG, Inc.) VANDERBEEK.A Idaho National Engineering Laboratory FIN Octools EGG Ntt 7/317 88/04/20) NRC Na Detailed Attication Given. 16pp. 69556 101-69556 116.
- 8812200185 Application for amend to Liceuse NFF-21 revising Tech Spec Survivillance Requirement 4.8.1.1.2.e.7 so that Tech Specs consistent widesign of automatic bypass function of deset generator to steep paid SORENSENIGC Washington Pothic Power Supply System 88/12/02 Document Control Branch (Document Control Desk), 3pp. 47867-270-47867-273
- -8812200188 Proposed 1ech Specificusing Surveillance 4.8 1.1.2.9.7 to be consistent widesign of automatic bypass function of dissel generator trips.
 Washington Public Power Supply System, 88/12/02. 1p. 47867-273-47867-273.
- 8812150136 Confirms NRR pasition on interpretation of monthly channel functional test of 416 kV emergency bus undervollage (degraded vollage) protection circulary (Tech Spec 3/4) 3 ECCS actuation instrumental on Table 4 3 3 1-1, tlem D 2) SAMWORTHR B. Froject Directorary V 88/12/05 SCPENSEN.G C. Washington Public Power Supply System. 4pp. 4/830 132-47630 135
- 8812150083 Forwards safety evaluation relationate rod injection (ARI) & recirculation pump stip (ARI) per unit 870413 & 850624 tirs ARI design in compliance w/ATWS rule RPT design not in full compliance w/Live RPT inclusion logic to be modified SAMWORTH R B Project Directorate V 88/12/08 SORFISEN,G C Washington Public Power Supply System 3pp 47830 258/47839 270
- -8812150084 Safety evaluation re-compliance w/ATWS rule 10CFR50.62 concerning elements rod injection (ARI) & recirculation pump trip (RPT) sys.RRI design in compliance w/rule RPT initiation logic design not in full compliance w/rule * NRC No Desafed Afficiation Given 88/12/06 10pp 47830.261-47830.270
- 8812150013 Provides description of decision process used to determine channel func-tional test boundaries for second level undervoltage protection utilized at facility SORENSENIGC Washington Public Power Supply System 881/12/07. Document Control Branch (Deciment Control Desk) 55pp 47800 261 47800 317.
- 8812210254 Application for amend to License NPF-21,modifying Tech Spec Table 3 3 7 12-1 re radoactive gas efficer mor toning instrumentation to allow operation of main condenser oil gas treatment sys who redundant hydrogen mor nor Fee pairl SORENISENG C. Washington Public Power Supply System 88/12/12. Document Control Branch (Document Control Desk). Spp. 47876 023-47876 028.
- ~8812210255 Preposed Tech Spec Table 3.3.7.12-1, 'Aadioactive Gasgous Effluent Mon-tonng Instrumentation Washington Public Power Supply System 88/12/12 1p. 47876 028-47876 028

Q. Inspection reports, IE Bulletins & correspondence

- 8812060080 Forwards Exam Rept 50 397/OL-88-02 of exam administered on 880921-22 & 1004 Simulator continues to display fidelity problems to extent that comprehensive NRC operating exams can not be administered. PATE,RJ Region 5, 01c of the Director. 88/11/10. DXSEN,L. Washington Public Power Supply System. 2pp. 47736;223.47736;336.
- -8812060082 Exam Rept 50:397/OL:88-02 on 880921-22 & 1004 Exam results: four senior reactor operators passed all exams.
 MEADOWS,T.R., EUN.J.O. Region 5. Ofc of the Director 88/11/08, 111pp 47736 225-47736 335
- --8812060084 Advisos that all facility comments resolved during 881004 post-exam review w/T Meadows No formal comments will be submitted SORENSENGC Washington Public Power Supply System 88/10/21 MARTIN, J.B. Region 5, Ofc of the Director. 1p. 47736-336-47736-336.
- 8811180260 Forwards risk based inspiguides described in mods to Inspi Manual Chapter

2515.W/o encis LONG,S.M. Risk Applications Branch 88/11/18. LANHAM,D. Document Control Branch (Document Control Desk), 1p. 47597,114-47601,019

- 8812060288 Forwards executive summary for impaired function testing of Limitorque gearbox relief values per agreement during ext meeting re Insp Rept 50-397/88-12 SORENSENIG C. Washington Public Power Supply System 88/11/16. MARTIN,J.B. Region 5, Ofc of the Director. 5pp. 47762:195-47752 199
- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc hst enct.
 CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729).
 88/11/22. Consolidated Ed.son Co. of New York, Inc. 99pp. 47708.255-47708.257.
- 8811180467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Tests." Svc list encl ROSSICE: Division of Operational Events Assessment (Post 870411), 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp 47708.042-47708.142.

- 8811200304 Informs that no further action plannad on 881121 request for enforcement discretion re. Tech Spec. 3.0.3 Servorlance testing of time delay relays completes a enforcement discretion no fonger requested por tele
- 8812120001 Forwards Insp. Rept. 50:397788-24 on U880822 0902 & notice of violation Overall conclusions Issted including problems not being adequately identified at working fevel.

 MARTIN, J.B. Region 5, Ofc. of the Director, 08/11/23 SORENSEN,G.C. Washington
 Public Power Supply System, 4pp. 47/89 158-47789, 192.
- --8812120002 Notice of violation from inspirence 880822-0902 Violations noted charges to Surveillance Procedure 7.4.4.3.1.4 made thirting thywell sump flow menter caters. Surveyance in not completed grocation for completed MARTINUE Region 5, Ofc of the Director 88/11/23 Cpp. 47/89 162-4/783 167
- -8812129003 Insp Rept 50:397788-24 on 880822-0902 Violations noted. Major Bleas inspected mantleng need by determine a continuous relations related Major meas inspected mantleng needs & OA activities related the self-united generator system clear steam supply shuldflays O'ANGELOA, TATUMUL, FIGRELLIG Region 5, Old of the Director 83/11/15 25pp 47789.188-47789 192.
- 8812150001 Forwards Insp. Rept. 50.307788.38 on 881906-1107 Violations noted Violation will bin subj. of separatin correspondence.
 KIRSCH,D.F. Region 5, Otc. of the Director. 88/11/25. SORENSEN,G.C. Washington Public Power Supply System. 2pp. 47830-210, 47830-223.
- -8812150002 Insp Rept 50-397/68-39 on 681006-07 No violations noted. Major areas inspected follow-up on two unresolved items in area of environ qualification of electical adjument JOHNSON A.D., PATE, R.J. Region 5, Old of the Director 88/11/25, 4pp, 47830.212-47830 223
- 8812020259 Responds to NRC 861027 ltr re-violations & deviations noted in tosp Repl 50-397/89-32 Corrective actions missing lack wasters replaced & all hydraulic central unit hald down botts torqued chacked SORENSENGC. Washington Public Power Supply System 88/11/28 Document Control Branch (Document Control Branch (Document Control Desk) 10pp. 47717-106-47717-115
- 8812060287 Ack receipt of 881104 ltr informing NHC of steps taken to correct violations noted in Insp. Rept. 50-397/88-33. Advises that results from 881011 test inconclusive & additiost most be partiamed. YUHAS,G.P. Region 5, Oit of the Director. 88/11/28. SOITENSON,G.C. Washington Public Power Supply System. 2pp. 47734-168-47734-172.
- 8812130130 Clanties min statting needed for safe shuldown re thisp Rept 50 397/89-16
- dtd 880725.Util understands that any confidention of personnet meeting 10CFR59,App. SORENSEN.G.C. Washington Public Power Supply System 89/11/28 MARTIN,JB Region 5, Oic of the Director. 2pp. 47797:218 47797:217
- 8812070045 Responds to NRC 881104 ltr re violations nated in Insp Rept 50 397/88 36 Corrective action taken posting immediately restored to correct position & indepth framing on testing to verify restoration of radiation area posting provided SQREMSENGC Westington Public Power Supply System 88/111/30 Document Control Branch (Document Control Dosk) 3pp 47745-358-47745-360.
- 8812150239 Ack receipt of 880729 Its informing NRC of steps taken to correct violations PATE R J. Region 5, Ofc of the Director, 88/12/01, SCRENSEN,G.C. Washington Pubic Power Supply System, 2pp. 47830 253, 47830 257.
- 8811290030 NRC Info Notice 88.093, "Teletherapy Events" Svc list onch CUNNINGHAM.R.E. Division of Industrial & Madical Nuclear Safety (Post 879728) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp 47611:103-47811
- 8811290538 NRC Into Notice 88-094, "Potentially Undorsized Valve Actuators" Svc list encl. ROSSI, C.E. Division of Operational Events Assessment (Post 870411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708-143-47708-254.
- 8812020287 NRC Info Notice 88:095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svc list encl. ROSSICE Division of Operational Evonts Assessment (Post 870411) 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807.302.
- 6812220353 Forwards Rev 1 to "Insp of ANF Fuol Assemblies 1163 & 1164 After One-Cycle of Irradiation at Washington Nuclear Plant 2 Reactor." Insps metivated in part by util concerns to crud induced localized corposion Rept withheld (ref. 10CFR2.790) SORENSEN.G.C. Washington Public Power Supply Systom 88/1/2708. Document Control Branch (Document Control Dusk). 5pp. 47914/225-47914:229.
- 8812210070 Ack receipt of 881130 ftr informing NRC of steps taken to correct violations noted in Insp. Rept 50-397/88-36.
 YUHAS,G.P. Region 5, Ofc of the Director, 88/12/12, SORENSEN,G.C. Washington Public Power Supply System. 1p. 47877:121-47877:124.

R. Periodic operating reports & related correspondence

8812200086 Monthly operating rept for Nov 1988 for Washington Nuclear Plant-2.W/ 561208 III HUTCHISON,L.B., POWERS,C.M. Washington Public Power Supply System, 88/11/ 30. 4pp. 47871.054-47871.057.

S. Reportable occurrences, LERs & related correspondence

8811290352 Requests addl into re Special Rept LER 88-024 concerning temp in roactor comainment in excess of Tech Spec limit of 150 F, including actions taken after 880720 to reduce temps.

KIRSCH D.F. Region 5, Oic of the Director, 88/11/18, OXSEN,A L. Washington Public Power Supply System. 2pp. 47665:035-47665:036.

- 8811300187 PriO-Y-88-083 on 881121 liconson ductared unusual event as result of entry into Tech Spec 3.0.3.8 ponting reactor shufdown Action occurred due to inoperable relays Relay lessing completed 8 unit returned to power JOHKSON,P, BOSTED.C. Region 5. Otc of the Director 88/11/21 1p. 47676-238-47676-238.
- 8812080023 PNO-V-88 064 on 881130 unusual event declared & reactor shallown initialed due to determination that leakage from suppression pool vacuum breaker valve CSP-V9 in excess of Tech Spec timil Valve will be repaired.

 CALDWELLC, BOSTED,C Region 5, Ofc of the Director 88/12/01, 1p. 47783 226-47783 226.
- 8812080124 TER 88 035:00 on 881101, determined that control rod block intermediate range monitor quarterly channol calibris surveillances not performed. Caused by tack of rowew of testing required for changes in conditions W/881201 ltr. WASH-NGTON,SL. POWERS,C.M. Washington Public Power Supply System. 88/12/01. 6pp. 47757.090.47757.095.

V. Operator Examinations

- 8812060080 Forwards Exam Rept 50-397/OL-88-02 of exam administered on 880921-22 & 1004 Sirrulator continues to display fidelity problems to extent that comprehensive NRC operating exams can not be administered PATE/R J. Regron 5, Oto of the Director 89/11/10 OXSEN,L. Washington Public Power Supply System 2pp 47736-223-47736:336
- --\$812080082 Exam Rept 50-397/OL-88-02 on 880921-22 & 1004 Exam results: four senior reactor operators passed all oxems.
 MEADOWS,T.R., ELIN,J.O. Region 5, Ofc. of the Director 88/11/08, 111pp 47736-225-47738-335
- --9812060084 Advises that all facility comments resolved during 861004 post-exam review w/T Meadows No formal comments will be submitted SORENSEN.G.C. Washington Pub'rc Power Supply System. 86/10/21. MARTIN,J.B. Reg.on 5, Ofc of the Director 1p. 47730-336-47736.336.
- 8812140061 Forwards revised agenda for annual operator liconsing mosting on 890110.W/o encl PATE,R.J. Region 5, Olic of the Director, 88/12/05, BARMETTLOR,R. Washington Public Power Supply System 1p. 47709:299-47799.299.

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811300508 Forwards Rev 3 to Emergency Procedure PEP-101, "Emergency Classification & Initial Emergency Actions." Hav 14 to amergency plan completed. Fraining on naw emergency action fewal flow paths provided to operators WATSON,R.A. Carofina Power & Light Co. 86/11/14. Document Control Brench (Document Control Desk). 1p. 47705.027-47705.036.
- ~8811300521 Ray 3 to Emergency Plan Implementing Procedure PEP-101, "Emergency Classification & Initial Emergency Actions" W/two gversize ancis
 HENNANT.C S. Carolina Power & Light Co. 86/11/03. 9pp. 47705.028-47705.036.
- 8812060267 Forwards Insp Rept 50-400/88-38 on 880921-1020 No violations or doviations coted

atons noted VERRELLIO,M. Ragion 2, Ofc at the Director 88/11/23. UTLEY,E.E. Carolina Power 8 Light Co. 2pp. 47734:261-47734:272.

- -8812060271 Insp. Rept. 50-400/88-38 on 880921-1020 No violations or deviations noted. Major areas inspected surveillance obsurvations, maint observations, radiotogical protection program, physical security program & LEHs BRADFORD, W.H., SHANNON, M.C., FREDRICKSON, P. Region 2, Ofc of the Director. 88/11/23, 10pp. 47734-263-47734.272.
- 8812050 191 Responds to NRC 8B1031 ltr re violations noted in Insp. Ropt 50-400/88-33.Corrective actions fire watch personnel cautioned on seriousness of not complying whoutly life watch requirements. WATSONR A. Carolina Power & Light Co. 88/11/20. Document Control Branch (Document Control Dosk). 4pp. 47731:131-47731:134.
- 8812200092 Advisos that 880822 Rov 14 to emergency plan meets planning stds of 100F R50.47(b) & requirements of App E & acceptable.
 DECKER,T.R. Region 2, Oit of this Director. 88/12/13. UTLEY,E.E. Carolina Power & Light Co. 2pp. 47860.307.47860.308
- 8812220278 Approves 830415 requests for approval of use of alternate locations in place of backup emergency operations facilities for plants. IO.R.FI. Project Directorate II-1, 88/12/16, UTLEY,E.E. Carolina Power & Light Co. 4pp. 47902:288-47902:281.

P. Operating license stage documents & correspondence

- 6811290523 Forwards summary of 860923 presentation made to NRC ro wall thickness of RCS piping at plant LOFLINL.1 Carolina Power & Light Co. 88/11/18. Document Control Branch (Document Control Desk). 40pp. 47662.160-47662:199.
- 8811280048 Generic Lift 88:20 to all licenscues holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnorabilities.Svc list
- ends: CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consolideted Edison Co. of New York, Inc. 81pp. 47728 303-47729.024.
- 8812070132 Requests that util address Generic Ltr 88-17 re loss of DHR during nonpower operation.Industry response to Generic Ltr 87-12 deficient in areas of prevention of accident initiation & mitigation of accidents. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02. SMITH.S.H. Carolina Power & Light Co. 3pp. 47749:263-47749:265.
- 8812140082 Advises that I start project managers reassigned to plants, effective on 881205.

 ADENSAM,E.G. Project Directorate II-1, 88/12/08, UTLEY,E.E. Carolina Power & Light Co. 3pp. 47799:240-47799:242.

Q. Inspection reports, IE Bulletins & correspondence

- 8811230015 Forwards Insp. Rept. 50.400/88:35 on 881011-14.No violations or deviations noted HERDT, A.R. Region 2, Ofc of the Director. 88/11/10. UTLEY, F.E. Carolina Power & Light Co. 2pp. 47652.081-47652.089.
- -8811230019 Insp. Rept. 50-400/88-35 on 881011-14.No violations or deviations noted Major areas inspected produced testing, post-rollering startup tests & beginning of cycle power operation. BURNET1,P.T., JAPE,F. Region 2, Ofc. of the Director. 88/11/08. 7pp. 47652.083-47652.059.
- 8811300045 Discussos SALP Ropt 50 400/89-17 & forwards summary of 880916 meeting SALP presentation strices & 881028 response ERNST,ML Region 2, Otc of the Director, 88/11/21 UTLEY,E.E. Carolina Power & Light Co. 57pp. 47668 226-47668 285
- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svo list encl CUNNINGHAM,RE. Division of Industrial & Medical Nuclear Safety (Post 870729), 88/11/22 Consol.dated Edison Co. of New York, Inc. 99pp. 47708-255-47708-257.
- 8811160467 NRC Info Notice 88-091, "Irr:proper Administration & Control of Psychological Yosts" Svc list end ROSSI,C.E. Division of Operational Events Assussment (Post 870411), 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708-042-47708-142.
- 8812080113 Forwards Insp. Rept 50 400/86-34 on 880319-23 & 1003-07 & notice of violation ERNST,M.L. Region 2, Ofc of the Director 88/11/22, UTLEY,E.E. Carolina Power & Light Co. 2pp. 47757,118-47757;161.
- -8812080116 Notice of violation from Insp on 880919-23 & 1003-07. Violation noted faiture to document that caution tag audit conducted & guideline limits on work hours for maint exceeded w/o required euthoraction during 880730-0916. ERNST,M.L. Region 2, Otc of the Director, 88/11/22, 2pp. 47757.120-47757:121.
- -9812080118 Insp Rept 50:400/88:34 on 880919:23 & 1003:07 Violation noted Major aross Inspected licensee current fovol performance in plant operations including maint,QA,training in supporting safe plant operations & engineering SHYMLOCK,M. BRESLAU,B. Region 2, Otc of the Director. 88/11/09 40pp 47757:122-47757:161.
- 8811300410 Responds to NRC 881025 lir ru doviations noted in Insp. Ropt 50-400/88-29 Corrective action existing program will be modified to evaluate 8 trend devices found out of allowable victue criteria. WATSON R.A. Core on Power 8, Linkly Co. 88/41/23, Document Cooked Respect (Doc.

WATSON R A Carolina Power & Light Co. 88/11/23. Document Control Branch (Document Control Dosk). 3pp. 47673:151-47673.153

- 8812060267 Forwards Insp. Rept. 50-400/68-36 on 660921-1020.No violations or deviations noted VERRELULD M. Region 2, Old of the Director 88/11/23, UTLEY,E.E. Carolina Power & Light Co. 2pp. 47734:261-47734:272
- -8812080271 Insp. Rept. 50.400/88-38 on 880921-1020.Np violations or deviations noted Major areas inspected survariance observations maint observations, radiological protection program, physical security program & LERs BRADFORD.W H., STANNON, MC., FREDRICKSON.P. Region 2, Oic of the Director. 88/11/23, 10pp. 47734-263-47734-272.
- 8812050191 Responds to NRC 861031 Iff re violations noted in Insp. Rept 50-400/88-33 Corrective ections fire watch personnel cautioned on seriousness of not complying

w/hourly life watch requirements.

WATSON,R A. Carolina Power & Light Co. 88/11/29. Document Control Branch (Document Control Dosk). 4pp. 47731:131-47731:134.

- 8812050195 Responds to NRC 881031 ftr re violations noted in Insp Rept 50-400/88-27. Corrective actions t-dreins properly installed in Limitorque valve operator IMS-70 & equipmont qualification restored. WATSON,R.A. Carolina Power & Light Co. 88/11/29. Document Control Branch (Document Control Dosk), 3pp. 47731:135-47731:137.
- 8811290030 NRC Info Notice 88:093, "Telatherapy Events." Svc list encl CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safaty (Post 870729), 88/12/02. Consolidated Edison Co. of New York, Iric. 112pp. 47811:103:47811.215.
- 8B1129053B NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708-143-47708-254.
- 8812020287 NRC Info Natice 88-095, "Inadequate Procurement Requirements Imposed by Licansees on Vendors" Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807 302.
- 8812210021 Ack receipt of 881112 ftr Informing NRC of steps taken to correct violations noted in Insp Rept 50-400/88-28 NRC records changed to assign Severity Level V to Violation C.in consideration of Info provided in response. COLLINS,D.M. Region 2, Ofc of the Director, 88/12/09, UTLEY,E.E. Carolina Power & Light Co. 1p. 47880:180-47880:180
- 8812210016 Ack receipt of 881129 ltr informing NRC of steps taken to correct violations noted in Insp. Rept. 50-400/86-33.
- noted in Insp Rept 50-400/88-33.
 VERRELLI,D.M. Region 2, Ofc of the Director, 88/12/16, UTLEY,E.E. Carolina Power 8 Light Co. 1p. 47881;106-47881:108.
- 8812270134 Responds to NRC 881122 ltr re Vlolation B noted in Insp Rept 50-400/88-34. Corrective actions methods by which audis scheduled & documented made & copies of completed audit forms retained until original received by document sxcs. WATSON,R A. Carolina Power & Uight Co. 88/12/19, Document Control Branch (Document Control Desk), 3pp. 47926:175-47926:177.

8812200117 Monthly operating rept for two 1988 for Harris Nuclear Power Plant Unit 1 W/881215 fr HALE,M.W., WATSON,R.A. Carolina Power & Light Co. 88/11/30, 5pp. 47861-053-47861 057

S. Reportable occurrences, LERs & related correspondence

- 8812010218 LER 68 031.00 on 880614-21 & 0723-26,wide range gas monitor inoperable & compensatory actions not taken or documented as being taken as required due to personnel error Caused by faithre to Instell EC4-X as required W/881128 lin. SCHWABENBAUER, WATSON.R.A. Caro na Power & Light Co. 88/11/28 4pp. 47703 211-47703 214.
- 8812050217 LER 88-032-00 on 881030.manual reactor trip upon loss of main feedwater occurred Causod by trip of heater drain pumps attributed to privided cover latt inside Feedwater Heater 3A following maint Plywood cover removed W7881129 lin JOHNSON JR, WATSON,R.A. Carolina Power & Light Ca. 88/11/29. 8pp 47730.297-47730.302

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F. Security, medical, emergency & fire protection plans

- 8811290008 Forwards Physical Security thap Rept 50-409/88-09 on 881021-28 & 1101 No violetions noted GREGER.L.R. Region 3, Olic of the Director. 88/11/18 TAYLOR,J.W. Dairyland Power Cooperative 2pp. 47688:100-47668:102.
- -8811290008 Partially withhald physical security Insp Rept 50-409/88-09 on 881021-28 & 1101 (ret 10CFR2.780(d) Major areas insp. Implementation of newly approved physical security plan for SNM "possession only" site.
 FUNK,DF, CREED,JR. Region 3, Ofc of the Director, 88/11/16, 1p. 47888,102-47688-102.
- 8812060144 Advisos that 081101 Rev 4 to security pran & guard training & qualification plan moets 10CFR50 54(p) & acceptable GREGERJL R Reg on 3, Otc of the Director, 88/11/30 TAYLORJW. Dairyland Power Cooperative, 2pp. 47740:324-47740 325
- 8812080160 Advises that 881115 Rev 6 to QA program consistent w/ provisions of 10CFR50.App B & acceptable Rev involves organization changes including fire protection respons bitly new assigned to technical support engineer. WRIGHT,G.C. Region 3, Qic of the Director 88/12/05 TAYLOR,J.W Daryland Power Cooperative 1p. 47754:144.47754:144.

J. insurance & Indemnity information

- 8811290429 Forwards temporary exemption from 10CFR50.54(w)(5)(i) schedular requirements of property insurance rule re insurance policies that prioritize insurance proceeds for stabilization & decontamination after accident ERICKSONP B. Standardization & Non-Power Reactor Project Oirectorate, 88/11/18, TAYLOR,J.W. Dairyland Fower Cooperative, 4pp. 47665.001-47665;015
- -8811290433 Temporary exemption from 10CFR50.54(w)(5)(i) re increase in amount of onsite property darrage insurance required by power reactor licensess & Insurance that prioritize insurance proceeds for stabilization & docontemination after accident IOLAHANG M Division of Reactor Projects - IJI, IV. V & Special Projects (Post 870411), 89/11/18. Daryland Power Cooperative 4pp 47665.005-47685:015.

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 98-20 to all ficensees holding OLs & CPs for nuclear power reactor factures to individual plant exam for severe accident vulnerabilities. Svc list enci. CRUTCHFIELD.D., Associate Director for Projects (Post 870411), 98/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 8812080150 Advises that 891115 Rev 6 to QA program consistent w/ provisions of 10CFR50,App 8 & acceptable Rev involves organization changes including fire protection responsibility now assigned to technical support engineer.
 WRIGHT,G.C. Region 3, Olo of the Director. 88712/05. TAYLOR,J.W. Dairyland
 Power Cooperative 1p. 47754-144-47754-145.
- 8812140182 Responds to Genant Lit 88-14, "Instrument Air Supply Problems Affecting Safety-Related Equipment." Emergency procedures for loss of control air revised in Feb 1988 to reflect current status of plant.
 TAYLORJ.W. Daryland Power Cooperative. 88/12/06. Document Control Branch (Document Control Desk), 2pp. 47800.158-47800;159.

Q. Inspection reports, IE Bulletine & correspondence

- 8811290006 Forwards Physical Security Insp Rept 50-409/88-09 on 881021-26 &
 - T101.No violations noted GREGER, L.R. Reg on 3, Otc of the Director, 88/11/18, TAYLOR, J.W. Dairyland Power Cooperative, 2pp. 47688:100-47668;102.
- -8811290008 Partially withhold physical security Insp Rept 50-409/98-09 on 881021-26 & 1101 (ref 10CFR2.790(d).Mejor areas insp: implementation of newly approved physical security plan for SNM "possession only" ent. FUNK.DF., CREED.J.R. Region 3, Old of the Director. 88/11/16. 1p. 47669:102-47688:102.

cal Tests." Svc list end.

ROSSI,C.E. D. vision of Operational Events Assossment (Post 870411), 88/11/22

Consol.dated Ed.son Co. of New York, Inc. 101pp. 47708.042-47708.142

- 8811290830 NRC Info Notice 88-093, "Teletherapy Events." Svc Lst enct.
 CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Salety (Post 670723)
 88/12/02, Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Sycist ROSSICE Division of Operational Events Assessment (Post 870411) 99/12/02 Consolidated Edward Color New York, Inc. 121pp. 47708 143-47708 254
- 8812020287 NRC Info Notice 88-085, "Inadequate Procurement Requirements Iniposed by Licensees on Vendors" Svc 1st oncl.
 ROSSIC E Division of Operational Events Assessment (Post 870411) 88/12/68
 Consolidated Edison Co. of New York, Inc. 112pp 47807:191-47807:302.

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8811290504 Forwards Insp Repts 50-220/88-30 & 50-410/88-29 on 880926-30 No vo-EBNETERS D. Region 1, Ofc of the Director 88/11/18. MANGAN,C.V. Naçala Mohawk Power Corp. 2pp. 47662 238-47662 249
- -6811290610 Insp Repts 50-220/88-30 & 50-410/88-29 on 880926-38 No violations noted Major areas Inspected security plan & procedures.mgl organization, sudits, records & repts, testing & maint, berriers, security power supply & asprocedures,mgl sessment aids TOB.N.W.J. Region 1, Oic of the Director 88/11/16, 10pp, 47662,240-47662,249
- 8812090292 Advises that 880524 Flov 5 to physical security plan consistent w/prositions of 10CFR50.54(p) & acceptable BELLAM/R.R. Region 1, Oic of the Director, 88/11/29 MANGAN,C.V Niegara Mohawk Power Corp. 4pp. 47784/346-47784,349.

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 88:20 to all licensees holding QEs & CPs for nuclear power reactor facilities se individual plant exam for sovere accident vulnerabilities Svc list enci. CRUTCHFIELD.D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 8812020296 Provides summary of results of technical analyses in response to Generic tir 88-11,dtd 880712 Prossure/temp km/s need to be updated & schedule proposed for updating Tech Specs. TERRYCD. Niegara Mohawk Power Corp. 88/11/28. Document Control Branch (Document Control Desk). 3pp. 47718.263-47718-265.
- 8812210332 Forwards application for amend to License NPF-69 Amend revises Tech Spec Sections 4.8.4.4.8.4.8.4.5 re reactor protection sys (RPS) electric power monitoring (RPS) logic) 8 (scram solonoids), respectively Fee paid. TERRY.C.D. Niagara Mohawk Power Corp. 88/12/15 Document Control Branch (Document Control Desk). 1p. 47890.059.47890.071
- -8612210335 Application for amend to Licenso NPF-69, changing Tech Spocs to revise surveillance frequency for performance of channel functional feats on reactor profection as polectical profection as sembles TERRY,C D. Niagara Mohawk Power Corp. 88/12/15, 2pp. 47890:060-47890.061
- -8812210336 Proposed Tech Specs re-reactor protection sys electric power mon toring (RPS logic) & electric power mon toring (scram solenoids). * N\u00e4gara Mohawk Power Corp. 88/12/15. 10pp. 47890.062-47890.071

Q. Inspection reports, IE Bulletins & correspondence

- 6811290504 Forwards Insp Repts 50-220/88-30 & 50-410/88-29 on 880926-30.No vio-History noted. EBNETERS.D. Region 1, OIc of the Director, 88/11/18, MANGAN,C.V. Niagare Mohawk Power Corp. 2pp. 47662 238-47662.249.
- -8811290510 Insp Repts 60-220/88-30 & 50-410/88-29 on 880926-30.No violations noted Major areas inspected security plan & procedures mgl organization audits records & repts, testing & maint, barriers, security power supply & astogenics decides a tepis, lesting a maint, partiers, secontly power supply a se-sessment aids.

 TOBIN,W.J., CAMERON,D.F., KEIMIG,R.R. Region 1, Oic of the Director. 89/11/16 10pp. 47662:240-47662:249.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc Isl enct.
 CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Satety (Post 870729).
 88/11/22. Consolidated Edison Co. of New York, Inc. 98pp. 47708:255-47708.257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologcal Tests " Svc hist encl.

 ROSSI,C E. Division of Operational Events Assessment (Post 870411). 86/11/22.

 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708:142.
- 8811290030 NRC Into Notice 88-093, "Teletherapy Events." Svc list enct. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 670729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215

BOSSI, C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254

- 8612090303 Responds to NRC 880915 ltr re violations noted in Insp Repts 50:220/88-17 & 50:410/88-17.Corrective actions util hirod indepundent consultant to review QA program & deficiency documents reviewed to assure that each adequately addressed BURKHARDT,L. Nagara Mohawk Power Corp. 88/12/02 Document Control Branch (Document Control Desk). 13pp. 47761:157-47761:169
- 8912090314 Responds to violations noted in Insp. Rept. 50.410788-18. Corrective actions temporary change notice to Procedure N2-ISP-RIMC-101 issued which placed recording of required data in proper sequence. BURKHARDT, L. Niegara Moltawk Power Corp. 89/12/02. Document Control Desk). 4pp. 47785:143-47785-146.

8812020287 NRC Info Notice 88:095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors". Svc. I st encl. ROSSIC E. Division of Operational Events Assessment (Post 870411). 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807.101-47807.302

- 8812270160 Forwards Insp Repts 50-220/88-19 & 50-410/88-19 on 881004-1117 Resdecl hispectors will be closely monitoring trent in personnel errors inspectors should be informed of root cause of recirculation loop discharge valve binding. KANE.W.F. Region 1, Olc of the Director, 88/12/16 BURKHAHDT,L. Nlagara Mohawk Power Corp. 3pp. 47927.097-47927.121.
- -8812270162 Insp Repts 50:220/88-19 & 50:410/88-19 on 881004-1117. Concerns noted Major areas inspected operations action on previously identified items plant tours, safety sys walkdowns, LER reviews, Part 21 rept review & allegations JOHNSON, J.R. Region 1, Old of the Director, 88/12/15, 22pp. 47927:100-47927.121.

R. Periodic operating reports & related correspondence

- 8812190410 Monthly operating rept for Nov 1088 for Nine Mile Point Unit 2 W/881208
 - TOMLINSON,E., WILLIS,J.L. Niagara Mohawk Power Corp. 88/11/30 25pp. 47852;114-47852;138

S. Reportable occurrences, LERs & related correspondence

- 8811290547 Part 21 rept re defect in design of control circuits for Cooper Energy Svcs Div 1.8. Il emergency desail generators. Non-Category 1F components disconnected from generator start circuits Plant mod planned TERRY_C.D. Nagara Mchawk Power Corp. 88/10/05 RUSSELL,W.T. Region 1, Otc.
- of the Director, 3pp. 47802 318-47802 320
- 8811230288 Part 21 ropt re-defect in design of component mtg by Cooper Energy Svcs Initially reported on 881115 Util bocamo aware of problem on 881103.Div I emer-gency desel generator doclared Inoperable & vulve reclassified TERRY.C.D. Niagara Mohawk Power Corp. 88/11/21. RUSSELL,W.T. Region 1, Oto
 - of the Director, 3pp. 47652:063-47652:065
- 8811300497 LER 88-058-00 on 881007 APRM surveillance performed late due to programmatic deficiency Caused by personnel error. Station general order wit be issued to restrict use of Tech Spec surveillance max allowable extensions.W/881121 ltr. KINSLEY,J.R., WILLIS,J.L. Niagara Mohawk Power Corp. 88/11/21. 5pp. 47676:180-1728-18. 47676 184.
- 8812010061 Special rept on 881109,main stack & radwasto/reactor bidg vent gaseous effluent monitoring sys declared inoperable. Caused by equipment mallunction Troubleshooting of sys involved underway but equipment not yet returned
- to evc WILUS./L. Niagara Mohawk Powor Corp. 88/11/23 Document Control Branch (Document Control Dosk). 2pp. 47702.316-47702.317.
- 88 12010183 LER 88:059:00:on 88:1025;ESF actuation occurred Caused by accidental contact of heat sink plates of power source w/flox conduit Lessons learned transmittal issued to appropriate depts & warning will be emplaced W/881123 itr.
 LAGOE,LJ, WILLIS,JL. Niegara Mohawk Power Corp. 88/11/23. Spp. 47703.102-
- 88 12010199 Part 21 rept to delect in GE Type 180 Indicating type meters initially reported on 881027.NSSS.inc identified as firm supplying component.Meters will not be authorized for use in safety-related applications pending resolution BURKHARDT,L. Nlagara Mohawk Power Corp. 88/11/23. RUSSELL,W.T. Region 1, Ofc of the Offector. 3pp. 47707:146-47707:148.
- 8812060254 LER 88-060-00 on 881010,Tech Specs noncompliance due to missed surveillance on radiation monitor 2SWP*RE1468 Causad by programmatic deficiency.Monitor declared Inoperable & surveillance tests taken.W/881128 it. VOLZA,P., WILLIS,J.L. Niagara Mohawk Power Corp. 88/11/28. Spp. 47742.252-47742-256.
- 8812060234 LER 88-061-00 on 881030 facility experienced ESF actuation white reactor mode switch in shutdown Caused by equipment malfunction Work stopped on gas treatment sys & vortication that no actual high ratifation signals noted W/881129 tr. LAGOE, LJ., WILLIS, J.L. Niagara Mohawk Power Corp. 88/11/29. 5pp. 47762:189-477
- 812060318 LER 88-063-00 on 881103.facility experienced actuation of ESF, specifically, isolation signal to MSIV.Caused by procedural deficiency isolation result 8 unveillance procedure revised W/841201 lft. LAGOELJ., WILLIS, J.L. Niagara Mohawk Power Corp. 88/12/01. 6pp 47752:158-47752:163 47752.163
- 8812140243 LER 88-064-00 on 881104.Tech Spec 3 8.4.2 violated Caused by Installation desiclency by contractor Work requests issued to replace 100 amp breakers w/30 amp breakers Affected drawings will be revised W/881205 ltr. MAZZAFERRO,P. WILLIS,J. Niagara Mohawk Power Corp. 88/12/05. 5pp. 47800:352-47800:358

F. Security, medical, emergency & fire protection plans

0812090192 Advisos that 880427 Rev 4 to physical security plan consistent w/provisions of 10CFH50 54(p) & acceptable BELLAMY,R.R. Region 1, Ote of the Director 88/12/01. SIEBER,J.D. Ouquesne Light Co. 3pp. 47785 033-47785 035

- 8012090272 Forwards Revs 6 to Issue 4 to physical socurity plan Rev withheld (ref 10CFR2 700(d) & 73 21)
 SIEBER, J.D. Duquesne Light Co. 88/12/00 Document Control Branch (Document Control Dask). 2pp. 47785.001-47785.002
- 8812150006 Forwards Saloty Insp. Repts 50-334/88-28 & 50-412/88-22 on 891001-1115 & notice of violation
 WIGGINS.J.T. Region 1, Oic of the Director. 88/12/07. SIEBER J.D. Dequesne Light
 Co. 2pp. 47823.019-47823.044.
- ~8812150011 Insp. Ropis 50:334/88/28 & 50:412/88/22 on 881001-1115 Violations noted Major areas Inspected plant operations, Security, radiological controls, plant housekeeping & fire protection, maint & surveillance testing.

 TRIPPLE Region 1, Ote of the Director #8/12/06 23pp 47823.022 47823.044.

H. General correspondence

- 8812010421 Comment opposing proposed rule 10CFR26 re random drug testing provision in Filness for Duty Program Local 142 members can accopt & work under Fitness for Duty Program that contains only just cause drug testing provision SPEAKMAN,R J. International Brotherhood of Electrical Workers 88/11/28 Docketing & Services Branch Tip. 47679 291-47079 291
- 8812020030 Comment opcosing proposed rule 10CFR26 re random testing provision of Filness for Duty Program Mombers of Local 142 at plant can accept & work under Fitness for Duty Program that contains only just cause drug testing provision MINSINGER, W.J. Infarnational Brotherhood of Electrical Workers. 88/11/28. Docketing & Servicus Branch. 1p. 47680.019-47680.019
- 8812020077 Comment on proposed rule 10CFR26 to Fitness for Duty Program Local 142 members opposed to proposed random drug tosting Supports just cause drug tosting provision NOWAK,J.M. International Brotherhood of Electrical Workers. 89/11/28. Docketing & Sprvices Branch, 1p. 47880.026-47680.028.

- 8811230083 Forwards for for 881027 application for primary component support shubber elimination VASSELLOUV. Duquesne Light Co. 88/11/10. NRC - No Data and Affiliation Given 1p. 47652-032-47652-032
- 8811230291 Forwards response to NRC 880920 request for addl into to support Pro-posed License Change 15 re spent fuel pool Util intends to use neutron absorber sur-veillance program to detect degraded borallox specimens. SIEBERJUD. Duquesne Light Co. 88/11/110 Decument Control Branch (Document Control Desk). 4pp. 47652,103-47652 106.
- 8812160099 Forwards "DCRDR Second Suppl Summary Rept," per stated review,conducted to ensure satisfaction w/NUREG-0737, published by Generic Ltr 82-SIEBER.J.D. Duquesne Light Co. 88/11/15. Document Control Branch (Document Control Desk). 2pp. 47831 010-47831:244
- ~8812160113 "OCRDR Second Suppl Summary Rept,"
 * Duqueene Light Co. 88/11/15, 200pp. 47831:012-47831.244.
- 8811280048 Generic Ltr 68:20 to all Icensees holding Ots & CPs for nuclear power reactor facilities re individual plant examillor severe accident vulnerabilities Svc list CRUTCHFIELD D Associate Director for Projects (Post 870411), 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47720-024.
- 8812010021 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Matts & Impact on Plant Operations". Util currently evaluating new heatup & cooldown curves. Tochnical analysis end:
 SIEBER, Jr. Duquasne Light Co. 88/11/23, Dacument Control Branch (Document Control Desk). 29pp. 47/02/345-47703.013.
- 8812080103 Forwards environ assessment & finding of no significant impact re-880622 request to exclude all containment isolation weight. & spring-loaded check valves not subjite Type-C testing from lift test requirements of Spec 4.6.3.1. TAMP.S. Project Orectorate 1-4. 88/12/01. SIEBER.J.D. Duquesne Light Co. 2pp 47755 178-47755:183.
- --8812080107 Environ assessment & finding of no significant impact supporting amend application changing Tech Spac 4.6.3.1 whilch would exclude containment isolation spring-loaded & weight-loaded check valves from lift test requirements STOL2_J.F. Project Directorate 1.4. 88/12/01. 4pp 47755-180-47755:83.
- 8812080109 Requests that util address Generic Ltr 86-17 re loss of DHR during non-power operation accordingly.Believes that Industry did not aggressively respond to Generic Ltr 87-12 MURLEYT E Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02. VON SCHACK,W. Duquesne Ught Co. 3pp. 47754 221-47754 223
- 8812220268 Forwards Amends 133 & 9 to Licenses DPR-66 & NPF-73, respectively & safety evaluation Amends exclude all containment isolation weight & spring loaded check valves not subj to Type C testing from Tech Spec 4.6.3.1. TAMPS, Project D frectorate 1-4, 88/12/13 SIEBFR,J.D. Duquesne Light Co. 3pp 47901.093-47901.115.

DOCKETED ITEMS

R. Periodic operating reports & related correspondence

8812050254 Forwards quarterly rept of changes to procedures & plant meds described in FSAR for Third Quarter 1988. WATSCH,R.A. Carolina Power & Light Co. 88/11/28. Document Control Branch (Cocument Control Desk). 25pp. 47731 067-47731 091.

8812200117 Monthly operating rept for Nov 1989 for Harns Nuclear Power Plant Unit HALE,M.W., WATSON,R.A. Caro no Power & Light Co. 88/11/30, 5pp. 47881.653-

S. Reportable occurrences, LERs & related correspondence

- 8812010218 LER 68-031-00 on 880614-21 & 0723-26,wde tango gas monitor inoperable & componsatory actions not taken or documented as being taken as required due to personnel error Caused by feutre to install ECAX as required W/881128 to SCHWABENBAUEH, WATSON,R A Carolina Power & Light Co. 88/11/28, 4pp 47703 211 47703 214.
- 8812050217 LER 88-032-00 on 681030,manual reactor trip upon loss of main feedwater occurred Caused by trip of heater dirtin pumps attributed to plywood cover left inside Feedwater Heater 3A fcl/owing maint Prywood cover removed W/881129 ltr. JOHNSCHURE WATSON,RA Carolina Power & Light Co 68/11/29 6pp JOHNSON, J.R., WA' 47730;297-47730,302.

DOCKET 60-409 LA CROSSE BOILING WATER REACTOR

F. Security, medical, emergency & fire protection plans

- 8811290006 Forwards Physical Security Insp. Rept 50-409/88-09 on 881021-28 & 1101 No violations noted GREGERL R. Region 3, Otc of the Director, 88/11/18, TAYLOR,JW Dairyland Power Cooperative 2pp 47668.100-47668.102.
- --8811290008 Perially withheld physical security Insp Rept 50 409/68.09 on 881021-26 & 1101 (rot 10CFR2 790(d) Major areas Insp. implementation of newly approved physical security plan for SNM "possassion only" site. FUNK,DF, CREED,JR Region 3, Ofc of the Director 88/11/16, 1p. 47668.102-47688:102.
- 8812060144 Advisos that 8B1101 Rev 4 to security plan & guard training & quartication plan meets 100FR50,54[p) & acceptable. GREGERIL.P. Region 3, Ofc. of the Objector. 88/11/30, TAYLOR,J.W. Dairyland Power Cooperative 2pp 47740-324-47740.325
- 8812080150 Advises that 891115 Rev 6 to QA program consistent will provisions of 10CFR50-App B & acceptable Rev involves organization changes including fire protection responsibility now assigned to technical support organization than WRIGHT, GC. Region 3, Olic of the Director. 88/12/05 TAYLOR, J.W. Dairyland Power Cooperative 1p 47754-144-47754-144.

J. Insurance & Indemnity Information

- 8811290429 Forwards temporary exemption from 10CFR50.54(w)(5)(i) schedular requirements of property insurance rule re-insurance policies that prioritize insurance proceeds for statistization & decontamination after accident. ERICKSON,P.B. Stendardization & Non-Power Reactor Project Directorate, 88/11/18 TAYLOR,J.W. Dairyland Power Cooperative 4pp. 47665.001-47665.016.
- -8811290433 Temporary exemption from 10CFR50.54(w)(5)(i) re-increase in amount of onsite property damage insurance required by power reactor (consees & insurance that priorities insurance proceeds for stabilitation & decontamination after accident. HOLAHANGAM Division of Reactor Projects (III.V.V & Special Projects (Post 670411), 88/11/10 Dairyland Power Cooperativa 4pp. 47665 005-47665:015

P. Operating license stage documents & correspondence

- 8911280049 Generic Ltr 98-20 to all ficensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc fist
 - CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47726:303-47729.024.
- 8812080150 Advises that 881115 Rev 8 to QA program consistent w/ provisions of 10CFR50,App 8 & acceptable Rev Involves organization changes,including fire protection responsibility new assigned to technical support orgineer. WRIGHT,G.C. Region 3, Ofc of the Director. 88/12/05. TAYLOR,J.W. Deiryland Power Cooperative. 1p. 47754:144-47754:144.
- 8812140162 Responds to Generic Ltr 88-14, "Instrument At Supply Problems Atlacting Safety-Related Equipment," Emergency procedures for loss of control air revised in Feb 1988 to rattact current status of plaint. TAYLORJ.W. Dairyland Power Cooperative 88/12/06. Document Control Branch (Document Control Desk), 2pp. 47800:158-47800:159.

Q. Inspection reports, IE Bulistins & correspondence

Forwards Physical Security Insp Rept 50-409/88-09 on 881021-26 &

olations noted. "R. Region 3, Ofci of the Director. 88/11/18. TAYLOR,J.W. Dairyland nerstive, 2pp. 47688:100-47658:102.

ithheld physical security Insp Rept 50-409/88-09 on 881021-26 30(d).Major arces Insp. implementation of newly approved physi-ith "possession only" site. R. Region 3, Oto of the Okector, 88/11/16 lp. 47668.102-

- 8811160211 NRC Into Notice 88:090, "Unauthorized Removal of Industrial Nuclear Gauges "Svc list encl CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 879726) 88/11/22, Consolidated Edison Co. of New York, Inc. 99pp. 47708:255 47708:257
- 8811160467 NRC Into Notice 88-091, "Improper Administration & Control of Psychologcal Tosts." Svc list enci ROSSICE: Division of Operational Events Assessment (Post 870411). 88/11/22 Consolidated Ediscri Co. of New York, Inc. 101pp. 47708 042-47708.142.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events" Svc list oncl. CUNNINGHAM, R.E. Ovision of Industrial & Medical Nuclear Salety (Post 87072s) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp 47811.103-47811.215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc 1st ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708-143-47708-254
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements imposed by Licensees on Vendors" Svc 1st encl FIOSSICE: Division of Operational Events Assessment (Post 870411) 89/12/C8 Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807.302

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8811290504 Forwards Insp Repts 50:220/88:30 & 50:410/88:29 on 880926:30 No vio-IBTORS FORD EBNETERS D. Region 1, Old of the Director 88/11/18, MANGAN.C.V. Phagara Mohawk Power Corp. 2pp. 47662 236 47662 249
- -8811290510 Insp Repts 50-220/88-30 & 50-410/88-29 on 880926-30 No violators noted Major areas inspected security plan & procedures mgt organization audits, records & repts, testing & maint, barners, security power supply & assessmort aids TOBIN,W J. Region 1, Old of the Director, 88/11/16, 10pp. 47662 240-47662 249
- 8812090292 Advisos that 890524 Rev 5 to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable.
 BELLAMY.R.P. Region 1, Oic of the Director, 88/11/29 MANGAN,C.V Negata Mohawk Power Corp. 4pp. 47784:346-47784:349.

P. Operating license stage documents & correspondence

- 8811280048 Generic Lir 86:20 to all I censeus holding OLs & CPs for nuclear power reactor fectures re individual plant exam for severe accident vulnerabilities Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consordated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 8812020298 Provides summary of results of technical analyses in response to Generic Lit 88.11.dtd 880712.Prossure/temp limits need to be updated & schedule proposed for updating Tech Specs.
 TERRY,C.D. Niagara Mohawk Power Corp. 88/11/28. Document Centrol Branch (Document Control Desk), 3pp. 47718 263-47718 265
- 8812210332 Forwards application for amend to Liconse NPF-69.Amend revises Tech Spec Sections 4.8.4.4.8.4.8.4.5 re reactor protection sys (RPS) electric power montoring (RPS logic) & (scram solencids), respectively Fee paid.

 TERRYC.D. Niagara Mohawk Power Copp. 68/12/15. Document Control Branch (Document Control Dosk) 1p. 47890.059.47890.071
- --8812210335 Application for amend to Licenso NPF-89, changing Tech Specs to roy-so surveillence frequency for performance of channel functional tests on reactor protection eys electrical protection assemblies
 TERRY, C.D. Naggra Monawk Power Corp. 88/12/15, 2pp. 47890:060-47890.061.
- -8812210336 Proposed Tech Specs re-reactor protection sys electric power monitoring (RPS logic) & electric power monitoring (scram solenoids).
 Niagara Mohawk Power Corp. 8B/12/15, 10pp. 47890:062-47890:071.

Q. inspection reports, IE Bulletins & correspondence

- 8811290504 Forwards Insp Repts 50-220/88-30 & 50-410/88-29 on 880926-30.No vio-History noted:
 EBNETER,S.D. Region 1, Otc. of the Director, 88/11/18, MANGAN,C.V. Niagara
 Mohawk Power Corp. 2pp. 47662 238-47862:249.
- -8811290510 Insp Repts 50-220/88-30 & 50-410/88-29 on 880926-30.No violations noted Major procedures,mgt noted Major areas inspected security plan & procedures mgt organization, audits, records & repts, testing & maint, barriers, security power supply & assessment aids.
 TOBIN.W.J., CAMERON.D.F., KEIMIG.R.R. Region 1, Old of the Director 88/11/16.
 10pp. 47662 240-47662:249.
- 8811160211 NRC Info Notice 88:090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list encil CUNNNGHAM, RE. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 98pp. 47708:255-47708:257.
- 8811160467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Tests" Svc list encl.

 ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/11/22.

 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708:142.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc list enct. CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Safety (Post 870729)-88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.

- 8811290538 NRC Info Notice 88:094, "Potentially Undersized Valve Actuators." Svc list
 - enct. ROSSLCE Division of Operational Events Assossment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143:47708 254
- 6612090303 Responds to NRC 660915 ltr re violations noted in Insp Repts 50 220/88-17 & 50-410/88-17 Corrective actions util hired independent consultant to review OA Program & dahic ency documents reviewed to assure that ruch adequately addressed BURKHARDT, L. N'agara Mahawk Power Corp. 88/12/02. Document Control Branch (Document Control Dask). 13pp. 47761:157-47761-169.
- 8812090314 Responds to violations noted in Insp. Rept. 50-410/88-18. Corrective actions:temporary change notice to Procedure N2-ISP-RMC-101 Issued which placed recording of required data in propor sequence. BURKHARDT, L. Niagara Mohawk Power Corp. 88/12/02. Document Control Branch (Document Control Desk). 47785;143-47785;146.

- 8812020287 NRC Info Notice 80:005, "Inadequate Procurement Regulaments Imposed by Licensees on Vendors" Svc list end!
 ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/08.
 Consolidated Edison Co. of New York, Inc. 112pp. 47897.191-47897.392
- 8812270160 Forwards Insp Repts 50-220/68-10 & 50-410/68-19 on 861004-1117 fless-dent inspectors will be closely monitoring trend in personnal arrors inspectors should be informed of root cause of recirculation loop discharge valve binding KANEWF. Region 1, Otc of the Director. 86/12/16 GURKHARDT, C. Niagare Mehawk Power Corp. 3pp. 47927.097-47927:121
- -8812270162 Insp. Repts 50-220768-19 & 50-410768-19 on 881004-1117. Concurns noted Major areas Inspected operations action on proviously identified items.plant lours.selets system Moderns, LER reviews.Part 21 rept review & altegations JOHNSON,J.R. Region 1, Oto of the Director 88/12/15 22pp. 47927:100-47927:121

R. Periodic operating reports & related correspondence

- 8812190410 Monthly operating rept for Nov 1988 for Nine Mile Point Unit 2 W/881208 tr. TOMLINSON,E. WILLIS,J.L. Niagara Mohawk Power Corp. 86/11/30 25pp. 47852;114-47852.138
- S. Reportable occurrences, LERs & related correspondence
- 8811290547 Part 21 ropt re-dotect in design of control circuits for Cooper Energy Svcs Drv I & II emergency diesol generators. Non Category 1E, components disconnected from generator start circuis-Plant mod plannous. TERRYCO, Negagar Mohawk Power Corp. 88/10/05. RUSSELL,Wit. Region 1, Otc. of the Director. 3pp. 47802/318-47802/320.

- 8811230288 Part 21 rept re dutect in dosign of component mig by Cooper Energy Sycs Initially reported on 881115. Util bincamo aware of problem on 881103 D.v. I emergancy diesel generate doctared insperable & valve reclassified.

 1EHHY.C.D., Niagara Mohawk Power Corp. 68/11/21. RUSSELL,W.T. Region 1, Ofc of the Director. 3pp. 47652 663-47652 065
- 6811300497 LER 86-058-00 on 881007,APRM surveillance performed tate due to pro-grammable deficiency.Caused by personnel criar. Station general article will be issued to restrict use of Tech Spee surveillance max allowable extensions Wid81121 th KINSLEY.J.R., WILLIS.J.L. Niagera Mohawk Power Corp. 88/11/21. 5pp. 47678 180-4747618. 47676:164
- 8812010064 Special reption 881109 main stack & radwaste/reactor bidg vent gaseous effluent monitoring sys declared inoperable Caused by equipment maltanetion. Troubleshooting of sys involved underway but equipment not yet returned

WILLIS.J.L. Niagara Mohawk Power Corp. 88/11/23. Document Control Branch (Document Control Desk). 2pp. 47702:316-47702:317

- 8812010183 LER 88-059-00 on 881025,ESF actuation occurred Caused by accidental contact of heat sink plates of power source w/ffex conduit Lessons fearned transmitter issued to appropriate dopts & warning will be amplaced.W/881123 ltr.
 LAGOEL J., WILLIS,J.L. Niagara Mohawk Power Corp. 88/11/23, 5pp. 47703:102-47703.108.
- 8812010199 Part 21 reptire defact in GE Type 160 indicating type meters Initially reported on 881027.NSSS.Inc Identified as firm supplying component Meters will not be authorized for use in safety-folated applications panding resolution.

 BURKITARDT,L. Nilagers Mohawk Power Corp 88/11/23. RUSSELL,W.T. Region 1, Ofc of the Director. 3pp. 47707:146.47707.148.
- 8612060254 LER 88-080-00 on 881010.Tech Specs noncompliance due to missed surveillance on radiation monitor 2SWP*RE1468 Caused by programmatic deficiency Monitor declared Inoperable & surveillance tests taken W/881128 lit. VOLZAP WILLIS.J.L. Niagara Mohawk Power Corp. 88/11/28. 5pp. 47742 252-
- 6812060234 LER 68 061-00 on 881030 facility experienced ESF actuation while reactor mode switch in shutdown Caused by equipment malfunction Work stopped on gas treatment sys & verification that no actual high radiation signals noted.W/881129 ltr. LAGOELJ. WILLIS,JL. Niagara Mohawk Power Corp. 68/11/29, 5pp. 47752:189-
- 812060318 LER 86.063.00.on 881103,fac.hty experienced actuation of ESF, specifically,isolation signal to MSIV Caused by procedural deliciency,isolation reset & surveillance procedure revised W/8812011tr LAGOE, L.J., WILLIS, J.L. Nagara Mohawk Power Corp 88/12/01. 6pp. 47752.158-RR 12080318 47752.163
- 8812140243 LER 88-064-00 on 881104,Tech Spec 3.6.4.2 violated Caused by Installation deficiency by contractor.Work requests issued to replace 100 amp breakers w/30 amp breakers Atlected drawings will be revised W/881205 ltr.
 MAZZAFERRO.P., WILLIS,J.L. Niagara Mohawk Power Corp. 88/12/05. 5pp 47800.352-47800.356.

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8812090192 Advisos that 893427 Rev 4 to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable BELLAMY,R R. Region 1, Otc of the Director 88/12/01 SIERER,J.O Duquesne Light Co 3pp. 47785 033-47785 035.
- 8812090272 Forwards Revs 6 to Issue 4 to physical security plan Rev. withheld (roll 10CFR2.790(d) & 73.21) SIEBERIJ.D Duquesno Light Ca. 88/12/06 Document Centrol Branch (Document Control Dask) 2pp 47/85:001-47/85 002.
- 8812150006 Forwards Safety Insp Repts 50-334/89-28 & 50-412/88-22 on 891001-1115 & rotice of violation. WIGGINSULT, Rog on 1, Old of the Director 88/12/07 SIEBERU () Duquestin Light Co. 2pp. 47823.019.47823.044.
- --8812150011 Insp. Repts 50:334/86:28 & 50:412/86:22 on 881001-1115. Violations noted Major, areas, inspected plant operations, security, radiological controls, plant housekeeping & fire protection, what is surverlance test of the ground that the TRIPP, L.E. Region 1, Otc of the Director. 88/12/06, 23pp. 47823-022-47823-044

H. General correspondence

- 8812010421 Comment opposing proposed rule 10CFR28 re random rlug testing provision in Fitness for Duty Program Local 142 members can accept 8 work unite: Fitness for Duty Program that contains only last cerso drug festing provision. SPEAKMAN,R J International Brotherhood of Electrical Workers 88/11/28. Docketing & Services Branch. 1p. 47679 291-476/9 291.
- 8812020030 Comment opposing proposed rule 10CFR28 raination testing provision of Fitness for Duty Program Members of Local 142 at plant can accept & work undur Fitness for Duty Program that contains only just cause drug testing provision MINSINGER.W.J. International Brothurhood of Electrical Workers 89/11/28 Docket-ing & Sarvices Branch. 1p. 47680.019-47680.019.
- 6812020077 Comment on proposed rule 10CFR26 to Fitness for Duty Program Local 142 members opposed to proposed random drug tosting Supports first cause drug testing provision.

 NOWAK,J.M. International Brotherhood of Electrical Workers, 88/11/28, Docksting & Servicus Branch 1p. 47680.026-47680.026

- 8811230083 Forwards (se for 681027 application for primary compenent support shutibor etimination VASSELLO.JV. Duguosne Light Co. 88/11/10. NRC - No Detailod Attiliation Given by 47852-032-47652-032.
- 8811230291 Forwards response to NRC 880920 request for addl info to support Proposed License Change 15 re spent fuel pool Util interds to use nauton absorber surverlance program to dolect degraded borallox specimens. SIEBER, J.D. Dequesne Light Co. 88/11/10. Document Control Branch (Decument Control Desk), 4pp. 47852-103-47652-106.
- 8812160099 Forwards "DCRDR Socond Suppl Summary Rept," per slated review,conducted to answer salisfaction w/NUREG-0737, published by Genuric Ltr 82-SIEBER.J.D. Duquesne Light Co. 88/11/15. Document Control Branch (Oucument Control Deak). 2pp. 47831:010 47831.244
- -8812160113 "DCRDR Second Suppl Summary Rept,"
 * Ouquesna Light Co. 88/11/15, 200pp. 47831.012-47831 244.
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities to individual plant exam for severe accident vulnerabilities Svc 1st GRUTCHFIELD,D. Associate Director for Projects (Post 670411) 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024
- 8812010021 Apsponds to Generic Lir 88-11, "NRC Position on Redigition Embrittionion) of Reactor Vessel Matte & Impact on Plant Operations." Util currently evaluating new heatup & cooldown curves Technical analysis and SIEBER, J.D. Duquesne, Ught Co. 88/11/23. Document Control Branch (Document Control Desk) 28pp. 47/02/345-47703/013
- 8812080103 Forwards environ assessment & finding of no significant Impact to 880622 request to exclude all containment Isolation weight. & spring-loaded check valves not subjite Type C tosing from lift test requirements of Spec 4.6.3.1. TAM.P.S. Project Directorate 1-4. 88/12/01. SIEBEH.J.D. Duquesno Light Co. 2pp 47755:178-47755:183
- --8812080107 Environ assessment & finding of no significant impact supporting amend application changing Tech Spec 4.6.3 I which would exclude containment isolation spring-loaded & weight-loaded check valves from lift test requirements STOLZ_J.F. Project Directorate 1-4.88/12/01. 4pp. 47755.180-47755.183
- 8812080109 Requests that util address Generic Lit 88:17 re loss of DHR during non-power operation accordingly.Believes that industry did not aggressively respond to Generic Ltr 87:12. MURLEY.T.E. Office of Nuclear Reactor Regulation, Director (Post 670411). 8R/12/ 02 VON SCHACK,W. Duquesne Light Co. 3pp. 47754:221-47754.223
- 8812220288 Forwards Amends 133 & 9 to Licenses DPR-66 & NPF-73, respectively & safety evaluation.Amends exclude all containment isolation weight & spring loaded check valves not subj to Type C testing from Tech Spec 4 6 3 1 TAM,P.S. Project Directorate I-4, 88/12/13 SIEBER,J D Duquesne Light Co 3pp 47901:093-47901:115.

- -8812220272 Amends 133 & 9 to Licenses DPR-66 & ft/PF-73,respectively, excluding all contaminent isolation weight & spring loaded check valves not subjite Type Cillesting from Tech Special 5-8-1, requirements. SYO_ZJ, PF. Project Directoratif-4, 88/12/13, 15pp. 47901-098-47901-110
- --8612220273 Safety evaluation supporting Amends 133 & 9 to titlenses DPH-66 & NPF-73,respectively
 * Office of Nuclear Reactor Regulation, Oirector (Post 870411) 88/12/13, 2pp 47901 111-47901:113
- ~8812220278 Notice of issuance of Amends 133 & 9 to ticenses DPR-56 & NPF-73,respectively,Amends exclude all confarment isolation weight & spring loaded chock valves not subjite Type Citesting from Tech Specific 1 requirements TAMLPIS Project Directorate 1-4 89/12/13 2pp 47901-114-47301-115
- 8812220199 Forwards Amends 134 & 11 to Licenses DPR 66 & NPF-73, respectively & safety evalual on Amends clarify several action statements to reactor trip breakers in Table 3.3-1 of Tech Spacs TAMPS Project Directorate 14 88/12/19, SIEBERUD Duquesne Light Co. 3pp. 47892 166-47892 100.
- -9812220202 Amonds 134 & 11 to License DPR-66 & NPF-73 respectively clarifying several action statements re reactor the broakers in Table 3.3-1 of Tech Specs STOL2, JF Project Directorate 1-4, 88/12/19, 10pp, 47692.169-47892.178
- -8812220204 Safety evaluation supporting Amends 134 & 11 to Licenses DPR-66 & NPF-73 respectively
 Olince of Nuclear Reactor Regulation, Director (Post 870411) 88/12/19 2pp
 47692-179 47692-180

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 88 090, "Unauthorized Removal of Industrial Nuclear Gauges" Sic list enct.
 CUNNINGHAV,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729)
 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologycal Tests" Svc list enci ROSSIC E. Division of Operational Events Assessment (Post 870411), 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.
- 8812050045 Forwards supplemental response to NRC Bullatin 88:008, "Thormal Strosses in Piping Connected to RCS." SIGBERJJD, Duquesno Light Co. 68/11/28 Document Control Branch (Document Control Desk), 5pp. 47732:340-47732
- 8812060023 Forwards Insp Repts 50-334/68-27 & 50-412/88-21 on 881017- 21 No vio lations noted.

 BELLAMY, R.R. Hagron 1, Ofc of the Director, 89/11/28, SIEBER, J.D. Duquesne Light
 Co. 2pp. 47743:028-47743.040.
- -8812060027 Insp. Rights 50-334/88-27 & 50-412/88-21 on 881017-21.No worldions noted Major areas inspected:licensed radioactive offluent controls radiwaste & transportation & radiological environ monitoring programs. PASCIAK, W. J. DAVIDSON,B.S. KOTTAN, J. J. Region 1, Otc. of the Director, 88/11/28, 11pp, 47743-030-47743-040.
- 8911290030 NRC Info Notice 89.093, "Toletherapy Events" Svolist and CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Salaty (Post 870729), 88712702, Consolidated Edison Co. of New York, Inc. 112pp. 47811.103.47811.215
- 8811290536 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Svc Rst end ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708.254.
- 8812160006 Forwards Safety Insp Repts 50-334/88-28 & 50-412/68-22 on 881001-
 - 1115 & notice of violation
 WiGGINS, J.T. Region 1, Otc of the Director, 88/12/07, SIEBER, J.D. Duquesne Light
 Co. 2pp. 47823 019-47823.044.
- -8812150009 Notice of violation from insp on 881001-1115 Violations noted licenses corrective actions in response to insp tradings found inadequate to preclude repetition in that flaccurate into shown on conviol room status prints.

 * Region 1, City of the Director, 88/12/07, 1p. 47823 021-47823 021.
- -8812150011 Insp. Repts 50:334/88/28 & 50.412/88/22 on 881001-1115. Violations noted Major areas inspected plant operations, security,radiological controls,pta/of housekeeping & fire protection,maint & surveillance testing. TRIPP, L. E. Roglon 1, Ote of the Director, 88/12/06, 23pp. 47823:022-47823.044
- 8812020287 NRC Into Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" "Svc list end. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/08, Consolidated Edison Co. of New York, Inc. 112pp. 47807.191-47807:302.

R. Partodic operating reports & related correspondence

- 8811300509 Discharge monitoring rept for Oct 1988 for Beaver Valley Units 1 & 2.W/ DRUGA, R.J. Duquesne Light Co. 88/10/31, 21pp. 47680.262-47680:282.
- 8812140267 Monthly operating repts for Nov 1988 for Beaver Valley Units 1 & 2 W/ 881207 lir. WINGER, SIEBER, J.D. Duquesna Light Co. 88/11/30, 11pp. 47812.069-47812.079.

S. Reportable occurrences, LERs & related correspondence

8812010197 Part 21 Rept 88-018-00 re binding problems w/Telemecanique Gould MCC A821 & A822 knostarters.Initiatly reported on 881123 Etavan Intestarters speaked & remaining linestarters with be inepocted during first refueling outage. NOONAN,T.P. Duquesne Light Co. 89/11/28. Document Control Branch (Document Control Desk). 4pp. 47709 245-47709 249.

- 8812950300 LER 88 017-00 on 681005 bench-board position indication rights for PORT showed dual indication Caused by degraded witing & gaskets Gaskets replaced w/--proved model PORVs returned to operable status W/881201 ltr
 NOONAN_T.P. Duquesne Light Co. 88/12/01 7pp. 47740.243-47740.249
- 8812200194 LER 88-016-09 on 881115 inadvariant actuation of chemical injection 5 at 2 occurred Caused by operator error Chemical injection pump immediately shutdows 8 incensed operator involved counseled W/881215 it. HOCNAN, 7.P. Duquesne Light Co. 88/12/15, 5pp. 47862-140-47862-144.

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812090029 Forwards public version of Rev 28 to "Chais Mgt Plan" W/ DH Gimsley unfalled felease memo TUCKER,H B. Duke Power Co. 88/11/22 Document Control Branch (Document Con-trol Dusk). 4pp. 47/57.171-47757.215
- --8812090034 Public version of Rev 28 to "Crisis Mgt Plan for Nuclear Stations" Duke Power Co. 88/12/01, 41pp. 47757;175-47757,215.

H. General correspondence

8812090335 Confirms meeting w/util on 881209 at Region II ofcire reorganization.per 881121 18:con ERNST M L. Region 2, Ofc of the Director 88/12/01. TUCKER,H B. Duke Power Cc Ip 47782:231-47782:231.

- 8812020039 Forwards response to request for addl into re-direct generation response Spectra per 88/104 III
 TUCKER,H B Duke Power Co. 88/11/21. Document Central Branch (Document Cr. trol Dosk), 22pp. 47717.219-47717:240.
- 8811280048 Generic Ltr 88:20 to all licensees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnarabilities Svc list CRUICHFIELD,D. Associate Director for Projects (Post 8704+1) 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728-303-47729.024.
- 8812010223 Notification of 881205 meeting w/util in Rockvite.MD to discuss in Litred generation response spectra & snubbor reduction program for Units 1 & 2 Agenda enct. JABBOUR,K.N. Project Oirectorate #/3 88/11/28. MATTHEWS,D.B. Project Oirectorate #/3. 4pp. 47703/019-47703;022.
- 8812020028 Responds to Generic Ltr 88.11, "NRC Position on Radiation Embrittlement of Reactor Vessel Matis & Impact on Plant Operations." Changes to heatup & cool down 1mils needed for conservative operation up to 10 EFPY,por Reg Guida 1.99 TUCKER,HB Duke Power Co. 88/11/28. Document Control Branch (Document Control Desk). 2pp. 47711:136-47711:137.
- 88 12070025 Application for amends to Licenses NPF-35,NPF-52,NPF-9 & NPF-17,clarifying Tech Spec 6 2.3 re safety raviow group Fee paid TUCKER,HB Duke Power Co. 88/11/28. Document Control Branch (Document Control Dest) 11pp. 47746.050-47746.066.
- 8812070027 Proposed Tech Spec 6.2 3 re safety roview group.
 Duke Power Co. 88/11/28 Spp. 47746:061-47746:066
- 8812050076 Informs that NRC statt plans to provide guidance on snutibers by issuance of approved Tech Specs in fatter part of 1989. NRC positions on several matters including proposed Changes 3 & 4 with be addressed.

 MATTHEWS.D.B. Project Directorate II-3. 88/11/29. TUCKER,H.B. Duke Power Co 3pp. 47731:214-47731:216.
- 8812050126 Submits addit clanfication for 880526 response to Generic Ltr 88-03 for plant TUCKER.H.B. Duke Power Co. 88/11/28. Document Control Brench (Document Control Desk). 2pp. 47732:291-47732:292.
- 8812050066 Advises that util 880526 & 1129 responses to Generic Ltr 88-09, "Steam Binding of Auxiliary Feedwater Pumps," satisfactory. JASBOUR,KIN. Project Directorate II:3. 88/12/02 TUCKER,H.B. Duke Power Co. 3pp 47731:217-47731:219.
- 8812080080 Requests that util address Generic Ltr 88-17 re loss of DHR during non-power operation/Issue of high priority & shou'd be addressed accordingly. MURIEV.T.E. Office of Nuclear Reactor Republion, Director (Post 870411) 88/12/ 02. LEE,W S Duke Power Co. 6pp. 47753:128-47753:133.
- 8812140227 Application for amends to Licenses NPF-35 & NPF-52, revising Surveillance Requirement 4.7.1.2.1a.4 to apply to CA discharge flow path & substitute facility specific wording in place of STS wording.
 TUCKER-H.B. Duke Power Co. 89/12/05. Document Control Branch (Document Control Desk). 2pp. 47813.322-47813:330.
- -8812140228 Proposed Tech Specs, clarifying intent of Surveillance Requirement 4.7.1.2.18 4. * Duke Power Co. 88/12/05, 7pp. 47813:324-47813:330.

- 8812120012 Forwards "Emergency Dose Assessment Manual" TUCKER,H.B. Duke Power Co. 88/12/07. Document Control Branch (Document Control Desk). 3pp. 47780.219-47781:120.
- ~8812120014 "Duke Power Co Emergency Dose Assessment Manual." TUCKER,H.B. Duke Power Co. 88/11/21, 259pp. 47780:222-47781:120.

Slate procedure enct TUCKER,I/ B. Duke Power Co. 88/12/07. Occument Control Branch (Document Control Desk). 2pp. 4/8/3/224-4/8/3/225

- 8312160069 Summary of 831205 meeting wi/uni & JD Stovenson & Assoc to direct general on response spectra & shubber reduction program Unit committed to provide listed into a sussed consistent wischaut/d for shubber removal.W/attendance list UABSOLR K.N. Project Circotorato 14.3, 88/12/13 Project Directorato 14.3 /pp 47832 338 47832 344
- 8912270307 Adwises that author will respond to NRC 881018 reguest for additinitoring performance tosting of reflet & safety valves prior to 890224 Response delayed in order to obtain necessary vendor into TUCKERPLB Duke Power Co. 88712713. Cosument Control Branch (Document Control Dest). 1p. 47025-304-47925-304.

Q. Inspection reports, IE Bulletins & correspondence

- 6811290036 Forwards Insp Repts 50:413/86:34 & 50 414/88:34 on 080926- 1025 &
 - notice of vo²ation BROWNLEE,Y L. Region 2, Old of the Director 88731716, TUCKER H.B. Duke Power Co. 2pp. 47667 030-47667 050
- ~8611290043 Notice of violation from inspiror 880026-1025 Violations noted two Instru ment & electrical technicians working w/o procedures & Procedures AP-0-A-5500-34 & CVP 2-29 (nadequate PROWNLEE, V.L. Region 2, Orc of the Director, BB/11/16, 3pp, 47667-032-47667-034.
- ~8811290049 Insp Repts 50:413/88:34 & 50:414/88:34 on 880926:1025 Violations noted Major areas inspected plant operations, surveillance observation,maint observa-tion & review of Iconsection overticipts ORDERS,W.T., LESSER,M.S., PEEBLES,T.A. Region 2, Orci of the Director, 58/11/15 16pp, 47867 035-47667 050.
- 8811280216 Ack receipt of 881028 ftr informing NRC of stops taken to correct violations dused in Irisp Regis 50 413788-27 & 59-414788-27 ERNST, M.L., Region 2, Otc of the Director, 88711718, TUCKER,H.B., Duke Power Co. Tp. 47655 342-47655 342
- 8811290264 Provides community re NRC SALP Ropts 50:413788:24, 50:414788:24,50:359788:21, 8:50:370788:21, TUCKERJHB Duke Power Cu 88/11/21 Document Central Basis, 2pp 47650:033-47650:034
- 6811160211 NRC Info Notice 66-090, "Unnuthorized Removal of Industrial Nuclear Gauges" Svc list end CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870/28) 89/11/22 Consolidated Edison Co. of New York, Inc. 99pp 47/08/255-47708/257.
- 8811180467 NRC Info Notice 89.091, "Improper Aifministration & Centrol of Psychological Tests," Sychistenci ROSS/CE: Disson of Operational Events Assessment (Post 870411) 88711/22 Consciliated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142
- 8612050032 Responds to NRC 881024 ltr re violations noted in Inap Repts 59 413/88 07 & 50-414/88-07 Corrective action resistance temp (letectors replaced & qualified
 - Termination Sept Installed Fee paid TUCKER H B. Duke Power Co. 88/11/23 Document Control Branch (Document Control Desk). 7pp 47732 052-47732 058
- 8812050072 Advises that use of ASME Code Cases N-401,N-416,N-426 & N-427 in in-ECTVICE INSP program approved per 880302 request
 MATTHEWS,D.B. Project Directorate II-3 88/12/01. TUCKER,H.B. Duke Power Co.
 7pp. 47734:020-47734.028
- 8812120118 Provides action status update re NRC Bullotin 88-004, "Potential Safety Related Pump Loss: Migs contacted re-anticipated response time after 890601. TUCKER,H.B. Duke Power Co. 88/12/01 Document Control Branch (Document Control Desk). 2pp. 47791.339 47791.346
- 8811290030 NRC Info Notice 88-093, "Teletherepy Events." Svc list encl CUNN NGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp 47811.103-47811:215
- 6811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc tist ROSSI,C E Division of Operational Evunts Assussment (Post 870411) 88/12/02 Consol dated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812120274 Ack recept of payment for civil panalty imposed by NRC on 881024 in amount of \$50,000.

 LIEBERMAN,J. Ofc of Enforcement (Post 870413) 88712706 TUCKER,H.B. Duke Power Co. 1p. 47789 203-47789 203.
- 8812190110 Ack receipt of 881116 lit informing NHC of steps taken to correct violations noted in Insp.Repts 50.414788.33 & 50.414788.33. EROWNLEE.V.L. Region 2, Olic of the Director 88/12/07, TUCKER,H.B. Duke Power Co. 1p. 47849.158-47849.158
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" Svc list encl. ROSSI,CE. Division of Operational Evonts Assessment (Post 870411). 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302
- 8812200269 Forwards Insp Repts 50-413/69-35 & 50-414/88-35 on 881026-1125 &
 - unacovado nomenos insplitiepts 50-413/68-35 & 50-414/68-35 on 881026- 1125 & noblico of violation GROWNLEE,V.L. Region 2, Otc of the Director 88/12/09, TUCKER,H.B. Duke Power Co. 2pp. 47864.341-47864:353
- --0812200271 Notice of violation from insp on 881026-1126 Vigiations noted instrument & d'ectrical technicians observed using inaccurate,out of date copy of Westinghouse Technical Manual Process Instrumentation & Control CNM 1399-03-252. BROWNLEE, V.L. Region 2, Ofc of the Director, 88/12/09, 2pp. 47864:343-47864:344.

- observations, he consider no recut no event repts & following of previously identified dams ORDERS,W.T., LESSER,M.S., PEEBLES,T.A. Region 2, Ofc of the Director 88/12/09 Upp: 47864.345-47864.353
- 8812210257 Forwards summary of 881020 & 21 SALP presentation meetings. List of licensees & NRC attenders & stides used during presentation also encl. ERNST ML. Region 2, Ore of the Director. 88/12/14. TUCKER,H.B. Duke Power Co. 84pp. 47877, 162-47877.247.

R. Periodic operating reports & related correspondence

- 8812200217 Forwards monthly operating repts for Nev 1988 for Catawba Units 1 & 2 & corrected repts for Aug & Oct 1988 for Units 1 & 2,respectively. TUCKER,H.B. Duke Power Co. 88/12/15 Document Control Branch (Document Control Desk) 1p. 47861-202-47861-216
- -8812200277 Monthly operating repts for Nov 1988 for Catawba Units 1 & 2. WILLIAMS,R A. Duke Power Co. 88/11/30, 10pp. 47881:203-47881.212
- -8812200279 Monthly operating rept for Aug 1988 for Catawtia Unit 1. MEAD,J.J. Duke Power Co. 98/08/31, 2pp. 47861:213-47861,214
- -8812200283 Monthly operating rept for Oct 1988 for Catawba Unit 2 MEADJ 1 Duko Power Co. 88/10/31 2pp. 47861 215-47861.216

S. Reportable occurrences, LERs & related correspondence

- 8012010351 LER 88-023-00 on 881025, Trains A & B control room ventilation reperable Gauser by functional design delicionary of cooling water flow control valve Flow to lutio oil cooler increased by adjusting valve W/881123 ltr. TORRE J.G., TUCKER, H.B., Duka Power Co. 88/11/23, 5pp. 47702.252-47702:256.
- 8812020035 Special rept on 881025,Diosof Generator (DG) 18 invalid failure occurred Caused by left front turbo lube of sensor 11,DPT5246 vonling continuously Falled sensor replaced & mads to delete DG pneumatic trip instrumentation planned.
 TUCKER/LIB Duke Power Co. 89/11/23 Document Control Branch (Document Control Desk) 5pp 47707 149 47707 153
- 8812070023 LER 88 024-00 on 881019,add tions made to waste gas storage tank w/o Tech Spec required analysis due to migt deficiency. Change to corroct & clarify waste gas operational procedure written W/881130 ltr.
 TORRE,J.G., TUCKER,H.B. Duke Power Co. 88/11/30. 6pp. 4/749,315-47749.320.
- 8812270305 LER 89 025-00 on 881113,one auxiliary bldg ventilation systrain inoperable for greater than 7-day period contrary to Tech Spec 3.7.7 Caused by personnel errors & design deficiency.W/881215 ltr.
 TORREJ G. TUCKER

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8812090029 Forwards public version of Rev 2B to "Crisis Mgt Plan." W/ DH Grimsley undated release nigmo.
 TUCKER,H B. Duke Power Co. 88/11/22, Document Control Branch (Document Control Dosk) 4pp 47757.171-47757.215
- ~8812090034 Public version of Rev 28 to "Crists Mgt Pran for Nuclear Stations."

 * Duke Power Co. 88/12/01, 41pp. 47/57:175-47757:215

H. General correspondence

8812090335 Contirms meeting w/util on 881209 at Region II ofcire reorganization,per 881121 telcon ERNST.M.L. Region 2, Ofc of the Director, 88/12/01, TUCKER.H.B. Duke Power Co. 1p. 47782-231-47782-231.

- 8812020039 Forwards response to request for additinfo re-direct generation response
- epectra.por 881:104 tr TUCKER.H.B. Duke Power Co. 88/11/21. Document Control Branch (Document Control Deak) 22pp. 47717-218-47717:240.
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities no individual plant exam for severe accident vulnerabilities Svc Lst CRUTCHFIELD.D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729:024.
- 8812010223 Notification of 881205 meeting w/util in Rockville,MD to discuss util direct generation response spectra & snubber reduction program for Units 1 & 2 Agenda
 - JABBOUR, K.N. Project Directorate II-3, 88/11/28, MATTHEWS, D.B. Project Directorate II-3, 4pp. 47703 019 47703 022
- 8812020028 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrillement of Reactor Vessel Matts & Impact on Plant Operations." Changes to heatup & cooldown limits needed for conservative operation up to 10 EFPY,per Reg Guide 1.99. TUCKER,H B. Duke Power Co. 88/11/28. Document Control Branch (Document Control Desk). 2pp. 47/11.136-47711.137.
- 8812070025 Application for amends to Liconses NPF-35,NPF-62,NPF-9 & NPF-17,clarl-lying Tech Spac 6 2 3 re safety review group Fee paid TUCKER,II B. Duke Power Co. 88/11/28. Document Control Branch (Document Con-trol Dosk). 11pp 47746.050-47746.066.

- -8812070027 Proposed Tech Spec 6.2 3 re safety review group Duke Power Co. 86/11/28 6cp. 47746.061.47746.066
- 8812050076 Informs that NRC staff plans to provide guidance on shubbers by issuance of approved. Toch Specs in latter part of 1989 NRC positions on several matters, including proposud Changes 3.8.4 wit be addressed.
 MATTHEWS.D.B. Project Directorate III-3, 88/11/29, 7UCKER.H.B. Duke Power Co. 3pp. 47731:214-47731.216.
- 8812050125 Submits additionalism for 860526 response to Generic Ltr 88-03 for

plant TUCKER.H.B. Duke Power Co. 88/11/29 Document Control Branch (Document Control Ocean 2pp. 17732:291-47732:292

- 8812050066 Articises that util 880528 & 1129 responses to Goneric Ltr 88-09, "Steam Binding of Auril any Feedwater Pumps," estistactory. JABBCUR.K.ft. Project Oroctorate III-3, 88/12/02, TUCKER,H.B. Duke Power Co. 3pp. 477-31:217-47731:219
- 8812080080 Requests that util address Generic Lir 88-17 to loss of DHR during non-Power operation Issue of high priority & should be eithlessed accordingly MURLEY T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/02 LEE,W.S. Duke Power Co. Spp. 47753-129-47753-131
- 8812140227 Application for amonds to Licenses NPF-35 & NPF-52, revising Survolliance Registerment 4.7.1.2 ta 3 to apply to CA discharge flow path & substitute facility appoints working in place of STS working TUCKER, HB Duke Power Co. 86712/05 Document Control Branch (Document Control Desk) 2pp 47813 322-47813 330
- -- 9812140228 Proposed Tech Specs, clarifying Intent of Surveillance Requirement 4.7.1.2.1e 4. * Duko Power Co. 88/12/05 7pp 47813 324-47813 339.
- 8812120012 Forwards "Emergency Dose Assessment Manua"" TUCKER,H.B. Duka Power Co. 68/12/07. Document Control Branch (Document Control Desk), 3pp. 47780:219-47781-120.
- 8812120014 "Onke Power Col Emergency Doso Assessment Menual" TUCKER,H B. Duke Power Co. 88/11/21, 259pp. 47780 222-47781;120.
- 8812160086 Informs that removal of RTD bypass manifolds & replacement withst re-sponse thermown mounted RTDs completed for unit. Results using unit foad stoady state procedure and TUCKER.H.B. Duke Power Co. 98/12/07. Document Control Branch (Document Control Desk), 2pp. 47873.224-47873.225
- 8812160069 Summary of 881205 meeting w/uti & JD Stavanson & Assoc to direct generation response spectra & snubber roduction program.Util committed to provide listed info discussed consistent wischedule for anabor romovel.Wattendance list JABBOUR, K.N. Project Directorate III.3 88/12/13. Project Directorate III.3 7pp. 47032 338 47832 344
- 8812270307 Advises that author will respond to NRC 881018 request for addl info re performance tosting of refet & safety valves prior to 890224 Response delayed in order to obtain necessary wonder info.
 TUCKER,H.B. Duke Power Co. 88/12/13. Document Control Branch (Document Control Desk). 1p. 47925:304-47925:304.

Q. Inspection reports, IE Bulletins & correspondence

- 8811290038 Forwards Insp Ropts 50-413/68-34 & 50-414/88-34 on 880926- 1025 & notice of violation.

 BROWNLEE,V.E., Region 2, O(c of the Director, 86/11/16, TUCKER,H.B. Duke Power Co. 2pp. 47667,030-47667;050.
- --8811290043 Notice of violation from Insp on 880926 1025 Violations noted two instru-ment & efectrical technicians working wife procedures & Procedures AP-0-A-5500-34

R9/11/16, 3pp. 47667:032-47667:034.

34 on 880926-1025 Violations inco observation,maint observa-

2, Ofc of the Director, 68/11/15.

1 steps taken to correct violations

TUCKER H.B. Duke Power Co.

50-413/88-24, 60-414/88-24.50-

Control Branch (Document Con-

Removal of Industrial Nuclear

Nuclear Salety (Post 870729). 99pp. 47708:255-47708:257.

stration & Control of Psychologi-

nent (Post 870411), 88/11/22, '08:042-47708:142.

noted in Insp Repts 50-413/88beit-lour seplaced & qualified

Control Branch (Document Con-

401 N 416 N 426 & N 427 In in-TUCKER,H.B. Duke Power Co.

- 8812120118 Provides action status update re NRC Bulletin 88-004, "Potential Salety Related Pump Loss" Migs contacted no anticipated response time after 890001, TUCKER, HB Duke Power Co. 88/12/01, Document Control Branch (Document Centrol Dask), 2pp. 47791:339-47791:340
- 8811290030 NHC Into Notice 88-093, "Telethtropy Events." Size 1st oncl. CUNNINGHAM, F.E. Division of Industrial & Modical Nuclear Safety (Post 970729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811-103-47811-215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Advators," Syctal unct. ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp 47708.143-47708.254.
- 8812120274 Ack recorpt of payment for civil penalty imposed by NRC on 881824 in amount of \$50,000 LIEBERMAN,J. Ofc. of Enforcement (Post 870413), 88/12/06. TUCKER,H.B. D.:+e Power Co. 1p. 47789:203-47789.203
- 8812190110 Ack receipt of 881116 ftr informing NRC of stops taken to correct violations risted in this Repts 50-413768-33 & 50-414768-33.

 8HOWNI EE,V.L. Region 2, Ote of the Director. 88/12/07. TUCKER,H.B. Duke Power Co. 1p. 47849-158.
- 8812020287 NRC Into Hobba 88-095, 'Inadequate Procurement Requirements 'mpose' by Lleonseos on Vendors' 'Svollist and.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/09
 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812200269 Forwards Insp. Repts 50 413/88/35 & 50-414/88/35 on 881026- 1125 & notice of violation BROWNLEE, VL. Region 2, Ofc of the Director 88/12/09, TUCKER,HB. Duke Power Co. 2pp. 47884-341-47884-353
- -8812200271 Notice of violation from Inspirent 881026-1120 Violations noted instrume:

 & electrical tuchnicians observed using inaccurate,out of date copy of Westinghouse Technical Manual Process Instrumentation & Control CNM 1390-03-252. BROWNLEE, V.L. Region 2, Old of the Director, 88/12/09, 2pp. 47864.343-47864.344
- -8912200273 Insp Repts 50-413/88/35 & 50-414/88/35 on 881028-1125 Violations noted Major areas Inspected plant operations, surveillance & mail observations, licensee nonroutine event repts & followup of proviously identified dows ORDERS W.T., LESSER, M.S., PEEBLES, T.A. Region 2, Offic of the Director, 88/12/09 9pp. 47864:345-47864.353.
- 6012210257 Forwards summary of 681020 & 21 SALP presentation meetings. List of liconsecs & NRC attentions & skitos used during presentation also enci. ERNST.M.L. Region 2, Otc. of the Director. 88/12/14. TUCKER,H.B. Duke Power Co. 84pp. 1497:162-4797.247.

R. Periodic operating reports & related correspondence

- 8812200217 Forwards monthly operating repts for Nov 1988 for Catawba Units 1 & 2 & corrected repts for Aug & Oct 1988 for Units 1 & 2, respectively. TUCKER, H.B. Duke Power Co. 88/12/15. Document Control Branch (Occument Control Dosk). 1p. 47861:202-47861 216
- -8812200277 Monthly operating ropts for Nov 1988 for Catawba Units 1 & 2 WILLIAMS,R.A. Duke Power Co. 88/11/30, 10pp. 47861:203-47861:212
- -6812200263 Monthly operating rept for Oct 1888 for Catawba Un. 2. MEAD, J.J. Duke Power Co. 86/10/31, 2pp. 47861:215-47861:216.

S. Reportable occurrences, LERs & related correspondence

- 8812140268 LER 88-029-00:on 681025,both trains of containment isolation valve nieclion water sys inoperable. Train B inoperable due to being isolated from assured makeup supply for HX cleaning & Train A due to depressurizing surge chamber. W/ 881123 ltr. TORRE, J.G., TUCKER, H.B. Duke Power Co. 88/11/23, 5pp. 47814.036-47814:040.
- 8812200318 Advises of submission of LER 414/88-30 re inoperability of power range neutron flux instrumentation on 881111 Delay allows for complete evaluation TUCKER,H.B. Duke Power Co. 88/12/09. Document Control Branch (Document Control Desk). 1p. 47894-192-47894-192.

DOCKET 50-418 GRAND GULF NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811150217 Forwards Insp Rept 50-416/88-22 on 880919-23.No violations or devi-DECKER, T.A. Region 2, Old of the Director, 88/11/03, CLONINGER, T.H. System Energy Resources, Inc. 2pp. 47802/321-47802:328.
- -8811150221 Insp. Rept. 50-416/68-22 on 880919-23.No violations or deviations noted Major areas inspected emergency preparedness including emergency plan & Implementing procedures emergency facilities, Iralning & reviews/audits.

 KREH,J.L., DECKER,T.A. Region 2, Ofc of the Director. 88/10/31. 6pp. 47802 323-47802:328.
- 8812060126 Confirms 881207 enforcement conference in Region II ofc to discuss recent security event.per 681118 telcon. ERNST,M.L. Region 2, Ofc of the Discotor, 88/11/23. COTTLE,W.T. System Energy Resources, Inc. 3pp. 47741:228-47741:230.
- 8812080104 Forwards Rev 3 to updated FSAR for Grand Guif Nucloar Station UPL1. COTTLE,W.T. System Energy Resources, Inc. 88/12/01. Document Control Branch (Document Control Desk). 5pp. 47771,054-47775:089

- 8812090168 Roy 17 to Emergency Plan Procedure 10.S.01.6, "Notification of Offsite Agencies & Plant On Call Emergency Pursonnel." W7891206 ltr. HLRLEY,J. COTTON,S.R., CESARE,J.G. System Energy Resources, Inc. 88/12/06. 26pp. 47/57 216.47757:241.
- 8812220041 Forwards summary of 881207 enforcement conference re Insp Rept 50-416/88-24 & discovery of Iwo pistols introduced undetected into protected 81220041 Forwards Summary or do text entertained undefected into profested area Meeting handous also encl ERNST,M.L. Region 2, Old of the Director 88/12/16, COTTLE,W.T. System Energy Resources, Inc. 16pp. 47914-048-47914-063

I. Financial information

- 8812130295 Requests that oncl now Paragraph 2 B(7) re-sale & leaseback transaction of urdwided interest be aitfed to 891019 amend application. CLONNGER,TH. System Forety Resources, Inc. 86/12/07. Document Control Branch (Document Centrol Desk). 6pp. 47796-242-47/96/247.
- 8812200028 Provides general info,per 10CFH50.33(a)-(d) re corporation, Textron.Inc. that may purchase interest in fac.lity.per util 881019 proposed amend to Licenso NPF-29,ccr.cerring selb & feasoback transaction.Textron annual ropt encl. CLO:InGER,T.H. System Energy Resources, Inc. 88/12/14. Document Control Branch (Cncument Control Desk). 28pp. 47871:102-47871:271.
- --8812200041 "Toxtron Financial Corp. 1987 Annual Rept." DAVIS,S.J. Textron, Inc. 87/12/31, 140pp. 47871;124-47871;271.

K. Ullity Final Safety Analysis Report (FSAR) & amends

- 8812080104 Forwards Roy 3 to updated FSAR for Grand Gulf Nuclear Station Unit 1. COTTLE,W.T. System Energy Resources, Inc. 88/12/01. Document Control Branch (Occument Control Dosk). 5pp. 47771 054-47775:089.
- -8812080106 Rev 3 to updated FSAR for Grand Gulf Nuclear Station Unit 1. *System Energy Resources, Inc. 88/12/31, 1,471pp, 47771:059-47775:089

- 8811290339 Forwards Rev. 1 to current cyclo safety analysis providing Info on current fuel cycle operations & contains analyses supporting operations, procedural changes, Tach Spec changes & current fuel reload.

 COTTLE,W.T. System Energy Resources, Inc. 88/11/21, Document Control Branch (Document Control Dask), 17pp. 47649.293-47650.028.
- 8811300283 Forwards response to NRC 881108 request for addl info to Boratlux mail contained in tacks & associated Borallox monitoring program
 CESAHE,J.G. System Energy Resources, Inc. 88/11/21 Document Control Branch
 (Document Control Dosk). 5pp. 47698:018-47698 020.
- 8811290048 Generic Ltr 88-20 to all licensees inciding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnorabilities Svc 1st CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 8812010297 Forwards notice of unviron assessment & finding of no significant Impact re-Ltll 871216 & 860803 amond requests to update qualification requirements of training ctr Instructors & unit operations personnel.por 10CFR55.
 KINTNER,LL. Project Directorate II-1. 88/11/23. COTTLE,W.T. Systam Energy Resources, Inc. 2pp. 47703:315-47703:320.
- -8812010301 Environ assessment & finding of no significant impact to util 871216 & 880803 applications for amond to update qualification requirements of training ctr instructors 8 unit operators personnel per 10CFR55.

 ADENSAM,E.G. Project Directorate II-1, 88/11/23, 4pp. 47703:317-47703:320.
- 8811290438 Submits info re Tech Spec position statements,in response to 880928 meeting & 881006 & 20 tolcons. CESARE_JG. System Energy Resources, Inc. 88/11/25. Document Control Branch (Document Control Dask). 18pp. 47849:225-47849:242.
- 8811300240 Requests additinto re 880819 & 1109 requests for changes to Tech Specs 3.0 & 4.0 per Generic Ltr 87-09.
 KINTNER,L.L. Project Directorate II-1. 88/11/26. COTTLE,W T. System Energy Resources, Inc. 4pp. 47680:121-47680:124.
- 6911300416 Roquests addl into re 881027 roquest for review of criticality analysis for proposed storage of Cycle 4 fuel in spent fuel storage racks of lactifity. KINTNER,L.L. Project Directorate II-1, 88/11/25. COTTLE,W.T. System Energy Resources, Inc. 3pp. 47680;113 47680:115.
- 8812010281 Forwards notice of environ assessment & lindings of no significant impact re surveillance of emergency diesel generators for plant.per request dtd 880728 KINTNERILL. Project Directorate II-1. 88/11/28. COTTLE.W.T. System Energy Resources, Inc. 2pp. 47707.099-47707.104.
- -8812010267 Environ assessment & finding of no significant impact re-proposed amend to Tech Specs separating 24 h surveillance test of emergency diesel generators from surveillance test simulating loss of offsite power in conjuction w/ECCS. ADENSAM,E.G. Project Directorate II-1, 88/11/28, 4pp. 47707:101-47707:104.
- 8812010215 Forwards environ assessment & finding of no significant impact ro util 880701 amond request to change schedule for implementing recommendations of Reg Guide 1.97 for monitoring neutron flux in reactor following accident. KINTNER, L. Project Directionale II-1, 88/11/29. COTTLE, W.T. System Energy Resources, Inc. 3pp. 47801:126-47801:132.
- 47901:132

- 8812020008 Forwards Amend 50 to ticense NPF-29 & safety evaluation. Amend revises Toch Spec 3/4 1 3.3, "Control Red Scram Accumulators"
 KIN1NER,L L Project Directorate II-1 88/11/30. COTTLE,W.T. System Energy Resources, Inc. 3pp. 47718.024-47716.036
- -8812020009 Amond 50 to Liconse NPF-29,revising Tech Spac 3/4 1 3 3 re-control red scram accumulators ADENSAM,E.G. Project Directorate II-1, 88/11/30, 6pp. 47718 027-47718 032
- ~8812020010 Safety evaluation supporting Amend 50 to License NPF-29, revising Tech Spec 3/4.1 3.3 re-control rod scram accumulators
 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/11/30 4cp 47718 033-47718 036
- 8812050281 Forwards response to 881125 request for addl info re impact of gaps in boraflex on criticality analysis of Cycle 4 fuel to stored in facility spent fuel pool storage racks GESARE, I.G. System Energy Resources, Inc. 88/11/30 Document Control Brench (Document Control Dosk), 4pp. 47731:188-47731-189
- 8812070017 Application for amoud to Liconso NPF-20, rovising surveillance requirements for fuol handling platform to accompdate addition of new auxiliary host Fee paid. COTTLE W.T. System Energy Resources, Inc. 88/12/02 Document Control Branch (Document Control Desk). 8pp. 47746.098-47746.106
- -8812070018 Proposed Tach Specs re suive llarice requirements for fuel handling plattorm.
 * System Energy Resources, Inc. 88/12/02 1p. 47748:106-47746-106.
- 8812060313 Summary of 881116 niceting w/util to briof reviewers re-request for Tech Specichanges per Generic Ltr 87:09 KINTNER, L.L. Project Directorate II-1, 68/12/05 Project Directorate II-1, 17pp 47742:229-47742:246
- 8812070157 Forwards Amoud 51 to Liconso NPF-29 & safety ovariation. Amend de-letes OL Condition 2.C(30) to quartications of training cit instructors & changes Tech Speci to incorporate changes in unit operations personnel qualifications. KINTNER, L. Project Directorate II-1, 88/12/05. COTTLE, W.T. Systom Energy Re-sources, Inc. 2pp. 47748 311-47748 322
- --8812070160 Amord 51 to License NPF-23,dctoting Ot. Condition 2 C.(30) re qualitications of training instructors & changing Toch Specs to Incorporate changes in unit operations personnel qualifications & training requirements.

 ADENSAM,E.G. Project Directorate It-1, 89/12/05, 4pp. 47748-313-47748-316.
- ~8812070161 Safety evaluation supporting Amend 51 to Liceuse NFF 29
 * Office of Nuclear Reactin Regulation, Director (Post 670411), 88/12/05, 3pp
 47749-317-47748-319
- -8812070162 Notice of issuance of Amend 51 to Liconse NPF-29,changing License & Tech Specs to incorporate changes resulting from 870528 rev to 10CFR55. AOENSAM,E.G. Project Directorate II-1, 88/12/05, 3pp. 47748-320-47748-322.
- 8812090348 Advisos that results of analysis will be submitted w/ description & schedulo for Borattox survoulance program on 890228 CESARE J.G., CRAWFORD.M.L. Systum Energy Resources, Inc. 88/12/05. Document Control Branch (Occument Control Branch (Occument Control Dask). 2pp. 47775-359-47775:369.
- 8812180047 Discusses concours to 880828 Rev 7 to Operational OA Manual MPt-TOP-1A for facility-Based on clarification of concorns to Policios 3.4 2 & 2 5 2 QA program continues to meet requirements of 10CFRS0,App B & acceptable JULIAN,C A. Region 2, Oft of the Director. 88/12/05 COTTLE,W.T. Systom Energy Resources, Inc. 2pp. 47834-289-47834.270.
- 8812090204 Forwards response to NRC 800809 request for addlinfoire long-term containment purge critoria & marked up version of containment purge sys Tech Specs. CESARE J.G. System Energy Resources, Inc 80/12/06. Document Control Brench (Document Control Desk). 13pp. 47761:286.47761:278.
- 8812120127 Application for amond to License NPF-29, revising Tech Spec to support Cycle 4 religad for facility. Foe pad Repts re-related forwarded ANF-88-183(P) withheld. COTTLE, W.T. System Energy Resources, inc. 86/12/06. Document Control Branch (Document Control Dask). 12pp. 47787-200-47788-006.
- --8812120131 Proposed Tech Specs rev to support Cycle 4 reload for facility.
 * System Energy Resources, Inc. 88/12/06, 21pp. 47787,212-47787,232.
- --8812120138 "Grand Gulf Nuclear Station Unit 1 Cyclo 4 Roload Summary Rept."
 * System Energy Resources, Inc. 88/11/30, 31pp. 47787,233-47787;263.
- -8812120140 "Grand Gulf Nuclear Station Unit 1 Cycle 4 Proposed Startup Physics Tests."
 * System Energy Resources, Inc. 68/11/30, 3pp. 47787:264-47787.266
- --8812120145 "Grand Guff Unit 1 Cycle 4 Reload Analysis"
 REYNOLDS.R.S. GRUMMER.R.G. Advanced Nuclear Fuels Corp. (formerly Exxon Nuclear Co., Inc.). ANF-88-149. 88/11/11. 45pp. 47787-267-47787.311.
- --8812120147 "Grand Guff Unit 1 Cycle 4 Plant Transient Analysis" REYNOLDS AS Advanced Nuclear Fuels Corp. (formetty Exxon Nuclear Co., Inc.). ANF-88-150, 88/11/11, 40pp. 47787:312-47787.351.
- -8812120161 "Grand Gulf Nuclear Station Unit 1 Revised Flow Dependent Thermal Limis." NIR.L. SMITH,F.H., TEMPLE,T.L. MSU Systems Services, Inc. NESDO-83-003 R00. 88/11/07. 17pp. 47787:352-47788:006.
- 8812130145 Requests that 870706 application for amend to License NPF-29 to isolation Instrumentation be withdrawn
 CESARE,J.G. System Energy Resources, Inc. 88/12/86. Document Control Branch
 (Document Control Desk). 2pp. 47797:218-47797.219.
- 8812130226 Forwards Amond 53 to License NPF-29 & safety evaluation. Amond revises Attachment 1 to OL by extending implementation date for meeting. Reg. Gu de 1.97 iscommendations for neutron flux mon-toxing instrumentation until Aug. 1990. KINTNERFLL, Project Directorate III-1, 88/12/06. COTTLE,W.T. System Energy Resources, Inc. 3pp. 47793.079-47793.090.

- -8812130228 Amund 53 to License NPF 29 changing Attachment 1 to OL to extend implementation date for meeting Reg Guide 1.97 recommendations for neutron flux monitoring instrumentation until tough treueting outlage in Aug 1990 ADENSAME G. Project Directorato it 1.89/12/05.4pp. 47793.082-47793.085
- -8812130230 Safety evaluation supporting Amend 53 to License NPF-29
 Office of Nuclear Reactor Regulation, Director (Post 870411) 88712706 3pp
 47793 086-47793 068.
- -8812130232 Notice of issuance 8 availability of Amend 52 to Ucense NPF-29 Amend changes Attachment 1 to Ot to extend implementation date for meeting Reg Guide 1 97 recommendations for neutron flux monitoring instrumentation ADENSAM, E.G. Project Directorate III-1 88/12/06 2pp 47793 089-47793 090.
- 8812130237 Forwards Amend 52 to License MPF-29 & selety evaluation Amend revises Tech Specs re survollance test of emurgency disseligenerators KINTINER, LL Project Directorale III-1, 88/1/2/06 COTTLE, WIT System Energy Resources, Inc. 3pp. 47797-243-47797-256
- -8812130240 Amond 52 to License NPF-29,changes Toch Spocs separating 24 hisurveillance tost of emorgency dioset generators from suscellance test is mulating toss of offsite power in comprision w/ECCS actual on 5 gnal. ADENSAMLE G. Project O rectorate ill-1, 88/12/06, 5pp. 47797-246-47797-250.
- --8812130241 Satety evaluation supporting Antend 52 to License NPF-29 Proposed Tech Spec change would separate loss of offsite power test from 24 hitest * Project Directorate II-1, 88/12/06, 3pp. 47797-251-47797-253.
- -8812130242 Notice of escance of Amend 52 to License NPF-29. AOENSAM, E.G. Project Directorate II-1, 88/12/06, 3pp. 47797-254-47797-256.
- 8812130295 Requests that end new Paragraph 2.8(7) re-sale 8 feasoback transaction of undwated interest be added to 881019 amend application. CLON-NGEH,Till System Energy Resources, Inc. 86/12/07, Document Control Branch (Document Control Desk). 6pp. 47796.242-47796.247.
- 8812130213 Roquests add info re dosign supports for konspe proposed alternato DHR sys (ADHRS). Response requested by 881223 Informs of NRC plant visit on 890105-06 to assess ADHRS supports adequacy per 881205 to/con w/ull representatives KINTINER LL. Project Directorate Iii. 89/12/08. COTTLE, W T. Systom Energy Resources, Inc. 4pp. 47792:331-47792-334
- 8812190157 Forwards safety evaluation re-fuol enrichment increase. Short-term storage of Cycle 4 8x8 reload fuol essembles & 9x9 feed lest tuel essembles in spent fuel storage rachs would result in stated, heritocitive & acceptable KINTNER t. 1. Project Directorate III-1. 88/12/12 COTTLE,W.T. System Energy Resources, Inc. 2pp. 47855-046-47855-050.
- --8812190162 Safety evaluation accepting fuel enrichment increase.

 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/12 3pp 47855 048-47855:050
- 8812200198 Noticetion of 881228 meeting w/utll in Rockvillo,MD to discuss potential changes to Toch Specs KINTNER, I. 4. Project Directorate II-1, 88/12/14, ADENSAM,E.G. Project Directorate II-1, 2pp. 47869,354-47868,355.
- 8812200380 Resummts application for amond to License NPF-29 to provide add into re-Tech Spec 3.0 4,per NRC 881125 request COTTLE,W.T. System Energy Resources, Inc. 89/12/14 Document Control Branch (Document Control Desk) 114pp. 47861:314-47882-139.
- --9812200381 Proposed Tech Specs,relaining Tech Spec 3.0 4 per Genord Ltr 87-09 * System Energy Flesources, Inc 88/12/14 72pp. 47862 068-47862.139
- 8812210261 Responds to NRC 681025 regulatory effoctiveness review results COTTLE.W.T. System Energy Resources, Inc. 68/12/15 Document Control Branch (Document Control Dosk). 8pp. 47875 177-47875 184.
- 8812220232 Forwards Amend 64 to License NPF-29 & salety evaluation. Amend adds licensu condition authorizing sale & leaseback of portion of 90% ownership interest in facility by Sys Energy Resources, Inc. KINTNER.L. Project Directorate (II-1, 88/12/19, COTTLE,W.T. System Energy Resources, Inc. 3pp. 47900-315-47900-323.
- -8812220235 Amend 54 to License NPF-29,adding Lease condition authorizing sale & leaseback of portion of 90% ownership interest in facility by Sys Energy Resources.tec.
 VARGA,S.A. Diresion of Reactor Projects I/II (Post 870411), 88/12/19, 2pp. 47900-318-47900-319.
- -8812220236 Safety evaluation supporting Amend 54 to Licenso N/PF-29.
 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88712719, 4pp. 47900 320-47900.323.
- 8812220355 Advises that changes to Amend 54 to License NPF-29, authorizing sale & leaseback by Sys Energy Rospurces,hip of portion of ownership interest in facility unnecessary since amond & ovaluation did not describe potential investors. KMTNBERLI. Project Directorate II-1 88/12/20. COTFLE,W.T. System Energy Resources, (no. 4pp. 47892-252-47892-255)

Q. Inspection reports, IE Bulletins & correspondence

- 8811150217 Forwards Insp Rept 50-416/88-22 on 880919-23 No violations or deviations nated DECKERT R. Region 2, Ofc of the Director, 88/11/03, CLONINGER,T.H. System Energy Resources, Inc. 2pp. 47802-321, 47802-326,
- -8811160221 Insp. Rept. 50-416/88-22 on 880918-23 No violations or deviations noted. Major areas inspected emergency preparedness, including emergency plan & implementing procedures, emergency facities, training & reviews/audits. KREHJLL DECKER, TR. Region 2, Ofc. of the Director. 88/10/31. 8pp. 47802-323-47802-326
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc. Latidical CUNN. NGRAMAR E. Division of Industrial & Medical Nuclear Safety (Post 870729), 88711/22 Consolidated Edison Co. of New York, Inc. 93pp. 47708 255-47708 267.

- 8811(60467 NRC Into Notice 88:091, "Improper Administration & Control of Psychological Tests" Suctification of Operational Events. Assessment (Post 870411) 85/11/22 Consolidated Edison Co. of New York, Inc. 101pp 47708
- 8812060126 Confirms 881207 enfercement conference in Region II ofcital discess record security event.per 881118 rocon. ERNST.M.L. Region 2, Ofcital the Director 88/11/23 COTTLE.W.T. System Energy Resources, Inc. 3pp. 47741 228-47741, 230.
- 8811290030 NRC Info Notice 88-093, "Toletherapy Events." Svc Isl and: CUNTINGHAM,R.E. Division of Industrial & Magical Nuclear Safety (Post 870723, 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811 103-17511 215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Velvo Actuators" Svc. st. eccl. ROSSIC E. Division of Operational Events Assessment (Post 870411), 88712702 Consolidated Erison Co. of New York, Inc. 121pp, 47708
- 8812160131 Forwards Insp. Rept 50:416/88-25 on 881021-1118 No violations or disations noted. VERRELLI,D.M. Region 2, Old of the Director, 88/12/05, COTTLE,W.T. System Energy Resources, Inc. 2pp. 47834-238-47834-250.
- -8812160136 Insp. Rept. 50-416/88-25 on 881021-1118 No violations or dozistions roted Major areas inspected operational safety vertication, mark observation, surveillance observation, ESF sys walkdown & action on previous insp. Indings.
 CHRSTENSEN,H., MATHISUL, DANCE,H.C. Region 2, Oto of the Director 88/12/02 1106-47834 240-47934 250
- 8812160052 Forwards Insp Ropt 50.416/88-26 on 881114-17 & notice of violet on Ending withhold (ref 10CFR2 790(d) 8-73.21). CLINE,W.E. Region 2, Olic of the Director, 88/12/06, COTTLE,W.T. System Energy Resources, Inc. 2pp. 47869.333-47869.334.
- 8812020287 NRC Into Notice 88-985, "Inadequate Procurement Requirements Imposed by Liconseos on Vendors." Svc 1st end.
 ROSSIC E. Division of Operational Events Assessment (Post 870411) 88/12/98 Consolidated Edison Co. of New York, Inc. 112/pp. 47807-191-47807-302
- 8812220041 Forwards summary of 881207 enforcement confurence to lose fleet 59-410788-24 & discovery of two pistols introduced undetected into pretect 1 and Meeting handouts also encl. ERNIST, M.L. Region 2, Official this Director. 88/12/16 COTTLE,W.T. System Energy Resources, Inc. 16pp. 47914-048-47914:063.

R. Periodic operating reports & related correspondence

- 8812020299 Summary of changes,tests & expounded for Jan-May 1988. Attachment 1 contains brief description of evaluations performed under 10CFR50.59 that support Rev 3 to updated FSAR. CESAREUG. System Energy Resources, Inc. 88/11/29. Document Control Branch (Document Control Desk). 82pp. 47711:138-47711.223.
- 8812200231 Monthly operating rept for Nov 1988 for Grand Gulf Nuclear Station Unit 1 W/681215 ltr. EDGE,WE, DESARE,J G. System Energy Resources, Inc. 88/11/30 4pp 47868 165-47868 168

S. Reportable occurrences, LERs & related correspondence

- 8811290649 Corrected Special Rept 89:006 on 881021,inoporability of accident range rediation monitor discovered Caused by damaged cable assembly Cable assembly to placed.
 CESARE JG System Energy Resources, Inc. 89/11/04. Document Centrol Branch (Document Control Dask) 2pp. 47648 218-47648 219.
- 8B11280107 LEH 87-002-01 on 870203, spurious control room Isolation & slandby firest air unit start occurred Caused by apparent spurious trip from chlorine detoction sys. possibly triggered by radio transmission Mod will be implemented W7881125 1th BYFID.R.W., CESARE, J.G., System Energy Resources, Inc. 887/11725, 5pp. 47662 289-4760 289-4760 289-4760 289-4760 289-4760 289-4760 289-4760 289-4760 289-476
- 47662:303.

 88 12060017 LER 88-012-01 on 880015 plant tripped on APRM & several APRMs nomentarity spiked high due to electrical grounding of sys which transmitted voltage spikes. Caused by focation of grounding straps W/861130 ltr.

 DIFFFERINT,P.M. CESARE,J.G. System Energy Resources, Inc. 88/11/39 57p. 47746:133-47746:137.
- 8812090332 PNO-II-88-069 on 881129, spurious actuation of 19 out of 30 alort & not fill cation sitons occurred Protiminary Info indicated that spurious foliae activation caused by cit activation sys decommissioned later on same rtay.

 DANCE,H. Region 2, Oto of the Director, 88/11/30, 1p. 47762,069-47762,069.

V. Operator Examinations

- 8812160013 Forwards NRC Forms 396 & 398 requesting Econse renewal for EK Hall as reactor operator & CA Bottemiller & CD Stafford as senter reactor operators W/o enci-CESARE.J.G. System Energy Resources, Inc. 88/12/02. ERNST,M.L. Region 2, Crc of the Director. 2pp. 47835.146-47835.147.
 - 51 to Licanso NPF-29 & safety evaluation. Amend dequalifications of training cir instructors & changes Tech in unit operations personnel qualifications rate 11-1, 88/12/05, COTTLE,W.T. System Energy Rc-17748.322.

inse NPF-29,deleting OL Condition 2.C (30) re qualifica changing Tech Spacs to Incorporate changes in unit opins & training requirements prate II-1, 88/12/05, 4pp. 47740-313-47748-316

- ~8812070161 Safety evaluation supporting Amend 51 to License NPF-29.

 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/05, 3pp. 47748/317-47748.319.
- ~8612070162 Notice of Issuance of Amend 51 to License NPF-29,changing license & Tech Specs to incorporate changes resulting from 870526 rev to 10CFR55. ADENSAM,E.G. Project Directorate II-1, 88/12/05, 3pp. 47748:320-47748.322.

DOCKET 60-417 GRAND GULF NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

6611280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactly facilities re individual plant exam for severe accident vulnerabilities Svc list each

CRUTCHFIELD.D. Associate Director for Projects (Post 870411), 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024.

Q. Inspection reports, IE Bulletins & correspondence

- 8811180211 NRC Info Notice 88-090, "Unauthorized Romovel of Industrial Nuclear Gauges" Svc list enct.
 CUNNINGHAM,RE. Dviston of Industrial & Medical Nuclear Satety (Post 870729).
 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811180467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests" Svc list enct.
 ROSSIC E. Division of Operational Events Assessment (Post 870411). 88/11/22.
 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142
- 8811290030 NRC Info Notice 88-093, "To'otherapy Events." Svc list onci. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Into Notice 88-094, "Potentially Undersized Valve Actuators." Svc list encl. POSSIC.E. Division of Operational Events Assessment (Post 870411), 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812020287 NRC Info Notice 88:095, "Inadequato Procurement Requirements Imposed by Licenseos on Vendors." Svc list encl. ROSSI, CE Division of Operational Events Assessment (Post 870411), 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.

DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8811300298 Forwards Sateguards Insp. Repts 50-213/88-21,50-245/88-22, 50-338/88-25 & 50-423/88-21 on 881017-21-Ng violations noted BELLAMY,R.R. Region 1, Oto of the Director. 88/11/15. MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 47678.019-47678.024.
- -8811300298 Physical Security Insp. Ropts 50:213/88:21,50:245/88:22, 50:336/88:25
 8. 50:423/88:21 on 881017:21 No noncompliance noted Major areas inspected safeguards into program corporate ofcs.
 LANCASTER,W.K. Rogion 1, Otc of the Director. 88/11/15. 4pp. 47678:021-47678:024.
- 8811280068 "Millstone Nuclear Power Station Emergency Response Exercise, Nov
 - 1988."
 Northeast Nuclear Energy Co. (subs. of Northeast Utrities). 88/11/30. 395pp. 47658.052-47659.056.
- 88 12070178 Rev 13 to Emergency Plan Implementing Procedure EPIP-4304, "Emergency Response Facilities Operating Instructions." SCACE.S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 88/12/01. 35pp. 47745:288-47745:332.

H. General correspondence

8812010055 Comment supporting proposed rule 10CFR26 re fitness-for-duty program MROCZKA,EJ. Nartheast Utilities 89/11/21. CHILK,S.J. Office of the Secretary of the Commission. 9p. 47679.046-47670.054.

P. Operating license stage documents & correspondence

- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities. Svc list encl. CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consoil-dated Edison Co. of New York, Inc. 81pp. 47728.303-47728.024.
- 8812080069 Requests that util address Generic Ltr 88-17 re loss of DHR during nonpower operation. Issue of high priority & should be addressed accordingly. MURLEY.T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 02. ELLIS,W.B. Northeast Utilities, 3pp. 47767-008-47757-010.
- 8612120214 Forwards Rev 1 to "Radiological Effluent Monitoring & Offsite Dose Calculation Monual & Process Control Program." Attachment 1 provides detailed list of proposed changes for NRC approval. Fee paid. MROCZKA, E.J., SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities), MROCZKA, E.J., Northeast Utilities, 88/12/09. Document Control Branch (Document Control Deak), 11pp. 47788:120-47788:187.
- -8812120250 Rev 1 to, "Radiological Effluent Monitoring & Offsite Dose Calculation Manual & Process Control Program."

 Northoast Nuclear Energy Co. (subs. of Northeast Utilities). 89/01/31, 37pp. 47789:131-47789:187.

Q. Inspection reports, IE Bulletins & correspondence

- 8811290027 Clarifies schedule for completion of trams b.c. & d of IE Bullatin 85-003 & submission of final repts (florn f), per discussions w/NRC MROCZKA,E.J. Connecticut Yankea Atomic Power Co. 87/12/30 RUSSELL,W.T. Region 1, Ofc of the Director 5pp. 47667-198-47667-201.
- 8812010034 Advises that volumetric exam of feodwater nozzle-to-pipe welds feedwater piping welds to first support & feedwater line-to-containment periotration welds performed as required by IE Bullet. 79-13 lines summary rept expected by B80508 MROCZKA,E.J., Northeast Nuclear Energy Co. (subs. of Northeast Unitee) MROCZKA,E.J., SEARS,C.F. Northeast Utilities (89/03/21, RUSSELL,W.T. Region 1, Ote of the Director. 2pp. 47703-183-47703, 184
- 8811180354 Draft "PRA Applications Program for Inspirat Milistone, Unit 3." GREGG,R.E., WRIGHT,R.E. EG&G Idaho, Inc. (subs. of EG&G, Inc.), GREGG,R.E. Idaho National Engineering Laboratory, EGG-SSHE-8016 DRFT 88/03/31, NRC - No Detailed Affiliation Given 54pp. 47598:356-47599.048
- 6811300296 Forwards Saleguards Insp. Repts 50:213/88:21,50:245/88:22, 50:336/88:25 & 50:423/88:21 on 861017:21.No violations noted BELLAMY, R. R. Region 1, Oto of the Director, 86/11/15 MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 47678.019-47678:024.
- -8811300298 Physical Security Insp Repts 50-213/88-21,50-245/88-22, 50-336/88-25 8 50-423/88-21 on 881017-21.No noncompliance noted Major sreas inspected safeguards into program corporate ofcs LANCASTER,W.K. Region 1, Otc of the Director 88/11/15 4pp. 47678.021-47678.024
- 8811160211 NRC Into Notice 88-090, "Unauthorized Removat of Industrial Nuclear Gauges." Svc list encl CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708.255-47708:257.
- 8811160467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Tests." Svc tist encl ROSSIC E. Division of Operational Events Assessment (Post 870411). 88/11/22. Cansolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708:142
- 8812050325 Forwards list of nozzles in steam generaturs & prossurizor subjito thermal fatigue mechanisms,por util 881018 additinto re-first 10-yr inservice inspiprogram. MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utifiles). MRCOZKA,E.J. Northeast Utifiles. 88/12/01. Document Control Branch (Occument Control Desk). 4pp. 47734:153-47734:156.
- 8811290030 NRC Info Notice 88-093, "Tetotherapy Events." Svc list ericl CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870/29) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47611.103-47811:215
- 8811290538 NRC Info Notice 88-094, "Patentially Undersized Valvo Actuators." Svc list onc!. ROSSI,C E. Division of Operational Events Assessment (Post 870411) 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708-149-47708-254
- 8812120178 Provides status of implementation plan re corrective ections planned to prevent recurrence of event per Insp Rept 50 423/68-03.

 MROCZKA,E.J., ROMBERG,W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utritides, MROCZKA,E.J. Northeast Utritides, 120-1200. RUSSELL,W.T. Region 1, Oic of the Director, 2pp. 47786:214-47786 216.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svc list oncl.
 ROSSI, C.E. Division of Opporational Events Assessment (Post 870411). 88/12/08
 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807.302.
- 8912210054 Responds to NRC 880706 III re violations noted in Insp Rept 50-423/88-04.Corrective actions:Electrical Installation Spec 078 & Procedure MP-3788AH will be rovised by next refueling outlage to proporty reflect bend radius criterion MROCZKA,E.J. Northeast Muclear Energy Co. (subs. of Northeast Utitios). MROCZKA,E.J. Northeast Utitios. 88/12/08. RUSSELL,W.T. Region 1, Oic of the Orrector. 3pp. 47888-098-47888-098.
- 8812270277 Forwards Safety Insp Rept 50:423/88-18 on 880927-1110.No violations noted Util attention directed to Detail 6 of rept re post-trip cooldowns for facility which have been larger than expected BETTENHAUSENL. Region 1, Oto of the Director. 88/12/16 MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 47925:270-47825.298.
- --8812270278 Onsite Resident Insp. Rept. 50-423/88-18 on 880927-1110 No unacceptable conditions,violations or deviations Identified. Major areas inspected plant operations, previous lasp findings & traum lovets Inside containment. MCCABE,E.C. Region 1, Otc. of the Director, 88/12/15, 27pp. 47925:272-47925-298.

R. Periodic operating reports & related correspondence

8812160097 Monthly operating rept for Nov 1988 for Millstone Unit 3, W/881208 ltr. ELMS,A.L., SCACE,S.E. Northeast Utilides. SCACE,S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilides). 88/11/30. 5pp. 47873/328-47873/333.

S. Reportable occurrences, LERs & related correspondence

- 8811280150 LER 88-024-00:on 881022,manual reactor trip due to Imminent turbina trip due to low condenser vactuum Caused by environ conditions Mods to travetting screen sys trash trough to Increase debris removal capability Implemented W/881121 th. NICHOLS,B.W., SCACE,S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). SCACE,S.E. Northeast Utilities. 88/11/21. 4pp. 47652:235-47652:238.
- 8812210083 Special reption 881106 & 07, area temp monitoring data of main steam valve bidg (MSVB) not in actual area temp. Caused by procedural deficiency. Procedural guidance on MSVB ventilation will be strengthened by 890131. SCACE, S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). SCACE, S.E. Northeast Utilities. 88/12/07. Document Control Branch (Document Control Desk). 3pp. 4788-0.095-47988-0.095-47988-0.095

- 8812200133 LER 97-042 01 on 871117, infermediate range/power range surveillance not performed due to procedural inadequacy. Applicable surveillances satisfactority performed W/881215 III.
 LYONS, T., SCACE, S.E. Northeast Utilities LYONS, T. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 88/12/15. 6pp. 47860, 240, 47850, 245.
- 8812200287 LER 88 025 00 on 031117 hourly fire watch not established in Train A 4,160 volt ac switchgear room after fire detection degraded Caused by personnel error Fire protection zone roof-tie switch returned to posit as W7681216 ftr FREEMAN,P.A., SCACE,S.E. Northeast Nuclear Energy Co (subs. of Northeast Utilies). SCACE,S.E. Northeast Utilies.

DOCKET 50-424 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811280055 Confirms date of 690726 to conduct 1989 annual emergency preparendress exercise at plant. HAIPSTCN,W.G. Georgia Power Co. 86/11/16. Document Control Branch (Document Control Dosk). 1p. 47654;154:47654-154.
- 8811300571 Forwards Insp Repts 50-424/88/38 & 50-425/88/42 on 860315-19 & notice of violation COLLINS.D.M. Region 2, Okc of the Director 88/11/18 HARSTON,W.G. Georgia Power Co. 3pp. 47673.154-47673.194.
- -8811300573 Notice of violation from this on 860815-18 Violation noted; site emergency proparedness supervisor faced to subtril to plant general manager written ropt including commonts & corrective actions.

 COLLINS,D.M. Region 2, Otc of the Director, 88/11/18, 3pp. 47673.157-476/3-160
- -8811300574 Insp. Repts. 50:424/88-36 & 50:425/88-42 on 880815-19. Violations noted. Major areas inspected side & corporate emergency proparedness programs & Identification of programmatic of ferences &/or changes specific to Unit 2. CUNNINGHAM, A. L., DECKER, T. R., Region 2, Ofc. of the Director, 88/11/16, 30pp. 47673-181-47670-181-47670-181-47670-181-47670-1
- 8811230241 Forwards rovs to physical security & conlingency planiper NRC 880920 III. Revs withheld (rd 10CF R73.21 & 2.790) HAIRSTONING, Georgia Power Co. 89/11/21, Document Control Branch (Document Control Desk) 2pp. 47657:300-47657.301.
- 8811280106 Forwards Amend 13 to Licensu NPF-68 & safeguards evaluation. Amend modifies Paragraph 2 £ to require compliance w/ amended physical security plan. HOPKINSJ B. Project Directorate II:3 88/11/21. HAIRSTON,W.G. Georgia Power Co. 7pp 47654/283-47654/298.
- --8811280109 Amend 13 to License NPF-68,modifying Paragraph 2.E to require compilance w/amended physical security plan.
 MATTHEWS,D.B. Project Directorate it-3: 88/11/21, 3pp. 47654:280-47664.292
- -8811280113 Saleguards evaluation rept supporting Amend 13 to License NPF-68.
 Project Directorate It-3, 88711/21, 4pp 47654,293-47654,298.
- 8811280028 Forwards corrected changes to security plantincluding properly marked-up Pages E1-24-16-3 & Insent to Page 6-3 Encl withheld HAIRSTON,W.G. Georgia Power Co. 88/11/22 Document Control Branch (Document Control Dest). 2pp. 47701-250-47701-251
- 8911280144 Forwards revised response to violations noted in finsp Rept 50 424/88-29 Encil withheld (ref 100CFR13 21 & 2 780)
 HAIRSTON,WG Georgia Power Co. 88/11/23, Document Control Branch (Document Control Desk), 2pp. 47654-035-47654-036.
- 8812050250 Forwards Insp Repts 50-424/68-49 & 50-425/88-59 on 881017-20.No violations or deviations nated Attention trivited to identified unresolved flom HERDT.A.R. Region 2, Ofc of the Director. 89/11/25, MAIRSTON.W.G. Georgia Power Co. 2pp. 47730 267-47730 296
- --8812050255 Insp Repts 50-424/88-49 & 50-425/88-59 on 881017-20 No violations or deviations noted Major areas inspected fro protoct on & ficensee actions re implementation of plant safe shutdown gu dence provided in SRP 9 5-1. WISEMAN, G. CONLON, I. Rogen 2, Ofc of the Director. 88/11/22, 28pp. 47730-268-47730-296.
- 8812090299 Forwards FEMA offs.to exercise rept for plant on 880524. Resolution of identified items should be completed prior to nov1 full scale emergency preparedness exercise.
- Districts.

 DECKER, T.R. Region 2, Old of the Director. 88/11/25 HAIRSTON, W.G. Georgia.

 Power Co. 2p. 47752:120-47762.168.
- 8812080001 Forwards Insp Rept 50-424/88-44 on 881001-28 & notice of violation BROWNLEE,V.L. Region 2, Otc of the Director, 88/11/26, HAIRSTON,W.G. Georgie Power Co. 2pp. 47753.182-47753 200.
- -8812080009 Insp. Rept. 50.424/88.44 on 881001-28.Violations noted Major areas inspected plant operations, radiological controls, maint, survoitlance, fire protection, security, principle of the protection, security, programs & administrative controls affecting quality, ROGGE_JF., SCHEPENS, RJ., BURGER, C.W. Region 2, Otc. of the Director, 88/11/28, 15pp. 47753;186-47753;200
- 8812160141 Forward Insp. Repts. 50 424/88-47 & 50 425/88-62 on 881031-1104.No violations or deviations identified DECKERJ.T.R. Region 2, Otc. of the Director, 88/12/02 HAIRSTON,W.G. Georgia Power Co. 2pp. 47832:283-47832:295.
- -8812160144 Preoperational Insp Repts 50-424/88.47 & 50-425/88.62 on 881031-1104.No violations or drawations noted Weakness noted Major areas inspected radiation protection organization & training & external exposure control. GLOERSEN,WB., HOSEY,C.M. Region 2, Ofc of the Director. 88/12/02. https://doi.org/10.1006/10
- 8812220112 Forwards SALP Repts 50-424/88-41 & 50-425/88-53 for Oct 1987 Sept 1988-Mgt control needed to reduce problems in field Fluid sys leaks continue to be problem ERNST.M.L. Region 2, Ofe of the Director. 88/12/05, HAIRSTON,W.G. Georgia Power Co. 3pp 47800.253-47800.314.

- -8812220120 SALP Repts 50-424/88-41 & 50-425/88-53 for Oct 1987 Sept 1968 * Region 2, Oct of the Director, 88/1/2/05 | 59pp | 47903 256-47909 314
- 8812180117 Forwards revs to physical security & contingency plantievs withteld (ref 100FR73.21 & 2.790). HAIRSTON,W G. Georgia Power Co. 88/12/14 Document Control Branch (focument Control Dash). 2pp. 47852.174-47852.175

H. General correspondence

8812120059 Commont opposing proposed rule 10CFR2 re-records related to techning they level redweste geologic repository. Uni andorses EEI comments to be submitted to NRC HARSTON, W.G. Georgia Power Co. 88/12/05. CHILK, S.J. Office at the Servetary of the Commission. 2pp. 47798.087-47798.088.

K. Utility Final Safety Analysis Report (FSAR) & amends

8812010103 Amond 39 to FSAH for Vogile Unils 1 8 2 W/881123 ftr. RICE,P.D. Georgia Power Co. 88/11/30: 1,699pp. 47712 001-47716.259.

- 8811290556 Forwards proposed revs to final draft of combined Tech Specs resulting from NRC 881114-15 meetings willicunsee Meeting summary also encil Compictor of Action 23 relaction statement for Tach Spec 3.7.6 among NRC concerns BAILEY_JA Georgia Power to 88/11/18. Document Control Branch (Decument Control Desk), 118pp. 47668 032-47666.147.
- 8811280108 Forwards Amend 13 to License NPF-88 & satinguards evaluation. Amend modifies Paragraph 2 E to require compliance w/ amended physical security plan HOPKINSUB. Project Directorate N-3. 88/11/21. HAIRSTON,W.G. Georgia Point: Co-7pp. 47654:283-47664:288.
- ~8811280109 Amond 13 to Liconse NPF-68,modifying Paragraph 2 E to require compleance w/amended physical security plan.

 MATTHEWS,D.B. Project Directorate II-3, 88/11/21, 3pp. 47654 290-47654;292.
- ~8811280113 Safeguards evaluation rept aupporting Amend 13 to Licenso NPF-85 * Project Directorate II-3, 88/11/21, 4pp. 47654,293-47654,296.
- 8811290302 Informs that 881011 ftr re-plant License Condition 2.C (9) concerning a content radwastal vortilation exhaust mod reviewed. HOPKINS.UB. Project Directorate III-3. 88/11/21 HAIRSTON,W.G. Georgia Power Co. 3pp. 47605.037-47605.039.
- 8811300126 Forwards supplemental safety evaluation accepting SPDS w/commitment to complete 1000 in availability tost & submit results License Condition 2 C 7(b) closed HOPKINS,JB. Project Directorate II-3 88/11/22. HAIRSTON,W.G. Georgia Power Co 3pp. 47677:035-47677:047.
- ~8811300129 Suppremental safety evaluation concluding that commitment 8 sct-25/4 is 14 open litems concorning SPDS acceptable. Commitment to complete 1000 h availability test by 881231 acceptable.Requirements of License Condition 2 (778-) met.

 * NRC No Detailed Affiliation Given, 88/11/22, 10pp. 47877.038-47677:047.
- 8811280049 Generic Ltr 88:20 to all licensees holding OLs & CPs for nuclear power reactor facilities to Individual plant exam for severe accident vulnerab. Ites Sic list end CRUTCHFIELD.D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 8812010350 Forwards comparison of ref milductibly transition temp values cells/1315d utilizing Rog Guide 1.99,Rev 2 vs values provided in util 880902 fir.per Generic bt 68-11.

 HAIRSTON,W.G. Georgia Power Co. 88/11/28. Document Control Branch (Document Control Desk), 3pp. 47710:094-47710.096.
- 8812020285 Application for amend to Liconso NPF-68, changing Tach Specs revise in strument numbers provided for containment pressure monitoring Fee paid. HAIRSTON,W.G. Georg's Power Co. 88/11/28. Document Centrol Branch (Occurrant Control Desk), 5pp. 47930-274-47930-280.
- -3812020266 Proposeti Tech Spoc changes revising instrument numbers provided for containment pressure monitoring * Georgia Power Co. 88/11/28. 1p. 47930:280-47930:280.
- 8812020218 Forwards fifth suppl to summary rept of plant startup test program Suppl addresses remaining startup tosts incomplete as of last submittal. HAIRSTON,W.G. Georgia Power Co. 88/11/30. Document Control Branch (Occurrent Control Desk). 3pp. 47722-184-47722:186.
- 8812960181 Application for amend to Licenso NPF-424,revising 881107 amend request to Include Inadvertenity omitted Tech Spoc 3/4 3-62. HAIRSTON,W.G. Georgia Power Co. 88/12/01. Document Control Branch (Document Control Desk). 2pp. 47743:112-47743:114.
- -8812080184 Proposed Tech Specs 3/4 3-62,re-numbering Action 31 rels to Action 31a or Action 31b.

 * Georgia Power Co., 88/12/01. 1p. 47743 114-47743:114.
- 881280111 Requests that util addresse Generic Ltr 88-17 to loss of DHR during accupancy operation.
 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 68/12/02. SCHERER,R. Georgia Power Co. 2pp. 47783:247-47783:248
- 8812090153 Forwards Amend 14 to License NPF-68 Amend rovises Tech 50ec3 to clarify that RHR cold leg Injection valves may be closed in Mode 3 during check valve leak testing.

 HOPKINS_J.B. Project Directorate II-3. 88/12/05. HAIRSTON,W.G. Georg'a Pawer Co 3pp. 47782:200-47782:213.

- 8812090154 Amend 14 to Licensa NPF-68, modifying Tech Space to clerify that RHR cold leg injection valves may the closed in Mode 3 during check valve lenk tosting MATTHEWS, 0.8 Project Directorate II-3 88/12/05 Rpp. 47/82:203-47/82:210
- B812090156 Safety evaluation supporting Americh 14 to License NPF-68
 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/05 3pp 47782/211-47782/215
- 312120264 Application for amend to Ucenso NPF-68 rovising Fech Specificquirements for control room emergency filtration says 8 associated actuation instrumental or techniques of techniques associated actuation instrumental on to reflect control room configuration for two unit operation if on pair!

 HAIRSTONIW.G. Georga Power Co. 88/12/06. Document Control Branch (Document Control Desk). 2pp. 47811-216-47811.268.
- 8812120268 Proposed Tech Specs revising requirements for control room emergency filtration sys & associated actuation instrumentation to reflect control room configuration for two unit operation Fee paid.
- Georg's Power Co 88/12/06 52pp 47811 218-4/811 268
- 612210046 Application for amend to Licenso NPF-68 rovising Tech Spac 4.8.1.1.2 to raise min voltage for tests not requiring discuit breaker closure to ensure disset generator ready to load condition mat Fee path. HAIRSTON,W.G. George Power Co. 88/12/06 Document Control Branch (Occument Control Desk). 8pp. 47889-025-47889-034
- 8812210049 Proposed Tech Specs re-surveillance requirements & limiting condition for operation diesel generator voltage
 * Georgia Power Co. 88/12/06, 4pp. 47889 031-47889 034
- 8.12.30268 Forwards analysis of chemistry QC check samples MAIRSTON,W.G. Georgia Power Co. 89/12/09. Region 2, Otc of the Oxector. 3pp. 47797-097-47797-099.
- 812130296 Forwards notice of consideration of issuance of amend to License NPF-68 & proposed NSHC determination & apportunity for hearing on 881206 requisit re-relsing min voltage for tests not requiring circuit breaker closure. FIOPKINS.J.B. Project Directorate III-3 88/12/09 HAMSTON,W.G. Georgia Power Co. 3pp 47796 207-47796 218
- -8812130298 Notice of consideration of Issuance of amond to Liconso NPF-68 & proposed NSHC determination & opportunity for Froamp on 891208 request Amond changes Tech Specs to railso test min voltage of disciplinations during survoiflance HOPKINS.J.B. Project Directorate II-3, 88712709, 9pp. 47798 219-47798 218
- IB12220124 Forwards notice of consideration of Issuance of amond to License NPF-88 B proposed NSIIC determination & opportunity for hearing on 881208 request to rovise Tech Specs for control room generoey littration sys & instrumentation, HOPKINS & B Project Directorate II-3 89/12/09, HAIRSTON,W G. Georgia Power Co. 33pp. 47892:213-47892:226.
- -8812220127 Notice of consideration of issuance of amend to License NPF-68 & proposed NSHC determination & apportunity to incaring Amend revises furth Space for control room emergency filtration sys & associated actuation instrumentation HQPKINS, J.B. Project Directorate II 3 88/12/09 11pp 47892 216 4/892 226
- 3812190116 Application for amond to Licenso NPF 68, replacing Tech Spocs w/combned Unit 1 & 2 Tech Spocs Onscription & basis for change end Fee paid MARSTON, W.G. Georgia Power Co. 88/12/12. Document Control Branch (Document Control Desk). 3pp. 47835-174-47836-319.
- -8812190118 Proposed Tech Specs replacing unit Tech Specs w/combined Unit 1 & 2 Tech Specs.

 * Georg's Power Co. 88/12/12 517pp. 47835 177-47836 319
- 8612200119 Forwards updated tistings of outstanding licensing requests for plant,for NRC review & approval including Generic Ltr 83-28 items & NUREG-0737, Item ITI.0.1,1.
 - HARSTON,W.G. Georgia Powor Co. 88/12/14. Document Control Branch (Document Control Dask), 8pp. 47871:048-47871:053.
- 8912200227 Forwards radial peaking factor limit ropt for Cyclo 2 operation of plant 8 graph of elevation-dependent peaking factor vs core height figure HARSTON,W G. Georgia Power Co. 86/12/16. Document Control Branch (Document Control Dosk). 3pp. 47863.047-47863:049.
- Q. Inspection reports, IE Bulletins & correspondence
- 8812070097 Forwards response to 880324 request for addlinfo rolulii 870904 response to NRC Bulletin 85.003 Water hamnor due to valve closure not in liaity considered in determination of differential pressures performed per bulletin. MCDONALD.R.P. Georgia Power Co. 88/04/25. Decument Control Branch (Document Control Dask). 11pp. 47745;246-47745.256

47673:161-47673:194.

- 6811300571 Forwards Insp Ropts 50-424/88-38 & 59-425/88-42 on 880815-19 & notice of violation.

 COLLINS D.M. Region 2, Ofc of the Director. 88/11/18. HAIRSTON,W.G. Georgia
 Powor Co. 3pp. 47673:154-47673:194.
- -8811300573 Notice of violation from Insp. on 880815-10 Violation noted: site emergency preparedness supervisor falled to submit to plant general manager written rept including comments & corrective actions

 COLLINS,D.M. Region 2, Otc of the Director, 88/11/18, 3pp. 47673.157-47673:160.
- -8811300574 Insp Repts 50-424/88-38 & 50-425/88-42 on 880815-19. Violations noted Melor areas inspected eite & corporate omergency preparedness programs & Identification of programmatic differences &/or changes specific to Unity 2 CUNIY/NGHAM,ALL DECKER, T.R. Region 2. Oic of the Director 86/11/16
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list encl.
 CUNNINGHAM,R.E. Division of Industrial & Med.cal Nuclear Safety (Post 870729).
 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811160467 NRC Info Notice 86-091, "Improper Administration & Control of Psychological Tests," Svc list encl.

 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 8B/11/22.

 Consolidated Edison Co. of New York, Inc. 101pp. 47709:042-47708 142

- 8812080010 Forwards Insp Rept 50-424/88-45 on 881017-21.No violations or deviations noted Attention invited to unresolved item:
 HERDT,A.R. Rogion 2, Ofc. of the Director 88/11/22 HAIRSTON,W.G. Georgia
 Power Co. 2pp. 47754-029-47754-046
- --9812080012 Insp. Rept. 50.424/88.45 on 891017-21 No violations or deviations noted Major, areas, inspected inservice, insp. including review of inservice insp. program plan for outago & review of NDE procedures. NEWSOME, R.W., BLAKE, J.J. Region 2, Ofc. of the Director. 88/11/15, 16pp. 47754.031-47754.046.
- 8811280144 Forwards rovised response to violations noted in Insp. Rept. 50-424/88-29 Encl withheid (ref. 10CFR/3 21 & 2.780). HAIRSTON,W.G. Guorg a Power Co. 88/11/23. Document Control Branch (Document Control Dosk). 2pp. 47654-035-47654-035.
- 8812050250 Forwards Insp Repts 50 424/88-49 & 50 425/88 59 on 881017-20 No via lations or deviations noted Atlant on invited to identified unresolved item HERDT.A.R. Region 2, One of the Director 88/11/25 HAIRSTON W.G. Georgia Power Co. 2pp. 47730 287-47730 296
- ~8812050255 Insp Rapls 50:424/88:49 & 50:425/88:59 on 881017:20 No violations of deviations noted Major areas Inspected fire protect on & licensee actions to implementation of prant safe shutdown guidance provided in SRP 9.5-1. WISEMAN,G., CONTON,T. Ragion 2, Old of the Director 88/11/22, 2Ppp. 47730 269-
- 8812090134 Forwards Exam Repts 50-424/OL-88-02 & 50-425/OL-86-02 administered on 880919-22.

 JULIAN,C A. Region 2, Olc of the Director. 88/11/25 HAIRSTON,W.G. Georgia
 Power Co. 2pp 4/762 334-47/63 347.
- -8812090142 Exam Repts 50-124/OL-88-02 & 50-425/OL-88-02 on 890919-22. Exam rosults'all candidates passed ARILDSEN J. MUNHO, J.F. Region 2, Otc. of the Director 89/11/16, 274pp 47782-336-47763-249
- -8812090145 Forwards comments compiled by training dept re reactor operator & saner reactor operator written exams conducted at plant on 880919 BOCKHOLD,G. Georgia Power Co. 88/09/21. MUNRO,J. Region 2, Otc of the Director 90pp. 47763 250-47763 347.
- 8812080263 Forwards Insp Repts 50-424/88-40 & 50-425/88-81 on 881017-21 No violations noted: DECKER, T.N. Rogion 2, Otc of the Director 88/11/25, HAIRSTON, W.G. Georgia Power Co. 2pp. 47784 350-47784 359
- -8812090268 Insp Repts 50-424/89-46 & 50-425/88-61 on 881017-21.No violations noted Major areas inspected rad ological efficients & plant chemistry KARLE, J.B., HUGHEY, C.A., Region 2, Otc. of the Director, 88/11/25, 8pp. 47784-352-
- 8812080001 Forwards Insp Rept 50-424/88-44 on 881001-28 & notice of violation. BROWNLEE,V.L. Region 2, Otc of the Director, 88/11/28, HA/RSTON,W.G. Georgia Power Co. 2pp. 47753 182-47753.200.
- -8812080008 Notice of violation from insp on 881001-28 Violation noted improper log knoping & inadequate corrective action re-dieset generator fuel litter differential pres BROWNLEE,V.L. Region 2, Ofc of the Director, 68/11/28, 2pp. 47753.184-47753:185.
- --8812080008 Insp. Rept. 50-424/88.44 on 881001-28 Violations noted Major areas inspected plant operations, advicagled controls, maint, survoillance, the protection, security, outage, quality programs & administrative controls affecting quality. IROGGE, J.F., SCHEPENS, P.J., BURGER, C.W. Region 2, Ofc of the Director, 88/11/28, 15pp. 47753-186-47753-200.
- 8812130285 Ack receipt of 881123 ftr informing NRC of steps taken to correct violations noted in thisp Ropt 50-424/88-29 CLINE,W E. Region 2, Otc of the Director. 80/11/30 HAIRSTON,W.G. Georgia Power Co. 2pp. 47795-359
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc list cncl. CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Salety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215
- 8811290538 NRC Info Notice 88-994, "Potentially Undersized Valve Actuators " Svc list
- anct. ROSSI,C.E. Division of Operatorial Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708.254
- 8812160141 Forward Insp Repts 50-424/88-47 & 50-425/88-62 on 881031-1104.No violations or deviations identified DECKER,T.R Region 2, Otc of the Director. 88/12/02. HAIRSTON,W.G. Georgia Power Co. 2pp. 47632-263-47632-295.
- -9812160144 Preoperational Insp. Repts 50-424/88-47 & 50-425/88-62 on 881031-1104 No. violations or devaltions noted Weakness noted Major areas inspected red alton protection regarkations & training & oxternal oxpoure control GLOERSEN.W.B., HOSEY,C.M. Region 2, Olic of the Director. 88/12/02. 11pp. 47832.285-47832 295.
- 8812190006 Forwards Insp Repts 50-424/88-50 & 50-425/88-64 on 881024- 28 No violatons or devialions noted. BROWNLEE, V.L. Rogion 2, Ofc of the Director, 88/12/05, HAIRSTON,W.G. Georgia Power Co. 2pp. 47850 330-47859:341.
- --8812190009 Insp Repts 50-424/88-50 & 50-425/88-64 on 881024-28 No violations or deviations noted Major areas inspected quality concerns program (QCP),including open concerns task force review of QCP & root cause & review of concerns. DEMIRANDA,O. PATTERSON,C.A. SINKULE,M.V. Region 2, Otc of the Director. 88/ 12/02. 10pp. 47850:332-47850.341.

DOCKETED ITEMS 144

- 8812220112 Forwards SALP Repts 50-424/88-41 & 50-425/88-53 to: Oct 1987 Sept 1988 Mgt control needed to reduce problems in field. Fluid sys leaks continue to be
- ERNST,M.L. Region 2, Old of the Director, 89/12/05, HAIRSTON,W.G. Georgia Power Co 3pp 47900 253-47900 314
- -8812220120 SALP Repis 50 424/89-41 & 50-425/88-53 for Oct 1987 Sept 1988
 * Region 2, Otc of the Director, 88/12/05, 59pp, 47900 258-47900 314,
- 8812198257 Forwards Insp Repts 50-424/88 54 & 50-425/88 70 on 851114- 18 No vio
- lations of deviations holed.

 DECKER,TR Region 2, Ofci of the Cirector 88/12/06 HAIRSTON,W.G. Georgia.
 Power Co. 2pp. 47853 323-47853.334.
- -8812 190258 Irisp Ropis 50 424/88-54 & 50 425/88-70 on 891 114-18 No violations or deviations noted Major eriors inspected Core Modure 84750 risp at Unit 1 & preoporational inspect Of Unit 2 in areas of Irg. 3 & gaseous radwaste processing. SCDDART P. G. KAHLE J.B. Region 2, Otc. of the Director. 89/12/01. 10pp
- 47853:325-47853:334
- 8812090254 Responds to NRC Bulletin 88-003 requesting that inspecto performed for all GE tatching-type HFA relays in Class 1E applications Fouriering GE 12HFA54E187H relays inspected on 831108 for Unit 1 & on 880608 for Unit 2 HAIRSTON,W.G. Georg 1 Power Co. 88/12/07 Document Control Brench (Document Control Desk). 3pp. 47762-112-47762:114. 8812090261 Responds to NRC Bulletin 88 009 to thirrble tube insps. Thimble tube
- Insps parformed for prant revealing wall loss indications on 20 of 50 thimbin tubes HAIRSTON,W G. Georgia Power Co. 99/12/07. Document Central Branch (Document Control Desk.) 2pp. 47/82 093-47782 093-4 6812160108 Ferwards Insp Repts 50 424/89-51 & 50-425/88-66 on 881031-1104 & 07-
- 10.No violations or deviations noted HERDT,A.R. Region 2, Ofc. of the Erector. 88/12/07. HAIRSTON,W.G. Georgia Power Co. 2pp. 47832 307-47832 326.
- -8812160115 Insp. Repts 50:424/88:51 & 50:425/68-66 on 881031:1104 & 07:10 Weaknosses identified Major areas inspected Unit 1 IE Butotia 85:003 program & complex survaliance & Unit 2 preoporational testing procedure review.

 DESALB. SZCZEPANIECA, TINGENS. Region 2, Ofc of the Director 88/12/07. 17pp 47832.309 47832 325.
- 8812190045 Forwards Insp Repl 50-424/88-48 on 881023-28 & notice of violation CCLLINS,D M. Region 2, Ofc of the Director, 68/12/07, HAIRSTON,W.G. Georgia Power Co. 2pp. 47840.147-47840.167.
- -8812190050 Notice of violation from inspired 881023-28 Violation noted procedures not followed when and vidual performed work in containment. COLLINS,D M. Region 2, Ote of the Director. 88/12/07, 4pp. 47840:148-47840:152.
- --8812190053 insp. Rept. 50-424/88-48 on 881023-28 Violations noted Mejor areas inspected digenization & mgt. controls,travining & qualifications,external exposure control & assessment & control of radioactive metrs. SHORTRIDGE,R.B., LAUER,M.T., HOSEY,C.M. Region 2, Old of the Director, 88/12/06, 15pp. 47840-153-47840,167.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Suc 1st enct. ROSSI, CE. Division of Operational Events Assessment (Post 870411), 88/12/08. Constituted Edison Co. of New York, Inc. 11259, 47807;191-47807;302.
- 8812190249 Forwards Insp Repts 50-424/88 42 & 50-425/88-54 on 880909-12 & 1112-16 No violations or deviations noted. HERDT,A.R. Region 2, Ofc of the Director, 88/12/09 HAIRSTON,W.G. Georgia Power Co., 2pp. 47853 308 47863 317.
- ## 8812190251 Insp. Repts 50-424/88-42 & 50-425/88-54 on 880909-12 & 1112-18 No violations or deviations noted Major areas inspected Unit 2 piping thermal expansion & vibration to design & Unit 1 subber surveitlence program

 LENAHANITAL, JAPE,F. Region 2, Otc of the Creator, 88/12/08, 8pp. 47853/310-4785/310-4785/31
- 8812140289 Responds to NRC fit re-violation noted in Insp Repts 50 424/88/38 & 50-425/86-42.Corrective actions:site emergency preparedness supervisor counseled re-violation & retrained on Procedure 91602-C requirements. HAIRSTON,W.G. Georgia Power Co. 88/12/09. Cocument Control Branch (Document Control Desk). 3pp. 47812 G60-47812 062.
- 8812210059 Confirms 881219 mgt meeting w/util in 8/mingham,AL to discuss nuclear plant oversignt responsibilities leachnical support responsibilities & activities of corporate organization,per 881205 letcon relisted inspirepts. ERNST,ML. Region 2, Otc. of the Director. 88/12/13 HARSTON,W.G. Georgia Powar Co. 3pp. 47898:101-47888:103.
- 8812210249 Provides info necessary to complete util response to NRC Bulletin 88-004 re potential safety-related pump loss. MCDONALD.R.P. Georgia Power Co. 88/12/15. Document Control Branch (Occurrent Control Desk). 3pp. 47876.004-47876:006.
- 8812270217 Responds to violations noted in Insp Rept 50-424/88-44 on 881(01)-28 Coursetive actions Procedure 1185-C rovised to include comment section for noting abnormal conditions & actions lated a bloodelping requirements reamphasized. HAIRSTON.W.G. Georgia Power Co. 88/12/20. Document Control Branch (Occument Control Desk). 3pp. 47924:208-47924-210
- R. Periodic operating reports & related correspondence
- 8812209001 Morabby operating rept for Nov 1986 for Vegite Unit 1.W/ 881213 ftr DitWORTH,S.C., HAIRSTON,W.G. Georgia Power Co. 88/11/30, 7cm, 47871-995.

- S. Reportable occurrences, LERs & related correspondence
- 8811290572 LER 88-020-01 on 880629 redundant overload protection IIIC process by magnetic-only-breakers working Tach Spac 3-8-4 t requirements Caused by Most equate functional testing Thermal magnetic breakers installed W/681118 in SWARTZWELDERU, HAIRSTON.W.G. Georgia Power Co. 85/11/18 856
- SWARTZWELDER,J 47657.361-47657.360
- 8811290575 LER 88:025:01 on 880731 lightning struck containment bing caseing icast for the 8 isolation of main feedwater sys. Caused by lightning strike which icastics a electrical surge Crount board replaced W/881118 ftr 47651:201-47651:206
- 88 11290292 LER 88-016-01 on 880603, smoke from electric duct heater a tratel i smoze detection elarms. & caused water leakage into control from from ce³ regions of b_s inadequate design of control room celling Permanent seal installed W.6811221. SWARTZWELDERJ, HARRSTON,W.G. Georgie Power Co. 88/11/22 909 47665 040 47665:048.
- 8811290072 Special Rept 88:008 on 881026,diesel generator Train B did not reach Called Voltage & Inquiency within required time, por Rey Guid et al. (1738.). Called Voltage & Inquiency within required time, por Rey Guid et al. (1738.). Called E. Called Voltage Branch (1738.) Called Voltage Branch (1738.) Control Desk). 2gp. 47849.251-47649.252

8812010344 LEFR 88-031-00 on 881030,protection sys Train A trouble and uncertain ob-

- served II & input error inhibit switch on solid state protection sys fraint and included an inhibit position. Caused by inadequate procedures W/881128 lir SWART/WELDER, J. HAIRSTON,W.G. Georgia. Power Co. 68/11/26 (cp. 47707:137-47707:140).
- 88 12020115 LER 88-030-00 on 881027 discovered that plant computer dosign foal set for monitoring deviations between digital rod indication sys & demand position sys not implemented within computer software. W/801128 ftr SWARTZWELDERJ., HARRSTON W.G. Guorgia Power Co. 86/11/28. \$\$\phi\$\$ 47718 001-47719.005.
- 8812060273 LER 88-031-01 on 881030,core afterations suspended white Train Albas of offsite power test conducted blocking actuation of Train A ESF. Test procedure will be corrected W/881201 lin. SWARTZWELDER, J., HAIRSTON W.G. Georgia Power Co. 86/11/28 2; p. 47741.050-47741.051.
- 8812120133 LER 88-032-00 on 881026, values insorted into monitors, resulting in trip satpoints in excess of Tech Spec Limits. Caused by parsonnal arccident interests counseled on importance of ensuring procedural compliance Wi881265 fit SWARTZWELDERJ, HAIRSTON, W.G. Georgia Power Co. 88/12/05 app. 47/35047-47798 050. 8812140120 LER 88.033.00 on 881109.control room isolation dampers lead open Caused by personnel error Dampers placed in correct position Field shifts perch sor counseled W/881209 tit.
 SWARTZWELDERJ., HAIRSTON,W.G. Georgia Power Co 88/12/07 4pp 47802:229 47802:232.
 - 8812140062 LER 88-034-03 on 881112,RHR Train B RX intel valve found locked closed Caused by personnel error. Valve positioned to correct position & Individual's counseled to importance of proper communications & valve alignment W/891265 for SWARTZWELDER, J. HAIRSTON,W.G. Georgia Power Co 88/12/03 \$40,47802,233,47802,237.
- 8812200259 LER 88-029-00 on 881020 power supply disturbance fod to computer memory loss in refuelling machino which caused fuel bundle problems as stated Procedural & hardware changes will be impromedied.W/881214 lin SWARTZWELDER,1, HAIASTON,W.G. Georgia Power Co. 88/12/12 4pp 47864:302-47864:305.
- 8812220081 LER 88-035-00-pn 881113.control from Isolation occurred during suvol-lance testing. Cause under Investigation Static transfer switch which would have pre-vented momonlary loss of power to be installed during retuering outage W7681213 to SWARTZWELDERJ, HAIRSTON, W.G. Georgia Power Co. 88/12/16 4:pp 47903-045-47903:048.
- 8812220079 LER 88-036-00 on 881115.improper cable splice found on wring load Lora Channel 2 pressurizer pressure transmitter. Caused by improper installation during plant const-brice connection properly completed W/881215 ltr.
 SWARTZWELDERJ, HAIRSTON,W.G. Georgia Power Co. 88/12/15 4pp. 47800:198-47900.201.
- 8812200213 LER 88-037-00.on 881116,O-dings found missing from 4 CONAX T-8 ficad junction baxes Caused by O-rings not being installed during initial installation indices baxes will be sealed & maint procedures updated W7881216 ft.
 SWARTZWELDERJ, HAIRSTON,W.G. Georgia Power Co. 88/12/16 Spp 47871:319-47871:323.
- 8812200219 LEA 88-038-00.on 881116, during review of deficiency card, discovered that indicators had been giving erroneous readings since software change in Oct 1987. Caused by feiture to delect error prior to implementation. W/881216 III. SWARTZWELDER_J. HAIRSTON,W.G. Georgia Power Co. 68/12/16. 4pp. 47859:351-47859:354.
- 8812200236 LER 86-040-00 on 881121, containment ventilation isolation signal interest during Tech Spec surveillance calibra. Caused by personnel error Personnel invoved counseled re importance of compliance w/procedure 47860 284 47860 287.
- 8812200243 LER 88-039-00 on 981121, fuel handling bidg isolation occurred due to Tomentary loss of power to radiation monitor Supply & exhaust units restarted & pot: accident hitration units secured & resol. Cause unknown. W/881216 lir. SWARTZWEIDER LA HAIRSTON W.G. Georgia Payer Co. 88/12/16 426.

7. Operator Examinations

- 1812090134 Forwards Exam Ropts 50-424/OL-88-02 & 50-425/OL-88-02 administered on 800319-22
 JULIAN,C A Region 2, Oic of the Director, 88/11/25, HAIRSTON,W.G. Georgia
 Power Co. 2pp. 47762.334-47763.347.
- -8812090142 Exam Repts 50-424/OL-88-02 & 50-425/OL-88-02 on 980919-22 Exam results all candidates passed.
 ARTDSENJ, MUNROJF, Region 2, Old of the Director, 89/11/16, 274pp.
 47762:335-47763:246
- --3812090145 Forwards commonts complied by trelning dept re reactor operator & serior reactor operator written exams conducted at plant on 890919.

 BOCKHOLDG. Georgia Power Co. 88/09/21. MUNRO,J. Region 2, Otc of the Director. 89pp. 47763:250-47763:347.

DOCKET 50-425 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

- 8811290556 Forwards proposed ravs to final dreft of combined Tech Space resulting from NRC 881114-15 meetings w/ficensee Meeting summary also enci. Completion of Action 28 re-action statement for Tech Spec 3.7.6 among NRC concerns. BAILEY.J A. George Power Co. 88/11/18. Document Control Branch (Document Control Desk). 116pp. 47666-032-47668;147.
- 8811300126 Forwards supplemental safety evaluation accepting SPDS w/commitment to complete 1000 h availability tost & submit results. License Condition 2.C 7(b) closed. HOPKINS.J.B. Project Directorate II.3. 88/11/22. HAIRSTON,W.G. Georgia Power Co. 3pp. 47677.035-47677.047.
- 6811280046 Generic Ltr 68-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities. Svc list
 - CRUTCHFIELD.D. Associate Director for Projects (Post 870411), 98/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729:024.
- 8812010350 Forwards comparison of refinal-ductility transition temp values calculated Uturing Reg Guide 1.99,Rev 2 vs values provided in util 880902 ltr.per Generic Ltr 86-11. HAIRSTON,W.G. Georgia Power Co. 88/11/28. Document Control Branch (Document Control Desk). 3pp. 47710.094-47710.098.
- 8812020207 Forwards environ assessment & finding of no significant impact to exemption from 10CFR50.App J,relaxing requirement for eirfock leakage testing before entering Mode 4 each time that airlock has been opened in Modes 5 or 6. HOPKINS.JB. Project Directorate II-3. 88/11/30. HAIRSTON,W.G. Georgia Power Co. ip. 47711:015-47711.020.
- --8812020211 Environ essessment & finding of no significant impact re exemption from requirements of Paragraph III.D.2 of App J to 10CFR50.
 HATTHEWS,D.B. Project Directorate It-3, 88/11/30, 5pp 47711:016-47711:020.
- 8812050091 Forwards Rev 4 to ISI-O-010, "Preservice Insp Program Vogile Electric Generaling Plant Unit 2:" BANLEY, J.A. Georgia Power Co. 88/11/30. Document Control Branch (Document Control Desk), 1p. 47732-345-47732:345.
- -8812050093 Rev 4 to ISI-P-010, "Preservice Insp Program Vogile Electric Generaling Plant Unit 2 * Georgia Power Co. 88/11/11, 16pp. 47732:346-47732:381.
- 8812050128 Informs that seismic separation program fully implemented for Unit 2 & fer-tilization programs FP-7 & FP-14 walkdowns completed. BAILEY, J.A., Georgia Power Co. 88/11/30. Document Control Branch (Document Con-trol Desk). 1p. 47733:296-47733:296.
- \$812060026 Confirms that Preoperational Test 2-3BB-05 completed Util considers Con-Frmatory Item 28 resolved.

 8AILET J.A. Georgia Power Co. 88/11/30. Document Control Branch (Occument Control Branch (Occument Control Branch).

 100 Desk). 10. 47734-238-477378-238.
- 6812080111 Requests that util addresse Generic Lir 88-17 re loss of DHR during nonpower operation.
 MURLEY.T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/02. SCHERER,R. Georgia Power Co. 2pp. 47783:247-47783:248.
- 8912190272 Forwards summary of 881116-17 mgt meetings at plant re unit const status.List of attendees.agenda.handouts & meeting summary enct. ERNST.M.L. Region 2, Oto of the Director. 88/12/07. HAIRSTON,W.G. Georgia Power Co. 74pp. 47850:134-47850:207.
- 8812190385 Advises that reactor vessel level instrumentation sys testing should be per-lormed prior to fuel load to develop required conditions in RCS.Schedule for Unit 1
- BAILEY, J.A. Georgia Power Co. 88/12/08. Document Control Branch (Document Control Deak). 2pp. 47850:328-47850.329.
- 812190379 Requests temporary exemption from schedular requirements of 10CFR50.33(k)(1):Financial planning responsive for rule initiated & util intends to submit funding replac on 900727.

 8/11E/YJA. Georgia Power Co. 88/12/13. Document Control Brench (Document Control Desk). 4pp. 47851:252-47851:255.
- 8812200202 Forwards results of spent fuel racks multi-rack analysis, per commitment at 881004-08 audit. BAILEY,J.A. Georgia Power Co. 88/12/13. Document Control Branch (Document Con-trol Deak). 1p. 47884:199-47884:212.
- ~8812200249 "Multi-Rack Analysis for Vogite West Pool." SOLER,A.I. Holtec International, HI-88316, 88/12/01, 13pp. 47884:200-47864:212.

- 6812200119 Forwards updated listings of outstanding Loonsing requests for plant for NRC review & approval including Generic Ltr 83-28 items & NUREG-0737, Item
 - HID 1.1 HAIRSTON,W.G. Georgia Power Co. 88/12/14. Document Control Branch (Document Control Desk). 6pp. 47871-048-47871.053
- 8812228047 Forwards proposed changes to FSAR Table 16.3-5, "Containment Penetra-tion Conductor Overcurrent Protective Devices & Isolation Devices for Class 1E to Nan Class 1E Feeds" Changes refect incorporation of Unit 2 protect and devices BAILEY,J. A. Georga Power Co. 86/12/14. Document Control Branch (Document Control Deak), 34pp. 47814, 125-47914, 158.
- 8812230077 Forwards marked up FSAR pages to incorporate revire elastomer diaphrein storage life Changes reliect longer storage life allowance.
 BAILEY, J.A. Georgia Power Co. 88/12/15. Document Control Branch (Document Control Desk). 4pp. 47914-356-47914-359.
- 8812230097 Forwards FSAR page marked-up to rellect deletion of fire delection instrumen's from facility fro detection Zono 28
 BAILEY, J.A. Georgia Power Co. 88/12/15 Document Control Branch (Cocument Control Desk). 2pp. 47916 360-47916.361
- 8812230101 Forwards listing of rooms that require area temp monitoring for lacility Rooms should be added to Table 3.7-3 of final draft Tech Space. BAILEY.J. A Georgia Power Co. 88/12/19 Document Control Branch (Document Control Desk), 3pp. 47911:004-47911.006

F. Security, medical, emergency & fire protection plans

- 8811280055 Contirms date of 890726 to conduct 1989 annual emergency preparendndss exercise at plant HARIBSTON,W.G. Georgis Power Co. 88/11/16. Document Control Branch (Oocument Control Desk) 1p. 47654:154-47654:154
- 8811300571 Forwards Insp Repts 50-424/88-38 & 50-425/88-42 on 880815-19 & notice OLLINS,D.M. Region 2, Olc of the Director, 88/11/18 HAIRSTON,W.G. Georgia Power Co. 3pp. 47673:154-47673:194.
- -8811300574 Insp Repts 50-424/88-38 & 50-425/88-42 on 880816-19. Violations noted Major areas inspected site & corporate emergency proparedness programs & identification of programmatic differences &/or changes specific to Unit 2. CUNNINGHAM,A1. Region 2, Old of the Director. 88/11/16. 30pp. 47873.181-47673:194.
- 8811230241 Forwards rays to physical security & contingency ptan por NRC 880920 itr.Revs withheld (ref 10CFR73.21.8.2.780) HAIRSTON,W.G. Georgia Power Co. 88/11/21 Document Control Desk). 2pp. 47657:300-47657.301.
- 8811280028 Forwards corrected changes to security plan.Including properly marked up Pages E1-2,4-1,6-3 & Insert to Page 8-3 Enct withhold HARSTON,W.G. Georgia Power Co. 88/11/22. Document Control Branch (Document Control Desk). 2pp. 47701:250-47701:251.
- 8812090138 Forwards Insp. Rept. 50-425/88-58 on 881024-27.No violations or devi-ations noted Encl partially withheld (ref. 10CFR2 700 & 73.21). CLINE,W.E. Region 2, Ofc of the Director. 88/11/22. HAIRSTON,W.G. Guorgia Power Co. 2pp. 47782:001-47782:003.
- -8812090140 Partially withheld Insp Rept 50:425/88-58 on 881024-27 (rel: 10CFR2.790 & 73.21) No violations noted Major eross inspected physical security plan & implementing procedures, security organization, testing & maint & physical barriers.

 TILLMAN,A, MCGUIRE,D.R. Region 2, Ofc of the Director. 88/11/16. 1p. 47782.003-47782.003.
- 8812050009 Forwards update to Module 23 of facility readiness review program Encl withhold fref 10CFR73 21 & 2760). RICE, P.D. Georgia Power Co. 88/11/23. Document Control Brench (Document Control Dask). 2pp. 47730:335-47730:336.
- 8812050250 Forwards Insp Repts 50-424/88-49 & 50-425/88-59 on 881017-20.No vio-lations or deviations noted Attention Invited to Identified unresolved item. HERDT,A.R. Region 2, Oic of the Director. 88/11/25. HAIRSTON.W.G. Georgia Power Co. 2pp. 47730:267-47730:296.
- -8812050255 Insp Repts 60-424/88-49 & 60-425/88-59 on 881017-20.No violations or deviations noted.Major areas inspected fire protection & licensee actions re implementation of plant sale shuldown guidance provided in SRP 9.5-1.
 WISEMAN,G. Region 2, Ofc of the Director. 88/11/22, 28pp. 47730:269-47730.286.
- 8812090299 Forwards FEMA offsite exorcise rept for plant on 880524. Resolution of identified items should be completed prior to next full scale amergency preparedness
 - Revercise.

 DECKER,T.R. Rogion 2, Ofc of the Director, 88/11/25. HAIRSTON,W.G. Georgia Power Co. 2p. 47/62:120-47/62:168.
- 8812160141 Forward Insp Repts 50:424/88:47 & 50:425/88:62 on 881031-1104.No violations or deviations identified.

 DECKER,T.R. Region 2, Oto of the Director. 88/12/02. HAIRSTON,W.G. Georgia Power Co. 2pp. 47832:283-47832:295.
- ---8812160144 Preoperational Insp. Repts 50-424/88-47 & 50-425/88-62 on 881031-1104.No violations or deviations noted Weakness noted Major areas inspected redilation protection organization. & training & external exposure control GLOERSEN,W.B. Region 2, Otc of the Director. 88/12/02. 11pp. 47832-285-
- 8812220112 Forwards SALP Repts 50-424/88-41 & 50-425/88-53 for Oct 1987 Sept 1988.Mgt control needed to reduce problems in field Fluid sys leaks continue to be problem.
 ERNST.M.L. Region 2. Ofc of the Director. 88/12/05. HAIRSTON,W.G. Georgia Power Co. 3pp. 47800:253-47900.314.

DOCKETED ITEMS 146

- -9812220120 SALP Repts 50-424708 41 & 50 425788-53 for Oct 1087 Sept 1988
 * Region 2, Otc of the Director, 68/12/05, 56pp, 47900 255-47900 314
- 8812160117 Forwards rovs to physical security & contingency plan Revs withheld (ref
- 100FR/3 21 8 2 790)
 HAIRS1DN,W.G. Georgia Power Co. 88/12/14 Document Comrol Branch (Cocument Control Desk). 2pp. 47852.174-47052:175
- 8812210142 Forwards add' Info in response to 881117 & 30 telechs re-oversized seals, embedded conduits & fire hazards analysis Proposed FSAR page changes also end Proposed changes will be incorporated into future amend to FSAR BAILEY, JA. Georgia Power Co. 88/12/14. Decument Control Branch (Document Control Desk), 65pp. 47888-256-47888:362

H. General correspondence

- 8812120059 Comment opposing proposed rule 10CFR2 re-records related to ficensing high fevel radivaste geologic repository. Util endorses EEI comments to be submitted to NRC. HAIRSTON,W.G. Georgia Power Co. 88/12/05 CHILK,S.J. Office of the Secretary of the Commission, 20p. 47798,087-47708;088
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8812010103 Agreed 39 to FSAR for Vogite Units 1 & 2 W/891123 ltr. RICE,P D. Georgia Power Co. 88/11/30, 1,699pp, 47712 001-47716 259.
- P. Operating license stage documents & correspondence
- 8812230273 Contimes completed requirements of Generic Lin 88-03, "Steam Binding of Auxiliary Feedwater Pumps "Procedure 11882-2 requires checking auxiliary leedwater pumps socition & p.p.ing temps & 13610-2 describes valve backleakage symptoms. RICE, P.D. Georg & Power Co. 88/12712. Document Control Branch (Document Control Desk) 2pp 47916-141-47916-142.
- Q. Inspection reports, IE Bulletins & correspondence
- 8811230238 Responds to violations noted in Insp Rept 60-425788-48 reliature to properly tighten flewble conduit in contement

 RiCE,P.D. Georgia Power Co. 88/11/07 Document Centro! Brench (Document Control Desk). 2pp. 47622:248-47622-249
- 8811230244 Responds to violations noted in Insp. Rept 50-425/88-49 re-failure to pro-tect installed equipment Corrective actions, broken flexible conduit & bent Instrument tine condition I stod for reper on room turnover purchilist RIDE, P.D. Georgia Power Co. 88/11/07, Document Control Branch (Document Con-trol Desk), 2pp. 47652-133-47652-134.
- 8811300571 Forwards Insp Repts 50-424788-38 & 50-425788-42 on 880815-19 & notice of wideton COLLINS,D.M. Region 2, Otc of the Director, 08/11/18, HAIRSTON,W.G. Georgia Power Co. 3pp. 47673,154-47673,194
- -8811306574 Insp. Repts 50 424/88/38 & 50 425/88/42 on 880815/19. Violations noted Major areas: inspecied site & corporate emergency preparedness programs & identification of programmatic differences Afor changes specific to Unit 2. CUNNINGHAM A L., DECKER, T.R., Region 2, Olic pt tha Director, 88/11/16, 30pp. 47673.161-47673.194
- 8811160211 NRC Info Notice 88-990, "Unauthorized Removal of Industrial Nuclear Gauges" Svc Isl and CUNNINGHAM.R.E. Drilson of Industrial & Medical Nuclea: Salety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 03pp. 47708 255-47708 257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tosts." Svc list encl.
 ROSSI,C E. Division of Operational Events Assessment (Post 870411), 88/11/22
 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47703 142.
- 8812090138 Forwards Insp Rept 50-425/88-58 on 881024-27.No violations or devi-ations noted Enclipartially withheld (ref. IGCFR2.790 & 73.21). CLINE,W.E. Region 2, Ofc of the Ofractor. 88/11/22. HAIRSTON,W.G. Georgia Power Co. 2pp. 47782-001-47782-003.
- -8812090146 Partially withheld Insp Ropt 50-425/08-58 on 881024-27 (rol 10CFR2.790 & 73.21) No violations noted Major areas inspected physical security plan & implementing procedures, security organization, testing & maint & physical barners. TILLMAN, ... MCGUIRE, D.R. Region 2, Otc of the Director. 88/11/16. pp. 47782.003-47782:003
- 8812090253 Forwards Insp Rept 50-425/88-57 on 881003-07 & 11-14 No violations or devisitions noted.
 HERDT, A.B. Rogion 2, Otc. of the Director. 88/11/22. HAIRSTON, W.G. Georgia.
 Power Co. 2pp. 47782-220-47782;230.
- --8812090258 Insp Rapt 50-425/08:57 on 881003-07 & 11-14.No violations or devi-ations noted Major areas inspectod, preoperational & hot functional test witnessing, preoperational test procedure review & licensee action on previous insp findings JAPEF, SZCZEPANIEC,A, ZEILEAJ, Region 2, Oic of the Director, 88/11/17, 9pp. 47/82:22-47782.230.
- 8812050241 Forwards Insp. Rept 50-425/98-67 on 881031-1103,No violations or deviations noted HERDT,A.R. Region 2, Ofc of the Director, 88/11/25 HAIRSTON,W.G. Georgia Power Co. 2pp. 47731:041-47731.054.

~8812050245 Insp Rept 50-425/86-87 on 881031-1103.No violations or deviations

- 8812050250 Forwards Insp Ropts 50:424/88 49 & 50:425/88-59 on 891017-20.No violations or devintions noted Affeit on invitor to identified unresolved tiem
 HERDTA.F. Report 2, Oic of the Director 88/11/25, HAIRSTON.W.G. Goodga
 Power Co. 2pp. 47730 267-47730 296
- -8812059255 insp Repts 50-424/88-49 8 50-425/88-59 on 881017-20.No viersons or devalions noted Mejor areas respected fre protection 8 Leansea actions re Implamentation of plant state shutdown guidance provided in SRP 8 5-1.
 WISEMAN,G., COMILON,T. Region 2, Old of the Director: 88/11/22 28pp 47730 269-47730 296
- 6812090134 Forwards Exam Ropts 50-421/OL-88-02 & 50-425/OL-88-02 administrate on 880919 22

 JULIAN.C A. Region 2, Ctc of the Director, 88/11/25 HAIRSTON,W.G. Georgia

 Power Co. 2pp. 47762.334-47763.347.
- -8812090142 Exam Ficpts 50-424/OL-88 02 8 50-425/OL-88-02 on 800018-22 Exam results all candidates passed. ARILDSEN,J. Region 2, Oto of the Director, 88/11/16, 274pp. 47762 336-47763 249
- -8812090145 Forwards commonts compiled by training dept re-reactor operator & socior reactor operator written exems conflucted at plant on 880919 BBCSKHOLD,G Georgia Power Co. 88709721 MUNRO,J Region 2, Ofc of the Director
- 8812090283 Forwards Insp Riopis 50 424788 46 & 50 425788 61 on 881017 21 No violations rolled DECKER,T.R. Region 2, Olic of the Director, 88/11/25, HAIRSTON,W.G. Georges Power Co. 2pp. 47784/350-47784/359.
- -8812090268 Insp. Ropts 50:424/88:46 & 50:425/88:61 on 881017-21.No violations noted Major areas inspected rad ological effucits & plant chemistry.

 KAHLE J.B. HUGHEY C.A. Region 2, Otc of the Director, 88/11/25, 8pp. 47784 352-
- 8812050146 Forwards response to NRC Bulletin 88:005 re safety-related fitings 8 flanges supplied by West Jorsey Mfg 8 Piping Supplies, inc. Rept of design evaluation of subj fittings 8 flanges and BAILEY, A George Power Co 88/11/30 Document Control Branch (Document Control Dosk) 3pp. 47732 098-47732-280.
- -8812050222 "Response to NRC Bulletin 88:005 for Plant Vogite." Response consists of records review, fosting results, analyses & conclusions from program for determined whether retinated refused fittings & flunges consistent w/ASME Code criteria. "Georgia Power Co. 88/11/30, 148pp. 47732-101-47732-248
- --8812050224 "Dosign Evaluation of Wost Jorsey Mfg/Piping Supplies.ing Fillings & Flanges w/Estimated Strength Below 66 KSI for Plant Vogite.Unit 2."

 * Georgia Power Co. 88/11/30, 44pp. 47732,247-47732;290.
- 8812060202 Forwards Rov 0 to ISI.P-014, "Inservice Insp. Program," for review Attachment A lists differences between Rov 0 of Unit 2 program & Rov 2 of Unit 1 program BAILEY, J.A. Southern Company Services, Inc. 69/11/30. Document Control Branch (Occument Control Desk) 2pp. 47736:337-47737-317.
- -8812050207 Rev 0 to ISI P-014, "Inservice Insp Program."
 * Scuthorn Company Services, Inc. 88/10/25, 338pp. 47736:339,47737:317.
- 8812090323 Forwards Insp. Rept 50-425/88 65 on 881024-28 No violations or dovations noted. HERDT.A.R. Region 2, Ofc of the Director. 88/12/01. HAIRSTON,W.G. Georgia Power Co. 2pp. 47761:140-47761:149.
- -8812090327 Insp. Ropt. 50-425/88-65 on. 881024-28 No. violations or dowletons noted Major areas inspected containment local teak rate preoperational test program review & reactor protection sys preoperational test procedure review. WRITENERS.H., ZELER.J., JAPE.J. Region. 2, Ofc. of the Offector. 88/11/30. 8pp. 47761-142-47761:149.
- 8811290030 NRC Into Notice 88-093, "Teletherapy Events." Svc list enct. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Salety (Post 970725). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8811290538 NRC Into Notice 68-094, "Potentially Undersized Valve Actuators." Syc list encl. ROSSI,C.E. Dw.sion of Operational Events Assassment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708;143-47708:254.
- 8812180141 Forward Insp Repts 50.424/88.47 & 50.425/88.62 on 881031-1104 No violations or deviations identified DECKER,T.R. Region 2, Ofc of the Director. 88/12/02. HAIRSTON,W.G. Georgia Power Co. 2pp. 47832 283-47832 295.
- --9812160144 Pragperational Insp. Repts 60-424/88-47 & 50-425/88-62 on 981031-1104 No violations of deviations noted Weakness noted Mejor areas Inspected rediation protection organization & training & external exposure control. GLOERSEN.W B., HOSEY.C.M. Region 2, Ofc of the Director. 89/12/02. 11pp 47632 265-47832-295.
- 8812190006 Forwards Insp Repts 50-424/88-50 & 50-425/88-64 on 881024-28 No vio-lations or deviations noted. BROWNLEE,V.L. Region 2, Otc of the Director. 88/12/05. HAIRSTON,W.G. Georgia Power Co. 2pp. 47850-330-47850-341.
- ~8812190009 Insp Repts 50:424/88:50 & 50:425/88:84 on 881024-28:No violations of deviations noted Major areas inspected quality concerns program (OCP),including open concerns.lask force review of OCP & root cause & review of concerns. DEMIRANDA,O., PATTERSON,C.A., SINKULE,M.V. Region 2, Ofc of the Director. 88/12/02. 10pp. 47850.332:47850.341.
- 8812220112 Forwards SALP Repts 50-424/88-41 & 50-425/88-53 for Oct 1987 Sect

8812190257 Forwards Insp Repts 50-424/88-54 & 50-425/88-70 on 881114- 18 No viglations or deviations noted.

OECKER,T.R. Region 2, Ofc. of the Director, 88/12/08, HAIRSTON,W.G. Georgia.

Power Co. 2pp. 47853:323-47853:334.

- --B812190258 Insp Repts 50-424/88-54 & 50-425/88-70 on 881114-18.No violations or deviations noted Major areas inspected.Core Modulo 84750 insp at Unit 1 & preoperational Insps of Unit 2 in areas of liquid & gaseous radwaste processing STODDART,P.G. KAHLE,J.B. Region 2, Ofc of the Director. 88/12/01. 10pp 47853 325-47853:334.
- 6812190277 Discusses NRC evaluation of facility readiness review of initial test program preoperational test phase Module 03A, Phase 2 submitted on 880324 ERNST,M. Region 2, Oic of the Director. 88/12/06. HAIRSTON,W.G. Georgia Power Co. 2pp. 47860:113-47880:114.
- 6812090254 Responds to NRC Bulletin 88:003 requesting that Insps be performed for all GE tatching-type HFA relays in Class 1E applications Fourteen GE 12HFA54E187H relays inspected on 881108 for Unit 1 & on 880606 for Unit 2. HAIRSTON,W.G. Georgia Power Co. 88/12/07. Document Control Branch (Document Control Desk). 3pp 47762:112-47762:114.
- 6812160108 Forwards Insp Repts 50-424/88-51 & 50-425/88-56 on 881031-1104 & 07-10 No violations or deviations noted.

 HERDT, A.R. Region 2, Otc. of the Director. 88/12/07. HAIRSTON, W.G. Georgia.
 Power Co. 2pp. 47832:307-47832:325.
- -8812190115 Insp. Repts 50:424/88:51 & 50:425/88:66 on 881031:1104 & 07-10.Weaknesses identified Major greas Inspected:Unit 1 IE Bulletin 85:003 program & complex surveillance & Unit 2 preoperational testing procedure review. DESALB, SZCZEPANIEC,A, TINGEN,S. Region 2, Ofc of the Director. 88/12/07 17pp. 47832:309:47832:325.
- 8812020287 NRC Info Notice 88-085, "Inadequate Procurement Requirements Imposed by Licenseas on Vendors." Svc list end.
 ROSSI/CE Division of Operational Events Assessment (Post 870411), 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302
- 8912190249 Forwards Insp Repts 50-424/88-42 & 50-425/88-54 on 880909-12 & 1112-18.No violations or deviations noted. HEROT,A.R. Region 2, Ofc of the Director, 88/12/08. HAIRSTON,W.G. Georg's Power Co. 2pp. 47853.308-47853.317.
- -8812190251 Insp Repts 50-424/88-42 & 50-425/88-54 on 880909-12 & 1112-16.No violations or deviations noted Major areas inspected Unit 2 piping thermal expansion & vibration testing & Unit 1 snubber surveillance program.

 LENAHAN, T.J., JAPE, F. Region 2, Ofc of the Director. 88/12/08. 8pp. 47853.310-47853.317.
- 8812140269 Responds to NRC ltr re violation noted in Insp Repts 50-424/88-38 & 50-425/88-42 Corrective actions site omergency preparedness supervisor counseled revisitation 8 retrained on Proceedure 91602-C requirements.

 HAIRSTON,W.G. Georgia Power Co. 88/12/09. Document Control Branch (Document Control Desk). 3pp. 47812.060-47812.062
- 6812150148 Advises that util response to IE Bulletin 68-005 enci in JA Bailey 881130 Itr. RICE,P.D. Georgie Power Co. 88/12/12. Document Control Brench (Document Control Desk). 2pp. 47822:146-47822:336.
- 8812200284 Ack receipt of 881107 ltr Informing NRC of steps taken to correct violations noted in Inag Repts 50-425/88-48 & 50-425/88-49.
 HERDT,A.R. Region 2, Oto of the Director. 88/12/13. HAIRSTON,W.G. Georgia Power Co. 2pp. 47860.339-47880:340.
- 8812210059 Confirms 881219 mgt meeting w/util in Birmingham.AL to discuss nuclear plant oversight responsibilities,technical support responsibilities & activities of corporate organization.per 881205 telcon reliested inspirapts. ERNST, ML. Region 2, Otc of the Director. 88/12/13, HAIRSTON,W.G. Georgia Power Co. 3pp. 47888:101-47888:103.
- 8812210164 Submits supplemental response to NRC Bulletin 88-005 Reedy Associates rept. "Rept on ASME Reply to Georgia Power Co Inquiry" enci to explain util position re codo compilance of piping sys w/WJM/PSI matl. BAILEY_JA. Georgia Power Co. 88/12/15. Document Control Branch (Document Control Desk). 2pp. 47878:294-47878:306.
- -6812210155 "Rept on ASME Repty to Georgia Power Co Inquiry."
 Reedy Associates, Inc. 88/12/14, 11pp. 47878:296-47878:306.
- 8812210249 Provides info necessary to complete util response to NRC Bulletin 88-004 re potential safety-related pump loss. MCDONALD,R.P. Georgia Power Co. 88/12/15. Document Control Branch (Document Control Desk), 3pp. 47876.004-47878:006.

S. Reportable occurrences, LERs & related correspondence

- 6811300566 Deficiency rept re misapplication of Raychem criteria in selection of some mati used in electrical cable field splice kita.initially reported on 880920.investigation is in process Final rept will be submitted by 881222.

 RICE, F.O. Georgia Fower Co. 88/11/21. Document Control Branch (Document Control Desk). 1p. 47674:128-47674:128.
- 8812210191 Deficiency rept re ASME Class 1 tees forged.Caused by forged tees w/ structural discontinuities being used in ASME Class 1 piping sys.Ali ASME Class 1 lorged tees reconciled into piping sys stress analyses. RICE, P.D. Georgia Power Co. 88712/15. Document Control Branch (Document Con-trol Desk). 4pp. 47874:307-47874:310.

V. Operator Examinations

- 8812090134 Forwards Exam Ropts 50 424/QL-88-02 & 50 425/QL-88-02 administered on 880919-22.

 JULIAN,C.A. Region 2, Ofc of the Director 68/11/25. HAIRSTON,W.G. Georgia
 Power Co. 2pp. 47762 334-47763 347.
- -8812090142 Exam Repts 50-424/OL-88-02 & 50-425/OL-88-02 on 880919-22 Exam results 8t candidates passed ARILDSENJ, MUNROUF. Region 2, Ofc of the Director. 88/11/16. 274pp. 47762 336-47763 249.
- --8812090145 Forwards comments compiled by training dept re reactor operator & senior reactor operator written exams conducted at plant on 880919 BOCKHOLDG. Georgia Power Co. 88/09/21. MUNRO,J. Region 2, Oic of the Director

DOCKET STN-50-437 FLOATING NUCLEAR PLANT

A. Application/construction stage documents & correspondence

8611280046 Genoric Ltr 66-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnerabilities Svc list enci CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 69/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728/303-47729.024

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 88 090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list encl.
 CUNNINGHAMP E. Division of Industrial & Medical Nuclear Safety (Post 870729)
 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811180467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Tosts." Svc fist and.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/11/22.
 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142.
- 8811290030 NRC Info Notice 88 893, "Telethorapy Events." Svc list encl. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02, Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215
- 8811290538 NRC Info Notice 88-094, "Potentially Understand Valve Actuators." Svc Fst onci. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp 47708;143-47708;254.
- 8812020287 NRC Info Notice 88-985, "Inadequate Procurement Requirements Imposed by Liconsees on Vendors" Svc 1st enct.
 ROSSI, CE. Division of Operational Evente Assessment (Post 870411), 88/12/08.
 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.

DOCKET 60-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exem for sovere accident vulnerabilities Syc list GRUTCHFIELD,D. Associate Director for Projects (Past 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024
- 8812150222 Discusses Generic Ltr 83-28, "Regulred Actions Based on Generic Implicalons of Salem ATWS Events for listed plants Reactor trip breaker maint & trending lasues should be addressed as prant-specific Issues. BRADFUTE_J.O. Project Directorate V. 88/12/06 AULUCK,R. Otc of Special Projects. 3pp. 47825.073-47825.075.

F. Security, medical, emergency & fire protection plans

8812210195 Revised control emergency control ctr emergency plan implementing procedures including Rev 1 to CECC-EPIP-1,Rov 2 to CECC-EPIP-2,Rev 2 to CECC-EPIP-3,Rev 3 to CECC-EPIP-4, Rev 2 to CECC-EPIP-5 & Rov 2 to CECC-EPIP-7,W/ MCANALLY, J.L. Tennessee Valley Authority. 88/12/16. 86pp 47906 304-47907.053

Q. Inspection reports, IE Bulletins & correspondence

- 8811280042 Forwards Insp Rept 50-438/88-05 on 881005.No violations or deviations noted. MCCOY,F.R. Otc of Special Projects. 88/11/04. WHITE,S.A. Tennessee Valley Authority. 2pp. 47655:344-47655:347.
- -8811280046 Insp. Rept. 50-438/88-05 on 881005.No violations or deviations noted Major areas inspected/protection of fuel storage facility. THOMPSON,D., MCGUIRE,D.R. Region. 2, Otc. of the Director. 88/11/03. 2pp. 47855:346-47855:347.
- 8811160211 NRC Info Notice 68 090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc Isl encl. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22. Consolidator Edison Co. of New York, Inc. 99pp. 47708.255-47708.267.
- 8811160467 NRC Info Notice 88-991, "Improper Administration & Control of Psychological Tests "Svc list encl.

 ROSSI,C E. Division of Operational Events Assessment (Post 870411). 98/11/22, Consolidated Edison Co. of New York, Inc. 101pp 47708.042.47709:142.

spector at plants revito enforcement policy & proposed enforcement actions for operator inattentiveness at Peach Bottom.
BLACK, S.C. Ofc. of Special Projects #8/11/23 KINGSLEY,O.D. Tennessee Valloy Authority. 3pp. 47709

8811290030 NRC Into Notice 88-093, "Teletherapy Events." Svc Let encl CUNNINGHAM,R E. Division of Industrial & Modical Nuclear Safety (Post 870729) 68/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811

8611290538 NRC Info Notice 68 094, "Potenhally Undersized Valve Actuators." Svc I st ent. ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp 47708:143-47708 254

8812020287 NRC Into Notice 88-095, "Inadequate Produrement Requirements Imposed by Liconsees on Vandors" Svc list end:
ROSSI, C. Division of Operational Events Assessment (Post 870411) 88/12/08, Consol dated Edison Color New York, Inc. 112pp. 47807.191-47807.302.

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8811280048 Generic Ltr 88 20 to all I censoes holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnerabilities Svc Lst exct.

COLITICATION D. Associate Director for Religious (Rept. 2011). (8411/23, Control.)

CRUTCHF(ELD,D. Associate Director for Projects (Post 870411), 88/11/23 Consolidated Edison Co. of New York, Inc. 81pp. 47/28 303-47729,024

8812150222 Discusses Generic Lir 83-28, "Required Actions Based on Generic Implications of Sa'em ATWS Events" for listed plants Reactor trip breaker maint & trending issues should be addressed as plant-specific issues BRAOFUTE_JO Project Directorate V. 88/12/08 AULUCK,R Ofc of Special Projects. 3pp. 47825 073-47825 075.

F. Security, medical, emergency & fire protection plans

8812210195 Revised central emergency control of emergency plan implementing procedures including Rev 1 to CECC-EPIP-1, Rev 2 to CECC-EPIP-2, Rev 2 to CECC-EPIP-3, Rev 3 to CECC-EPIP-4, Rev 2 to CECC-EPIP-5 & Rev 2 to CECC-EPIP-7, W/881216 (ft. WCANALLY, J. Tennassee Valley Authority, 86/12/16 86pp. 47006.304-47907-053

Q. Inspection reports, IE Bulletins & correspondence

8811160211 NRC Into Notice 88:090, *Unauthorized Removal of Industrial Nuclear Gauges ** Svc list enci CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/11/22: Consolidated Edison Co. of New York, Inc. 90pp. 47708:255-47708:257.

8811180467 NRC Info Notice 88-991, "Improper Administration & Control of Psychological Tasts." Swifat end:
ROSSICE Division of Operational Events Assessment (Past 870411), 88/11/22.
Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708.142.

8812010188 Forwards V Stello 881117 lir to all util executives re-presence of NRC inspector at plants revito enforcement policy & proposed enforcement actions for oporator leatentiferness at Poach Bottom BLACK, S.C. Olic of Special Projects 88/11/23. KINGSLEY,O.D. Tonnessee Valley Authority, 3pp. 47708:258-47709:309.

8811290030 NAC Info Notice 88:033, "Teletherapy Events," Syc list encl. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.

8811290538 NRC Info Notice 88-094, "Potentially Undersized Valva Actuators." Svc list

and ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 68/12/02. Corsol dated Edison Co. of New York, Inc., 121pp. 47708:143-47708:254.

8812020287 NRC Into Notice 88 095, "Inadequate Procurement Regulroments Imposed by Licensees on Vendors" Svc 1st encl ROSSI, CE. Division of Operational Events Assessment (Post 870411). 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

47864:071-47664-168

8611290183 Forwards final rept of 880504 full participation exercise of offsite radiological emergency response plans. No deficiencies observed & eight areas requiring corrective action identified.

KRIMM.R.W. Federal Emergency Management Agency. 88/11/02. CONGEL.F.J. Division of Radiation Protection & Emergency Preparedness (Post 870411). 10.

-8811290191 Final Rept of 880504 Perry Nuclear Power Plant Joint Exercise."

* Federal Emergency Management Agency, 86710720, 88pp., 47664;072,47664;158.

8812050292 Revised "Emergency Public Info Organization Implementing Instructions Manual," WJ881201 ltr. HEFFNER,G., KAPLAN,A Cleveland Electric Illuminating Co. 88/11/07, 144pp. 47723:226-47724:009.

8812080049 Rev 9 to "Emergency Plan for Parry Nuclear Power Plant." W/ 881130 Nr. ANDERSON, J.D., KAPLAN, A. Cleveland Electric Ituminating Co. 88/11/29, 544pp. 47735.037-47736 220.

aspects of plant exercise conducted on 880504. FEMA Identified no deficances in performances of offsite agencies during exercise. GREGERLA Region 3, Oto of the Directic 88/12/05, KAPLANIA, Creveland Electric Pluminating Co. 2pp. 47761:290-47762.019.

8812140189 Advises util to take listed corrective actions re evacuation instructions in accordance w/FEMA recommendations during next annual update of emergency into handbook Commitment to making corrections requested within 33 days. HANNON,J.N. Project Directorate III-3, 88/12/08. KAPLAN,A. Cloveland Electric IN-minating Co. 3pp. 47821,004-47821-043.

G. Adjudicatory correspondence

8812020147 Forwards final Director's Decision on issues contained in 880725 supplemental petition to public into an plant. Polition denied based on considerations 18250 in 880725 suppl.

MURLEY, T.E. Office of Nuclour Reactor Regulation, Director (Post 870411), 88/11/29 KUNEC, GURLING, T., O'CONNELL, R. Affiliation Not Assigned 3pp. 48992, 333-48092, 334.

--8812020150 Final Director's Decision DD-89-19 granting petitioners request to improvements in emergency preparednose program MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 66/11/29, 1490-48092,340-48092,353.

-8812020154 Notice of issuance of final Director's Decision to 870922 position for valid correct alleged deficiencies in public into handbook on omergency planning for part MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/29, 2pp. 48092,354-48092,355.

H. General correspondence

8812010266 Comment on preposed rule 10CFR28 re-filness for duty program.U2 in agreement w/majority of comments submitted by NUMARC & Nuclear U1 I Backfiting & Reform Group.

KAPLAN,A. Cloveland Electric ItumInating Co. 88/11/18 Docketing & Services Branch 8pp 47679 131-47679 138.

P. Operating license stage documents & correspondence

8812050013 Provides discussion relissue of seismic margin evaluation for facility Utulanticipate finalizing criteria & commencing preparatory work by first refueling.completing preparatory work & walkdowns by third refueling. KAPLAN,A. Claveland Electric Illuminating Co. 86/07/21, Document Control Branch (Document Control Desk) 4pp 47723.149-47723:152.

8811280048 Generic Ltr 88:20 to all licenseds holding OLs & CPs for nuclear power reactor facilities no individual plant exam for severe accident vulnerabilities 5xc 1st encl. CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23 Consequently Edward Edward Co. of New York, Inc. 81pp. 47728:303-47729:024.

8612050169 Application for amend to Licunse NPF-58,revising Tech Special 2.1.2.3.2.1,3.2.2.8.3.2.3 to satisfy limit min critical power ratio 8 associated power distribution firms for fuel to be loaded into core for second cycle-Feo pard.

KAPLAN,A. Cloveland Electric lituminating Co. 88/11/28. Document Centrol 8:anch (Document Centrol Desk). 11pp. 47723:033-47723:102.

--8812050170 Proposed Tech Spec Sections 2.1.2,3.2.1,3.2.2.8.3.2.3 re-safety in liminarities power ratio & associated power distribution limits for fuel.
* Cleveland Electric Illuminating Co. 88/11/28, 34pp. 47723.045-47723.090.

-8812050172 "Supplemental Relead Licensing Submittal for Perry Nuclear Power Plant Unit 1,Relead 1,Cyclo 2."
CHARNLEY, JS., PLOTYCIA, G.D., MARRIOTT, P.W. Genural Electric Co. 23A5648 R01. 88/11/30 22pp. 47723.081-47723:102.

8812090091 Forwards safety evaluation in response to util response to Part 1 of Lem 2.2 to Generic Lit 83-28, "Equipment Classification for Alt Other Safety-Refered Components." COLBURN, T.G. Project Directorate III-3, 88/12/06, KAPLAN, A. Cleveland Electric Huminating Co. 2pp. 47786.305-47786:326.

-8812090093 Saloty evaluation documenting NRC review of licensee response to Generic Ltr 83-28 Evaluation concludes that licensee adequately meets provisions of Pa1 1 of licen 2 2 to Generic Ltr 83-28.

 Office of Nuclear Reactor Regulation, Director (Post 670411). 86/12/06 3pp 47766:307-47786:326.

8812130294 Summary of 881207 meeting w/utils & DEVONRUE to use of IPCS descripenerator as ellernate at power source to satisfy 10CFR50.63 for 8WR/6 p'acts. TAMP.S. Project Directorate I-4. 88/12/07. Project Directorate I-4. 18pp. 47796.017-47786.034.

8812090270 Forwards Amend 18 to Licenso NPF-58 & safety evaluation. Amend allows one-time extension re disassembly & inspiral furbine control turbine stop.low prossuse turbine intercept & low pressure turbine intermediate stop valves. CCI,BURNITG. Project Directorate III-3, 88/12/08. KAPLAN,A. Cleveland Efective 155 minating Co. 2pp. 47782:193-47762:202.

--8812090271 Amand 18 to Liconse NPF-58, allowing one-time extension for disaster biy & insp of turbine control, turbine stop, low pressure turbine intercept & low pressure & low pressure turbine intercept & low pressure & low pressure turbine intercept & low pres

-8812090275 Salaty evaluation supporting Amend 18 to License NPF-58.

Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/08 3pp 47782:202

- 812180072 Confirms plans to conduct monthly status meeting at facility on 881220 re reflueting outage workscope/properation for outage licensee initiative to eliminate rissed Rad Chem survollances & roview of record plant sys status rept GREENWAYLEG, Region 3, Ofc of the Director 88/12/09. KAPLAN,A Cleveland Electric Illuminating Co. 2pp. 47873:228-47873:229.
- 812270074 Confirms 881219 significant licensee meeting in Chicago, IL & 881220 site meeting to discuss recent plant performance. GREENAMA, E.G. Region 3, Olf of the Director, 88/12/16, KAPLAN, A. Claveland Electric Lumineting Co. 2pp. 47916.162-47916;163.
- 812290266 Final response to FOIA request for documents Forwards App B & C documents App A & B available in PDR.App C & D partially & totally withhold, respectively (rel FOIA Examptions & 8.5, respectively). GRIMSLEY, D.H. Division of Freedom of Information & Publications Services (Post 880515), 88/12/20. HIATT, S. Ohlo Citizens for Responsible Energy, 8pp. 47962-186-47962-356.
- -8805030507 Forwards SER donying OCRE 2 208 potition for immediate action to re-fleve undue risk posed by Inadequate scismic design of plant Susponsion of license pending add studies (geological & geophysical) & onglineering review unwarranted BAGCHLO. Structural & Geoscionces Branch. 88/04/28. PERKINS.K.E. Project Directorate III-3, 5pp. 47962 320-47962 324
- -8908310058 Forwards "Earthquakes,Injection Wolfs & Perry Nuclear Power Pant Claveland,OH," which appeared in Aug 1988 Geology magazine. Art.cte conclusions w/o basis & merely used to attract attention.

 REITERL. Structural & Geoscionces Branch. 88/08/29. BAGCHIG., RICHARDSON,J., SHAO,L. NRC No Datailed Affination Given 1p. 47982-954-47942-348.
- 8808310128 "Earthquakos,Injociton Wells & Perry Nuclear Power Plant, Cleveland,OH," reprinted from Aug. 1988. Geology magazine. AHMAD,M.U. Ohio Univ., Athens, OH. 88/08/31, 4pp. 47902.355.47962:358.
- 8812300014 Forwards corrected copy of 880622 forwarding fir of Director Docslon DD-89-10 to replace incorrect distribution copy of subj lit. PERKINSKE. Project Directorate III-3, 86/08/29. MURLEY,T., SNIEZEKJ, WIRAGLIA,Z NRC · No Detailed Affiliation Given. 1p. 47962:325-47982-341.
- 8812300022 Forwards per 030701 tolcon request Director Ducisian DD-88-10 ro alleged selsmic inadequacies at plant.
 HÖEFLING,R.K. Olitica of the Ganaral Counsol 88/07/06. SILBERG,J.E. Shaw, Pittman, Polits & Trowbridge. 12pp. 47982:342-47982:353.
- l. Inspection reports, IE Bulletins & correspondence
- 81130026\$ Forwards relief request to insorvice insp program,per NRC 880209 ltr.Fee
- pald. KAPUAN,A. Cleveland Electric Illuminating Co. 88/11/18. Document Control Branch (Document Control Desk). 48pp. 47680:341-47681:028.
- 811230277 Responds to NRC 881021 ltr re violations noted in Insp Rept 50-440/88-14. Corrective actions plant Administrative Procedure PAP-0512 re radiation work permits will be modified & radiatogical controls training enhanced KAPLAN.A. Cleveland Electric Illuminating Co. 88/11/21. Document Control Branch (Document Control Desk). 2pp. 47652:120-47652:121.
- 811180211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list encl. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870720) 68/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708.255-47708/267.
- 811160487 NRC Info Notice 88 091, "Improper Administration & Control of Psychologi-cel Tests." Svc list encl. ROSSI.CE. Division of Operational Events Assessment (Post 870411), 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp 47708/042-47708:142.
- \$11290060 Forwards supplemental response to violation noted in Insp Rept 50-440/ 88-08.per 881025 request Failures to use &/or adhere to procedures required by 10CFR50.App B not result of lack of knowledge that procedures must be followed KAPLAN, A. Cleveland Electric Illuminating Co. 88/11/23. Document Control Branch (Document Control Desk). 2pp. 47682:358-47662.359.
- 811290030 NRC Info Notice BB-093, "Telethorapy Events." Syc list enct. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Salety (Post 870729). BB/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 311290538 NRC Info Notice B8-094, "Potentially Undersized Valve Actuators." Svc fiet
- enci. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 312060280 Informs that util Immediately enacting listed interim operation changes based on agreements reached at 881122 meeting. KAPLAN, A. Cleveland Electric illuminating Co. 88/12/02. Document Control Branch (Document Control Desk). 1p. 47741:228-47741:228.
- \$12020287 NRC Into Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Svo list enci.
 ROSSI,CE, Division of Operational Events Assessment (Post 870411). 88/12/08.
 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 112090270 Forwards Amend 18 to License NPF-58 & safety evaluation. Amend allows one-time extension re disassembly & insp of turbine controllutible stop, low pressure turbine intercept & low pressure turbine intermediate stop valves.

 COLBURN,T.G. Project Directorate III-3. 88/12/08. KAPLAN,A. Cleveland Electric Illuminating Co. 2pp. 47762:193-47762:202.
- 8812090271 Amend 18 to Licenso NPF-58, allowing one-time extension for disassem-by & Insp of turbine control turbine stap tow pressure turbine intercept & low pressure turbine intermediate stop valve until first rotueling outleg. HANNON, J.N. Project Directorate RI-3, 88/12/08, 5pp. 47782:195-47782.198.
- **8812090275** Safety evaluation supporting Amend 15-3 License NPF-58.
 * Office of Nuclear Reactor Regi^{ol}stron, Director (Past 870411), 88/12/08, 3pp. 47762,200-47762;802.

- 8812200062 Responds to violations coted in Insp. Rept. 50-440/88-16. Corrective action. Feedwaler pump Biplaced in master level control. KAPLAN, A. Cleveland Electric Illium nating Co. 88/12/19. Document Control Branch (Document Control Desk). 3pp. 47860-237-47880-239.
- 8812270123 Forwards Safety Insp Rept 50-440/88-18 on 881107-10 & not.ce of viole-GREGER, L.R. Region 3, Old of the Director 88/12/15 KAPLAN, A. Clovoland Electric Illuminating Co. 2pp. 47927.064-47927-075
- --8612270127 Notice of violation from inspirent 861107-10 Violation noted. Conductivity Recorder IP33-R197,Dissolved Oxygen Recorder IP33-R198 & Sodium Recorder IP33-R398 found inoperator for periods of time ranging from 2.5 to 6 months GREGER,L.R. Region 3, Old of the Director. 88712/15. 1p. 47927-066-47927:066.
- -8812270131 Insp. Rept. 50-440/88-18 on 881107-10 Violation noted Mejor arous inspected chamistry program including procedures, organization & training reactor sysweter QC programs QA/QC programs in lab & nonzed otagical confirmatory measure-HOUSE, J.E., SCHUMACHER, M.C. Region 3, Ofc of the Director, 88/12/14, 9pp. 47927.067-47927.075.

R. Periodic operating reports & related correspondence

- 8812060249 Forwards "Eighth Quarterly Rept CEt Seismic Monitoring Notwork for Jul-Sept 1988," for CEI operated Micro bot, monitoring area in vicinity of two waste injudtion wells about 3 milos south of plant site
 KAPLAN,A Clayeland Electric III, minasting Co. 88/11/28, Document Control Branch
 (Document Control Desk), 2pp. 47742.257-47742.277.
- -8812060261 "Eight Quarterly Ropt CEI So'smic Monitoring Network Jul-Sop 1988."

 * Weston Geophysical 66/09/30 Creveland Electric (furrinating Co. 10pp. 47742:259-47742.277.
- 8812200187 Monthly operating rept for Nov 1988 for Porry Nuclear Power Plant Unit 1.W/881215 ltr.
 DUNN.G.A., KAPLAN,A Cleveland Electric Illuminating Co. 86/11/30. 7pp. 47859:344-47859:350.
- 8812290286 Final response to FOIA request for documents Forwards App B & C documents App A & B available in PDR-App C & D partially & totally withheld-respectively (ref FOIA Examptions 6 & 5, respectively).
 GRIMSLEY,D.H. Division of Freedom of Intermation & Publications Services (Post 880515), 88/12/20, HIATT,S. Oilyo Citizons for Responsible Energy, App. 47902:186-47962:227.
- -8703110292 Forwards "Quarterly Progress Rept Cloyoland Electric filturninging Solsmic Monitoring Progrem for Northassian Oblo 861015-870116," per request. RELTER,L. Risk & Reliablisty Assessment Branch. 87703709, AHMAD,M. Ohio Univ., Athons, OH. 1p. 47962 263-47962 263.

S. Reportable occurrences, LERs & related correspondence

- 8812050060 Forwards LERs 88-042-00 & 88-037-01.

 KAPLAN,A. Cleveland Electric Illuminating Co. 88/11/18 Document Control Branch (Document Control Desk), 1p. 47695.326-47695-331.
- -8811220208 LER 88-042-00 on 881021 reactor protection ays actuation occurred due to APRM channel exceeding neutron flux-figh soldown life solpoint Caused by local power range monitor letters False channel removed from sec.

 DUNN,G.A. Cleveland Electric fruminating Co. 88/11/21, 2pp. 47695-327-47695-328.
- -8812050067 LER 88-037-01:on 880918,automatic shift of control room HVAC sys to amergency recirculation mode occurred due to high toxic gas ararms from two of four ethylene oxide detectors. Caused by exhaust tumos from auxiliary bottom. DUNN,G.A. Cleveland Electric lituminating Co. 88/11/18. 3pp. 47895;329-47695.331.
- 8811290107 LER 68-043-00.on 981030,HPCS pump room coolor Inadvertently started during performance of breaker retest.Caused by procedural deficiency Rolest guidelines will be added to generic electrical instructions for maint.W78B1126 ltr. DUNNGA, KAPLANA Cloveland Electric Illuminating Co. 88/11/26. 3pp. 47667-202-47667:204.
- 8812270057 Forwards LERs 88-044-00 & 68-045-00 KAPLAN,A. Clavaland Electric Iliuminating Co. 88/12/18. Document Control Branch (Document Control Dask), 1p. 47924:190-47924:198.
- -8812190358 LER 88-044-00.on 881116.12 Inches of tire wrep on cable trays in control complex discovered missing Caused by inadequate design Fire watch established Cable tray wrap extended to Interface wifer seal. DUNN,G.A. Cleveland Electric iffurminating Co. 88/12/10. 3pp. 47924:191-47024:193
- -8812270062 LER 88-045-00 on 881121, both trains of standby liquid control aye became inoperable when concentration of sodium pentaborate abution exceeded Tech Spec requirements Caused by program deficiency. Guidelines added to proce-DUNN,G.A. Cleveland Electric Illuminating Co. 88/12/16, 3pp. 47924;184-47924;196.

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8811280048 Generic Lir 88:20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities 5vo its CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728;303-47729.024.

- 8812090091 Forwards safety evaluation in response to util response to Part 1 of Item 2.2 to Generic Ltr 83-28. "Equipment Classification for All Other Safety-Related Com
 - ponents** COLBURNITIG. Project Directorate I'l-3: 88/12/08: KAFLANIA: Clavatand Electric Illuminating Co. 2pp. 47788-305-47786-326
- 8812290266 Final response to FOIA request for documents Forwards. App. 8 & C. documents App. A & B. availatile in POR App. C & D. partielly & totally withit of respectively fref FOIA Exemptions 6.8.5, respectively:
 GRIMSLEY, D.H. Dwisson of Freedom of Information & Pubrications Services (Post 880515), 88/12/20 HIATTLS Offic Citizens for Responsible Energy. 8:pp. 47962-186-
- --8805030507 Forwards SER denying OCRE 2.206 petition for immediate action to relieve undue risk posed by inadequate seismic design of plant Suspension of Todase pending additious (geological & geophysical) & engineering review unwarranted. BAGCHIG. Studucial & Geosciences Branch. 28704728. PERKINS,K.E. Project Directorate III-3, 6pp. 47962.320-47952.324.
- -8808310058 Forwards Earthquakes,injection Wells & Perry Nuclear Power Plant, Cleveland, OH, "which appeared in Aug 1988 Geology magazine. Article conclusions w/o basis & merely used to attract attanton." REITER, L. Structural & Geosciences Branch 88/09/29 BAGCHIG, RICHARDSCNJ, SHAOLL NRC No Detailed Afficiation Given 1p. 47882,354-4365-2388. 47962:358
- 8808310128 "Earthquakes,injection Wel's & Perry Nuclear Power Plant, Cleve'and,CH," reprinted from Aug 1988 Geotogy magazine AHMAD,M U. Ohlo Univ., Athens, OH. 88/08/31, 4pp. 47962-355-47962,356. -8808310128
- --8812300014 Forwards corrected copy of 880622 forwarding fit of Director Decision DD-88-10 to replace incorrect distribution copy of sub, ff: PERKINSK E Project Directorate III-3, 88/06/28 MURLEY,T., SAIEZEK,J., MIRAGUIA,Z. NRC No Delated Attlabon Grzen tp. 47962-325-47962-341.
- -8812300022 Forwards per 880701 telcon request Director Decision DD-88-10 re atleged so smic inadequacies at plant.
 HOEFLING.R.K. Office of the General Counsel #8/07/06 SILBERG.J.E. Shaw, Pilt. man. Potis & Trowbridge 12pp, 47962 342-47962 353

F. Security, medical, emergency & fire protection plans

- 8811290183 Forwards final rept of 880504 full participation exercise of offsite radiological emergency response plans No deliciencies observed & eight areas requiring corrective action identified
- Notice action tentimes KRIMM,R.W. Federal Emergency Management Agency. 88/11/02, CONGEL,F.J. Deu-sion of Rediation Protection & Emergency Preparedness (Post 870411). 1p. 47664 071-47664:158.
- -8811290191 "Fina" Rept of 880504 Perry Nuclear Power Plant Joint Exercise "
 Federal Emergency Management Agency, 88/10/20, 88pp. 47664,072-47664;158.
- 8812050292 Revised "Emergoncy Public Into Organization Implementing Instructions Manual "W/8812011tr.
 HEFFNER,G., KAPLAN,A. Cleveland Electric Illuminating Co. 88/11/07 144pp.
 47723 226-47724,099.
- 8812080049 Rev 9 to "Emergency Pian for Perry Nuclear Power Plant" W/ 881130 ltr. ANDERSONJO, KAPLANA Croveland Electric Huminating Co. 88/11/29, 544pp. 47735.037-47736 220.
- 8812090108 Forwards FEMA 881102 ftr re-indings for oitsite emergency preparedness aspects of plant exercise conducted on 880504. FEMA identified no delictencies in performances of citisite agencies during exercise. GREGER, I. R. Regen 3, Ot of the Director 88/12/05. KAPLAN,A. Cleveland Electric Ithurmating Co. 2pp. 47761.290-47762.018
- 8812140189 Advises util to take listed corrective actions re evacuation instructions in accordance w/FEMA recommendations during next annual update of emergency into handbook.Commitment to making corrections requested within 30-days. HANNON,J N. Project Directorate III-3, 88/12/06, KAPLAN,A. Cleveland Electric IIIIuminating Co. 3pp. 47821.004-47821.043.

G. Adjudicatory correspondence

- 8812020147 Forwards final Director's Decision on issues contained in 880725 supplemental polition re-public into on plant. Petrion denied based on considerations raised in 880725 suppl.

 MURILEY.T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/29 KLINE,C., BURLING,T., O'CONNELL,R. Affiliation Not Assigned, 3pp. 48092,333-48092,334.
- ~8812020150 Final Director's Decision DD-88-19 granting petitioners request re improvements in emergency preparedness program. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/29 14pp. 48092
- --8812020154 Notice of issuance of final Director's Decision re 870922 petition for util to correct efleged defictencies in public into handbook on emergency planning for plant. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/29, 2pp. 48092:354-48092:355.

H. General correspondence

8612010266 Commont on proposed rule 10CFR26 refilness for duty program. Util in agreement w/majority of comments submitted by NUMARC & Nuclear Util Backlitting & Reform Group.

KAPLAN A Cloveland Electric filtuminating Co. 88/11/18 Docketing & Services Branch. 8pp 47679:131-47679:138

P. Operating Ilicense stage documents & correspondence

8812090093 Safety evaluation documenting NRC review of ficensee response to General Ltt 83:28 Evaluation concludes that licensee adequately meets provisions of Part 1 of Item 2.2 to Generic Ltt 83:28.

* Office of Nuclear Reactor Regulation, Director (Post 870411), 89/12/96 360 47786.307-47789:326

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gaugos." Svc hist encl CUNNINGHAM,R E. D.viston of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255 47708:257.
- 8811160467 NRC Info Notice 68-091, "Improper Administration & Control of Psychologi-ROSSICE Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708.142.
- 8811290030 NRC Info Notice 68-093, "Tetelhorapy Evonts." Svc Fet and. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Satety (Post 670729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103 47811 255.
- 8811290538 NRC Info Notice 88-994, "Potentially Undersized Valve Actuators" Syc hat enci ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp 47708:143-47708:254
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors." Sec list end.
 ROSSICE. Division of Operational Events Assessment (Post 870411), 88/12/08.
 Censol/dated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.

R. Periodic operating reports & related correspondence

- 8812080249 Forwards "Eighth Quarterly Rept CEI Seismic Monitoring Netwerk for Jul-Sept 1988," for CEI operated Micro-not, monitoring area in vicinity of two was/a hypo-tion well's about 3 miles south of plant site. KAPLANA: Clayeland Electric Illuminating Co. 88/11/28. Document Control Bishoch (Document Control Dask), 2pp. 47742:257-47742:277.
- -8812060261 "Eight Quarterly Rept CEI Selsmic Monitoring Network Jul-Sep 1988."
 Waston Geophysical 88709730. Cleveland Electric Huminating Cc. 10cp. 47742;259-47742;277.
- 8812290286 Final response to FOIA request for documents Forwards App. 8 8 C documents App. A 8 B available in PDR.App. C 8 D partially 8 totally withheld itespectively (ref. FOIA Examptions 8 8 5, respectively)
 GRIMSLEY.D.H. Division of Freedom of Information 8 Publications Services (Fost 880515), 88712720. HIATT,S Ohio Citizons for Responsible Energy, 8pp. 47962-186-47962-227.
- ~8703110292 Forwards "Quartorly Progross Rept.Clovoland Electric Illuminating Seis-mic Monitoring Program for Northeastern Ohio 661015-870115," per request REITER,L. Risk & Rellability Assessment Branch. 87/03/09, AHMAD,M. Ohio Univ Athens, OH. 1p. 47962:263-47962:263.

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812140002 Roys 41 & 42 to "Production Emergency Response Manual." W/681209 MACOONALD,J.A., THCIMAS,G.S. Public Service Co. of New Hampshire. 88/11/22, 193pp. 47799:307-47800:139.
- 8812190044 Seacoast Anti-Pollution League response to applicant interrogatorios & request for production of documents to all interveners & participating local govts to contentions....* W/rolated into & Svc list.Rolated correspondence.

 DOUGHTY,J. Seacoast Anti-Pollution League, #488 7829, 88/12/05 Publ.c Service Co of New Hampshire, 48pp. 47802.107-47802:152.
- 8812140191 Forwards Safety Insp. Rept. 50-443/88-13 on 888907-1017 & notice of violation Violation re Identification of & fallure to rept non-Class 1E load powered from Class 1E source which had not been tested per Tech Space.
 WIGGINS,J.T. Region 1, Ofc of the Director, 88/12/06, BROWN,E.A. Public Service Co. of New Hampshire, 3pp. 47813:352-47814:031.
- ~8812140194 Day & Backshifts Insp Rept 60-443/88-13 on 880907-1017.Mejor treas inspected:operational safety.NRC temporary instructions.previous insp findings.NRC bulletins & into notices & potentially reportable occurrences.

 HAVERIKAMP.D.R. Region 1, Ofc of the Director, 88/11/29, 31pp. 47814001-
- 8812270067 Motion in limine of Commonwealth of MA atty general re FEMA post-exercise evaluation & assessment rept.* Board should grant motion & direct FEMA to provide details of destruction documents.W/eupporting documentation & Certificate of Svc. TRAFICONTE, J.M. Massachusetts, Commonwealth of, #488 7703, 88/12/13 Atomic Safety and Licensing Board Panel, 22pp. 47872:327-47872:348.
- 8812270099 Motion for reconsiduration of memorandum & order-Part I (ruting on contentions on Seabrook plan for Commonwealth of MA communities).* Contentions 65 & 76 should not be rejected per ALA8-965 W// uprocring info & Certificate of Svc. TRAFICONTE,J. Massachusatts. Commonwealt. of #488-7705. 88/12/16. Atomic Safety and Licensing Board Phone. 18pp. 4/8/2.199-47872.216.

motion for schodure.1 Applicant motion should be deficed on basis that LLCO plan aheady fully digated. Supporting documentation & Certificate of Security and TRAFICCNTE.J. Massachusetts, Communication of #40s. 7726 88/12/19 Atomic Safety and Licensing Board Panel 50pp. 47885 078-47985 136.

3812210294 Final response to FOIA request for records App A records encl & available GRIMSLEY.D.H. Division of Freedom of Information & Publications Services (Fost 880515) 88/12/20 BELAIR,R.R. Kirkpatrick & Lockhart BELAIR,R.H. Suffolk County, NY, 2pp. 47874:049-47874.056

-8812210298 "Shoreham Seabrook Exercise History" NRC - No Detailed Affidation Given 88/12/20, 4pp 47874 051-47874 056

G. Adjudicatory correspondence

8812020092 City of Newburyport request for limited participation status.* Served on 881125.Granted for Board on 881125.

SAINT ANDRE,B. Newburyport, MA. #468 7562 88/11/16. Atomic Safety and Licensing Board Panel. by 47643 284-47640 264

6812020044 NRC Staff response to applicant motion for summary disposition of Joint Intervence Contentions 44A & 44B.* Efficient conduct of proceeding requires that filling ation continue under erailsminule Conflicate of Svc enct. SC-NTOJF. Assistant General Counsel for Heavings #488 7566 98/11/21 Atomic Safety and Licensing Board Panel. 8pp. 47643 151-47643 159

8812020062 Advises that person designated to receive copies of proceedings changed from author to S Brotseth at stated address. PEVEAR,R.C. New Hampshire, State of: #488 7580 88/11/21 Docketing & Servicus Branch 1p 47643

- 8812020166 Applicant answer in opposition to Commonwealth of MA alty general motion to compel answers to interregatories.* Median should be decided Certificate of SVITH.J.B. Public Service Co. of New Hampshire SMITH.J.B. Ropes & Gray. #488 7573. 88/11/21. Atomic Safety and Licensing Board Panel. 11pp. 47644.320.
- 8812020163 Applicant advice to Commission * Advisos Commission that on 881116,ap. plicant board of directors approved MOU between util 8 Messachusetts Missic pal Windess's Electric Co W/ Certificate of Svc.
 SELLECK,K.A. Public Service Co of New Hempshire SELLECK,K.A. Ropos 8 Gray. #488 7574, 88/11/21, 4pp. 47844:333-47644:338.

- 8812020060 Seacoast Anti-Pollution League comments on significance of ALAB-903 to exercise contentions. Svc list and. BACKUS,R.A. Seacoast Anti-Pollution League. BACKUS,R.A. Backus, Muyer & Solution From #486.7550. 88/11/22. Atomic Safety and Licensing Board Panel. https://doi.org/10.1006/10.1
- 8812020074 Town of West Nuwbury response to NRC Staff motion to compet answers to interrogatories & production of documents by fown of West Newbury.* Certificate of
 - SVERIJH. West Newbury, MA #488 7553 88/11/22. Office of the General Coun-sel. Spp. 47643:209-47843:217.
- 8812020081 Town of Hamption (TOH) & New England Coalition on Nuclear Pollision (NECNP) response to Board order dtd 881114 to TOH/ NECNP Ex. 1.* Requests admission of Exercise Contention Ex. 1. W/Contribute of Syc. BROCK.M.T. Hampton, NH. BROCK,M.T. New England Coalition on Nuclear Pollution BROCK,M.T. Shaines & McEachern. #468 7554, 88/11/22. Atomic Safety and Licensing Board Panel. 8pp. 47643 226-47643:232.
- 86 12020064 New England Coalition on Nuclear Pollution comments on aignificance of ALAB-803 to Soabrook offsite exercise contentions.* Svc list enci. CURRAND, New England Coahition on Nuclear Pollution CURRAND. Harmon, Curran & Toustay. #488 7563. 88/11/22. Atomic Satety and Licensing Board Panel 9pp. 47643:241-47643:249.
- 8812020089 Responses of FEMA to town of Amesbury first set of interrogatories & request for production of documents to FEMA on Seatrook plan for Commonwealth of MA communities." W/Confilicate of Svc. Related correspondence FLYNN,HJ, Federal Emergency Management Agency #488 7569, 88/11/22 Amesbury, MA, 14pp. 47643-250-47643-263.
- 8812020019 Applicant memorandum in response to 881114 Board memorandum * Inter-
- venors contentions should be disposed of as set forth in applicant response to intervenors contentions on June 1988 exercise W/Continuate of Svc.

 SMITH_J.B. Public Service Co. of New Hampshire. SMITH_J.B. Ropes & Gray #488
 7655. 68/11/23. Atomic Safety and Licensing Board Panel. 31pp. 47643.043-
- 8812020110 Comments of Commonwealth of MA Atty General on significance of ALAB-903 on exercise (it.gation.* Requests oral argument prior to decision on admissibility of exercise contentions. Certificate of Svc encl.
 TRAFICONTE_J. Messachusetts, Commonwealth of. #488-7575-88/11/23. Atomic Salety and Licensing Board Panel. 18pp. 47844:075-47644.090.
- 8812020117 NRC Staff response to 881114 Board order requesting comments on significance of ALAB-903 for Seabrook proposed general exercise contentions.* Contentions & bases should be denied. Certificate of Svc enct. CHAN,E.I. Assistant General Counsol for Hearings. #488 7565, 88/11/23. Atomic Safety and Licensing Board Panel, 13pp. 47644.091-47644.103.
- 8812020149 Forwards documents ret in RW Donovan 881109 & 10 deposition, including forms on which results of interviews verifying itre of agreement recorded.W/o stated documents Certificate of Svc encl. Related correspondenco. FLYNN,HJ. Federal Emergency Management Agency. #488 7572 8B/11/23. TRAFICONTE,J. Massachusetts, Commonwealth of. 7pp. 47644:313-47644-319.
- 8912020025 Motion of Commonwealth of MA Aity General JM Shannon for leave to file document not authorized by Commission rules of practice.* Requests to life response to joint applicant & NRC response to atty general 881 102 motions JONAS, S.A. Massachusetts, Commonwealth of. #488 7576, 88/11/25 Commissioners, 3pp. 47643;084-47643;126.

- Staff 8 joint applicants in response to 861102 motions under 10CFR2 734 to respon-record *Commission should reject NRC 8 applicant arguments JCNASS A Massachusetts, Commonwealth of 88/11/25 Commissioners 17pp 47643 097-47643 103
- --8812020051 Alfulavit of Peter M Strauss* Responds to J Potersen, PB Eriksen & LI Kopp alfudavits Supporting documentation & Certificate of Svc anci STRAUSS.P.M. Massachusotts, Commonwealth of STRAUSS.P.M. MHB Tectinical Associates 88/11/22 22pp 47643 104-47643 125
- 8812140023 NRC Staff response to Ucentring Board order of 881025 * Joint Interveneral motion to reopen record should be denied & emergency planning contention should not be admitted for kingation.
 BERRY,G.A. Assistant General Counset for Hearings. #488-7592, 88/11/28-12pp. 47770.040-47770.072
- -8812140030 Alfidavit of GJ Conkin & DG Ruscitto to Joint Intervences motion to reopon record to admit lato-filed contention challenging certain assets of applicant rad glogical emergency response plant My/Certal cale of Sv. CONKTINCO. Region 1, Oto of the Director, 19USCHTO, D.G. NRC - No Detailed Aftipallon Gruin 88/11/28, 21pp. 47770.052-47770.072
- 8812140028 Applicant motion to compot responses from Commonwealth of MA atty general to applicant request for admissions.* Request should be compelled Cartificate of Syc engl. TROUT J.P. Public Service Co. of New Hampshire TROUT J.P. Ropes & Gray. #488 7588, 88/11/28. Atomic Salety and Licensing Board Panel Upp. 47/69.257
- 8812140034 Applicant motion to compet answer from Joint Intervences to applicant re-quest for admissions? Proper answer should be competted Certificate of Svc encil SELLECK, K.A. Public Service Co. of New Hampstire. SELLECK, K.A. Ropes & Gray #489.7589. 88/11/28. Atomic Safety and Licensing Board Panel. Spp. 47769.252-7789.7589.
- 8812140057 Applicant motion to compel production of documents by Commonwoa'th of MA atty general.* Order should be issued compelling production of all documents responsive to applicant second request Certificate of Sec enci.

 18001.J.P. Pubic Service Co. of New Hampshire. 18001.J.P. Repect & Gray. #488
 7500—88711728. Atomic Safety and Liconsing Board Panel. 11pp. 47793.227-4770.227. 47760 237.
- 8812020127 Decision * Altirms Board 880808 Momorandum & Order LBP-88-20 determining that RG-58 cable issue rued not be resolved prior to authorization of low power operation of facity. Sorved on 681129.

 9HOEMAKER.C.J. Atomic Safety and Licensing Appeal Panel #488 7578 88/11/29 10pp. 47644 106 47644 115.
- 8812140126 Applicant motion for leave to life applicant response to miswer of Commonwealth of MA afty general in opposition to applicant motion for summary disposition of Joint Intervent Contentions 44A & 44B ** SMITH.J.B. Public Service Co. of New Hampshire SMITH.J.B. Popos & Gray. #488 7626 88/11/30. Alomic Safety and Liconsing Board Panel 2pp. 47930.231-

47930 304

- -8901030055 Applicant response to answer of Commonwealth of MA utty general in apposition to applicant motion for semmany disposition of Joint Intervenor Contentions 44A & 44B (answer). Whethicate of Svc. SMITH_JB Public Service Co. of New Hampshire SMITH_JB Ropes & Gray 887117 30. Atomic Safety and Licensing Board Panel. 22pp. 47930:283-47930.304.
- 8812190084 Ack receipt of applicant motion to compel responses from Commonwealth of MA atty general to applicant request for admissions 8 maion to compol answer from Joint Intervenors, dtd 89.1128 NRC does not inlend to respond to motions. TURK,S.E. Assistant General Counsol for Hearings #488 7637, 88/11/30 SMITH.IW., HARBOUR.J., LINENBERGER.G. Atonic Safoty and Licensing Board Panel 1p. 47892.155.47802.155.
- 8812140020 NRC Staff response to Commonwealth of MA atty general request for leave to tile reply to responses of applicant 8 NRC Staff. Request should be defiled Certificate of Sive enci.

 BERRY, G.A. Assistant General Counsel for Hearings. #488-7585-88/12/01. Commissioners. 8pp. 47769:280-47769:273
- 8812140037 Applicant response to motion of Massachusutts Atty General JM Shannon for feave to file document not authorized by Commission rules of practice." Moton should be denied. Certificate of Svc and, DIGNAN, T.G. Public Service Co. of New Hampshire, DIGNAN, T.G. Ropes & Gray. #488 7619. 88/12/01. Cammissioners. Spp. 47770 173-47770.177.
- 8812140043 Applicant answer in opposition to Commonwealth of MA atty general (AG) motion to compet answers to Commonwealth of MA AG second set of Interregatories.* Motion to compet answers should be denied Certificate of Size encl. TROUT.J.P. Public Service Co. of New Hampstire. #488 7591, 88/12/01. Atomic Satety and Ucensing Board Panel. 14pp. 47769.238-47769.251.
- 8812140087 Memorandum & order.* Alty general of Commonwealth of MA appeal from Licensing Board 881012 momorandum & order dismissed as promature Served on SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #488-7598-88/12/01. Massachusetts, Commonwealth of. 8pp. 47770.222-47770:229.
- 812190002 Advisos that NRC Staff received responses from towns of Amosbury,Newbury,West Newbury & Merrimac & city of Newburyport to NRC first set of interrogatories & List request for production of documents.

 BERGQUIST,S.A. Assistant General Counsol for Hearings. #488 7645. 88/12/01 SMITH,I.W., HARBOUR,J., LINENBERGER,G. Atomic Safety and Licensing Board Panel. 1p. 47802 206-47802 206. 8812190002
- 8812190152 Opposes granting of Commonwealth of MA atty general 881129 request to addi opportunity to support preposed general exected contentions on grounds the Board geve parties apportunity to submit comments on or before 881123 CHAN,E.1. Assistant General Counsel for Hearings. #480 7644 89/12/01 SMITH.LW, HARBOURD, LINENSERGER,G. Alomic Safety and Licensing Board Panel. 2pp. 47801:097-47801:098.

- 8812143114 Discusses impact of ALAB 903 on exercise flighton. Applicant offered no interpretation of ALAB 903 but instead the additional elegation to content on Restrates listed points. The FICONIE J. Massachusetts, Commonwealth of #468 7617 88/12/02 SMINTENT HARECURIS, LINETABERGERG. Along a Safety and Licensing Board Panel 3pp. 47770 083-47770 085.
- ~8812140124 Advises that Commonwealth of MA atty general ofc established encl policy & procedures to ensure that protected into received reighant beensing proceed. Ings not disclosed to unauthorized persons.

 SHARYON J.M. Massach iserts. Commonwealth of 89/12/02 SM/TH, I.V., LINER/BERGER, CHARBOUR, J. Alomb. Safety and Licensing Board Panel. 4pp. 47770 066-47770 069.
- **8812140128 Motion for reconsideration & for clarification 1 in event Board elects to maintain sanction in piece Commonwealth of MA move Board to deathy meaning FERCE, A.R. Massachisetts. Commonwealth of 89/12/02, Atomic Safety and Licensing Board Panet, 16pp. 47770 059, 47770 105.
- -8812140135 Affidavit of PiTafbotize applicant interrogatory on buses. Certificate of Svo TALBOT, P. Massachusetts, Commonwealth of 88/12/02, 9pp. 47770 106-47770 114.
- -8812140148 Expresses apprehation for cooperation in provensing Page 7 of Commonwealth of IMA aity general supplemental response to applicant first set of interrogationes from public disclosure. TALBOT, Plassactivisetts, Commonwealth of 88/10/19. JULIAN,E. NRC No Detailed Affiliation Given inp. 47/70.115-47/70.115.
- -8812140151 Affidant of EU Keough re supplemental response to applicant fest set of interrogationes which inadvertently contained protected info Cersi cate of Svc encl. KECLGHE J. Massactivisets. Commonwealin of 88/12/02 6pp 47770.118-
- 8812190206 Forwards State of NH fourteenth suppremental order of notice re-plant do-commissioning fund Retaind correspondence. HAFFER A Sheetan, Phoney, Bass & Green, Professional Association, #488 7668 88/12/02 NRC No Detailed Affication Given 3pp. 47801 019 47601 021
- 8812190044 Seacoast Anti-Pollution League response to epplicant interrogationes & request for production of documents to all intervenors & participating focal govts re-contentions. Wirefated into & Six List Realed conespondence OCUGHTY J. Seacoast Anti-Pollution League, 4488, 7629, 89/12/05. Public Service Co. of New Hampshire. 45pp. 47802, 107-47802,152.
- 8812190080 Supplemental response to applicant first set of interrogationes & supplemental response to applicant interrogationes & request for production of documents to all intervenors. * Size I st ancil Related correspondence.

 DOUGHTY,J. Seacoast Anti-Polition League #469 7630, 88/12/05. Public Service Co. of New Hampshire. 6pp. 47601-203, 47801-208.
- 8812270028 Petrion for thRC review & evaluation of 6.4 magnitude Quebec.Canada earthquake for express purpose of comparative analysis w/safe studdown earthquake (SSE) of Seatorot, unitie & "Certylicate of Sive and Served on 881215 WEINHOLD,E.D. Affiation Not Assigned, #488.7677 88/12705 Atomic Safety and Licensing Board Panel 1390, 47873.119.47873.131.
- 8812190014 Memorandum & order (motions for leave to Fle responses re summary dis-position of Joint Intervenor Correntions 44A & 44B)* Grants applicant & Common-weal th of MA leave to Fle responses Served on 681206 SM-TMJ.VI. Atom'c Safety and Licensing Board Panet. #488 7628. 88/12/06. Massa-chusetts. Commonwealth of 2pp 47802.105 47802.105
- 8812190048 Memorandum & cider (ruing upon applicant motion for summary disposition). Applicant 660909 motion for summary disposition granted & New England Coelibon on Nuclear Pollution Conference 18.2 dismissed Served on 881208. WOLFE,S.J., HARBOURJ, LUEBKE E.A. Alomo, Safety and Licensing Board Panol. #488 7635—88712707. Office of the General Course! 23pp. 47602 161-47602 183.
- 8812190071 Forwards corrected Page 5 for insertion in NRC response to Board 881114 order requesting comments on significance of ALAB-903 for plant proposed general exercise contembors, drd 881123 TURK, SE Assistant General Counse' for Hearings. #488 7639, 88/12/07. SMITH, LW. HARBOUR, J., LINENSERGER, G., Atomic Safety and Licensing Board Panet. 2pp 47802:153-47602:154
- 8812190205 Joint Intervenors motion for leave to submit response to NRC Statt re-sponse to Licensing Board order of 881025° Leave requested to the and response. JONAS,S.A. Massachusetts, Commonwealth of JONAS,S.A. Hampton, NH. JONAS,S.A. Naw England Coat too on Nuclear Polition. #488.7669 88/12/07. Atomic Safety and Licensing Board Panel, 3pp. 47801.022-47801.034.
- -8812190215 Joint Intervenors response to INRC Stell response to Board order of 881025.* Onsite exercise contention should be admitted for lingation Certificate of Svo
- BOWAS,S.A. Massachusetts. Commonworith of JONAS,S.A. Hampton, NH. JONAS,S.A. New England Coalison on Nuclear Pollution 88/12/07. Atomic Salety and Licensing Board Panel. 10pp. 47801.025-47801.034.
- 8812190113 Advises that NRC agrees that listed flown of Amesbury draft documents need not be produced per conversation earlie; in wk Related correspondence. BERGQUIST'S A. Assistant General Counset for Hearings. #488 7662. 88/12/08. SAINT ANDRE,B. Kope/man & Paige. 1p. 47802.083-47802.083.
- 8812190144 Commonwealth of MA aity general motor to compel response by FEMA to interrogatories & requests for production of documeras.* Atty general moves that order be issued comporting FEMA to respond to discovery.W/Svc list.

 SNEIDERIC S Massachusetts. Commonwealth of Mala 7684, 88/12/08. Atcmic Satety and Ucensing Board Panel, 6pp. 47601.099.47801:104.
- 8612190001 Reply by FENA to Commonwealth of MA alty general motion to compete response by FEMA to interrogationes & requests for production of documents. * Motion to compet considered moot.

 FLYNN,H.J. Federal Emergency Management Agency. #498 7672. 88/12/09. Atomic Safety and Licensing Board Panet 1p. 47602 084 47602.104.

- -8812190004 Rosponsos of FEMA to Commonwealth of MA atty general tist set the terrogator as to FEMA concerning Seatmost plant for Commonwealth of MA (27). tass: FLYNN,H J. Federal Emiryponcy Management Agency. 88/12/09 Massar a Commonwealth of 10pp 47802 095 47802 094.
- 8812270097 Town of Ameshury request for limited participation status * Sesection 881216 Granted for Board on 881215 SAINT PIERRIE,B. Ameshury, MA. SAINT PIERRIE,B. Kopotman & Paige #443 Pill B8/12/09. Momik: Safety and Liconary Roard Pailot. 1p. 47872 217-1/872 217.
- 8812270079 Applicant revised required for admissions from Corningwesting May general." Supporting documentation & Cornificate of Svc and Refet (1999) enco TROUT, J.P. Public Service Co. of New Hampshire TROUT, J.P. Popes & Grey #43 7697, 88/12/12 Massachusotte, Commonwealth of Bop. 47872 297 4197 565
- 8812270031 Town of Newbury response to applicant second set of intercognisms to guest for production of documents f W. Cortificate of Svc Related consponders HILL-WHILTON R. Newbury, MA. #488-7689, 88/12/13, Public Service Co. (1) Newbury and Pampshing 16pp. 47873:103-47873.116.
- 8912270067 Motion in Immic of Commonwealth of MA alty general to FEMA poster cise availation & assessment rept.* Board should grant motion & direct FEMA logs wide delears of destruction documents W/supporting documentation & Configs a TRAFICONTE J.M. Massachusotta, Commonwealth of. #408 7703 68/12/13 Pty. Safety and Liconsing Board Panol. 22pp. 47872:327-47872 348
- 8812270101 Town of Nowbury responses to applicant interregatories & repositive of duction of documents to all intervenors & participating local govts to deal from the Contentions 8 & 27-63. W/Certificate of Svc Related correspondence intervenors & Newbury, MA 4488 7688, 88712/13 Public Service College Hampshire 12pp 47872 187-47872 198.
- 8812270137 Forwards document prepared by NRR Policy Davelopment & Artherser reapplicant Financial qualification to operato & decommission plan for Ling BERAY, G. A. Assistant General Counsel for Hearings #488-7710 (3/12/1) CHILK,S.J. Office of the Secretary of the Commission, 36pp. 47872-113 4787213
- 8812270093 Intervenous advice to Commission.* Discusses resolution of jortlea... interesting of Language and claims against applicant. Supporting documentation & Swrist end BACKUS.R.A. Spaceous Anti-Pollution League. BACKUS.R.A. Missierhers & Gommonweetth of BACKUS.R.A. Hampton, Nit. #488-7690. 88(12):14. 12pp 4001272
- 8812280160 NRC Staff motion to compol answers to interrugatories & producers a documents by Commonwearth of MA atty general.* Atty general should be corpleted to provide answers to interrugatories 2.4 & 10.14. TURK S.E. Assistant General Counsel for Hoerings. #488 7757, 88/12/14 Alexa Sefety and Licensing Board Panel. 11pp. 47884:222-47884:237.
- **8812280186 NRC Stall third set of interrogatories & request for production of documents." Advises that documents responsive to request will be available for rough of of commonwealth of MA aity general W/Certificate of Svc.
 TALBOT,P. Massachusetts, Commonwealth of .60/11/18. TURK,S.E. Assistal General Counsel for Headings. 5pp. 47884:233-47684:237.
- 8812270053 Momorandum & order (ruling on June 1898 general exercise contactors' Board will conduct proteoning conference on hitigation of 1898 exercise contactors of Commonwealth of MA may submit addit comments on ALAS-003 Served on 69/2/3 HARBOUR, J. LINENBERGER, SMITH, I.W. Atomic Safety and Licerses 23-24 Panel. #488 7693. 88/12/15. Office of the General Coursel 71pp 4/8/234 479/3-093.
- 8812270076 Town of Newbury request for limited participation.* Requests paints of participate in Litigation of Joint Interveners Contentions 4.7,8,45 & 60.Cert.(cere.et Science).
- MIZNER,J.H. Wost Nowbury, MA. #488 7698, 88/12/16. Atomic Safety and Leasing Board Pangl. 3pp. 47872 310-47872:312.
- 8812270087 Town of Newbury answers to applicant Interrogatories 8 respect to ye duction of documents to all intervenors 8 incorporating Joint Intervenor Contents 126 6 8 2 7-65.1 W/ Certificate of Svc.Related correspondence.

 MIZNER J.H. West Newbury, MA. 4488 7698, 88/12/15. Public Service Co. of her Hampshire. 19pp. 47872-266-47872-284.
- 8812270105 Applicant motion to compel answer to interrountery by Seacoast AntiPeta-lion League.* Certificate of Svc encl. TROUT,J.P. Public Service Co. of New Hampshire, TROUT,J.P. Ropes & Gray #463 7706. 88/12/15. Atomic Safety and Licensing Board Panel. 7pp. 47872-174-47872-180. 47872:180.
- 8812280156 Advises that NRC does not intend to file response to applicant motes for leave to the response to answer Commenwealth of MA atty general in Epocation's applicant motion for summary disposition of Contonitions 444 & 448.

 TURK,SE. Assistant Genoral Counsel for Hearings #488 7756. 68/12/15 SMITH,W., HARBOURJ, LINENBERGER,G. Atomic Safety and Licensing Board Panel. Ip. 47884-2921-47884-2921 Panel. 1p. 47884:221-47894:221.
- 8812280194 Advises that encl patition for review & evaluation of 6.4 magritude Chiebec,Canada earthquake for purpose of analyzing wisate stuttown earthquake for plant & evacuation planning rept should be denied,per 10CFR2.734.W/Certicale of Svc. plant & evecuation planning rept should be defined, you is a second of the second of t

ence. TRAF.CONTE.J. Messachusetts, Commonwealth of. #488-7704, 88/12/16 Public Service Co. of New Hampshire. 8pp. 47872:288-47872-293.

3812270099 Motion for reconsideration of memorandum & order-Part I (ruling on contentions on Seabrook plan for Commonwealth of MA communities).* Contentions 65 & 76 should not be rejected por ALAB-905 W/supporting into & Certificate of Svc. TRAF-CONTE.J. Massachusatts, Commonwealth of #488 7705 88/12/16. Atomic Saley and Licensing Board Pariet 18pp. 47872.198-47872.216.

8812270116 Applicant motion for schodule * Roquests that stated schedule be established for remaining contentions το 880828- 29 FEMA-graded exercise.W/Cont.cate of Svc.

SELLECK,K.A. Punks Service Co. of New Hampshire SELLECK,K.A. Ropes & Gray. #488 7707. 88/12/16. Atomic Safety and Licensing Board Panel. 13pp. 47872.161-

- 8812280146 Town of Newbury response to NRC Statt third set of interrogatories & request for production of documents to towns of Amesbury,Newbury,Saliebury,West Newbury & Merrimac & city of....* W/Contincate of Svc Rolated correspondence HTLL-WHC LTON.R. Newbury, M. #488 7731. 88/12/16. Office of the General Counsci. 17pp. 47884:248-47894:264
- 8812280085 Applicant motion to compel answers to interrogatories & production of docurrents by town of West Nowbury 1 Town should be compelled to provide complete answers on or before certain date Contribute of Svc encl.

 TROUT.J.P. Public Service Co. of Now Hampshire. TROUT.J.P. Ropes & Gray. #488 7742. 88/12/17. Atomic Safety and Licensing Board Panel 7pp. 47886.167-47898.187 47886 173.
- 8612280090 Forwards draft order memorializing oral rulings made by Board on 881213 te than-outstanding discovery disputes between applicant & atty general for Common-wealth of MA,por Board instructions
 TRCUT_J.P. Public Service Co. of New Hampsh ra TROUT_J.P. Ropes & Gray, #488
 7744. 89/12/17. SMITH,I.W., HARBOUR,J., LINENBERGER,G. Atomic Safety and Li-censing Board Pariel. 8pp. 47886:174-47886.179.

- 88 12270171 Order.* Advises that time for Commission to determine whether to review ALAB-892 extended until 801221 Served on 881220. CHLK.S.J. Office of the Secretary of the Commission. #488 7714. 88/12/19. Commissioners. 1p. 47872.081-47872.081.
- 8812270172 Order.* Advises that time for Commission to determine whether to review ALB-895 extended until 881221. Served on 881220. CHIK.K.S.J. Office of the Socretary of the Commission. #488 7715 88/12/19. Commissioners. 1p. 47872 030-47872 080.
- 8812270176 Memorandum (memortalizing rulings of prehearing conference on discovery matters held 881213). Discusses 881213 prohearing conference addressing unresolved discovery dispulsa in J Traflicante 881209 its Served on 881220. Atomic Sately and Liconsing Board Panel. #488 7716. 88/12/19. Spp. 47872.076
- 47872.070. 8812280001 Commonwealth of MA Atty General JM Shannon renowed motion to compel responses by FEMA to interrogatories & requests for production of documents. Conflicate of Svc encl.

 SNEIDERICS. Messachusoits, Commonwealth of #488 7723, 88/12/19. Atomic

Safety and Liconsing Board Panel. 19pp. 47885:136-47885:154.

- 8812280904 Commonwealth of MA alty general second supplemental response to NRC Staff first set of interrogatories & first request for documents.* W/Certificate of Svc.Related correspondence.
 TALBOT.P. Massachusotts, Commonwealth of. #488 7724, 88/12/19. Office of the General Counsel. 18pp. 47885:155-47885.172.
- 8812280024 Sescoast Anti-Pollution League answer to applicant motion to compel & motion for protective order.* Requests protective order against motions to compel answer to Interrogatory 77 on basis that request burdensome Svc fist enct. BACKUS,R.A. Sescoast Anti-Pollution League. BACKUS,R.A. Backus, Meyor & Sotomon #488 7737. 88/12/18. Atomic Safety and Liconsing Board Panel. 5pp. 47896:073.47886.077.
- 8812280069 Expresses concorn that GA Berry 881207 memo to Chik re financial qualifications of applicant considered procedurally inappropriate,unfairly prejudices rights of parties in proceeding & misstates mail facts on audi.

 JONAS,S.A. Massachusetts, Commonwealth of. #488 7718. 88/12/19. ZECH,L.W., ROGERS,K.C., ROBERTS,T.M. Commissioners. 4pp. 47884:334-47884;337.
- 8812280091 Town of West Newbury answers to NRC Staff third set of Interrogatories & request for production of documents to towns of Amesbury, Newbury, Sallsbury, West Newbury & Merrimac & city of....* W/Cortificate of Svc, Related correspondence. MIZNEH, J.H. West Newbury, Ma. #488 7721, 86/12/19. Office of the General Counsel, 14pp, 47884:347-47884:359.
- 8812260099 Notice of Commonwealth of MA atty general of Intention not to Illigate specific Seabrook plan for Commonwealth of MA communities contentions & bases.*
 Contentions & bases listed W/Certificate of Svc.
 TRAFICONTE 47884:327-47884:332
- 8812280115 Preliminary answer of Commonwealth of MA atty general to applicant motion for schedule. Applicant motion should be dealed on basis that LILCO plan already fully litigated. Supporting documentation & Certificate of Svc anci. TRAFICONTE,J. Massachusetts, Commonwealth of. #488 7726, 88/12/19. Atomio Sefety and Licensing Board Panel. 59pp. 47885.078-47885:135.
- 8812280118 Notice of appearance.* Advises that author will enter appearance in proceeding on behalf of Commonwealth of MA.W/ Certificate of Svc.
 GREER,L.B. Massachusetts, Commonwealth of. #488 7727. 88/12/19. 5pp. 47884:037-47884:041
- 8812280123 Answers & responses of Commonwealth of MA atty general to applicant interrogatories & request for production concerning Joint Intervenors Contentions 6 & 27-63. W/ Certificate of Svc Related correspondence.
 TRAFICONTE_J. Messachusetts, Commonwealth of: #488 7728. 88/12/19. Public Service Co. of New Hampshire. 155pp. 47884:042-47884:197.

respondence
TRAFICONTE, J. Massachusetts, Commonwealth of #488 7729 88/12/19 Office of rogator da di roquasia foi pribuaction di documenta comincate di Syc chim Netated coi the General Counsol 14pp. 47886.078-47886.091.

8812280142 Commonwealth of MA sity general supplemental response to applicant second request for production of documents. W/ Certificate of Svc Related corre-

- Security Indicates a process of the 8812280168 NRC Stalf response to Commonwealth of MA atty general motion for re-consideration 8/or c'artication of ru'ng on applicant motion for spinctions." Motion op-posed & clarification of order unnecessary. W/Certificate of Svc. TURK, S.E. Assistant General Coursel for Hearings #488 7749 88/12/20. Atomic Safety and Licensing Board Panel. 5pp. 47886:185-47886 189.
- 8812280217 Decision CLI-88-10.* Commission has determined w/reasonable assurance that decommissioning funds available & will accept applicant proffered plan to fund before receipt of low power I cense Served on 88121.

 HOYLE, J.C. Office of the Secretary of the Commission #488 7735 68/12/21, 36pp. 47886.096-47886:131.

H. General correspondence

- 8812080175 Forwards constituent RJ Perry communits opposing proposed rule 10CFR50 re emergency planning & preparedness requirements for nuclear power plant fuel loading & trillial low power operations. HUMPHREY,G.J. New Hampshire, State of 86/11/03 ZECH,L.W Commissioners 4pp. 47749 357 47749 360.
- 8812210306 Responds to 881103 fir to Chairman Zoch requesting repty to constituent RJ Perry concern re-selety stds for licensing of nuclear power plants Seabtrook plant will not commence operation until NRC fully satisfied that stds met.

 STELLO,V. Old of the Executive Director for Operations. 88712712. HUMPHREY,G.J. Senate, Bpp. 47881,003-47881,012.
- -8812210311 Requests response to encl constituent RJ Perry concorns releafety sids for licensing of nuclear power plants. HUMPHREY.G.J. Senate. 88/11/03. ZECH,L.W. Commissioners. 4pp. 47881.009

1 Financial Information

- 8612020026 Motion of Commonwealth of MA Atty General JM Shannon for leave to file document not authorized by Commission rules of practice. Requests to file response to lith applicant & NRC response to ethy general 881.102 motions. JONAS,S.A. Massachusetts, Commonwealth of. #488.7576. 88/11/26. Commissioners 3pp. 47843.084-47643:125.
- -- 8812020051 Affidavit of Poter M Strauss.* Responds to J Peterson, PB Eriksen & LI Kopp affidavits Supporting documentation & Cortificate of Svc encl. STRAUSS.P.M. Massechusetts, Commonwealth of STRAUSS.P.M. MHB Tochnical Associates. 88/11/22. 22pp. 47643:104-47643:125.
- 8812270137 Forwards document propared by NRR Policy Development & Analysis Staff re applicant financial qualification to operate & docommission plan for filing BERRY,G.A. Assistant General Counsel for Hearings #488 7710. 88/12/13. CHILK,S.J. Office of the Secretary of the Commission. 36pp. 47072.119-47872.154.
- 8812270093 Intervenors advice to Commission.* Discusses resolution of joint owners releasing all claims egainst applicant. Supporting documentation & Svc list enci.
 BACKUS.R.A. Seacoast Anti-Poliution League. BACKUS.R.A. Massachusetts, Commonwealth of BACKUS.R.A. Hampton, NH. #488 7809. 88/12/14. 13pp. 47872:220-

- 8811280135 Forwards E-255-1389, "Test Rept on Electrical Testing of Class IE Com-munication Isolation Device for Digital Radiation Monitoring Sys & E-255-1333, "Test Rept on Electrical Testing of Isolation Devices for Digital...." THOMAS, G.S., Public Service Co. of New Hampshire, 88/11/18. Document Control Branch (Document Control Desk), 4pp. 47675:214-47676:217.
- 8811280048 Generic Ltr 88:20 to all licenseos holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities, Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411): 86/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024.
- 8812060199 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Malls & Impact on Plant Operations." Required changes,per Rev 2 to Reg Guide 1.99, anticipated to be submitted prior to second outage. THOMAS,G.S. Public Service Co. of New Hampshire. 86/11/30. Document Control Branch (Document Control Desk). 2pp. 47734:358-47734:357.
- 8812120210 Clarifies procedures for handling polyethylene bags covering fuel assemblies received onsite & removed from shipping containers.Plant Operating Procedure RS-0722 requires bag covers be untastened & removed prior to moving assemblies. THOMAS,G.S. Public Service Co. of New Hampshire. 88/12/02. Document Control Branch (Document Control Desk). 2pp. 47788:107-47788:108.
- 8812120233 Requests that util address Generic Ltr 88-17 re loss of DHR during nonpower operation. Lt Issued due to potentially serious consequences resulting from Indequacy of Industry response to Generic Ltr 87-12. MIRCE YLT. E. Ottice of Nuclear Reactor Regulation, Director (Post 870411), 88/12/02. BROWN,E.A. Public Service Co. of New Hampshire. 3pp. 47789.075-47789.077.

- 8812220342 Advises that B91019 changes to operational CA program for facility acceptable Effectiveness of OA program & procedure implementation will continue to be subjectional original insps MART:N,TT Region 1, Ofc of the Director 88/12/13 BHOWN,EA Public Service Colof flow Hampshire 2pp 47903 081-47003 082
- 8812200265 Forwards description of prantispecific design for ATWS mitigation sys (AMS) per V. Nerses 880725 request Each of 14 tems identified by NRC in SER issued for Westinghouse Owners Group generic AMS das gradifies

Q. Inapection reports, IE Bulletins & correspondence

- 8812140172 Responds to NRC Buileth 86-001, "Delects in Westinghouse Circuit Break-er." Five DS-416 circuit breakers inspected found to contem pole strait welds not meeting acceptance interface as required corrective action. THOMASIGS. Public Service Co. of New Hampship. 68/03/30. RUSSELL,WIT Region 1, Ofciot the Director Spp. 47803-324-47800-328.
- 8812090156 Responds to NRC Builesh 87-001 relippe wall prosign/ corrosion monitoring program currently being developed for plant TROMAS,GIS Public Service Co. of New Harrpshire 88/09/11. RUSSELL,WIT Region 1, Old of the Director Spp. 47782 354-47782 358
- 8811160211 NRC rate Notice 88-030, "Unauthorized Removal of Industrial Nuclear
- Gauges "Svc Ist end. CUNNINGHAM R E. Division of Industrial & Modical Nuclear Safety (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257. 8811160467 NAC Info Notice 88-091, "Improper Administration & Control of Psychologi-
- cal Tests " Syc list enct.

 ROSSICE Division of Operational Events Assessment (Post 870411) 88/11/22
 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708-142
- 8811290030 NRC Info Notice 88 093, "Teletherapy Events" Syc hat encl. CUNNINGHAM,R.E. Division of industrial & Medical Nuclear Safety (Post 870729) 88/12/02, Consolidated Edison Co. of New York, Inc. 112pp. 47611:103-47811.215
- 8811290538 NRC Into Notice 88-034, "Potentially Undersized Valve Actuators" Svc list encl. RUSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp 47708.143-47708.254.
- 8812120213 Responds to NRC Buteth 88:003, "Inadequate Latch Engagement in HFA Type Latching Relays Mtg by GE."
 THOMAS,G.S. Public Service Co. of New Hampshire 88/12/02 RUSSELL,W.T. Region 1, Olic of the Director. Spp. 47/87-122-47/87-126
- 8812140191 Forwards Safety finsp Ropt 50:443788-13 on 880907-1017 & notice of violation. Violation rolident-fication of & fature to rept non-Class 1E foad powered from Class 1E source which had not been rested per Tech Specs.
 WIGGINS.J.T. Region 1, Oto 6 the Director 80/12/06. BROWN,E.A. Public Service Co. of New Hampshire. 3pp. 47813-352-47814-031.
- -8612140192 Notice of violation from inspiron 880907-1017 Violation noted non-Class 1E emergency todwater pump tachemoler powered from Class source_contrary to Tech Spec 4.8 4.2 6 discovery of condition not reported. Region 1, Ofc at the Director, 69/12/06, 6pp. 4/813,355.47813 360 TE power
- --8812140194 Day & Backshifts Insp Rept 50-443/88-13 on 880907-1017.Mejor areas inspected operational sately, NRC temporary instructions previous frep findings, NRC bulletins & into notices & potentially reportable occurrences HAVERICAMP, D.R. Region 1, Oto of the Director 89/11/29 31pp. 47814.001-47814 031
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 08/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302
- 8812220342 Advises that 881019 changes to operational QA program for facility acceptable.Effectiveness of QA program & procedure implementation will continue to be subject outline logicinal linsps.

 MRRTIN,T.T. Region 1, Otc of the Director. 88/12/13. BROWN,£ A. Public Service Co. of New Hampshire. 2pp. 47903.061-47903.062.
- 8812270225 Forwards SER re util 880815 & 1014 responses to NRC Bulletin 88-005 NRC concludes that Identification & testing programs & results of analytical pro-cedures used by util to qualify nonconforming parts, acceptable to resolve concerns. VARIGAS A Division of Reactor Purjects. VIII [Post 800411) 88/12/15. BROWN,E. Public Service Co of New Hampshire. 6pp. 47924:224-47924 245
- -8812270229 SER accopting util testing program & structural analysis of nonconforming flampes & fittings.per NRC Bullotin 88 005.

 **NRC No Detailed Afficiation Given: 88/12/15, 16pp. 47924.230-47924.245.

R. Periodic operating reports & related correspondence

- 8812080100 Forwards "Seabrook Station 10CFR50.59 Safety Evaluations Quarterly Rept for Jul Sopt 1988"
 THOMAS G.S. Public Service Co. of New Hampshire. 88/11/30. Document Control Branch (Document Control Desk). 7pp. 47742

S. Reportable occurrences, LERs & related correspondence

8811300289 LER 88-007-00 on 881020,7/a ns A & B cables for post-accident nuclear instrumentation identified as separated by less than required 20 ft.per 10CFR50,App R Mod completed for reinstal/ation of cables W/881121 ls. PUCKO,7 G., THOMAS,G S. Public Sorvice Co. of New Hampshire. 88/11/21. 3pp. 47897:192-47697:194.

T. Hearing transcripts on non-antitrust matters

- 8811300149 Forwards erials to transcripts of 881103 meeting w/util to discuss prant readines for issuance of law power license
 THOMAS,G.S. Public Service Co. of Now Hampshire 88/11/18 Document Control Branch (Document Control Desk) 5pp. 47681:060-47681:084.
- 8812150087 Transcript of 881212 status conference in Bothosda,MD re-oftship emergency planning Pp 14,859-14,904.
 ** Atomic Safety and Uconsing Board Panel 88/12/12 48pp 47824 120-47624 175
- 8812220146 Transcript of 881220 evidentiary hearing in Bathesda, MD re clisto emakingericy planning Pp 14,908-15,181.
 Atomic Satioty and Licensing Board Panel 88/12/20 278pp 47893:118 47884 036

U. Congressional/Executive Correspondence

- 8811300078 Forwards NRC quarterly status rept covering Third Quarter CY53 to 46 sponse to direction given in House Rept 97-850.
 ZECHLLW. Commissioners. 88/11/10. BEVILL.T. House of Rep., Appropriations 12pp 47733-031-4773
- 8811300881 Forwards quarterly status rept on emergency preparedness for nicless power plants for Jul-Sept 1988 healthly of Commission to forecast begins of school of Shoreham & Seaturook roted. ZECHL.W Commissioners 88/11/10 BREAUX.J.B Sonate, Environment & Public Works 5pp 47754 227-47754 231.

DOCKET 60-444 SEABROOK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

- 8811280048 Generic Lir 88-20 to all licensoes holding OLs & CPs for nuclear power reactor facilities re Individual plant exam for severe accident vulnerabilities Svc. list CRUTCHFIELD.D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729:024.
- 8812120233 Requests that util address Generic Lir 88-17 to loss of Diffi during non-
- power operation Lit Issued due to potentially senious consequences msuling from in adoquecy of industry response to Generic Lit 87-12.

 MURIEY I.E. Office of Nuclear Reactor Regulation, Director (Post 870411) E8/12/02 BNOWNE A Public Service Co. of New Hampshire. 3pp. 17788-075 47789-077.

F. Security, medical, emergency & tire protection plans

- 8812190044 Seacoast Anti-Pollution Loague response to applicant Interregator 39 & request for production of documents to all intervenors & participating local governo continuous. "Wirelated Info & Svc list.Rulated correspondence.
 DOUGHTY, J. Seacoast Anti-Pollution League. #489, 7520, 88/12/05, Public Service Co. of New Hampshire. 46pp. 47802.107-47802.152.
- 8812270867 Motion in limine of Commonwealth of MA atty general re FEMA post care-cise evaluation & assossment ropt.* Board should grant motion & direct FEMA to pro-yide dotails of destruction documents.W/supporting documentation & Certificate of STRAFICONTE.J.M. Massachusoits, Commonwealth of: #488 7703. 88/12/13. Atomic Safety and Licensing Board Panel. 22pp. 47872.327-47872.348.
- 8812270099 Motion for reconsideration of momorandum & order-Part 1 (n-fing on contentions on Seabtrook plan for Commonwealth of MA communities).* Contentions 65 & 76 should not be rejected per ALAB-905.W/supporting into & Certificato of Svc. TRAFICONTE,J. Massachusetts, Commonwealth of #488 7705 8B/12/16. Alonic Safety and Liconsing Board Panel. 18pp. 47672:199-47872:216.
- 8812280115 Preliminary answer of Commonwealth of MA atty general to applicant motion for schedulo. Applicant motion should be denied on basis that ELECO pan atready tuly ingated. Supporting documentation & Certificate of Six enci. FRAFICONTE, J. Massechusetts, Commonwealth of #488 7726. 88/12/19 Atomic Safety and Liconsing Board Panel. 59pp. 47885.078-47885.135
- 8812210294 Final response to FOIA request for records.App A records enci & available in POR GRIMSLEY,D.H. Division of Freedom of Information & Publications Services (Post 880515) 88/12/20. BELAIR,R.R. Kirkpatrick & Lockhart. 2pp. 47874.049-47874.049
- **8812210298 "Shoreham-Seabrook Exercise History."
 NRC No Detailed Athligtion Given, 88712720, 4pp, 47874,051-47874;056

G. Adjudicatory correspondence

- 8812020092 City of Newburyport request for limited participation status.* Served on 881125 Granted for Board on 881123. SAINT ANDRE B. Newburyport, Ma. #488 7582, 88/11/16. Atomic Safety and Licensing Board Panel 1p. 47643:264-47643:264.
- 8812020044 NRC Staff response to applicant motion for summary disposition of Jord Intervenor Contentions 44A & 44B * Efficient conduct of proceeding requires that £5-gation continue under erails mule Continuate of Svc en
- 8812020062 Advises that person designated to receive copies of proceedings changod from author to S Breiseth at stated address. PEYEAR,R.C. New Hampshire, State of. #488 7590. 88/11/21. Docketing & Services Brench. 1p. 47843-202-47643-202

- 8812020156 Applicant answer in opposition to Commonwealth of MA atty general motion to compel answers to interrogationes.* Motion should be denied Certificate of Svc encl SVITH J.B. Public Sorvice Co. of New Hampshire SMITH, J.B. Ropes & Gray #488 7573 68/11/21. Atomic Safety and Loonsing Board Panel. 11pp. 47644-320-47844 330
- 8812020163 Applicant advice to Commission * Advises Commission that on 881116,applicant board of directors approved MOU between util & Massachusetts Municipal Wholesate Electric Co W/ Certificate of Svc

SELLECK,K.A. Public Service Co. of New Harrpshire SELLECK,K.A. Ropes & Gray #468 7574 88/11/21 4pp 47644.333-47644.336

- 8812020060 Seacoast Anti-Poliution League comments on Eignificance of ALAB-903 to exercise contentions.* Svc fist end.

 8ACKUS,R.A. Seacoast Anti-Pollution League BACKUS,R.A. Backus, Neyor & Solomen. #488-7550, 89/11/22. Atomic Safety and Licensing Board Panel https://doi.org/10.1006/ 47643 182 47643 192
- 8812020074 Town of West Newbury response to NRC Staff motion to compal answers to interrogatories & production of recuments by town of West Newbury.* Cartilicate of MIZNER J.H. West Newbury, MA. #488 7553 88/11/22 Office of the General Counsel 9pp 47643 209 47643.217.
- 8812020081 Town of Hampton (TOH) & New England Coalition on Nuclear Pollution (NECNP) response to Board order did 381114 to TOH/ NECNP Ex 1.º Requests admission of Exercise Contention Ex 1. W/Contribute of Sec. BROCK,M.T. Hampton, NH BROCK,M.T. New England Coalition on Nuclear Pollution BROCK,M.T. Shaines & McEachern #488 7554 88/11/22 Atomic Safety and Literature New 478-478 16 178-478-48. censing Board Panel 8pp 47643 225-47643 232.
- 8812020084 New England Conflion on Nuclear Pollution commants on significance of ALAB-903 to Seatrook offsite exercise contentions.* See list encl. CURRAND. New England Coalition on Nuclear Pollution, CUHRAND. Harmon, Curran & Tousley, #488-7553, 88/11/22. Atomic Safety and Licensing Board Panel, 9pp. 47643-241-47643-249.
- 68 12020089 Responses of FEMA to town of Amesbury tirst set of Interrogationes & request for production of documents to FEMA on Scalarock plan for Commonwealth of MA communities.* W/Confilicate of Svc Related correspondence FLYNN/HJ, Federal Emergency Management Agency, #488-7569, 88/11/22 Amesbury, MA 14pp. 47643-250-47643-263.
- 8812020019 Applicant memorandum :: response to 881114 Board memorandum.* Intervenous contentions should be disposed of as set forth in applicant response to fallowerers contentions on June 1988 extress W/Certificate of Svc. SMITH_JB Public Service Co of New Hampstrio, SMITH_JB Ropes & Gray, #488 7555 88/11/23. Atomic Safety and Licensing Buard Panel, 31pp. 47643.043-7323.213
- 6812020117 NRC Staff response to 8811114 Board order requesting comments on sigr Tleance of ALAB-803 for Septrook proposed general exercise contembris 51-59.

 Contentions 8 bases should be denied. Certificate of Six encl
 CHANEJ, Assistant General Counsel for Healing. #488-7565, 88/11/23. Atomic
 Salety and Licensing Board Paint | 13pp. 47644:091-47644:103.
- 8812020149 Forwards documents rat in RW Donovan 181109 & 10 deposition, including forms on which results of Interviews verifying lits of agreement recorded W/o stated documents Certificate of Svc enct Related correspondence ELYRINES. Faderal Emergency Management Agency #488 7672 88/11/23. FLYFIN.H.J. Federal Emergency Management Agency #488 7672 88/ TRAFICONTE, J. Massachusetts, Commonweath of 7pp. 47844.313.47644.319.
- 8812020025 Motion of Commonwealth of MA Atty Conniel JM Shannon for leave to file document not authorized by Commission rules of practice.* Requests to file response to lot applicant 8 MIC response to lot applicant 8 MIC response to atty general file 102 motions.

 JONAS, S.A. Massachysetts, Commonwealth of Wh80 7576 88/11/25 Commission-
- ers 3pp 47643.084 47643 125
- -8812020042 Reply of Commonwealth of MA Atty General JM Shannon to filings of Statt & Joint applicants in response to 881102 motions under 10CFR2 734 to reopen record * Commission should reject NRC & applicant arguments.

 JONAS S A Moseachusetts, Commonwealth of 89/11/25 Commissioners 17pp 47643.087-47643:103
- --8812020051 Affidavit of Poter M Straums* Responds to J Poterson, PB Erikson & LI Kopp affidavits Supporting flocus ontation & Conflicate of Svc engl STRAUSS,P.M. Massachusotta, Commonwealth of STRAUSS,P.M. MHB Technical Associates. 88711722, 22pp. 47643:104-47643-125
- 8812140023 NRC Staff response to Liconsing Board order of 881025 * Joint Intervenors motion to reopen record should be dealed & emergency planning contention should not be admitted for integration. BERRY.G.A. Assistant General Counsel for Hearings. #488-7592-86/11/28, 12pp 47770.040-47770.072.
- --8812140030 Alfridavit of GJ Conklin & DG Ruscitto re Joint Intervenors motion to reopon record to admit late-filed contention challenging certain aspects of applicant radiological omergency response plan for plant W/Certificate of Svc. CONKLIN.C.J. Region 1, Oto of the Director, RUSCITTO.D.G. NRC No Detailed Affiliation Given. 88/11/28, 21pp. 47770.052-47770.072.
- 8812140028 Applicant motion to comput responses from Commonwealth of MA alty general to applicant request for admissions.* Reguest should be competed Cortricate TROUT_JP. Public Sarvice Co. of New Hampshire, TROUT_JP. Ropes & Gray, #488 7688, 88/11/28. Atomic Safety and Licensing Board Panel, 8pp 47789 257-47789 265.

- 8812140034 Applicant motion to compet answer from Joint Intervences to applicant re-quest for admissions. Proper answer should be competed Cartilicate of Sec and SELLECK.K.A. Public Service Co. of New Hampshire. SELLECK.K.A. Flopes. & Gray. #488.7589. 88/11/28. Atomic Safoty and Licensing Board. Panel. Spp. 47769.252. 47769,256
- 8812140057 Applicant motion to compet production of documents by Commonwealth of MA sity general.* Order should be issued competing production of all documents responsive to applicant second request Confected or 5 vs and TROUT_JP Public Service Co. of New Hampster TROUT_JP Repus 8 Gray #488 7590_88/11/28 Atomic Safety and Licensing Board Panel. 11pp. 47769.227-4789.027. 47769 237
- 8812920127 Decision.* Affirms Board 690808 Memorands.m & Order L8P-88-20 determining that RG-58 cable Issue need not be resolved prior to authorization of low power operation of facility. Served on 881129.

 SHOEMAKER,C J. Atomic Safety and Licensing Appeal Panel #469 7576. 88711/29. 10pp 47644 106 47644 115.
- 8812140126 Applicant motion for feavo to file applicant response to answer of Commonwealth of MA atty general in opposition to applicant motion for summary disposition of Joint Intervenor Contentions 444 & 448 "SMITH_JB Public Soncice Co. of New Hampstire SMITH_JB Repos & Gray #466 7626 88/11/30. Atomic Safety and Licensing Board Panol 2pp. 47930.281-
- -8901030055 Applicant response to answer of Commonwealth of MA atty general in opposition to applicant motion for summary disposition of Joint Intervenor Contembors 44A 8 44B (answer) * W/Certificate of Svc SMTH.J.B. Public Service Co of New Hampshire SMITH.J.B. Ropes & Gray. 88/11/ 30. Atomic Safety and Licensing Board Panel 22pp 47930 283-47950 304
- 8812190064 Ack receipt of applicant motion to compet responses from Commonwealth of MA atty general to applicant request for admissions & motion to compet answer from Joint Intervenors, did 881128.NRC does not intend to respend to motions. TURK,S.E. Assistant General Counsel for Hearings. #488, 7637, 88711730. SMITH,I.W., HARBOURJ, LINENBERGER,G. Momic Satoty and Licensing Board Panel, 1p. 47802.155-47802.155.
- 8812140020 NRC Staff response to Commonweetth of MA bity general request for leave to the reply to responses of applicant 8 NRC Staff Request should be doned Certificate of Svc onct. uon au Semilicare of Svc onci. BERRY, G.A. Assistant General Course! for Habrings. #488-7585-88/12/01. Comm's-sionaris. 9pg. 47769;265-47789-273.
- 8812140037 Applicant response to metion of Massachusetts Atty General JM Shence for leave to file document not nullionzed by Commission rules of practice.* Alchomshould be dealed. Certilicate of Svc encl
- 00 GNAN, T.G. Public Sorvico Go i Now Hampstillo, DIGNAN, T.G. Ropus & Gray #488 7619 88/12/01 Commissioners Spp. 47770 173-47770 177.
- 8812140043 Applicant answer in opposition to Commonwealth of MA atty general (AG) motion to compet answers to Commonwealth of MA AG second set of interregatories. Motion to compet enswers should be denied Certificate of Set enci-TROUT,JP, Public Sorvice Co. of New Hampstire. #488-7593. R8/12/01. Atomic Satety and Licensury Board Panel. 14pp. 47769-238-47760-251.
- 8812140087 Memorandum & order * Alty general of Commonwealth of MA appeal from Licensing Board 891012 memorandum & order dismissed as premiliare Serves on
 - SHOEMAKER,C.J. Atomic Sufety and Licensing Appinal Panel. #468 7598-88/12/01. Massachusatis, Commonweelth of. 8pp. 47770 222-47770:229
- 8812190002 Advises that NRC Staff received responsive from towns of Amesbury, Newbury, Woot Newbury & Morrimac & city of Nowbury, out of NRC first set of interrogatednes & first request for production of documents BERGQUIST, S.A. Assistant General Counsel for Hoppings #488 7645 88/12/01. SMITH, I.W., HARBOUR, J., LINENBERGER, G. Atomic Safety and Licensing Board Deat 1, 1700-2007, 2700-2700. Panni 1p. 47802 206 47802:206
- 8812190152 Opposes granting of Commonwoulth of MA atty general 881129 request to additionation to support proposed general exercise contentions on grounds that Board gave parties opportunity to submit comments on or before 881123 CHAN,E.I. Assistant General Counset for Heatings. #468 7644 88/12/01. SMTH,I.W., HARBOUR,J., UNICHBERGER,G. Attendo Safety and Economy Board Panel. 2pp. 47801 097-47801 098
- 8812140114 Discusses Impact of ALAB-903 on exercise litigation Applicant offered no Interpretation of ALAB-903 but instead tile addit written response to contentions Referedate listed points. TRAFICONTE J. Massachusetts, Commonweeliti of #483 7617 80/12/02. SMITH,LW., HARBOUR,J., LINENBERGER,G. Atomic Safety and Licensing Board Panel 3pp. 47770 083-47770 085
- --8812140124 Advises that Commonwealth of MA alty general ofd established encloped & procedures to ensure that protected into received re-plant Fcensing proceedings not disclosed to unauthorized persons. SHANNON,JM. Massachusetts, Commonwealth of 8/12/02 SMITH,J.W., LINENBERGERG, HARBOUR,J. Atomic Safety and Licensing Board Panel 4pp. 4324,098. 47770,086-47770 089.
- --8612140128 Motion for reconsideration &/or clarification.* In event Board clocks to maintain sentition in place, Commonwealth of MA move Board to clarify meaning FIERCE, A R. Massachuseits, Commonwealth of .88/12/02. Atomic Safety and Licensing Board Panol. 16pp. 47770-030-47770:105.
- -8812140135 Affidavit of P Talbot re applicant Interrogatory on buses. Certificate of Svc TALBOT,P. Massachusetts, Commonwealth of 88/12/02 9pp 47770.106-47770.114
- -8812140148 Expresses appreciation for cooperation in preventing Page 7 of Commonwealth of MA aity general supplimental response to applicant first set of interrigatories from public disclosure.
 TALBOT, Massachusotts, Commonwealth of 88/10/19, JULIAN,E. NRC - No Detailed Affiliation Given 1p. 47770.115

- KEOUGH,E.J. Massachusetts, Commonweelth of 88/12/02 6pp. 47770 116 47770 121.
- 8812190208 Forwards State of NH (curteenth supplemental order of notice re-plant de-commissioning fund Related correspondence HAFFER E.A. Sheehan, Phinney, Bass & Green, Professional Association #488 7668 88/12/02; NRC No Detailed Africation Green 3pp. 47801 019 47801 021
- 8812190044 Seacoast Anti-Politikon League response to applicant interrogatories & request for production of documents to all intervenors & participating focal govts re contentions. "Wite ated into & Swc list Related correspondence DOUGHTY_J. Seacoast Anti Politikon League #488 7629, 88/12/05, Public Service Co. of New Hampshire, 46pp. 47802 107-47802;152.
- 8812190080 Suppremental response to applicant first set of interrogatories & supplemental response to app'cant inforrogatores & request for production of documents to all therefores. "Syc list end. Refered correspondence DOUGHTY, Seacoast Anti-Pol-Lution League #488 7630 89/12/05. Public Service Co. of New Hampshire 6pp 47801 203-47601 209
- 8812270026 Patition for NRC review & evaluation of 6.4 magnitude Quebec,Canada earthquake for express purpose of comparative analysis w/safe shutdown earthquake (SSE) of Seatorook units & "Certificate of Svc end: Served on 881215 WEINHOLD,E.D. Affliation Not Assigned #488 7677, 88/12/05 Atomic Safety and Licensing Board Panel, 13pp. 47873 119 47873 131.
- 8812190014 Memo:andum 8 order (motions for teave to file responses re-summary disposition of Joint Intervenor Contentions 44A 8 44B.)* Grants applicant 8 Commonwealth of MA loave to file responses Served on 961206. SMITH,
- 8812190048 Memorandum & order fruing upon applicant motion for summary disposition) * Applicant 880909 motion for summary disposition granted & New England Coalition on Nuclear Polition Contention IB.2 dismissed Served on 881208 WOLFELS J., HARBOUR J., LUERKELE A. Atomic Safety and Liconsing Board Panet. #468 7635 89/12/07 Office of the General Counset 23pp. 47802.161-47802:183
- 8812190071 Forwards corrected Page 5 for insertion in NRC response to Board 881114 order requesting commonts on significance of ALAB-903 for plant proposed general exercise contentions,did 881123 TURK,S.E. Assistant General Counsel for Hearings #468 7638 88/12/07. SMITH,LW., HARBOUR,J., LINENBERGER,G. Atomic Safety and Liconsing Board Panof. 2pp. 47802 153-47802 154
- 8812190205 Joint Intervenors motion for feave to submit response to NRC Staff re-sponse to Licensing Board order of 881025. Leave requested to fre-end response JONAS,S.A. Messachuseits, Commonwealth of JONAS,S.A. Hampton, Nrt JONAS,S.A. New England Coalition on Nuclear Pollution, #483 7659, 88/12/07 Atomic Safety and Licensing Board Panel 3pp. 47801 022-47801:034.
- -9812190215 Joint Intervenors response to NRC Stall response to Board order of 881025.* Onsite exercise content on should be admitted for hitgation Certificate of Svc JONAS.S.A. Massechusetts, Commonweath of JONAS.S.A. Hampton, NH. JONAS.S.A. New England Coattion on Nuclear Pollution 88/12/07. Atomic Safety and Uconsing Board Panel, 10pp. 47801-025-47601-034.
- 8812190113 Advises that NRC agrees that Listed town of Amesbury draft documents need not be produced,per conversation earler in wk Related correspondence BERGQUIST,S.A. Assistant Goneral Counsel for Hearings, #488 7682 88/12/08. SAINT ANORE,B. Kopelman 8 Para to 47002 033-47802.083
- 8812190144 Commonwealth of MA atty general motion to compet response by FEMA to Interrogatories & requests for production of documents.* Atty general moves that order be Issued competting FEMA to respond to descovery. W/Svc list. SNEIDERICS. Messachusetts, Commonwealth of. #489 7864, 89/12/08, Atomic Safety and Liconsing Board Panel 6pp. 47801:099 47801:104.
- 8812190001 Reply by FEMA to Commonwealth of MA aity general motion to compot response by FEMA to interrogatories & requests for production of documents. Motion to compet considered mooil. FLYNN,H.J. Federal Emergency Management Agency, #468 7672, 88/12/09, Atomic Sefety and Licensing Board Panel. 1p. 47802/084-47802 104.
- --8612190004 Responses of FEMA to Commonwealth of MA atty general first set of interrogatories to FEMA concerning Seabrook plan for Commonwealth of MA communities
- TEYNN,H.J. Foderal Emergency Managament Agoncy, 88/12/08. Massachusetta, Commonwealth of: 10pp 47802/085-47802/094.
- --B812190007 Responses of FEMA to Commonwealth of MA ally general second request for production of documents to FEMA to Seabrook plan for Commonwealth of MA communities.* W/Cert.ficate of Svc FLYNN,H.J. Federal Emergency Management Agency. 88/12/09. Massachusetts, Commonwealth of, 10pp. 47802-095-47802:104.
- 8812270097 Town of Amesbury request for finited participation status.* Sorved on 081216 Granted for Board on 881215.
 SAINT PLERRE,B. Amesbury, MA SAINT PLERRE,B. Kopelman & Pe'ge. #488 7700 88/12/09. Atomic Salety and Licensing Board Panel. 1p. 47872 217-47872.217.
- 6812270079 Applicant revised request for admissions from Commonwealth of MA atty general." Supporting documentation & Certificate of Svc and Related correspond-
- ence. TROUT,J.P. Public Service Co. of Now Hampshiro, TROUT,J.P. Ropes & Grey. #488 7697. 88/12/12. Massachusetts, Commonwealth of 9pp. 47672.297-47872.305.
- 8812270031 Town of Newbury response to applicant second set of interrogatories & request for production of documents. W/ Certificate of Svo.Related correspondence. HILL-WHILTON,R. Newbury, MA. #488 7689 88/12/13 Public Service Co. of New Hampshire 16pp. 47873 103.47873 118

- vide details of destruction documents W/supporting documents TRAFICONTE,J.M. Massachusetts, Commonwealth of. #488 77/ Safoty and Licensing Board Panel. 22pp. 47872 327-47872 348
- 8812270101 Town of Newbury responses to applicant interregator duction of documents to all intervenors & participating local gov. Contentions 6 & 27-63 * W/Cortificate of Svc.Rulated correspond HILL-WHILTON,R. Newbury, MA. #488 7688 88/12/13. Public Hampshire. 12pp. 47872 187-47872.198
- 8812270137 Forwards document propared by NRR Policy Duveling re applicant financial qualification to operate & decommission pin BERRY GA Assistant General Counsel for Hearings #41 CHILK,S.J. Office of the Secretary of the Commission 36pp.
- 8812270093 Intervenors advice to Commission. Discusses resoluted advice in Commission. Obscusses resoluted in Commission of Comm 47872.232.
- 8812280160 NRC Staff motion to compel answers to interrogate documents by Commonwealth of MA atty general.* Atty gunterel to provide answers to interrogatories 2-4 & 10-14 TURK, S.E. Assistant General Coursel for Hoatings #488-775 Safety and Liconsing Board Panel 11pp. 47884:222-47884-237
- -B812280166 NRC Staff third set of inforrogatories & request for ments. Advises that documents responsive to request will be a ofc of Commonwealth of MA atty general WCommonwealth of Svc TALBOT,P. Massachusetts, Commonwealth of 88/11/18. TUITIN eral Counsel for Hearings. 5pp. 47884:233:47884:237.
- 8812270053 Memorandum & order (ruting on Juno 1988 general in Board will conduct prohoaring conference on Inligation of 1988 or Commonwealth of MA may submit addit commonts on ALAU-90 HARBOUR, J. LINENBERGER,G., SMITH,I.W. Alomic Safety / Panel. #488 7693, 88/12/15. Office of the General Common 47873 059.
- 8812270075 Town of Newbury request for limited participation.* The participate in Litigation of Joint Intervenors Contentions 4,7,8,45 8 MIZNER, J.H. West Nowbury, MA. #488 7698 88/12/15. Atomic Board Panel 3pp. 47872 310-47872.312
- 8812270087 Town of Newbury answers to applicant interrogational duction of documents to all intervenors & .. concerning Joint Intervenors & .. concerning Joint Intervenors & .. concerning Joint Intervenors & 26.6 & 27-63.1 W/ Centificate of Svc.Rolated correspondence MIZNER, J41. Wost Newbury, MA. #488 7500 68/12/15 Public Hampshire, 19pp. 47872;266-47872;284
- 8812270105 Applicant motion to compet enswer to inturregatory by ton League.* Certificate of Sve enci.
 TROUT, J.P. Public Service Co. of New Hampshire TROUT, J.P. 17708. 88/12/16. Atomic Safety and Licensing Board Paris
- 6812280156 Advises that NRC does not intend to file response to leave to file response to answer Commonwealth of MA atty prin applicant motion for summary disposition of Contentions 44A & 44 TURK, S.E. Assistant General Counsel for Hearings #4BP SMITH, J.W., HARBOUR, J., LINENBERGER, G. Atomic Safety & Panel 1p. 47884:221-47884:221.
- 8812280194 Advises that encl pattion for review & evaluation Quebec, Canada earthquake for purpose of analyzing w/sato club plant & evacuation planning rept should be denied, per 1007/H2 SVC. BERRY,G.A. Assistant General Counset for Hearings. #4th SMITH,I.W., HARBOUR,J., LINENBERGER,G. Alomic Safety n: Panel, 14pp. 47684:279-47884:292.
- 8812270084 Commonwealth of MA atty general answer to applicant admissions from Commonwealth of MA.* Certificate of Svc orici TRAFICONTE.J. Massachusetts, Commonweelth of: #488-771). Service Co. of New Hampshire, 8pp. 47872:288-47872:293.
- 8812270099 Motion for reconsideration of memorandum & order f 312270399 Molion for reconsideration of memorandum a proper fanilons on Seabrook plan for Commonwellth of MA communition 76 should not be rejected per ALAB-905-Wyapporting info & Cort TRAFICONTE, J. Massachusetts, Commonwealth of #488 7705 Safety and Licensing Board Panel. 18pp. 47872.199-47872.216.
- 8812270115 Applicant motion for schedule.* Requests that statud listed for remaining contentions to 880628- 28 FEMA graded or
- of Svc. SELLECK, K.A. Public Service Co. of Now Hampshire. SELLECK, #488 7707. 88/12/16. Atomic Safety and Licensing Board Page
- 8812280146 Town of Newbury response to NRC Staff third set of quest for production of documents to towns of Amesbury, Newbury & Morrimes & city of....* W/Certificate of Svc.Related co-HILL-WHILTON,R. Newbury, M. #488 7731, 88/12/16. Office of set. 17pp. 47884:248-47884;284.
- 8812280085 Applicant motion to compal enswers to interrogatorical uments by lown of West Nawbury." Town should be compalled answers on a before certain date Certificate of Svc encit TROUT, J.P. Public Service Co. of New Hampshire. TROUT, J.P. I 7742. 88/12/17. Atomic Safety and Licensing Board Pane 47886-173

157

to the outstanding discovery disputes between applicant & alty general for Commonwealth of MA per Board instructions.
TROUT, J.P. Public Service Co. of New Hampstere TROUT, J.P. Ropes & Gray #498
7744 88/12/17. SMITH, I.W. HARBOUR, J., LINENBERGER, G. Atomic Safety and U-censing Board Panel 6pp. 47886-174-47886-179.

8912270171 Order.* Advises that time for Commission to determine whether to review ALA9.892 extended until 891221.Snrved on 891220 CHILK, 5.) Office of the Secretary of the Commission #488 7714, 88/12/19 Commissioners 1p. 47872 081-47872.081

- 6912270172 Order * Advisos tital time for Commission to determine whether to review ALAB 895 extended until 891221. Served on 881220. CHILK 51 Office of the Secretary of the Commission #488 7715 88/12/19 Commissioners 1p. 47872 080-47872 080
- 47072.079.
- 8812280001 Commonwealth of MA Atty General JM Shannon renewed motion to compel responses by FEMA to interrogatories & requests for production of documents. Certificate of Sec end.

 SNEIDER,C.S. Messachusetts, Commonwealth of #488 7723 88/12/19 Atomic
 - Safety and Licensing Board Panel 19pp. 47885-136-47885-154
- 8312280004 Commonweelth of MA atty general second supptemental response to NRC Stall first set of Interrogatories 8 first request for documents. W/Cortificate of Svc Refated correspondence.
 TALBOT.P. Massachusetts, Commonwealth of #488 7724, 88/12/19. Office of the General Counsel. 18pp. 47885,155-47895,172.

8812280024 Seacoast Anti-Pollution League answer to applicant motion to compol 8 motion for protective order.* Requests protective order against motions to compol answer to Interrogatory 77 on basis that request burdensome Svc 1st encl. BACKUS,R.A. Seacoast Anti-Pollution League, BACKUS,R.A. Backus, Mayer & Solomon, #488, 7737, 88/12/19. Atomic Safety and Licensing Board Panel. Spp. 47886-073-47886-077.

8812200069 Expresses concern that GA Burry 981207 memo to Chilk re financial qualifications of applicant considered procedurally inappropriate unlawly prejudices rights of parties in proceeding 8 misstates mail facts on subj. JONAS,S A. Massachusotts, Commonwealth of, #488 7718, 68/12/19, ZECH,L.W., ROGERS,K.C., ROBERTS,T.M. Commissioners. 4pp. 47884:334-47884.337.

- 8812280099 Notice of Commonwealth of MA aity general of intention not to litigate specific Seabrook plan for Commonwealth of MA communities content ons & bases listed W/Certificate of Svc TRAFICONTE,J Massachusetts, Commonwealth of, #488 7722, 88/12/19 6pp 47884-327-47884:332

- 8812280115 Preliminary answer of Commonwealth of MA atty general to applicant motion for schedule. Applicant motion should be deriled on basis that LILCO plan already fully flugated Supporting documentation & Certificate of Svc enct. TRAFICONTEJ. Massachusetts, Commonwealth of .488 7726 88/12/18, Atom.c Safety and Licensing Board Panel. 59pp. 47885.078-47895 135.
- 8812280118 Not co of appearance * Advises that author w/l enter appearance in proceeding on behalf of Commonwealth of MA-W/ Confricatio of Svc GREER,L.B. Massachusetts, Commonwealth of #466 7727, 88/12/19 Spp. 47884:041
- 8812280123 Answers & responses of Commonwealth of MA atty general to applicant interregatories & request for production concerning Joint Intervenors Contentions 6 & 27-63 * W/ Conflicate of Svc.Roleted correspondence
 TRAFICONTEJ. Messachusoits, Commonwealth of. #488 7728, 88/12/19. Public Service Co. of New Hampshire, 155pp. 47884 042-47894:197.

8812280137 Commonwealth of MA atty general enswers to NRC Staff third set of inter-regetories & requests for production of documents Certificate of Svc enc. (Related cor-

tespondence.
TRAFICONTE.J. Massachusetts, Commonwealth of. #488 7729, 88/12/19 Office of the General Counsel. 14pp. 47886.078-47886.091.

- 8012280142 Commonwealth of MA atty general supplemental response to applicant second request for production of documental W/ Certificate of Svc Related corre-
- spondonce
 TALBOT,P. Massachusetts, Commonwealth of, #488 7730, 08/12/18, Public Solvice
 Co. of New Hampshire 10pp, 47884.238-47884.247.
- 8812280158 NRC Staff response to Commonwealth of MA aity general multion for re-consideration 8/or clarification of ruling on applicant motion for sanctions.* Motion op-posed & clambration of order unnocessary.W/Curtificate of Svc. TURKSE. Assistant Genoral Counset for Hoatings. #488.7749. 89/12/20 Atomic Safety and Licensing Board Panel. 5pp. 47886:185.47886.189.

8812280217 Decision CLI-88-10.* Commission has determined wireasonable assurance that documinisaloning funds available 8 will accept applicant proffered plan to fund before receipt of low power license. Surved on 681221.
HOYLEJ.C. Office of the Secretary of the Commission. #488 7735. 88/12/21. 36pp. 47886:096-47886:131.

H. General correspondence

4pp. 47749:357-47749.380.

8812080175 Forwards constituent RJ Perry commonts opposing proposed ruln 10CFR50 re-emergency planning & preparedness requirements for nuclear power plant tuol loading & initial low power operations. HUMPHRES. 3.3. Now Hampshire, State of BB/11/03. ZECH, L.W. Commissioners

8812210306 Responds to 881103 ltr to Chairman Zech requesting roply to constituent RJ Perry concernice safety sids for icensing of nuclear power plants Seabrook plant wit not commence operation until NRC July satisfied that sids mul STELLOV. Old of the Executive Director for Operations 88/12/12 HUMPHREY.G J Senate. 6pp. 47881.003-47881.012

-8812210311 Requests response to encl constituent RJ Perry concerns re-safety side for licensing of nuclear power plants
HUMPHREY,G.J. Senate. 88/11/00. ZECH,L.W. Commissioners. 4pp. 47881.009

I. Financial information

8812020025 Molion of Commonwealth of MA Atty General JM Shannon for leave to fig document not authorized by Commission rules of practico.* Hedgosts to fife response to joint applicant & NRC response to atty general #81102 molions JONAS, S.A. Messachusetts, Commonwealth of #488 7578 88/11/25 Commission ers 3pp 47643 CB4-47643 125

-6812020051 Affidavit of Poter M Strauss * Rosponds to J Poterson, PB Erikson & LI Kopp affidavits Supporting documentation & Certificate of Svc end STRAUSS P.M. Massachusetts, Commonwealth of. 68/11/22 22pp 47643.164-47643 125

8812270137 Forwards document propared by NRR Policy Development & Analysis Statl re applicant financial qualification to operate & decommission prantor time BERRY, GA. Assistant General Counsel for Hostorgs. #488 7710. 88/12/13 CHILK, S.J. Office of the Secretary of the Commission. 36pp. 47872.119-47872.154

8812270093 Intervenors advice to Commission * Discusses resolution of joint owners rotogang al dama against applicant Supporting documentation & Svo list enci.
BACKUS,R.A. Seecoast Anti-Polution League BACKUS,R.A. New England Coemon Nuclear Polution BACKUS,R.A. Seecoast Anti-Polution League BACKUS,R.A. New England Coemon Nuclear Polution BACKUS,R.A. Backus, Mayer & Solomon #488 7699 88/12/14 13pp. 47872 220 47872 232

Q. Inspection reports, IE Bulletins & correspondence

8812090155 Responds to NRC Bulletin 87-001 religipe wall erosion/ corrosion monitoring program curronlly being developed for plant
THOMAS,G.S. Public, Sorvice Co. of New Hampshira 89/00/11 RUSSELL,W.T.
Region 1, Ofc of the Director. 5pp. 47782:354-47782:358.

8811160211 NRC Info Notice 88-090, "Unauthorized Romoval of Industrial Nuclear

Gauges' Svc list encl.
CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Salety (Post 870729)
88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.

6611160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologi-Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142

8811290030 NRC Info Notice 08-093, "Toletherapy Events" Svc ast enct.
CUNNING (AM,R.E. Division of Industriet & Medical Nuclear Safety (Post 670729).
80/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215

8811290538 NRC Info Notice 88 094, "Potentially Undersized Valve Actuators" Svc list

ROSSI,C E. Division of Oparational Events Assessment (Past 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708 254.

8812020287 NRC Info Notice 88-095, "Inadequate Procurement Regularments Imposed by Licensees on Vondors." Svc 1st encl. ROSSICE. Division of Operational Events Assistance (Post 870411) 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807-191-47807-302.

T. Hearing transcripts on non-antitrust matters

8812150087 Transcript of 881212 status conference in Bethesda,MD to offsite emergency planning Pp 14,059-14,904
Atomic Safety and Licensing Board Panel 88/12/12 48pp 47824-128-47824-175

8812220146 Transcript of 881220 evidentiary hearing In Bethesda,MD re-olfsite emer-gency planning Pp. 14,906-15,181 * Atomic Sefety and Licensing Beard Panel. 68/12/20. 278pp. 47833:118 47864 036.

U. Congressional/Executive Correspondence

8811300078 Forwards NRC quarterly status rept covering Third Quarter CY88 in response to direction given in House Rept 97-850. ZECHILIW. Commissioners. 88/11/10. BEVILL,T. House of Rep., Appropriations. 12pp 47733-001-47733-012.

8811300081 Forwards quarterly status rept on emergency proparedness for nuclear power plants for Jul-Sept 1988.Inability of Commission to forecast ficensing schedule for Shoreham & Scabrook noted ZECH,L.W. Commissioners. 88/11/10. BREAUX,J.B. Senate, Environment & Public Works. 5pp. 47754:227-47754:231.

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 1

A. Application/construction stage documents & correspondence

8611230210 Not lication of 881206 meeting w/util in Flockville,MD to discuss design of ossential suc water sye.
WILSON.JH. Ofc. of Special Projects. 88/11/17. GRIMES,CI. Ofc. of Special Projects.
2pp. 47822.231-47822.232.

- Spec Improvement Program Tech Spec Requirements," per NRC Rev 4a of STS, for
 - COUNSIL W.G. TU Electric (formerly Toxes Ut ht es Genurating Co.): 68/11/17. Document Control Branch (Document Control Desk): 68pp. 47651:324-47652.031.
- 8811300023 Forwards marked-up proof 8 review of Tech Specs for plant. Version pre-pared from second draft Tech Specs transmitted on 860302,supplemented by info-from various util submittar's & uhl/MRC mostings. GRIMES.C.I. Ofte of Special Projects, 86711722. CCUNSIL,W.G. TU Electric (formerly Texas Uhl Les Generating Co.). 425pp. 47669-128-47670-263
- 8911280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities no individual plant exam for severe accident vulnerabilities Svo fist CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88/11/23. Consoldated Edison Co. of New York, Inc. 81p.: 47728:303-47729:024
- 8811300172 Revises util 881007 comments on draft environ protection plan Requests that Item 2 under Section 2.1 to aquatic issues be defeted Section 4.2.1 re-groundwater lezets & station water use monitoring be revised to read as stated.

 COUNSILING TU Electric (formerly Texas Utilities Generating Co.), 68/11/23. Document Control Branch (Document Control Bosk), 1p. 47676:222-47676.237.
- 8811290541 Updates status of recommendations per NUREG-1257.List of pending recommendations assigned to Ofc of Special Projects and STELLO,VI Ofc of the Executive Director for Operations, 88/11/25, ZECH Commissioners, 4pp. 47657.357-47657.360
- 8812020219 Responds to Generic Ltr 88-11, "Radiation Embritlement of Reactor Vessel Mails." Vegaci Mich., W.G. TU Electric (formally Taxas Utilities Generating Co.), 88/11/28. Document Control Branch (Document Control Desk). 1p. 47707:238-47707:238.
- 8812010138 Notification of B81208 meeting w/uti...n Gen Rose,TX to discuss S&W procedures for checking design carculations
 MALLOY,M. Ofciol Special Projects. 88/11/29. GRIMES,C.L. Ofciol Special Projects. 4pp. 47707,133.47707;138
- 6912070117 Notification of 691214 meeting w/util & TDLS in Glen Rose,TX to discuss utiligians for ASME XI VT-2 exams dissorbed in 660928 ftr GRIMES,CI Official Projects 88/12/05 PARTLOW,J.G Official Projects, 4pp 47746-096-47746-099
- 6812120050 Marked-up notification of canceled 881208 meeting w/util in Rockwio,MD se S&W procedures for checking design review calculations for plant MALLOY,M. Otc of Special Projects 88/12/06. GRIMES,C1. Otc of Special Projects 4pp. 47788 170-47788 173
- 8812120267 Concludes that corrective action establishes acceptable program for rosolving technical concerns associated w/ structural design of HVAC sys Suppl 18 to NUREG-0797 end. W/o end: GRIMES,C.). Oto of Special Projects 88/12/06 COUNSILW/O Toxas Utilities Co. 2pp. 47787.120-47787.121.
- 8812150232 Forwards Amonds 10 & 9 to CPs CPPR-126 & CPPR-127, respectively, safety evaluation & FR not ce Amends allow transfer in lownership from Brazos Electric Power Cooperative, Inc. to Texas Utilities Electric Co GRIMES, C1 Offic of Special Projects 88/12/08, COUNSIL, W.G. TU Efectric (formerly Texas Utilities Generating Co.), Spp. 47826-265-47828-277.
- -8812150234 Amends 10 & 0 to CPs CPPR-126 & CPPR-127, respectively, a lowing transfer in ownership includes from Brazos Electric Power Cooperative Inc. to Texas Utilities Electric Co. in amount of 38%. GRIMES,C1 Old of Special Projects 88/12/09, 2pp. 47826;270-47826;271.
- -8812150237 Salety evaluation supporting America 9 & 10 to CPs CPPR-126 & CPPR-
 - 127 respectively.

 * Ofc of Special Projects 88/12/68 4pp. 47626:272-47826-275.
- -8812160238 Notice of Issuance of Arronds 9 & 10 to CPs CPPR-128 & CPPR-127,re-Spective'y
 GRIMES,C.I. Old of Special Projects 88/12/08, 2pp. 47826-276-47826-277
- 8812130271 Forwards partial response to 881116 request for additinto re FSAR review. COUNSIL,W.G., WOODLAN,D.R. TU Electric (formarly Taxas Utilities Generating Co.), 88/12/09 Document Control Branch (Document Control Desk), 7pp. 47797.079-47797.085.
- 8812200251 Forwards marked-up proof & review version Tech Specs for ptantifor
- review & commants by 890125.

 GRIMES,C.I. Ofc of Special Projects. 86/12/15. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generaling Co.). 360pp. 47858;298-47859;343.
- 8812200040 Forwards technical requirements that util Inlends to Implement to Improve Usin 1 ave water reliability during time Unit 2 is in const. & test phase per 651208 meeting MV NRC In Rockev Ito,MD.

 COUNSIL W.G., WALKER,R.D. TU Electric (formerly Texas Utilities Generaling Co.), 88/12/16. Document Control Branch (Document Control Desk), 3pp. 47880.341-47660.343.
- 8812220016 Responds to NRC 881020 request for addlinfo re-natural circulation testing for facility steam electric station. Marked up draft revito FSAR App 5A and COUNSIL, W.G., WALKER, B.D. TU Electric (formetry Toxes Uthliefs Genorating Co.). 88/12/16. Document Control Branch (Document Control Desk). 34pp. 47903.317-
- 8812220071 Informs that responde to remaining FSAR sections will be provided by 890106,per 881201 telcon request for additinto re FSAR review.

 COUNSIL,W.G., WALKER,R.D. TU Electric (formerly Texas Unities Generating Co.), 88712716. Document Control Branch (Document Control Desk), 1p. 47903-039-47903-039-
- 8612270170 Forwards response to 881116 request for additing re FSAR Sections 6.5 & 1A(B),9.1.3,9.2.2,9.4.1,9.5.4,10.3.8. 10.4.9. Responses to remaining questions will be provided by 890106. COUNSIL,W.G., MARSHALL,J.S. TU Electric (formerly Texas Ubilities Generating Co.). 88/12/21. Document Control Branch (Document Control Desk). 18pp. 47978.073-47978.088.

- Technical Requirement Manual (TRM) Updated administrative control process for TRM COUNSILW.G., MARSHALL, J.S. TU Electric (formerly Toxas UTL'ses Generaling Co.). 88/12/21. Document Control Branch (Document Control Desk). 12cp. 47826-624-47926-036.
- 8812270190 Documents telcon w/NRC to delay at let response to Genoric Lt. 50.17 concerning loss of DHA capability Response will be delayed until expeditions 8 programmed enhancements addressed.
 COUNSIL,W.G., MARSHALL,U.S. TU Electric (formarly Texas Utilities Generating Co.).
 88/12/21 Document Control Branch (Document Control Dask) 1p. 47926335-

E. NRC Safety Evaluation Report (SER), suppls & correspondence

- 8812160177 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CO-MANCHE PEAK STEAM ELECTRIC STATION UNITS 1 AND 2 Docket Nos 60 445 And 50 446 (Texas Utilities Generating Company)
 NORKIN D.P. Olic of Special Projects NUREG-0787 \$17. 88/11/30. 20/200 47838 345-47838.020.
- 8812180178 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF COMMANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2 Docket Nos. 58 445 And 50-446 (Texas Unitles Generating Company)
 TERIOLD. Old of Special Projects NUREG-0797 S18 88/11/30, 96pp. 47639,021-
- 8812160181 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF (20-MANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2 Ducket Nos 50-415 And 50-446 (Texes Utilities Generaling Company) HU8BARDG, MALLOY, M. Ote of Special Projects NUREG-0797 S18. 8B/11/30-64pp 47838 121-47838.188.
- 8812190088 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CO MANCHE PEAK STEAM ELECTRIC STATION.UNITS 1 AND 2 Docket Nos 57-445 And 50-446 (Texas Unities Generating Company) MCKEE.P. BROWN.C. Oic of Special Projects
- 8812130006 Forwards request for add) into re-steam generator tube rupture enalysis to resolve proposed License Condition 18 of SSER 12 to NUREG-0797.Into requested by 881123 GRIMES, C.I. Oto of Special Projects. 88/12/06. COUNSIL, W.G. TU Electro (formedy Toxas Utilities Generating Co.). 15pp. 47799.172-47799.186.
- 8812120017 Forwards SSER 20 (NUREG-0787) re implementation of Comanche Pcak Response Team program plan & issue-specific action plans. Util assessment of root causes for design deficiencies acceptable W/o encl GRIMES,C.1. Ofte of Special Projects. 86/12/06. COUNSIL, W.G. TU Electric (for willy Tavas Utilities Generating Co.). 2pp. 47789:151-47789.152.
- 8812190181 Forwards SSER 19 (NUREG-0797) presenting satety evaluation on matters in corrective action program associated w/equipment qualification.NRC staticity by advised as to when this patient pacified property of the project of RIMES, C. Ote of Special Projects, 80/12/20, COUNSIL, W.G. TU Electric (formerly Taxas Utilities Generaling Co.). 3pp. 47851:280-47851;265.
- 8612200179 Forwards response to SER Items to proposed Toch Spacs COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/12/16 [Document Control Branch (Document Control Desk]. 5pp. 47859 356-47659 360.

F. Security, medical, emergency & fire protection plans

- 8812020034 Forwards Rev 8 to physical security plan & Rev 5 to plant training & c.-611 cation plan.Encil withheid (ref 100FR73 21 & 2.790(2)(4)). COM15tt. W.G. TU Electric (formerly Toxes Unities Generating Co.). 88/11/28 Document Control Branch (Document Control Desk). 2pp. 47721:005-47721:006.
- 9812210016 Forwards final SALP Repts 50-445/87-40 & 50-446/87-31 for Sept 1987 Avg 1988, summary of & viewgraphs from 881027 meeting & util 881128 response to SALP repti Util fit responsive to NRC concerns & recommendations. PARTLOW.JG. Of of Special Projects. 88/12/09. COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.). 4pp. 47876.051-47876:126.
- -8812210024 Final SALP Ropts 50-445/87-40 & 50-446/87-31 for Sept 1987 Aug
- Ofc of Special Projects 88/12/09.89pp. 47876.055.47878.126.

G. Adjudicatory correspondence

- 8812140097 Responds to 881007 correspondence from NUMAFIC to NRC re-beillels & Interpretation of plant sottlement NUMARC attempts to Influence Commission Inappropriate Served on 881201.

 MAFIOTTE:M. Nuclear Information & Resource Service. #488 7599. 88/11/11.
 ZECH.L.W. Commissioners. 3pp. 47770:230-47770:232.
- 8812270157 Motion for limited intervention.* Requests leave to proceed as Intervenx fimited to 870102 solltoment agreement.W/ Certificate of Svc. KOHN,S.M. Kohn & Associates #488 7712, 88/12/16 Atomic Safety and Licensing Board Panel. 4pp. 47872 083-47872.086.
- 8812270149 Crizens for Fair Uhil Regulation second suppl to 880811 request for hearing & polition for leave to intervene.* Request should be granted on basis of new Info recontly mede excitable W/supporting documentation & Certificate of Svo GRIFFIN.R.L. Critzens for Fair Unity Regulation. GRIFFIN.R.L. Griffin, R.L. #488 7711, 68/12/16. Commissioners. 320p. 4/872:087-47872:118.
- 8812280164 Memorandum & Order CLI-98-12.* Denies Citizens for Fair Util Regulation petition to intervene due to failure to justify lateness of petition. MOYLEJ.C. Office of the Secretary of the Commission, #488 7732, 88/12/21. Citizens for Fair Util ty Regulation, 11pp. 47884:318-47894:326.

H. General correspondence

- 8812020227 Urges Commission to act on Citizans for Fair Util Regulation petition & depty potition w/o further delay. Served on 881017 LEE,8 Nuclear Management & Rusources Council (NUMARC) (formerly Nuclear Utility Wanggo #488 7257 88/10/07. ZECFLL W. Commissioners. 3pp. 47879.349-47879.351.
- Q. Inspection reports, IE Bulletins & correspondence
- 831300368 Ack receipt of 881021 ftr Informing NRC of steps taken to correct violations noted in Insp. Regist 50.445/86-58 & 50.446/38-54.
 WARNICK RF. Dic of Special Projects 89/11/14 COUNSILW G. TU Electric (formerly Texas Utilities Generating Co.). 4pp. 47676-284-47676;287
- 8811300294 Ack receipt of 881027 itr informing NRC of steps taken to correct violations noted in Insp Ropis 50-445/88-54 & 50-446/86-50 WARNICK FF. Of of Special Popets 88111/16, COUNSIL,W.G. TU Electric (formerly Toxas Utilifes Generating Co.). 4pp. 47671-306, 47671:309.
- 8811230216 Forwards Insp. Ropts 50:445/88-68 & 50:446/88-64 on 881005-1101 No violations or deviations noted WARNICK.FLF. Ofc of Special Projects 88/11/17. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.), 5pp. 47622-218-47622-230
- -8811230219 Insp Ropts 50-445/88-89 & 50-446/88-84 on 881005-1101 No violations roted Major areas inspected action on 10CFR59-55(e) deficiencies, followup on NRC buffetins, plant tours & companson of as-built plant to FSAR description BITTER, SD_BURHUS, SP_WEBE, JS_Ofe of Special Projects 88/11/17 8pp 47622-223-47622-230.
- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list onci CUNNINGHAM,RE Division of Industrial & Modical Nuclear Safety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811160467 NRC Info Notice 88-001, "Impropur Administration & Control of Psychological Tests," Syc list end ROSSI, 62 Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142
- 8811290042 Responds to NRC 681003 fir ra violations noted in Insp Ropts 50.445/88-56 & 50.445/88-52 Corrective actions Rev & to TNE CS CA-CA-1a prepared to incorporate more conservative spacing criteria for hilli super lawk bolts instal allon. COUNSIL, W.G. TU Eluctric (formerly Toxes Unitios Generating Co) 88/11/22 Document Centrol Branch (Document Control Desk). 5pp. 47668-075-47668-079.
- 8812020221 Informs that util concurs w/NRC assessment of current level of performance of plant.per SALP rept for Sopt 1987 Aug 1988
 COUNSIL WG TU Electric (turnerly Toxas Utilities Generating Co.). 88/11/28 Document Control Branch (Document Control Dosk). 2pp. 47719:008-47719.007
- 8812050322 Ack receipt of 880301 & 1020 litrs informing NRC of stops taken to correct violations noted in Insp Repts 50-445/85-13 & 50-445/85-09. WARNICK, RF. Of of Spucial Projects 88/11/28. COUNSIL, W.G. TU Electric (formerly Texas Utilities Generaling Co.), 5pp. 47740-055-47740-060.
- 8812050211 Advises that completion date for correcting CAR-083 discrepancies in violation noted in Insp. Reptis 50-445/85-18-8-50-446/85-15 rescheduled for 881130. COUNSIL W.G. TU Electric (formerly Toxas Utilities Generating Co.) 88/11/30. Document Control Branch (Document Control Desk). 1p. 47733-153-47733:153
- 88 12050220 Revised response to Enforcement Action 86-09, App A, Item I C 1, based on util Inability to clearly recreate Corrective Action Request CAR-50 during reinsp Carrective actions electrical QC personnel retrained re QI-QP-11.3-26 COUNSIL, W.G. TU Electric (formerly Toxas Utilaties Generating Co). 88/11/30. Document Control Branch (Document Control Desk). 4pp. 47740.093-47740:098.
- 8812060012 Advises that anticipated date for full compliance of violation noted in thep Repts 50-445/86-07 & 60-446/86-05 revised to 890125 COUNSIL,W.G. TU Electric (formerly Toxas Uthiles Generating Co.). 88/11/30. Document Control Branch (Document Control Desk). 1p. 4/743-067-47743-067.
- 8812060032 Informs that commitments re safety-related sys & pumps made in response to NRC Bulletin 88.004 will be completed by 890213. COUNSIL, W.G. TU Electric (formerly Taxas Utilities Generating Co.). 88/11/30. Document Control Branch (Document Control Dosk). 2pp. 47734:238-47734:237.
- 8812060278 Ack receipt of B71015,880301 & 1020 this informing NRC of steps taken to correct violations in Insp. Repts 50-445/86-15 & 50-446/86-12 WARNICK, RF. Old of Special Projects 80/11/30. COUNSIL,W.G. TU Electric (formerly Yoxas Utilities Generating Co.), 4pp. 47743-043-47743-046.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events," Svc list enct. CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of Naw York, Inc. 112pp. 47811:103-47811:215.
- 8811290536 NRC Info Notice 68-094, "Potentially Undersized Valve Actuators." Svc list end... ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/12/02. Consolidated Ed-son Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812090267 Ack receipt of 880919 ltr Informing NRC of steps taken to correct violations noted in Insp Repts 50-445/80-51 & 50-446/88-47.
 WARNICK.R.F. Oic of Special Projects. 88/12/05. COUNSIL.W.G. TU Electric (formerly Texas Utilities Generating Co.). 4pp. 47761:262-47761 265.
- 8812120013 Responds to NRC 881017 litrite violations noted in Insp Ropts 50:445/88-64 & 50:446/88-60 Nonconformance repts initiated for worlds identified Disposition of nonconformance repts Indicates that welfds are suitable for use-as-is. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/12/05. Document Control Branch (Document Control Dask). 3pp. 47789.148-47789.150.
- 8812120098 Forwards Insp. Repts. 50-445/88-61 & 50-446/88-57 on 880624-1014.No violations or deviations noted. GRIMES,C.1. Old of Special Projects. 88/12/05. COUNSIL,W.G. TU Electric (formerly Toxas Utilities Ganeraling Co). 4pp. 47788:174-47788:186.

- -8812120099 Insp Repts 50-445/88-61 & 50-446/88-57 on 880624-1014 No violations or deviations noted Mejor grees inspected, previously identified ASME Code insp Inspirings & affegacions to QA/QC program & implementation WILLIAMS, C.C., GRIMES, C.I. Ofe of Spacial Projects 88/12/15 9pp. 47788-178-47788-186.
- 8812020287 NRC Info Notice 88 095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" "Svc list encl.
 ROSSI, CE. Division of Operational Events Assessment (Post 870411). 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp 47807.191-47807.302
- 8812210015 Forwards linal SALP Repis 50:445/87:40 & 50:446/87:31 for Sopt 1987 Aug 1988, summary of & viewgraphs from 881027 meeting & util 881128 response to SALP rept Util for responsive to NRC concerns & recommendations PARTLOW, J.G. Otc. of Spocial Projects 88/12/09 COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.). 4pp. 47876-051-47878-126
- -8812210024 Final SALP Ropts 50.445/87-40 & 50.448/87-31 for Sopt 1987 Aug 1888 Otto of Special Projects 88/12/09. 59pp 47878 055 47876 126
- 8812210076 Responds to NRC 881018 fir re-violations noted in Insp Repts 50-445/88-65 & 50-445/88-61 Corrective actions work orders issued to properly secure ASCO sciencial operated valvo, rework air supply fulling & replace capscrew in function box COUNSIL,W.G. TU Electric (formerly Toxas Utilies Generating Co.) 887/12/12 Document Control Branch (Document Control Desk), 3pp. 47877.043 47677.045
- 8812210081 Responds to NRC 881110 ltr re violations noted in Insp Repts 50:445/88-70 & 50:446/88-66 Corrective actions. Nonconformance Rept 88:16179 issued to resolve base metal damage on loaded embodded plates. COUNSIL, W.G. TU Electric (formerly Toxas Ull-files Generating Co.) 88/12/12 Document Control Branch (Document Control Desk). 3pp. 47881-154-47891-156.
- 8812200003 Forwards Insp. Repts 50 445/88-76 & 50-446/88-72 on 881102- 1206 No violations or daylet are noted WARNICK.R.F. Dic of Special Projects 86/12/14 COUNSIL.W.G. TU Electric (formerly Texas Utilities Generating Co). 4pp. 47871 024-47871.037
- ~8812200005 Insp Repts 50-445/68-76 & 50-446/68-72 on 891102 1206 No violations or deviations noted Major areas inspected closure of open items from previous NRC inspected closure of 10CFR50.55(e) deficiencies & general plant tours. RUNYAN,M.F., LUCERMORE,H.H. Otc. of Special Projects 88/12/14 10pp 47871.028-47871.037.
- 8812200007 Forwards Insp. Repts 50:445/88:79 & 50:446/88:75 on 881102: 1206 No violations or deviations noted WARNICK.RF. Oic of Special Projects 88/12/14. COUNSIL.W.G. TU Electric (formally Toxas Utilifies Generating Co.) 4pp. 47871 079:47871:093
- -8812200011 Insp Ropts 50.445/88-79 & 50.446/88-75 on 881102-1206 No volations or deviations noted Major eress inspected applicant actions on previous insp findings, preoperational retosting program & followup on Part 21 notices BITTER.S.D., BURRISS.P., WIEBE, J.S. Olic of Special Projects 88/12/14 11pp. 47671.083-47671.093.
- 8812270149 Citizens for Fair Util Regulation second suppl to 880811 request for heating & polition for leave to Intervene.* Request should be granted on basis of new inforecently made available W/suppointing documentation & Corthicate of Svc. GRIFFIN,R.L. Citizens for Fair Willy Regulation GRIFFIN,R.L. Griffin, R.L. #458 7711, 88/12/18. Commissioners. 32pp. 4/872/087-47872.118.

S. Reportable occurrences, LERs & related correspondence

- 8811230007 Supplemental Deliciency Rept CP-87-47 re consumable matts replacement program. Initially reported on 880209. Implementation of Procedure NEO 6 05 completed (or Unit 1 Further Implementation will be completed by 890414. COUNSIL.W.G., WOODLAN.D.R. TU Electric (formerly Texas Ulitice Generating Co.). 88/11/15. Document Control Branch (Document Control Desk). 1p. 47852.071-47652.071.
- 8811230044 Supplemental Deliciency Rept CP-88-22 of svc water discharge pipe missile protection. Initially reported on 860205 Addi Inissile protection will not be required & delicioncy not reportable under provisions of 10CFR50.55(e) COUNSIL,W.G., WOODLAN,D.R. TU Electric (formatiy Taxas Utilities Generating Co.). 88/11/16. Decument Control Branch (Document Control Desk). 1p. 47652.068-47652.068.
- 8812050208 Supplemental Delicioncy Rept CP-88-21 to JC White instrument tubing clamps Initially reported on 880129 Estimated completion data for implementation of Unit 1 revised to 880628 Junit 2 completion data has not changed COUNSIL, W.G. TU Electric (formerly Tuxas Utilities Generating Co.), 88711730, Document Control Branch (Document Control Desk), 1p. 47733:295-47733:295
- 8812050215 Supplemental Del.c.oncy Rept CP-88-29 re feedwater design med not incorporated in to FSAR Chapter 15 initially reported on 880422 Corrective action implementation schedule will be revised Completion enlicipated by 893003. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generaling Co.). 88/11/30. Document Control Branch (Document Control Desk). 1p. 47733:154-47733:154.
- 8812050328 Supplemental Deliciency Rept CP-87-964 re design basis tornado analysis for safety-related equipment initially reported on 880120. Estimated date for completion of equipment evaluation revised to 880130. COUNSIG. W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/11/30. Document Control Branch (Document Control Desk). 1p. 47740.101-47740:101.
- 8812060007 Supplementel Det.clency Rept CP-87-115 re modeling error for seismic analysis of svc water intake structure.Corrective action inprementation schedule updated & statement in unitir re-effects of revised Foor response spectrum revised. COUNSIL,W.G. TU Electric (formerly Taxes Utilities Generating Co.). 88/11/30. Document Control Branch (Document Control Dosk). 1p. 47743.047-47743.047.

- 8812080035 Suppremental Deficiency Rept CP-85-50 re use of Improper wolding process in mtg of cable tray tea fittings Initially reported on 870930.Completion date of 881130 for completion of activities rescheduled to 800301 COUNSILWIG TU Electric Hormary Texas Villies Generating Co.) 89/11/30 Docu
 - mont Control Branch (Document Control Desk) 1p. 47744:359-47744.359.
- 8812060152 Supplemental Deliciency Rept CP-88-19 re qualification of instrument cable insulation inside containment Intiaty reported on 880129 Engineering evaluation continuing. Corrective actions will be completed by 890428. COUNSYLWIG, WALKER,RO TO Electric (formerly Texas Utilities Generating Co) 88/12/01. Document Control Branch (Document Control Desk) 1p. 47745.041-4745.041
 - 47745 041.
- 8812060158 Supplemental Deliciency Rept CP-88-18 re-post-accident monitoring channels for RCS Initially reported on 880125 Installation of third monitoring channel for RCS pressure rescheduled for completion by 890320 Unit 2 unchanged COUNSIL W.G., WALKER,R.D. TU Electric (formerly Texas Ultrias Generating Co.). 88132101. Document Control Branch. (Document Control Desk) 1p. 47745.040 47745 040
- 8812060186 Deficiency reptire coating removal from station svc water sysip ping initially reported on 860923 Listed incomplete items with be completed by 861216 Compensatory measures discussed in ER ME-19 with remain in praction initially COUNSILING, WALKER, R.D. TU Electric (formarly Texas Utilities Generating Co) 88/12/01. Document Control Branch (Document Control Desk) 1p 47745,039-47745,039
- 8812060168 Supplemental Deficiency Rept CP-86-07 re wold failure & coating degradation in station svc water-initially reported on 860411 Estimated completion date of 881201 for corrective actions rescheduled for 890117.

 COUNSIL,WIG, WALKERAD. TU Electric (formerly Texas Utilities Generating Co) 86/12/01. Document Control Branch (Document Control Desk) 1p. 47745-038-47745-038
- 8812150055 Supplemental Delictency Rept CP-87-07 re items procured to improper code class. In tally reported on 880901. Unit 1 corrective actions for issue have been rescheduled for completion by 890531 & that for Unit 2 not changed COUNSIL, W.G., WODDLAN, DR. TU Electric (formerly Texas Unit less Generaling Co.). 88/12/09 Document Control Branch (Document Control Desk) 1p 47822.348-47823.249
- 8812210073 Supplemental Deficiency Rept CP-87-134 ra Class 1E ac electrical sys.Initially reported on 880111 Loading calculations affecting cable sizing & circuit breaker string completed Documentation update schedured for 890125. COUNSIL, W.G. TU Electric (formerly Texas Ulitilise Generating Co.) 88/12/12 Document Control Branch (Document Control Dosk). 1p. 47878/293-47878/293.
- 8812220011 Supplemental Deliciency Rept CP-86-82 re-cable tray hanger spice worlds Initially reported on 870108. Corrective actions for Unit 1 rescheduled for completion by 890630. Unit 2 remains as previously scheduled. COUNSIL, W.G., WOODLAN, D.R. TU Electric (formerly Texas Utilities Generating Co.). 88/1/2/13. Document Control Branch (Document Control Desk) 1p. 47903/037-47003/037 47903 037
- 8612200038 Interim Deficiency Rept CP-88-37 re ASCO solono.d valve coil toads Initially reported on 881114 Crass 1E ASCO solonolds received on Purchase Order #685-70352 will be scrapped per Nonconformance Rept 86-15048.

 COUNSIL, W.G., WOODLAN, D.R. TU Electric (formerly Texas Utilities Gonorating Co.) 88/12/14. Document Control Branch (Document Control Dask). 2pp. 47868-231-47868-232.
- 8812200044 Final Deficiency Rept CP-88-38 re steam generator PORV capacity in analysis of design basis steam generator tube rupture initially reported on 881114.Licensed will revise design basis analysis. COUNSIL,W.G. TU Electric (formerly Toxes Utitios Generating Co.). 88/12/14. Document Control Branch (Document Control Desk). 2pp. 47868.237-47868.238.
- 8912200065 Supplemental Deficiency Rept CP-87-132 re unqualified Limitorque actuators in itality reported on 880105-Unit 1 corrective actions rescheduled for completion by 890503. Schedule for Unit 2 remains unchanged. COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/12/14. Document Control Branch (Document Control Dask). 1p. 47860-350-47860-350.
- 88 12200083 Supplemental Deticiency Rept CP-87-100 re tack of overpressure protection for three containment penetrations in tiety reported on 871201. Administrative procedure changes implemented for Unit 1. Compilot on date is 880228 COUNSIL, W.G., WOODLAN, D.F. TU Electric (formerly Toxas Utilities Generating Co.). 88/12/14. Document Control Branch (Document Control Dask). 2pp. 47860 295-47860 295.
- 8812200068 Supplemental Deficiency Rept CP-88-12 ra violation of electrical separation oriteria initially reported on 880111. Estimated completion date for rejouting 8 redesignation of cables revised to 890215. COUNSILWIG, MARSHALL JS. TU Electric (formerly Texas Utilities Generating Co.). 68/12/15. Document Control Branch (Document Control Dest). 1p. 47868-230-230-230.

47880, 298.

47888 230

- 8812200156 Supplemental Deficiency Rept CP-88-018 re-difficulties in starting & operating safety chilled water chiller units. Initially reported on 860521.Comptetion date for corrective actions rescheduled for 896530.
 COUNSIL,W.G., MARSHALL,J.S. TU Electric (formerly Texas Ultities Generating Co).
 88/12/15. Document Control Branch (Document Control Desk). 1pp. 47801:125-
- 8812210129 Supplemental Deficiency Rept CP-86-45 to Selsmic Category II says & components initially reported on 871016 Completion of Unit 1 corrective actions rescheduled for 890630 Scheduled for Unit 2 corrective actions unchanged. COUNSIL,W.G., MARSHALL.J.S. TU Effective (formerly Towas Utilities Generating Co.). 88/12/15. Document Control Branch (Document Control Desk). 1p. 47875;326-43375;305
- 8812210135 Supplemental Deficiency Rept CP-88-19 to Class IE instrument Installations initially reported on 880128. Unit 1 corrective actions rescheduled for completion by 890612. Schedule for full 2 unchanged.

 COUNSIL, W.G., MARSHALL, J.S. TU Electric (formerly Texas Utilities Generating Co.).

 88/12/15. Document Control Branch (Document Control Desk). 1p. 47892.027-47992-907 47882-027

- 8812210157 Supplemental Deliciency Rept CP-87-101 re Class tC cabra arrangement Initially reported on 880111.Corrective action for Unit 1 reschiedured by complet on by 890301 & schedule for Unit 2 remains unchanged COUNSULWG, MARSHALLS 3 TU Electric (formenty Texes Utilities Generaling 88/12/15 Document Control Branch (Document Control Desk) 1p 47698 130-47698 150
- 8812210163 Supplemental Deficiency Rept CP-87-23 re-conduct unions Initially reported on 870727 Unit 1 corrective actions reschadulad for completion by 890402 Unit 2 corrective actions completion schedule unchanged. COUNSIL, W.G., MARSHALL, J.S. TU Electric (formerly Texas Utilities Generating Co.) 88/12/15. Document Control Branch (Document Control Dosk). 1p. 47875/250-4208-230
- 8812200143 Supplemental Deliciency Rept CP-87-55 re-containment spray pump recu-culation piging initially reported on 871208 Replacement of affected containment spray pump recirculation piging w/ASME Class 2 pipe & Category I supports continu ing COUNSIL,W.G. TU Electric (formerly Texas Utritios Generating Co.), 88/12/18. Document Control Branch (Document Control Dosk), 1p. 47870.334-47870.334
- 8812200184 Supplemental Deficiency Rept CP-84-08 re-curtain fire dampars findlefy re-ported on 840620 Corrective action stated in 870817. Its communing New correct va-action estimated completion date set for 880630. COUNSIL W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/12/16. Deci-ment Control Brench (Document Control Desk). 1p. 47863-076-47863-076.
- 8812270174 Supplemental Deticioncy Rept CP-88-23 re design basis groundwater elevation. Initially reported on 880204 Unit 1 completion date for mod of waterproofing & leak collection sys & installation of plezometers revised to 890417. COUNSIL, W.G., MARSHALL, JS TU Electric (formerly Texas Utilios General Ing. Co.) 88/12/21. Document Control Branch (Document Control Desk) 1p. 47926 174-47926:174
- 8812270175 Interim Deticioncy Rept CP-88-38 ro RHR valve position indicator to-liefly reported on 881122.issue under evaluation for safety impact.Next rept subtricted by 890210 BB/12/21. Document Control Branch (Document Control Desk). 2pp. 47927.035-47927.038
- 8812270177 Supplemental Deliciency Rept CP-87-19 re ambient temp effects on MSIV actuators initially reported on 880118. Corrective actions for Unit 2 astimated to be completed 6 months prior to fuel load.

 COUNSIL,W.G., MARSHALL.J.S. TU Electric (formorly Texas Utilities General by Co.)

 86/12/21. Document Control Branch (Document Control Dest). 1p. 47926 168.

 47926-168.
- 8812270184 Supplemental & Interim Deficiency Repts CP-88-34 re RHR HXs support design. In flatly reported on 881098. Closure of mod documentation in progress & will be completed by 800224.

 COUNSIL, W.G., MARSHALL, J.S. TU Electric (formerly Taxas Utinies Generating Co.) 88/12/21. Document Control Branch (Document Control Desk) 1p. 47926. 336-47926.336.
- 8812270224 Supplemental Deficiency Rept CP-85-54 re-seismic quelification of NVAC supports.Initially reported on 860926. Estimated completion date for constitution for Unit 1 rescheduled to 890630.

 COUNSIL.W.G., MARSHALL,J.S. TU Electric (formerly Texas Utilities Generating Co.) 88/12/21. Document Control Branch (Document Control Desk). 1p. 47927.061. 47927.061.

U. Congressional/Executive Correspondence

8811300076 Forwards NRC quarterly status ropt covering Third Quarter CY88 in response to direction given in House Ropt 97-850. ZECH,L.W. Commissioners 98/11/10. BEVILL,T. House of Rep., Appropriators 12pp. 47733.001-47733.012.

DOCKET 50-448 COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 2

A. Application/construction stage documents & correspondence

- 8811230210 Notification of 881206 meeting w/util in Flockville,MD to discuss design of essential svc watersys.
 WILSON.J.H. of Special Projects 88/11/17. GRIMES,C.I. Otc of Special Projects 25p. 4762:231-47622:232.
- 8611280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729:024.
- 8611300172 Revises will 881007 comments on draft environ protection plan Requests that Item 2 under Section 2.1 re aquatic issues be deleted. Section 4.2.1 re groundwat-
- relievels & station water use monitoring be revised to read as stated.

 COUNSIL, W.G. TU Electric (formally Texas Utilities Generating Co.). 88/11/23 Document Control Branch (Document Control Desk). 1p. 47676:222-47676:237.
- 8811290541 Updates status of recommendations per NUREG-1257.List of pending recommendations assigned to Ofc of Special Projects encl. STELLO,V. Ofc of the Executive Director for Operations, 88/11/25, ZECH Commissioners, 4pp. 47657:357-47657:380.
- 8812020219 Responds to Generic Ltr 88-11, "Radiation Embrittlement of Reactor Vessel Mails COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.), 88/11/28, Document Control Branch (Document Control Dask), 1p. 47707:238-47707:238.

- 8812010138 Notification of 881208 meeting w/ut.l in G'en Rose,TX to discuss S&W procedures for checking design calculations
 MALLOY,M. Old of Special Projects 88/11/29 GRIMES,C.I. Old of Special Projects,
 4pp. 47707.133.47707.136
- 8812070117 Notification of 881214 meeting w/util & TDLS in Glen Rose,TX to discuss uit plans for ASME XI VT-2 exams described in 880928 ltr.
 GRIMES,CI. Ofc. of Special Projects 88/12/05. PARTLOW,J.G. Ofc of Special Projects 4pp. 47746.888-47746.888.
- 8812120980 Marked-up notification of canceled 881208 moeting w/util in Rockville,MD re S&W procedures for checking dosign review calculations for plant.

 MALLOY M. Oto of Special Projects 88/12/06. GRIMES,C I. Oto of Special Projects.
 40p. 47/88 170-47/86:173
- 8812120267 Concludes that corrective action establishes acceptable program for resolving fechalcal concerns associated w/ structural design of HVAC sys Suppl 18 to NUREC 0797 encl. W/o encl. GRIMES,CI. Ofc. of Special Projects. 88/12/06 COUNSIL,W.G. Texas Utilities Co. 2pp. 47787.120.47787.121.
- 8612150232 Forwards Amends 10 & 9 to CPs CPPR-126 & CPPR-127, respectively, seletly evaluation & FR notice Amends allow transfer in ownership from Brazos Electric Power Cooperative, Inc to Texas Utritiae Electric Co. GR
- -8812160234 Amends 10 & 9 to CPs CPPR-126 & CPPR-127, respectively, allowing transfer in ownership interest from Brazos Etectric Power Cooperative, Inc. to Texas Utilities Electric Co in amount of 3.8%.
 GRMES.C.I. Ofc of Special Projects 88/12/08. 2pp 47828.270-47828.271.
- -8812150237 Safety evaluation supporting Amends 9 & 10 to CPs CPPR-128 & CPPR-127, respectively. Ole of Special Projects, 88/12/08, 4pp. 47826 272-47826:275.
- -8812150238 Notice of issuance of Amends 9 & 10 to CPs CPPR-126 & CPPR-127,tospectivery. GR MES,C I. Ofc of Special Projects 88/12/08 2pp. 47826:276-47828:277.
- 8812130271 Forwards partial response to 681116 request for addl Info re FSAR review. COUNSIL.W.O., WOODLAN,D.R. 7U Electric (formarly Toxas Utilities Generating Co.) 8812709. Document Control Branch (Document Control Desk) 7pp. 4779.079-
- 47797 085
- 8812200040 Forwards technical requirements that util intends to implement to improve Until sec water reliability during time Unit 2 is in const. & test phase,per 681206 mobiling W/ NRC in Rockovillo,MD.
 CCUNSt.,W.G., WALKER,R.D. TU Electric (formerly Texas Utilities Generating Co.). 88/12/16. Document Control Branch (Document Control Dosk). 3pp. 47680.341-4769.0341. 47860 343.
- 8812220016 Responds to NRC 881020 request for addl Info re natural circulation test-Ing for facility steam electric station. Marked-up draft rov to FSAR App 5A enci.
 COUNSIL W.G., WALKER, F.D. TU Electric (formarly Texas Utilities Generating Co.).
 88/12/18. Document Control Branch (Document Control Desk). 34pp. 47803/317-47903 350.
- 8812220071 Informs that response to remaining FSAR sections will be provided by 890108 per 881201 telcon request for addit Info re FSAR review.

 COUNSIL,W.G. WALKER,R.D. TU Electric (formerly Texas Utilities Generating Co.).

 8812218. Document Control Branch (Oocument Control Desk). 1p. 47903:039-47903 039.
- 8812270170 Forwards response to 861116 request for addl info re FSAR Sections 6.5 & 1A(9),9.1.3,9.2.2,9.4.1,9.5.4,10.3 & 10.4.9. Responses to remaining questions will be provided by 800108. COUNSIL, W.G., MARSHALL, J.S. TU Electric (formerly Texas Utilities Generating Co.). 88/12/21, Document Control Branch (Occument Control Dask). 18pp. 47978.073-47079-809

8812270190 Documents telcon w/NRC re delay of util response to Generic Ltr 88-17 concerning loss of DHR capability.Response will be delayed until expeditious actions 8 programmed enhancements addressed.

COUNSIL,W.G., MARSHALL,J.S. TU Electric (formerly Texas Utilities Generating Co.).

88/12/21. Document Control Branch (Document Control Desk). 1p. 47928-335-4298-325.

E. NRC Safety Evaluation Report (SER), supple & correspondence

47826 335.

- 8812180177 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CO-MANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2 Docket Nos 50-446 And 50-446, Texase Utilities Genorating Company) NORKIN, D.P. Ofc al Spocial Projects. NUREG-0797 \$17. 68/11/30. 200pp.
- 8812160178 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CO-MANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2.Docket Nos. 50-446 And 50-446 (Texas Uli'llies Generaling Company) TERAC.D. Ofc of Special Projects. NUREG-0797 S18. 88/11/30. 96pp. 47838:021-
- 8812160181 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CO-MANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2. Docket Nos. 50-446 And 50-446. (Texas Utilities Generaling Company) HUBBARD, MALLOY, M. Ofc of Special Projects. NUREG-0797 S19. 88/11/30. 64pp. 47838:121-47838:188.
- 8812190088 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CO-MANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2 Docket Nos. 60-445 And 50-446, (Texas utilities Generating Company) MCKEE, BROWN, C Ofc of Special Projects. NUREQ-0797 S20. 88/11/30. 380pp. 47840:198-47841:058.

- 8812120017 Forwards SSER 20 (NUREG-0797) re implementation of Comanche Peak Response Team program plan & issue-specific action plans Util assessment of root causes for design deliciencies acceptable.W/o encl.
 GRIMES,C I. Ofic of Special Projects 801/2/08 COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.). 2pp. 47789.151-47789.152.
- 8812190181 Forwards SSER 19 (NUREG-0797), presenting safety evaluation on matters re-corrective action program associated w/oquipment qualification NRC should be advised as to when util anticipate reaching 90% compitation point W/o enci.
 GRIMES,C. I. Otto of Special Projects, 88/12/09, COUNSIL,W.G. TU Electric (formetry Texas Utilities Generating Co.), 3pp. 47851:263-47851:265.

F. Security, medical, emergency & fire protection plans

- 8812020034 Forwards Roy 6 to physical socurity plan & Rey 5 to plant training & qualification plan Encis withheld (ref 10CFR73.21 & 2.790(2)(4)).
 COUNSIL W.G. TU Electric (formerly Texas Utilities Generating Co.) 88/11/28 Document Control Branch (Occument Control Desk). 2pp. 47721.005-47721.006.
- 8812210015 Forwards final SALP Repts 50-445/87-40 & 50-446/87-31 for Sept 1987 -Aug 1096, summary of 8 viewgraphs from 981027 niceting 8 util 891128 response to SALP rept Util ftr responsive to NRC concerne 8 recommendations PARTLOW, JG. Otc of Special Projects. 89/12/209 COUNSIL, WG TU Electric (termerly Toxas Utilities Generating Co.). 4pp. 47876 051-47876:126
- +8812210024 Final SALP Repts 50-445/87-40 & 50-446/87-31 for Sept 1987 Aug Ofc of Special Projects, 88/12/09, 69pp. 47876 055-47876:126.

G. Adjudicatory correspondence

- 8812140097 Responds to 881007 correspondence from NUMARC to NRC re-befiels & interpretation of plant settlement NUMARC attempts to incluence Commission inappropriate Served on 881201.

 MARIOTTE,M. Nuclear Information & Resource Service. #488 7599. 88/11/11. ZECH,L.W. Commissioners 3pp. 47770:230. 47770:232.
- 8812270157 Motion for limited intervention.* Requests leave to proceed as Intervenor limited to 870102 settlement agreement.W/ Certificate of Svc KOHN,S.M. Kohn & Associates, #488 7712, 88/12/15, Atomic Safety and Licensing Board Panel, 4pp. 47872.083-47872.086.
- 8812270149 Citizens for Fair Util Regulation second supplite 880811 request for hearing 8 petition for leave to intervene.* Request should be granted on basis of new info recently made available.W/supporting documentation & Certificate of Svc. GRIFFIN.R.L. Citizens for Fair Uting Regulation. GRIFFIN.R.L. Gittin, R.L. #488 7711. 88/12/16. Commissioners. 32pp. 47872:087-47872:118.
- 8812280164 Momorandum & Order CLI-88-12.* Denies Citizens for Fair Util Regulation petition to infervene due to fellure to justify lateness of petition HOYLE, J.C. Office of the Secretary of the Commission, #486 7732, 86/12/21, Citizens for Fair Utility Regulation, 11pp. 47884:316-47884:326.

H. General correspondence

8812020227 Urges Commission to act on Citizens for Fair Util Regulation potition & deny potition w/o further delay. Served on 881017.
LEF,B. Nuclear Management & Resources Council (NUMARC) (formarly Nuclear Utility Manage. #488 7257. 88/10/07. ZECH,L.W. Commissioners. 3pp. 47878 349-47879.351.

Q. Inspection reports, IE Builetins & correspondence

- 8811300368 Ack receipt of 881021 ltr informing NRC of steps taken to correct violations noted in Insp Regis 50-445/88-58 & 50-446/88-54.
 WARNICK, R.F. Oic of Special Projects. 886/11/14. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.). 4pp. 47676:284-47678:287.
- 8811300294 Ack receipt of 881027 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-445/88-54 & 50-446/88-50.

 WARNICK, F.F. Dic of Special Projects, 88/11/18, COUNSIL,W.G. TU Electric (tormerly Texas Utilities Generating Co.), 4pp. 47671:308-47671:309.
- 8611230216 Forwards Insp. Repts 50-445/88-68 & 50-446/88-64 on 861005-1101.No violations or deviations noted.
 WARNICK,R.F. Of of Special Projects. 88/11/17. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.). 5pp. 47622:218-47622:230.
- -8511230219 Insp Repts 50-445/88-88 & 50-446/88-64 on 861005-1101 No violations noted. Major areas Inspected action on 10CFR50.55(e) deficiencies followup on NRC builtetins plant tours & comparison of es-built plant to FSAR description.

 BITTER.S.D., BURRIS.S.P., WIEBE.J.S. Ofc of Special Projects. 86/11/17. 8pp. 47822:223-47622:230.
- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc list enct.
 CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729).
 86/11/22. Consolidated Edison Co. of New York, Inc. 89pp. 47708 255-47708 257.
- 8811180487 NRC Info Notice 88-091, "improper Administration & Control of Psychological Tests." Syc list enct. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708-042-47708:142.
- 8811290042 Responds to NRC 881003 ltr re violations noted in insp Repts 50-445/88-56 & 50-446/88-52.Corrective actions Rev 8 to TNE-CS-CA-CA-ta prepared to incorporate more conservative spacing criteria for hittl super kwik botts instellation. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/11/22. Document Control Branch (Document Control Desk). 6pp. 47668:075-47668.079.

- 8812020221 Informs that util concurs w/NRC assessment of current feval of perform ance at pfant per SALP rept for Sept 1987 Ang 1988. COUNSILW G. 7U Electric (furmerly Texas Utilities Generating Co.): 88/11/28. Document Control Branch (Decument Control Desk): 26p. 47719.996-47719.907.
- 8812050322 Ack record of 880301 & 1020 firs informing NRC of steps taken to correct violations noted in linsp Repts 50 445/85/13 & 50-445/85/09 WYARNICKA F. Ote of Special Projects, 88/11/28 COURSILIANG. TU Electric (fea
- 8812050211 Advises that completen date for correcting CAR 063 discrepancies in vio-lation noted in http://doi.org/10.1007/10.0007/10.
- 8812050220 Revised response to Enforcement Action 86-09, App Alitem 1 C. 1, Lased on of Linabity to clearly recreate Corrective Action Request CARI-50 during reinspicotrective actions ofcethea? OC personnel revained to QI OP-113-28 COUNSTLIM G. TU Efectic (formerly Toxas Utilities Generating Co.) 897-11730. Document Control Branch (Document Control Dosk). 4pp. 47740-033-47740-096.
- 8812060012 Advises that enticipated date for full compliance of vicialism noted in Insp. Repts 50-445786-07 & 50-445786 for revised to 690125. COUNSIL W.G. TU Electric (formerly Texas 80/files Generating Co.): 88/11/30 Document Control Branch (Document Control Desk), 1p. 47743-067-47743.067.
- 8812060032 Informs that commitments to safety related sys & pumps made in response to NRC Buffetin 88 004 will be comfided by \$90213. COUNSIL, WIGHTU Existing fromerly Texas Ultilies Generating Co.) 88/11/30. Document Control Branch (Document Control Dosk). 2pp. 47734-236-47734.237.
- 8812060278 Ack receipt of 871015,880301 & 1020 lits informing NRC of steps taken to correct violations in http://deepis.50.445786-15 & 50.445786-12. WARNICK,R.F. Ofc. of Special Projects, 88711730 COUNSILW.G. TU Electric (formerly Texas Utilities Generating Co.). 4pp. 47743-043-47743-048
- 8811290030 NRC fato Notice 88/093, "Teletherapy Evants." Svoillst enct. CUNN:NGHAM,R.E. Division of Industrial & Modical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811.215.
- 8811290538 NRC Into Notice 88 094, "Potentially Undersized Valve Actuators" Syc fist enci ROSSI,C.E. Division of Operational Events Assussment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47706 143-47708 254.
- 8812090257 Ack receipt of 680919 ftr Informing NRC of steps taken to correct violations noted in Insp Ropits 50-445/88.51 & 50-446/88-47 WARN.CK,R F. Ofc of Special Projects 88/12/05 COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.) 4pp. 47761:265
- 8812120013 Hespands to NRC 881017 ftr re-violations noted in linsp Repla 50-445/88-64 & 50-440/88-60 Nonconformance repts in tiated for walds identified Disposition of nonconformance repts indicates that welds are suitable for use as is COUNSIC W.G. TU Electric (formerly Texas Utilities Generating Co.), 68/12/05 Docu-ment Control Branch (Document Control Desk). 3pp. 47789-148-47789.150
- 8812120096 Forwards Insp. Repts 50-445/88-61 & 50 446/88-57 on 889624-1014 No. violations or deviations solied.

 GRIMES,C.I. Ofc of Special Projects 68/12/05, COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.), 4pp. 47788.174-47788.186
- -9812120099 trisp Repts 50-445/88-61 & 50-446/88-57 on 880824-1014 No including of deviations noted Major areas inspected previously identified ASME Code insp. findings & allegations to OA/OC program & implementation WILLIAMS, CC., CRIMES, CI. Old of Special Projects 88/12/15, 9pp. 47788-178-47788 186
- 8812020287 NRC into Notice 89:095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors," Svc list end. ROSSI, C.E. Division of Operational Events Assessment (Post 870411) 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812210015 Forwards final SALP Repts 50.445/87-40 8 50.448/87-31 for Sopt 1907 Aug 1998, summary of & viewgraphs from 881027 meeting & util 881128 response to SALP rept.Util fir responsive to NRC concerns & recommendations. PARTLOW.J.G. Ofc of Special Projects 88/12/09 COUNSIL.W.G. TU Electric (formarly Texas Utilities Generating Co.), 4pp. 47878 051-47876;128
- -8812210024 Final SALP Repts 50-445/87-40 & 50-448/87-31 for Sept 1087 Aug. * Ofc of Special Projects 88/12/09, 69pp. 47876-055 47876-128
- 8812210078 Responds to NAC 881018 ltr re violations noted in Insp Repts 50 445/88. 65 & 50.446/09-61 Corrective actions work orders issued to properly secure ASCO solono'd operated valve, rework air supply fubling & replace capscrow in junction box COUNSIL, W.G. TU Electure (formerly Texas 2 Unitios Generating Co.) 88/12/12. Document Control Branch (Document Control Desk), 3pp. 47877.043 47877:045
- 8812210081 Responds to NRC 881110 ftr re-violations noted in Insp. Repts 50-445/88-70 & 50-446/88-68 Corrective actions: Nonconformance Rept 68-16179 issued to resolve base metal damage on loaded embedded plates COUNSIL, W.G. TU Electric (formetly Texas Utilities Generating Co.). 88/12/12. Document Control Branch (Document Control Desk). 3pp. 47681:154-47881:156.
- 8812200003 Forwards Insp Repts 50-445/88-76 & 50-446/88-72 on 861102- 1206.No
 - violations or deviations noted WARNICK, R.F. Otc. of Special Projects 88/12/14. COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.) 4pp. 47871.024-47871.037.
- -8812200005 Insp Repis 50.445/88.76 & 50.446/88.72 on 881102-1206 No violations or deviations noted Major areas inspected closure of open tioms from provious NRC insp ropts,review & closure of 10CFR50.55(e) deficiences & general plant tours. RUNYAM,M.F. LIVERMORE,H.H. Ofc. of Special Projects. 88/12/14. 10pp 47871.028.47871.027.
- 8812200007 Forwards Insp Repts 50-445/88-79 & 50-446/88-75 on 881102- 1206 No violations or deviations noted WARNICK, R.F. Old of Special Projects. 88/12/14. COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.) 4pp. 47871-079-47871-093.

- -8812200011 Insp. Ropts 50:445/88-79 & 50:446/88-75 on 881102:1206 No verations or devalors noted Major areas inspected applicant actions on previous 1550 indivise preparational rotesting program & followup on Part 21 natices. BITER S.D., BURRIS.S.P., WEBEJS, Orc. of Special Projects 88/12/14, 11pp. 47671 083 47871 093
- 8812270149 Cilizens for Fair Uti Regulation second supplite 88811 request for hearing 8 petition for feave to intervene. Request should be granted on hasts of new inforcerelly made available Waspporting documentation & Certificate of Svc GRIFFINR L. Citzens for Fair Utility Regulation. #488,7711, 88/12/16. Commissioners, 32pp. 47872,087-47872,118.

S. Reportable occurrences, LERs & related correspondence

- 8811230007 Supplemental Colicionary Flopt CP-87-47 to consumable mails replacement program. In tiety reported on 880209, implementation of Procedure NEO 6.05 completed the Unit in Further implementation will be completed by 890414. COUNSIL, W.G., WOODLAN, D.R. TU Electric (burnerly Toxas Ultimos Generaling Co.) 88/11/15. Document Control Branch (Document Control Dask). 1p. 47652-97 (-22012)
- 8811230044 Supplemental Deficiency Ropit CP-88-22 rollsve water discharge openwissie protection fellialty reported on 880205 Adult missile protection will not be required 8 deficiency not reportable under provisions of 10CFR50 55(a).

 CCUNSIL,W.G., WOODLAN,D.R. TU Electric (formerly Toxas Unities Generating Co.) 88/11/15. Decument. Control. Branch. (Document. Control. Desk.). 1p. 47852 068-47652 069.
- 8812850205 Supplemental Dehicioncy Rept CP-88-21 to 3C White instrument Liting clamps fraillelly reported on 880129 Estimated completion date for implementation of Unit 1 coxised to 890689 Unit 2 completion date has not changed COUNSIL, Wid. TU Electric (furnierly Toxas Unities Gonerating Co.) 88/11/30. Document Control Branch (Document Control Dosk) 1p. 47733-295.
- 8912050215 Supplemental Doliciancy Rept CP-86-29 re loodwater design mod not in-corporated in to FSAR Chapter 15 Initially reported on 880422 Corrective action impro-mentation schedulo will be revised Completion anticipated by 890303 COUNSELW.G. TU Efecting (formerly Tuxas Unities Generating Co.). 88/11/30. Docu-ment Control Branch (Document Control Desk). 1p. 47733-154-47733:154
- 8812050329 Supplemental Dot.ciency Rept CP-87-084 re design basis for add analysis for safety related equipment in tally reported on 880120 Estimated date for comptct-on of equipment evaluation revised to 890130 CCUNSII, W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/11/30 [Nocument Control Branch (Document Control Desk). 1p. 47740:101-47740.101.
- 8812060007 Supplemental Deficiency Rept CP-87-115 re modeling error for scientic analysis of six water inteks structure. Corrective action implementation schools updated 8 statement in will lit re effects or revised floor response specime revised. COUNSILWIG TU Electric (formerly Toxes Utritios Generating Co.). 88/11/20 Deciment Control Branch (Document Control Dosk). 1p. 47743-047-47743-047.
- 8812060035 Supplemental Deficiency Rept CP-85-50 re use of improper walding process in mig of cable tray tee fillings initially reported on 870930 Completion date of 881130 for completion of activities rescheduled to 800301.
 COUNSIL W.G. TU Electric (formorty Texas Utilities Generating Co.). 88/11/30. (XX urnent Control Branch (Document Control Dusk). 1p. 47744.359-47744:359.
- 8812988152 Supplemental Deliciency Rept CP-88-19 re qualification of instrument cable insulation inside containment Initially reported on 880129 Engineering evaluation continuing Corrective actions will be completed by 890428.

 COUNSIL, W.G., WALKER, R.D., TU Efectric (formerly Toxas Utilities Generaling Co.) 88/12/01. Document Control Branch (Document Control Dosk). 1p. 47745-041-47745-041. 47745.041.
- 8812860158 Supplamental Deliciency Rept CP-88-18 to post-accident monitoring channols for RCS Initially reported on 880125. Installation of third monitoring channols RCS pressure rescheduled for completion by 880920 Unit 2 unchanged COUNSIL,W.G., WALKER,R.D. FU Electric (formally Toxes Utilities Generally Co.) 88712701. Document Control Branch (Document Control Dosk) 1p. 47745-040-47745-040.
- 8812060166 Delicioncy rept re-coating removal from station svc water sys p.ping In 331y reported on 880823.Listed incomplete items will be completed by 881218 Compensatory menaures discussed in En-ME-19 will remain in place in Interim COUNSIL, W.G., WALKET, R.D. TU Electric (formerly Toxas Utilities Generating Co.). 88/12/01. Document Control Branch (Document Control Dosk) 1p. 47745-039-4745-039 47745 039
- 8812060188 Supplemental Deliciency Rept CP-86-07 re weld fallure & coaling clogreda-tion in station svc water initially reported on 880411.Estimated completion date of 881201 for corrective actions rescheduled for 890117. CCUNSIL,W.G., WALKER.R.D. TU Electric (formarily Toxas Utilities Generaling Co.). 8812/91. Document Control Branch (Document Control Desk) 1p. 47745-038-47745:03B.
- 8812150055 Supplemental Deficiency Rept CP-87-07 re items procured to improper code class initially reported on 880901 Unit 1 corrective actions for issue have been rescheduled for completion by 890531 & that for Unit 2 not changed COUNSIL.W G., WOODLAN, D.R. TU Electric (formerly Texas Utilities Generaling Co.) 887/12709. Document Control Branch (Document Control Desk). 1p. 47822.348.
- 8812210073 Supplemental Deficiency Right CP-87-134 re Class IE ac plockical sys Initially reported on 880111.Loading calculations affecting cable sizing & circuit breaker sizing completed Documentation update scheduled for 890125. COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/12/12. Document Control Branch (Document Control Dosk). 1p. 47878,293-47878.293
- 8812220011 Supplemental Deficiency Rept CP-86-82 ro cable tray hargor spice wilds initially reported on 870108 Corrective actions for Unit 1 rescheduled for completion by 89080 Unit 2 remains as previously scheduled COUNSIL W.G., WOODLAN, D.R. TU Electric (formerly Toxas Utilities Generating Co. 1 88/12/13. Document Control Branch (Document Control Desk). 1p. 47903.037-47903.037.

- 8812200044 Final Deliciency Rept CP-80-38 re-steem generator PORV capacity in analysis of design basis steam generator tube rupture inflially reported on 881114 Licensee will revise design basis analysis COLNSIL, W.G. TU Electric (tormetry Texas Utritios Generating Co.) 88/12/14. Document Control Branch (Document Control Dask). 2pp. 47868-237-47868-238.
- 8812200065 Suppremental Doticlency Rept CP-87-132 ro unqualified Limitorque actuators Initially reported on 880105 tinit 1 corrective actions rescheduled for completion by 890503. Schedule for Unit 2 remains unchanged COUNSII, W.G. TU Electric (formerly Toxes Utilities Generating Co.) 88/12/14 Document Control Branch (Document Control Desk). 1p. 47860.360-47860.360.
- 8812200083 Supplemental Deticiency Ropt CP-87-100 re tack of overpressure protection for three contemment penetrations. Initially reported on 871201 Administrative procedure changes implemented for Unit 1 Completion date is 980228. COUNSIL W.G., WOODLAN,D.R. TU Electric (formerly Toyas Utilities Generating Co.). 88/12/14. Document Control Branch (Document Control Desk). 2pp. 47860-295-47880-296.
- 8812200156 Supplemental Deficiency Rept CP-86-018 re difficulties in starting & operating safety chilled water chiller units. Initially reported on 880521.Completion date for corrective actions reschoolated for 890630.

 COUNSILIWIG., MARSHALLIJS TU Electric (formerly Toxas Ultitios Generaling Co.) 88/12/15. Document Control Branch (Document Control Desk). 1pp. 47901.125-47901.125.
- 8812210129 Supplemental Delicitancy Ropt CP-86-45 re Seismic Category II sys 8 components initiatly reported on 8/1016 Completion of Unit 1 corrective actions rescheduled for 8963-05 Schodule for Unit 2 corrective actions unchanged COUNSIL W.G., MARSHALL, J.S. TU Electric (formerly Texas Utilitios Generating Co.). 88/12/15. Document Control Branch (Document Control Desk). 1p. 47875-325-47875-325.
- 8812210135 Supplemental Deficiency Rept CP-86-19 re Class 1E Instrument Isstal attons. Initially reported on 860129 Unit 1 corrective actions rescheduled for completion by 890812. Schedule for Unit 2 unchanged COURSIL W.G., MARSHALL, I.S. TU Electric (formerly Texas Vitities Generating Co.). 88/19/15. Document Control Branch (Document Control Desk). 1p. 47892 027-47082 027.
- 8812210157 Supplemental Deliciency Rept CP-87-101 re Class 1E cable arrangement Initiatiy reported on 880111. Corrective action for Unit 1 rescheduled for completion by 8903018 a schedule for Unit 2 remains unchanged.

 COUNSIL W G , MARSHALL, 3 S. TU Electric (formerly Toxas Unities Generating Co) 88/12/15. Document Control Branch (Document Control Desk). 1p 47888:100-47889:100 47888:100
- 8812210163 Suppremental Deficiency Rept CP-87-23 re conduit unions. Initially reported on 870727 Unit 1 corrective actions rescheduled for completion by 890402 Unit 2 corrective actions completion schedule unchanged COUNSIL W.G., MARSHALL, i.S. TU Electric (formerly Toxes Utritles Generaling Co.). 88/12/15 Document Control Branch (Document Control Desk). 1p. 47878-230-47878-230.
- 8812200143 Supplemental Deficiency Rept CP-87-55 (e containment spray pump recirculation piping Initially reported on 871200. Replacement of affected containment spray pump rectrculation piping w/ASME Class 2 pipe & Category I supporte continuing ing COUNSIL, W.G. TU Electric (formerly Toxas Utilities Generating Co.). 88/12/16. Document Control Branch (Document Control Dosk). 1p. 476/70.334-478/70.334.
- 8812200184 Supplemental Deficioncy Rept CP-84-08 re-curtain fire dampers Intesting reported on 840820.Corrective action sated in 870817 ftr continuing New corrective action estimated completion date set for 890830.

 COUNSIL, W.G. TU Efectite (formerly Texes Utilities Generating Co.). 88/12/16. Document Control Branch (Document Control Dock). 1p. 47863.076-47863.076
- 8812270174 Supplemental Deficiency Ropt CP-88-23 ro design basis groundwater elevation Initially reported on 880204 Unit 1 completion date for mod of waterproofing 8 feak collection sys & Installation of placements revised to 880417. COUNSIL,WG, MARSHALLJS TU Electric (formerly Toxas Unities Generating Co). CB/12/21. Document Control Branch (Document Control Desk). 1p. 47926:174-47926:174.
- 8812270176 Interim Deficiency Rept CP-88-39 re RHR valve position indicator.initially reported on 881122.Issue under evaluation for safety impact Next rept submitted by

890210 COUNSIL, W.G., MARSHALL, J.S. TU Electric (formerly Texas Utifiles Generating Co.). 88/12/21. Document Control Branch (Document Control Desk). 2pp. 47827:035-47827.036

8812270177 Supplemental Deficiency Rept CP-87-19 (e ambient temp effects on MSIV actuators.Initially reported on 880118 Corrective actions for Unit 2 estimated to be completed 6 months prior to fuel load.
COUNSIL,W.G., MARSHALL, JS. TU Electric (formerly Texas Utilities Generating Co.).
68/3/2/21. Document Control Branch (Document Control Desk). 1p. 47928:168-

47926 18R

8812270184 Supplemental & Interim Deficiency Repts CP-88-34 re RHR HXs support design initially reported on 881006.Closure of mod documentation in progress & will be completed by 890224.

COUNSIL,W.G., MARSHALL,J.S. TU Electric (formerly Texas Utilities Generating Co.). 88/12/21. Document Control Branch (Document Control Desk). 1p. 47926:336-4798-328.

8812270224 Supplemental Deficiency Rept CP-85-54 to seismic qualification of HVAC supports Initially reported on 860926. Estimated completion date for const rework for Unit 1 rescheduled to 890630. COUNSIL,W.G., MARSHALL,J.S. TU Electric (formerly Texas Utilities Generating Co.). 88/12/21. Document Control Branch (Document Control Desk). 1p. 47927:061-47927:061.

U. Congressional/Executive Correspondence

8811300078 Forwards NRC quarterly status rept covering Third Quarter CY88 in response to direction given in House Rept 87-850. ZECHI,L W. Commissioners. 88/11/10. BEVILL,T. House of Rep., Appropriations. 12pp. 47733-001-47733-012.

DOCKET STN-50-454 BYRON STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812200091 Forwards Amond 11 to "Byron/Braidwood Stations Fire Protection Rept."
 HUNSADER,S C. Commonwealth Edison Co. 88/12/14 MURLEY,T.E. Office of Nuclear Reactor Regulation, Oirector (Post 870411). 2pp. 47871.356-47872
- -8812200097 Amend 11 to "Byron & Braidwood Stations Fire Protection Rept" *Commonwealth Edison Co. 88/12/31, 77pp. 47871,358-47872,074.
- 8812270151 Advises that 881018 Rev 28 & 3b to Braidwood Annex & Byron Annex generating station emergency plans respectively, consistent w/10CFR50.54(q) & acceptable Each rev includes table of station-specific emergency action levels. GREGER, L. R. Reg on 3, Ofc. of the Director. 88/12/15. REED,C. Commonwealth Edison Co. 2pp. 47924.248-47925.039
- -8812270153 Forwards revised generic emergency action levels (EALs) for plants in re-sponse to NRC concerns.Commitment to implement EAL changes for Braidwood by 880830 revised to indicate that EALs will be implemented within 30 days of NRC approval JOHNSON,I M. Commonwealth Edison Co. 88/09/28. DAVIS,A B. Rogion 3, Olc of the Director, 160pp, 47924;250-47925 039.

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8812190196 Forwards updated FSAR for Byron Station Units 1 & 2 & Braidwood Station Units 1 & 2 HUNSADERS.C. Commonweelth Edson Co. 88/12/14 MURLEY,TE. Office of Nu-clear Reactor Regulation, Director (Post 870411) 2pp. 47880.001-48012:114
- ~8812190216 Updated FSAR for Byron Units 1 & 2 & Braidwood Units 1 & 2. Rev 0 to change log onci. Commonwealth Edison Co. 88/12/14, 12,869pp 47980.003-47989:134
- -8812190236 Chapter 1, "Introduction & General Description of Plant," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.
 **Commonwealth Ed son Co. 881/21/14, 221pp. 47882 050-47982:270.
- -8812190250 Chapter 3, "Design of Structures Companionts, Equipment 8, Sys." to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.
 **Commonwealth Edison Co. 88/12/14, 1,000pp. 47882.271-47983:314.
- ~8812190254 Chapter 2, "Site Characteristics," to Byron Units 1 & 2 updated FSAR. *Commonwealth Edison Co. 88/12/14, 1,400pp, 47983:315-47987:086
- ~8812190259 "Rosults of Grouting Plant Foundation,Category I Structures." Dames & Moore 88/12/14 88pp. 47987.087-47987:182.
- ~8812190326 "Results of Grouting Essential Svc Water Cooling Towers Foundation." Dames & Moore 88/12/14, 40pp 47987;183-47987;234.
- --8812190327 "Fault Specific Geotechnical Investigation."

 * Commonwealth Edison Co. 88/12/14, 124pp 47987;235-47987 357.
- -8812190329 "Detailed Mapping of Excavations" * Dames & Moore, 88/12/14, 131pp, 47987:358-47988:125.
- -8812190330 "Blast Monitoring Program." Dames & Moore: 88/12/14, 134pp, 47988:126-47988:281.
- --8812190331 "Written Communications Ref in Section 2.5."

 * Commonwealth Edison Co. 88/12/14, 10pp. 47988 262-47988.271.
- -8812190332 "Const.Surveillance & Pipeline Corridor."
 * Dames & Moore, 88/12/14, 126pp, 47988:272-47989:035.
- ~8812190335 "Addendum Rept Fill Placement Surveillance Byron Nuclear Generating Station Units 1 & 2 Commonwealth Edison Co."
 * Dames & Moore, 5643-061-07, 78/05/03, 16pp, 47989.036-47989.051.
- --8812190337 "Rept Geological Investigation of Solution Features Byron Station Units 1 8.2 Commonwealth Edison Co."

 **Dames & Moore, 5643-120-07, 88/12/14, 82pp, 47869,052-47869;134.
- --8812190338 "Rept Geotechnical Sycs Selamic Crosshold Survay & Dynamic Soil Properties at River Screenhouse Byron Station Units 1 & 2 Commonwealth Edison Co." Dames & Moore, 88/12/14, 22pp. 47989:135-47889.156.
- -8812190344 Chapter 2, "Site Characteristics," to Braidwood Units 1 & 2 updated Commonwealth Edison Co. 88/12/14, 1,500pp. 47989;167-47993.090.
- -9812190346 "Observations Made By State of IL Geological Survey Stall During Visit to Braldwood Site on 760311."

 * Illinois, State of, 77703/08, 3pp. 47993:091-47993:093.
- -8612190347 "Geologic Reconnaissance of Clinton & Braidwood Reactor Excavations." SKROVE J.W. Division of Site Safety & Environmental Analysis. 76/04/27, 3pp. 47993:094-47993:096.
- -8812190349 "Onsite Water Well Borehole Log." TREWORGY,J.D. Ill nois, State of. 77/04/11. 3pp. 47893:097-47993:099.
- -8812190351 "Written Communications Ref in Section 2.5."
 * Commonwealth Edison Co. 88/12/14, 10pp, 47993;100-47993;109.
- --8812190352 "Subcompartment Pressurization Studies Outside Containment." Commonwealth Edison Co. 88/12/14, 30pp. 47993:110-47993:141.
- --8812190363 "Selection of Pipe Mall Properties for Use in Pipe Whilp Analysis."
 * Commonwealth Edison Co. 88/12/14, 3pp. 47993;142-47993;144.

- -9812 190355 "Main Steamline Break in Main Steam Tunnel"
 Commonwealth Edison Co. MAD-7577, 76/07/31, 31pp. 47993:145-47993.175.
- -8812190357 "Flooding"
 " Commonwealth Edison Co. 89/12/14, 3pp. 47993 176-47993 314
- -8812190360 "Issues re Reevaluation of Byron/Braidwood Seismic Design" Commonweath Edison Co. 86/12/14, 450pp, 47993 315-47996 091
- -8812190366 Chapter 4, "Reactor," to Byron Units 1 & 2 & Braidwood Units 1 & 2 up-
- Commonwealth Edison Co. 89/12/14, 300pp, 47936,092-47996-356
- ~8812190367 Chapter 5, "RCS & Connected Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAA.
 **Commonwealth Edison Co. 88/12/14, 400pp. 47998 357-47997-265
- -8812190369 Chapter 6, "ESF," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR * Commonwealth Edison Co. 88/12/14, 900pp, 47997, 266, 47999, 068.
- -8812190372 Chapter 7, "Instrumentation & Controls," to Byron Units 1 & 2 & Bradwood Units 1 & 2 updated FSAR
 * Commonwealth Edison Co. 88/12/14, 450pp. 47999 191-48000.339
- -8812190373 Chapter 8, "Electric Power," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR. * Commonwealth Edison Co. 88/12/14, 275pp. 48000:310-48001 098
- -8812190380 Chapter 9, "Auxiliary Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2 Commanwealth Edison Co. 88/12/14, 1,800pp, 48001,059-48004,338
- --8812190382 Chapter 10, "Steam & Power Conversion Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR

 * Commonwealth Edison Co. 88/12/14 4C0pp 48004.339.48005.192.
- -8812190363 Chapter 11, "Hadwasta Mgt," to Byron Unit 1 & 2 & Braidwood Unit 1 & 2 updated FSAR.
 * Commonwealth Edison Co. 88/12/14 800pp 48005:193-48006.329
- -9812190389 Chapter 12, "Radiation Protection," to Byron Units 1 & 2 & Breidwood Units 1 & 2 updated FSAR Commonwoalth Edison Co. 88/12/14, 500pp, 48006,330,48007;343.
- -8812190390 Chapter 13, "Conduct of Operations," to Byron Units 1 & 2 & Braldwood Units 1 & 2 updated FSAFI.
- Commonwealth Edison Co. 88/12/14, 77pp. 48007.344-48008.058.
- ~8812190391 Chapter 14, "Initial Test Program," to Byron Units 1 & 2 & Bretdwood Units 1 & 2 updated FSAFI. Commonwea'th Edison Co. 88/12/14, 123pp. 48008;059-48008;181.
- --8812190392 Chapter 15, "Accident Analyses," to Byron Units 1 & 2 & Breidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14, 400pp. 48008;182-49009:290.
- -8812190393 Chapter 16, "Tech Specs," to Byron Units 1 & 2 & Braidwood Units 1 & 2
- updated FSAR. Commonwealth Edison Co. 88/12/14, 12pp, 48009:305-48009-316.
- ~8812190395 Chapter 17, "QA," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR. * Commonwealth Edison Co. 88/12/14, 2pp. 48009 317-48009 318
- -8812190400 App A, "Application of NRC Rog Guides," to Byron Units 1 & 2 & Breidwood Units 1 & 2 updated FSAR.
 Commonwea'th Edison Co. 88/12/14, 210pp 48009.319 48010.172.
- --8812190401 App 6, "Const Mail Std & QC Procedures," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.
 * Commonwealth Edison Col 88/12/14, 61pp. 48010:173-48010.233.
- --8812190402 App C, "Turbine Missi'o Study," to Byron Units 1 & 2 & Bra'dwood Units 1 & 2 updated FSAR,

 ' Commonwealth Edison Co. 89/12/14, 50pp, 48010 234-48010;283.
- -3812190403 App D, "Computer Programs," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co 88/12/14, 72pp, 48010:284-48011:096.
- -8812190404 App E. "Requirements Resulting From TMI-2 Accident," to Byron Units 1 & 2 8 Braidwood Units 1 & 2 updated FSAR.
 * Commonwealth Edison Co. 88/12/14, 400pp, 48011:097-48012:114.
- -6812200223 App 6.3A, "Proper Positioning of Valves," to Byron Units 1 & 2 & Breidwood Units 1 & 2 updated FSAR.
 *Commonwea'th Edison Co. 88/12/14, 5pp. 47999 069-47999:177
- -8812200226 "Iodine Removal Effectiveness Evaluation of Containment Spray Sys." *Commonwealth Edison Co. 88/12/14, 11pp, 47899:176-47999, 190.
- -8812200234 "Dose Models Used to Evaluate Environ Consequences of Accidents." Commonwealth Edison Co. 88/12/14, 7pp. 48009 291-48009 297.
- --8812200237 "Models for LOCA Analysis."

 * Commonwealth Edison Co. 88/12/14, 7pp. 48009:288-48009:304.
- P. Operating license stage documents & correspondence
- 8812010121 Requests NRC position re classiscation of amergency diesel generator val'd demands. Criteria ra emergency diesel generator run Istad. CHRZANOWSKI,R. Commonwealth Edison Co. 88/11/22 MULLER,D.R. Office of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 47703.014-47703.015

- 8812010228 Forwards load summary to loss of offside power.per 1.4(C) 6.65-627 request showing that each 4,160 will bus 8 threafter feeting ESF bus from starting transformer rated to carry LOCA loads of one unit 8 safe stuitflown leads of CC-4. CHRZANOWSKI,R Commonwealth Edison Co. 88/11/22 MURLEY,T,F. (21ca of the close Regulation, Director (Post 870411), 3pp. 47702 3t9 47702 3c0
- 8811280048 Generic Ltr 88-20 to all hoursees holding OLS & CPs for notice at power reactor facilities re-individual plant examilior severe accident with reliefus \$50 kst. enct CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88711723 (2015c) dated Edison Co. of New York, Inc. 81pp. 47728 303 47729 024
- 8811290408 Forwards Amenda 24 to Liconses NPF-37 8 NPF-66/respectively. Amenda change Toch Spocs to require availability of one unit essential sec water primp white other unit operator. Safety evaluation encl.

 OLSHANTA IN Project Directorate III-2, 88/11/23 BLISS,H.E. Commonwealth £d sec. Co. 4pp. 47668:127-47668.139
- -8811290416 Amonds 24 to Licenses NPF-37 & NPF-60,respectively, through 5 feets Specs to require availability of one unit essential size water pump while of an unit co-OFBIRS MULLER,D.R. Project Directorata III-2-88/11/23, 7pp-47668-131-47668-137
- -8811290419 Safety Evaluation to Tech Spec changes requiring averable, of thet t essential svc water pump white Unit 2 is operating
 Office of Nuclear Reactor Regulation, Director (Post 870.11) INSTITUTE 3 356 47668:138-47668:139
- 8811300443 Requests FR publication of notice of issuance of Aniends 24 to 1 < 0.000. NPF-37 & NPF-06 Amends rovise Tech Specs to require evalently of charmacters in tilal svc water pump white other unit operating.

 OLSHAN,L N. Project Directorate III-2: 88/11/23. NRC - No Delated Attacks Grace App. 47677.093-47677.096
- 8812010305 Provides analysis of Rog Guidn 1.99,flov 2, "Ratintian Etrian herocal of Reactor Vessal Mails" for impact on pressure-temp heating & coordinal conves contained in Tech Specs,per Genoric Ltr 88-11.

 RICHTER.M.H. Commonwealth Edison Co. 88/11/28. Denument Control Provision (Procument Control Desk), 2pp. 47703.049 47703.050
- 8812090286 Informs of util intention to seismically qualify two plant duop weils £ technique. "Soismic Qualification of Byron Duop Wells," Flow 1,dtd Nov 1986 will be utilised to revise Byron/ Braidwood updated FSAR.

 CHRZANOWSKI,R Commonwealth Edison Co. 88/11/30 MURGEY, L.E. Office of Rector Regulation, Director (Post 870411). 1p. 47775-106 47775,192
- ~8812090294 Rev 1 to "Seismic Qualification of Byron Dimp Wolfs"
 * Sargent & Lundy, Inc. SL-4492 R01, 86/11/30, 85pp. 47775 107-47775 162
- 8812070239 Notification of 881207 meeting w/util in Hockyde,MD to it sches 13€ fit(¥1 submittal of 000025.
 SANDS,S.P. Project Directorate III-2, 88/12/02 MURILEY,1, SMF7F.K.J., MIRAGLIA,F. NRC - No Detailed Affiliation Given 3pp. 47749 275-47740 277.
- 8812070281 Romlie fee for application for amonds to Excenses NPF-37, 107 +6,1405 12 & NPF-77.
 LARA,S.C. Commonwealth Edison Co. 88/12/86 MURI FY,T.E. Office of Nichold Re actor Regulation, Director (Post 870411). 1p. 47748.076-47748.076.
- 8812200274 Application for amends to Licensos NPF-37,NPF-66,NPF-72 5 4.6.F.-75,changing Tech Spec 4.2.2.2.o to remove fixed Fxy Timits to NRC via representing the Feo paid.

 CHRZANOWSKI,R. Commonwealth Edison Co. 88/12/12 MULLER,D to Others cit the clear Reactor Regulation, Director (Post 870411), 2pp. 47864-277-47884.202
- ~8812200276 Proposed Tech Spec 4.2.2.2 gremowing fixed Fxy himls 8 substituting 4.6 quirement to submit Fxy limits to NRC via operating limits rept.

 * Commonwealth Edison Co. 88/12/12, 14pp. 47864;279,47864;292.
- 8812230162 AppScation for amends to Liconses NPR-37,NPF-66,NPF-72 & Pairs-76,modifying Tech Specs to change Bases Page 374 4-2 which addis cladification for power-operated digital values operability. CHRZANOWSKI,R. Commonwealth Edison Co. 88712712, MULLER,DR, English Carecterate III-2, 2pp. 47911 326-47911:330.
- -8812230172 Proposed Tech Specs 3/4.4.2.4 adding clarification for prossulted powers operated rolled valves operatifity.
 Commonwealth Edison Co. 88/12/12, 3pp. 47911.328-47911.330.
- 8812220206 Forwards proprietary & nonpropriotary NESR 0033, "VIPREZ WHB-1 DEGRA Thormal Limit for Westinghouse OFA Fuol." Alfidevit & application for withing the pro-priotary reptilates and. Proprietary version withind (rot 100FR2700) TRZYNA,G.E. Commonwealth Edison Co. 88712715, Office of Nuclear Reactor Responsation, Oriector (Post 870411), App. 47892.257-47892.330.

Q. Inspection reports, IE Bulletins & correspondence

- 8811300444 Forwards addl into clarifying Westinghouse Rept MT-SME-427(56) to \$245 fication & thermal cycling issues in response to 801101 tercon request concernation NRC Bullatin 88-008. CHRZANOWSKI,R. Commonwealth Edison Co. 88/11/09. MURLEY,T E. Olike of N.) clear Reactor Regulation, Director (Post 870411). 2pp. 47697 256 47697 257
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial # #11/36 Gauges." Svc list enct. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870725) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708.255 47700 257
- 8811160467 NRC Into Nedice 88-091, "Improper Administration & Control of Physics ა cal Tests." Svc list enci. ROSSICE. Division of Operational Events Assessment (Post 870411). 89/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142

- 8811280073 Forwards Salety Insp. Repts 50-454/88-20 & 50-455/88-17 on 881010-
 - 1114 No violations noted
 Ct.AYTON,B Region 3, Ofc of the Director, 88/11/23 REED,C Commonwealth
 Edison Co 2pp 47654 057-47654 068
- -8811280076 Insp Repts 50:454/89:20 & 50:455/86:17 on 881001-1114:No violations noted Major areas Inspected licensee actions on previous inspected licensee actions on previous inspected licensee actions. LERs operations summary, training, maint/surveillance, operational safety & Region III requests. H NDS,J.M. Region 3, Ofc of the Director, 68/11/23, 10pp, 47654,059,47654,068.
- 8811290030 NRC Info Natice 88-093, "Telatherapy Events" Svc tist end CUNN'NGHAM,R.E. D.vision of Industrial & Modical Nuclear Safety (Post 870729), 88/12/02, Cansolidated Edison Co. of New York, Inc. 112pp. 47811 103-47811:215.
- 8811290538 NRC Into Notice 88-094, "Potentially Understand Valve Actuators" Syc 1st encl ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708-254.
- 8812020297 NRC Into Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensess on Vendors." Svc. list encl.
 ROSSI.CE Division of Operational Events Assessment (Post 870411), 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812210390 Forwards Safety Insp. Ropts 50-454/88-21 & 50-455/88-18 on 881018-1103 & notice of violation. GREGERLR. Region 3. Otc. of the Director. 88/12/08. REED.C. Commonwealth Edison Co. 2pp. 47875.050-47875:068.
- --8812210393 Notice of violation from Insp on 681010-1103 Violation noted failure to follow radiation protection procedure & shipment of radioactive mail w/o required shipping notice & marking GREGER.L.R. Region 3, Ofc of the Director. 88/12/08 2pp 47875.052-47875.053.
- -6812210396 Insp Repts 50.454/88.21 & 50.455/88-18 on 861019-1103. Violations noted Major areas inspected occupational exposure during extended outages shipping and transportation & response to NRC Into Notice 87-032. GRANT, W.B., GREGER, L.R., Region 3, Otc. of the Director. 88/12/08, 13pp. 47675.054-47675.066.
- 8812220382 Forwards Rov 2 to "Braldwood Nuctour Power Station Units 1 & 2 Inservice Insp & Testing Program Plan First Insp Interval." Related Info presenting comparison of Bradwood & Byron plants Inservice Insp programs encl. HUNSADER,S.C. Commonwealth Edison Co. 88/12/15. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 14pp. 47904:037-47806:279.

R. Periodic operating reports & related correspondence

- 8812090206 Forwards corrected effluent & waste disposal semiannual repts for Jan 1985 through Dec 1986. PLENTEWICZ,R. Commonwealth Edigon Co. 86/11/21. Document Control Brench (Document Control Dask). 1p. 47762:079-47762.083.
- --8812090211 Corrocted "Effluent & Wasto Disposal Somiannual Rept for Jan-Juno 1985"
 • Commonwealth Edison Co. 85/08/30. 1p. 47762 080-47762 080.
- --8812090221 Corrected "Effluent & Waste Disposel Semiannual Rept for Jul Dec * Commonwealth Edison Co. 88/12/31, 1p. 47762.081-47762.081.
- -8812090227 Corrected "Effluent & Wasto Disposal Semiannus! Rept for Jan-June 1986." * Commonwaelth Edison Co. 86/06/30, 1p. 47762.082-47762:082
- -8812090231 Corrector "Effluent & Waste Disposal Semiannual Rept for Jul-Dec 1986."
 • Commonwealth Edison Co. 86/12/31, 1p. 47762 083-47782.083.
- 8812200027 Monthly operating ropts for Nov 1988 for Byron Units 1 & 2. W/881210 ltr. SPITZER,D.J., PLENIEWICZ,R. Commonwealth Edison Co. B8/11/30. 18pp. 47871:289-47871:301

S. Reportable occurrences, LERs & related correspondence

- 8811300190 Responds to NRC 881004 ltr re two concerns related to loss of one train of RHR that occurred on 880919. Util has conducted extensive investigation & self-assessment review to determine how event occurred.

 REED.C. Commonwealth Edison Co. 88/11/17, MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), DAVIS,A.B. Region 3, Ofc of the Director. 3pp. 47897:208-47697:208.
- 8812080248 LER 88-010 00.on 881105,satety injection accumulator fill line break due to fatigue requiring plant shutdown per Tech Specs.Caused by fatigue induced cracking.Accumulator fill lines dye penetrant Insp.Flawed pipes replaced W/881202 ltr. TULON,T., PLENIEWICZ,R. Commonwealth Edison Co. 88/12/02, 5pp. 47742:247-47742:251.

V. Operator Examinations

88.120.100.46 Requests approval to substitute INPO accredited, performance-based reactor operator & senior reactor operator license requalification program for that previously approved by NRC,per 10CFR55.59 & Generic Ltr 87-07. TRZYNA,G.E. Commonwealth Edison Co. 88/11/18. DAVIS,A.B. Region 3, Ofc of the Director. 1p. 47703:174-47703:174.

DOCKET STN-50-455 BYRON STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- -8812200097 Amend 11 to "Byron & Braidwood Stations Fire Protection Rept." *Commonwealth Ed.son Co. 88/12/31, 77pp. 47871:358-47872.074,
- 8812270151 Advises that 881018 Rev 2a 8 3b to Braidwood Annex & Byron Annex generating station emergency plans respectively, consistent w/10CFR50.54(q) & acceptable Each rov includes table of station-specific emergency action levels. GREGER, L. R. Region 3, Ofc. of the Director. 86/12/15. REED,C. Commonwealth Edison Co. 2pp. 47924 248-47925.039.
- -9812270153 Forwards revised generic emergency action levels (EALs) for plants in response to NRC concerns Commitment to linetenent EAL changes for Braidwood by 880930 revised to indicate that EALs will be implemented within 30 days of NRC ap-JOHNSON,I M. Commonwealth Edison Co. 68/09/28. DAVIS,A.B. Region 3. Ofc of the Director. 150pp. 47924:250-47925.039

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8812190196 Forwards updated FSAR for Byton Station Units 1 & 2 & Braidwood Station HUNSADER,S.C. Commonwealth Edison Co. 88/12/14. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 47980:001-48012.114.
- --8812190216 Updaled FSAR for Byron Units 1 & 2 & Braidwood Units 1 & 2. Rev 0 to change log enct.

 * Commonwealth Edison Co. 8B/12/14. 12,869pp. 47980 003-47989 134.
- --8812190236 Chapter 1, "Introduction & General Description of Plant," to Byron Units 1 & 2 Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 8B/12/14 | 221pp. 47982.050.47982.270.
- --8812190250 Chapter 3, "Design of Structures, Components, Equipment & Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14, 1,000pp, 47982:271-47983:314.
- -8812190254 Chapter 2, "Site Characteristics," to Byron Units 1 & 2 updated FSAR.
 *Commonwealth Edison Co. 88/12/14, 1,400pp, 47983:315-47987-088.
- -8812190269 "Results of Grouting Plant Foundation, Category I Structures."
 Dames & Moore, 88/12/14, 88pp. 47987.087-47987;182.
- -8812190326 "Results of Grouting Essential Svc Water Cooling Towers Foundation."
 Dames & Moore, 88/12/14, 48pp, 47987;183-47987;234.
- -8812190327 "Fault Specific Geotechnical Investigation,"
 * Commonwealth Edison Co. 80/12/14, 124pp, 47087:235-47987:357,
- -8812190329 "Deta-lod Mapping of Excavations."
 Dames & Moore 88/12/14, 131pp 47987:358-47988.125.
- -8812190330 "Blast Monitoring Program"
 Dames & Moore, 88/12/14, 134pp, 47988;128-47988;281,
- -8812190331 "Watten Communications Ref In Section 2.5." *Commonwealth Edison Co. 88/12/14, 10pp. 47988:262-47988:271,
- --9812190332 "Const Surveillance & Pipeline Corridor."

 * Dames & Moore, 88/12/14, 125pp, 47988 272-47989,035
- -8812190335 "Addendum Rept Fill Placement Surveillance Byron Nuclear Generating Station Units 1 & 2 Commonwealth Edison Co."
 * Dames & Moore, 5643-061-07, 78/05/03, 16pp. 47989.036-47989:051.
- -9812190337 "Rept Geological Investigation of Solution Features Byron Station Units 1 & 2 Commonwealth Edison Co." Dames & Moore, 5643-120-07, 88/12/14, 82pp. 47899.052-47889:134.
- --8812190338 "Rapt Geotechnical Svcs Solamic Crosshote Survey & Dynamic Soil Properties at River Screanhouse Byron Station Units 1 & 2 Commonwealth Edison Co." Dames & Moore. 88/12/14. 22pp. 47989:135-47889.156.
- --8812190352 "Subcompartment Pressurization Studies Outside Containment," * Commonwealth Edison Co. 88/12/14, 30pp. 47993;110-47993;141.
- --8812190353 "Selection of Pipe Mail Properties for Use in Pipe Whip Analysis." Commonwealth Edison Co. 88/12/14, 3pp. 47893:142-47993 144.
- -8812190356 "Main Steamline Break in Main Steam Tunnel."
 * Commonwealth Edison Co. MAD-7577, 76/07/31, 31pp. 47993:145-47993:176.
- --8812190357 "Flooding."

 * Commonwealth Edison Co. 88/12/14, 3pp. 47993:176-47993:314.
- -8812190360 "Issues re Reevaluation of Byron/Braidwood Selsmio Design." *Commonwealth Edison Co. 88/12/14, 450pp, 47993;315-47996;081.
- -8812190366 Chapter 4, "Reactor," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR. Commonwealth Edison Co. 88/12/14, 300pp. 47996:092-47996:356.
- ••8812190367 Chapter 5, "RCS & Connected Sys," to Syron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.
 Commonwealth Edison Co. 88/12/14, 400pp, 47996:357-47997:265.
- -8812190389 Chapter 6, "ESF," to Byron Units 1 & 2 & Braldwood Units 1 & 2 updated
- FSAR.
 * Commonwealth Edison Co. 88/12/14, 900pp, 47997,266,47999,068.
- --8812190372 Chapter 7, "Instrumentation & Controls," to Byron Units 1 & 2 & Braldwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14, 450pp, 47999;191-48000.309.

166 DOCKETED HEMS

- -8812190380 Chapter 9, "Auxi ary Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2
 - Commonwealth Edison Co. 88/12/14 1,800pp 48001.009-48004:008
- -8812190382 Chapter 10, "Steem & Power Conversion Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR
 * Commonwealth Edison Co. 8B/12/14, 460pp. 48004;339-48005.192.
- --8812190389 Chapter 12, "Radiation Protection," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR
 * Commonwea'th Edison Co 68/12/14, 500pp 46008 330-48007 343
- -9812196390 Chapter 13, "Conduct of Operators," to Byron Units 1 & 2 & Breidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14 77pp. 48007 344-48008 058.
- -8812190391 Chapter 14, "Initial Test Program," 10 Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR

 * Commonwealth Edison Co. 88/12/14, 123pp. 48008 059-48008 181.
- -8812190392 Chapter 15, "Accident Analyses," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14, 400pp, 48008;182-48009;290
- --8812190393 Chapter 16, "Tech Specs," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR "Commonwealth Edison Co. 88/12/14, 12pp. 48009 305-48009.316.
- →8812190395 Chapter 17, "QA." to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR. * Commonwealth Edison Co. 88/12/14, 2pp. 48009 317-48009 318
- -8812190400 App A, "Application of NRC Reg Guides," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.
 *Commonwealth Edison Co. 88/12/14, 210pp 48009.319-48010 172.
- -8812190401 App B, "Const Mati,Std & QC Procedures," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14, 61pp. 48010.173-48010.233.
- -8812190402 App C, "Turbine Missile Study," to Byton Units 1 & 2 & Brefdwood Units 1 & 2 updated FSAR
 *Commonwealth Edison Co. 88/12/14, 50pp 48010;234-48010 283.
- -8812190403 App D, "Computer Programs," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14, 72pp. 48010;284-48011:096
- -8812190404 App E, "Requirementa Resulting From TMI-2 Accident," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14 | 400pp. 48011.097-48012.114.
- -8812200223 App 6.3A, "Proper Positioning of Velves," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14. 5pp. 47999 069-47999.177.
- -8812200226 "logine Removal Effectiveness Evaluation of Containment Spray Sys." Commonwealth Edison Co. 88/12/14, 11pp. 47999:178-47999.190.
- --8812200234 "Dose Mode's Used to Evaluate Environ Consequences of Accidents." Commonwealth Edison Co. 88/12/14, 7pp. 46009.291-48009:297.
- -8812200237 "Models for LOCA Analys's "
 * Commonwealth Edison Co. 88/12/14, 7pp. 48009:298-48009:304.

P. Operating license stage documents & correspondence

- 8812010121 Requests NRC position re classification of emergency diesel generator valid demands. Criteria re emergency diesel generator run listed. CHRZANOWSKI, R. Commonwealth Edison Co. 88/11/22, MULLER, D.R. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47703.014-47703.015.
- 8812010228 Forwards load summary re loss of offsite power.per NRC 880627 request, showing that each 4,160 not bus & breaker feeding ESF bus from startup transformer rated to carry LOCA loads of one unit & safe shutdown loads of other
- unit. CHRZANOWSKI,R. Commonwea'th Edison Co. 88/11/22, MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 3pp. 47702:318-47702:320.
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exem for severe accident vulnerabilities. Svc list enct CRUTCHFIELD,O. Associate Director for Projects (Post 670411), 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 6811290406 Forwards Amends 24 to Licenses NPF-37 & NPF-66 respectively. Amends change Toch Specs to require availability of one unit essential avc water pump white other unit operates. Safety evaluation encl. OLSHAN, L.N. Project Directorate III-2. 88/11/23. BLISS,H.E. Commonwealth Edison Co. 4pp. 47688:127-47688-139.
- 8811300443 Requests FR publication of notice of issuance of Amends 24 to Licenses NPF-37 & NPF-66 Amends revise Tech Spees to require availability of one unit essential syc water pump while other unit operating.
 OLSHAN,
 - 4pp. 47677:093-47677:096
- 8812010305 Provides analysis of Reg Guide 1.89, Rev 2, "Radiation Embrittlement of Reactor Vessel Matter for impact on pressure-temp heatup & cooldown curves contained in Tech Specs.per Generic Ltr 88-11.

 RICHTER, M.H. Commonwealth Edison Co. 98/11/28. Document Control Branch (Document Control Desk). 2pp. 47703:048-47703:050.

- 8812090286 Informs of util intention to seismically qualify two plant deep we ანოამ Person "Seismic Qualification of Byron Deep Wells," Rev. 1,dtd Nov. 1988 will be აის 200 revise Byron/ Braidwood updated FSAR CHRZANOWSKI,R Commonwealth Edison Co. 68/11/30 MURLEY,T.C. Chick of the clear Reactor Regulation, Director (Post 870411) 1p. 47775:108-47775 192
- -8812090294 Rev 1 to "Seismic Qualification of Byron Deep Wells" * Sargent & Lundy, Inc. St. 4492 R01, 88/11/30, 85pp. 47775,107,47775 192
- 8812070239 Notification of 881207 meeting w/util in Rocky/le,MD to discuss DCROR submittal of 880825 SANDS,S.P. Project Directorate III-2 88/12/02 MURLEY,T., SMEZEK,J. MIRAGLIA,F. NRC - No Detailed Affiliation Given: 3pp. 47749 275-47749 277.
- 8612070261 Remits foe for application for amends to Licenses NPF-37, NPF-56,14PF-72 & NPF-77. LARA SC Commonwea'th Edison Co. 88/12/06. MURLEY T.E. Office of Nextoal Reactor Regulation, Director (Post 870411). 1p. 47748/076-47748/076.
- 8812200274 Application for amends to Licenses NPF-37,NPF-66,NP7-72 A NFF-75,Changing Tech Spec 4.2.2.2.u to remove fixed Fxy limits to NRC via species limits rept Fee paid CHRZANOWSKI,R. Commonwealth Edison Co. 88/12/12 MULLER,D.B. Clikto of NV clear Reactor Regulation, Director (Post 870411), 2pp. 47864-277-47864-282.
- -8812200278 Proposed Tech Spec 4.2.2.2 eremoving fixed Fxy limits & substituting 49 quirement to submit Fxy limits to NRC via operating limits rept.

 **Commonwealth Edison Co. 88/12/12, 14pp. 47884:279 47864:202.
- 8812230162 Application for amends to Licenses NPR-37,NPF-86,NPf-72 & NPF-75,modifying Tech Specs to change Bases Page 3/4 4/2 which adds call cation for power-operated relief valves operability.

 CHRZANOWSKI,R Commonwealth Edison Co. 88/12/12. MULLER,DIR Project Chrectorate III-2, 2pp. 47911:326-47911:330.
- -8812230172 Proposed Tech Specs 3/4.4.2-4.adding clarification for prossulter power operated relief valves operability.
 * Commonwealth Edison Co. 88/12/12 3pp. 47911:328-47911.330
- 8812220206 Forwards proprietary & nonproprietary NFSR-0033, "VIPRE/ WR8-1 DNBB Thermal Limit for Westinghouse OFA Fuel." Affidavit & application for withbut of prietary rept also enct. Proprietary version withheld (ref 10CFR2 780) TRZYNA,G.E. Commonwealth Edison Co. 88/12/15. Clicc of Nuclear Resulty Regulation, Director (Post 870411). App. 47892.257-47892.330.

O. inspection reports, IE Bulletins & correspondence

- 8811300444 Forwards additinfo clarifying Westinghouse Rept MT-SME-127(88) re-strata fication & thormal cycling issues in response to 881101 telcon request concerning NRC Bulletin 88-008.

 CHRZANOWSKI,R. Commonwealth Edison Co. 88/11/09, MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47697 258-47697:257.
- 8811160211 NRC Into Notice 88-090, "Unauthorized Romoval of Industral Nucleon Gauges" Svc list end. CUNNINGHAM,RE. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708.255-47708.257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychology cal Tests." Svc list encl.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/11/22
 Consol·dated Edison Co. of New York, Inc. 101pp. 47708.042-47708:142.
- 8811280073 Forwards Safety Insp Repts 50-454/88-20 & 50-455/88-17 on 861010-1114 No volations noted.

 CLAYTON,B. Region 3, Ofc of the Director. 88/11/23, REED,C. Commonwoalth Edison Co. 2pp. 47654.057-47654:068.
- -8811280076 Insp Repis 50-454/88-20 & 50-455/88-17 on 881001-1114 No voia bona noted.Major areas inspected.licensea actions on provious losp indings_LERs.operations summary,training, maint/surveillance.operational safety Region III requests. HINDS,J.M. Region 3, Old of the Director, 88/11/23, 10pp. 47654.059-47654.069
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events," Svc list enct. CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Safety (Post 970729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-97811-215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Svc Est ROSSI,C.E. Division of Operational Events Assessment (Post 970411). 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708;143-47708;254.
- 8812020287 NRC Info Notice 88:095, "Inadequate Procurement Requirements Imposed by Dicensees on Vendors". Svc list encl.

 ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 68/12/08
 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812210390 Forwards Salety Insp Repts 50-454/88-21 & 50-455/88-18 on 861019. 1103 & notice of violation.

 1103 & notice of violation.

 GREGER,L.B. Region 3, Otc of the Director. 88/12/08. REED,C. Commonwealth.

 Edison Co. 2pp. 47875:050-47875:066.
- -8812210393 Notice of violation from Insp on 881019-1103. Violation noted alive to follow radiation protection procedure & shipment of radioactive meti w/o required shipping notice & marking.

 GREGERIL R. Region 3, Otc of the Director. 88/12/08. 2pp. 47875:052-47876 053.
- ~8812210396 Insp Repts 50-454/88-21 & 50-455/88-18 on 881019-1103 Violations vorte: rouse imp replix อน-จวศ/ชะ/21 & อบ-455/88-18 on 881019-1103 Volutions noted Major areas inspected occupational exposure during extended outages รักษณะจ and transportation & response to NRC Info Notice 87-032. GRANT,W.B. GREGER,L.R. Region 3, Old of the Director. 88/12/08 13pp 47875:054-47875:086.

167

8812220382 Forwards Rev. 2 to "Braidwood Nuclear Power Station Units 1 & 2 Inservice Insp. & Testing Program Plan First Insp. Interval." Related into presenting companison of Braidwood & Byron plants inservice insp. programs ent.
HUNSADER, S.C. Commonwealth Edison Co. 88/12/15, MURILEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 14pp. 47904.037-47906.279

R. Periodic operating reports & related correspondence

- 8812090206 Forwards corrected effluent & waste disposal samianniral repts for Jan 1985 through Doc 1986 PLENIEWICZ,R. Commonwealth Edison Co 86/11/21. Document Control Branch (Document Control Desk) 1p. 47762 079-47762 083
- -8812090211 Corrected "Effluent & Waste Disposal Semigrinual Rept for Jan-June
 - 1985" * Commonwealth Ed.son Co. 85/06/30, 1p. 47762 080-47762,080
- -8612090221 Corrected "Effluent & Wasto Disposo! Semannual Rept for Jul-Doc
 - Commonwoalth Edison Co. 88/12/31 1p. 47762/081-47762/081
- -8812090227 Corrected "Effluent & Waste Disposal Semiannual Rept for Jan-June 1986 **
 * Commonwealth Edison Co. 86/06/30 1p 47/62.082 47762.082
- -8812090231 Corrected "Effluent & Waste Disposal Samlannual Rept for Jul-Dec
 - Commonwealth Edison Co. 86/12/31, 1p. 47762.083-47762.083
- 8812200027 Monthly operating repts for Nov 1988 for Byron Units 1 & 2 W/881210 ftr SPITZER,D.J. PLENIEWICZ.R. Commanwealth Edison Co. 88/11/30 16pp 47871-289-47871-304.

S. Reportable occurrences, LERs & related correspondence

- 8811300190 Responds to NRC 881004 fir re two concerns related to loss of one train of RHR that occurred on 880919 Util has conducted extensive investigation & setassessment review to determine how event occurred REED.C. Commonwealth Edison Co. 88/11/17. MURLEY, T.E. Office of Nuclear Reac-tor Regulation, Director (Post 870411). DAVIS, A.B. Region 3, Ofc. of the Director, 3pp. 47697-288-47697-208.
- 8811300392 LER 88-107-00 on 881005.2A diosol generator failed to reach rated speed 8 subsequently tripped on incomplete sequence Caused sineted to reach rated speed 4Ex3 relay Relay 4Ex3 ramoved & replaced w/now relay W/881118 ltr WALTERW. PLENIEWICZ,R Commonwealth Edison Co. 88/11/18. DAVIS,A B. Rogion 3, Ofc of the Droctor 3pp. 47676:185-47676.187.

V. Operator Examinations

8812010046 Requests approval to substitute INPO accredited, performance based reactor operator & senior reactor operator liconse requestication program for that proviously approved by NRC per 10CFR55.59 & Generic Ltr 67-2 Director. 1p. 47703:174-47703:174.

DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8810050121 Responds to NRC 880629 ftr re violations noted in Insp Repts 50-456/88-18 & 50-457/88-18 Corrective actions:util policy of deadly force as currently stated in security plan has been established w/10CFR73.55 Encl withhold BLISS.H.E. Commonwealth Edison Co. 88/09/16 DAVIS,A.B. Region 3, Ofc of the Director. 2pp. 47701:351-47701:352.
- 8812050324 Forwards response to regulatory effective review.Response withheld (ref
- 10CFR73.21).

 BLISS,H.E. Commonwealth Ed.son Co. 88/11/22, MURLEY,T.E. Office of Nuclear Re-actor Regulation, Director (Post 870411), 1p. 47731:220-47731:220
- 8812060142 Forwards Safeguards Insp Rept 50 456/88 30 & 50 457/88 30 on 881025-28 No violations noted.

 GREGER,L.R. Region 3, Ofc of the Director. 88/11/30 REED,C. Commonwealth Edison Co. 2pp. 47741:231-47741:233.
- --8812080145 Insp Repts 50:456/88:30 & 50:457/88:30 on 881025:28 & 31 & 1101 No violations noted. Major areas inspected mgt support, security program plans, & audits protected & vital erea physical berriers & detection & assessment alds MADEDA,T J., CREED,J.R. Region 3, Ote of the Director. 88/11/30. 1p. 47741.233-47741:233.
- 6812190265 Forwards Salety Insp Repts 50-456/88-31 & 50-457/88-31 on 881202 No
 - violations noted GREGER,L.R. Region 3, Ofc of the Director. 88/12/13. REED,C. Commonwealth Edison Co. 2pp. 47853:294-47853:299.
- -8812190267 Insp. Repts. 50-456/88:31 & 50-457/88:31 on 881202.Major areas inspected open flems identified during previous emergency preparedness insps. & on IE Info Notice 87-055. PLOSKI,T., SNELL,W. Region 3, Ofc of the Director, 88/12/12, 4pp. 47853:296-47853:299.
- 8812200091 Forwards Amend 11 to "Byron/Braidwood Stations Fire Protection Rept." HUNSADER,S.C. Commonwealth Edison Co. 88/12/14. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 47871:356-47872:074.
- --8812200097 Amend 11 to "Byron & Braidwood Stations Fire Protection Rept."
 Commonwealth Edison Co. 88/12/31 77pp. 47871:358-47872:074.

- 8812270151 Advises that 881018 Rev 2a & 3b to Braidwood Annox & Byron Annox generating station emergency plans, respectively, consistent w/10CFRS0.54(q) & acceptable Each revinculos table of station-specific emergency action levels. GREGERJ, R. Region 3, Ofc. of the Director. 88/12/15 REED,C. Commonwealth Edison Co. 2pp. 4/924-248-47925.039
- -9812270153 Farwards revised generic enlargency action levels (EAtis) for plurits in response to NRC concerns Committed to implement EAL changes for Braidwood by 880930 revised to indicate that EALs will be implemented within 30 days of NRC applications. proval JOHNSON,I.M Commonwealth Edison Co 88/09/28. DAVIS,A 8 Region 3, Otc of the Director 150pp. 47924 250-47925 039.

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8812190196 Forwards updated FSAR for Byron Station Units 1 & 2 & Braidwood Station Units 1 & 2. HUNSADER,S.C. Commonwealth Edison Co. 88/12/14. MURLEY,T.E. Office of Nu-clear Regulation, Director (Post 870411). 2pp. 47080.001-48012.114.
- -8812190216 Updated FSAR for Byron Units 1 & 2 & Braidwood Units 1 & 2 Roy 0 to chango log encl Commonwealth Edison Co. 88/12/14, 12,869pp, 47980 003-47989 134
- -8812190238 Chapter 1, "Introduction & General Description of Prent," to Byron Units 1 & 2 & Brainwood Units 1 & 2 updated FSAR.
 **Commonwealth Ed son Co. 88/12/14 221pp 47982-050-47982-270
- -8912190250 Chapter 3, "Ossign of Structures, Components, Eq., princit & Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR Commonwealth Edison Co. 88712/14 1,000pp. 47982 271-47983 314
- -8812190344 Chapter 2, "Site Characteristics," to Braidwood Units 1 & 2 updated FSAH * Commonwealth Edison Co. 88/12/14, 1,500pp, 47989 157-47993.090
- -9812190345 "Observations Made By Stato of It. Geological Survey Staff During Visit to Braidwood State on 760311" Illinois, State of 7703708, 3pp. 47993.091-47993.093.
- -8812190347 "Geologic Reconneissance of Clinton & Braidwood Reactor Excavations." SKROVE,JW. Dwston of Site Safety & Environmental Analysis 76/04/27. 3pp. 47993-094-47993-096.
- -8812190349 "Onsite Water Well Boreho'e Log " TREWORGY,J.D. Illinois, State of 77/04/11, 3pp. 47993 697-47993 099.
- -8812190351 "Written Communications Rot in Section 2.5." * Commonwealth Edison Co. 88/12/14, 10pp. 47993:100-47993 109.
- -8812190352 "Subcompartment Pressurzation Studies Outs/de Containment," *Commonwealth Edison Co. 88/12/14, 30pp. 47993.110-47993.141.
- --8812190353 "Selection of Pipe Mall Properties for Use in Pipe Whip Analysis " * Commonwealth Edison Co. 88/12/14, 3pp. 47993;142-47993,144
- --9812190355 "Main Steamline Broak in Main Steam Tunnol."

 ' Commonwealth Edison Co. MAD-7577, 76/07/31, 31pp, 47993 145-47993;175.
- -- 6812190357 "Flooding " Commonwealth Edison Co. 88/12/14. 3pp. 47993.176-47993:314
- -8812190360 "Issues re Regyalization of Byron/Braxtwood Setsin c Design " *Contimonwealth Edison Co. 88/12/14, 450pp, 47903,315,47008,091.
- -8812190366 Chapter 4, "Reactor," to Byron Units 1 & 2 & Breidwood Units 1 & 2 updated FSAR.
 - Commonwealth Edison Co. 88/12/14 300pp 47896.092-47996.356
- --8812190367 Chapter 5, "RCS & Connected Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR. Commonwealth Ed son Co. 88/12/14, 400pp. 47096 357-47997 265
- -8612190369 Chapter 6, "ESF," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR. Commonwealth Edison Co. 88/12/14, 900pp, 47997:266-47999-068.
- -8812190372 Chapter 7, "Instrumentation & Contro's," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14, 450pp, 47899:191-48000 309
- -8812190373 Chapter 8, "Electric Power," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR. * Commonwealth Edison Co. 88/12/14, 275pp. 48000:310-48001:098
- -8812190380 Chapter 9, "Auxiliary Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.
 * Commonwealth Edison Co. 88/12/14. 1,800pp. 48001:099-48004:338
- --8812190382 Chapter 10, "Steam & Power Conversion Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR. Commonwealth Edison Co. 88/12/14, 400pp, 48004:339-48005, 192.
- -8812190383 Chapter 11, "Radwaste Mpt," to Byron Unit 1 & 2 & Braidwood Unit 1 & 2 updated FSAR.
 * Commonwealth Edison Co. 88/12/14, 600pp 48005,193-48006;329
- --6812190369 Chapter 12, "Radiation Protection," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.
- Commonwealth Edison Co. 88/12/14, 500pp. 48006 330-48007;343. -8812190390 Chapter 13, "Conduct of Operations," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.
- Commonwealth Edison Co. 88/12/14 77pp. 48007:344-48008.058

- -8812190391 Chapter 14, "Initial Test Program," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR Commonwealth Edison Co. 88/12/14 123pp 48008 059-48008 181.
- -8812190392 Chapter 15, "Accident Analyses," to Byton Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR * Commonwealth Edison Co 88/12/14, 400pp 48008 182-48009 290.
- -8812190393 Chapter 16, "Tech Specs," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR
 - Commonwealth Ed son Co. 88/12/14 12pp 48009 305-48009 316
- -8812190395 Chapter 17, "QA," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated
 - FSAR. * Commonwealth Edison Co. 88/12/14, 2pp. 48009:317-48009:318.
- -8812190400 App. A, "Application of NRC Reg Guides," to Byton Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR
 * Commonwealth Edison Co. 88/12/14 210pp 48009 319-48010.172.
- -88121904D1 App B, "Const Mail,Std & QC Proceduras," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14 61pp 48010:173-48010 233.
- -8812190402 App C, "Tutbine Missi'e Study," to Byron Units 1 & 2 & Breidwood Units 1 & 2 updated FSAR.

 **Commonwealth Edison Co. 88/12/14, 50pp. 46010:234-48010:283.
- -8812190403 App D, "Computer Programs," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co 88/12/14, 72pp 48010;284-48011;096.
- --8812190404 App E, "Requirements Resulting From TMI-2 Accident," to Byron Units 1 & 2 & Site dwood Units 1 & 2 updated FSAR.

 **Commonwealth Edison Co. 88/12/14, 400pp. 48011.097-48012.114.
- -8812200223 App 6.3A, *Proper Positioning of Valves," to Byron Units 1 & 2 & Breidwood Units 1 & 2 updated FSAR.
 *Commonwealth Edison Co. 88/12/14 5pp. 47999.069-47999.177.
- --8812200228 "Tod ne Remova! Effectiveness Evaluation of Containment Spray Sys." * Commonwealth Edison Co. 88/12/14, 11pp. 47999:178-47999:190.
- -8812200234 Dose Models Used to Evaluate Environ Consequences of Accidents." Commonwealth Edison Co. 88/12/14, 7pp. 46009 291-48009,297.
- -8812200237 "Models for LOCA Analysis"
 * Commonwealth Edison Co. 88/12/14, 7pp. 48009:298-48009.304
- P. Operating license stage documents & correspondence
- 8811290081 Forwards addl Info supporting 881026 proposed amend to Tech Spec 4.8.1.1.21 and losel generator testing requirement. Acceptance of amend will allow Unit 1 survaillance outlage to be cancelled. NUNSADER,SIC. Commonwealth Ed son Co. 88/11/22. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 55pp. 47665-323-47686:017.
- 8812050324 Forwards response to regulatory effective review. Response withheld (ref
- 10CFR73[21].
 BLISS,H.E. Commonwealth Edison Co. 8B/11/22 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 47731:220-47731:220.
- 8811280048 Generic Ltr 68-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities.Svc list
- CRUTCHFIELD,D. Associate Director for Projects (Post 670411), 88/11/23 Consoll-dated Edison Co. of New York, Inc. 81pp. 47728:303-47729:024.
- 8812010305 Provides analysis of Reg Gulde 1.99.Rev 2, "Radiation Embrittlement of Roactor Vesset Matts" for Impact on pressure-temp heatup & cooldown curves contained in Tech Specs, per Generic Ltr 88-11.

 RICHTER,MH. Commonwealth Edison Co. 88/11/28 Document Control Branch (Document Control Desk), 2pp. 47703:049-47703.050.
- 8812070057 Forwards util evaluation of ENSPEC 3000 engine analyzer results,per 881026 application for amend to License NPF-72, extending on one-time basis,31-month surveillance testing requirement for Diesel Generators i DG01KA & 1DC01KB HUNSADER,S.C. Commonwealth Edison Co. 88/11/29, MURILEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47753.094-47753:095.
- 8812070239 Notification of 681207 meeting w/uhl in Rockville,MO to discuss DCROR submittel of 880825.
 SANDS,S.P. Project Directorate III-2, 88/12/02. MURLEY,T., SNIEZEK,J., MIRAGLIA,F. NRC No Detailed Affihation Given. 3pp. 47749.275.47749:277.
- 8812140141 Advises that util 881129 fir which provided evaluation of ENSPEC 3000 engine analyzer results did not mention Ignition column data because data does not apply to plant diesel generators which are compression ignition type.
 HUNSADER,S.C. Commonwealth Edison Co. 88/12/05. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47812:048-47812:049.
- 8812070261 Remits fee for application for amends to Licenses NPF-37, NPF-66,NPF-72
- LARA S.C. Commonwea'th Edison Co. 88/12/06. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 47748.076.47748.076.
- 8812200274 Application for amends to Licenses NPF-37,NPF-86,NPF-72 & NPF-75,changing 1 ech Spec 4.2 2.2.e to remove fixed Fxy limits to NRC via operating limits rept Fee perd. CHRZANOWSKI,R. Commonwealth Edison Co. 88/12/12, MULLER,D.B. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47864:277-47864:292.
- --8812200276 Proposed Tech Spec 4.2.2.2.e.removing fixed Fxy limits & substituting requirement to submit Fxy limits to NRC via operating limits rept.
 * Commonwealth Edison Co. 88/12/12, 14pp. 47864;279-47864;292.

- 6812230162 Application for amends to Licenses NPR-37,NPF-86,NPF-72 & #IPF-75,modifying Tech Spacs to change Bases Page 374 4-2 which adds clarification for power-operated relief valves operability. CHRZANOWSKI.R. Commonwealth Edison Co. 88/12/12 MULLER,D H. Project Discourage.
 - rectorate III-2, 2pp 47911,326-47911:330.
- ~8812230172 Proposed Tech Specs 3/44.2-4.edding clarification for prossurter power-operated relief valves operability.

 **Commonwealth Edison Co. 88/12/12. 3pp. 47911:328-47911.330
- 8812220206 Forwards proprietary & nonproprietary NFSR-0033, "VIPRE/ WRB 1 DNBR Thermal Limit for Westinghouse OFA Fuel." Attidavit & application for withholding proprietary rapit also encil Proprietary resion withhold (ref 100FR2760). TRZYNA.G.E. Commonwealth Edison Co. 88/12/15. Office of Nuclear Reacts/ Regulation, Director (Post 870411). 4pp. 47892.257-47892.330.

Q. Inspection reports, IE Bulletins & correspondence

- 8810050121 Responds to NRC 880829 fir re-violations noted in Insp Repis 50 456768-18 & 50-457788-18 Corrective actions out policy of deadly force as currently stated an security plan has been established w/100CFR73.55.Encl withheld.
 BLISS,H.E. Commonweal'th Edison Co. 88/09/16 DAVIS.A B. Region 3, Otc of the 12 rector. 2pp. 47701:351-47701:352.
- 8811300444 Forwards addl into clarifying Westinghouse Rept MT-SME-427(66) re-6trab-fication. 8 thermal cycling Issues in response to 881101 telcon request concerning NRC Bulletin 88-008 CHRZANOW9KI,R. Commonwealth Edison Co. 88/11/09. MURLEY,T.€. Office of Noticear Reactor Regulation, Director (Post 870411). 2pp. 47697:256-47697.257
- 8811300547 Forwards Safety Insp. Repts 50-456/88-28 & 50-457/88-28 on 681015

1103.No violations noted.
GREENMAN,E.G. Region 3, Old of the Director. 88/11/17. REED,C. Commonwealth Edison Co. 2pp. 47873:195-47673:206.

- -8611300551 Insp Repts 50-456/88-28 & 50-467/88-28 on 881015-1103 No volations noted Major areas inspected events aurrounding several missed or Improperty porformed Tech Spec surveillances HINDS,J.M. Region 3, Oic of the Director, 88/11/17, 10pp. 47673:107-47673:206.
- 8811300281 EN-88-101:on 881123,notice of proposed imposition of civil penalty in amount of \$75,000 will be issued to licensee. Action based on lailures to adequately implement environ qualification requirements of 10CFR50.48. LUCHMANJ, LIEBERMANJ, Ofc. of Enforcement (Post 870413). 88711718 1p. 47677:322-47677:322.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industria" Nucleur Gauges "Svc list enct. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 670729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47703.257.
- 8811160467 NRC Into Notice 88-091, "Impropor Administration & Control of Peychological Tests." Suc list enci.
 ROSSI.C.E. Division of Operational Evente Assessment (Post 870411), 68/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708:142.
- 8812080282 Responds to NRC 8B1027 ltr re violations noted in Insp Ropts 50 456768 26 & 50-457768-25 on 800828-1015 Corrective actions that parsonnol informed that chemistry to be notified of panel/sink trouble annunciator plarms.
 BLISS,H.E. Commonwealth Edison Co. 88/11/22. DAVIS.A B. Region 3, Otc of the Darector. 3pp. 47741:047-47741:049.
- 8811290544 Ack receipt of 881118 ltr & payment in amount \$50,000 for NRC rttposodictvi penalty per NRC 881018 order. LIEBERMANJ, Ofc of Enforcement (Post 870413), 88/11/23, REEO,C. Commonwealth Edison Co. 1p. 47650:135-47650.135.
- 8811300400 Forwards notice of violation & proposed imposition of civil possity in amount of \$76,000.

 DAVIS,A B. Region 3, Ofc of the Director, 88/11/23, O'CONNOR, J J Commonwo aith Edison Co. 4pp. 47701:280-47701:295.
- --8811300406 Nolice of violation & proposed imposition of civil penalty in smooth of \$75,000.Noncompliance noted electric equipment important to safety not proporty qualified by teeling &for analysis & specific maint soll
- 8812060142 Forwards Safeguards Insp Rept 50-456/88-30 & 50-457/88-30 on 8810.25-28.No violations noted.
 GREGER,L.R. Region 3, Ofc of the Director. 88/11/30. REED,C. Commonwoa!th
 Edison Co. 2pp. 47741:231-47741:233.
- -8812060145 Insp Repts 60-456/88-30 & 50-457/88-30 on 881025-28 & 31 & 1101 No violations noted Major areas inspected mg support, security program plans, & audits protected & vital area physical barriers & detection & assessment olds MADEDA, T.J., CREED, J.R. Region 3, Old of the Director, 88/11/30, 1p 47741.293-47741:293-
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc list enci. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811.103-47815 215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Svc 652 enci.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02.
 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812020287 NRC Into Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vandors." Svc list enci.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/12/08.
 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.

- ~8812140256 Notice of violation from Insp on 881016-1126. Violation noted condition edverse to quality not properly identified & corrected in that, on 881031, MSIV 1A declared inoperable, notification was not made within 1-b requirement to NRC CLAYTON.B. Region 3, Oto of the Director. 88/12/09. 1p. 47800-177-47800.177.
- -8812140257 Insp. Repts 50:456/88:29 & 50:457/88:29 on 881016:1126 Violations noted Major areas Inspected licenses action on proviously identified items.LERs review, regional request, temporary instruction, ESF sys & training effectiveness. HINDS,J M. Region 3, Otc of the Director. 88/12/08. 14pp. 47800.178-47800.191.
- 8812190265 Forwards Saloty Insp. Repts 50-456/88-31 & 50-457/88-31 on 881202.No violations noted.
 GREGER,L.R. Region 3, Ofc of the Director. 88/12/13. REED,C. Commonwealth Ed son Co. 2pp. 47853.294-47853:299.
- -8612190267 Insp. Repts 50-456/88-31 & 50-457/88-31 on 881202 Major areas inspected open items identified during previous emergency preparedness insps & on (E Into Notice 87-058 PLOSKI,T., SNELL,W. Region 3, Ofc of the Director, 88/12/12, 4pp 47853/296-47853/299.
- 8312190388 Discusses enforcement conference held on 881123 re Insp. conducted on 881018-1103 concerning several instances of missed or improperly performed surveillance Summary end. Of the Director. 88/12/13. REED,C. Commonwealth Edison Co. 4pp. 47851:268-47851:269.
- 8812220382 Forwards Rev 2 to "Braidwood Nuclear Power Station Units 1 & 2 Inservice Insp & Testing Program Plan First Insp Interval." Related Info presenting comparison of Braidwood & Byron plants Inservice Insp programs enci. HUNSADER,SC Commonwealth Edison Co. 88/12/15. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 14pp. 47804:037-47906 279.
- -8812220385 Rev 2 to "Braidwood Nuclear Power Station Units 1 & 2 Inservice Insp & Testing Program Plan First Insp Interval."
 * Commonwealth Edison Co. 88/12/15, 800pp, 47904:051-47906:279.

R. Periodic operating reports & related correspondence

- 8812020197 Forwards supplemental rept to 10CFR50.59 annual rept to plant to include instrumentation selpoint/scaling changes. HUNSADER,S.C. Commonwealth Edison Co. 88/11/28. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 6pp. 47707:175-47707:181.
- 8912150217 Monthly operating repts for Nov 1998 for Braidwood Units 1 & 2.W/881209 PETERSON,M.W., QUERIO,R.E. Commonweelth Edison Co. 88/11/30. 14pp. 47826:337-47826:350.

9. Reportable occurrences, LERs & related correspondence

- 8812060011 LER 88-024-00:on 881031 operator noted that hydraul.c pump on 1A MStV pumping continuously.Caused by faiture of "M1" four way valve Nuclear Work Request A28531 written to replace defective four way hydraulic valve M1.W/861130 ftr. STROH,D., QUERIO,R.E. Commonwealth Edison Co. 88/11/07, 6pp 47743-089-47743-089.
- 8812050206 Confirms 881123 plans for 881206 mgt meeting w/util to discuss turbine bidg instrument air ring header fallure induced Unit 1 & 2 scrams, review & analysis of 1988 reactor scrams.

 GREENMAN,E.G. Region 3, Old of the Director, 88/11/29, REED,C. Commonwealth Edison Co. 2pp. 47731:145-47731:146.
- 8812090297 Special reption 881020,discovered that sensor Channels LM001 & LM009 were in low afarm. Caused by fraying of insulated fibre jacket of microdot connector cable. Sensor channels replaced.
 HUNSADER,S.C. Commonwealth Edison Co. 88/11/29. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47775:202-47776.203.
- 8812210007 LER 88-025-00:on 881115,manual reactor trip initiated due to decreasing steam generator levels. Caused by Inadequate instellation of coupling in Instrument air header. Add pipe supports will be added to header. W/881212 ltr. NYKAZA,P., QUERIO,P. Commonwealth Edison Co. 88/12/13, 5pp. 47876:288-47878:282.

V. Operator Examinations

8812140053 Informs that requalification program evaluation visit scheduled for wk of 890417.Fac/lify will need to furnish approved items listed in Encl 1 at least 60 days prior to exam date.

WRIGHT.G.C. Region 3, Otc of the Director. 88/12/05, REED,C. Commonwealth Edison Co. 8pp. 47796:132-47796:139.

DOCKET STN-50-467 BRAIDWOOD STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8810050121 Responds to NRC 880628 ftr re violations noted in Insp Repts 50-458/88-18 & 50-457/88-18.Corrective actions:util policy of deadly force as currently stated in security plan has been established w/10CFR73.55.Encl withheld.
 BLISS,H.E. Commonwealth Edison Co. 88/09/16. DAVIS,A.B. Region 3, Ofc of the Director. 2pp. 47701:351-47701:352.
- 8812050324 Forwards response to regulatory effective review. Response withhold (ref
 - 10CFR73.21).

 BLISS,H.E. Commonwealth Edison Co. 88/11/22. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 47731:220-47731:220.

- --8812080145 Insp Ropts 50-456/88:30 & 50-457/88:30 on 881025:28 & 31 & 1101 No violations indeed Major areas inspected mgl support, security program plans, & audits protocted & vital area physical barriers & detection & assossment aids. MADEDA,T.J. Regran 3, Oic of the Director. 88/11/30. pp 47741:233-47741:233.
- 8812190265 Forwards Safety Insp Repts 50-456/88-31 & 50-457/88-31 on 681202 No violations noted GREGERI,L.R. Region 3. Ofc. of the Director. 88/12/13. REED,C. Commonwealth Edison Co. 2pp. 47853-294-47853-299.
- -8812190267 Insp. Repts 50.456/88-31 & 50.457/88-31 on 881202.Major areas inspected open rems identified during previous emergency preparedness this in IE Into Notice 87-058. PLOSKI,T., SNELL,W Region 3, Ofc of the Director 86/12/12, 4pp. 47853 296-47853 290
- 8812200091 Forwards Amend 11 to "Byron/Braldwood Stations Fire Protection Rept." HUNSADER,S.C. Commonwealth Edison Co. 88/12/14 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47871:356-47872
- -8812200097 Amend 11 to "Byron & Breidwood Stations Fire Protection Rept" Commonwealth Edison Co. 88/12/31, 77pp. 47871:358-47872 074.
- 8812270151 Advises that 881018 Rev 2a & 3b to Braidwood Annex & Byron Annex generating station omergency plans, respectively, consistent w/10CFR50.54(q) & acceptable Each rev includes table of station-specific emergency action levels (EREGER), L.R. Region 3, Ofic of the Director, 89/12/15, REED,C. Commonwealth Ed son Co. 2pp. 47824:248-47925.039.
- -8812270153 Forwards revised generic emergency action levels (EALs) for plants, in reeponse to NRC concerns Commitment to Implement EAL changes for Braidwood by 880930 revised to Indicate that EALs will be Implemented within 30 days of NRC ap-JOHNSON,I.M. Commonwealth Edison Co. 88/09/28. DAVIS,A.B. Region 3, Otc of the Director. 150pp. 47824:250.47925.039.

K. Uillijy Final Safety Analysis Report (FSAR) & amends

- 8812190198 Forwards updated FSAR for Byron Station Units 1 & 2 & Braidwood Station HUNSADER,S.C. Commonwea'th Edison Co. 88/12/14. MURLEY,T.E. Office of Nuclear Regulation, Director (Post 870411). 2pp. 47980.001-47989:166.
- →8812190216 Updated FSAR for Byron Units 1 & 2 & Braidwood Units 1 & 2. Rev 0 to change log encl * Commonwealth Edison Co. 88/12/14, 12,869pp, 47980,003-47989,134
- --8812190236 Chapter 1, "Introduction & General Description of Plant," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonweelth Edison Co. 88/12/14, 221pp. 47982-050-47982-276.
- --8812190250 Chapter 3, "Design of Structures, Components, Equipment & Sys," to Byton Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14, 1,000pp, 47982:271-47983 314.
- -8812190344 Chapter 2, "Site Characteristics," to Braidwood Units 1 & 2 updated FSAR. * Commonwealth Edison Co. 88/12/14. 1,500pp. 47989:157-47903 090
- -8812190345 "Observations Made By State of IL Goological Survay Staff During Visit to Braidwood Site on 760311."
 * Illinois, State of. 77/03/08. 3pp. 47993:091-47993.093.
- --8812190347 "Geologic Roconnaissance of Clinton & Braidwood Reactor Excavations." SKROVE J.W. Division of Site Safety & Environmental Analysis. 76/04/27. 3pp. 47993.094-47993.096
- --8812190349 "Onsite Water Well Borehole Log " TREWORGY,J.D. Illinois, State of. 77/04/11, 3pp. 47993:097-47993:099.
- -8812190351 "Written Communications Ref in Section 2.5." Commonwealth Edison Co. 88/12/14. 10pp. 47893:100-47893:109.
- -8812190352 "Subcompartment Pressurization Studies Outside Containment." Commonwealth Edison Co. 88/12/14. 30pp. 47993:110-47993:141.
- --8812190363 "Selection of Pipe Mati Properties for Use In Pipe Whip Analysis."

 * Commonwealth Edison Co. 88/12/14, 3pp. 47993:142-47993:144.
- -8812190355 "Main Steamline Break in Main Steam Tunnel."
 " Commonwealth Edison Co. MAD-7677, 76/07/31, 31pp. 47993:145-47993:175.
- -8812190357 "Flooding."
 * Commonwealth Edison Co. 88/12/14, 3pp. 47993:176-47993:314.
- --8812190360 "Issues re Reevalustion of Byron/Braidwood Seismic Design." Commonwealth Edison Co. 88/12/14, 450pp, 47993:315-47996:091.
- -8812190366 Chapter 4, "Reactor," to Byron Units 1 & 2 & Braidwood Units 1 & 2 up-
- Commonwealth Edison Co. 88/12/14. 300pp. 47896:092-47996:356.
- --8812190367 Chapter 5, "RCS & Connected Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.
 - Commonwealth Edison Co. 88/12/14, 400pp, 47996:357-47997:265.
- -8812190369 Chapter 6, "ESF," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR. * Commonwealth Edison Co. 88/12/14. 900pp. 47997:268-47999.068.

- -8812190372 Chapter 7, "Instrumentation & Controls," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR
 - Commonwea th Edison Co | 88/12/14 | 45Cpp. 47999 191 48000 309
- -8812190373 Chapter 6, "Electric Power," to Byren Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR Commonwealth Edison Co. 88/12/14 275pp 48000 310 48001.098
- -8812190380 Chapter 9, "Auxiliary Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2
- Commonwealth Edison Co. 68/12/14 | 1 800pp | 48001 099-48004 338
- --8812190382 Chapter 10, "Steam & Power Conversion Sys," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSA9

 * Commonwealth Edison Col 68/12/14 400pp 48004:339-48005:192.
- -8812190383 Chapter 11, "Radwaste Mgt" to Byron Unit 1 8 2 8 Braidwood Unit 1 8 2 updated FSAR
- Commonwealth Edison Co. 88/12/14, 600pp, 48005:193-48006:329.
- -8812190389 Chapter 12, "Red ation Protection," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR,

 *Commonwealth Edison Co. 88/12/14, 590pp. 48006.330-48007;343.
- -8812190390 Chapter 13, "Conduct of Operations," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR
- Commonwealth Edison Co. 88/12/14, 77pp. 48007:344-48008:058
- --8812190391 Chapter 14. "Initial Test Program," to Byron Units 1 & 2 & Brakfwood Units 1 & 2 updated FSAR.

 **Commonweat's Edison Co. 88/12/14, 123pp. 48008 059-48008:181.
- -8812190392 Chapter 15, "Accident Analyses," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.
- Commonwealth Edison Co. 88/12/14, 400pp. 48008 182-48009 290
- ←8812190393 Chapter 16, "Tech Specs," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR Commonwealth Edison Co. 88/12/14, 12pp. 48009.305-48009.316
- -8812190395 Chapter 17, "QA," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated
- Commonwealth Edison Co. 88/12/14, 2pp. 48009:317-48009:318
- →8812190400 App A, "Application of NRC Reg Guides," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR

 * Commonwealth Edison Co. 88/12/14, 210pp, 48009,319,48010,172
- -8812190401 App B, "Const Mati Std & OC Procodures," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR
 * Commonwealth Edison Co. 88/12/14 81pp. 48010.173-48010:233.
- --8812190402 App C, "Tuibine Missile Study," to Byron Umis 1 & 2 & Braidwood Umis 1 & 2 updated FSAR 1 Commonweelth Edison Co. 88/12/14, 50pp. 48010 234-48010:283
- --8812190403 App D, "Computer Programs," to Byron Units 1 & 2 & Braidwood Units 1 & 2 & Braidwood Units 1
- Commonwealth Edison Co. 88/12/14, 72pp, 48010 284-48011:098.
- -8812190404 App E, "Requirements Resulting From TMI-2 Accident," to Byron Units 1 & 2 & Braidwood Umis 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14, 400pp, 48011,097-48012,114.
- →8812200223 App 6 3A, "Proper Positioning of Valves," to Byron Units 1 & 2 & Braidwood Units 1 & 2 updated FSAR.

 * Commonwealth Edison Co. 88/12/14, 5pp. 47999 069-47999.177.
- -8812200228 "Todine Removal Effectiveness Evaluation of Containment Spray Sys."
 Commonwealth Edison Co. 86/12/14, 11pp. 47993:176-47999:190.
- 8812200234 "Dose Models Used to Evaluate Environ Consequences of Accidents."
 Commonwealth Edison Co. 86/12/14, 7pp. 48008/291-48008/207.
- -8812200237 "Models for LOCA Analysis."
 * Commonwealth Edison Co. 86/12/14, 7pp 48009 298-48009 304.
- P. Operating license stage documents & correspondence
- 8812050324 Forwards response to regulatory effective review Response withheld (ref. 10CFR73.21).
 BLISS,H.E. Commonwealth Edison Co. 88/11/22, MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 970411), 1p. 47731:220-47731:220.
- 8811280048 Ganeric Ltt 89-20 to all I censees holding OLs & CPs for nuclear power reactor facilities no individual plant exam for severe accident vulnerabilities. Svc list
- CRUTCHFIELD.D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728 303-47729.024.
- 8812010305 Provides analysis of Reg Guide 1.98,Rev 2, "Radiation Embrittlement of Reactor Vessel Matts" for impact on pressure-temp heatup & cooldown curves contained in Tech Spocs per Generic Ltr 83-11.

 RICHTER.M.H. Commonwealth Edison Co. 88/11/28 Document Control Branch (Document Control Desk). 2pp. 47703.049-47703:050
- 8812070239 Notification of 881207 meeting w/util in Rockyille,MD to discuss DCRDR submittal of 880825
 SANDS,S.P. Project Directorate III-2. 88/12/02: MURLEY,T. NRC - No Detailed Affiliation Given. 3pp. 47749:275-47749:277.
- 8812070261 Remits fee for application for amends to Licenses NPF-37, NPF-68,NPF-72 8 NPF-77. LARA,S.C. Commonwealth Edison Co. 88/12/06. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 47748 076-47748 076.

- 8812200274 Application for amends to Licenses NPF-37,NPF-66,NPF-72 \$ NPF-75,changing Tech Spec 4.2.2.2 a to remove fixed Fxy limits to NRC via operating in its reptified paid. CHRZAROWSKIR, Commonwealth Edison Co. 88/12/12, MULLUR,D.B., Office of the clear Reactor Regulation, Director (Post 870411). 2pp. 47864.277-47864.292.
- •8812200276 Proposed Tech Spice 4.2.2.2 a removing fixed Fxy firmts & subsections requirement to submit Fxy firmts to NRC via operating times rept.
 * Commenwealth Edison Co. 88/12/12, 14pp. 47864;279:47804;292.
- 8812230162 Application for emends to Licenses NPR-37,NPF-86,NFF-72 & NPF-76,modifying Tech Specs to change Bases Page 374 4-2 which adds dischance for power-operated relief valves operability. CHRZANOWSKIR Commonwealth Edison Co. 88712712 MULLER,D,R. Project Directorate III-2, 2pp. 47911,326,47911,330
- -8812230172 Proposed Tech Specs 374.4.2-4,adding clarification for pressurate poweroperated reflet valves operability
 **Commonwealth Edison Co. 88/12/12, 3pp. 47911:328-47911,330.
- 8812220206 Forwards prophetary & nonprophetary NESR-0033, "VIPRE/ WROLL CNDR Thermal Limit for Westinghouse OFA Fue!" Affidavit & application for with-clung pro-phetary rept also end! Prophetary version withhold (ref. 100ER) 790. TRZYNA,G.E. Commonwealth Edison Co. 88712715, Office of Nuclear Resident Regu-lation, Director (Post 870411), 4pp. 47892.257-47892, 330.
- Q. Inspection reports, IE Bulletins & correspondence

47677:322-47677.322

- 8810050121 Responds to NRC 880628 filt rely obtained in Insp. Repts 50 456/98 18 & 50-457/88-18. Corrective actions util policy of ideality force as currently stated the security plan has been established wy10CFR73.55 Encl withheld BLISS-HE. Commonwealth Edison Co. 88/09/16. DAVISIA B. Region 3, Otc of the Cyroctor. 2pp. 47701.351-47701.352
- 6811300547 Forwards Safety Insp. Repts 50 456/88-28 & 50 457/89-28 on 631015-1103 No violations noted GREENMAN,E.G. Region 3, Otc. of the Director, 88/11/17, REED,C. Co. intingualth Edison Co. 2pp. 47873.195-47873.206
- -8811300551 Insp Repla 50 456/86-28 & 50 457/06-20 on 881015-1103 No ve মা ১০১ noted Major areas. Inspected events, surrounding, several, missed, or impropuly, per-lombed tech Spic surveillances. HINDS,J.M. Ragion 3, Ofe of the Director, 08/11/17, 10pp, 47673-197-47873-209.
- 8811300261 EN-88-101 on 881123,notice of proposed imposition of civil principy in amount of \$75,000 will be issued to Loonseo. Action based on fadures to edwy.act. ty implement environ qualification requirements of 10CFR0.40

 LUEHMANJ_LIEBERMANJ_Otc of Enforcement (Post 870413) 88/11/19 1p.
- 8811300444 Forwards addl into claufying Wustinghouse Rept MT-SME 427(03) ic stratification & thermal cycling issues in response to 881101 tolcon request concerning NRC Buttetin 88,008
 - CHRZANOWSKI,R. Commonwealth Edison Co. 88/11/09. MURLEY,T.E. Office of No-cloar Reactor Regulation, Director (Post 870411). 2pp. 47697 256-47697 257.
- 8811160211 NRC Info Notice 88 090, "Unauthorized Removal of Industrial Nuclear Gauges." Sec list and: CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Salety (Past 8/07/29) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp 47708 255 4/703 257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Centrol of Psychology cal Tests." Suc list encl ROSSICE. Division of Operational Events Assessment (Post 670411) 69/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142
- 8812060282 Responds to NRC 881027 ftr re-violations noted in Insp Repts 50-1/41/68-26 & 50-457/88-26 on 880828-1015.Corrective actions:shift personnel inforced that chamistry to be notified of panol/sink trouble annunciator elemns.

 8LISS,HC Commonwealth Edison Co 88/11/22, DAVIS,A.B. Region 3, Ofc of the Carector, 3pp. 47741:047-47741:049.
- 8811300400 Forwards notice of violation & proposed Imposition of civil penalty an amount of \$75,000.

 DAVIS,A.B. Region 3, Old of the Director, 88/11/23, O'CONNOR,J.J. Commonwestin Edison Co. 4pp. 47701:280-47701:295.
- -8811300406 Notice of violation & proposed imposition of civil penalty in amount of \$75,000.Noncompliance noted clactric equipment important to safety not property qualified by testing \$70x analysis & specific maint activities not implemented DAVIS,A.B. Region 3, Otc of the Director 88/11/23, 8pp. 47701-264-47701-235
- 8812060142 Forwards Safeguards Inap Rept 50-456/88-30 & 50-457/89-30 on 881025 20.No violations noted.

 GREGER,L.R. Region 3, Ofc. of the Director. 88/11/30. REED,C. Commonwealth Edison Co. 2pp. 47741:231-47741:233.
- --8812080145 Insp Repts 50-456/68-30 & 50-457/68-30 on 881025-28 & 31 & 1101 No violations noted Major areas inspected mgl support, accurity grogram tans. & audits projected & vital area physical barriors & detection & assessment eds MADEDA, TJ, CREED, JR. Region 3, Old of the Director, 88/11/30, 1p. 47/41 233-47741:233.
- 8811290030 NRC Info Notice 68-093, "Teletherapy Events." Svc Lst encl CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811
- 8811290536 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Syc less enct. ROSSI.C.E. Division of Operational Evonts Assessment (Post 870411) 68/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708-143-47708-254

11512U2U2U1 NOC By Licensees on Vendors" Svc list and.

ROSS:(CE Division of Operational Events Assessment (Post 870411). 88/12/08
Consol dated Edison Co. of New York, Inc. 112pp. 47807:191-47807.302 magoddaio middienieni nedo ienienis inibasan

8812140255 Forwards Safety Insp Repts 50 456/88 29 8 50 457/88 29 on 881016 126 8 notice of violation
CLAYTON,B. Region 3, Old of the Director 88/12/09 REED,C Commonwealth
Edison Co. 20p. 47800:175-47800.191.

- -8812140257 Insp Ropts 50-456/88-29 & 50-457/88-29 on 881016-1126. Violations rated Major areas inspected licenses action on previously identified items, LERs review, regional request, temporary instruction, ESF sys & training offectiveness HINDS, J.M. Region 3, Otc of the Director 88/12/08 14pp. 47800 178-47800 191
- 6812190265 Forwards Safety Insp Ropts 50-456/88-31 & 50-457/88-31 on 881202.No

violations noted GREGER,L R. Region 3, Otc of the Director 88/12/13. REED,C Commonwealth Edison Co. 2pp. 47853 294-47853:299.

- -4812190267 Insp. Repts 50-456/68-31 & 50-457/68-31 on 881202.Major areas inspected-open items identified during previous emurgency preparedness insps & on IE Info Notice 87-058 PŁOSKIT, SNELL,W. Region 3, Ofc of the Director, 88/12/12, 4pp. 47853-296-47853:298.
- 8812190366 Discusses enforcement conference he'd on 881123 re inspiconducted on 881015-103 concerning several instances of missed or improperly performed survei lance. Summary encl. GREENMAN.E.G. Region 3, Ofc of the Director. 88/12/13. REED,C. Commonwealth Ed son Co. 4pp. 47851:266-47851:269.

8812220382 Forwards Rev 2 to "Braldwood Nuclear Power Station Units 1 & 2 Inservice Insp & Testing Program Plan First Insp Intorval" Holated Info presenting comparison of Braidwood & Byron plants Inservice Insp programs and.
HUNSADER,S.C. Commonwealth Edison Co. 68/12/15. MURLEY,T.E. Office of Nuclear Reactor Regulation, Orrector (Post 870411), 14pp. 47904:037-47906.279

-8812220385 Rev 2 to "Braidwood Nuclear Power Station Units 1 & 2 Inservice Insp 8 Testing Program Plan First Insp Interval."
Commonwealth Edison Co. 881/2/15. 800pp. 47904:051-47906:279.

R. Periodic operating reports & related correspondence

8812020197 Forwards supplemental rept to 10CFR50.59 annual rept for plant to include instrumentation sorpoint/scaling changes. HUNSADER,S.C. Commonwealth Edison Co. 88/11/28, MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 6pp. 47707;176-47707.181.

8812150217 Monthly operating repts for Nov 1988 for Braidwood Units 1 & 2.W/881209 Лу. PETERSON,M.W., QUERIO,R.E. Commonwealth Edison Co. 88/11/30. 14pp. 47828 337-47826:350.

S. Reportable occurrences, LERs & related correspondence

- 8811290161 LER 88-029-00:on 081025,manual reactor trip & RICS Inventory belance in excess of required time interval occurred Causard by condensate pump suction strainers plugging Main condenser thoroughly inspected & cleaned W/881122 lir. LEWAND, M., QUERIO,R.E. Commonwealth Edison Co. 88/11/09. 8pp. 47849 287-47849 292
- 8812060034 LER 88-030-00:on 881030 steam generator water level reached high level due to overfeeding Caused by nuclear stellon operator lack of experience Steam generator water levels restored to normal band.W/861129 tir. IBRAHIM.D.W., QUERIO,R.E. Commonwealth Edison Co. 86/11/14. 4pp. 47744 295-47744:298.
- 8812060010 LER 88:031:00:on 881105, reactor trip due to negative rate trip on all instru-mentallon sys power range channols occurred Caused by incorrect rolay 1H setting due to conflicting Info In technical manual: W/881128 itr. WIEGAND.C., QUERIO,R.E. Commonwealth Edison Co. 88/11/18. 4pp. 47735:001-47735 004
- 8812050206 Confirms 881123 plans for 881206 mgt moeting w/uti to discuss turbine bidg Instrument air ring header fallure induced Unit 1 & 2 scrams, review & analysis of 1989 reactor scrams.

 GREENMAN,E.G. Region 3, Ofc of the Director. 88/11/29. REED.C. Commonwealth Ed son Co. 2pp. 47731:145-47731:146.

- 8812210003 LER 88-027-00:on 8B1115, containment ventilation isolation occurred due to transient loss of 345 kV switchyard line due to thunderstorm. Radiation monitor in: at-ed interlock & manuelly reset Event considered spurious W/881209 ltr.
 ROUNTREE,R., QUERIO,R.E. Commonwealth Edison Co. 8B/12/02. 4pp. 47889 231-
- 8812210001 LER 88-028-00:on 883117, reactor trip due to lo-lo level in 28 steam generator occurred. Caused by procedural deficiency. Pneumatic converters & positioners of feedwater regulating bypass valves recalibr. W/881212 ltr. IBRAHIM.D.W., QUERIO,R.E. Commonwealth Edison Co. 88/12/08. 4pp. 47878 307-47876.310.

V. Operator Examinations

8812140053 Informs that requalification program evaluation visit scheduled for wk of 890417.Facility will need to furnish approved Itoms fisted in Encl 1 at least 80 days prior to exam date.
WHIGHT.G.C. Region 3, Ofc of the Director, 98/12/05. REED,C. Commonwealth Ed son Co 8pp. 47796.132-47796:139.

DOCKET 50-458 HIVEN BEND STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811300086 Advises that 881014 changes to amergency plan accoptable CALANI, J. Rogion 4, Oil of the Director, 88711718, DEDDENS, J.C. Gulf. States Utilities Co. 2pp. 47896.282-47696.283.
- 8812060310 Forwards supplemental response to violation noted in Insp Rept 50:4587 88:03-Response withhold (ref 10CFH73.21) BOOKERJUE Gull States Utitize Co. 887/11/30. Office of Nuclear Reactor Regula-tion, Director (Post 870411). hp. 47741-052-47741-052.
- 8812140066 Forwards Insp. Rept 59 458/68-23 on 880918-1105 & notice of violation. CALLANUL J. Region 4, Dick of the Director 18/12/07 DEODENS J.C. Gull States Unities Co. 2pp. 47799-213-47799-231.
- --B812140083 Insp Rept 50-458/88/23 on 880918-1105 Violations noted. Mejor areas inspected accessed action on previous insp findings & NRC Notice 88-043 surveillance test & maint observations operational safety ventication & security. FORDLEJ, JONES, W.B., CONSTABLE,G.L. Region 4, Old of the Director, 88/12/06 15pp. 47790/217-47799/231.
- 8812140103 Forwards Rev. 11 to physical sucurity plan Rev. contains seleguards matl & willhold (rof 10CFR/3.21)
 DEDDENS.J.C. Gulf States (Millers Co. 88/12/08. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 47802-268-47802-269.
- 8812140107 Forwards Roy 7 to security training & qual-fication plan.Roy contains safe-quards matt & withheld (of 10CFR73 21) DENDENS, J.C. Girl States Utilities Co. 88712709. Office of Nuclear Material Safety & Safeguards, Diructor. 2pp. 47632 256-47802 257.

H. General correspondence

- 8812080006 Forwards authorization of Board of Directors of util for JE Booker to sign firs to NRC transmitting amonds to OL or in response to any NRC Inspirept. DEDDENS,J.C. Gulf States Utilizes Co. 88711729. Document Control Branch (Docu-ment Control Desk), 2pp. 47743 065-47743 066
- 8812200354 Rosponds to 881017 ltr expressing concerns in Rev 1 to updated SAR Attridevil and w/880825 ltr acceptable certification 8 iconsee chose special symbol indicators placed above 8 below area changed PAULSON.W.A. Division of Reactor Projects III,IV.V. 8 Special Projects (Post 870411), 86/12/14, PLETTINGER.H.A. Attribution Not Assigned 4pp. 47864.177-47864.187 47864:180.

P. Operating license stage documents & correspondence

- 8811280212 Forwards Amond 30 to Licenso NPF-47 & safety evaluation. Amend deletes requirement for NRC approval of asiatic clam control program prior to Introducing river water to plant sys & adds monitoring clariter influent for Corb cula, PAULSON,W-A Project Directorate IV. 88/11/18 DEDDENS,J.C Gulf States Utilities Co. 5pp. 47656:317-47656:330
- --8811280213 Anxind 30 to License NPF-47, dotoing requirement for NRC approval of asialic claim control program prior to river water introduction to prant sys & adding requirement for monitoring classifier influent for Corticula CALVO, J.A. Project Circotoria V. 68/11/16 5pp 47656 322-47656 326
- -8811280214 Satety ovaluation supporting Amend 30 to Liconsc NPF-47.

 **Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/16, 4pp. 47856/327-47856/30.
- 8811300099 Forwards SER accepting util 840803,850520 & 880512 & 0811 responses to Generic Ltr 88:28,ttem 2.1 (Parts 1 & 2) re equipment classification & vendor interlace programs
 PAULSON,W.A. Project Directorate IV. 89/11/18. DEUDENS,J.C. Gu'l States Utilities
 Co. 4pp. 47696 336-47896:351.
- -8811300105 SER accepting util responses to Generic Lir 83-28,ttem 2.1, Part 1 re reactor trip sys components.
 * NRC - No Detailed Affiliation Given, 88/11/18, 2pp, 47696,340-47696;341.
- -8810120268 "Tochnical Evaluation Rept Conformance to Generic Lir 93-28 Item 2.1 (Part. I) Equipment Classification River Bond Stellon Unit 1." MCCORMICK, R.D. EG&G Idaho, Inc. (subs. of EG&G, Inc.). MCCORMICK, R.D. Idaho National Engineering Laboratory. FIN D-6001. EGG NTA-8142. 89/07/31. NRC No Detailed Affiliation Given. 8pp. 47696 342-47696 349
- --8812060066 SER accepting util response to Generic Ltr 83-28,ffem 2.1, Part 2 re vendor interface programs for reactor frip sys components

 * NRC No Detailed Affiliation Given 88/11/18, 2pp. 47696:350-47606.351.
- 8811300040 Forwards Amend 31 to License NPF-47 & safety evaluation. Amend revises Tech Specs to allow single recirculation loop operation. PAULSON,W.A. Project Directorate IV. 88/11/22 DEDDENS,J.C. Guil States Utilities Co. 4pp. 47876:054-47876:104.
- -8811300043 Amend 31 to Elecase NPF-47, revising Tech Specs to allow single recirculation loop operation. CALVO,J.A. Project Directorate IV. 88/11/22, 36pp. 47676 058-47676.093.
- -8811300046 Safety evaluation supporting Amend 31 to License NPF-47.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/22, 9pp. 47676.094-47676:102.
- --8811300048 Notice of Issuance of Amend 31 to License NPF-47.Amend revised Tech Specs to allow single recirculation toop operation. PAULSON,W A. Project Directorate IV. 88/11/22, 2pp. 47676:103-47676:104.

- 8812090003 Forwards notice of consideration of issuance of amend to Liconse NPF-47 & apportunity for hearing Amend dolotes 1 canso Condition 2.C (4),Attachment 2,Ilem PAULSON,W.A. Project Directorate IV 88/11/22, DEDDENS,J.C. Gulf States Utilities Co. 3pp. 47782 347-47782.353
- -8812090004 Notice of consideration of Issuance of amend to License NPF-47 & proposed NSEC determination & apportunity for hearing Amend coletes Licenso Condition 2 C (4), Attachment 2, Item 4. CALVO, J.A. Project Directorale IV. 88/11/22 4pp. 47782 350-47782 353.
- 8811280048 Generic Lir 68:20 to all licensees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnorabilities Svc list
- CRUTCHF-ELD.D. Associate Director for Projects (Post 870411), 88/11/23. Consolidator Edison Co. of New York, Inc. 81pp. 47728 393-47729.024
- 8811300056 Advises that NRC concurs w/ond EGG-NTA-7301, "Conformance to Generic Ltr 83-28 from 2.2.1 Equipment Classification For All Other Safety-Related Components: Fiver Bend 1."
 PAULSON,W.A. Project Directorate IV. 89/11/23. DEDCENS,J.C. Gulf States Utilii ds.
- Co 4pp. 47702 148-47702.151
- -8811210007 *Conformance to Genetic Lit 83-28,flort, 2-2.1 · Equipment Classification for All Other Safety-Ro's and Component's River Bend 1.1" UDY, A C. EG&G 'datho, Inc. (subsolid 686, Inc.). FIN D-6001. EGG NTA-7301. 887-10731. NRC · No Deat led Affiliation Grzen. 16pp. 47702-152-47702-166
- 8811300241 Forwards safety evaluation accepting u.t.t. 840803.850520 & 870922 re-sponses to Generic Ltr. 63.28, Item 4.5.2 re-reactor trip systrollability & online testing PAULSON,W.A. Project Directorate I.4. 88/11/23 CEDDENS,J.C. Gulf States Utilies Co. 4pp. 47680-116-47693.120. -8811300242 Safety evaluation accepting responses re-flem 4.5.2 of Generic Ltr 83-28 re reactor trip sys reliability chiline testing. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/23, 1p.
- 47680 120-47680 120 8812050127 Forwards environ essessment 8 finding of no significant impactire 980812 application for amend to Liconso NPF-47, revising Tech Specs to reduce min water coverage for inediated fuel 8 control rods during handling PAULSON,WIA Project Directorate IV. 88/11/29. DEODENSUIC Gulf States Utilinos Co. 3pp. 47734-031-47734-008
- -8812050141 Environ assessment & Ending of no aignificant impact re 880812 application Amend revises Tech Specs 4.9.6.1.c. & 4.9.6.2.c. to permit descreating min water coverage for mad sted fittel & control rods during hand ing CALVO, A Project Directorate IV. 88/11/29 Spp. 47734.004.47734:008
- 8812060163 Forwards response to 881003 request for addlinter 683805 application for amend to License NIF-47 to after expending wifeedwafer heaters out of see BOOKER, J.E. Gulf Steles Utilities Co. 89/11/30, Document Control Branch (Document Centrol Desk), 4pp. 47741 214-47741 217.
- 8812060172 Forwards response to W Paulson 881114 telcon request re Toch Spec 37 4.6 for primary conteinment integrity requirements during reflueling. DEDIENS, IC Gur States UI it as Co. 88/11/30 Document Control Dosk) 9pp. 47743.115 47743.123
- 8812060154 Updates util 850114 response re status of const completion & testing at tuel load Bidgi roof & sterm drain activities not rolated to plant startup or operations & scheduled for completion prior to first revier
- ment Control Desk), 35p. 47743:155-47743:157 8812210204 Forwards Amend 32 to License NPF-47 & safety evaluation. Amend re-
- duces min water coverage above spentitue' assembly in storage pool & above irradiated control red during spentituel & tradiated control red Panding operations PAULSON,W.A. Project Directorate IV. 88/12/13. DEDDENS,J.C. Quil States Utilities Co. 4pp. 47876 233-47876:248
- -8812210208 Amend 32 to Licenso NPF-47 reducing min water coverage above sport fuel assembly in storage pool & above tradiated control rod during sport fuel & liradiated control rod harding operations. CALVO, J.A. Project Directorate IV. 88/12/13. 7pp. 47876:237-47876.243
- --8812210209 Safety evaluation supporting Amend 32 to Licenso NPF-47.
 Project Directorate IV 88712713, 3pp. 47876 244-47876:246.
- --8812210210 Notice of issuance of Amend 32 to License NPF-47, reducing min water coverage above spent fuel assembly in storage pool 8 above irradiated control red during spent fuel 8 irradiated control red handling PAULSON, W.A. Project Directorate IV, 88/12/13, 2pp. 47876:247-47878.248.
- Q. Inapaction reports, IE Bulletins & correspondence
- 8811220457 Ack receipt of 880519 for informing NRC of steps taken to correct violations noted in Insp Rept 50-458768-21.

 CALLANI, J. Region 4, Old of the Director, 88/11/17, DEDDENS, J.C. Gulf States Utities Co. 2pp. 47875-313-47675-327.
- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges" Svc list each CUNNINGHAM, R.E. Division of Industrial & Medical Nuclear Salety (Post 870729) 88711722: Consolidated Edison Co. of New York, Inc. 99pp. 47708-255-47708-257.
- 8811180467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests." Svc list enct. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/11/22. Consolidated Edson Co. of New York, Inc. 101pp 47703:042-47708:142.
- 8811300191 Responds to NRC 881018 ltr re-violations noted in Insp Rept 50-458/88-19 Corrective actions training conducted to caution all lechnicians on requirements for rollowing steps in secuence prescribed in procedures DEDDENS.J.C. Gulf States Unities Co. 88/11/23. Document Control Branch (Document Control Disk) 4pp. 47678 026-47678031.

- 8812060229 Forwards supplemental response to violations noted in this item 50, 4597 88-18 Corrective actions for standing noted issued for STP 402-501 to need actual testing requirements for standing the treatment sys Afficiant end. DEPDENSIJC Gull States Unifices Co. 88711/30. Document Control Planch ((Xxxx) ment Control Desk), 6pp. 47743-001-47743-006.
- 8812060310 Forwards supplemental response to we'alion noted in Insp.Rcpt.50.4555 88.09 Response withheld (red.10CFB73.21) BOOKER,J.E. Gulf. States Unities Co. 88711730. Office of Nuclear Beactor. Regulation, Director (Post 870411), 1p. 47741.062-47741.062
- 8811290030 NRC Info Notice 88:093, "Tulotherapy Events" Svc Lst encl CUNNINGHAM,Rt.E. Division of Industrial & Modicul Nuclear Saloty (Fost 670725) 88/12/02 Consolidated Edward Co. of New York, Inc. 112pp. 47811.10.) 17811-215
- 8811290538 NRC Info Notice 88-994, "Potentially Undersized Valve Actigtors " Syc Fsi ROSSICE Division of Operational Events Assessment (Post 970111) 68/12/62 Consolidated Ed.son Co. of New York, Inc. 121pp. 47708.143 47709.251
- 8812130139 Forwards Insp Flopt 50-458788-25 on 881031-1104 No violations on device CALLAN,L.J. Region 4, Ofc of the Director (18/12/02 DEDDENS,J.C. Galistates Us-ifies Co. 2pp. 47784 331-47794.343
- -8812130141 Insp. Rept. 50.459788-25 on .881031-1104.No volutions or dicinatives nated Major largest inspected followup on provides linsplandings, both is , Part. 21 repts, determine implementation scram discharge vol capability. MURPHY, ME. B.MDPHY, H.F., MCNEILL, W.M. Boglon 4, Ofc of the Orestor 897111/23 ttpp. 47794,333-47794,343
- 8812140066 Forwards Insp. Ropt 50:458/88/23 on 880918-1105 8 notce of websited CALLANUU Region 4, Otc of the Director, 88712707 DEDDENS,J.C. Gut States Utilities Co. 2pp. 47799 213:47709:231
- -8812140081 Notice of violation from hep on 880018-1105 Violation noted for tare № follow maint work order procedures Region 4, Ofc of the Director, 80/12/07, 2pp. 47799 215-47799 216
- --8812140083 Insp. Ropt. 50.458/68-23 on .080018-1105.Vicialions note: Mayor excessingpoted licensed action on provious unsp. findings. 8.NRC Notice 69.040 successive test & main observed ons, operational satisfy vortication & security. FORDE J. JONES.W.B. CONSTABLE, G. L. Hugion 4, Ofc. of the Ouerts. 8.0712.33 15pp 47709.217-47709.231.
- 8812020287 NRC Info Notice 88 095, "Inadequate Procurement Regularized by Licensoes on Vendors." See tist enci.
 ROSSIC E. Division of Operational Events Assessment (Post 870411) 69712736
 Consolidated Edison Co. of New York, Inc. 112pp. 47807-191-47807-502
- 8812150076 Ack reculpt of 881123 lir informing NRC of steps taken to corect 포함하는 of noted in Insp Rept 50-458/88-19 on 881016.
 CALLAN, U.Roglon 4, Ofc of the Oirector, 88712709, DEDDENS, I.C. G로드States Utilities Co. 2pp. 47824.177-47824 182
- 8812150112 Ack race at at 800930 & 1130 litra informing NRC of steps being to consci ATAINSTITE ACK TODA DE OF OURSON OF THAT THE INFORMING PARTS TO CAPACI Wollshors noted in Insp. Rept 50-459/89-18. CALLANL J. Region 4, Ote of the Danctor 88/12/09. DECIDENS JC. Get State U2 (608 Co. 2pp. 47826 255-47028.258)
- 8812220073 Responds to wetations noted in Insp. Rept. 50.459/98.22 on 8.86.4.29.0915 Corrective actions Med Request MR 88-0300 issued to provide control tasks with tistion sys local heater operability indicator I ght Atlictivat ericl. BOOKER, J.E. Gulf States Utilizes Co. 88/12/15. Document Control Date: (Case) ment Control Desk). 7pp. 47014.041-47014:047.

R. Periodic operating reports & related correspondence

- 8812020250 "Rivor Bond Station-Unit 1 Semilarmual Radioactive Effluori Refease Erg Addordum" "W/881123 IIr. FANTACCI.CL , CARGIEL,E M , BOOKER,J.E. Gulf States Unities Co. Eff. おいと 155 47716 323-47718 320

 - 8811300231 Forwards revised monthly operating rapt for Sept 1980 for Poor 1994 \$1900 Unit 1 Rept revised to correct forced outage rate duration for Shabban 88 14,6 ration of Power Roduction 88-15 & duration of Shaldown 88-16 BOOKER, JE Gulf States Unities Co. 88/11/22. Document Control Branch (Comment Control Desk) 1p. 47677:284-47677:288.
 - ~8811300272 Revised monthly operating ropt for Sept 1080 for Rever Bond Statistin U

COLE,R E. Gulf States Utilities Co. 88/09/30, 4pp. 47677 205 47677 203

- S. Reportable occurrences, LERs & related correspondence
- 8811300318 LER 88 021-01.on 880906 reactor scram occurred Caused by feet to a re-trall grounding transformer due to alray call shorting out high განე transformer Transformer replaced & protection of terminations under 1905 განების 881123 lt ENGLAND, L.A., BOOKER, J.E. Gulf. States. Util hos. Co., 88/10/05, 5(£, 476.37.2)
- 8811300267 LER 88-022-02 on 880906,1011 & 22,fuol bidg ventilation treatment to a set to started due to high radiation alarm.Caused by background activity 652-10 radia radion & previously contaminated ductwork Work request initiated W761121 by ENGLAND, A., BOOKER, J.E., Gulf States Utilities Co. 88711721, 519, 47607.247697.266.

- 8811300286 LER 88-024-00.on 881027,ESF actuation occurred resulting in Isolation of RWCU sys Caused by cross tripping phonomenon of tomp switches & procedural error Temporary change notice prepared to leave switches in bypass position W/ 681123 ltr. ENGLAND, L.A., BOOKER, J.E., Gulf, Statos, Utilities, Co., 88/11/23, 4pp., 47681:043-
- 8812010232 LER 88-008-01 on 880219 reactor shutdown required by TS due to reactor recirculation pump motor trip Causad by moleture intrusion from leaking sec water valve Leaking valve tepaired & termination cabinot cleaned & dried W/881123 LERGLAND, LA, BOOKER, JE. Gulf Stotes Utrities Co. 89/11/23, 4pp. 47703 201-
- 8812010235 Special reption 880825 & 0906,two injections of ECCS occurred during un-related but similar reactor scrams Caused by reactor scram Initiated by turbine control vatre fest closure.

 BOOKER,J.E. Gulf States Utilities Co. 88/11/23. Document Control Branch (Document Control Desk). 3pp. 47703:303-47703:305

V. Coerator Examinations

8811300382 Confirms operator license exame at site during was of 890213 & 20,per telcon.Util should furnish approved ref mait listed in encl by 881213 Rule & guidance 8 exam requirements also encl. CALLAN.L.J. Region 4, Oic of the Director. 88/11/18 DEDDENS.J.C. Gulf States Util-ries Co. 11pp. 47674.092-47674:102

DOCKET 60-460 WPPSS NUCLEAR PROJECT, UNIT 1

A. Application/construction stage documents & correspondence

- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vurnerabilities. Svc 1st CRUICHFIELD.D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp 47728:303-47729:024
- 8812150225 Discusses MPA B-61 requirements for Units 1 & 3.per Generic Ltr 63-28, "Regulred Actions Based on Generic Implications of Salom ATWS Events." Reactor trip breaker maint & tranding Issues should be addressed as plant-specific Issues. BRADFUTE, J.O. Project Directorate V. 89/12/05. VISSING, G.S. Standardization & Non-Power Reactor Project Directorate. 3pp. 47826:295-47826:297.

DOCKET 50-481 CLINTON POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8812070081 Revised emergency plan implementing procedures including Rev 3 to PR-02, "Joint Public Info Ctr Operations," Rev 3 to PR-03, "Preparation of IPC Emergency Info" & Rev 3 to PR-04, "Dissemination of IPC Emergency Info" PAULSON.8F., HALLSP., MADISON.8. Illinois Power Co. 88/11/28. 69pp. 47748 119 47748 186

K. Utility Final Safety Analysis Report (FSAR) & amends

- \$812190196 Forwards updated FSAR for Byron Station Units 1 & 2 & Braidwood Station
- Units 1 & 2.
 HUNSADER,S.C. Commonwealth Edison Co. 88/12/14. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 47880.001.47889:158.
- -8812190347 "Geologic Reconnaissance of Clinton & Braidwood Reactor Excavations" SKROVE,J.W. Division of Site Safety & Environmental Analys's. 76/04/27. 3pp. 47983:094-47993:096.

M. Antitrust correspondence

- 8811300293 Forwards FR notice of proposed amend to License NPF-62 re merger of Soyland Power Cooperative, Inc & Western Illinois Power Cooperative, Inc & request for
- comments on antitrust issues.

 THOMAS,C.O. Policy Development & Technical Support Branch (Post 870411). 88/11/17. NRC No Detailed Affiliation Given. 2pp. 47877:053-47877.084.
- -8811390295 Notice of proposed amend to License NPF-82, reflecting merger of Soyland Power Cooperative, Inc & Western Illinois Power Cooperative, Inc & request for comments on antitrust issues.

MULLER, D.R. Project Directorate III-2, 88/11/22, 3pp. 47877:055-47677:064.

P. Operating license stage documents & correspondence

- 5811300440 Ack receipt of 881021 ltr & attachments describing actions taken re-potental tampering of nonately related valves. Util investigation, analysis & corrective actions thorough & appropriate to address issue.

 NORELUSCE. Region 3, Otc of the Director. 88/11/17. GERSTNER,W.C. Hinols Power Co. 2pp. 47681.040-47681.041,
- 8611230269 Requests FR publication of notice of Issuance of Amend 12 to License NPF-62 Amend deletes requirement for chloring detection sys. STEVENS.J.A. Project Directorate III-2. 88/11/21. NRC - No Detailed Alhi.atlon Given. 2pp. 47632-069-47652-070.

- 8812070130 Requests FR publication of notice of consideration of issuance of amend BD518 request or recorded NSHC determination & opportunity for hearing on 880518 request reliev to Tech Spec Table 3.3.7.5-1, "Accident Monitoring "STEVENS,J.A. Project Directorate III-2, 88/12/01, NRC - No Data led Africation Given. 8pp 47748:355-47748 360
- 8812070181 Requests FR publication of notice of consideration of issuance of amend to License NPF-62 & proposed NSHC determination & apportunity for hearing on 880205 request to incorporate startup test program data into Tech Specs STEVENS, J.A. Project Directorate III-2, 88/12/01, NRC No Detailed Affiliation Given 5pp. 47748-303-47746-307
- 8812070191 Requests FR publication of notice of consideration of issuance of amend to License NPF-82 & proposed NSHC determination & eppartumity for hearing on 800205 request re-doleron of License Condition 2 C.6.
 STEVENS.JA Project Directorate III-2, 88/12/01 NRC No Detailed Affiliation Given. 5pp. 47747 084,47747.088
- 8812070215 Requests FR publication of notice of consideration of issuance of amend to License NPF-62 & proposed NSHC determination & opportunity for hearing on 880205 request re-deletion of note attached to CHANNEL CHECK requirement. STEVENS.J.A. Project Directorate II: 2. 88/12/01 | NRC No Detailed Affiliation Given 6pp 47746:263-47746-268
- 8812070253 Requests FR publication of notice of consideration of Issuance of amend to Licence NPF-82 & proposed NSMC determination & apportunity for hearing on 880518 request relevaling Tech Spec Soction 4.1.3.3.b.1.b. STEVENS.J.A. Project Directorate III.2.88/12/01. NRC - No Dotalted Afrillation Given 5pp. 47748 077-47748 GB1.
- 8812080008 Requests FR publication of notice of consideration of issuance of amond to License NPF-82 & proposed NSHC determination & opportunity for hearing on 890518 request re-channel configuration for main steam line STEVENS,J.A., Project Directorate III-2 88/12/01. NIRG No Dataried Affidation Given. 5pp 47763:157-47753 161.
- 8812080083 Requests FR publication of notice of consideration of issuance of amend to License NPF-62 & proposed NSRC determination & opportunity for hearing on 880518 request to Tech Spec 4.11.2-1 to Include several changes re Note C. STEVENS J.A. Project Directorate III-2. 88/12/01. NRC No Detarted Affiliation Given. 8pp. 47753:117-47753 122
- 8812140178 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Matts & Impact on Plant Operations" to comply w/Rev 2 to Reg Guido 1.99 Neutron desimator will be removed during first refueling outage. HOLTZSCHER,DL. It mols Power Co. 88/12/206. Document Control Branch (Document Control Desk) 3pp. 47800 201-47800 203.
- 8812130294 Summary of 881207 meeting w/utils & DEVONRUE re use of HPCS diesel generator as afternate ac power source to satisfy 10CFR50 63 for BWR/6 plants. TAMP.S. Project Directorate 1-4. 18pp. 47796 017-47796 034
- 8812210089 Submits util interpretation of Tech Spec provisions re-operability of sys pro-viding support to safety sys Examples of consequences resulting from interpretation of operability which would restrict lumiting conditions for operation and IALL_D.P. Illinois Power Co. 88/12/09. Occurrent Control Branch (Document Control (Desk), 5pp. 47880 348 47880 352.

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges " Svc list encl.
 CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729).
 88/11/22. Consolidated Edison Co. of New York, Inc. 89pp. 47708:255-47708:257.
- 8811160467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Taste." Svo I stienci. ROSSI,CE. Dwiston of Operational Events Assessment (Post 870411). 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708:142.
- 8811300168 Informs that insplot PMS records Indicated that util purchased Class IE components or sizes for plant.PMS certifications covering safety-related electrical equipment supplied to I censees not adequately documented MULLER.D.R. Project Directorate III-2 88/11/23. HALL,D.P. Illinois Power Co. 6pp. 47671:011-47671.016.
- 8811290030 NRC Into Notice 88-093, "Teletherapy Events." Svc list enct. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 6811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators," Svc list enci. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 8B/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812140235 Forwards Safety Insp Rept 50-461/88-28 on 881114-17.No violations noted insp conducted in response to 881114 event which resulted in lose of main Nansformer due to fire
 KNOP.R.C. Region 3, Ofc of the Director, 88/12/07. GERSTNER,W.C. Illinois Power
 Co. 2pp. 47800 219 47800.233.
- --8812149238 Safety Insp Rept 50-461/88-28 on 881114-17.No violations noted Melor areas inspected 881114 event re loss of main transformer due to fire resulting in loss of all nonvital actoads in plant Some procedural weaknesses noted. COOPER,R.W. Region 3, Ofc of the Orector. 88/12/06. 13pp. 47800.221-47800:233.

174 DOCKETED ITEMS

- 88 12020287 NRC Into Notice 89 095, "Inadequate Produrement Requirements imposed by Licensees on Vendors." Svoltst end.

 ROSSI,CE Division of Operational Events Assessment (Post 670411) 89/12/08.
 Consol dated Edican Co. of New York, Inc. 112cp. 47807:191-47807:302
- 8812190274 Responds to violations noted in Insp. Rept 50-461/88-23. Corrective actions Procedure 3505-01 will be rowsed to incorporate results of review. HOLTZSCHER,DL. II nois Power Co. 98/12/09 DAVIS,A.B. Region 5, Old of the Director 5pp. 47851-245-47851-249.
- 8812200288 Forwards inservice inspiritogram Relef Request 2008,Rev. 2, involving re-quests to after leak rate testing requirements for containment isolation & oxcess flow

HOLTZSCHER, D.L. Hindis Power Co. 88/12/13 Cocument Control Branch (Document Control Desk), 14cp. 47867;320-47867;533

R. Portodic operating reports & related correspondence

8812190229 Monthly operating rept for Nov 1988 for Cinion Power Station W/881215 HOLTZSCHER, D.L. II no.s Power Co. 88/11/30, 6pp. 47855,023-47865-028.

S. Reportable occurrences, LERs & related correspondence

- 8812020228 LER 86 025-00 on 680728 partial loss of feedwater (FW) heating led to Train A FW heating sys isolation Causard by inappropriate sorting of FW heater fevel controllers Levot controllers adjusted & procedure te
- 8812050049 LER 89-024-00-on 881019/faiture to recognize inoperable damper impact results in inoperable control room ventilation sys initiation of Tech Spec 3-0.3 shutdown Caused by personnel error Ventilation sys clarified WV881130 ltr SCHALLERRE, HOLTZSCHERDL III nois Power Co 88/11/30 8pp 47733-299-47733:306
- 8812060279 LER 88-022-01.on 880901.automatic initiation of HPCS sya injection of water into reactor occurred Caused by false low reactor pressure vessel water 1898 signat Technicians briefed on evert.W/68130 lir CAMILLERI,T.J., HOLTZSCHER,O.L. II. no.s. Power Co. 88/11/30 6pp. 47734:339-47734:344
- 8812140231 LER 88-028-00 on 881111,main power transformer fau't reguits in turbine generator injo & reactor scram Caused by Internal fault on high voltage side of main power transformer Main power transformer than power transformer (*C. replaced W/681208 lt. SCHALLER,R.F., HOLTZSCHER,D.L. III no.s. Power Co. 89/12/08. 5;p. 47800-339. 47800 343
- 8812200101 LER 88 026-00 on 881109,air identified flowing into secondary containment prossure boundary Caused by absence of loop seal traps in floor drain sys & Inoperably of loop seal trap in pressure boundary W/881209 ltr.

 SCHALLER,R.F., HOLTZSCHER,D.L. Ill no.s Power Co. 88/12/09. Epp. 47864:225-
- 47864 230 6812220133 LER 88-027-00 on 681110 identified fature to track implementation of design change removing disk from bypose ochaust line tendering Dwill ideast generator inoperable Caused by personnel fature Disk removed W/881213 It.
 FREEMAN,R.D., HOLTZSCHER,D.L. Timois Power Co. 88/12/13 Spp. 47900:204-
- 47900 208

V. Operator Exeminations

8812150128 Forwards rev to requallication training program, for review approval Proposed Changes provide (dinoral program) improvements & support requirements of 10CFR55
HOLTZSCHERD. L Illinois Power Co. 88/12/06 Document Control Branch (Document Control Desk), 13pp. 47830 240-47830 252

DOCKET STN-50-470 CESSAR SYSTEM 60

A. Application/construction stage documents & correspondence

- 8811300491 Forwards Advanced Reactor Severe Accident Program Topic Paper Set 6, "Development of Severe Accident Mgt Program," for roview SCHERER, A.E. Combust on Engineering, Inc. 88/11/11, CRUTCHFIELD,O. Associate Director for Projects (Post 870411), 31pp. 47680.222-47680.252.
- 8812050189 Noblication of 881220 meeting w/C-E in Rockwile,MD to discuss selamic issues involved in containment dosign for CESSAR-DC Sys 80e re-so-t/structure interaction phases. VISS:NG G.S. Standardization & Non-Power Reactor Project Orectorate 88/11/28.
 MILLER.C.L. Standard zation & Non-Power Roactor Project Directorate 4pp.
 - 47732:300-47732 303
- 8812150015 Forwards additinto re CESSAR DC, Chapters 5 & 9,per GS Vissing 880803
- SCHERERA.E. Combustion Engineering, Inc. 88/12/07. VISS.NG.G. Standardization & Non-Power Reactor Project Directorate. 34pp. 47802:329-47802:362.
- 8812200181 Notifies of relocation of C-E nuclear licensing dept, Washington nuclear operations ofd from Bathesda to Rockylle,MD New address & telephone numbers pro-
 - NOSCI.

 BRINKMAN,C.B. Combustion Engineering, Inc. 88/12/13, VISSING,G. Standardization & Non-Power Reactor Project Directorate. 1p. 47806 293-47906 293.
- 8812220242 Forwards request for additinto re ARSAP Topic Paper 3, including Item 3.1, "External Events," Item 3.2, "Success Criteria & Mission Time" & Item 3.3, "Accident

- 8812220286 Forwards requests for addition to Amend D to Chapters 3.4, 5 & 6 & CESSAR-DC.Sys 80 + Response requested within 90 days from receipt of 1. VISSING G S. Stendardzation & Non-Power Reactor Project Directorals #8/12/16 SCHERER,A.E. Combuston Engineering, Inc. 8pp. 47900 203-47900 21
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 8812210027 Responds to NRC request for addl info on steam generator lebe rupture analysis for Sys 80 design.per SER confirmatory issue Dose methodology & rosolos conservatively account for tube uncovery.
 SCHERER,A.E. Combustion Engineering, Inc. 88/12/07 VISSING,G.S. Standarders tign & Non-Power Reactor Project Directorate 8pp. 47880,340-47880;347

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

F. Security, medical, emergency & fire protection plans

- 8611300300 Revised emorgency plan implementing procedures,tacturing Emorgency Procedure Change Notice 01-2.1-6-1 to Rev 6 to EPP 01-2.1,Rev 9 to EPP 02-1.2,Rev 5 to EPP 02-1.4,Rev 0 to EPP 03-5.2 & EPP 03-5.3,Rev 2 to EPP 03-7.1,Wv931121 BAILEY, J.A. Wolf Creek Nuclear Operating Corp. 88/11/21 78pp. 47577.144 47677 221
- P. Operating Ricense stage documents & correspondence
- 8812020178 Advises that time for Commission to review Decision ():> 88-14 expired Commission declared review Decision became lineal agracy action on 880816 Served on 880928.

 CHILK,S.J. Office of the Secretary of the Commission #488 7145, 89709723 GARDE,B.P. Government Accountability Project 1p. 47680.047-47680.047
- 8811280185 Application for amond to Licenso NPF-42 revising Tech Spec 6.5.1.2 re
 - plant safety review committee composition to add manager ructear plant angino comp Wolf Creek as committee member Fee pald BAILEYJA. Wolf Creek Nucoar Operating Corp. 88/11/21. Document Corts: Branch (Document Control Dosk). 4pp. 47656.208-47656.303
- -8811280187 Proposed Tech Spac 6.5.1.2 adding manager nuclear plant cryindering Wolf Creek to plant safety review committee. *Wolf Creek Nuclear Operating Corp. 88/11/21, 2pp. 47656 302-4/656 J03.
- 8811280048 Generic Ltr 88:20 to all licensees holding OLs & CPs for nucleit power reactor facilities no individual plant exam for severe accident vulnerations Syc. 1st CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 88711/23 Consolidated Edison Co. of New York, Inc. 81pp. 47728-303-47729-024
- 8811300059 Summary of 881117 meeting w/util to decision to replace rediction control assemblies at plant PICKETT.D.V. Project Directorate IV. 88/11/25. CALVO.J.A. Project Directorate IV. 8pp. 4768-303-47688-308.
- 8812060043 Requests NRC authorize use of ASME Code Case N.460, "Agenta's \$ am Coverage for Class 1 & Class 2 Welds, Section XI Div 1," per 10CF1150 554(4)(3) for
- plant F6e paid WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 88/11/28. Documert Contact Branch (Document Control Dosk). 2pp. 47732.072-47732.073. 8812020232 Forwards environ assessment & finding of no significant impactive 890226 request to revise emergency vanilation/ exhaust sys Tacti Specs PICKETT,0.V. Project Directorate IV. 88/11/29. WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 2pp. 47722.114.47722-122.
- -8812020234 Environ assessment & linding of no significant impact to proposed amond to Ucense NPF-42 revising Toch Space TS 3/4.7.6,3/4.7.7 & 3/4.9.13 & Toch Space Bases B 3/4.7.7 & B 3/4.9.13. CALVO, J.A. Project Directorato IV. 88/11/29, 5pp. 47722-118-47722-122
- 8812090224 Requests that util address Generic Ltr 88-17 to loss of DHR duing mon power operation Industry response to Generic Ltt 87-12 delictiont in areas of greven-tion of accident industries a mitigation of accidents
 MURLEY.T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 89/12/
- 8812090302 Forwards Amend 22 to License NPF-42 & safety evaluation. Amend revises Tech Specs (2/4.7.6,3/4.7.7,3/4.9.13 & Bases B 3/4.7.7 & B 3/4.9.13 to emergency axhaust sys Notice of issuance encl. PICKETT,D.V. Project Directorato IV. 88/12/05 WITHERS,B.D. Wolf. Crook Nuclear Operating Corp. 4pp. 47786.032.47786.036.
- --9612090309 Amend 22 to Liconse NPF-42,revising Toch Specs 3/47-6, 3/4-9.13,Bases B 3/4.7.7 & B 3/4.9.13. CALVO,J A. Project Directorate IV. 88/12/05. 13pp. 47786.036-47786-048.
- -8812090311 Safety evaluation supporting Amend 22 to License NPF-42.

 Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/05 ويولي 47788.049-47786.054
- --8812090318 Notice of Issuance of Amend 22 to License NPF-42 revising Tuch Space 3/4.7.6,3/4.7.7,3/4.0.13 & Bases B 3/4.7.7 & B 3/4.9.13 re emergency enhaust sys PICKETT,D.V. Project Directorate IV. 88/12/05 2pp. 47786
- 8812180030 Forwards Amend 23 to License NPF-42 Amend rovises Tech Specs & corresponding bases necessary for Cycle 4 operation. Changes increase botton concentrations in refueling water storage tank 8, accumulators Safety evaluation enci. PICKETT.DV. Project Orrectionate IV. 89/12/05. WITHERS.B.D. Wolf Creek Nuclear Operating Corp. 4pp. 47869.036-47869.070.

- -8812160033 Safety evaluation supporting Amend 23 to License NPF-42
 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/12/05 4pp 47869 067-47869 070.
- 181220183 Forwards portions of this to utilis utilizing hafnium rod cluster control assembles & synopsis of info provided to NRC in 881123 felician Potential safety Issue concerns mechanizat functionality of rod cluster control assembles.

 JCHNSCNW.J. Westinghouse Electric Corp. 88712708 ROSSI, C.E. Division of Operational Eventa Assessment (Post 870411) 13pp. 47892 181-47892.193
- IS12160023 Forwards Tech Spec Pages 3/4 1-11 & 3/4 1-12 orbitted from Amend 23 to License NPF-42 Issued on 881205 which revised Tech Specs & corresponding beses necessary for Cycle 4 operation. PICKETT, D.V. Project Directorate IV. 88/12/13 WITHERS, & D. Wolf Crosk Nuclear Operating Corp. 4pp. 47835:127-47835:133
- -8812180025 Tech Spec Pages 3/4 1-11 & 3/4 1-12 to Amend 23 to License NPF-42 inadvertenily omitted from amend issued on 881205. Tech Specs concern reactivity control sys, borated water course shutdown & broated water sources operating * Project Directorate IV: 88/12/13, 3pp. 47835.131-47835.133.
- 1812210119 Forwards requests for rolled from certain requirements defineated in Section XI of ASME Botler & Prossuro Vosset Code Fee paid WITHERS.B.D. Wolf Creek Nuclear Operating Corp 88/12/13 Document Control Branch (Document Control Desk). 10pp 47869.012-47880.021
- 8812210003 Advises that u.l. 881128 request for use of ASME Section XI Code Case N. 480, "Alternate Exam Coverage for Class 1.8 Class 2 Webls. Section XI D.v.1" acceptable CALVO.J.A. Region 4, Oic of the Director 88/12/14 WiTHERS.B.D. Wolf Creek Nuclear Operating Corp. 5pp. 47888-080-47888-084

Q. Inspection reports, IE Bulletins & correspondence

- 8811290202 Advises that 880708 & 0929 responses to NRC Bulletin R8-004 fulfill requirement in responding to bulletin PICKETT,D.V. Project Directorate IV. 88/11/17. WITHERS,B.D. Well Crook Nuclear Operating Corp. 4pp. 47651:255-47651:258.
- 8911290328 Advises of cancellation of Insp Rept 50-482/88-31 instead of inadvertently cancelled Insp Rept 50-482/88-33. CALLAN, L. J. Region 4, Olic of the Director, 88/11/18, WITHERS,B D. Wolf Creek Nuclear Operating Corp. 2pp. 47865:110-47865:111.
- 8811300404 Responds to NRC 881021 ltr re violatione noted in Insp Rept 50-482/88-25 Corrective actions Procedure HPH 04-077 being rowsed to provide clarification of set up following litter change out & require togging background & afairs satting 8A*LEV_3A. Wolf Creek Nuclear Operating Corp. 88/11/1721. Document Control Branch (Document Control Desk). 4pp. 47677:290-47677:293.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svo list encl CUN-INDRHAM, R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 68/11/22. Consolidated Edison Co. of New York, Inc. 90pp. 47/08 255-47/08 257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests." Syc list enci.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/11/22 Consolidated Edison Co. of New York, Inc. 101pp 47708:042-47708:142
- 8811290402 Informs of changes made in motor-operated valve program developed to meet requirements of NRC Bulletin 85-003. Limitorque motor actuator characterizer will be used to test valves rather than MOVATS signature analysis technique. BAILEY,J.A. Wolf Greek Nuclear Operating Corp. 80/11/22. Document Control Branch (Document Control Desk). 2pp. 47930:256-47930:257.
- 4812050153 Responds to NRC 881028 fir re violations noted in Insp Repl 50-482/88-24.Corrective actions roubleshooting activities on four-way valve in progress, Mode 3 to two checklists revised & surveillance procedure changed. WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 88/11/28. Document Control Branch (Occument Control Deek). 5pp. 47732:295-47732:299.
- 8812050256 Responds to NRC 881019 ltr re violations noted in Insp. Repl. 50-482/68-20 Concetive actions work stopped, vendor contacted & heating limitations added to governing work request by rev. WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 88/11/30 Document Control Branch (Document Control Desk). 18pp. 47730:309-47730.326.
- 8812060253 Ack receipt of 871211 & 881021 tirs informing NRC of steps taken to correct violation noted in Insp. Rept 50-482767-23.

 CALLAN,L. J. Region 4, Ofc. of the Director. 88711/30. WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 2pp. 47744:323-47744:325.
- -8810280324 Forwards Suppl 1 to Special Ropt 87-007.Suppl withhold (rel 10CFR73,21). Will THERS.B.D. Wolf Creek Nuclear Operating Corp. 88/10/21. Document Control Branch (Document Control Deak). 1p. 47744:326-47744:325.
- 8812060269 Ack receipt of 881114 ftr informing NRC of steps taken to correct violations noted in Insp Rept 50-482/88-29. CALLAN,LJ. Region 4, Ofc of the Director, 88/11/30, WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 2pp. 47763.001-47753:003.
- 8812050178 Responds to NRC 881031 itr re-violations noted in Insp Rept 50-482/88-28 & problems identified w/PASS.Corrective actions tochniciens involved tested more frequently on failed parameter & tracked for analytical performance WiTHERS.B.D. Wolf Creek Nuclear Operating Corp. 88/12/01. Document Control Branch (Document Control Desk), 4pp. 47732-304-47732-307.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events." Svc list encl. CUNNINGHAM,R.E. Division of industrial & Medical Nuclear Safety (Post 870729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811.103-47811.215.
- 8811290538 NRC Info Notice 88-084, "Potentially Undersized Valve Actuators." Svc list soci. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.

- 8812140060 Ack recopt of 881026 ftr informing NRC of steps taken to correctly olations noted in Insp Rept 50-482788-22.
 CALLANJ, I. Region 4, Old of the Director 88/12/07 WITHERS,B D. Wolf Creek Nuclear Operating Corp. 2pp. 47799-289-47799-203
- 8812140152 Forwards Insp Rept 50-482/88-30 on 881001-31 & notice of violation CALLAN,L.J. Region 4, Otc of the Director. 88/12/07 WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 2pp. 47821.114-47821.126
- -8812140161 Notice of violation from hispidon 881001-13 Violation noted: on 881029,w/ plant in Mode 6 & less than 23 ft of water above vessel flange,one diesel not maintained operable.

 *Region 4, Oto of the Director 88/12/07 iip 47821-116-47821 116
- →8812140168 Insp. Rept. 50-482/88-30 on 881001-31 Violations noted Major areas inspected plant—status, operational—safety—verification, monthly—surveillance observation, monthly—main observation, cold weather preparations 8 onsite event. BARTLETT, B.L., SKOW, M.E., CHAMBERILAIN, D. Rag on 4, Oto of the Director—887-11/30-10pp, 47821-117-47821-126.
- 8812020287 NRC Info Notice 88 095, "Irradequate Procurement Requirements Imposed by Liconsons on Vendors". Svc 1st and.
 ROSSIC E. Division of Operational Events Assessment (Post 870411). 88/12/08.
 Co.:solidated Edison Co. of New York, Inc. 112pp. 47897:191-47807:302.
- 8812150067 Forwards Insp. Repl. 50-462/88-38 on 881107-11 No violations or deviations noted CALLAN, L.J. Region 4, Otc of the Director, 88/12/09 WITHERS, B.D. Wolf Craek Nuclear Operating Corp. 2pp. 47928 086-47828 094
- -8812150073 Insp. Rept. 50. 482/88.38 on 881107-11 No voletions or deviations nated Major erast inspected Tech. Spac required calibr program to prant instrumentation & action on proviously identified insp. findings. JOHNSON,A.R., STETIKA,T. Region 4, Ofc of the Director, 88/12/00, 7pp. 47828.088-47828.094.
- 0812160024 Ack receipt of 881121 fir informing NRC of steps taken to correct vulations noted in thisp Rept 50-482/48-25 CALLANL J. Region 4, Oic of the Director 88/12/09 WITHERS,BID Wolf Creek Nuclear Operating Corp. 2pp 47873 230 47873 232
- 8812210401 Provides additinfe to violations noted in linsp Rept 50 482788-21 Corrective actions control procedure revised to require operator specifically verify that main foodwater pump reset push button has been reset. WITHERS B.D. WOT Creek Nuclear Operating Corp. 88/12/12. Document Control Branch (Document Control Desk). 3pp. 47882.053-47882.055
- 8012220025 Forwards Insp. Rept 50:482/89:39 on 881128-1202.Violations noted.NRC concorned that type of fullures discussed in rept could have led to common mode failures of plant emergency riesel generators.

 CALLAN,L.J. Replon 4, Ofc of the Director 88/12/12, WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 2pp. 47903 229-47903:239
- ~8612220027 Insp Ropt 50:482/88-39 on 881128-1202.Violations noted Major arcas Inspected actions on previously identified insp Entlings, surveillance test observation & followup on emergency (liesel generator fire on 881127.
 BUNDY,H.F., SEIDLE,W.C. Region 4, Ofc of the Director 88/12/09. 9pp. 47903:231-47803:239.
- 8812210331 Forwards Insp Ropt 50-482/88-27 on 880918-23 & 1003-07 & reduces of violation & deviation. CALLAN, J. Rop on 4, Old of the Director, 88/12/15, WiTHERS,B D. Well Crack Nuclear Operating Corp. 3pp 47887:100-47887
- -8812210337 Notice of violation from insp on 880918-23 & 1003-07 Violation notod safety-related chock valvos isolating nonsafety-related portion of compressed air eye not included in Locansoe setablished check valve to
- -8812210341 Notice of doviation from Insp. on 880919-23 & 1003-07 Deviation noted battery powered emergency fighting units in south electrical penetration room inoperable & inadequate in some areas of plant.

 * Region 4, Ofc of the Director, 88/12/15 2pp. 47887:104-47887:105.
- -8812210342 Insp Rept 50-482/68-27 on 880918-23 & 1003-97 Violation & deviation noted Major areas inspected meint program consisting of overall plant performance remain, mgt support of maint & maint activities implementation.

 GAGLIARDO, J.E. Rogion 4, Ofc of the Director. 88/12/12 45pp. 47687:106-47687:150.

R. Periodic operating reports & related correspondence

- 8811300193 Summary of Operating Reactor Events Meeting 88-46 on 881122 LANNING,W.D. Events Assessment Branch. 88/11/25 ROSSICE. Division of Operational Events Assessment (Post 870411). 11pp. 47680.201-47680.211.
- 8812200208 Monthly operating ropt for Nov 1988 for Wolf Creek Station, W/881213 Mr. WILLIAMS,M.G., WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 88/11/30 7pp. 47868:139-47868:145.

S. Reportable occurrences, LERs & related correspondence

- 8811300219 PNO-IV-88-089 on 981121, seven people externally contaminated when low temp reactor coolant inadvertionally sprayed from top of reactor vessel. All work stopped pending decontamination of reactor bidg Cause under twastigation. HOWELL, A.T. Region 4, Oic of the Director, 88/11/21, 2pp. 47701:319-47701:320.
- 8811300483 LER 88-021-00 on 881025, containment cooling fan B declared inoperable Caused by motor overcurrent condition Motor replaced & addi evaluations ongoing W/881125 ltr. WILLIAMS,M.G., BAILEY,J.A. Walt Creek Nuclear Operating Corp. 88/11/25. Spp. 47673:128-47673:132.

- 8812090185 LER 88 021-01 on 881025,containment cooling fair could not be relied upon to perform intended design function due to motor overcurrent condition Fair declared inoperable Motor replaced wirqualified motor W/681202 ltr. WILLIAVS M.S. WITHERS, B.O. Wolf Creek Nuclear Operating Corp. 88/12/02 5pp. 47786 351-47786 355.
- 8812130272 LER 88 023-00 cn 850908,caviation downstream of throtted butterfly valves causes erosion of essential six water discharge piping below code allowable trickness Essential six water sys 8 damaged piping replaced Wired1207 ltr.
 WILLIAMS,M.G., WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 88/12/07, 6pp. 47786 227-47786 232.
- 8612140260 LER 88-024-00 on 881310.containment purge isotation signal, control room ventilation isotation signal 8 fuel bidg isotation signal ectuations occurred Caused by faiture of +16 vor do power supply Evaluation in
- 8812200349 Special Rept 88 002 on 881115-16,two failures of emergency desel generator. Biocouried Caused by Inadequate forquing of capscraws Capscraws replaced Testing frequency increased Supplemental rept will be submitted by 890315 MTHERS B.D. Wolf Creek Nuclear Operating Corp. 88/12/15 Document Control Branch (Document Control Desk). 3pp. 47862 219-47862-221.

V. Operator Examinations

8811290002 Notifies that TE Wooley no longer amployed as licensed reactor operator at plantiper 10CFR50.74. BA*LEY.J A Wolf Cheek Nuclear Operating Corp 88/11/21. Document Control Branch (Occument Control Desk). 2pp. 47650.051-47650.052.

DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8811300144 Requests in: alion of inquiry of allegation relaborant behavior of security officer at plant & Implementation of corrective actions as appropriate Written rept of results of review within 30 days of receipt of the also requested NORELIUS, CE. Region 3, Oto of the Director 88/11/18. SCHNELL, D.F. Union Electric Co. 2pp. 47673 243-47673:244
- 8812050319 Rev B to Emergancy Plan Implementing Procedure EIP-ZZ-00224, "Injury or Illness Procedure for Callaway Plant" SUDNAK,P. Union Electric Co. 88/11/23 30pp 47740 081-47740 090
- 8812050033 Rev 4 to Emergency Plan Implementing Procedure EIP-22-C0015, "Activation of Backup Emergency Operations Facility HARVEY,S. Union Electric Co. 88/11/23 16pp 47741 354-47742.009.
- 8812130052 Rev. 14 to Emergency Plan Implementing Procedure EIP-22:00201, "Notifications" FAULKENIA Union Electric Co. 88/12/08, 27pp. 47794 131-47794:157.
- 8812210372 Rev 6 to Emergency Plan Imprementing Procedure EIP-ZZ-00202 Rev 3 to EIP-ZZ-00221 & Temporary Change Notice 86-0779 to Rev 2 to EIP-ZZ-00230. HARVEY,S,P. Union Efectic Co. 68/12/09. 15pp. 47675:300-47875:314.

H. General correspondence

8812020007 Comment on proposed rule 10CFR26 re Fitness for Duty Program Policy of yearly testing & testing for cause backed up by training for drug provention supported PATTERSON, J.T., Attiliation Not Assigned, 88/11/25, ROBERTS NRC - No Detailed Affiliation Green 1p. 47680.049 47690.049.

P. Operating license stage documents & correspondence

- 8811300334 Forwards addl into to suppl 880830 application for amend to Licenso NPF-30 re steam generator low leve! trip Circuis SCHNELLD F. Union Electric Co. 88731718. Document Control Branch (Occument Control Desk), 7pp 47674.129-47674:135.
- 8811300581 Forwards Westinghouse revised application for withholding proprietary infocontained in 880830 application for amend to License NPF-30 Requests that Infomarked in WCAP-11883 be withheld from public disclosure (ref. 10CFR2.790). SCHNELL,D.F. Unor Electric Co. 88/11/18. Document Control Branch (Document Control Desk). 3pp. 47674:103-47674.115.
- -8811300582 Requests that proprietary info marked in WCAP-11883, "Implementation of Steam Generator Low Low love! Reactor Trip Time Delay & Environ A'lowance Mod fier in Cal'away Pian." be withheld from public disclosure (of 10CFR2.790). WIESEMANTJ, R.A. Wastinghouse Electric Corp. 88713711. MURLEY.T. Office of Nuclear Reactor Regulation, Director (Post 870411). 10pp. 47674:106-47674:115.
- 8811280048 Generic Ltr 88-20 to all Ecensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for sovere accident vulnerabilities. Svc fist encl. CRUTCHFIELD.D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024.
- 8812020199 Summary of 881005 monthing w/util relicenses proposed steam generator level reactor trip mod for plantList of attendess & nonproprietary stides end ALEX/ON,T.W. Project Directorate III-3, 88/11/29, Project Directorate III-3, 49pp. 47716:330-47717:018.
- 8812060018 Responds to Generic Ltt 88-11 to radiation embrittlement of reactor vessel matts Util utilizes draft Rev 2 to Rog Guide 1.99 methodology to predict effect of neutron radiation on reactor vessel matts. SCHNELL, D.F. Union Electric Co. 88/11/20. Document Control Branch (Document Control Dest). 4pp 47741:092-47741.055.
- 8812070155 Requests that util address Generic Ltr 88-17 re loss of DHR nonpower operation accordingly due to Industry delic ent responso to Generic Ltr 87-12. MURLEY, T.E. Olitico of Nuclear Reactor Regulation, Director (Post 870411). 88/12/ 02: CORNELIUS,W.E. Union Electric Co. 2pp. 47748;245-47746;246.

- 8812080338 Forwards Amend 40 to Liconse NPF-30 & setoly evaluation. Arrord remoses Tech Spoc 3.5.1 to allow plant remain in hot standby w/RCS pressure less than or equal to 1,000 psig w/ one accumulator inoperable ALEXION TW Project Directorate III-3 88/12/05 SCHNELL,DF kinlon Electric Co 2pp. 47744 329-47744 340
- --8812080337 Amend 40 to License NPF-30, revising Tech Spec 3.5.1 to all A plant to remain in hot standby w/RCS pressure loss than or equal to 1,000 psig wrone accommutate appendix.

 HANKONUN Project Directorate III-3 88/12/05, 7pp. 47744 331 47744 337
- --9812060339 Safety evaluation supporting Amend 40 to Licerise (APF-30: Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12-05 359 47744-338-47744-348
- 8812220163 Forwards portions of firs to utilis utilizing halfnum rod cluster control assemblies & synopsis of Info provided to NRC in 881123 tolcon Potential safety issue concerns mechanical functionality of rod cluster control assemblies. JOHNSON,W.J. Westinghouse Electric Corp. 88712708. ROSSIGE. Division of Operational Events Assessment (Post 870411). 13pp. 47892.181.47892.193.

Q. Inspection reports, IE Bulletins & correspondence

- 8811180211 NRC Info Notice 88:090, "Unauthorized Removal of Industrial Muclear Gauges" Svc list encl CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Pes: 970725) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255, 47708:257.
- 8811180467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Tests" Svo list end ROSSICE Division of Operational Events Assessment (Post 870411) 89/11/22 Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708.142
- 8811290030 NRC Info Notice 88 093, "Teletherapy Events" Svc list encil CUNNINGHAM.R.E. Division of Industrial & Madical Nuclear Saloty (Post 970729) 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103 4/841 215
- 8811290538 NRC Info Notice 88-094, "Potentially Understand Valve Actuators" Swe had encl. ROSSI,C E. Division of Operational Events Assessment (Post 870411). 89/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708
- 8812020287 NRC Info Notice 88:095, "Inadequate Procurement Requirements Proposed by Licenseas on Vanders." Svc list encl.
 ROSSICE Division of Operational Events Assessment (Post 870411) 88/12/08 Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807 302.
- 8812200052 Forwards Safety Insp. Rept. 50-483/88-18 on 881031-1130 No ანქისაია noted GREGERIL R. Region 3, Ofc of the Director. 88/12/12 SCHNELL,D F. Union Electric Co. 2pp. 47862-222-47862-244.
- --8812200055 Insp. Rept. 50-483/68-18 on .881031-1130.No wolations or destations noted Major areas inspected radiation protection radwaste mgt programs.inclusing coganization & mgt controls, talming & qualifications & external exposure controls GILL, C.F., KUNOWSKI, M.A., GREGER, L.R., Rogion 3, Otc of the Orector. 86/12/17 21pp. 47862:224-47862:244.
- 8812270208 Responds to AB Daws 881031 lir transmitting SALP 8 Board Pept 50, 4637, 88-01 for June 1997 Aug 1988 No significant comments on rept offered Arces, kdorolised for Increased attention 8 improvement ack. SCHNELL,0 F. Union Electric Co. 88/12/12. Document Control Branch (Document Control Desk), 2pp. 47924:211-47924:212.
- 8812210283 Forwards salety ovaluation concluding that first 10-yr inservice into pregram planw/addl info provided & specific written reliefs, constitutes basis for the eting 100FRS0.55a & Tech Spec 4.0.5 requirements, EGG-SD-7537 also onci HANNEN, JN. Project Directorate III-3, 88/12/14 SCHNELL, D.F. Union Electic Co-2pp 47901:178-47901:223.
- -9812210284 Safety evaluation concluding that facility first 10-yr inservice hisp program plan w/addit Into provided & specific written rollofs granted constitute bases for complance w/10CFR50.558 & Tech Spec 4.0.6.
 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/14. 7pp 47901:180-47901:186.
- --8710140322 "Technical Evaluation on First 10-Yr Inservice Insp Program PlanCalaway Nuclear Power Plant," informat rept.

 BROWN,B.W., MUDLIN,J.D. EG&G Idaho, Inc. (subs. of EG&G, Inc.) BROWN,D.W. idaho National Engineering Laborationy. FIND 9-6022. EGG-SD-7537. B7703733. NRC. No Datal'ed Affiliation Given. 37pp. 47601:187-47901:223.

R. Periodic operating reports & related correspondence

8812130291 Monthly operating rept for Nov 1988 for Callaway Plant Unit 1.W/881205 It. MCCANN,R J., BLOSSER,J.D. Union Electric Co. 88/11/30 7pp. 47/97.072.

S. Reportable occurrences, LERs & related correspondence

- 8812050040 LER 88-013-00:on 881029,steam gonerator level transmitter AE-LT-0513 identified by engineers as heaving improperly installed Raychern heat-st-link formerations on lead wires. Caused by use of outdated procedure-W/881128 ftr MCGRAWJA, BLOSSER,J.D. Union Electric Co. 88/11/28 7pp. 47723 141-47723:148.
- 8812210133 PNO-III-88-102 on 881210 unit shut down to inspect Raychem heal shows tubing on about 170 safety-related electrical splices & panetrations to essure that tubing installation meets environ qualification requirements. DEFAYETTE,R., KNOP,R. Region 3, Ofc of the Director. 88/12/12. 1p 47877 055-47877:055.

termed within 1 h of diesel generator Trein 8 (noporability Causard by cognitive personnel self critique & evant analysis performed W/881214 lit.
1A1COR.M.E. BLOSSER,J.D. Union Electric Co. 88/12/14. Spp. 47876.011-

8812210057 LER 86-015-00 on 981116 & 17,two ESFs actuations occurred. Caused by ineffective training & spurious high spike. Additional training planned & relays recal brated W/881216 ftr.

TAYLOR,M.E., BLOSSER,J.D. Union Electric Co. 88/12/16. 8pp. 47880.219-

V. Operator Examinations

47876:016

- 8812200052 Forwards Safety Insp. Rept. 50-483/88-18 on 881031-1130.No violations no'ed. GREGER, L.R. Region 3, Old of the Director, 88/12/12 SCHNELL, D.F. Un'on Electric Co. 2pp 47862:222-47862:244.
- -9812200055 Insp. Rept 50-483/88-18 on 881031-1130 No violations or deviations noted Major areas inspected rediation protection redwaste mgt programs, including organization & mgt controls, training & qualifications & external exposure controls. GILL, C.F., KUNOWSKI,M.A., GREGER,L.R. Region 3, Ofc of the Director. 88/12/12 21pp. 47682.224-47662-244.

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

F. Sacurity, medical, emergency & fire protection plans

- 6811300064 Advises that 880930 Rev 13 to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable. CALVO,J.A. Project Directorate IV. 88/11/22. GOLDBERG,J.H. Houston Lighting & Power Co. 5pp. 47680:127-47880:131.
- 8812060294 Forwards prompt notification sys lest rept using FEMA Region VI reporting form for Apr-Oct 1988.
 MCBURNETT,M.A. Houston Lighting & Power Co. 88/11/23. LANSFORD,R.A. Texas, State of 3pp. 47744:326-47744:328.
- 8812080152 Revised emergency plan implementing procedures including Rev 4 to OEPP01-ZA-0003,Rev 5 to OEPP01-ZA-0005,Rev 5 to OEPP01-ZA-0014,Rev 8 to OEPP01-ZA-0016,Rev 3 to OEPP01-ZA-0016 8 Rev 5 to OEPP01-ZA-0031.W/
 - MCBURNETT,M.A. Houston Lighting & Power Co. 88/12/02. 248pp. 47755.301-
- 8812090320 Discusses NRC Investigation Rept 4-88-004 on 880129-0415 re apparent feligification of fire watch logs at plant on Dec 1987 & Jan 1988 & forwards notice of
- WARTIN,R.D. Region 4, Ofc of the Director, 88/12/05, GOLDBERG,J.H. Houston Lighting & Power Co. 2pp. 47762;203-47762;208.
- -8812090326 Notice of violation from NRC investigation rept on 880129-0418. Violations noted plant fire watch supervisor & line watch personnel assigned fire protection sys compensatory hoully watches initialed fire watch logs.

 MARTIN,R.D. Region 4, Otc of the Director. 88/12/05. 2pp. 47762 205-47762:208.
- 8812150101 Forwards Insp Repts 50-498/88-71 & 50-499/88-71 on 881031-1104.No Violations or deviations noted CALLAN, L.J. Region 4, Offic of the Director, 88/12/08, GOLDBERG, J.H. Houston Lighting & Power Co. 3pp. 47828:367-47828:380.
- --8812150105 Perilally withheld Physical Security Insp Repts 50-496/68-71 & 50-496/ 88-71 on 881031-1104.No violations noted Major areas inspected physical barriers vial area.detection sids vital area.communications & lighting. EARNEST.A.B., TOBIN.W., EVERETT.R.J. Region 4, Old of the Director. 88/11/22. 1p. 47828-360-47828:360.

P. Operating license stage documents & correspondence

- 8811300492 Requests fee for 880601 application submitted for review be remitted for Unit 1.Costs for Unit 2 will be included in OL review costs. DIGGS.R.M. Licenso Foe Management Branch. 88/11/01. VAUGHN,G.E. Houston Lighting & Power Co. 1p. 47701:259-47701:259.
- 8811290164 Forwards Rev 22 of QA program description for design & const phase,per requirements of 10CFR50.55(f)(3).
 GOLDBERG.J.H. Houston Lighting & Power Co. 88/11/22. Document Control Branch (Document Control Desk). 3pp. 47684:271-47684:281.
- --8811290175 Rev 22 to QA program for design & const. * Houston Lighting & Power Co. 68/11/22, 8pp, 47684:274-47664:281.
- 8812020090 Forwards response to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Mails & Impact on Plant Operations." Pressure temp curves determined more conservative than Rev 2 to Reg Guide 1.99 requirements. GOLDBERG,J.H. Houston Lighting & Power Co. 88/11/22. Document Control Branch (Occument Control Desk). 3pp. 47711:129-47711:131.
- 8812080202 Forwards response to NRC concerns identified during onsite assessment of qualified display processing sys. Procedures will provide checklist & response for each flem on diagnostics display which includes power supply voltage. MCBURNETT,MA. Houston Lighting & Power Co. 88/11/22. Document Control Branch (Document Control Desk), 9pp. 47757.081-47757.089.
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re Individual plant exam for severe accident vulnerabilities. Svc list eand.
 CRUTCHFIELD.D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728:303-47729:024.
- 8811290363 "South Texas Project Electric Generating Station Unit 1 Startup Rept." W/ 881123 tr. MCBURNETT,M.A. Houston Lighting & Power Co. 68/11/23. 200pp. 47930:008-47930:253.

- of operational readiness review during wk of 881114 Detailed response to Instrument at Issues will be provided in response to Generic Lir 88-14 VAUGHM, G.E. Houston Lighting & Power Co. 88/11/23 Document Control Branch (Document Control Desk). 8pp. 47678.013-47676.018
- 8812020283 Forwards Amend 3 to License NPF-76 & safety evaluation Amend changes App A Tech Spocs by deteting Figure 6.2-1, "Offsite Organization," & Figure 6.2-2, "Unit Organization," & Figure 6.2-2, "Unit Organization," B Power Ca. 7pp. 47734 068-47734 087.
- -8812020288 Amond 3 to Licenso NPF-76, changing App A Tech Specs by deteining Figure 6.2-1, "Dilste Organization," & Pigure 6.2-2, "Unit Organization," & providing appropriate changes to administrative control requirements CALVO_JA, Project Directorate IV. 88/11/28, 10pp, 47734-075-47734-084.
- -8812020290 Safety evaluation supporting Amend 3 to Licenso NPF-76.
 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/11/26. 3pp. 47734.085-47734.087.
- 8812220049 Forwards proprietary draft WCAP-12067, "South Texas Unit 2 Pressurizer Surge Line & RHR Line Stratification Presentation to NRC 881130." Rept withheld fret 10CFR2.7801. BURNETT,M A. Houston Lighting & Power Co. 88/11/29. Document Control Branch (Document Control Desk). 2pp. 47903 282-47903 283
- 8812070192 Advises that proprietary WCAP-11963, "NRC Update Meeting, South Texas BMI Flux Thimble Wear,880810," will be withheld from public disclosure (ref 10CFR2.700) DICK,G.F. Project Directorate IV. 88/12/01. GOLDBERG,J.H. Houston Lighting & Power Co. 5pp 47749 245 47749 249
- 8812080061 Grants withholding of WCAP-11761,Hev 1, "South Texas Units 1 & 2 Roactor Vessol Till & Wavinoss Clarification Study," per 10CFR2 790. DICK,G.F. Project D rectorate U., 88/12/01. GOLDBERG,J.H. Houston Lighting & Power Co. Spp. 47753.166-47753.170
- 8812080070 Grants withholding of WCAP-11555, "Technical Beess for Eliminating Rup-ture of Accumulator Line & Attached RHR Piping from Structural Design Bases for South Texas Project, Units 1 & 2," per 10CFR2.780. DICK,G.P. Project Orectorate IV. 88/12/01. GOLDBERG,J.H. Bouston Lighting & Power Co. 4pp. 47757:003-47757.007.
- 8612080076 Grants withholding of WCAP-11773, "Technical Bases for Eliminating RHR Line Rupture From Structural Design Basis for South Texas Project Units 1 & 2" DICK.G.F. Project Directorato 1V. 88/12/01. GOLDBERG.J.H. Houston Lighting & Power Co. 5pp. 47764/214-47754/218.
- 8812090337 Submits outline of plans for usage & monitoring of full length Italinium con-trol rods Util will perform control rod insps similar to those at Wolf Creek at or before third columing outage.

 MCBURNETT,M A Houston Lighting & Power Co 88/12/02 Document Control Branch (Document Control Desk). 2pp. 47784 360 47784 361.
- 8812130300 Requests that surverlance associated w/CV-0215 not be included in Tech Spocs Rationale for not including valve in surveillance program provided. Diffulion flow path will be removed at first returning outage W/non oversize drawing, MCBURRETT,MA. I flouston Lighting & Power Co. 08/12/05. Document Control Branch (Document Control Desk). 4pp. 47798-242-47798-245.
- 8812140003 Forwards draft proprietary WCAP-12087, "South Texas Unit 2 Pressurizor Surge Ling & RHR Line Strathication," (rol 10CFR2.790). Rept revised to include addition requested by NRC during uit 881130 prosentation MCBURNETT,M.A. Houston Lighting & Power Co. 88/12/08 Document Control Branch (Document Control Desk). 3pp. 47821.001-47821.003.
- 8812070168 Requests that util addresses Generic Lir 88-17 to loss of DHR during non-power operation issue of high priority & should be addressed accordingly. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 07, JORDAN,D.D. Houston Industries, Inc. 4pp. 47749.311-47749.314.
- 6812130115 Discusses review of Tech Spec Table 5.7-1, per apparent discrepancies between Tech Spec table & FSAR Table 3.9-8 re monitoring plant transients to assure Cycle stress limits
 MCBURNETT,M.A. Hauston Lighting & Power Co. 88/12/07. Document Control
 Branch (Document Control Desk). 3pp 47796:233-47796:235.
- 8812130207 Forwards ennotated FSAR pages to provide advance clarification in plant organization per discussion w/ EJ Holler Description of proposed changes to Chapter 17 encl. MCBURNETT,M.A. Houston Lighting & Power Co. 88/12/07. Document Control Branch (Document Control Desk). 41pp. 47797:148-47797:213
- 8812140251 Forwards profirminary response to Generic Ltr 88-17, "Loss of DHR" No reduced inventory operations will be conducted until actions taken to resolve concerns identified in itr. Response to generic itr will be provided by 890118. VAUGHN,GE. Houston Lighting & Power Co. 88/12/09. Document Control Branch (Document Control Desk). 8pp. 47812.040-47812.047.
- 8812150095 Forwards response to NRC questions re corrective action to address mi-crotiplogically reduced corrosion in emergency deset generator (acket water. MCBURNETT,MA. Houston Lighting 8 Power Co. 88/12/09. Document Control Brench (Document Control Desk). 4pp. 47828:069-47825.072.
- 8812150099 Certilies that encl final draft Tech Specs consistent w/FSAR & as built fa-cillies except for comments & editorial changes noted on attached marked pages, VAUGHN,GE. Houston Lighting & Power Co. 88/12/09. Document Control Branch (Document Control Dask). 49pp. 47825.078.47825.124.
- 8812210029 Forwards proprietary WCAP-12067 & nonproprietary WCAP-12067, "South Texas Units 1 & 2 Pressurizer Surge Line & RHR Line Stratification." Proprietary rept withheld (ref 10CFR2.790).
 MCBURNETT,MA. Houston Lighting & Power Co. 88/12/09. Document Control Branch (Document Control Desk). 3pp. 47887:156-47888.075.

118 DOCKETED HEWS

- -8812210031 Requests withholding of WCAP-12087, "South Texas Ucits 1-8-2 Pressurizer Surge Line & REPE Line Straid atton," per 100FR2 790 Alfidavit etcl. WIESEMANN.R.A. Westinghouse Electric Corp. 88/12/09 JMURE EYT. Office of Nuclear Reactor Regulation, Director (Post 870411) 10pp 47897.159-47887.168
- -8012210034 Nonproprietary "South Texas Units 1 & 2 Pressurizer Surge Line & Brits Line Stratiscation :

 BAMFORD,W.H., BRICE NASH R.L., CAFILSON,R.W. Westinghouse Electric Corp. WCAP-12087, 88/12/31, 265pp. 47887 169 47889 876
- 8812200012 Responds to Generic Ltr 86-14, "Instrument Air Supply Sys Problems Af-focting Safety-Related Equipment." Util reviewed generic In & NUREG-1275,Vol 2 & purformed design & operations vonlication of nathriment art sys for plant GOLOBERG, J.H. Houston Lighting & Power Co. 89712713. Document Control Branch (Document Control Desk). 8pp. 47871;548-47871;355.
- 8812210397 Forwards enholated FSAR text & revised ligures re-updated plant subsidence into talo covers monitoring results for deep ref benchmarks & regional near surface subsidence MCSURNETT,M.A. Hausten Lighting & Power Co. 88/12/14. Document Control Branch (Document Control Desk), 10pp. 47881/144-47881 153.
- 8812220384 Forwards Libense NPF-78, nullionizing operation at up to five percent full power. Technical basis included in SER, St.pp's 1-6 (NUREG 0781). HOLAHAN,G M. D.vison of Reactor Projects III, IV. V. 8. Sputial Projects (Post 67041). 88/12/16. GCLD3ERG J.H. Forda Power & Light Co. Epp. 47903.244-
- --8812220094 "Environ Protection Plan (Nonredulogical) for Facility.App 6 to Licenses NPF-76 & NPF-78." * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/31 20pp
 - 47903 262 47903 281.
- Q. Inspection reports, IE Bulletins & correspondence
- 8811160211 NRC Into Notice 88 090, "Unauthorized Removal of Industrial Nuclear Gauges "Sve list encl CUNNINGHAM.R E. Division of Industrial & Medical Nuclour Saluty (Post 870729) 88/11/22 Consolidated Edison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 6611160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychologi-ROSSIC E. Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708-142
- 8811300032 Forwards revised response to violations noted in Insp Ropts 50.498/88.54. 8 50.498/08-54 Response addressed addit concerns in Insp. Repts 50-498/88-61,50-498/88-72 & 50-499/88-72 Concert ve actions procedures revised VAUG/N/N/G.E. Houston Lighting & Power Co. 88/11/23 Document Control Branch (Document Control Desk). 8pp. 47897.339-47697.314.
- 8811290030 NRC Info Notice 68-083, "Telethorapy Events" Svc I st anci-CUNNINGHAM,R.E. Dwis on of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-47811.215.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators" Svc list
- enci. ROSSICE, Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254. 8812090320 Discusses NRC Investigation Rept 4.88-004 on 880129-0415 re apparent falsification of fire watch legs at plant on Doc 1987 & Jan 1988 & forwards notice of
- Wolation.
 WARTIN,R D. Region 4, Ofc of the Director, 88/12/05 GOLDBERG,JH. Houston Lighting & Power Co. 2pp. 47762 203-47762 206.
- --8812090326 Notice of violation from NRC Investigation reption 880129-0415 Violations noted plant fire watch supervisor & fire watch personnel assigned fire protection system compensatory hourly watches initiated fire watch logs. MRTIN,R D. Region 4, Oto of the Director. 88/12/06, 2pp. 47782:205-47762 206
- 6812130231 Forwards response schedules for NRC generic correspondence, per G
- Disk request.
 MCBURNETT,M.A. Houston Lighting & Power Co. 88/12/06. Document Control Brench (Document Control Desk). 5pp. 47797:238-47797:242
- 8812150224 Forwards Insp. Repts 50-498/88-77 & 60-499/88-77 on 881114-18.No. violations or deviations noted CALLAN.L.J. Region 4. Otc of the Director, 88/12/07, GOLDBERG.J.H. Houston Lighting & Power Co. 3pp. 47825.042-47825.050.
- -8612150226 Inap Riopts 50.498/88-77 & 50.499/88-77 on 881114-18.No violations of deviations noted Major areas inspected Unit 2 preoperational testing including witnessing of selected tests & preoperational test results evaluation. AZUA, RV, BUNDY, H.F., SEIDLE, W.C., Reg on 4, Ofc of the Oiroctor, 88/12/07, 6pp 47825:045-47825.050.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Liconsees on Vendors," Svo list end ROSSI, C.E. Division of Operational Events Assessment (Post 870411) 88/12/08. Consolidated Edison Co. of New York, Inc. \$12pp. 47807;191-47807.302.
- 8812150101 Forwards (nsp. Repts 50-498/88-71 & 50-499/88-71 on 881031-1104.No violations or dowaldows noted:
 CALLAN,L.J., Region 4, Otc. of the Director 88/12/08, GOLDBERG,J.H. Houston Lighting & Power Co. 3pp. 47826-357-47826-360.
- -8812150105 Partially withheld Physical Socurity Insp Repis 50-498/88-71 & 50-499/88-71 & 50-499/88-71 and 881031-1104.No violations noted. Major areas inspected physical barriers vital area_detection aids vital area_communications & lighting. EARNEST.A.B., TOSIN,W, EVERETT,R.J Region 4, Otc of the Director. 88/11/22. 1p. 47828.360-47826;360.
- 8812200021 Provides revised schadule for completion of Open Rems 498/88-30-10 8 498/87-20-02 re callbr of gaseous & liquid radioactivity monitors & sampling & analysis of plant effluents by 990101 agreed to during 860429 elecon. VAUGHN G.E. Houston Lighting & Power Co. 88/12/14. Document Cantrol Branch (Document Control Dosk). 4pp. 47858-285-47858-289.

- 8812220190 Responds to NRC 881115 ftr re-violations noted in Insp. Repts 50-498/68-46 & 50-499/68-46 Corrective actions Maint Work Request HE-65094 inhated to re-place E1C11 heater control panel bolts & crew briefings provided VAUGHAN, G.E. Houston Lighthing & Power Co. 86/12/14. Document Control Branch (Document Control Deak), 5pp. 47884-356-47884-360.
- R. Periodic operating reports & related correspondence
- 8812200127 Monthly operating ropt for Nov 1988 for South Texas Electric Generating Station Unit 1.W/881213 ftr. RENT.A.P., MCBURNETT,M.A. Houston Lighting & Power Co. 68/11/30. 9;0 47864:316:47864:324.
- S. Reportable occurrences, LERs & related correspondence
- 8811300154 Special reptioose paris monitoring sys (LPMS) Channels 2.6 & 11 Inoposable for 30 days LPMS Channel 6 inoperable due to falled accelerometric Channels 2 & 11 inoperable due to continuous alarms Accelerometric will be replaced VALIGHIN,G.E. Houston Lighting & Power Co. 88/11/18. Document Central Branch (Document Control Desk) 4pp. 47695 339-47695:342
- 8812020087 LERI 88.061.00 on 881027, omergency operating procedure error found during special inspiritue to inadequate roview Procedure required to institute procedure revised to correct error. W/881121 to: AYALA,CA, VAUGHN,G.E. Houston Lighting 8 Power Co. 88/11/21 5pc 47213-124-47711:128.
- 8812050122 Spucial rupt on 881027, standby diesel generator (SDG) 13 hipped which re-leased from emergency mode during startup. Caused by nonemergency mode shurt-down circuit Instrumentation connected to shutdown at header & restarted VAUGHIN,G.E. Houston Lighting & Power Co. 88/11/23. Document Cortol Branch (D. cument Control Dask). 4pp. 47734-009-47734.012.
- 8812020302 PNO IV-88-092 on 881129,discovered that vortex breakers not installed in any of three emorgancy containment sumps. Util invest gating why vortex heak or a not installed 8 instituted steps to fabricate or optacement vortex breakers. FOCLER, G. Flegion 4, Oto of the Director, 69/11/30, 2pp. 47718,307-47718,308.
- 812200266 Part 21 & final deficiency rept re containment hydrogen analyzers Romening Unit 1 flow regulator replaced w/ regulator containing stainless steel diaphragm (SSD: Unit 2 regulators w/SSDs installed GCLDBERG.J.H. Houston Lighting & Power Co. 88/12/13. Document Control Branch (Document Control Desk). Spp. 47860:288-47860.292. 8612200266
- 8812210011 LER 88-050-01:on 880827 ESF actuation of all three trains of HVAC for control room envelope & fuel handing bidg occurred simultaneously.Caused by high frequency harmon'c generated by ground fault invortor sys evaluated W/65/21.4 ftr. AYALA.CA., VAUGHN,G.E. Houston Lighting & Power Co. 88/12/14. 5pp 4788.1:101-47081.105.
- 8812270282 Special reption 881006 high-hoad safety injection to RCS occured Caused by Inadvertent start of Train C high head safety injection pump by becosed operator. Value of usage factor not reportable at present per Tech Special 2.2. VAUGHN.G E Houston Lighting & Power Co. 88/12/21. Document Control Deak) 3pp. 47926:141-47926:143.

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

- A. Application/construction stage documents & correspondence
- 8811290164 Forwards Flov 22 of OA program description for design & constiphase.per requirements of 10CFR50.55(f)(3). GOI OBERG.J.H. Houston Lighting & Power Co. 88/11/22. Document Control Branch (Document Control Dask). 3pp. 47864:271-47864:281.
- -8811290175 Rev 22 to QA program for design & const.
 * Houston Lighting & Power Co. 88/11/22. 8pp. 47684:274-47684:281.
- 8812020000 Forwards response to Generic Ltr 88-11, "NRC Position on Radation Embrittement of Roactor Vessel Matis & Impact on Plant Operations," Pressure temp curves determined more conservative than Rev 2 to Reg Guide 1.99 requirements GOLDBERG,J.H. Housion Lighting & Power Co. 88/11/22. Document Control Deskl. 3pp. 47711:120-47711:131.
- 8812080202 Forwards response to NRC concerns identified during one is assessment of qualified display processing sys Procedures will provide checkflist & response for each item on diagnostics display which includes power supply voltage MCBURNETT, M.A. Houston Lighting & Power Co. 88/11/22. Document Control Branch (Document Control Desk). 8pp. 47787.081-47767:089.
- 8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabilities Svc Est
 - GRUTCHFIELD,D Associate Director for Projects (Post 870411), 88/11/23, Consciedated Edison Co. of New York, Inc. 81pp. 47728:303-47728.024.
- 8811290322 Notification of 881130 meeting w/util In Rockville,MD to discuss thermal stratification in pressurare surgo line.

 DICK,G.F. Project Directorate IV. 88/11/23. MURLEY,T., SNIEZEK,J., MIRAGLIA,F. NRC No Detailed Affailation Given, 5pp. 47649;173-47649:177.
- 6811300139 Forwards summary schedule for corrective actions & responses to fundings of operational readiness review during wk of 881114. Detailed response to instrument air issues will be provided in response to Generic Ltr 68-14.

 VAUGHN,GE Houston Lighting & Power Co. 88/111/23. Document Control Branch (Document Control Desk): 6pp. 47678:013-47676.018.
- 8812220049 Forwards proprietary draft WCAP-12067, "South Toxas Unit 2 Pressurface Surge Line & RHFI Line Stratification Presentation to NRC 881130." Rept withhold (rel 10CFR2.700).
 BURNETT,MA. Houston Lighting & Power Co. 88/11/29. Document Control Branch (Document Control Desk) 2pp. 47003 282-47903.203.

- 8612010080 Forwards draft unsigned, undated License NPF-78 & notice of issuance of Loense.
 HOLAHAN,G.M. Division of Reactor Projects III,IV.V & Special Projects (Post 670411), 88/12/01, GOLDBERG.J.H. Houston Lighting & Power Co. 4pp. 47703.116-
- -8812010083 Draft Licenso NPF-78.
 * Division of Roactor Projects III,IV,V & Special Projects (Post 870411) 88/12/01.
 6pp 47703:121-47703:126
- -8812010085 Draft notice of Issuance of License NPF-76 to South Texas Project Unit 2 Project Directorate IV. 88/12/01. 3pp. 47703:127-47703:129.
- 8812070192 Advises that proprietary WCAP-11963, "NRC Update Meeting, South Toxas BMI Flux Thimble Wear,880810," will be withheld from public disclosure (ref BMI Flux Thimble Wear,880810," will be withheld from public disclosure (rot 10CFR2 790).
 DICK,9.7 Project Directorate IV. 88/12/01. GOLDBERG,J.H. Houston Lighting &

Power Co. Spp. 47749:245-47749:249.

- 8912080061 Grants withholding of WCAP-11761, Rev 1, "South Texas Units 1 & 2 Reactor Vessel Till & Waviness Clarification Study," per 10CFR2.790. DICK, G.F. Project Directorate 1V. 88/12/01. GOLDBERG, J.H. Houston Lighting & Power Co. Spp. 47753:186-47753:170.
- 8812080070 Grants withholding of WCAP-11555, "Technical Bases for Eliminating Rupture of Accumulator Line & Attached RHR Piping from Structural Design Bases for South Texas Project, Units 1 & 2." por 10CFR2-790.

 DICK_GF. Project Directorate IV. 88/12/01. GOLDBERG,J.H. Houston Lighting & Power Co. 4pp. 47757:003-47757:007.
- 8812080076 Grants withholding of WCAP-11773, "Technical Bases for Eliminating RHR Line Rupture From Structural Design Basis for South Texas Project Units 1 & 2." DICK,G.F. Project Directorate IV. 88/12/01. GOLDBERG,J.H. Houston Lighting & Power Co. 5pp. 47754:214-47754:21B.
- 6812090344 Discusses status of equipment qualification program to provide assurance that safety-related electrical & mechanical equipment perform intended function.per NRC request for addition or edifferences between Units 1 & 2.
 WESTERMEIERJ. Houston Lighting & Power Co. 88/12/01. Document Control Branch (Document Control Desk). 8pp. 47782-214-47782.219.

- 8812090305 Summary of 881129 meeting w/util & Newman & Holtzinger re-roadiness for low power license List of attendees & viewgraphs oncl.

 DICK_GF, Project Directorate IV. 88/12/02. Project Directorate IV. 22pp. 47767:338-47757:360.
- 8812090337 Submits autime of plans for usage & monitoring of full length halfrum control rods Util will perform control rod Insps similar to those at Wolf Creek at or before third reluciling outage.

 MCBURNETT.MA. Houston Lighting & Powor Co. 88/12/02. Document Control Branch (Document Control Desk). 2pp. 47784:360-47784:381.
- 8812120211 Requests schodular exemption from requirements of 10CFR50.33(k) & 50.75 re submitted of ropt contenting certification of financial assurance for funds to decommission facility. Affidavit encl Foe paid VAUGHIN.GE. Houston Lighting & Power Co. 88/12/02. Document Control Branch (Document Control Desk). 4pp. 47788.017-47788.020.
- 8812090346 Informs of util readiness for fuel loading & low power feeting of util as early as 881216 but no later than 881224. Completion of NRC requirements at time of fuel load expected except items detailed in encl.
 GOLDBERG.J.H. Houston Lighting & Power Co. 88/12/03 Document Control Branch (Document Control Desk), 42pp. 47775:236-47775:277.
- 8812130300 Requests that surveillance associated w/CV-0215 not be included in Tech Specs Rationale for not including valve in surveillance program provided. Dilution flow peth will be removed at first refueling outage. W/one oversize drawing. MCBURNETT,M.A. Houston Lighting & Power Co. 88/12/05. Document Control Branch (Document Control Desk). 4pp. 47798:242-47798:245.
- 8812140003 Forwards draft proprietary WCAP-12067, "South Texas Unit 2 Pressurizer Surge Line 8 RHR Line Stratification," (ref. 10CFR2.790) Rept revised to include additing requested by NRC during util 881130 presentation.

 MCBURNETT,M.A. Houston Lighting & Power Co. 88/12/06. Document Control Branch (Document Control Desk). 3pp. 47821:001-47821:003.
- 8812070168 Requests that util addresses Generic Ltr 88-17 re loss of DNR during non-power operation issue of high priority & should be addressed accordingly. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 88/12/ 07. JORDAN,D.D. Houston Industries, Inc. 4pp. 47749:311-47749.314.
- 8812130115 Discusses review of Tech Spec Table 5.7-1,per apparent discrepancies between Tech Spec table & FSAR Table 3.9-8 re monitoring plant transients to assure cyclic stress limits.

 MCBURNETT,M.A. Houston Lighting & Power Co. 88/12/07. Document Control Branch (Document Control Desk). 3pp. 47798:233-47796:235.
- 8812130207 Forwards annotated FSAR pages to provide advance clarification in plant organization,per discussion w/ EJ Holler Description of proposed changes to Chapter 17 encl.
- MCBURNETT,M.A. Houston Lighting & Power Co. 88/12/07. Document Control Brench (Document Control Desk), 41pp. 47797:148-47797:213.
- 8812130246 Forwards environ assessment & finding of no significant impact re 860115 request for exemption from 10CFR50 App J. Evaluation published in SSER 3 (NUTREG-0781).
 CALVO.J.A. Project Directorate IV. 88/12/07. GOLDBERG.J.H. Houston Lighting & Power Co. 5pp. 47798:252-47798:280.
- --8812130247 Notice of Environ assessment & finding of no significant impact re 860115 fit concerning exemption from 10CFR60 App J. CALVO,J.A. Project Directorate IV. 88/12/07. 4pp. 47796:267-47796:260.
- 8812130250 Forwards environ assessment & finding of no significant impact re 881202 request for temporary exemption from schedular requirements of decommissioning nuls, IOCFR50.33(k) & IOCFR50.76. DICK.G.F. Project Directorate IV. 89/12/07. GOLDBERG,J.H. Houston Lighting & Power Co. 4pp. 47797:267-47797:264.

- -8812130256 Environ assessment & finding of no significant impact re exemption from 10CFR50.33(k) & 10CFR50.75 CALVO,J A. Project O rectorate IV. 88/12/07, 4pp. 47797-261-47797.264
- 8812120220 Submits addl status of equipment qualification program Sys component evaluation worksheet, solamic & dynamic qualification summary & status of safety-related equipment for new equipment and WESTERMEIER,J. Houston Lighting & Power Co. 88/12/08 Document Control Branch (Document Control Bash) 43pp. 47788 211-47788:253.
- 8812140251 Forwards preliminary response to Generic Ltr 88-17, "Loss of DHA" No reduced inventiory operations will be conducted until actions taken to resolve concerns identified in itr Response to generic lir will be provided by 890.118 VAUGHN,G.E. Houston Lighting & Power Co. 88/12/09. Document Control Branch (Document Control Dosk). 8pp. 47812.040-47812.047.
- 8812150095 Forwards response to NRC questions re corrective action to address microbiologically reduced correction in emergency triesel generator jacket water. MCBURKETT,M.A. Houston Lighting & Power Co. 88/12/09. Document Control Branch (Document Control Desk). 4pp. 47825.069-47825.072
- 8812150099 Certifies that enct final draft Tech Specs consistent w/FSAR & as-bu't faclines except for comments & od/orial changes noted on attached marked pages VAUGHN,G.E. Houston Lighting & Power Co. 68/12/09 Document Control Branch (Document Control Desk). 49pp. 47825.076-47825-124.
- 8812210029 Forwards proprietary WCAP-12067 & nonproprietary WCAP-12087, "South Toxas Units 1 & 2 Pressurtor Surge Line & RHR Line Stratification." Proprietary rept withheld (ref 10CFP2.790)
 MCBURNETT, M.A. Houston Lighting & Power Co. 88/12/09. Document Control Branch (Document Control Desk) 3pp. 47887:156-47888.075
- -8812210031 Requests withholding of WCAP-12067, "South Texas Units 1 & 2 Pressurizor Surge Line & RHR Line Stratification," per 10CFR2 790 Affiliava encl. WIESEMANN,R A. Westinghouse Electric Corp. 86/12/09 MURLEY,T. Office of Nuclear Reactor Regulation, Director (Post 870411). 10pp. 47887:159-47887; 168.
- ~8612210034 Nonproprietary "South Texas Units 1 & 2 Pressurizor Surge Line & RHR Line Stratification "
 BAMFORD,W H., BRICE-NASH,R L., CARLSON,R W. Westinghouse Electric Corp. WCAP-12087-88/12/31. 265pp. 47897.168-47898.075
- 8812200250 Informs that equipment covered by seismic & environ qualifications qualified & installed. BAILEY, J.N. Houston Lighting & Power Co. 88/12/12. Document Control Branch (Document Control Desk). 2pp. 47862.158-47862.157.
- 8812200012 Responds to Generic Ltr 88-14, "Instrument Air Supply Sys Problems Af-lecting Salety-Related Equipment," Util reviewed generic Itr & NUREG-1275,Vof 2 & performed design & operations verification of instrument air sys for plant. GOLDBERGJ.H Houston Lighting & Power Co. 88/12/13. Document Control Branch (Document Control Desk). 8pp. 478/1:348-478/1.355.
- 8812200260 Discusses commitment to Install low raise preamphilier in remaining source range channel prior to fuel load Addl justification for rev to Tach Spac surveillance requirements for source range channels oncl.per 881208 tir WESTERMEERJ Houston Lighting & Power Co. 88/12/13. Document Control Branch (Document Control Dost). 5pp. 47864:306-47884:310.
- 8612210397 Forwards annotated FSAR text & revised figures re-updated plant subskil-ance info.info.covers monitoring results for deep ref benchmarks & regional near-surface subsidence MCBURNETT,MA. Houston Lighting & Power Co. 88/12/14 Document Control Branch (Document Control Desk), 10pp. 47881:144-47881:153
- 8812270291 Submits notification that all mechanical equipment covered by seismic & environ qualification qualified & installed & maint & surveillance programs to proserve qualification of aquipment in piace.

 BAILEY_JN. Houston Lighting & Power Co. 88/12/15. Document Control Branch (Document Control Desk). 2pp. 47926:022-47926.023.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 8812130246 Forwards environ assessment & finding of no significant impact re 860115 request for exemption from 10CFR50 App J. Evaluation published in SSER 3 (NUREG-0781).
 CALVO_I.A. Project Directorate IV. 88/12/07. GOLDBERG,J.M. Houston Lighting & Power Co. 5pp. 47796:252-47796.260.
- 8812220384 Forwards License NPF-78,authorizing operation of up to tivo percent full power.Technical basis included in SER,Supple 1- 6 (NUREG-0781). HOLAHAN,G.M. Division of Reactor Projects In,IV,V & Special Projects (Post 87041). 89/12/18. GOLDBERG,J.H. Florida Power & Light Co. 5pp. 47603:244-47903:281.
- F. Security, medical, emergency & fire protection plans
- 8611300064 Advises that 880930 Rev 13 to physical security plan consistent w/provielons of 10CFR50.54(n) & acceptable.

 CALVO,J.A. Project Directorale IV. 88/11/22. GQLDBERG,J.H. Houston Lighting & Power Co. 6pp. 47680:127-47680:131.
- 8812060294 Forwards prompt notification systest rept using FEMA Region VI reporting form for Apr-Oct 1988.
 MCBURNETT,MA. Houston Lighting & Power Co. 88/11/23. LANSFORD,R A. Texas, State of. 3pp. 47744:328. 47744:328.
- 8812080152 Revised emergency plan implementing procedures including Rev 4 to OEPP01-ZA-0003,Rev 5 to OEPP01-ZA-0005,Rev 5 to OEPP01-ZA-0014,Rev 8 to OEPP01-ZA-0016,Rev 3 to OEPP01-ZA-0018,Rev 6 to OEPP01-ZA-0031 W/ MCBURNETT,M.A. Houston Lighting & Power Co. 88/12/02, 248pp. 47755;301-

- 88 12090320 Discusses NRC Investigation Rept 4-88 004 on 650129 0415 re apparent fals-feation of the watch logs at plant on Dec 1987 8 Jan 1388 & towards notice of sections.
 - worst.cn MARTIN:RID Region 4. Ofci of the Director 88/12/05. GOLDBERGIJH Houston Lighting & Prover Co. 2 pp. 47762-203-47762-206.
- -6817090326 Notice of volation from NRC investigation ropt on 880129-0415 Viciations noted plant the watch supervisor 8 fra watch personnel assigned fire protection system personnel assigned fire protections. WARTIPLED Region 4, Order time Director 88/12/05 (2pp. 47762-205-47762-206).
- 8812150101 Forwards Insp Replis 50 493/89/71 & 50 499/88/71 on 881031-1104 No
- Volations or deviations noted CALLARIL J. Region 4, Ord of the Director 68/12/08. GOLDBERG JH. Houston Lighting & Power Co. 3pp. 47826 357-47828 350
- -8812150105 Partially withheld Physical Security Insp. Repts 50-498/88-71 & 50-499/ 88-71 on 681031-1104 No wolstons noted Major areas inspected physical barriers -vital area detection axis vital area communications & lighting EARNEST A.B. Region 4, Ordict the Director, 89/11/22 in 47825-360-47825-360

J. Insurance & Indemnity Information

- 8812200138 Forwards Certificates M-116 8 N-116 to MAELU Policy 1 & NEUA Policy 1,985pc;threir, which provides proct of secondary transal protection.

 BALEY J.N. Houston Lighting & Power Co. 88/11/29 Document Control Branch (Document Control Dask) 32pp. 47868.197-47869.228
- 8812090324 Forwards environ assessment & finding of no significant impactire exemp-tion from 19CFR50.54(w)(5)(1) re increase in amount of onsire property damage insur-ance required carried by power reactor increases DICK, G.F. Project Directorate IV: 88/12/05 GCLDBERGUH Houston Lighting & Power Co. Spp. 47775-193-47775-201
- -8812090379 Environ assessment & "nding of noisign ficent impact concerning exemp-tion from 10CERSO 54(M)(S)M to increase in amount of one to property damage insur-ance required carried by power reactor Leasees CALVO_J A Project Directorale IV, 88/12/05 4pp 47775 198-47775:201.

P. Operating license stage documents & correspondence

- 8812220384 Forwards License NPF-78,authorizing operation at up to tive percent full power Technical basis included in SER Supplia 1- 6 (NUREG 0781). HOLAHANG M. Drivson of Reactor Projects IIII/V. & Special Projects (Post 870411) 88/12/16. GOLDBERG,J.H. Florda Power & Light Co. 5pp. 47803.244-47003 2R1
- -8812220388 Licenso NPF-78,authorizing operation at up to five percent of full power. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/ 16, 7pp. 4790.2494-7903.255
- -88.12220391 Notice of consideration of issuance of amend to License NPF-76 & proposed NSHC determination & opportunity for hearing License authorizes operation at up to five percent of full power DICK G.F. Project Directorate IV. 88/12/16 6pp. 47903:256-47903:261.
- -8812220394 "Environ Protection Plan (Norrad d'ogical) for Facility.App Billo Licenses NPF-76 8 NPF-78"
 "Office of Nuclear Reactor Regulation, Circotor (Post 870411), 88/12/31, 20pp.
- 47903:282-47903:281

Q. Inspection reports, IF. Bulletins & correspondence

- 8811300456 Advises that addit chemical & mechanical testing described in 881101 for completed per NRC Bullatin 88-05 Enct results of testing do not after conclusion that mattingstated in unit acceptable for user in safety-related ASME code applications. GOLOBERG, JH. Pousson Lighting & Power Co. 68/11/17. Document Control Branch (Document Control Desk). 3pp. 47702.041-47702.077.
- -8812070173 Rev 1 to "IE Builetin 88-005 Investigation Rept, South Texas Project Elec-tric Generating Station Unit 2"

 * Houston Lighting & Power Co. 88/11/15, 34pp. 47702 044-47702 077.
- 8811160211 NRC Info Notice 88-093. "Unauthorized Removal of Industrial Nuclear Gauges: Svc I st end CUNNINGHAM.R E. Ovision of Industrial & Medical Nuclear Safety (Post 870729) 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708.257.
- 8811160467 NRC Info Notice 88-091, "Improper Administration & Control of Psychological Tests" Svc 1st encl ROSSICE Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708 142.
- 8811300032 Forwards revised response to volations noted in finsp Repts 50-498/88-54 & 50-499/88-54 Response addressed addl concerns in linsp Repts 50-498/88-51-50-499/88-51-50-498/88-72 & 50-499/88-72-Corrective actions procedures revised VAUGHN,GE Houston Lighting & Power Co. 88/11/23. Document Control Branch (Document Control Desk). 8pp. 47697-309-47697-314.
- 8811290030 NRC Info Notice 88 093, "Teletherapy Events " Svolist and CUNNINGNAM,R E. Drusion of Industrial & Medical Nuclear Safety (Post 870728), 88/12/02 Consocidated Edison Co. of New York, Inc. 112pp. 47811:103-47811:215.
- 8611290538 NRC Info Notice 88-094, "Potentia"y Undersized Valve Actuators " Svc fist enci ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8812070108 Forwards "Preservice Insp Summary Rept for Class 1 Class 2 & Class 3 Component Supports at South Texas Project Electric Generating Station Unit 2." BAILEY,J.N. Houston Lighting & Power Co. 88/12/202. Document Control Branch (Document Control Desk) 2pp 47745049-47745209

- -8812070107 "Proservice Insp. (PSI) Summary Hept for Class 1-penent Supports at South Toxes Project Electric Generating 5-years bases for PSI program & describes scope of PSI exams STEWARTM A., BEVERLY R.L., MCINTYRE, A.C., Houston Lys-12/31 158pp 47745 051-47745 20H
- 8812090345 Hospands to NHC Burlella 88 010, "Noncontaria ng tr Broakers" Due to magnitudo & complexity of tesk not clear to the actions required prior to fuel lead Results of evaluation expects to VALIGHNIGE Houston Lighting & Power Co. 88 12/02 Doc. (Document Centrel Desk), 5pp. 47761-126, 47761-133
- 8812130287 Forwards labulation of as-built recorditation ic. calculations.pdr IE Builatin 70-14 No conacceptable deviations to a nguranons nome WESTERMEIER,J. Houston Lighting & Power Co. 88/12/12 Branch (Document Control Dask), 6pp. 4/798.001-47796-006
- 8812090320 Discusses NRC Invostigation Rept 4-88-004 on 86.112 fals fication of the watch logs at plant on Doc 1987-8 Jan 1988-4
- WARTIN,R.D. Region 4, Otc. of the Director, 88/12/05, GOLC: Lighting & Power Co. 2pp. 47762 203 47762 206
- --8812090326 Notice of violation from NRC invostigation rept on REL noted prent fire waich supervisor & fire watch personnel assignist compensatory bousty watches initiated fice watch logs.

 MARTIN,FLD. Reg en 4, Otc of the Director, 88712/05, 2pp. 47762
- 8812130231 Forwards response schedules for NRC generic con-Dck request MCBURNETT,M.A. Houston Lighting & Power Co. 88/12/06 Branch (Document Control Desk). 5pp. 47/97 238-47797 242
- 8812130297 Forwards Roy 2 to "IE Buttelin 88-005 Investigation Project Electric Generating Station Unit 2 "
 GOLDBERG J.H. Houston Lighting & Power Co. 68/12/06 Doccor [Document Centre) Desk). Opp. 47813 277-47813.317.
- -8812140018 Rev 2 to "IE Bulletin 68-005 Investigation Rept South the Generating Station Unit 2:"
 1 Houston Lighting & Power Co. 88/12/05, 38pp. 47813 280-47813
- 8812160224 Forwards Insp Repts 50 409/68-77 & 50 499/88-77 chations or deviations holod.

 CALLANIL J. Region 4, Old of the Utreator, 88/12/07, GOLD Elighting & Power Co. 3pp. 47025 042-47025.050.
- -8812160226 Insp. Repts 50:408/#8-77 & 50:40U/88-77 on 881114 devaitions noted Major areas Inspected Unit 2 preoperational testing of selected tests & preoperational test results evaluation AZUA,RV, BUNDY,HF, SCIDLE,W.C. Region 4, Ofc of the Dece 47825-045-47825.050
- 8812020287 NRC Into Notice 98 095, "Inadequate Procurement Re-by Licensees on Vendors." Svc list end: ROSSICE Division of Operational Events Assessment (Post Consolidated Edison Co. of New York, Inc. 112/pp. 47807.191-476
- 8812130236 Responds to 881108 request rulepectic disposition of results review 2.51.P.01. "Safety Rejection Sys Train A," per unresines Rept 50 409/86 93 from onlice modification was respectively. I Boston Lighting & Power Co. 88/12/08 Branch (Document Control Desk). 3pp. 47797.069-47797.071.
- 8812160101 Forwards Insp. Repts 50-498/88-71 & 50-499/88-71 violations or deviations noted CALLANL J. Region 4, Ofc. of the Director, 88/12/08 GOLD Lighting & Power Co. 3pp. 47820-357-47820-360.
- -8812150105 Part ally withhold Physical Security Insp Repts 50 44 88-71 on 881031-1104 No violations noted Major areas inspecte vial area.decision aids with area.communications & lighting EARNEST, A.B., TOBIN, W., EVERETT, B.J. Region 4, Ofc of the 1p 47626.360-47626.360.
- 6812200286 Documents (Iconsed commitment to submit Inservice in first (0-yr Insp. Intervation in ICERTISO 65a(p)(4)(i).
 BAILEY_JN. Houston Lighting & Powor Co. 88/12/13. Document Control Dask). 2pp. 47871.030 47871:039
- 8812200016 Provides supplemental response to NRC Bufetin 88-00 tigghouse Circuit Broakers "Dofficient pole shalls for 34 DS-206 breakers replaced w/pole shalls passing wold inap for unrestricted GOLDBERGUJH. Houston Lighting 8 Power Co. 88/12/14. Docur (Document Central Cask). 3pp. 47860.304-47860.306
- 8812220190 Responds to NRC 881115 lir re violations noted in In: 46 & 50-499/88-46 Corrective actions Maint Work Request HE-5 place E1C11 heater control panel bolts & crow briefings provided VAUGHAN,G E. Houslon Lighting & Power Co. 88/12/14. Docur (Document Control Desk) 5pp. 47894:356-47894:360.

9. Reportable occurrences, LERs & related correspondence

- 8812060286 Part 21 & final dofficioncy ropt to ESF diese damage Initially reported on 881028 Damaged parts on d replaced Deficioncy is solely attributable to Cooper-Bossemer ma. GOLDBERG, J.H. Houston Lighting & Power Co. 88/11/23. Docu (Document Control Desk). 4pp. 47742.196 47742:199
- 8812130243 PNO-IV-98 095:employees accidentally electroculed clear well intake screen on allo water woll. One employee decidence fruck boom confacting 13.8 kV electric line. HUNNICUIT, D. Region 4, Ofc of the Director. 88/12/09. 1p. 4

- 812290265 Part 21 & final deficiency rept re conteinment hydrogen analyzers Remaining Unit 1 flow regulator replaced w/ regulator containing stainless afeel diaphragen (SSD). Unit 2 regulators w/SSDs installed GOL 095EG, JH. Houston Lighting & Power Co. 88/12/13. Document Control Branch (Document Control Desk). 5pp. 47860-288-47860-292. 8812260266 Part 21
- 8812200267 Final deficiency & Part 21 rept re Class 1E ballery cables in hally reported on 881109 Util compared quaffication of other jumper cables for use & unquaffied cables replaced w/ qualified cables.

GOLDBERGUH Houston Lighting & Power Co. 88/12/13. Document Control Branch (Document Control Desk). 4pp. 47860.208-47860:211

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A. Application/construction stage documents & correspondence

- 8911300235 Submits additinto in response to questions on geosciences program clarifying rates of erosion elong State of OR & State of WA coastines re formation of modern wavecut platforms Questions aroso from NRC Sept 1988 visit. SORENSEN,G C. Washington Public Power Supply System. 88/11/21. Document Control Branch (Document Control Dosk). 4pp. 47677:261-47677:264
- 8911280049 Generic Ltr 88-20 to all licensess holding OLs & CPs for nuclear power reactor (actitiles re individual plant exam for severe accident vulnerabilities Svc list
 - encl CRUTCHFIELD.D Associate Director for Projects (Post 870411) 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728-303-47729-024.
- 8812150245 Notification of 890111 meeting w/util in Flocky lie,MD to discuss facility Geoscionce program Agenda onci VISSING.G.S. Standardization & Non-Power Reactor Project Directorate. 88/12/07. MILLER.C.L. Standardization & Non-Power Reactor Project Directorate. 3pp. 47830-232-47830-234
- 8912160225 Discussos MPA B-81 requirements for Units 1 & 3.per Genetic Ltt 83:28, "Required Actions Based on Generic Implications of Salem ATWS Events." Reactor Reactor hip breaker maint & trending Issues should be addressed as plant-specific Issues.

 BRADFUTE, J.O. Project Directorate V. 88/12/05 VISSING, G.S. Standardization & Non-Power Reactor Project Directorate. Spp. 47826:295-47826:297

Q. Inspection reports, IE Bulletins & correspondence

- 8811160211 NRC Info Notice 86-090, "Unauthorized Removal of Industrial Nuclear
 - Gauges: "Svc list enct. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 89/11722 Consolidated Edison Co. of New York, Inc. 89pp. 47708-255-47708-257.
- 8811180467 NRC Into Notice 88-091, "Improper Administration & Control of Psychological Tests." Svc list end. ROSS(C.E. Division of Operational Evente Assessment (Post 670411). 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708 042-47708:142.
- 8811290030 NRC Info Notice 88-093, "Telethorapy Events." Svc list onci. CUNNINGHAM,R.E. Division of Industrial & Modical Nuclear Safety (Post 670729). 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp 47811:103-47811:215.
- 88 i 1290538 NRC Info Notice 88-094, "Potentially Undersized Velve Actuators." Svc list
- enci. ROSSI, C.E. Division of Operational Events Assessment (Post 870411), 88/12/02. Cansolidated Edison Co. of New York, Inc. 121pp. 47708.143-47708-254.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors" Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.

DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

Q. inspection reports, IE Bulletins & correspondence

8812010341 Provides supplemental response to violations noted in Insp Rept 60-518/ 87-01.Corrective actions:complation of procedure on prescribing preventive mainte-nance requirements reachoduled for 890301. GRIOLEY,R. Tennessee Valley Authority, 88/11/29. Document Control Branch (Docu-ment Control Desk). 3pp. 47703:051-47703:053.

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8812070009 Advises that Amend 17 to physical security plan consistent w/provisions of 10CFR60.46(p) & acceptable.
 SCARANO,R.A. Region 5, Oic of the Director. 88/11/30. KARNER.D.B. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 4pp. 47749:233-47749:238.
- 8812210066 Forwards Security Insp Repts 60.528/88.31,50.528/88.30 & 50.539/88.29 on 880928-1025 & notice of violation. Insp repts & notice of violation withheld (ref 10CFR2.760).

 PATER.J. Region 5, Oto of the Director. 88/12/09. KARNER.D. Arizona Nuclear Power Project (formerly Arizona Public Servico Co.). 3pp. 47889.022-47889.024.

J. Insurance & Indemnity Information

8812070015 Forwards Endorsement 10 to NELIA Certificates N-88 & N-107 & Endorsement 10 to MAELU Certificates M-80 & M-107.
KARNER D.B. Arizona Nuclear Power Project (fo trarty Arizona Public Service Co.).
88/11/30 Document Control Brazila (Document Control Desk). 25pp. 47749.278-

P. Operating license stage documents & correspondence

- 8811300080 Notification of significant meeting on 681201 in Winterstrung,AZ to review
- util action on NRC concerns
 Region 5, Dit of the Director, 88/11/21, Region 6, Ofc of the Director, 2pp.
 47696 280-47896 281.
- 8811300138 Notification of 881269 mosting w/util in Rockville,MD to present engineer-Ing excellence program.
 DAVIS.M.J. Project Directorate V. 88/11/21. Project Directorate V. 5pp. 47670.284-
- 8811280048 Generic Ltr 88-20 to all Iconsess holding OLs & CPs for nuclear power reactor facilities re Individual plant exam for sovere accident vulnorabilities Svc list enci CRUTCHFIELD,O Associato Director for Projects (Post 870411), 88/11/23, Consoli-dated Edison Co. at New York, Inc. 81pp. 47728 303-47729.024
- 8812070136 Forwards EGG-N1A-7432, "Conformance to Generic Ltr. 83-28, Item 2.2.1, Equipment Classification for all Other Safety-Related Components," Palo Verde Units 1,2.8.3." Response acceptable CHAN, T.L. Project Directorate V. 89/11/28, KARNER, (1) B. Auzona Nuclear Power Project (formerly Arizona Public Service Co.). 4pp. 47747.123-47747.147
- --8811220443 "Conformance to Generic Lift 83-28 tiem: 2.2.1 Equipment Classification for All Other Safety-Rolated Components Palo Verde Units 1,2 & 3," Informal rept. UDY, A.C. EG&G Idaho, Inc. (subs. of EG&G, Inc.) UDY, A.C. Idaho Neconal Engineering Laboratory, FIN D-8001 EGGNTA-7432 88/02/29, NRC No Dotailed Alf Salico Given. 21pp. 47747.127-47747:147
- 8812150132 Requests response to Generic Ltr 88-17 re loss of shutdown cooling con-current w/significant core decay heat industry response to Generic Ltr 87-12 deficient in great of prevention of accident initiation & miligation of accidents MURLEY,T.E. Office of Nuclear Reactor Regulation. Director (Post 870411). 88/12/ 02. DEMICHELE,O M. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 3pp. 47830.129-47830.131.

O. Inspection reports, IE Bulletins & correspondence

- 8812050202 Forwards Insp. Repts 50:528/88:33.50:529/88:32 & 50:530/88:31 on 880918:23.No violations noted Continuing need for improvement in area of occupational radiation protection indicated Ref made to 10CFR19:15,19:16 & 19:20.
 SCARANOR.A. Region 5, Ofc of the Director 88/11/15, KARRER.D.B. Arizona Nuclear Power Project (formarly Arizona Public Service Co.). 2pp. 47731-055-47731-068.
- -8812050204 Insp. Ropts 50-528/88-33.50-529/88-32 & 50-530/88-31 on 880918-23.No violations or deviations noted Major areas inspected followup of open items & Info notices, followup of anforcement items & rowew of Allegation 88-RV-A-0041 CILLIS.M., NORTH,H.S., Rog on 5, Otc of the Director, 88/11/15, 10pp. 47731.057-47731-068.
- 8811160211 NRC Info Notice 88-090, "Unauthorized Romoval of Industrial Nuclear Gauges" Svc list enct. CUNNINGHAMR E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/11/22. Consolidated Euison Co. of New York, Inc. 99pp. 47708 255-47708 257.
- 8811160467 NRC Into Natice 88-091, "Improper Administration & Control of Psychologi-cal Tests," Svc fist enct. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/11/22. Consolidated Edison Co. of New York, Inc. 101pp. 47708.042-47708.142.
- 8812070073 EN.88-103 on 881201 notice of proposed imposition of civil penalty in amount of \$250,000 will be issued to ficensee based on problems in areas of plant operations a radiological controls. LUEFIMANJ, LIEBERMANJ Oic of Enforcement (Post 870413). B8/11/29 2pp. 47746,081-47746,082.
- 8812210017 Forwards Insp. Repts 50-528/68-32,50-529/88-31 & 50-530/88-30 on 880918-1105 & notice of violation Number of observations made by Inspectors indicate personnel not consistently adhoring to procedural requirements.

 PATE,R.J. Region 5, Otc of the Director. 88/11/30. KARNER,D.B. Arizona Nuclear

 Power Project (formatly Arizona Pubic Service Co.). 3pp. 47891:032-47881:080.
- ~8812210019 Notice of violation from insp on 880918-1105.Violation noted:Train A diesel genorator maint progressed to disassembly of temp control valve w/o corresponding documentation of previously completed steps in instruction.

 PATE R.J. Region 5, Old of the Director, 88/11/30, 2pp. 47881:035-47881.036.
- ~8812210023 Insp. Repts. 50.528/88:32,50.528/88-31. & 50-530/88-30 on 880818-1105.Violations noted.Major areas inspected, previously lidentified items,roview of plant activities,ESF sys walkdowns,surveillance testing & plant maint. POLICH.T., COED., FIORELLI,G. Region S, Ofc of the Director. 88/11/30. 24pp. 47881:037-47881:060.
- 8812190171 Discusses Insps Repts 50-529/88-14,50-529/88-22, 50-528/88-24,50-529/88-26,50-528/88-30,50-528/88-35, 50-529/88-37, & 50-530/88-33 on 880520-1012 & forwards two notices of violation & proposed imposition of cwl ponetty. MARTIN.J.B. Region 5, Off of the Director. 88/12/01. KARNER,D.B. Arizona Nuclear Power Project (formarly Artzona Public Service Co.). 4pp. 47850.224-47850-236.
- -8812190174 Notice of violation & proposed imposition of civil penalty in amount of \$50,000 Violation noted both loops of essential chilled water sys rundered inoperable but util neither restored operability nor placed until in required model MARTIN.J.B. Region 5, Oto of the Director. 89/12/01, 2pp. 47850:228-47850:229.
- --8812190178 Notice of violation & proposed imposition of civil penelty in amount of \$200,000.Violations noted individual received accumulated whicle body dose of 3.209 rem for Second Quarter 1988 & ALARA meetings not held from Mar 1987 Jul 1988. MARTIN,J.B. Region 6, Olc of the Director 88/12/01. 7pp. 47850 230-47860:236.
- 8811290030 NRC Info Notice 88-093, "Teletherapy Events," Svc list encl. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/12/02, Consolidated Edison Co. of New York, Inc. 112pp. 47811:103-42811:215.

- 8818290238 MHT LUD MO: CO OC 034 enci ROSSI C.E. Division of Operational Evoris Assossment (Post 870411). 88/12/02. Conso Jaled Edison Co. of New York, Inc. 121pp. 47708 143-47708 254.
- 8812190413 Forwards Incp. Repts 50-528/88-40-50-528/89-59 & 50-530/89-58 on 881031-1104 & notice of violation One activity was not conducted in full compliance w/IJFIC regarements YUJHAS G.P. Region S. Oto of the Chector 68/12/02 KARNEA, D.B. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 47850-345-47850-358
- -8812190414 hotice of violation from inspirence 661031-1104 Violation instead flowmoler for Environ Sampling Station 15 & 14a returned to svc w/o having been adjusted to 15 containment failure mode.

YUHAS,G P. Fiegion 5, O'c of the Cirector, 88/12/02, 2pp. 47850 347-47850 348.

- -8812190415 Insp. Repts. 50-528/68-40,59-529/68-39 & 50-500/88-39 on 881031-1104 Viciation noted Major areas inspected environ protection (ic/lowup & tours of facdby CCOTTEGR: NORTHINS Region 5, Old of the Director, 88/11/29, 10pp. 47850 349-47850 358
- 8812210028 Forwards Insp. Repts 50-528/88-39.50-528/88-39 & 50-530/88-37 on 881031+1104 No motations noted. HICHARDS A. Region 5, Oto of the Director 88/12/05 KARNER D.B. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 47890.106 47890.118
- -8812210035 Insp. Repts. 50-528/88-39,50-529/88-38. & 50-530/88-37 on -881031-1104 No Notations noted Major areas Inspected ivarious vital areas and equipment & assessment of forousing teams & LERs. BURDO N.J.F. Region 5, Ofc of the Director -68/12/05. 12pp. 47890, 107-47890,118.
- 8812020267 NRC Info Notice 66-095, "Inadequate Procurement Requirements Imposed by Licensees on Vondors" "Svoilstierd", ROSSI, CE Cwision of Operational Events Assessment (Post 870411), 88/12/08, Consolidated Edison Co

- 8912200334 Forwards Exam Repts 50:528/OL-88.01.50:529/OL-88.01.8.50:530/OL-68.01 of exems administered during wks of 881012.8.25. Recurring problem of stimuta-tion facility modeling & stimutator feetity was again noted in preparation of exam RICHARDS, S. A. Region 5, Offic of the Director. 88:12/08. KARIKER,D. Arizona Nuclo-av Power Project (formatly Arizona Public Sonice Co.). 5pp. 47855:235-47856.263.
- -8812200335 Exam Repts 60-528/OL-88-01,50-529/OL-88-01,50-530/OL-88-01 on
- 8812210066 Forwards Security Insp. Repts 50-528/83-31.50-529/88-30 & 50-530/88-29 on 860926 (025 & notice of violation haspirepts & notice of violation withheld (ref. 100FR2.790)

PATE,R J. Region 5, Clc. ct. the Director. 88/12/09. KARNER,D. Arizona Nuclear Power Project (formerly Arizona Pub'ic Service Co.). 3pp. 47889-022-47889-024.

R. Periodic operating reports & related correspondence

8812190278 Monthly operating repts for Nov 1988 for Pato Verde Nuclear Generating Station Units 1,2 & 3 W1681215 to. BORST, S.G. HANNES, J.G. Arizona Nuclear Power Project (formerly Arizona Public Service Co.), 88/11/30, 16pp. 47850/302-47850/317.

S. Reportable occurrences, LERs & related correspondence

- 8811300281 LER 68-009-00 on 881018 incorrect setpoint for control room ventilation red-ahon monitor identified Caused by incorrect conversion factor & alarm selecting en-tered by personnel. Alarm/tip selecting restW/881117 Iz. SHRIVER.T. D., HAYNES.J.G. Anzona Nuclear Power Project (formerly Arizona Public Service Ca.) 88/11/17. 6gp. 47676 288-47676.293
- 8811290358 Special Rept 1-SR-68-008 on 981113, Tech Spoiss violated Caused by loose part detection channel being inoperable for more than 30 days due to problems wifalse of lating Sys will be mon-lored once per 24 h & investigation initiated. HAYNESJIG Arizona Nuclear Power Project (formarly Arizona Public Service Co.) 88/11/22 Document Control Branch (Document Control Desk) 2pp. 47665-269-47665-270.
- 8812130041 LER 89-026-00 on 881105.control element assembly slipped approx 10 inches below other assemblies in group during performance of surveillance test. Caused by apparent ground on lower gropper co. Assembly realigned. W/881205 SHRIVER, T.D., HAYNES, J.G. Arizona Nuclear Power Project (formerly Arizona Public Service Co.), 88/12/05. 6pp. 47799:151-47793.158.

V. Operator Examinations

- 8812140065 Forwards revised agenda for annual operator licensing meeting on 890110 W/o enci
 PATE,R.J. Region 5, Ofc of the Oxector, 58/12/05, FERNOW,W. Arizona Nuclear
 Power Project (formerly Arizona Public Service Co.), 1p. 47796.150-47796.150.
- 8812200334 Forwards Exam Repts 59:528/OL-88-01;50:523/OL-88-01 & 50:530/OL-88-01 of exams administered during wks of 891012 & 25 Recurring problem of simulation facility modeling & simulator fidelity was again noted in preparation of exam. RICHARDS,S.A. Region 5, Oto of the Director. 88/12/OB, KAHNER,D. Anzona Nuclear Power Project (formerly Anzona Public Service Co.), 5pp. 47855 235-47856:263.
- ~88.12200335 Exam Repts 50-528/QL-88.01.50-529/QL-88.01.50-539/QL-88.01 on 80.1012-14.8.25-28 Exam results nine senior reactor operators & six reactor operators passed written portion of exam One reactor operator failed written exam. ROYACK,M.J., MORRILL.P., JOHNSTON,G. Region 5, Ofc of the Exector, 68/12/02, 1000pp. 47855:240-47858:263.

F. Security, medical, emergency & fire protection plans

8812070009 Advises that Amend 17 to physical security plan consistent without 10CFR50.54(p) & acceptable. SCARANO,R A. Region 5. Old of the Diroctor. 88/11/30. KARNER.D.B. A. clear Power Project (formarly Arizona Public Service Co.). 4pp. 47742/2334

8812210066 Forwards Socumy Insp Ropts 50-528/88-31.50-529/88-33 & 50 to 980826-1025 & notice of violation lines replie & notice of violation will 10CFR2 700). TOCHE 700.

PATE,R.J. Hoglon 5, Ofc of the Director, 88/12/09, KARNER,D. Arton.

Power Project (formarly Arizona Public Survice Co.), 3pp. 47889.022 47890

J. Insurance & Indemnity Information

8812070015 Forwards Endorsement 10 to NELIA Cortificates N-86 & N-107 8 ment 10 to MAELU Certificates M-86 & M-107. KARKER, D.B. Arizona Nuclear Power Project (formerly Arizona Public Selection Deciment Control Branch (Document Control Desk), 25pp 4 47749:302.

P. Operating license stage documents & correspondence

- 8811300080 Noblication of significant meeting on 881201 in Winterstury A2 uit action on NRC concerns.

 * Region 5, Otc of the Disctor. 88/11/21, Region 5, Otc of the Disctor. 88/11/21, Region 5, Otc of the Disctor.
- 8811300138 Natification of 881209 meeting w/util in Reckville,MD to present ing excellence program DAVIS,M.J. Project Directorate V 88/11/21. Project Directorate V 5pp of
- 8811280049 Generic Ltr 88:20 to all licensees holding OLs & CPa for audireactor facilities re individual plant exam for sovere accident vulnorabilities.
- CRUTCHFIELD,D. Associate Director for Projects (Post 870411), 88/11/2 dated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024
- 8812070135 Forwards EGG-NTA-7432, "Conformance to Generic Lir 83-26, Equipment Classification for all Other Safety- Related Components," Pale V. 1,2 & 3." Response acceptable. CHAN,T.L. Project Directorate V. 88/11/29, KARNER,D.B. Anzona Nucl Project (formerly Anzona Public Service Co.): 4pp. 47747:123-47747:147
- -881120443 "Conformance to Goneric Ltr 83-28, Itom 2.2.1 Equipment Ctor All Other Sefety-Related Components" Pale Vorde Units 1.2.8.3." of UDY.A.C. Ed86 Idaho, Inc. (subs. of Ed86, Inc.). UDY.A.C. Idaho Naicra Ing Laboratory. FIN D-5001. EG6. NTA-7432. 88/02/29 NRC ND Dotale Given. 21pp. 47747:127-47747:147.
- 8812150132 Requests response to Generic Ltr 88-17 to loss of shuldown of of 2180132 Hadguest response to Capacific for BE-17 to loss of induction for current w/ significant core decay had Industry response to Generic Life?In areas of prevention of accident initiotion & miligation of accidente MURLEY,TE. Office of Nuclear Reactor Regulation, Director (Post 8704) OZ. DEMICHELE,OM. Airzona Nuclear Power Project (formorly Arizona Pul Co.). 3pp. 47830.128-47830.131.

Q. Inspection reports, IE Bulletins & correspondence

- 8812050202 Forwards Insp. Repts 50-528/88-33,50-529/88-32 & 60-53: 880919-23.No violations noted Continuing need for improvement in area transl radiation protection indicated Ref made to 10CFR19.16,19.18 & 10.2 SCARANO,R.A. Region 5, Oto of the Director, 88/11/16. KARNER,D.B. cloar Power Project (formerly Arizona Public Service Co.), 2pp. 47731-055
- -8812050204 Insp. Repts 50.528/88.33.50.529/88.32 & 50.530/88.31 of 23 No violations or deviations noted Major areas inspected followup of or info notices/followup of enforcement Items & review of Allegation 88.4V-A-CILUS-M, NORTH,H.S. Region 5, Ofc of the Director, 88/11/15 10pp. 47731:086.
- 88[1160211_NRC Into Notice 88-090, 'Unauthorized Removal of Indust Gauges. Svc list enct.
 CUMMINGHAM,R.E. Division of Industrial & Medical Nuclear Salay Pt.
 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47
- 8811160487 NRC Into Notice 88-091, "Improper Administration & Control of cal Tests." Sve list encl.
 ROSSICE: Division of Operational Events Assessment (Post 870411)
 Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708:142
- 8812070073 EN-88-103:an 881201, notice of proposed imposition of civeramount of \$250,000 will be issued to ficensee based on problems in an operations & radiological controls. LUERMAN, J. LUEBERMAN, J. Ofc of Enforcement (Post 870413): 68/47748.081-47748.082.
- 8812210017 Forwards insp. Repts. 50-528/88-32,50-529/88-31. & 50-52 880918-1105 & notice of volation. Number of observations made by ins calle personnel not consistently adhering to procedural requirements PATE.R.J. Region 5, Otc of the Director. 88/11/2/0. (ARNER,D.B. Ariz Power Project (formerly Arizona Public Servico Co.). 3pp. 47881:032-4788
- ■8812210019 Notice of violation from finep on 800919,1105.Violation in dissel generator maint progressed to disease. Prof. of temp control valve sponding documentation of previously conveted etaps in instruction PATE,R.J. Region 5, Otc of the Projector, 88/11/30, 2pp, 47881-035-4788.

8812190171 Discusses Insps Ropts 50-529/88-14,50-529/88-22, 50-529/88-24,50-529/88-26,50-528/88-30,50-528/88-35, 50-529/88-37 & 50-530/88-33 on 880520-1012 & 100-2005 two notices of violation & proposed Imposition of civil penalty. MARTIN, 19. Region 5, Ofc of the Director, BB/12/01, KARNER, D B Anzona Nuclear Power Project (formerly Arizona Public Service Co.) 4pp. 47850;224-47850-236

- ~8812190178 Notice of violation & proposed imposition of civil penalty in amount of \$200,000 Violations noted.Individual received accumulated whole body dose of 3.200 rem for Second Quarter 1988 & ALARA meetings not held from Mar 1987 Jul 1989 MARTIN,J.B. Region 5, Otc of the Director. 88/12/61, 7pp. 47850 230-47850 236.
- 8811290030 NRC Info Notice 88:093, "Teletherapy Events" Svc fiel enci CUNN'NGHAM,R E. Division of Industrial 8. Medical Nuclear Safety (Past 870729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp 47811.103-47811
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators " Svc 1st
- enci. ROSSI,C.E. Division of Operational Evonta Assessment (Post 870411) 98/12/02 Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708.254. 8812190413 Forwards Insp. Repts 50-528/88-40,50-529/88-39 & 50-530/88-38 on 881031-1104 & notice of violation One ectivity was not conducted in full compliance
- W/NRC requirements.
 YUHAS,G.P. Region 5, Otc of the Director, 88/12/02, KARNER,D.B. Arizona Nuclear Power Project (formerly Anzona Public Service Co.), 2pp. 47850:345-47850-358
- -8812190414 Notice of violation from insp on 881031-1104 Violation noted townster for Environ Sampling Station 15 & 14a returned to svc w/o having been adjusted to 1.5 containment failure mode. YUHAS, Q.P. Region 5, Otc of the Director, 89/12/02, 2pp. 47850 347-47850 348
- --8812190415 Insp Repts 50-528/88-40,50-529/88-39 & 50-530/88-38 on 891031-1104. Violation noted Major areas inspected environ protection, followup & tours of facity. CICOTTE,G.R., NORTH,H.S. Region 5, Otc of the Director 88/11/29 10pp 47850-349-47850-358.
- **881021-0028** Forwards Insp. Repts. 50-528/88-39,50-529/88-38. & 50-530/88-37. on 881031-1104.No violations noted. RICHARDS, A. Region 5, Otc. of the Director. 88/12/05, KARNER D.B. Artzona Nuclear Power Project (formarly Artzona Public Servico Co.). 2pp. 47890-105-47890-118
- --8812210035 Insp. Repts 50-528/88-39,60-529/88-38 & 50-530/88-37 on 881031-1104.No violations noted Major areas inspected, various vital areas and equipment & assassment of followup items & LERs BURDOIN,J.F. Region δ, Ofc of the Director, 86/12/05, 12pp 47690:107-47690 118
- 8812020287 NRC Into Notice 88 095, "Inadequate Procurement Requirements Imposed by Ucensees on Vandors." Svc list end.
 ROSSIC E. Division of Operational Events Assessment (Post 870411), 88/12/08, Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807.302.
- 8612200334 Forwards Exam Repts 50-528/QL-88-01,50-528/QL-88-01 & 50-530/QL-
- 88-01 of exams administered during wise of 88 t012 & 25. Recurring problem of smuls-ton facility modeling & simulator fidelity was again noted in graparation of usem RICHARDS & A. Region 5, Otc of the Director. 88/14/208 KARTIERD, Anzona Nuclear Power Project (formerly Arizona Public Service Co.). 5pp. 47855:235-47858-263
- -8812200335 Exam Repts 50-528/OL-88-01,50-529/OL-88-01,50-530/OL-88-01 on 881012-14 & 25-28,Exam results:nine sentor reactor operators & six reactor operators passed written portion of exam One reactor operator failed written exam ROYACK,M.J., DEFFERDING,L., ELIN,J.O. Region 5, Ofc of the Director 88/12/02. 1000pp. 47855-240-47858-283.
- 8812210066 Forwards Security Insp Repts 50-528/88-31,50-529/88-30 & 50-530/68-29 on 880926-1025 & notice of violation. Insp repts & notice of violation withheld (ref
 - PATE.R.J. Region 5, Ofc of the Director, 88/12/09, KARNER,D. Arizona Nuclear Power Project (formerly Arizona Public Service Co.), 3pp., 47889.022-47889.024.
- R. Periodic operating reports & related correspondence
- 8812190278 Monthly operating repts for Nov 1988 for Palo Verde Nuclear Generating Station Units 1,2 & 3.W/881215 ftr. BORST, S.G., HAYNES, J.G. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 88/11/30. 16pp. 47850:302-47850.317.

S. Reportable occurrences, LERs & related correspondence

47797:237.

- 8811280060 PNO-V-88-061:on 881107, reactor cavity sump level inside containment observed to increase slightly 8 on 881116, reactor trip occurred due to low steam generator water favel.Ceused by feiture of main feedwater jump.
 RICHARDS,S., POLICH,T. Region 5, Otc of the Director, 88/11/16 1p. 47654:152-
- 8811300284 LER 88-009-01:on 880913,condenser evacuation offluent monitor sample filter improperly assembled Caused by personnel error. New particulate & charcoal litters assembled & reinstalled W/881117 ltr.
 SHRIVER, T.D., HAYNES, J.G. Artzona Nuclear Power Project (formerly Arizona Public Service Co.). 88/11/17. 5pp. 47676:284-47676.298.
- 8612130306 Special Rept 23-SR-86-008:on 881108,7 day l-mit for inoperability of post accident sampling sys exceeded Caused by inadequate flow measuring unit trial isolation valve reinstalled.

 HAYNES,J.G. Arzona Nuclear Power Project (formerly Arizona Public Service Co.). 68/12/08. Document Control Branch (Document Control Desk). 2pp. 47797:236-47797:236

V. Operator Examinations

8612140065 Forwards revised agenda for annual operator licensing innering of

880110 Wig end PATE.R.J. Region 5, Old of the Director. 88/12/05 FERNOW,W. Arizona Nuclea Power Project (formerly Arizona Public Servine Co.). Ip. 47786-150-17786-150.

- 8812200334 Forwards Exam Rects 50-528/OL-88-01.50-529/OL-88-01 & 50-530/OL 8801 of exams administrated during was of 881012 & 25 Recurring problem of simulation facility modeling & simulator fidelity was again noted in preparation of exam R.CHARDS,S.A. Region 5, Ofc of the Director, 88/12/08. KARNER,D. Arizona Nucle ar Power Project (formerly Arizona Public Service Co.), 5pp. 47855 235-47858 263
- -8812200336 Exam Repts 50.528/OL-88-01.50.528/OL-88-01.50.530/OL-89-01 or 881012-14-8-25-28 Exam results nine senior reactor operators 8 six reactor operator passed written period of exam Chaireactor operator letted written exam ROYACK M.J. MORRILL.P., JCHNSTON,G. Region 5, Ofci of the Director, 89/12/02 1000pp. 47855-240-47858-263

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8812070009 Advises that Amond 17 to physical security plan consistent w/provisions of
 - 10CFR50 54(p) & acceptable SCARANO,R A. Region 5, Ofc of the Director #89/11/30. KARNER,D B. Arizona Nu clear Power Project (formerly Arizona Public Service Co.). 4pp. 47749:233-47749:236
- 8812210086 Forwards Security Insp Repts 50 528/89-31,50-529/88-30 & 50-539/88-20 on 860926-1025 & notice of violation.insp repts & notice of violation withheld (re-IOCFR2-700). PATER J. Region 5, Otc of the Director, 88/12/09, KARNER D. Arizona Niiclea Power Project (fermerly Arizona Public Sorvice Co.), 3pp. 47899:022-47889.024

J. Ineurence & Indemnity Information

8812070015 Forwards Endorsement 10 to NELIA Cortificates N-69 & N-107 & Endorsement 10 to MAELU Cortificates M-88 & M-107.

KARNER D.B. Anzona Nuclear Power Project (formerly Anzona Public Service Co.) 88/11/30. Document Control Branch (Document Control Dest), 25pp 47749.278

P. Operating licenso stage documents & correspondence

- 8811300080 Nutilication of significant moeting on 881201 in Wintersburg,A2 to roviousl action on NTC concerns.

 * Region 5, Ofc of the Director, 88711721 Region 5, Ofc of the Director, 2pp. 47696-240-47698-281.
- 8811300138 Notification of 881209 mosting w/util in Rockvilla,MD to present engineer
- ing excellence program

 DAVIS,M.J. Project Directorate V. 88/11/21. Project Directorate V. 5pp. 47670 264
- 8811280046 Generic 1.tr 88-20 to all liconsees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for sovere accident vulnerabilities Svc 19 anct.
- CRUTCHFIELD,D. Associate Director for Projects (Post 670411) 66/11/23. Consolidated Edison Co. at New York, Inc. 81pp. 47728:303-47728:024
- 8812070135 Forwards EGG-NTA-7432, "Conformance to Generic Ltr 83-28, Item 2.2 "Equipment Classification for all Other Safety- Related Components," Pale Verde Unit 1.2 8-3." Response acceptable. CHANTLL Project Directorate V. 86/11/29, KARNER, D.B. Arizona Nuclear Power Project (formerly Arizona Public Service Co.), 4pp. 47747:123-47747:147.
- -8811220443 "Conformance to Genetic Ltr 83:28,Item 2:21 Equipment Classification of All Other Safety-Related Components, Palo Verdo Units 1,2 & 3," informal republy, AC, E08G Idaho, Inc. [subs. of EG&G, Inc.), UDY, AC, Idaho National Engineeing Laboratory, FIN D-6001, EGG-NTA-7432, 88/02/29, NRC No Detailed Affrance Given, 21pp, 47747:127-47747, 147.
- 8812160132 Requests response to Generic Lir 88-17 re loss of shuldown cooling co-current w/significant core decay heat industry response to Generic Lir 87-12 deficient a great of prevention of accident initiation & militation of accidents MURLEY,T.E. Direct of Nuclear Reactor Regulation, Director (Post 870411) 88/12 02. DEMICHELE,O.M. Arizona Nuclear Power Project (formerly Arizona Public Servic Co.). 3pp. 47830:129-47830:131.

Q. Inspection reports, IE Bulletins & correspondence

- 8812050202 Forwards Insp. Repts. 50-528/88-33,50-529/88-32 & 50-530/88-31 c 880919-23.No violations noted Continuing need for improvement in area of occup tional radiation protection indicated Ref made to 10CFR19-15,19-16 & 19-20 SCARANORA, Region 5, Otc of the Director. 80/11/15, KARNERI,D.B. Arizona Niclear Power Project (formorly Arizona Public Scruce Co.). 2pp. 47731-055-47731-06
- -8812050204 Insp. Repts 50-528/88-33,50-529/88-32 & 50-530/88-31 on 88091 23.No violations or deviations noted Major areas inspected followup of open items into notices followup of enforcement items & review of Allegation 88-RV-A 0041 CILLISM, NORTH,H.S. Region 5, Ofc of the Director, 88/11/15, 10pp, 47731:0547731.068.

8811160211 NRC Info Notice 88 090 "Unaulticrized Removal of Industrial Nuclear Gauges" See list enci. CUNNINGHAM,RE Division of Industrial 8 Medical Nuclear Safety (Post 870728) 88/11/22. Consolidated Edison Co. of New York Inc. 99pp. 47708:255-47708 257.

- 8811160467 NRC Into Notice 69-691, "Improper Administration & Control of Psychological Tests " Syc fist end. ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Colid Fig. 10 (1016) 47708-042-47708-142.
- 8812070073 EN-88-103.cn 881201 notice of proposed emposition of civil penalty in amount of \$250,000 will be issued to I censee based on problems in areas of plant operations & rad o'og cal controls LUEHMANU Offic of Enforcement (Post 870413) 88/11/29 2pp 47746:081-47746 082
- 8812210017 Forwards Insp Repts 50-528/88-32,50-529/88-31 & 50-530/88-30 on 880918-1105 & notice of violation. Number of observations made by inspectors indicate personnel not consistently adhering to procedural requirements.

 PATE,R.J. Region 5, Ofc. of the Director, 88/11/30, KARNER,D.B. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 3pp. 47881:032-47881.060.
- -8812210023 Insp. Repis 50.528/88.32.50-529/88-31 & 50-530/88.30 on 880818-1105 Violetions insted Major lareas inspected, previously Identified interspection of plant activities ESF sys walkdowns, surveillance testing & plant maint. POLICHT., COE.D., FiORELLI,G. Region 5, Cit. of the Director 88/11/30, 24pp 47881-037-47881-060
- 8812190171 Discusses Insps Repts 50:529/88:14,50:529/88:22, 50:528/88:24,50:529/88:28,50:528/88:30,50:528/88:35, 50:529/68:37 & 50:530/86:33 on 680520:1012 & forwards two notices of vioration & proposed imposition of civil penality MARTIN J.B. Region 5, Otc of the Director #8/12/01 KARNER D.B. Artzona Nuclear Power Project (formerly Artzona Public Service Co.). 4pp. 47850:224:47850:238
- -8812190178 Notice of violation 8 proposed imposition of civil ponatty in amount of \$200,000 Violations noted individual received accumulated whole body dose of 3 20 rem for Second Querter 1988 & ALARA meetings not titlet from Mar 1987 Jul 1988. MARTIN, J B. Region 5, Old of the Director, 88/12/01, 7pp 47850/230-47850/236.
- 8811290030 NRC Info Notice 89-093, "Telotherapy Events" Svc 1st enct.
 CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729).
 88/12/02. Consolidated Edison Co. of New York, Inc. 112pp. 47811.103-47811:215
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc fist encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708 143-47708.254.
- 8812190413 Forwards Insp. Repts 50-528/68-40,50-529/68-39 & 50-530/68-38 on 881031-1104 & notice of violation. One activity was not conducted in full comphance w/NRC requirements.
 YUHAS,G.P. Region 5, Ofciot the Orractor, 88/12/02, KARNER,D.B. Arizona Nictear Power Project (formerly Arizona Public Service Co.), 2pp. 47850-345-47850-358.
- -8812190414 Notice of violation from Insp. on 881031-1104 Violation inpled flowing for for Environ Sampling Station 15 & 14a returned to svc w/o having been adjusted to 1.5 contelliment failure mode. YUHAS,G P. Region 5, Old of the Director, 68/12/02, 2pp. 47850.347-47850.348
- ~8812190415 Insp Flepis 50.528/88-40.50-529/88-39 & 50.530/86-36 on 881031-1104. Violation noted Major areas inspected environ protection, followup & tours of fa-
- CHANGE G.R., NORTH.H.S. Region 5, Old of the Director, 88/11/29, 10pp. 47850 349 47850 358
- 8812210028 Forwards Insp. Repts 50:528/88:39,50:529/88:38 & 60:530/88:37 on 881031-1104 No vibrations noted RICHARDS,S.A. Region 5, 01c of the Orector 88/12/95. KARNER,D.B. Arizona Nuclear Power Project (termerly Arizona Public Service Co.): 2pp. 47890:105-47890:118.
- #8812210035 Insp Repts 50-528/86-39,50-529/88-38 & 50-530/88-37 on 881031-1104,No violations noted Major areas inspected various vital areas and equipment & assessment of followup Rems & LERs, BURDOIN,J.F. Regton 5, Ofc of the Director, 88/12/05, 12pp. 47890-107-47890:118.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licenseas on Vandors." Svc i'st end ROSSI, CE. Dwiston at Operational Events Assessment (Post 870411). 88/12/08. Consolidated Edison Co. of New York, Inc. 112pp. 47807:191-47807:302.
- 8812200334 Forwards Exam Repts 50-528/OL-88-01,50-529/OL-88-01 & 50-530/OL-88-01 of exams administered during wks of 881012 & 25-Recurring problem of simulation facility modeling & simulator fidelity was again noted in preparation of exam. RICHARDS,S.A. Region 5. Ofc of the Director, 88/12/08. KARNER,D. Artona Nuclear Power Project (formerly Arizona Public Service Co.). Spp. 47855 235-47658 283.
- --8812200335 Exam Repts 50-528/O1-88-01;50-529/OL-88-01;50-530/OL-88-01 on 881012-14-8 25-28.Exam results nine senior reactor operators & six reactor operators passed written portion of exam One reactor operator fatted written exam. ROYACK M.J. Region 5. Ofc of the Director. 88/12/02. 1000pp. 47855:240-47858 263
- 8812210066 Forwards Security Insp Repts 50-528/88-31,50-529/88-30 & 60-530/88-28 on 880926-1025 & notice of violation. Insp repts & notice of violation withheld (ref 10CFH2.790).

 PATE,R.J. Region 5, Ofc of the Director, 68/12/09, KARNER,D. Anzona Nuclear Power Project [formerly Anzona Public Service Co.). 3pp. 47889:022-47889:024.
- R. Periodic operating reports & related correspondence
- 8812190278 Monthly operating repts for Nov 1988 for Palo Verda Nuclear Generating Station Units 1,2 & 3 W/881215 ftr.
 BORST,S.G., HAYNES,J.G. Arizona Nuclear Power Project (formerly Arizona Public Service Co.), 8B/11/30 18pp, 47850 302-47850.317.

V. Operator Examinations

- 8812140065 Forwards revised agenda for annual operator licensing monthing on 890110.W/d end. PATE,RJ. Region 5, Old of the Director 88/12/05 FERNOWW Arizona Nuclear Power Project (formerly Arizona Public Service Co.) 1p. 47796 150-47796 150.
- 8812200334 Forwards Exam Repts 50-528/OL-88-01,50-528/OL-88-01 & 50-530/CC-88-01 of exams administered during wiks of 881012 & 25.Recutring problem of suring a tion facility modeling & simulator fidelity was again noted in proparation of example RICHARDS,S.A. Region 5, Oto of the Director, 88/12/08 KARNER D Ar conamics at Power Project (formerly Arizona Public Service Co.), 5pp. 47855;235-47559-263
- -6812200335 Exam Repts 50-529/OL-88-01,50-529/OL-88-01,50-539/OL-58-01 on 881012-14 & 25-28 Exam results: nine senior reactor operators & six reactor operators passed written portion of exam. One reactor operator failed written exam ROYACK.M.J., MORRILL.P., JOHNSTON,G. Region 5, Ole of the Circuit 88/12/02 1000pp. 47855:240-47858:263.

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

A. Application/construction stage documents & correspondence

8811280048 Generic Ltr 88-20 to all licensees holding OLs & CPs for nuclear power reactor facilities re-individual plant exam for severe accident vulnerabilities SVC 131 CRUTCHFIELD,O. Associate Director for Projects (Post 870411), 88/11/23. Consyl-dated Edison Co. of New York, Inc. 81pp. 47728:303-47729.024

DOCKET 50-601 RESAR SP/90

A. Application/construction stage documents & correspondence

- 8812020013 Provides responses to review of resolution of USIs & generic eafety is sucision RESAR SP/80,por 881027 request. for RESAR SP/80,por 881027 request. 8AGCHI.G. Structurei & Geosciences Branch. 88/11/18. MILLER,C.L. Standardization & Non-Power Reactor Project Directorate. 2pp. 47722:188-47722 189
- 8811300223 Provides guidance re-scope of design & NRC review of RESA9 SP/90 design.Washinghouse Intends to apply for design certification for RESA1 SP/90 design currently inhouse for protiminary design approvide. CRUTCHFIELD,D. Associate Director for Projects (Post 870411) 83/11/22 JOHNSON,W.J. Westinghouse Electric Corp. 8pp. 47680.161-47680 168
- 8812220309 Summary of 881108-09 meetings to approach to be used during review of USIs & medium & high priority generic safety issues for RESAR SP/00 design List of meeting attendage & viewgraphs and.

 KENYON,T.J. Standardization & Non-Power Reactor Project Directorate 63/12/03 MILLER,C.L. Standardization & Non-Power Reactor Project Directorate 15cp 47900:100-47900:114.

R. Periodic operating reports & related correspondence

8812060315 Forwards status ropt for Nov 1980 re std plant design technical reviews MILLER,C.L. Standardization & Non-Power Reactor Project Directorate, 83/11/23 SHAQ,L. Division of Engineering & Systems Tochnology (Post 870411), GR MES,R Olwision of Reactor Inspection & Safeguards (Post 870411), CONGEL, Dirision of Reddiation Protection & Emergency Proparadness (Post 870411), 15pp. 47742 200-47742234

DOCKET 50-802 UNIV. OF TEXAS RESEARCH REACTOR

A. Application/construction stage documents & correspondence

8812080065 Application for amend to CPRR-123,extending final completion date to 891231.
BAUER,T.L., KLEIN,D. Texas, Univ. of, Austin, TX. 88/11/23, ADAMS,A Olico of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 47753:164-47753.165.

DOCKET 60-603 ALCHEMIE FACILITY 1 - CPDF

A. Application/construction stage documents & correspondence

- 8812190093 Forwards environ assessment & finding of no significant impactive 38-0-917 request for exemption from 10CFR50.34(a)(10),80 30(b)(6)(c) & App E. ROUSE, L.C. Fuel Cycle Safety Branch. 88/12/07. SMELSER, J.H. All Chemical 4-so-tope Enrichment, Inc. 1p. 47849:145-47849:156.
- ~8812190098 Environ assessment & finding of no significant impact re consideration of issuance of exemption from requirements of 10CFR60.34(a)(10),50 34(a)(0),♥ ♣ App CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Fost 670729) 88/12/07. 3pp. 47849:146.47849:148.
- -9812220045 Environ assessment & finding of no significant impact re consideration of issuance of exemption from requirements of 10CFR50.34(a)(10),50.34(b)(8)(i) & App
 - C.UNNINGHAM,R.E. Division of Industrial & Medical Nuclear Salety (Post 870729) 88/12/07. 8pp. 47849;149-47849;156.
- 8812210125 Responds to 881028 ftr to Chairman Zech on expeditious processing of the cense application of AlChemiE. Understands negotiations to accommodate schedule in contract underway & progressing satisfactority.

 STELLOV. One of the Executive Director for Operations. 88/12/13. CLENENT, B. House of Rep. 1p. 47875:067-47875:068.

185

G. Adjudicatory correspondence

- 8812020067 Memorandum memorializing telcon of 881121.* Discusses Board 881121 telcon w/counsel for parties re-proheating & scheduling matters Served on 881123 MARGULIES M.B. Atomic Saloty and Licensing Board Penel. #488 7552. 88/11/22 3pp 47643 204-47643:206
- 8812020072 Lists questions raised by Board study of Iconsee environ repts on tacilities, for responses & comments, Served on 881125 MARGULIES, M.B. Atomic Safety and Liconsing Board Panel. #488 7551. 88/11/23 BOADENICK, B.M. Assistant General Counsel for Hearings. IRVING, S.A. All Chemical Isotope Enrichment, Inc. 2pp. 47643,207-47643 208.
- 8812140019 Memorandum memoralizing 881129 tolcon * Applicant & NRC agreed to submit joint proposed findings of fact & conclusions of law Served on 891202 MARGULES,M.B. Atomic Safety and Licensing Board Panel #488 7603, 88/12/01. 3pp. 47770.243-47770 245.
- 6812140025 Notice of hearing.* Notifies that hearing to be held in CP application pro-ceedings on 881221 cancelled & rescheduled to commence on 890104.Served on 801202. MARGULIES,MB Atomic Safety and Licensing Board Panel. #489 7604. 88/12/01. 1p 47770 242-47770 242.
- 8812140045 Notice of reconstitution of Board * Board reconstituted by appointing FJ Shon In place of EA Luebko as administrative judge Served on 881202 COTTER,8 P. Atomic Safety and Liconsing Board Panel. #488 7607. 88/12/01. 2pp 47770-239-47770-240.
- 8812190119 Forwards NRC supplementary testimony of JJ Swift,addressing ASLB in-quiries of 881018 & two attachments Encl suppls 881104 testimony. 6ORDENICK,B.M. Assistant General Counsel for Hearings. #468-7641. 88/12/08. MARGULIES,M.B., SHON,F.J., PARIS,O.H. Atomic Safety and Licensing Board Panel. 1p. 47801:144-47801:149.
- ~8612190126 NRC Statt supplementary testimony of JJ Switt addressing ASLB inquiries of 881018.* Proposed use of Oliver Springs site compatible w/protection of endangered or threatened species Related Info end; SWET,J.J. Office of the General Courset 88/12/08, 6pp. 47801:145-47801:149.
- 8812190136 Forwards NRC 681202 ltr to applicant for Info. 6OROENICK B.M. Assistant General Counsel for Hoarings #468-7642. 66/12/66. MARGULIES,M.B., SHON,F.J., PARIS,O.H. Atomic Safety and Licensing Board Panel. 2pp. 47801:123-47801:124.
- 8812190105 Forwards proprietary NRC testimony of WG Burnside & CB Sawyer addressing ASLB linguiries of 861116 & three attachments Encl withhold BCRDENICK B.M. Assistant General Councel for Hearings. #488 7639. 88/12/07. WARGULIES, M.B., SHON, F. J., PARIS, O.H. Atomic Safety and Licensing Board Panel. 1p. 47801:163-47801:163.
- 8812190041 Memorandum memorializing tolcon of 881207.* Parties advised that Board has no Intentitons to make site visits. Another prehearing tolcon schoduled for 891220. Served on 891209.

 MARGULES.M.B. Atomic Solety and Licensing Board Panel. #488 7652. 88/12/08. 2pp 47802-065-47802.056.
- 8612190211 Forwards NRC Staff 880817 environ assessment & finding of no significant impact. In connection w/applicant request for exemption from provisions of 10CFR50.34(a)(10), 50.30(b)(6)(v) & 10CFR50.34(a)(10), 50.30(b)(6)(v) & 10CFR50.34(a) Formal Provisions of BORDENICK, B.M. Assistant General Counted for Hostings. #488 7671. 88/12/12. MARGULIES, M.B., SHON, F.J., PARIS, O.H. Atomic Safety and Licensing Board Panel.
- 14pp. 47801:005-47801:018.
- 8812280185 Forwards NRC testimony of JJ Swift addressing ASLB inquirtes of 981118 & responses of AlChemiE to ASLB Inquiry of 881123. NRC will present testimony at hearing scheduled to commence on 890104. BORDENICK,B M. Assistant General Counsel for Hearings. #488 7750. 88/12/20. MARGULES,M B., SHON,F.J., PARIS,O.H. Atomic Safety and Liconsing Board Panel. 4pp. 47884-265-47884-270.
- --8812280178 NRC Staff testimony of JJ Swift addressing responses of AlChemiE to SALB Inquiry 1 of 861123.*
 SWIFT,J.J. Office of the General Counsel. 68/12/20. 2pp. 47884:269-47884:270.
- 8812280186 Forwards proprietary Part A & nonproprietary Part B to SSER 1 for const mod & licensing of Oak Ridge facility & for CP for Oliver Springs facility.Part A withheld.
- BORDENICK,B.M. Assistant General Counsel for Hearings. #488 7751, 88/12/20. MARQULIES,M.B., SHON,F.J., PARIS,O.H. Atomic Satety and Licensing Board Panel. 8pp. 47884:271-47884:278.
- 6612280134 Advises that NRC contemplating having all witnesses, AT Clark, JJ Swift & C8 Sawyer, w/exception of WG Burnside & JC Petersen, physically prosent at hearing in Knoxylite, TN to commence on 890104.
 BORDENICK BM. Assistant General Counsel for Hearings. #488 7746. 88/12/21. MARGULIES, M.B., SHON, F.J., PARIS, O.H. Atomic Safety and Licensing Board Panel. 4pp. 47985, 180-47885, 183.

I. Financial information

- 8811300437 Confirms 881118 telcon re financial assurances. AlChemite 881111 submit-tal did not provide financial assurance into that satisfies decommissioning regulation. Addit into required. SWIFT.J.J. Fuel Cycle Satety Branch. 88/11/21. SMELSER, J.A. All Chemical Isotope Enrichment, Inc. 2pp. 47930:254-47930:255.
- 8812060231 Confirms 881202 telcon to draft trust agreement provided on 881129. Agreement in concert w/tlr of credit acceptable in principle & meets NRC decommissioning rule amends.
 ROUSE, L.C. Fuel Cycle Safety Branch. 88/12/02. SMELSER, J.H. All Chemical Isotope Enrichment, Inc. 1p. 47783:283-47783:283.

T. Hearing transcripts on non-antitrust matters

8811280173 Transcript of 881121 telcon in Bethesda,MD re AlChemiE. Pp 70-100.

* Atomic Safety and Licensing Board Panel. 88/11/21, 33pp. 47653:277-47653:309.

- 8812020229 Transcript of 881129 prehoering telcon in Bathesda,MD. Pp. 101-142
 * Atomic Safety and Ucensing Board Panel. 88/11/29. 44pp. 47711:310-47711.353.
- 8812060050 Transcript of 881201 hearing in Bethesda,MD Pp 143-152
 * Atomic Safety and Licensing Board Panel 88/12/01, 12pp 47742 340-47742 351
- 8812190119 Forwards NRC supplementary test mony of JJ Swift addressing ASLB In-quirles of 881018 & two attachmonis Encl supple 881104 testimony BORDCNICK,8 M. Asyldant Gonera' Councel for Hearings #489 7641 68/12/06 MARGULIES,M.B. SHON,F.J., PARIS,O.H. Atomic Safety and Licensing Board Panel 1D 47801:144 47801:149.
- --8812190126 NRC Staff supplementary test meny of JJ Swift addressing ASLB Inquiries at 881018.* Proposed use of Oliver Springs site computitile w/protection of andangored or threatened species Reliated and entil SWIFT,
- 8812280165 Forwards NRC testimony of JJ Switt addressing ASLB inquiries of 881116 & responses of AlChernte to ASLB inquiry of 891123. NRC will prosent testimony at hearing scheduled to commence on 890104. BORDENICK,B.M. Assistant General Coursel for Hearings, #489, 7750, 89/12/20. MARGULIES,M.B., SHONE J., PARIS,O.H. Atomic Safety and Licensing Goard Panel 4pp 47884 265 47884 270
- ~8812280178 NRC Staff test mony of JJ Swift addressing responses of AfChemIE to ASLB Inquiry 1 of 881123.* SWIFT, J.J. Office of the General Counset 68/12/20. 2pp. 47884 269-47884 270

DOCKET 50-604 ALCHEMIE FACILITY 2 - OLIVER SPRINGS

A. Application/construction stage documents & correspondence

- 8812010373 Forwards "AlChomile Facility 2 Oliver Springs Ecological Survey," per 881117 request re-evidence of threatened or endangered species THOMPSON,H.L. All Chenical Isologo Enrichment, Inc. 88/11/21, SMELSER,J.H. Office of Nuclear Material Safety & Safeguards,Director 2pp. 47703:215-47703:272.
- --8812010376 "AIChiemiE,Inc Facility 2 Oliver Springs Ecological Survey."

 * EDGo Group, 88/11/18. All Chemical Isotope Enrichment, Inc. 28pp. 47703:217-47703:272
- 8812120055 D'scusses survey of flora & fauna conducted at Olivor Springs site on 881111 Area not appropriate habitat for any federally threatened or endangored plant species. List of endangored plant species known to occur on reservation enci. HAMMELMAN, J.E. Science Applications International Corp. (termotly Science Applications, Inc.). 89/12/05. SWIFT, J.J. Division of Industrial & Medical Nuclear Safety (Post 870728). 4pp. 47780.142-47780.145.
- 8812190093 Forwards environ assessment & finding of no significant impact to 880817 request for examplion from 10CFR50 34(a)(10),50 30(b)(6)(v) & App E. ROUSE, L.C. Fuol Cycle Saloty Branch. 88/12/07. SMELSER,J.H. All Chemical Isotope Enrichment, Inc. 1p. 47849 145-47849-156.
- --0812220045 Environ assessment & finding of no significant impact to consideration of Issuance of exemption from regulterments of 10CFR50 34(a)(10),50.34(b)(6)(v) & App. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/12/07, 8pp, 47849:149-47849:158.
- 8812210125 Responds to 881026 fir to Chairman Zech on expeditious processing of Ni-cense application of AlChemie. Understands negotiations to accommodate schedule in contract underway & progressing satisfactority. STELLOV. Oic of the Executive Director for Operations 88/12/13. CLEMENT, B. House of Rep. 1p. 47875.067-47875:068.

G. Adjudicatory correspondence

- 8612260134 Advises that NRC contemplating having all witnesses, AT Ctark, JJ Swift & CB Sawyer, w/oxception of WG Burnsido & JC Petersen, physically present at hearing in Knoxville, TN to commence on 890104.

 BORDENICK, B.M. Assistant General Counsel for Hoerings. #488 7746. 86/12/21.

 MARGULIES, M.B. Atomic Safety and Licensing Board Panel 4pp. 47896:180-47898-180. 47886:183.
- 8812020067 Memorandum memorializing telcon of 881121.* Discusses Board 681121 lelcon w/counsel for parties re prohearing & scheduling matters Served on 881123. MARQULIES,M.B. Alomic Safety and Licensing Board Panel. #488 7552 68/11/22. 3pp. 47643:204.47643:208.
- 8812020072 Lists questions raised by Board study of licensee environ repts on facilities, for responses & comments Served on 881125.

 MARGULIES, M.B. Atomic Safety and Licensing Board Panet #488 7581, 88/11/23, BORDENICK, B.M. Assistant General Counset for Hearings, IRVING, S.A. All Chemical Isotope Enrichment, Inc. 2pp. 47843:207-47643:208.
- 8812140019 Memorandum memoralizing 881129 telcon.* Applicant & NRC agreed to submit joint proposed findings of fact & conclusions of law Served on 881202. MARGULES,M.B. Atomic Safety and Licensing Board Panel. #488 7603. 3pp. 47770 243-47770 245.
- 8812140025 Notice of hearing.* Notifies that hearing to be held in CP application proceedings on 881221 cancelled & rescheduled to commence on 890104. Sorved on 891202. MARGULIES,M.B. Atomic Satety and Licensing Board Panel. #488 7604, 88/12/01.
 - 1p. 47770 242-47770 242.
- 8812140038 Notice of reconstitution of Board.* Board reconstituted by appointing FJ Shon in place of EA Luebke as administrative judge. Served on #81202. COTTER,B.P. Atomic Salety and Licensing Board Panel. #488 7606. 88/12/01. 2pp 47770:237-47770:238.

- 8812190119 Forwards NRC supplementary testinony of JJ Swift, addressing ASLB in-quiries of 881018 & two gittechments Enclis pprs 881104 testinony, BORDENICK BM. Assistant General Coursel for Hearings #486 7641, 68/12/06 MARGULIES, M.B., SPCN, F.J., PARIS, O.H. Alomic Safety and Licensing Board Panel 1p. 47601:144-47801:149
- -8812190126 NRC Staff supplementary testimony of JJ Swift addressing ASLB inquiries of 651018.* Proposed use of Civer Springs site compatible w/protocol of endangered or threatened species.Related into end
- WiFT_J J, Cff ce of the General Counsel 88/12/06 5pp 47801 145 47801 149.
- 8612190136 Forwards NRC 881202 lit to applicant/for info. BOMBENICK, B.M. Assistant General Counsel for Hearings. #466, 7642, PR/12/06. MARGUELES,M.B., SHON,F.J., PARIS,O.H. Atomic Safety and Ulcensing Board Panel. 2pp. 47801 123-47801 124.
- 8812190105 Forwards proprietary NRC tostimony of WG Burnsido & C8 Sawyor addressing ASLB inquirios of 881116 & three attachments First withheld.
 BRHDENICK BW. Assistant General Counsal for Hearings. #498, 7609, 88/12/07
 MARGULIES,M.B., SHON,F.J., PARIS,O.H., Atomic Safety and Licensing Board Pane' 1p. 47601 163-47801 163
- 8812190041 Memorandum memorializing teleon of 681207.1 Parties advised that Board has no Intentions to make site visits Another proheating teleon scheduled for 881220.Served on 881209 MARGULIES,M.B. Atomic Safety and Licensing Beard Panet. #488 7652 88/12/08 2pp. 47802.065-47802.066.
- 8812190211 Forwards NRC Staft 880817 environ assossment & Endring of no significant impact in connection whappicant request for exemption from provisions of 10CFR50 34(a)(10), 50.30(b)(6)(v) & 10CFR50,App £
 BCRDENICK B M. Assistant Genoral Counsel for Hearings, #488-7671, 88/12/12 MARGULIES M B., SHON,F J., PARIS,O.H. Atomic Sately and Licensing Board Panel 14pp. 47601:005-47801-018

- 8812280165 Forwards NRC testimony of JJ Swift addressing ASLB inquires of 881116 & responses of AlChemit to ASLB inquiry of 881123 NRC will present testimony at hearing scheduled to commonde on 690104 BORDENICK,B.M. Assistant Gonard Counsel for Hearings. #488.7750-88/12/20 MARGULIES,M.B., SPON,F.J., PARIS,O.H. Atomic Safety and Licensing Board Panel. 4pp. 47881.265-47884:270
- -8812280178 NRC Staff test-mony of JJ Swift addressing responses of AlChemiE to ASLB Inquiry 1 of 881123 * SWIFT,JJ. Office of the General Counsul 88/12/20 2pp. 47884/289-47884/270.
- 8812280188 Forwards proprietary Part A & noupropostary Part B to SSER 1 for const mod & licensing of Oak Ridge facility & for CP for Oliver Springs facility. A with-BORDENICK, B.M. Assistant General Courset to: Hearings #488 7751 88/12/20 MARGULIES, M.B., SHON, F.J., PARIS, O.H. Atomic Safety and Licensing Board Panel 8pp. 47894:271-47894:278
- 8812280134 Advises that NRC contemptating having all witnesses, AT Clark, JJ Swift & CB Sawyer, w/exception of WG Burns do & JC Patersen, physically present at hearing in Knoxylle, TN to commence on 890104. BORDEN: CK, B.M. Assistant General Counsel for Hearings. #488-7746-88/12/21 MARGULIES, M.B., SHON, F.J., PARIS, O.H., Atomic Safety and Licensing Board Panel 4no. 4786-1804-3788-181.

4pp 47886.180-47888.183

i. Financial information

- 8811306437 Confirms 881118 tolcon re-financial assurances AiChom'E 881111 submittel did not provide financial assurance into that satisfies docommissioning regulation.Addit frito required.
 SWIFT.J.J. Foot Cycle Satety Branch. 88/11/21 SMELSER,J.A. All Chemical feotope Enrichment, Inc. 2pp. 47930-254-47930.255
- 8812080231 Confirms 881202 telcon ro dieft trust agreement provided an 881129 Agreement in concert w/ltr of credit acceptation in principle & meets NRC decommissioning rule amends.
 ROUSE, L.C. Fuel Cycle Sefety Branch. 88/12/02 SMELSER, J.H. All Chemical Isotope Ennichment, Inc. 1p. 47763.283-47783-283

T. Hearing transcripts on non-antitrust matters

- 8811280173 Transcript of 881121 telcon in Bethesda MD re AlChemiE. Pp 70-100
 * Atomic Safety and Licensing Board Panel 88/11/21, 33pp 47653 277-47653.309.
- 8812020229 Transcript of 881129 prehearing telcon in Bethesda,MD. Pp. 101-142
 * Atomic Safety and Licensing Board Panel 68/11/29, 44pp 47711.310-47711.353
- 8812060050 Transcript of 881201 hearing in Bothesda,MD.Pp 143-152
 * Atomic Safety and Licensing Board Panel. 88/12/01 12pp, 47742,340-47742,351
- 8812190119 Forwards NRC supplementary testimony of JJ Swill addressing ASLB in-quirios of 881018 & two attachments Encl supple 881104 testimony. BORDENICK, B.M. Assistant General Courisel for Hearings. #488 7641, 88/12/06 MARGULIES,M.B. Atomic Safety and Licensing Board Panel 1p. 47801:144-
- --8812190126 NRC Staff supplementary testimony of JJ Swift addressing ASLB inquiries of 881018.* Proposed use of Oliver Springs site compatible w/protoction of endangered or the satened species Refated Info end SWIFT, J.J. Office of the General Counset 88/12/06. Spp. 47801:145-47801:149
- 8812280165 Forwards NRC testimony of JJ Swift addressing ASLB inquiries of 881116 & responses of AlChemie to ASLB inquiry of 891123. NRC will present testimony at hearing scheduled to commence on 890104. BORDENICK,B.M. Assistant General Counsel for Hearings #488 7750, 88/12/20. MARGULIES,M.B. Atomic Safety and Licensing Squrd Panel, 4pp 47884,285-
- --8812280178 NRC Staff fastimony of JJ Swift addressing responses of AlChemilE to ASLB Inquiry 1 of 881123.* SWIET, JJ. Office of the General Counsel, 88/12/20, 2pp. 47884:268-47884.270.

DOCKET STN-50-605 GE ADVANCED BWR DESIGN

- A. Application/construction stage documents & correspondence
- 8811300135 Provides recently developed into re-scope of future std design approximates 8 of staff review of Advanced BWA CRUITCHIELDO, Associate Director for Projects (Post 870411) 88711722 MARRIOTT.P.W. General Electric Co. 16pp. 47696;239-47696.254
- 8812130262 Forwards responses to 880920,0926 & 1026 requests for eddt info re SSAR for advancer BWR GE proprietary Info withhold MARRIOTT PW General Electric Co. 88/12/09. MILLER C.L. Standard Jabon. & Non-Power Reactor Project Directorate. 166pp. 47795.137.47795.302.

8. Periodic operating reports & related correspondence

8812060315 Forwards status rept for Nov 1988 to std plant design technical reviews MILLER.C.L. Standard attern & Non-Power Reactor Project Directorate 88/11/25 SHAO,L. Division of Engineering & Systems Technology (Post 87041), GRIME 5.8 Division of Reactor Inspection & Safeguards (Post 870411), CONGELE, Division of Reactor Inspection & Safeguards (Post 870411), CONGELE, Division of Reactor Inspection & Emergency Preparedness (Post 870411), 15ep 47742.20) 47742:214

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL.

DOCKET 70-0027 BABCOCK & WILCOX CO., LYNCHBURG, VA

- 8812220078 Forwards revito physical security plan, resulting from NRC/ DOE comparability review 8 expansion of facilities flev withheld (10CFR9 59(a)(11) 80YD.CC Batcock 8 Wilcox Co 88/10/05 SMITH,C N Division of Sateguards 8 Transportation (Post 870413), 2pp. 47903.040-47803.040
- 8812200320 Forwards quurierly rept on procurement of new drum scarmer sys Software mode addressed to mig which will install new aprilware subsequent to receipt of new
- Source BOYO.C.C. Baboock & Wicox Co. 88/10/14. SMITH,C.N. Licensing Branch (870413-881217). 1p. 47867-299-47867-299.
- 8812200322 Forwards proposed Aconse conditions to 10CFR74 requirements per CC Boyd 880930 fit to CN Smith W7o and 80YD, CC. Batacok & Wilcox Co. 80/10/14. SMITH,CN. Dwiston at Saleguards & Transportation (Post 870413), 2pp. 47868 286-47888-287.
- 8812220076 Application for fitting to License SNM-42, revising License Conduct 3 4 at stated, Fee paid GOYD, C.C. Babcock & Wilcox Co. 88/11/17. SMITH, C.N. Licensing Branch (870-413 881217). 2pp. 47803:309.47803:310.
- 8811290366 Discusses thap Rept 70-0027/88-18 & 70-0027/88-26 on 860810- C9-29 & forwards notice of violation & proposed Imposition of civil penalty ERNST,ML Region 2, Otto the Director, 86/11/16, TETRAULT,RE 8abcock & Wilcox Co 4pp 47648 181-47649 190.
- -8811290368 Notice of violation & proposed imposition of civil penalty in an own to \$6,250.Noncompliance noted inconses did not follow nuclear criticality double contin goncy policy incorporated ERNST,M.L. Region 2, Oic of the Director, 88/11/18, 6pp. 47648.185 47648.190
- 8811290454 Responds to violations noted in Insp. Right 70:0027/89:30 on 86:031.Cor rective actions requirements for radiation safety/ monitoring training for campbel County Sheriff Dopt ramoved from RCP & plant omergency toam training conducted TETRAULT.R.E. Babcock & Wiccox Co. 88/11/18. Document Control Branch (Document Control Branch (Document Control Dask). 3pp. 47649.158-47649:160.
- 8812070242 Forwards Insp Rept 70:0027/88:33 on 881024-28.No violations or devia ations noted.

 CLINEW.E. Region 2, Otc of the Director. 88/11/18. TETRAULT, R.E. Belicock & Wilcox Co. 2pp. 47753.081-47763.086.
- -8812070246 Insp. Rept. 70 0027/88-33 on 881024-28 No violations or deviation: noted Major areas inspected nuclear critically safety & operations review & facility general purpose area (KASNICKI,D.A., MCALPINE,E.J. Region 2, Ofc. of the Director. 88/11/18. 4pp 47753 069.
- 8812210356 Forwards insp ftept 70-0027/88-34 on 881025-31.No violations of deviations noted flagt withheld (ref 10CFR2.790(d) & 73-21) CUNE,WE. Region 2, Otc of the Director, 88/11/18, TETRAULT,R.E. Babcock & Wilcox Co. 3pp. 47882-065-47882-068.
- -8812210360 Partially withheld Insp Rept 70.0027/88-34 on 881025-31 (re-10CFR2.790(d) & 73.21).No violations or deviations noted. Major area inspected physical inventory, measurements, facility operations, internet controls & provious findings CLAY, E.L. BATES, J.W., MCALPINE, E.J. Region 2, Ofc of the Director. 88/11/18. 1p 47892:08-47892:088
- 8812140212 Application for amend to License SNM-42,revising Section IV reltadation safety spaces Fee paid.

 BOYD.C.C. Bathocok & Wilcox Co. 88/11/21. ROUSE,L.C. Division of Industrial & Medical Naclear Safety (Post 870729). 8pp. 47821:048-47821.054.
- 8812050296 Ack receipt of 881104 ftr Informing NRC of steps taken to correct voluments of these Rept 70-9027/88-20.

 DECKER,T.R. Region 2, Ofc of the Director, 88/11/25, TETRAULT,R.E. Bebook & Wilcox Co. 1p. 47/31-356-47/31-356

- 8812020293 Grants fi81117 request for extension of 10 days to complete activities required by 10CFR70.51(a) & 74.17 for Jul/Oct 1988 ending physical inventory issues Temporary License Condition TC(MC8A)-6 & revises License SNM-42 BURNETT, R.F. Dwisson of Safeguards & Transportation (Post 870413) 88/11/30 EOYD, C.C. Babcock & Wilcox Co. 1p. 47711.023-47711.023
- 8812060224 Responds to NRC 881110 Itrire violations noted in Insp Rept 70:0027/88-31.Corrective actions lead operators retrained to follow procedures literally & to raceg-nize difference between major & minor repairs TETRALI, T.R.E. Babcock & Wilcox Co. 88/12/01. Document Control Branch (Docu-ment Control Desk). 2pp. 47734 352-47734.353
- 8812190190 Ack receipt of 981118 fit informing NRC of steps taken to correct violations noted in Insp Rept 70.0027/88-30.

 DECKER,T R. Region 2, Ofc of the Director. 88/12/02. TETRAULT,R E. Bebcock & Wicox Co. 1p. 47851:251-47851:251.
- 8812150038 Forwards Amend 17 to License SNM-42 & SER Amend incorporates revised ratiological contingency plan
 ROUSE,L.C. Fuel Cycle Salety Branch 88/12/08. BOYU.C.C. Sequeyah Fuels Corp.
 [subs. of Kerr-McGea Nuclear Corp.), 1p. 47800 252-47800 257.
- -8812150043 Amend 17 to License SNM-0042 for B&W,authorizing use of 30,000 kgs Ulerriched.
 ROUSELL C. Drysion of Industrial 8 Medical Nuclear Safety (Post 870720), 88/12/08 3pp. 47800 253-47800 255.
- -8812/50046 Safety evaluation supporting Amend 17 to License SNM-0042 SOONS A L. Fuel Cycle Safety Branch. 88/12/08. 1p. 47800 256-47800 256.
- -8812150049 Discussos catogorical exclusion for amend request did 880929 Neilher EIS nor environ assessment warranted for proposed action ROUSE,L.C. Fuel Oycle Safety Branch: 89/12/08 Fuel Cycle Safety Branch 1p 47800 257-47800-257.

DOCKET 70-0036 COMBUSTION ENGINEERING, INC., WINDSOR, CT

- 8812220084 Forwards revised security plan for Homelife facility, W/o encl. RODE,J.A. Combustion Engineering, Inc. 88/10/27. GUNDERSEN,G.E. Licensing Brench (870413-881217) 1p. 47913-280-47913-280.
- 8812060247 Application for amond to License SNM-33,making organizational SCHERER,A.E. Combustion Engineering, Inc. 88/11/11 ROUSE,L.C. Fuel Cyclo Safety Branch. 53pp. 47734 278-47734.330.
- 8812080237 Forwards foe for 8B1111 application for amend to License SNM-33,refecting organizational charges.por 10CFR170.31 SCHERER.A.E. Combustion Engineering, Inc. 88/11/14 MCDONALD,W.G. Office of Administration & Resources Management, Director (Post 870412) 1p. 47756 189-47766:189
- 8812200310 Advises that License Condition 1.1 to Saloguards Amend SG-1 to License SNM-33 revised as stated per 881123 request SMITH,C.N. Licensing Branch (870413-881217) 88/12/14. SCHERER,A.E. Combis-ton Engineering, Inc. 1p. 47863:063-47863.063.

DOCKET 70-0135 BABCOCK & WILCOX CO., APOLLO, PA

8811300507 Responds to 881028 ftr re-request for Info on releases of radioactive mails from 8&W Apollo & Parks Township PA B&W has initiated cleanup of contemnated surface & subsurface sof Romelning soil mosts established guideline value RUSSELL.W.T. Region 1, Otc of the Director. 88/11/18. LINKES,S. Affiliation Not Assigned. 5pp. 47674.186-47674:100.

OOCKET 70-0143 NUCLEAR FUEL SERVICES, INC., ERWIN, TN

- 8812140013 Informs of withdrawat of Rev 108 to Section 8 of FNMCP encl w/KD Hensley 880111 lit Refund requested hENSELEY.KD Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 88/02/09. BRACH,E.W. Office of Nuclear Material Safety & Safeguards,Director. 1p. 47799-282-
 - 47769 282.
- 8812140007 Forwards ravised pages of radiological continguncy plan for replacement KNIGHT,8.E. Nuclear Fuol Services, Inc. (subs. of Getty Oil Co.). 88/04/28. ROUSE,L.C. Fuel Cycle Safety Branch. 4pp. 47799.283-47799:288.
- 8812200191 Application for amend to License SNM-124, revising License Condition 2.3 to accommodate preliminary operations involving SNM which must be completed prior to pranted decorralissioning projects Fap paid.

 HENSLEY, K.D. Nuclear Fuel Services, Inc. (subs. of Gotty Oil Co.) 88/09/29.

 SMITH, C.N. Licensing Branch (870413-881217). 3pp. 47868.078-47868.080
- 8812200319 Forwards proposed changes to Section 1.0 of fundamental nuclear matternical plan. Encil withheld (ref. 10CFR2.790(d)). Fee paid HENSLEY,K.D. Nuclear Fuel Servicos, Inc. (subs. of Getty O4 Co.). 08/09/30. SMITH,C.N. Licensing Branch (970413-881217). 1p. 47860:212-47860:212.
- 8612220109 Forwards proposed changes to Section 7.0 of FNMCP.Fee paid. Encl withheld (ref 10CFR2.780(d)). HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty O:I Co.). 88/10/04. SMITH,C.N. Licensing Branch (870413-881217). 1p. 47892.243-47892.243
- 8812200377 Forwards Rev 110 to Section 8.0 to FNMCP.Rev withheld (ref HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 88/10/12. ERNST,M.L. Region 2, Oic of the Director. 1p. 47882 245-47862 245.
- 8812220069 Application for emend to License SNM-124,revising SG-2 Condition 2.12 re highly emilched U-bearing figuld effluents Fee paid. HENSLEY, K.D. Nuclear Fuel Sorvices, Inc. (subs. of Getty Oil Co.). 89/10/14. SMITH.C.N. Licensing Branch (870413-881217) 3pp. 47903.311-47903.313.

- 8812140202 Forwards revised pages to Nov 1988 Rev 6 to radiological contingency plan per Liconse Condition 29. LONGUA Nuclear Fuel Services, Inc. (subs. of Getty OJ Co.). 88/10/28. ROUSE,L.C. Fuel Cyclo Safety Branch. 2pp. 47814-084-47814.124.
- --8812190394 Rev 6 to "Radiological Contingency Plan." JAMES,W R. Fuel Cycle Safety Branch. 88/10/12, 39pp. 47814:086-47814.124
- 8811230183 Forwards Insp Rept 70:0143/88-32 on 881017-20.No violations or deviations rolled. CLINE.W.E. Region 2, Ofc. of the Director, 88/11/04, LONG.J.A. Nuclear Fuel Services, Iric. (subs. of Getty Oil Co.). 2pp. 47623.025-47623.027
- -8811230186 Partially withhold Insp. Rept. 70:0143/88:32 on 881017:20 (ref. 10CFH2 790) No wolld one or deviations noted Major areas inspected facility operations internal controls records & repts & Iollowup Itoms. TODD, G.A., MCALPINE, E.J., Rag on 2, Otc of the Director, 89/11/04, 1p. 47623-027-47623.027
- 8812010099 Forwards Nuclear Fuel Sycs,Inc escraw agreement w/NCNB Natl Bank NEWMAN,N J. Nuclear Fuel Services, Inc. (subs. of Getty Od Col), 887/11/15. ROUSE,L C. Fuel Cycle Safety Branch. 8pp. 47699:331-47699:339
- 8811290528 Requests comments on end draft consolidation of NFS License SNM-124 by 8B1130 BIDINGER,G.H. Office of Nuclear Material Safety & Safeguards,Diractor. BB/11/18 MCALPINE,E.J., LEE,T.D. Rogon 2, Orc of the Director. 15pp. 47662 223-47602.237
- 8811300411 Forwards draft consolidation of License SNM-124 & 51 amends. Requests review & comment on accuracy of document by 881130. BIDINGER, G.H. Foot Cycle Safety Branch. 88/11/18. KNIGHT, B. Nuclear Fuel Services, Inc. (subs. of Getty O.I.Co.). 15pp. 47696.259-47696-272.
- 8812020256 Requests that listed changes be made to Rev 6 to Radiological Contingency plan LONG, J.A. Nucloar Fuel Services, Inc. (subs. of Gelty Oil Co.). 88/11/18. ROUSE,L.C. Fuel Cyclin Safety Branch. 2pp. 47711-120-47711.121.
- 8812220050 Application for amond to Licenso SNM-124 Fee pald.Enct withheld (ref. 10CFR2.790(d))
 HENSLEY,K.D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 88/11/18.
 SMITH,C.N. Licensing Brench (870413-881217) 1p. 47801.116-47001:116.
- 8812090128 Forwards Insp Rept 70-0143/88-34 on 881024-28 No violations noted CLINE,W.E. Regron 2, Old of the Checter 88/11/22 LONG,J.A. Nuclear Fue! Services, Inc. (subs. of Getty OJ Co.). 2pp. 47761:135-47761:137.
- -8812090132 Partially withhold Insp. Ropt. 70-0143/88-34 on 881024-28 (rot 10CFR73.21) No violations noted Major areas inspected protected & matt access ureas compunsatory measures, assessment arids. & access control of personnel MASNYK, D.M. MCGUIRE, D.R. Region 2, Old of the Director. 88/11/21. 1p. 47761.137-47761.137.
- 8812190225 Forwards "SW-R46 Sampting & Analystin Program Nucloar Fuel Svcs Erwin, TN Faculty Suitace Impoundments" LONG, J.A. Nucloar Fuel Servicos, Inc. (subs. of Getty O.I Co.), 88/11/30 LEMMING,E. Tennossee, State of 3pp 47851.001-47851:237.
- -8812190228 "SW-846 Sampling & Analysis Program Nuclear Fuel Sycs, Erwin,TN Facility Surface Impoundments."
 * EcoTok, Inc. 88/11/30, 215pp. 47851 004-47851 237.
- 8812190027 Forwards Insp Rept 70-0143/88-33 on 881011-1118 No violations or deviations noted Unresolved tem identified CLINE W.E. Region 2, Olic of the Director, 88/12/02, LONG, J.A. Nuclear Fuol Serv-loas, Inc. (subs of Galty Ok Co). 2pp. 47840-182-47840, 188.
- -8812190033 Insp Rept 70-0143/88-33 on 681011-1118 No violations or deviations noted Mejor areas inspected facility operations, maint & mode, nuclear criticality safety, redigition protection & redwaste mgl.omergency preparedness & mail control. LEE, T.O., MCALPINE, E.J. Region 2, Old of the Orrector, 88/12/02, 5pp. 47840-164-
- 47840:188. 8812200228 Forwards Rov 113 to Section 4 of FNMCP Encl withheld (rol 10CFR2.78u(d)). HENSLEY(K.D. Nuclear Fuel Services, Inc. (subs. of Gotty Oil Co.). 88/12/05. ERNST.M.L. Region 2, Ofc of the Oriector. 1p. 47888 229 47889:229
- 8812150231 Forwards Insp Rept 70-143/85/35 on 881116-17 No violations or devi-
- DECKER, T.R. Region 2, Ofc of the Director 88/12/08, LONG, J.A. Nuclear Fuel Sorvices, Inc. (subs. of Gotty OT.Co.). 2pp. 47830.145-47830.154. -8812150233 Insp. Rept. 70:0143/88-35 on 881116-17.No violations or deviations
- noted Major arcas inspecied and usinadological emorganicy exercise on 89 1116 KREHJUL, LEE, D., RANKIN,WH. Region 2, Old of the Director. 88/12/07. Spp. 47830:147-47830:154.
- 8812200343 Responds to violations noted in Insp Rept 70-0143/68-30. Corrective actions:retraining conducted for radiation monitors,monitor supervisors & emergency response organization members & tracking sys developed.

 LONGJA. Nuclear Fuel Services, Inc. (sebs. of Getty OT Co.).

 DECKER,T.R. Region 2, Otc of the Director. 3pp. 47868.174-47868.176.
- 8812220030 Trip rept of 881116-17 participation in observing NFS annual emergency oxercise Because of limitation of communications equipment notification of emergency event to offsite agencies not completed in timply feshion Surmary encl. SOONGS, Fuol Cycle Safety Branch. 88/12/12. BIDINGER,G H. Fuel Cycle Safety Branch. 8pp. 47900 237-47800:244
- 8812220034 Ack receipt of 881115 ftr transmitting NFS ascrow agreement w/NCNB Neil Bank. SOONG,S. Fuel Cycle Safety Branch. 88/12/12. NEWMAN,N.J. Nuclear Fuel Services, Inc. (subs. of Gelty Of Co.). 1p. 47892-352-47892-352.

188 DOCKETED HEIR

8812270223 Discusses proposed draft consolidation of ticense conditions to License SNM-124 Licensee to edit 8 revise draft consolidation of conditions for purposes of updating 8 converting conditions to current status of plant operations KNIGHT.BE Nuclear Firel Services, Inc. (subs. of Getty O1 Co.) 88/12/12 ROUSELL C. Fuel Cycle Safety Branch. 3pp. 47926 170-47926 172.

DOCKET 70-0364 BABCOCK & WILCOX CO., APOLLO, PA

8812070255 Application for amend to License SNM-414 detening Mt Vernon site in Mt Vernon, IN from License Conditions 10 & 11. Delated radiological survey results encl.Fee paid CUI BERSON,D.G. Babcock & Wicox Co. 68/11/15 ROUSE,L.C. Fuel Cycle Safety Branch 23pp. 47749.001-47749 021.

8811300507 Responds to 881028 lin re-request for info on roleases of radioactive matis from 88W Apollo & Parks Township PAIB8W has initiated cleanup of contaminated surface & subsurface soil Renaining schimets established guideline value. RUSSELL,W.T. Region 1, Oic of the Director 88711/18. LINKES,S. Alfiliation Not Assigned, 5pp. 47674;186.47674;190

8812150209 Requests that NRC delay action on 881115 request due to need to return ARIS sys to MI Vernon site for next 3 months. Vendor still intends to detate Mi Vernon site from Tecnse as authorized place of use CULBERSON,D.G. Babcock & Wildox Co. 88/12/07. ROUSE,L.C. Fuel Cycle Safety Branch. 3pp. 47826.283-47826.285

DOCKET 70-0371 UNC NAVAL PRODUCTS, INC., UNCASVILLE, CT

8811230228 Application for amend to License SNM 368.formaiting organization change, authorizing modified use of cart, reflecting minor changes in fuel component space 8 authorizing production limits for new fuel design.

GREGG,RI. United Nuclear Corp. (subs. of UNC Resources, Inc.), 88/05/06.

ROUSE,L.C. Fuel Cyclo Safety Branch. 15pp. 47622 233-47622 247.

8811230240 Application for amend to Licenso SNM-368, authorizing modified storage of fuel Fee paid GREGG.R.J. United Nuclear Corp. (subs. of UNC Resources, Inc.). 86/11/11 ROUSE,L.C. Fuel Cycle Saloty Branch 11pp 47622 259-47622 269

8812070221 Application for amend to License SNM-0371,authorizing modified storage of fled & stated organizational changes. Fee paid GREGG.R.J. United Nuclear Corp. (subs. of UNC Resources, Inc.). 88/11/11. ROUSELC Office of Nuclear Material Safety & Safeguards,Director 10pp 47739:332-47739:341.

8812120019 Discusses telcon w/7 Gulman on 881202 re validation of Leonsee nuclear cracarity safety code in error 8 reviol 880506 license amend nocessary. Gulman requested that NRC not reviow application until revisit submitted.
BIDINGER,G.H. NRC - No Detailed Affiliation Given 88/12/06, NRC - No Detailed Affiliation Given 19. 47780.218 47780/218

8812270274 Forwards request for addlinto to prepare environ assessment associated w/881014 request for amend to process full in Bldg Lifesponse requested by

SBUCCLS.
HORN,M.L. Fuel Cycle Safety Branch 88/12/22 GREGG,R. United Nuclear Corp.
(Bubs of UNC Resources, Inc.). 2pp. 47924-248-47924-247.

DOCKET 70-0398 COMMERCE, DEPT. OF, WASHINGTON, DC

8611300398 Application for amend to License SNM-362, changing name from NBS to Natl first of Stds & Technology Add info enct.
PEVEY, L.E. National Institute of Standards & Technology (formarly National Bureau of Standa, 88/10/31, Fuel Cycle Safety Branch, 5pp. 47677 048-47877 052.

8812270238 Forwards Amend 2 to License SNM-362, amending Conditions 1 & 9 to reflect name change to Nati Inst of Stds & Technology & to include date of 881031 re-

spectively.

ROUSEL C. Fuel Cycle Safety Branch, 88/12/22 PEVEY, L.E. National Institute of Standards & Technology (formerly National Bureau of Standa 3pp. 47927:134-47927-146.

-8812270240 Amend 2 to License SNM-362 for Nati Inst of Sids & Technology, authorizing use of listed icensed mail. ROUSELC. Division of Industrial & Medical Nuclear Sefety (Post 870729), 88/12/22. 3pp. 47927:137-47927:144.

~8812270246 SER supporting 681031 and cation for amond to License SNM-362 re-quest to change name of Leasee from NBS to Nati Inst of Stds & Technology, ROBINSON,C Fuel Cycle Safety Branch 88/12/22 1p. 47927:145-47927:145

-8812270248 Informs of categorical exclusion for 881031 request for amend to Licenso SNM-362 to change name on licenso to Nati Inst of Sids & Technology due to passage of Ornibus Trade & Competitiveness Act. ROUSE.L.C. Fuel Cyclo Safety Branch. 89/12/22. Fuel Cyclo Safety Branch. 1p. 47927;146-47927;146.

DOCKET 70-0822 ARMY, DEPT. OF, DOVER, NJ

8812220022 Application for amends to Licenses 29 00047-02,29-00047-06, 29-00047-08,28-00047-09,SUB-348 & SNM-581,authorizing R Moss as alternate radiation protection officer. Dept of 88/11/22. Region 1, Ofc of the Director. 11pp.

47902:333-47902-343

8812060322 Forwards Amend 1 to License SNM-991 & SER.Amend adds License Condition 19 re-physical protection pien ROUSE,L.C. Fuel Cycle Safety Branch 88/12/01, ELLIOTT,J.E. Army, Dept. of, Armsment Research & Development Command, 1p. 47741:040-47741.046

-8812060327 Amend 1 to License SNM-561 for Dept of Army, US Army Armament Research & Dovelopment Command revising license in entirety.

ROUSE L.C. Division of Industriel & Medical Nuclear Safety (Post 870729) 88/12/01.

2pp. 47741:041-47741 042 -8812060326 Safety evaluation supporting licensee 880727 application for arms//11a Cense SNM-561 to physical security plan ROBINSON,CH Fuel Cycle Safety Branch, 88/12/01, 1p. 47741 C43 47741,C43

-8812050330 Comments on Idensea 880727 submittal of revised physical securities Revised plan adequately addressed INRC comments & meets requirements of 10CFR73 67(d). Recommends approval of socurity plan GALLEGOS.R.C. Licensing Branch (870413-881217). 88/CB/06. MCCORKEE.3 Licensing Branch (870413-881217). 1p. 47741:044-47741:044.

--8810190472 Requests that stated License condition re-physical security ctan be abtent to License SNM-561,per 10CFR73-67(d).
MCCORREGOW. Licensing Granch (870413-881217) 88/08/09 RCUSELLC. Fuel Cycle Safety Branch 1p. 47741.045-47741:045.

-8809020051 Requests that fisted ficonse condition be added to License SNM-561 4

DOCKET 70-0687 CINTICHEM, INC., TUXEDO, NY

8812220104 Requests fee for 880921 application for route approvel W/a 10CFF1173 JACKSON,G. License Fee Management Branch. 88/11/02 FIART,H.C. Critic hern, Inc. 2pp. 47903 065-47903 069

--9812220100 Requests approval of route for shipment of 24 MTR type spent food etemonts using BMI-1 USA/5957/Bt JF shipping cash to Savannah River reprocessing plant which was previously used in Dec 1987.
HARTHC Cintichem, Inc. 88/09/21. HILLMAN.C. Transportation Stranch 269 47903 068-47903.069

8812120034 Forwards Matt Control & Accounting Insp 70-0687/89-07 ch 881 101-0416 violations noted BELLAMY,R.R. Region 1, Old of the Director, 88/12/01, MCGOVERNUL Canachim Inc. (subst of Med. Physics, Inc.). 2pp. 47797.354-47797.360

-8812120035 Insp Rept 70-0687/88-07 on 881101-04 No violations neted. Major areas

inspecied facility organization & mgt controls, facility operations & International Controls, physical inventory & records & repts.

DELLA RATTAA, JACKSON,R, TING,P, Region 1, Oto of the Director, 88/12/61 5pp. 47797 356 47797 360

DOCKET 70-0734 GENERAL ATOMICS, SAN DIEGO, CA

8812130293 Forwards revised pagos for physical protection plans. W/o cro's ASMUSSEN, K.E. General Atomics (formerly GA Technologies, Inc./General Atomic Co.), 88/03/11, MARTINUE, Region 5, Ofc. of the Director 2pp. 477/88

8812140208 Requests approval to ship 16 TRIGA fuel elements from Rb a MO to Sa-Diego.CA.Licensee will send two specialists to Univid MO to direct 8 assist in pack aging 8 shipping of fuel elements fee poid ASMUSSEN,KE. General Atomics (formally GA Tuchnologius, Inc /General Atomics Co). 88709708 ROUSELLC., MCCAUGHEY,D.A. Fuel Cyclo Safety Branch. 350 47821 055-47821 056

8812070026 Application for amend to Liconse SNM-696,authorizing stated addd address for shipping & recoving Fee paid.
ASMUSSEN K.E. General Atomics (formerly GA Technologies, fnc./General Atomic
Co.), 88/11/02, ROUSE,L.C. Office of Nuclear Material Safety & Safeguards, Dulector 4pp. 47747 089 47747 092

8812010285 Forwards Safety Insp. Rept. 70-0734/88-09 on 881024-28 No. violations noted.
YUHAS,G.P. Region 5, Old of the Director, 88/11/25, RADEMACHERR N. (Berchal Atomics (formerly GA Tochnologies, Inc./General Atomic Co.), 2pp. 47699-258-47699:271.

-8812010287 Insp Rept 70-0734/88-09 on 881024-28.No violations noted. Major areas inspected followup on Inspector identified items.mgt organization & confols.operator training & retraining.cm/cality safety & emergency preparedness. BROCKBL, PRENDERGAST,K, FISH.R. Region 5, Ofc. of the Carector 88711725

12pp. 47698;260-47698:271.

8812090101 Forwards "Confirmatory Survey of Phase IV Decommissioning Glocinal Atomics,San Dega,CA," final rept. EERGER,J.D. Oak Ridge Associated Univs. 88/11/30 THOMAS,B. Region 5, Ofcical the Director, 2pp. 47782-110-47782:197.

-8812090104 "Confirmatory Survey of Phase IV Decommissioning General Atomics, San Diego.CA," final ropt.
COTTEN.P.R. Oak Ridge Associated Univs. ORAU 88/J-79, 88/11/30, 87cp.
47782.111-47782:197.

8812210040 PNS-V-88-008:on 881212.discovered lesser quantity of SNM in contained stored under tampersating than indicated on mail accounting records licer sets or process of opening each of 20 containers to assure accuracy of SNM containers to assure accuracy of SNM containers of S 47881:161-47881:162

DOCKET 70-0820 UNC RECOVERY SYSTEMS, WOOD RIVER JUNCTION, RI

8812010402 "Annual Split Samples." " UNC Recovery Systems: 88/11/28, 45pp. 47710:126-47710:170

8812020016 Summary of 881117 monthing w/United Nuclear Corp in Rockwitte MD restatus of decommissioning for Wood River Junction facility.

HORN,M.L. Fuel Cycle Safety Branch, 88/11/30, Fuel Cycle Safety Branch, 5pp 47707:243-47707:247.

DOCKET 70-0824 BABCOCK & WILCOX CO., LYNCHBURG, VA

- 8812060263 FOIA request for records re B&W Mount Athos plant, including rept that led B&W to be fined in 1985 for violations of NRC radiation protection requirements BRANDT,S.G. Affiliation Not Assigned 88/11/01. ROBINSON,L.I. NRC No Detailed Afficience Given 1p. 47729-329-47729-329
- 8811300195 Informs that water leakage from transfer canal & storage pool discovered on 881013.Caused by pool inadvertently filled to 1p of gutters Drain lines from gutter temporarily plugged Steel sump to be constructed & installed CISEN,A.F. Babcock & Wilcox Co. 89/11/11. Document Control Branch (Document Control Desk). 3pp. 47680.169-47680.171.

DOCKET 70-0925 CIMMARON CORP., OKLAHOMA CITY, OK

- 8812140154 Forwards findings of Oak Ridge Associated Univs.of collected soil & water samples from 19 boreholes in potentially contaminated areas for Aug 1989 NRC unable to reconcile findings willarge estimates of contaminated on vo's.

 ROUSE, L.C. Fuel Cycle Safoty Branch 88/12/07. STAUTER, J.C. Cimerron Corp. 1p.
- -8812190054 Forwards analytical results for soft & water semples collected in Aug 1988 from 19 borsholes at Sequeyah Fuels. Elevated concentrations of gross sigha & gross beta contamination noted. BERGER, J.D. Oak Ridge Associated Univs 8B/11/11 SHUM,E Office of Nuclear Material Safety & Safeguards, Director, 9pp. 47B11 274-47811:282.

DOCKET 70-1100 COMBUSTION ENGINEERING, INC., WINDSOR, CT

- 8812220040 Requests delay in reporting measurements for shipment of SNM received at Windsor facility on 880007 Windsor facility currently does not have sufficient were-house space such that off-load shipment can be stored Foe pard. SCHERER.A.E. Combustion Engineering, Inc. 88/09/23 SMITH,C.N Licensing Branch (670413-881217). 3pp. 47803-314-47903:316
- 8611290456 Forwards Rev 1 to Part 2 of "C-E Nuclear Fuel Integrated Improvement Progam," w/status of commitments as of 861024 SCHERER, A E. Combustion Engineering, Inc. 86/11/09. RUSSELL, W.T. Reg on 1, Cto of the Director. 97pp. 47663;108-47863;282
- 8812090256 Forwards pages inadventonly conitrod from Rev 1 to Part 2 of C-E nuclear liet integrated improvement program, did 881109.

 SCHERIER, A.E. Combustion Engineering, Inc. 88/11/11. RUSSELL, W.T. Reg.on 1, Ote of the Director 5pp. 47781:345-47781.349.
- 8812209082 Responds to violations noted in Insu Ropts 70-1100/88 05 & 70-1100/88-06 Corrective action:methodology to measure U content in non-compactable waste ostabilished W/o stated encis.
 SCHERER,A.E. Combustion Engineering, Inc. 88
 Branch (870413-881217), 3pp. 47068 235-47868-236. 86/11/11. SMITH.C.N. Licensing
- 8812020261 Forwards "Radiological Survey Rept Wooded Area C.E,Inc Property." Concurrence requested to release erea for unrestricted use SCHERER, A.E. Combustion Engineering, Inc. 88/11/29 ROUSE, L.C. Fuel Cycle Safety Brench. 1p. 47703-330-47703-363.
- -8812020264 "Radiological Survey Rept Wooded Area C.E.Inc Property, Windsor, CT. *Combustion Engineering, Inc. 88/11/30, 32pp. 47703:331-47703:383.
- 8812010196 Advises that License Condition 1.1 to Safeguards Amend SG-2 to License SNM-1067 revised to read as stated in response to 881111 submittal of revised pages to FNMCP.

SMITH,C.N. Licensing Branch (870413-881217) 88/11/30 SCHERER,A.E. Combuston Engineering, Inc. 1p. 47709.237-47709.237.

- 8812090055 Ack receipt of 881104 lir & payment for civil panelty proposed by NRC in 881007 itr in amount of \$12,500. LIEBERMAN,J. Ofc of Enforcement (Post 870413), 88/12/06. BREWER,S. Combustion Engineering, Inc. 1p. 47784:337-47784:337.
- 8812230052 PNO-I-88-124:on 881200 worker broke 1 1/2-inch natural gas line white re-moving tree stumps from clearing Gas Inak Immediately isolated & gas flow shut clif Facility evacuated & local frac company called to site. HOTH,J. PASCIAK,W. Region 1, Otc of the Director. 88/12/09. 1p. 47914:350-

DOCKET 70-1113 GENERAL ELECTRIC CO., WILMINGTON, NO

- 8812200247 Requests one-time examption to current matt control 8 accountability regulations Fee paid Encl withheld (ref. 10CFR2:790(d)) WINSLOW,T.P. Genoral Electric Co. 88/09/19 SMITH,C.N. Office of Nuclear Material Selety 8 Sateguarde,Director 1p. 47863.075-47863:075.
- 6812200262 Forwards requests for change in FNMCP.Fee paid Encl withheld (ref
- 10CFR2.790(d)).
 WINSLOW.T.P. General Electric Co. 88/10/27. SMITH,C N. Office of Nuclear Material Safety & Safeguards,Director. 1p. 47868.147-47868:147.
- 8812010201 Requests response to encl 081020 Itr stating Intent to lower or not lower possession limit 8/or enrichment of current SNM, per 881122 telcon. SMITH,C.N. Licensing Branch (870413-881217): 88/11/30. WINSLOW,T.P. General Electric Co. 1p. 47709:232-47709:234.
- ~8812010203 Requests response indicating which afternative elected re lowering of possession limit &/or enrichment level within 30 days Liconsee may keep existing 500 kg U-235 limit, but lower max enrichment to 9.99%, as another alternative. SMITH,CN. Licensing Branch (870413-881217). 88/10/20 WINSLOW,T.P. General Electric Co. 2pp. 47709.233-47709.234.
- 8812210002 Forwards revs to Chapters 2 & 3 to FNMCP for fuel labrication facility in Wilmington,NC Revs withhold (ref 10CFR2.790(d)). WiNSLOWT.P. General Electric Co. 88/12/02. ERNST,M L. Region 2, Ofc of the Director, 2pp. 47880-150-47880-151.

- 8812210303 Forwards revs to Chapter 4 to FNMCP.Revs withhold (ref. 10CFR2.790(d)). WINSLOW,T.P. General Electric Co. 88/12/07, ERNST,M.L. Region 2, Ofc of the Director. 2pp. 47880 359-47880 360.
- 8812220086 Notifies of Lynchburg,VA plant selection for application of IAEA safeguards. Upon receipt of second notification due Feb-Mar 1989, vendor inventory rept & subsequent accounting repts required.

 SMITH,C N. Licensing Branch (870413 881217) 88/12/14 WATTERS,J.P. Babcock & Wiccox Co 2pp 47900 218-47900 219.

DOCKET 70-1161 WESTINGHOUSE ELECTRIC CORP., COLUMBIA, SC

- 8811230266 Discusses Insp Rept 70-1151/88-14 on 880926-30 & forwards notice of DECKER, T.R. Region 2, Otc of the Director 86/11/09, LOCH, E.P. Westingthouse Electric Corp. 2pp. 47631:302-47631:310
- -8811230267 Nollco of violation from inspion 880926-30 Violation noted: six controlled copies of site emergency plan & implementing procedures incomplete or not maln-tained in up-to-date memoral. DECKER,T.R. Region 2, Ofc of the Director, 88/11/09, 2pp. 47631:304-47631:305
- -8811230269 Insp Rept 70-1151/88-14 on 880926-30.Violation noted Major areas Inspected rout no unannounced has in emergency proparedness area TESTA,E.D., RANKIN,W.H. Region 2, Otc of the Director, 88/11/09, 5pp. 47631 306-47631:310
- 8811300460 Ack receipt of 881108 itr informing NRC of stops taken to correct violations noted in Insp Rept 70-1151/88-13.

 DECKER,T.R. Region 2, Old of the Director, 88/11/18, LOCH,E.P. Washinghouse Electric Corp. 1p. 47676-221-47678-221
- 8812080026 Forwards Insp. Rept. 70-1151/88-15 on 881027-28 No violations or devi-ations noted Weaknoss Idon; field relifative to conduct arinual radiological emergency drill at facility in manner adequate to test ability to implement amorgancy plan COLLINS, DM. Region 2, Old of the Director. 887/11/22 LOCH,E.P. Westinghouse Electric Corp. 2pp. 47754-089-47754:085.
- --8812080028 thsp Rept 70-1151/88-15 on 881027-28 No violations or deviations noted Mejor areas inspected licensee annual rad elegical emergency drift on 881027. KREH, JL., TESTA, E.D., RANKIN, W.H. Region 2, Ofe of the Director 88/11/22, 4pp 47754-082-47754-082.
- 8812200324 Forwards Insp Rept 70-1151/68-16 on 881031-1103 No viciations or dovi-ations noted Rept withhold (ref 10CFR2.780(d) & 73.21). CLINE,W.E. Region 2. Oto of the Director. 88711/28. LOCH,E.P. Westinghouse Elec-tric Corp. 2pp. 47871.275-47871:276.
- 8812130111 Responds to NRC 881109 ltr re-violations noted in Insp Rept 70-1151/88-14.Corrective action, manuals rev.owed & updated correctly using page by page insp-mathod & administrative controls improved. LOCH,E.P. Westinghouse Electric Corp. 88/12/07. Decument Control Brench (Occu-ment Control Desk). 2pp. 47794 086-47794 087.
- 8812200317 Forwards corrected pages to 880930 application re Licensa SNM-1107. NARDI,A.J. Westinghouse Electric Corp. 88/12/09. ROUSE,L.C. Fuot Cycle Safety Branch 4pp. 47888:328-47868:332
- 8812210055 Ack receipt of 681207 lit informing NRC of steps taken to correct violations noted in insp Rept 70-01161/88-14.

 DECKER,T.H. Region 2, Oic of the Director 88/12/14. LOCHLEP Westinghouse Electric Corp. 1p. 47875:326-47875.328.

DOCKET 70-1201 B&W FUEL CO., LYNCHBURG, VA

- 8812220117 Requests 30-day extension for conducting 1988 U physical Inventory to ac-comodate workloads & manpower requirements. Fue paid. WATTERS, JP. 88W Fuel Co. 88/10/06. BRACH, E.W. Licensing Branch (870413-881217). 2pp. 47900:251-47900.252.
- 8812060148 Advises of NRC team inspire 851128-1201 to evaluate mati control & accounting program for SNM.per 10CFR74.31 List of inspiream members & areas as Bigned and.
 CLINE,W.E. Region 2, Ofc of the Director 88/11/18. ALTO,R.A. Babcock & Wilcox Co. 3pp. 47740.321.47740.323.
- 8812160132 Forwards Insp Rept 70-1201/88-11 on 881114-18 & notice of violation.W/o notice of violation. Understanding of program weakness requested.

 DECKER, T.R. Region 2, Old of the Director, 88/12/07, ALTO,R A. B&W Fuel Co. 2pp. 47830:290 47830:297
- -8812166134 Insp Rept 70-1201/88-11 on 881114-18 Violation noted failure to document fire protection equipment audit results per Proceduro AS-1130.Major areas Inspected emergancy preparedness GOODEN,A., RANKIN,W.H. Region 2, Ofc of the Director, 88/12/02, 8pp. 47830:292-47830 297.

DOCKET 70-1257 ADVANCED NUCLEAR FUELS CORP., RICHLAND, WA

- 8812210299 Forwards Rev 20 of to FNMCP. Hov describes changes to mail control area structure Rev withhold (rel 10CFR2.709). Fee peld SCHNEIDER, R.A. Advanced Nuclear Fuels Corp. (formerly Exxon Nuclear Co., Inc.). 88/10/17. SMITH, C.N. Licensing Branch (870413-881217). 1p. 47880:161-47880.161.
- 8812220094 Application for amend to License SNM-1227, specifying authorized possession limit for Ujenriched up to 18,99 weight percent U-235, per Category III classification Table listing SNM possession limits onci. SCHNEIDER,R.A. Advanced Nuclear Fuels Corp. (formerly Exxon Nuclear Co., Inc.). 88/11/03. SMITH,C.N. Licensing Branch (870413-881217). 3pp. 47892:156-17003-159. 47892:158

8812070047 Informs that new page inserted into Chapter 11 of demonstration section of license application,per licensee 881101 correspondence PENNINGTON W.S. Fuel Cycle Safety Branch 88/12/01. MALCDV,C.W. Advanced Nuclear Fuels Corp. (formarly Exxon Nuclear Co., Inc.) 1p. 47749 237-47749 237.

8812070288 Advises that new page inserted into Chapter 11 of demonstration section of License SNM-1227.per 881101 request. PENNINGTON IV.S. Fuel Cycle Safety Branch 88/12/01 MALODY.C.W. Advanced Nuclear Fuels Corp. (formerly Exorn Nuclear Co., Inc.). 1p. 47746.074-47746.074

8812230068 Responds to NRC 881108 ftr re-vicial ons noted in Insp of License SNM-1227. Corrective actions protective clothing resuse policy w/respect to coveralls re-

besives & revised MALODY, C.W. Advanced Nuclear Fuels Corp (formerly Exxon Nuclear Co., Inc.) 88/ 12/15. Document Control Branch (Document Control Desk). 3pp. 47914-353-47914:355

DOCKET 70-1308 GENERAL ELECTRIC CO., SAN JOSE, CA

8812140130 Forwards review of NEDE-31559 re QA plantrellecting revs to previous QA pfan as result of recent organization changes. ROBERTS, J.P. Div.sion of Industrial 8 Medical Nuclear Safety (Pest 870729). 88/12/ 09. INGELS,T.E. General Electric Co. 5pp. 47814 190-47814:194

DOCKET 70-1428 TRANSNUCLEAR, INC., FALLS CHURCH, VA

812120061 Notifies of transient shipment of SNM of moderate strategic significance per 10CFR73.72(a) Informs that itria's a constitutes compliance on behalf of all carriers while shipment in US territory, per 10CFR70.201. Obvision of Safeguards & Transportation (Post 870413) 4pp. 47780-124.47760-127. 8812120061 Nobiles

DOCKET 70-1703 EASTMAN KODAK CO., ROCHESTER, NY

8812210407 Forwards Safeguards Insp. Rept. 70-1703/88-02 on 681116 No violations BELLAMY, R.R. Region 1, O'c of the Director 88/12/08, HEYER, J.H. Eastman Kodek Co. 2pp. 47877.057-47877:061

-8812210408 Safeguards Insp. 70-1703/88-02 on 981116.No violations noted. Major areas inspected nuclear mail controllaccounting & physical security including facility operation inventory, records & repts & physical protection measures for SNM DELLA RATIALA, KEIM.G.R.R. Region 1, Okt. of the Director 88/12/07, 3pp. 47877.059 47877:061.

DOCKET 70-1718 SHADYSIDE HOSP., PITTSBURGH, PA

8812150018 Ack receipt of 881111 itr & payment of civil penaties in amount of \$2,500,per NRC 891028 iir.
LIEBERMAN,J. Region 1, Otc of the Orector 88/12/09. MORDOH,H. Shariyeide Hasp , Pittsburgh ,PA 1p. 47807:181-47807:181

DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO., JOPLIN, MO

8812050338 Advises that McMaster Univ 980929 request for approval of encircule to be used for transport of spent reactor fuel from Fort Eria,NY to Aikon,SC meets requirements of 10CFR73.37.

MACDONALD,CE Transportation Branch 88/11/25. RiTCHIE,D.W. Tri-State Motor Transit Co (Subs. of Georgia Pacific Co.) 18pp. 47740 297-47740:314.

DOCKET 70-2479 TRANSHUCLEAR, INC., FALLS CHURCH, VA

8812050157 D'scusses 861020 request, for approval of route for transport of spent reac-tor fuel from Portsmouth Merine Torminel, Portsmouth,VA to DOE Savannah River Plant,Aiken,SC,including transient ports of Port Elizabeth,NJ & Bellumore. MACDONALO.CE. Transportation Branch, 88/11/29. MCLAUGHLIN,J. Transnuclear, Inc. 10pp. 47732:308-47732.317.

8812150050 Approves route to be used for transporting spent reactor fuel from Portsmouth,VA to Aikon,SC,per 881020 ft. MACDONALD.C.E. Transportation Branch 88/12/02 MANGUSI,J. Transpucteer, Inc. 10pp. 47833.037-47833.046.

DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8812050120 Advises that 881002 revised classification of facility fuel storage physical security plan consistent w/10CFR70 32(e) provisions Encl withhold (ref 10CFR2 780(d)).

CLINE,W.E. Region 2, Oic of the Director. 88/11/25. KINGSLEY,O.D. Tennossee Valley Authority. 2pp. 47732:293-47732:294.

8912090103 Advises that 681002 rev to fuel storage physical security plan consistent

w/10CFR70.32(e) 8 accoptable. CLINE W.E. Region 2, Old of the Director 88/11/26. KINGSLEY,O.D. Tennesses Valley Authority. 2pp. 47761:138-47761:139.

DOCKET 70-2817 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8812070268 Application for amend to Licenses SNM-1885 & SNM-1883, changing Section 2.1 re-radiation control to clarify that Bell'efonte will not have onsite health physics organization, but will be supported by unit corporate personnel.

GRIDLEY,R.L. Tennessee Valley Authority, 88/11/18, Document Control Branch (Document Control Desk), 35pp. 47748:016-47746-049.

8812200323 Forwards Rev 4 to fuel storage physical security plan & supple Rev reflects new organizational structure & show main control room as primary monitor & dispatcher for elarms.Rev withhold (ref 10CFR2.790).
GRIDLEYR. Tennassee Velley Authority, 88/11/28 Document Control Branch (Document Control Dosk). 3pp. 47871.272-47871:274.

DOCKET 70-2928 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8812050120 Advises that 881002 rovised classification of facility fuel storage physics security plan consistent w/10CFR70.32(e) provisions Encl withhald (re 10CFR2.790(d)).

CLINE.W.E. Region 2, Old of the Director 88711725, KINGSLEY,O.D. Tennosse-Valley Authority, 2pp. 47732 293-47732 294.

8812090103 Advises that 881002 rev to fuel storage physical security plan consisten

w/10CFR70 32(e) & acceptable
CLINEW.E. Region 2. Orc of the Director 88/11/25 KINGSLEY,O.D. Tennasset
Valley Authority. 2pp. 47761:138-47761:139

DOCKET 70-2932 TEXAS UTILITIES GENERATING CO., DALLAS, TX

8812080312 Forwards Amend 5 to Licerise SNM-1912 & salety evaluation Amend ex tonds expiration date to 911231.

ROUSE, L.C., Fuel Cycle Safety Branch 98/12/01. COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.). 1p. 47742 223-47742.228

-8612060314 Amend 5 to License SNM-1912, authorizing use of 2,200 kg & 40 o of U. 235 isotopes ROUSEL.C. Division of Industrial & Modical Nuclear Safety (Post 870729), 65/12/01. 3cp 47742:224-47742:226

~8812060316 Safety evaluation supporting Amend 5 to License SNM-1912 relicense extension ROBINSON,C., BIDINGER,GH. Fuol Cycle Safety Branch, 88/12/01, 1p. 47742,227-47742 228

-8812060317 Provides categorical exclusion for 881031 application for amend to LF

cense SNM-1912 extending expiration date EtS & environ assessment unwairanted.

Research Control Cycle Safety Branch 68/12/01. Fuel Cycle Safety Branch 68/12/01. Fuel Cycle Safety Branch 68/12/01. Fuel Cycle Safety Branch 68/12/01.

8812150081 Forwards Amend 6 to License SNM-1912 & SEH Amend translets ownership interests from Texas Municipal Power Agency to Texas Utils Electric Colombial to Indemnity Agreement B-98 also end. ROUSE, L.C. Fuel Cycle Safety Branch, 89/12/13 COUNSIL, W.G. TU Electric formerly Texas Utilities Generating Co.), 1p. 47822,354-47822,360.

-8812150065 Amend 6 to License SNM-1912 for Toxas Utils Electric Co. Taxia Electric Cooperative of Texas,Inc & Texas Municipal Power Agency,noting transfer of American alip ROUSE,L.C Division of Industrial & Moulical Nuclear Safety (Post 870729), 69/12/13 3pp. 47822:355-47822:357

-9812160068 Safety evaluation supporting Amend 6 to License SNM-1812 is herefor of ownership interest from Texas Municipal Power Agency to Texas Utils Electric Co. MCCAUGHEY,D A. Fuel Cycle Safety Branch. 88/12/13, 2pp. 47822;358 47822 359.

 -8812150071 Advises that no ther EIS nor environ assessment warranted for 690722 application to amend License SNM-1912, reflecting revised ownership increase, per 10CFR51 22(c)(10). ROUSE,L.C. Fuel Cycle Salety Branch. 68/12/13. Fuel Cycle Salety Bianch. 1p. 47822:360-47822:360.

DOCKET 70-2941 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, IN

8812070259 Application for amond to Licenses SNM-1865 & SNM-1863, chenging Section 2.1 re radiation control to clarify that Bellofonto will not have onsite health physics organization, but will be supported by util corporate personnel.

GRIDLEY.R.L. Tennessee Valley Authority, 88/11/118, Ducument Control Branch (Document Control Desk), 35pp. 47746-018-47748-049.

8812200323 Forwards Rev 4 to fuel storage physical security plan & suppls Rev reflects new organizational structure & show main control room as primary monitor & dispatcher for alarms. Rev withhold (ref. 10CFR2.790).
GRIDLEYR Tennessee Valley Authority. 88/11/28. Document Control Branch (Document Control Desk). 3pp. 47871:272-47871.274.

DOCKET 70-3041 INTERNATIONAL FREIGHT FORWARDERS, INC., ATLANTA, GA

88 12130079 Requests extension of enci route approval for 1989 in the name of German client.KFA.Jueilch.W/o enct.
HALPAUS,P. International Freight Forwardore, Inc. 88/11/22, MACDONALU.C.E.
Transportation Branch. 2pp. 47792:087-47792.088.

DOCKET 70-3064 PHILADELPHIA ELECTRIC CO., PHILADELPHIA, PA

8811280139 Provides supplemental into re 880506 application for amend to license SNM-1977,por D McCaughy request during 881015 telcon. KOWALSKI,S J. Philadelphia Electric Co. 88/10/28 MURLEY T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 47652;232-47652;233.

8811300014 Forwards revised License SNM-1977,adding Conditions 6.D,7.D, 8.D,17,18. & 18,revising Conditions 9 & 10,deleting Conditions 11 & 15 & authorizing use of U-236 isotope contained in fuel assemblies. ROUSE, L.C. Fuel Cyclo Safety Branch. 88/11/22. BRADLEY,E J. Philade'pha Electric Co. 2pp. 47880:283-47680:302.

-9811300015 Revisad License SNM-1977 for Philadelphia Electric Co. authorizing use of 2600 kg U-235 Isolope, adding Conditions 6 D.7.D.8.D.17.18 & 19.deleting Conditions 11.15 & 16 & revising Conditions 9 & 10.
ROUSELL C. Division of industrial & Medical Nuclear Setory (Post 870729). 88/11/22. 3pp. 47680 285 47680 287.

-8811300016 Safety evaluation rept to amend to License SNM-1977 for storage & use of unirradiated nuclear fuel assemblies. MCCAUGHEY,D.A. Fuel Cycle Salety Branch. 88/11/22. 7pp. 47680.286-47660.284

191

- ~8811300017 Notice of finding of no significant lineactire amend to License SNM-1977 Amend revisor I cense in entircty ROUSE,L.C. Fuel Cycle Safety Branch 88/11/07, 5pp. 47680 295-47680 299
- -8811300018 Concludes that no arguincant impacts associated w/proposed action to beings amond architecture to receive new fuel. LAROCHE,G., HÖRN,M. BIDINGER,G. H. Fuel Cyclo Safety Branch 88/11/04 Fuel Cyclo Safety Branch 3pp 47690 300-47680 302

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0024 HITTMAN NUCLEAR & DEVELOPMENT CORP.

- 8812210145 Forwards OA program plan for review & requests reviol subj QA program
- approval Fee paid
 BASTIN J J JOHNSON, W. J Westingtouse Electric Corp. 88/11/
 MACDONALD, C.E. Transportation Contribution Branch. 2pp 47890.076-47890.103.
- -8812210152 "OA Program Plan for Nuclear Svcs Div.Radiological Svcs Dept." BASTIN, J.J., CHRISTOPHER, T. Westinghouse Electric Corp. WCAP 9245 ADD 01 R00 88/11/30. 26pp. 47800 078-47890.103
- -8811280220 Requests remittance of fee for 881103 application for amend to DA program to radiosctive matt packago 0024

 JACKSON,G Licenso Fee Managuinent Branch 88/11/21 BASTIN,J.J Westinghouse Electric Curp 1p 47890 104-47890:104.

DOCKET 71-0102 SOURCE PROD. & EQUIP. CO., INC.

- 8811290336 Forwards Roy 2.1 to QA plan for reinstatement of QA program plan approval 0.02 W/o nnct.
 CICHARRY.R.D. Source Production 8 Equipment Co.,
 MACDONALD,C.E. Transportation Branch 1p. 47664-360-47664-360. Inc. 88/11/16.
- 8811300028 Requests 3 month extension until 890308 to submit into requested in
- B80608 ftr.por 881115 monting Addi time required to mits prototypos.perform Type B package tests & propero repts DICHARRY, D Source Production & Equipment Co., Inc. 88/11/16. MACDONALD,C E. Transportation Branch 2pp. 47698

DOCKET 71-0275 DUQUESNE LIGHT CO.

8811230084 Forwards fee for 680607 application for amend to QA program for radioactive mail packagos approval.0275. VASSELLO,J.V. Duquesne Light Co. 88/11/14, JACKSON,G. NRC - No Detailed Affiliation Given: 1p. 47631:360-47631:360.

DOCKET 71-0421 NAVY, DEPT. OF

- 8812200292 Forwards application for amend to QA Program Approval 0421.

 MALINOSKI,J.W. Navy, Dopt of, Naval Soa Systems Command. 88/12/12. Division of Saloguards & Transportation (Post 670413). 1p. 47862.145-47862.155.
- ~8812200295 Application for approval of QA program for radioactive matt packages as-sociated w/radiography instructions. BEAN,C.D. Navy, Dopt. of. 88/11/15 Office of Nuclear Material Safety & Safeguards,Director. 10pp. 47862:146-47862:155.

DOCKET 71-0454 ATOMIC ENERGY OF CANADA, LTD.

8812200103 Requests amend to QA program approval Curtilicate 0454 re name change of AECL former inc medical products div to Theratronics Intl Ltd.per 881209 telcon.Latest organization chart oncl. Fee pald. DOWNS,W E. Theratronics Intronational, Ltd. 86/12/15. WILLIAMS,S. Transportation Branch. 3pp. 47887.091-47887:099.

- --8812200111 Notifies that planned corporate reorganization, involving incorporation by AECL former medical products div has taken place on 880927 Requests listed the canase perfaining to business of div be transferred to Thoratronics Intl Ltd. WARLAND,H.M. Theratronics International, Ltd. 88709/30. KINNEMAN,J. Region 1, Cfc of the Director. 2pp. 47887:095-47887:096.
- -8812200125 Notifies of planned corporate reorganization involving incorporation by AECL of former medical products div. Requests listed licenses portaining to div be transforred to Thorefronics Intl Ltd upon closing of transfer transactions WARLAND,H M. Atomic Energy of Canada, Ltd. 88/09/01. Region 1, Ofc of the Director, 3pp. 47887.097-47887.099.

DOCKET 71-0508 BABCOCK & WILCOX CO.

- 8812150255 Forwards OA program approval for radioactive matl package: 0506,Rev 2.Rev reflect change in company name from B&W to B&W Fuel Co. MACDONALD,C.E. Transportation Branch. 88/12/12. MACKINNEY,A.L. B&W Fuel Co. 1p. 47830:143-47830.144.
- --8812150257 QA program approval for radioactive matl package.0506.Rev 2. MACDONALD.C.E. Transportation Branch. 88/12/12, 1p. 47830:144-47830.144.

DOCKET 71-0509 MET-CHEM ENGINEERING LABORATORIES, INC.

8612060007 Forwards QA program approval for radioactive matt package: 0509,Rev 2.W/o encl. MACDONALD.C.E. Transportation Branch. 88/12/05. Met Chem Testing Laboratories of Utah, Inc. 2pp 47753:162-47753:163.

DOCKET 71-0849 UNIV. OF CALIFORNIA, BERKELEY

- 8812150281 Forwards OA approval for radioactive matl package 0649,Rev 1 Approval revised to extend expiration date from 890228 to 890831.

 MACDONALD.CE Transportation Branch. 88/12/12 LIM.T.H California Univ of, Birtheley, CA 1p. 47825 061-47825.062
- -8812150262 QA program approval for radioactive mail package 0640,Rov 1, MACDONALD,C E Transportation Branch 98/12/12 1p 47825 082-47825 062.

DOCKET 71-0665 ULTRASONIC SPECIALISTS, INC.

- 8811210133 Forwards Rev 0 to "Shipping Container OA Requirements," for containers used to ship ir 192 sources used for industrial rad ography purposes.

 BLAKE,T. Ultrasonic Specialists, Inc. 88/11/18. Office of Nuclear Material Safety & Safeguards, Director 1p 47930-258-47930-265
- -8811210135 Rev 0 to "Shipping Container OA Requirements"

 * Ultrasonic Specialists, Inc. 86/12/18 6pp. 47930 259 47930.264
- -8812050106 Requests licenses remit fee for 881116 application for approval of QA program radioactivo mell package 0605 W/o enct.

 JACKSON,G. Ulcense Fee Management Branch, 88/12/01, BLAKE,T. Ultrascnic Specialists, Inc. 1p. 47930 265-47930 265.

DOCKET 71-3005 IRRADIATOR, ROCKWELL INTERNATIONAL CORP.

- 6812220008 Requests approval for one-time shipment of irradiator per 10CFR71.7 & 71.41(c). Sketches of Irradiator & map showing transport routo encil Fee paid.

 REMLEY, M.E. Rockwell International Corp. 88/11/23 MACDONALD, C.E. Transportation Branch. 8pp. 47902.308-47902.315.
- 8812220004 Remits fee for 881123 application for approval of transport of gamma radi-REMLEY,M.E. Rockwell International Corp. 88/11/28 MACDONALD,C.E. Transportation Branch. 1p. 47892:144-47892.144.
- 6812220005 Provides suppremental Info ro 881123 application for approval to transport Rockwell Science Ctr irradiator.por R Odegaarden to/con request. DENNISON,W.F. Rockwell International Corp. 88/11/29. MACDONALD,C.E. Transport tation Branch, 3pp. 47894:350-47894:352.
- 8812060026 Advises that Rockwell Intl exempt from package approval side of Subpart E of 10CFR71 for one-time shipment of irradiator containing 840 ct Co 60 in seated capsules Approvat record enct.
 MACDONALD,C E. Transportation Branch, 88/11/30, REMLEY,M.E. Rockwell International Corp. 3pp. 47740:315-47740 317.

DOCKET 71-3006 MODEL: 1500, TRANSPORTATION, DEPT. OF

- 8812230125 Requests assistance & recommendations to review of into submitted to quality Type 8() package willimitations as Type 8(U) package for import & export.Confirmation of Certificate of Compliance 5939 suthorizing byproduct meeting requested.
 WANGLER,M.E. Transportation, Dept. of 88/11/22, MACDONALD,C.E. Transporta tion Branch. 2pp. 47921:322-47921:342.
- --8812230129 "Model 1500 Transport Packago 1973 IAEA Regulatory Assessment."
 General Electric Co. 88/10/31, 18pp. 47921:324-47921:342.

DOCKET 71-4909 MODEL: GE-21PF-1, GENERAL ELECTRIC GO.

- 8812070249 Forwards second addendum to 880901 application for Certificate of Compliance 4909 for Model NCI-21PF-1.Addendum deletes request for Type B()F approval & verifies request for Type AF certificate of compliance.
 HOUSHOLDER,WR. Nuclear Containers, Inc. 88/11/28. MACDONALD,C € Office of Nuclear Material Safety & Safeguards,Director. 2pp. 47757-011-47757-035
- -8812070254 Addendum to 881128 application for Model NCI-21PF-1 protective shipoing package. Nuclear Containers, Inc. 88/11/28, 32pp. 47757:013-47757.036.

DOCKET 71-5971 MODEL: 200, GENERAL ELECTRIC CO.

- 8812230283 Requests registration as user of Model GE IPO-200.
 REMLEY.M.E. Rockwell International Corp. 88/12/06. MACDONALD,C.E. Transportation Branch. 1p. 47916:147-47916:148.
- 8812220170 Notification of registration as user of Certificate of Compliance 5971,per 881206 request.
 MACDONALD.C.E. Transportation Branch 88/12/19. REMLEY,M.E. Rockwell International Corp. 1p. 47892:250-47892:250.

DOCKET 71-5984 MODEL: 5984, J.L. SHEPHERD & ASSOCIATES

- 8812120170 Requests registration as user of Model DOT 20WC-5/B. LACEY,W.S. Duquesne Light Co. 88/11/29. Document Control Branch (Document Control Desk). 1p. 47785:205-47785:206.
- 8812220317 Informs of registration as user of Model DOT 20WC-5/B,per 881129 request.
 MACDONALD.C.E. Transportation Branch. 88/12/20. KOSMAL,J.A. Duquesne Light Co. 1p. 47892 256-47892 256.

DOCKET 71-6078 MODEL: 927A1 & 927C1, COMBUSTION ENGINEERING, INC.

- 8811230185 Informs of completion of shipment of unused fuel rods on 891101 from
- Yankee Rowe SCHERER.A.E. Combustion Engineering (nc. 88/11/11. MACDONALD,C.E. Transpor-tation Brench. 2pp. 47652 033-47652 034,
- 8811300425 Forwards responses to CE MacDonald 881021 request for additinto re Certheate of Compliance 6078 amond request concerning application for use of 927A1 8 927C1 fuel essembly shipping containers for transport of mall SCHERER,AE Combuston Engineering Inc. 88/11/16 MACDONALD.CE Transportation Branch. 4pp 47700 001-47700 034.
- -8811300436 Rev 1 to application for use of 927A1 & 927C1 fuel assembly shaping containers for transport of rad pactive mail
 Combustion Engineering, Inc. 88/11/16, 30pp 47700.005.47700.034

DOCKET 71-6348 MODEL: FSV-1 & 1A, GA TECHNOLOGIES, INC.

- 8812130072 Forwards additional pages omitted from Leanse 881025 ltr rovising allowable leakage rate used for Model FSV-1. Revised request to change Certificate of Comphance 6346 also and ASMUSSEN,K.E. General Atomics (formally GA Technologies, Inc./General Atomic Co.). 88/12/07 MACDONALD.C. Transportation Branch 5pp. 47792:238-47792:242
- 8812220301 Forwards revised Page 1-4 to GADS 55,clantying use of optional shield tube which may be used w/FSV-1-20A configuration.
 ASMUSSEN,K E. General Atomics (formerly GA Technologies, and /General Atomic Co.) 88/12/12. MACDONALD,C Transportation Branch. ap. 47900 234-47900 236.
- --8812220303 Page 1-4 of Rev 1 to Vol 1 to GADR 55 consisting of table Elustrating Model FSV-1 cask & three configurations.

 'General Atomics (formarly GA Technologies, Inc./General Atomic Co.), GADR 55 Vol R01 88/12/12 2pp 47900 235-47900 236.

DOCKET 71-6386 MODEL: 235R001, ENERGY, DEPT. OF

- 8812220172 Forwards Rev 11 to Certificate of Compliance 5388 for Model 235R001 MACDONALD.CE Transportation Branch, 88/12/19 ENGEL,W P Energy, Dept. of. 1p. 47990 245-47920 250
- -8612220177 Certificate of Compliance 6386, Rev 11 for Model 235F1001. Approval MACDCNALD,C.E. Transportation Branch 88/12/19 5pp. 47900:246-47900.250

DOCKET 71-6400 MODEL: 6400, WESTINGHOUSE ELECTRIC CORP.

- 8811290514 Forwards Roy 20 to Certificate of Compliance 6400 for Model 6400 shipping package.
 MACDONALD,C.E. Transportation Branch, 88/11/28, MCCALLUM,E. Energy, Dept. of. 1p. 47648:220-47648:235
- ~8811290519 Certificate of Compliance 6400,Rev 20,tor Model 6400, MACDONALD,C.E. Transportation Branch: 88/11/28, 15pp., 47648,221-47648,235

DOCKET 71-8801 MODEL: CNS 8-120, CHEM-NUCLEAR SYSTEMS, INC.

- 8811230191 Requests registration as user of Chem-Nuclear Sys,Inc CNS 8-120A rad.oactive mails shipping cask.
 VANDALE.M.T. Yankse Atomic Electric Co. B8/11/09 MACDONALO.C.E. Transporta-tion Branch. 2pp. 47831;329-47831 330
- 8812150253 Notification of registration as user of Model CNS 8-120,per 881109 re-
- quest MACDONALD,C.E. Transportation Branch. 88/12/12 VANDALE,M.T. Yankee Atomic Electric Co. 1p. 47825-055-47825:055.

DOCKET 71-6839 MODEL: MH-1A, ENERGY, DEPT. OF

- 8811230213 Requests that docket on MH-1A application be closed immediately due to lack of feasible a practicality.

 MCCALLUM,E.J. Energy, Dept. of. 88/11/07 MACDONALD,C.E. Transportation Branch, 2pp. 47622,250-47622,251
- 8812010288 Advises that review of application for Model MH-1A cask terminated per MACDONALD.C.E. Transportation Branch, 89/11/22, MCCALLUM,E.J. Energy, Dept. of. 1p. 47707.098-47707.098.

DOCKET 71-9010 MODEL: NLI-1/2, NUCLEAR ASSURANCE CORP.

- 8812010326 Discusses 881116 telcon w/Nuclear Assurance Corp re NRC 880814 approval for re Model Nt1-1/2 Approval does not require use of Configuration D ODEGAARDEN,RH, Transportation Branch, 88/11/29, Transportation Branch, 1p. 47710:100-47710.100.
- 8812130058 Forwards additin'o on amend to NLI-1/2 cask license for shipment of Mark WELLS,A.H. Nuclear Assurance Corp. 88/12/05. MACDONALD,C E Transportation Branch. 24pp. 47931.001-47931;024.
- 8812130058 Forwards additinto on amend to NLI-1/2 cask license for shipment of Mark 42 fuel,per 881107 request Plans to food fuel into shipping canister for trip from plant to hot cell. W/5 proprietary oversize drawings WELLS,A.H. Nuclear Assurance Corp. 68712/05. MACOONALD,C.E. Transportation Branch. 23pp. 47931:001-47931:024.

DOCKET 71-9080 MODEL: HN-600 & NUPAC 100, WESTINGHOUSE-HITTMAH NUCLEAR

8812050155 Confirms. Nuclear Packaging will not apply for renewal of Centicate of Compliance 9080 for Model NuPac 100 packago. TEMUS, CJ. Pacific Nuclear Systems, Inc. 88/11/28. MACDONALD,CE. NaC. - No. Detailed Affiliation Given 2pp. 47732-318-47732-319.

DOCKET 71-9105 MODEL: RAD-WASTE CR.I, CHEM-NUCLEAR SYSTEMS, INC.

8812010381 Application for renewal of Certificate of Compliance B105. Fee paid PAQUIN,PL. Chom-Nuclear Systems, Inc. 88/11/21. MACDONAL D.C.E. Transportation Branch. 2pp. 47703-054-7703-055.

DOCKET 71-9107 MODEL: 771, TECH/OPS, INC.

- 8812210353 Requests registration insider of TechOp/Amerisham package under Certificate of Compliance 9107.

 SAMBLE, O.C. Consent Inspection 88/12/08. MCDONALD,C.E., Office of Nuclear Material Safety & Sateguards Director 2pp. 47882 063-47882 064.
- 8812220166 Notification of registration as user of Contificate of Compliance 9107, per

881206 request
MACDONALD,C E. Transportation Branch 68/12/19 GAMBLE,O.C. Conam Inspection, 1p. 47892 251-47892 251

DOCKET 71-9147 MODEL: 850, TECH/OPS, INC.

8812080818 Requests add into in 870122 application, supplemented on 880330, requesting amend to Model 850 package into should the submitted within 30 days & to form of revised pages
MACDONALD.C E Transportation Branch A8/12/05 ROUGHAN.C M. Americaham Carp. 2pp. 47783.241-47783 242

DOCKET 71-9165 MODEL: 855, TECH/OPS, INC.

8811300003 Requests renewal of Certificate of Certification D185 for Amerisham Model 855 Type R(U) Fee paid ROUGHAN,C, Amerisham Corp 88/11/68 MACDONALD.CE Office of Nuclear Material Safety & Safeguards, Director 2pp 47668 293 47668 294

DOCKET 71-9180 MODEL: 600-SU-OP, AUTOMATION INDUSTRIES, INC.

- 8812160058 Forwards Certificate of Compliance 9180, Rev 2 for Model 500 SU CP shipping package MACDONALD,C.E. Transportation Branch 89/12/13 PICUGHANIC Amerikan Corp. 2np. 47833 076 47833 080
- ~8812160080 Certificate of Compliance 9180,Rev 2,for Model 500 SU-OP, Approval MACOONALD,C E Transportation Branch 88/12/13 3pp. 47833 078-47833.060

DOCKET 71-9187 MODEL: 885, TECH/OPS, INC.

8811300002 Requests renewal of Certificate of Compliance 9187 for American Model 865 Type 8(U) Fee paid.

ROUGHAN,C. American Corp. 88/11/08, MACDONALD,C.E. Office of Nuclear Material Safety & Safeguards, Director 2pp. 47668 298-47668 297.

DOCKET 71-9200 MODEL: 125-B, ENERGY, DEPT, OF

- 8812220001 Forwards description of Model 125-B soal availation program Model 125-B package determined to be in accordance w/ requirements of 10CFR71 & certificate of comphance.pet results of seal evaluation program.
 FRANZ,W.A. Idaho National Engineering Laboratory, 88/11/23, MACDONALDIC ENRC No Dotaled Africation Given 5pp. 47894 345-47894 349.
- 8812080127 Forwards Rev 9 to SAR for Model 125-B.per NRC request for additional Rev 9 pages address questions Stated pages & drawing changes remain in effect. TEMUS.CJ. Pacific Nuclear Systems, Inc. 88/11/28. MACDONALD,C.E. NRC Not Detailed Affrigition Given 6pp 47754:148-47754:188.
- ~8812080135 Rev 9 to "SAR for NUPAC 125-8 Fuel Shipping Cask."
 Pacific Nuclear Systems, Inc. 88/11/30, 30pp. 47754:154-47754:184

DOCKET 71-9202 MODEL: TN-BRP, TRANSNUCLEAR, INC.

8812010318 Summary of 881103 meeting w/DDE,Sandia,State of TN & EG&G in Rockville,MD re Models TN-BRP & TN-BEG. Summary of strosses that will be present ed in revised SAR encl.

DDEGAARDENRH, Transportation Branch 88/11/29 Transportation Branch 3pp 47710:123-47710.125.

DOCKET 71-9208 MODEL: TN-REG, TRANSNUCLEAR, INC.

8812010318 Summary of 881103 meeting w/DOE, Sandle, State of TN & EG&G in Rockville, MO re Models TN-BRP & TN-REG Summary of stresses that will be present od in revised SAR enci.

ODEGAARDEN,R.H. Transportation Branch, 88/11/29, Transportation Branch, 3pp 47710:123-47710:125.

DOCKET 71-9218 MODEL: TRUPACT-II, ENERGY, DEPT. OF

- 8812010271 Lists changes made to TRUPACT-II Units 2 & 3 outlined during 881107 telcon w/vendor/Changes include 1/4 Inch ceramic fiber (felf) added to outside of OCV & inside of outer shall & foam changed from 3708 to 9908 series general foam. ODEGAARDEN,PH. Transportation Branch. 88/11/29. CHAPPELL,R. Transportation Branch 2pp 47709.235.47709.236.
- 8812220333 Trip rept of 881204 visit to Albuquerque,NM re TRUPACT-II testing LEE,H.W. Transportation Branch. 88/12/19. Transportation Branch. 2pp 47892.240-47692.241.

DOCKET 71-9219 MODEL: HFIR, ENERGY, DEPT. OF

8812050147 Withdraws DOE application for certification of new shipping cask for HFIR spert fuel DOE will reapply for certificate of compliance if necessary to be used for shipments.

MAUCK,C.J. Energy, Dept. of. 88/11/30. MACDONALD,C.E. Transportation Branch. 2pp. 47732:330-47732:331.

DOCKET 71-9228 MODEL: QA-4, GENERAL ATOMICS

8812210395 Requests dockets numbers for Models GA-4, "Legal Weight Truck PWR Spent Fuel Shipping Cask." & GA-9, "Legal Weight BWR Spent Fuel Shipping Cask." ZIMMER, General Atomic Co.). 6805/17, MACDONALD,C.E. NRC - No Detailed Affiliation Given. 2pp. 47874:357-

DOCKET 71-9227 MODEL: GA-9, GENERAL ATOMICS

8812210395 Requests dockets numbers for Models GA-4, "Legal Weight Truck PWR Spent Fuel Shipping Cask." & GA-9, "Legal Weight BWR Spent Fuel Shipping Cask." ZMMERIA. General Atomics (formerly GA Technologies, Inc./Goneral Atomics Co), 89/05/17, MACDONALD,C.E. NRC - No Detailed Affiliation Given 2pp. 47874:357-

DOCKET 71-9229 MODEL: TITAN, WESTINGHOUSE ELECTRIC CORP.

8812220139 Requests that docket be established for legal weight Westinghouse tran cask certification efforts Certification plan to provide further details on approach to obtalaing certificate of compilance being prepared.
LITTLE.C.C. Westinghouse Electric Corp. 88/08/22. MACDONALD.C.E. Transportation Branch. 6pp. 47911:349-47911:356.

DOCKET 71-9233 MODEL: TN-RAM, TRANSNUCLEAR, INC.

8912080024 Application for Certificate of Compliance 9233 for Model TN-RAM.Rept E-10621, "SAR for TN-RAM," proprietary Drawings 990-002 through 99-008 & Lead Pouring Procedure E-10615 encl.W/o proprietary drawings & procedure.Fee paid. NCLAN,D.J. Transpucteer, Inc. 88/11/22. MACCONALD,C.E. Division of Safeguerds & Transportation (Post 870413). 2pp. 47758:158-47759.195.

-8812080031 "SAR for TN-RAM"
Transnucloar, Inc. E-10621, 88/11/30, 398pp. 47758, 158-47759; 195

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO.

8812140130 Forwards review of NEDE-31559 re QA plan, reflecting revs to previous QA

plan as result of recent organization changes. ROBERTS,J.P. Division of Industrial & Medical Nuclear Safety (Post 870729), 08/12/ 09. INGELS,T.E. General Electric Co. 5pp. 47814:190-47814:184.

DOCKET 72-0002 VIRGINIA ELECTRIC & POWER CO.

8812130071 Forwards Rev 13 to ISFSI nuclear security personnel training & qualifica-Ilon program Rev withheld (ref 10CFR73 21).

CARTWRIGHT,W R. Virginia Power (Virginia Electric & Power Co.). 88/12/08. Document Control Branch (Document Control Desk), 1p. 47792.128 47792:128

6812130081 Forwards replacement transmittal cover litrs for 860914 Rev 13 to personnel training & qualification program & plant ISFSI nuclear personnel training & qualification program W/o encl.

CARTWRIGHT, W.R. Virginia Power (Virginia Electric & Power Co.). 88/12/08. Document Control Branch (Document Control Deak). 1p. 47794:088-47794:088.

DOCKET 72-0003 CAROLINA POWER A LIGHT CO.

8812150052 Application for amend to License SNM-2502, raising Tmits in Tech Spec 2.4.1 for beta & gamma surface contamination of dry shielded canister. Fee paid UTLEY, E.E. Carolina Power & Light Co. 88/09/09. ROUSE Division of Industrial & Medical Nuclear Safety (Post 970729). 8pp. 47833.030-47833.035.

8811300042 Requests clarification of amended ISFSI decommissioning funding plan LOFLIN,L.1. Carolina Power & Light Co. 88/11/17. Document Control Branch (Document Control Desk), 2pp. 47668:222-47668:223.

DOCKET 72-0004 DUKE POWER CO., 50-269

8812130117 Forwards responses to NRC 880727 questions re-util license application for ISFSI SAFL

TUCKER,H.B. Duke Power Co. 88/11/23. Document Control Branch (Document Control Desk). 322pp. 47793:100-47794:081.

- 8312150172 Transcript of 881209 mooting in Rockvillo,MD w/public officials having response by for emergency planning for Prigrim Nuclear Power Plant.Related info sponsibility to encl.Pp 1-185
 - Commissione/s 8B/12/09, 300pp. 47823.093-47824 080.
- 8811300578 Revised staff requirements memo to 881110 briefing in Rockville,MD on final rule on stds for protection against radiation Commissioner Roberts requested that ACNW provide Commission position on deletion of 10CFH20 205.
 CHI,KSJ, Office of the Secretary of the Commission M881110, 88/11/29, STELLOV, Olic of the Secretary of the Commission M881110, 88/11/29, STELLOV, Olic of the Executive Director for Operations PARLER,W. Office of the General Counsel MOELLER,D.W. Advisory Committee on Nuclear Waste. 3pp. 47701:353-47701:355
- 8912010026 Staff requirements momo re Commission 881116 briefing in Rockville,MD on \$18ths of location of exploratory shall at Yucca Mountain.

 C-IIIIK,S.J. Citico of the Sacretary of the Commission. M881118. 88/11/28.

 STELLO,V. Oto of the Executive Director for Operations. DENTONH. Office of Governmental 8 Public Affairs (Post 870413). 2pp. 47702 278-47702:277.
- 6812010030 Staff requirements memo re Commission 881110 briefing in Rockville,MD on final rule on stds for protect on against radiation.

 C:-ILK.S.J. Office of the Secretary of the Commission. M881110. 88/11/28.

 STELLO,V. Ofc of the Executive Director for Operations. PARLER,W.C. Office of the General Counsel MOELLER,D.W. Advisory Committee on Nuclear Waste 3pp.
- 8612020095 Transcript of 881123 briefing in Rockville,MD re-effectiveness of diagnostic evaluations.Pp 1-63 Supporting documentation encl.
 * Commissioners 88/11/23, 85pp. 47711;224-47711;309.
- 8812020100 Transcript of NRC 881123 affirmation/discussion & vote in Rockville,MD.Pp. Commissioners, 88/11/23, 9pp. 47707;226-47707;234.
- 8812050257 Staff requirements memo re Commission 881123 approval voto concerning SECY-88-298 final rule 10CFR62, "Criteria & Procedures for Granting Emergency Access to Nonfederal & Rugional Low Level Waste Disposal Facilities." CHILK, S.J. Office of the Socretary of the Commission. M881123B. 88/12/01. STELLO, V. Ofc of the Executive Director for Operations. 1p. 47740.140-47740.140
- 8812050306 Final rusponse to FOIA request for records App A document encl & available in PDR App B documents complicibly withheld (ref FOIA Exemption 5).

 GRIMSLEY,D.H. Division of Freedom of Information & Publications Sorvices (Post 820515). 88/12/02. POWELSON,R. Scripps-Howard Newspapers. 4pp. 47729 080-47728.084
- -8812050311 Staff requirements memo on notice of violation & proposed imposition of c vil penaltics to communication.

 CHILK S.J. Office of the Secretary of the Commission. EA-88-253. 88/10/20. STELLO,V. Ofc of the Executive Director for Operations. 1p. 47729.084-47729.084.
- 8812060218 Transcript of 881201 meeting w/State of NV in Rockville,MD re high level waste program.Pp 1-54.
 * Commissioners. 88/12/01. 78pp. 47752:284-47752.362.
- 8812060250 Staff requirements momo re 881123 briefling in Rockville,MD on effectivenoss of diagnostic evaluations.

 CHILK,S.J. Office of the Secretary of the Commission. M881123A. 88/12/02.

 STELLO,V. Ofc of the Executive Director for Operations. 1p. 47741:080-47741:080.
- 8812070188 Transcript of 881201 open meeting/affirmation/discussion & vote in Rockvife,MD.Pp.1-2. Commissioners, 88/12/01, 7pp, 47753,072-47753:078.
- 8812130257 Staft requirements memo re 891201 affirmation/discussion & vote in Flockville,MD on SECV-88-291A concerning facility exercise.

 CHILK,S.J. Office of the Secretary of the Commission, M881201C, 88/12/08. Office of the Secretary of the Commission. 1p. 47795-357-47795-357.
- 8812140084 Statt requirements memoire Commissioners 881201 meeting w/ State of NV in Rockville, MD re high tevel waste program.
 CHILK,S.J. Office of the Secretary of the Commission. M881201A. 88/12/12. NRC .
 No Detailed Affiliation Given. 1p. 47797:223-47797:223.
- 8812210118 Partial response to FOIA request for closed Commission meeting transcripts between Jan 1980 & Dec 1985 re plant App A documents available in PDR App B partially withheld & App C documents completely withheld per Sunshine
- GRIMSLEY, D.H. Division of Freedom of Information & Publications Services (Post 880515), 88/12/19, SCHMIEGE, P.A. O'Melveny & Myers, 7pp. 47874:059-47874:127.
- --B812210120 Partially withheld transcript of 810331 closed Commission meeting in Washington,DC to discuss plant order.Pp 1-16.
 * Commissioners. 81/03/31. 13pp. 47874:068-47874:078.
- -8812210122 Partielly withheld transcript of 810825 closed Commission briefing in Washington, DC re-pending adjudicatory proceedings. Pp 1-83.
 * Commissioners. 81/08/25. 16pp. 47874.079-47874;123.
- 8612210178 Statt requirements memo re 861209 meeting w/public officials in Hocky.lie,MD re responsibility for emergency planning for plant. CH:LK,S.J. Office of the Secretary of the Commission. M881209. 88/12/20. Office of the Secretary of the Commission. 2pp. 47877:071-47877:072.

ACNW ADVISORY COMMITTEE ON NUCLEAR WASTE

- 8811300578 Revised staff requirements mamo re 881110 briefing in Rockville,MD on Instituto 78 Revised staff requirements intuition to do 1110 the impair in Proceedings of the Intelligence of the Commission of Staff requested that ACNW provide Commission position on deletion of 10CFR20 205.

 CHILK, S.J. Office of the Secretary of the Commission. W881110, 88/11/28.

 STELLO, V. Ofc of the Executive Director for Operations PARLER, W.C. Office of the General Counsel MCELLER, D.W. Advisory Committee on Nuclear Waste 3pp. 47701:353-47701:355.
- 8812270247 Transcript of Advisory Committee on Nuclear Waste 881221 meeting in Bethasda,MD.Pp 1-118 Supporting documentation encl.
 * Advisory Committee on Nuclear Waste . 88/12/21, 200pp 47924.012-47924.189.

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

- 8811230332 Transcript of ACRS 343rd general meeting on 881117 in Bethesda,MD Pp 1-42 Supporting documentation encl * ACRS - Advisory Committee on Reactor Saleguards, 88/11/17, 60pp. 47841:182-47841:241
- 8812010110 Confirms understanding that Issuance of SER will not constitute approval of power reactor interently safe module design REMICK,FJ. ACRS Advisory Committee on Reactor Safeguards 88/11/22. ZECH,L.W. Commissioners Spp. 47699:307-47699.311.
- 812010117 Concurs in NRC proposal to issue Reg Guido 1.9,Rev 3, "Selection,Design,Qualification,Toetling & Reliability of Diesol Generator Units as Onsitio Electric Power Sys at Nuclear Power Plants."

 REMICK,F.J. ACRS Advisory Committee on Reactor Sateguards. 89/11/22. STELLO,V. Otc of the Executive Director for Operations. 1p. 47699:312-47699
- 8812010143 Concurs in regulatory position of proposed reg guido, Task EE 006-6, "Qualification of Safety-Related Lead Storage Batteries for Nuclear Power Flants," based on ACRS 343rd meeting on 881117-18. REMICK, F.J. ACRS. Advisory Committee on Reactor Safeguerds. 89/11/22. STELLO, V. Otc of the Executive Director for Operations. 2pp. 47703.313-47703.314.
- 8812140203 Transcript of ACRS Subcommittee on Thormal Hydraulic Phenomona mooting on 881207 in Bathesda, MD Supporting documentation encl. Pp. 1-277.
 * ACRS - Advisory Committee on Reactor Safeguards 88/12/07, 500pp. 47612.080-
- 8812150169 Transcript of ACRS Subcommittee on Containment Sys 681206 mooting in Bethesda,MD Pp 1-212. Supporting documentalism and:

 * ACRS Advisory Committee on Reactor Safeguards, 88/12/06, 250pp 47826;126-47828-D09
- 8812220054 Transcript of ACRS Subcommittee on Reliability Assurance 881212 meeting in Bethesda,MD.Pp 1-199.Supporting documentation encl.
 ACRS - Advisory Committee on Reactor Saleguards, 88/12/12, 244pp, 47910;103-
- 8812220149 Transcript of ACRS Subcommittee on Advanced Reactor Designs meeting on 881213 in Bethesda MD.Pp 1-244 Supporting documentation enci.
 * ACRS - Advisory Committee on Reactor Safeguards, 88/12/13, 286pp 47882:091-
- 8812220383 Transcript of ACRS 344th meeting (day ond) on 881215 in Bothesda,MD.Pp 1-278.Viewgraphs encl.

 * ACRS Advisory Committee on Reactor Safeguards. 88/12/15. 381pp. 47890:120-47891:139
- 8812220398 Transcript of ACRS 344th general meeting (day two) on 881216 in Bethasda,MD.Pp 1-248.Supporting documentation encl.

 * ACRS Advisory Committee on Reactor Safeguards, 88/12/18, 428pp, 47893:002-

ADVCM NRC ADVISORY COMMITTEE

- 8811300678 Revised staff requirements memo re 881110 briefing in Rockvilla,MD on final rule on stds for protection against radiation.Commissioner Roberts requested that ACNW provide Commission position on detetion of 10CFR20,205. CHILK,SJ. Office of the Secretary of the Commission. M881110. 88/11/29. STELLO,V. Onc of the Executive Director for Operations. PARLER,W.C. Office of the General Counsel. MOELLER,D.W. Advisory Committee on Nuclear Waste. 3pp. 47701-35.47701-
- 47701:353-47701:356
- 8812080014 Forwards charter for Advisory Panel for Decontamination of TMI-2,extending committee life until 801128. HOYLE.J.C. Office of the Secretary of the Commission. 88/11/28. DEAN,J.L. General Services Administration. 4pp. 47757:102-47757:117.
- -8812080016 Forwards updated charter by NRC on 881128 to extend life of Advisory Panel for Deconfamination of TMI-2 until 901128. HOYLE.J.C. Office of the Secretary of the Commission. 88/11/28. Library of Congress. Ip. 47757:106.47757:106.
- --8812080019 Forwards charter for Advisory Panel for Decontamination of TMI-2. BRADBURNE, J.C. NRC No Detailed Affiliation Given. 88/11/28. SHARR-P.R. House of Rep., Energy & Commerce. UDALL, M.K. House of Rep., Interior & Insular Affairs. BREAUX,J. Senate, Environment & Public Works. 5pp. 47767:107-47767:111.
- -8812080021 Confirms proposal to renew Avisory Panel for the Decontamination of TMI-2 for 2 yrs.

 DEAN, J.L. General Services Administration 88/11/09, HOYLE, J.C. NRC - No Detailed Affiliation Given. 1p. 47757:112-47767:112.

-8812080022 Informs of NRC determination re-renewal of Advisory Panel for TNI-2 for addl 2 yr period. HOYLE, JC Office of the Secretary of the Commission 88/11/01. DEAN, J.L. General Sorvices Administration. 5pp. 47757:113-47757 117

8812270247 Transcript of Advisory Committee on Nuclear Waste 881221 monthing in Bethesda,MD.Pp 1-118 Supporting documentation encil. Advisory Committee on Nuclear Waste. 68/12/21, 200pp. 47824-012-47824:189

COMMISSION NRC COMMISSIONERS

- 8811140247 Responds to 881014 Itrice Commission proposed rule 10CFR26 on kingss-for duty. Rule considered significant step toward goal of ensuring that nuclear power plants operated by moviduals not impaired by drugs or alcohol ZECHI, W. Commissioners. 53FR136785 88/11/04. SHARP, P.R. House of Rep. Energy & Commisco 1p. 47536 208-47536 216
- 8811170122 Responds to 880927 request for review & comment of R Maricin rep119RC reviewed rept & concludes that no new safety concerns known or not being adequately addressed by inconsee improvement program Util committed to correct deficiencies ZECHL.W. Commissioners. 88111/10 D NGELL, J.D. House of Rep., Energy & Commerce. 4pp. 47587 160-47567.168.
- -8812080964 "Fermi II Problem Introduction," HUTCHINSON,W 8. l'er Research Institute 88/08/12, 75pp. 47792,339 47793,052.
- 88.11230077 Responds to 881017 ftr re plent 8 status of offsite emargency preparedness for town of Plymouth,MA Prant will not restart unit NRC satisfied that plant can be operated sately V Stello 881102 memo and, 22CH,LW. Commissioners 68/11/17. HADF-ELD,J.D. Plymouth, MA 4pp 47657:233-47657 242
- --8611230088 Comments on "under advisement" vote of NRC on 881014, which would have given permission to restert plant NRC should contact author for current & up-to-date assessment of where Plymouth is in planting process HADFIELD, J.D. Plymouth, MA 88/10/17, ZECH, L.W. Commissioners. 1p. 47667:242-
- 8811300078 Forwards NRC quarterly status rept covering Third Quarter CY68 in response to direction given in House Rept 97-850. ZECH,L.W. Commissioners. 88/11/10 BEVILL,T. House of Rep., Appropriations 12pp. 47733-001-47733-012
- 8811300081 Forwards quarterly status rept on emergency preparedness for nuclear power plants for Jul-Sept 1988.inability of Commission to forecast licensing schodule for Shoreham & Seabrook noted. ZECH,L.W. Commissioners OL-5 88/11/10. BREAUX,JB Senate, Environment & Public Works, 5pp. 47754:227-47754:231.
- 8811306266 Weekly into rept for wk ending 881118.

 BLAHA,J.L. Ofc of the Executive Director for Operations, 88/11/22, 36cp. 47697.315-
- 8811300288 Responds to 881020 ftr re operation of plants following steam generator teak at Indian Point 3.NRC evaluated event & concluded that no immediate safety concerns warrant shudown of tac-files ZECHL.W. Commissioners. 88/11/23 GILMAN.B.A. House of Rep. 2pp. 47688.313-
- -9811300290 Requests rept on steam generator release Incident at Unit 3 & overall safety of plant Plant should be shut down until public safety absolutely assured GILMAN, B.A. House of Rep. 88/10/20, ZECH, L.A. Commissioners. 3pp. 47689.123-47689:125
- 8812020002 Responds to 881012 ltr re restart of plant.Commission has decided to hold public maeting in Rocky.lle,MD re status of amergancy plans.
 ZECH,L. Commissioners, 88/11/28, YOUNG,A.P. Chatham, MA. 2pp 47754:224-
- --8812020004 Urges that plant not be reopened until viable evacuation plan devised & approved based on 881011 meeting to discuss reopening of plant YOUNG A.P. Chatham, MA. 88/10/12. ZECH,L. Commissioners 1p. 47764;226-
- 8812020012 Responds to 861124 lit re restart of Pilgrim Nuclear Power Station Notification of 861209 meeting in Rockville MD re status of emergency planning zone & reception citr communities re-public protection.
- ZECH.L. Commissioners. 68/11/28. KIRBY.E.P. Massachusetts. Commonwealth of 7pp. 47717.198-47717.204. -8812020014 Requests withhold of approval of operation at Pilgrim Nuclear generating
- pignt. KIRBY,E.P. Massachusetts, Commonwealth of 88/10/24, ZECH,L. Commissioners. 2рр. 47717:203-47717:204.
- 8812050035 Weekly into rept for wk ending 881125.

 BLAHA,J,L. Ofc of the Executive Director for Operations, 88/11/30, 31pp. 47720.331-
- 8812050044 Responds to 881012 lit re restart of plant informs that Commission post-poned decision on proposod restart of plant to further evaluate emergency planning issues & scheduled 881209 public meeting in Rockwile, MD (or hearing, 2ECH_L__Commissioners, 68/11/28, LAWLER,RA, Brewster, MA, 2pp. 47757.078-47757:080
- -8812050047 Informs that Board of Selectmen for Town of Brewster voted during 881011 meeting to request NRC not to reopen plant Board opposed to reopening of facility until adequate evacuation of an developed. LAWLER, R.A. Brewster, MA. 88/10/12. ZECH,L. Commissioners. 1p. 47757:080-
- 8812050327 Final response to FOIA request for documents Forwards App B documents & releasable portions of records identified in App C Documents I sted in App C partially withheld (ref FOIA Exemptions 4 & 6). App A,B & C records in PDB.

 GRIMSLEY,D.H. Division of Freedom of Information & Publications Services (Post 880515). 86/12/02. VAVRA,A. Sik*CO Co, inc. 5pp. 47729.093-47729:188.

- -8812050330 Thip rept of J Lubanau & D Mackenzie (80209 sile v sil of hRO, Inc. 4.3 surveys w/State of NY planned DENTON,HR Office of Governmental & Public Affairs (Post 873413) 8870373 ZECH, ROBERTS, BERNTHAL Commissioners 1p. 47723 396, 47729 698
 - 8812070236 Comments on DOE initial version dry cas's stronge study.cor 38090 request Presentation of spent fuel strenge requestions.com conscioused fuel that the age 8 dry storage technologies available well-trained conscioused as 25CHL W. Commissioners 88/11/18 ROUSSO,S Energy, Dept. of, Upp. 4773304

 - 8812070241 Responds to 881019 lit re-incident during Commission E8101 meeting Meeting scheduled for 881209 to status of ometigency plans 3 read need local communities to protect public in event of omergency ZECHLW Commissioners 88/11/28 DOWD,PIA: VOGLER,DI HAMMISHIAN Duxbury, MA 2pp 47739-351-47799-353
 - ~8812070245 Expresses outrage refereble ejection of State of MA, Assistant Sects ± of Public Safety,P Agnes from 881014 Commission meeting DOWD,P.A., VOGLER,D.J., HAMACEH,A.C. Duxbury, MA, 88710/19, Commission of the 1310-150 (1790-150). 1p. 47739 353-47739:353
 - 8812070259 Informs that Ofc of Invostigations reviewed all title developed (ching investigation of allegations & concluded that no additional work required first of investigations outlining lindings expected in Jan 1989. ZECHL W. Commissioners. 88711728. SHARP,P. House of Rep., Energy & Commissioners. 88711728. SHARP,P. House of Rep., Energy & Commissioners. 88711728.
 - 8812080011 Responds to 881031 requests from Town of Plymouth & Commonwealth MA for addit meatings re plant emorgency preparetiness issues ZECH,L.W. Commissioners 88/12/01 KENNEDY,E.M. KERRY J.F. STUDUS,G.E. House of Rep. 4pp. 47756 259-47756 264 Sect
 - -8812080016 Urgos NRC to agree w/Prymorith area residents re-status of emerges preparedness
 STUDDS,G.E. House of Rep. KENNEDY,E.M., KERRY,J.F. Senate 887:013
 ZECH,L.W. Commissioners. 2pp. 47758.263-47756.264
 - 8812080040 Responds to recommendations by GAO in GAO/RECD 88-184, "NHC 0 commissioning Cost Estimates Appear Low " Disagrees w/GA() conclusion that Nf decommissioning cost estimates appear low." ZECRL W. Commissioners 88/11/18 GLENN, J. Sanata, Governmental Affa-BROOKS, J. House of Rep., Government Operations BREAUX, J.P., Sanate, Environment & Public Works. 13pp. 47750-285-47756-324.
 - -8812080045 "PNL Rebuttal to GAO Rept on Decominiss onling Cents." SMITH,R.I. Battolla Momertal Instituto, Pactic Northwest Laboratory. FIN B 2902 & 10/31. Division of Engineering (Post 870413). 46pp. 47756-278-47756-324.
 - 8812080048 Informs that Commissioners will be unable to attend 491116 hearing plant restart, per 881026 request. ZECH,L.W. Commissioners. 88711710: BELL,C.D. Pennsylvaria. Counter wealth p. 47753:111-47753.116.

 - 47753.112-47753.116
 - 8812080052 Forwards rept of nondisclosure of sateguards into by NEW ter grave ending 880830. ZECHL W. Commissioners. 88711710. BUSH,G.H. Schale, President of the Scha WRIGHT, House of Rep. 5pp. 47753-123-47753.120.
 - 8812080055 Forwards MCU between NRC & DOJ to facilitate exchange of ofe of an enforcement actions & DOJ criminal prosecution. ZECH,L.W. Commissioners. 88710731, DENNIS,E.S. Justice, Dopt. of, Allering Gen. 81, Office of, 11pp. 47753:171-47753-181.
 - 8812090178 Informs of nonination of CI Grimos & RT Novillo for Congressional Awards exemptary suc to public Normhating statements for each non-line end ZECH,LW. Commissioners. 88/11/30 Office of Personnel Management. 6, 47791:337-47791:338.
 - --8812090180 Expresses appointing for outstanding assistance in preparing for Comission meeting held on 870224. Meeting domained great amount of near a transless attention to defail due to speakers attending. ZECH, L.W. Commissioners. 87709720. NEVILLE, R.T. Public Document Branch 47791:323-47791:323.
 - --8812090182 Ack recept of generic technical position on Borehole & Shaft scaling high tovel nuclear waste repositorios & technical position on items & scientics to for level waste geologic repository program subjite OA requirements.

 CHASE,G.H. Interior, Dept. of, Geological Survey, 98/10/19 SCPROLULM Put Document Branch 1p. 47791.324-47791.324.
 - -8812090184 Informs of visit to LPDR Corteous & professional assistance given
 - NRC staff outstanding PERKINS.N.B. Automated Sciences Group, Inc. 88/10/03 Public Document Brain 1p. 47791:325-47791-325.
 - -8812090188 Expresses appreciation for fist of publications titles requested dealing high level radwaste. KEMPEN.T.V. Wester Services, Inc. 88/03/30. WARD,M. Public Document Bran-1p. 47791:326-47791:326
 - -8812090193 Expresses gratitude for outslanding assistance provided in of any h LPDR.
 ROTELURI. Jordan, Apostel, Bitter Associates, Inc. 88/02/01 KILGOFEIL Pul
 Document Branch. 1p. 47791.327-47791.327.
 - -8812090195 Expresses appreciation for svc provided by LPDR on soveral occession BECKER,D. Nuclear Energy Services, Inc. 87712731. SHELBURNE,E. Public Doment Branch. 10, 4779-1328-47781-1328.

- -9812090198 Requests copy of NUHFG 0380,per 820225 telepin Extends appreciation for support & cooperation over est several wks. KUNISH,8 Miller Canteld, Paddock & Stone 87/02/26 WARD,M. Public Document Branch, 1p. 47/91
- -8812090207 Francesies approciation for assistance given by M Dunleavy EGAPL G. Software: Certification Instituti, Santa Mana, CA SHELBURNELE Public Occument Branch. by 47791 330-47791330. 87/01/03
- --8812090212 Expresses appreciation for laking time to set up special training session for PDR bibliographic rutinival sys to: TERA personne' LEVIN,HIA TERA Corp. 06/10/29 CALVIN,L. Public Document Branch, tp. 47791:331-47791:331
- -6812090217 Expresses appreciation for assistance & understanding re-visit to LPDR WESS,H.I. Full-right & Jawerski 65/10717 WARD,M. Public Document Branch 1p 47791-322-47791-322.
- -8612090220 Expresses approximation for telcon & matter of FOIA-85-115 & list of threats & acts of visioner made on insular facilities of threats & the COLA-85-115 & list of threats & satisfy of visioner made on insular facilities of the Colambia State Univ. Mankato, MN 86710716 DUNLAVEY,M. Public Document Branch 1p. 47791:333-47791:333
- -8812090225 Expresses approceeding for obtaining briefing on IAEA Chernobyl meeting transcript CKON EWSKI,C Allmation Not Assigned 86/10/25 KELVIN,L Public Document
- -8812090228 Expresses appreciation for commendable support recoved during DOJ/ CACL phrase labeling operation held at NRC on 860826-0926. PARKER,C CACLING Federal 86710706 SHELBURNE,E , KRONEBUSCH,J. NRC -No Dataled Afriation Given 1p. 47791-335-47791-335.
- --8812090238 American Congressional Award for examplery sec to public & Invites agency participation in important licence awards program Helated documents end GILMAN,B A. House of Hep. Post Office & Civil Service. 88711730. ZECH,L.W. Commissioners. 3pp. 47791;336-47791;338.
- 8812120125 Weekly into rept for wk ending 881202 BLANAUL, Otc of the Executive Director for Operations 88/12/07, 25pp. 47792 002-
- 8812130093 Responds to 881110 ltr requesting Info to Commission enforcement action noncerning 860320 tri from util CARR, K.M. Commissionnes EA.BB.253 - 88/12/06. DINGELL,J. House of Rep., Energy & Commerce 1Hpp - 47792 248-47792 270
- -8812130996 Requests that NRC provide risted Info re Commission dealings w/licensed 860320 lir concerning compliance w/Commission DA requirements.

 DINGELL,J.D. House of Hep., Energy & Commisco SECY-88-283 88/11/10.
 ZECHIL,W Commissioners Spp. 47792 266-47792 270
- 8812200364 Weekly into rupt for wk griding 881209 BLAHA,JL. Old of the Executive Director for Operations 88712715, 32pp. 47868 022-47868 039

CONTRACT NRC CONTRACTS AND MODIFICATIONS

Branch 1p 47791 334 47791 334

47702 026

- 8811290203 Notification of contract execution "Tochnical Assistance in Support of ISIC Planning Function," awarded to SUA/Maxima Corp. FIELDS,J. Administrative Contracts Branch (Pre 860421). FIN D-1229. NRC-33-85-324. 84712703. BASSETT,H.S. Dawsich of Automated Information Services (Pre 861123). FROST,J. NRC-No Deteiled Althuntion Given 1p. 47650:295-47651.087.
- -8811290205 Contract "Technical Assistance in Support of NRC Planning Function," awarded to SBA/Mexima Corp. JONES.P.E. Small Business Administration. * Maxima Corp. IVORY.B.J. Division of Contracts & Property Management (Post 880515). FIN D-1229. NRC-33-95-324, 84/12/03. 152pp. 47650.296.47851.087
- 8812010214 Notification of contract execution, Mod 10,to "Support Svcs for Evaluation of Severe Accident Phenomena" Contractor, BMI, PAGE, M. Contract Administration Branch FIN D-1595, NRC-04-87-086, 88/11/18, GUSTAVE, R. Pregram Managumont, Polyo Covolopment & Analysis Staff (Post 870413) WALKER, T. NRC No Detailed Afficiation Given, 1p. 47709,165-47709,166.
- -8812010221 Mod 10,adding incremental funding to "Support Svcs for Evaluation of Severa Accusent Phenomena."
 * Battelle Membral Instituto, Columbus Laboratories HAGAN,T.F. Division of Contacts & Property Menagement (Post 880515). FIN 0-1595. NRC-04-87-066. 88/11/16 1p. 47709.166 47709/166.
- 8812010226 Notification of contract execution, Mod 2,to "On-Call Maint of NRC Peripheral Computer Equipment" Contractor Computer Maint & Parts Corp. DORSEY, M. Contract Administration Branch. FIN D-1917. NRC-39:88-249. 88/11/18. KRUZIC, P.G. Division of Computer & Telecommunications Services (Post 870413). JONHSON, C. NRC No Detailed Affrication Given. 1p. 47708.176-47709.176.
- --9812010237 Mod 2,revising statement of work & location of equipment,to "On-Call Maint of NRC Peripheral Computer Equipment" STOVALL,WD, Computer Maintenance & Parts Corp. HAGAN,T.F. Division of Contacts & Property Management (Post 880515) FIN D-1917, NRC-39-88-249, 88/11/18 2pp. 47709.177-47709.178.
- 8812010276 Natification of contract execution, Mod 11, to "Technical Assistance in Geo-
- physical Mothods "Contract Neston Geophysical Core
 MACE MH. Contract Administration Branch NRC-02-84-001. 88/11/18
 FUNCHES JL Pegram Management, Policy Development & Analysis Staff (Post
 B70413) IBRAHIMA B MRC No Delaried Affiliation Given to 47709:173-870413). 47709:175.
- —8812010278 Med 11, extending period of performance at no additional, "Technical Assistance in Geophysical Methods." FANNONM Weston Geophysical Corp. HAGAN, T.F. Division of Contracts & Property Management (Post 8805.15), NRC-02-84-001, 687.11718, 2pp. 47709;174-47709;175.

- 8812010280 Notification of contract execution, Mod 6,to "Data Entry/ Processing FBI Cards Chriminal History Rule." Contractor SBA Subcontractor Kenrob & Assoc, Inc. PAGE, M. Contract Administration Branch NHC:33-87-225 88711718. BRADY, R.J. Division of Security (Post 970413). BRADSHAW, B. NRC No Ditabled Affiniation Givon. 1p. 47709.170.47709.172
- ~8812010282 Mod 6.providing incremental funding to "Data Entry" processing FBI Cards Criminal History Hule " Cards Criminal History Hule "Small Business Administration" Kninob & Associates, Inc. EDGEWORTH.P.J. Division of Contracts (870413-880514) NRC-33-87-225 89/11/18 2pp. 47709.171-47709 172
- 8812010284 Notification of contract execution, Mod 2 to "Application of Optical Disc Technology." Contractor Ref Technology, Inc FLEENOR,C. Contract Administration Branch NRC 39-88-243 88/11/18 AMENTA, J Deputy Director for Administration (Post 870413) SMITH, P.A. NRC No Datalled Affili-ation Givon 1p. 47709-256-47709-257
- --8812010288 Mod 2.changing project officer to "Application of Optical Disc Technology," Retrience Technology, inc HAGANT F. Division of Contracts & Proporty Management (Post 880515) NRC-39-88-243 88711718 pt. 47709 257-47709 257
- 8812010291 Notification of contract execution, Mod 18 to "Structural Integrity of LWR Boundary Components-II." Contractor Matis Engineering Associance BELL, S. Contract Administration Branch NRC-04-94-102, 99/11/18 FOREHAND, W. Program Management, Porcy Development & Analysis Staff (Post 870413), TABOADA, A. NRC No Dotal od Affiliation Given 1p. 47769-167-47709-169.
- -8812010294 Mod 18 extending period of performance for 2 months until 881201 at no additional Structural Integrity of LWR Boundary Components-III GREENBLATT, M. Materials Engineering Associates, Inc. HAGAN, T.F. Division of Contracts & Proporty Management (Post 880515). NRC-04-84-102. 88/11/18 2pp. 47709.188-47709.169
- 8812020003 Notification of contract execution: "Engineering Design Study for New NRC Operations Ctr." awarded to Science Applications Init Corp
 MCLEARENT Contract Administration Branch Fin L. 10369, NRC-26-89-291, 89/11/
 15 SPESSARD,RI, Owision of Operational Assessment (Post 870413), MARKSBERRY,D, NRC - No Detailed Affiliation Given 1p 47722-074-47722:082.
- --8812020005 Ltr Contract NRC-26-89-281: "Engineering Design Study for New Oper-stigns Ctr" awarded to Science Applications Intl Corp WIGGINS,E.) Division of Contracts & Property Management (Post 880515), NRC-28-89-281
- 6812050006 Notification of contract execution. "Ofc Moving Sycs," awarded to Alliance Moving & Storago, Inc.
 HAGEY, II Contract Negotiation Branch I. FIN D 2354 NRC-39-89-129. 68/11/15,
 MATTIA, MJ Division of Contracts & Properly Management (Post 880515) ESTEP, G.
 NRC - No Dotard Attitation Given 1p. 47733
- -8812050010 Contract "Ofc Moving Sycs," awarded to SBA Subcontractor, Alliance Moving & Storage.Inc Gooding Orb., Anatom to SDD December 1, Anti-SWAILES.MP Small Business Administration WIGGINS.E.J. Division of Contracts & Property Management (Post 880515). FIN D-2354. NRC-39-89-12B 80/11/15 98pp. 47733.163-47733-260
- 8812130166 Notification of contract execution, Mod 8,10 "Lease/Purchase of Westinghouse PWH Simurator." Contractor Westinghouse PAGE,M. Contract. Administration Branch. FIN B-8778. NRC-05-87-116. 88/11/28. SPESSARD,R.L. Division of Operational Assessment (Post 670413). SHOWE,S. NRC - No Detailed Affiliation Given 1p. 47794 076-47794 078
- -8812130171 Mod 8,adding funds for exercise of option for simulator lease in FY89,to "Lease/Purchase of Westinghouse PWR Simulator." HAMRICK,N.P. Westinghouse Electric Corp. EDGEWORTH,P.J. Division of Contracts & Property Managament (Post 880515). FIN B-8778, NRC-05-87-118. 887/1728, 2pp. 47794:077-47794-078.
- 8812130311 Notification of contract execution, Mod 14, to "Support of Continuing Activities of US Natl Committee for Rock Mechanics" Contractor:Bureau of Mines. CRAMPTON,S. Contract Administration Branch. GUPTA,D. NRC No Dotated Affiliation Given NRC-02-80-038. 891/12/05. DAVIS,E. Office of Nuclear Material Safety & Safeguards,Oirector. 1p. 47626-325-47626.326
- -8812140096 Mod 14, extending period of performance for 2 months at no cost to govi, to "Support of Continuing Activities of US Netl Committee for Rock Mechanics," WHITTLETON, T.R. Interior, Dept. of, Bureau of Mines. EDGEWORTH, P.J. Division of Contracts. & Property Management (Post 880515). NRC-02-80-038. 88/12/06. 1p. 47826.326-47826.326.
- 8812140105 Notification of contract execution. Mod 2,to "Environ Degradation of Overpack Matts." Contractor Cortest Columbus, Inc. MACE,M. Contract Administration Branch. FIN D-1892. NRC-04-87-089. 88/12/06 ARLOTTO,G. Division of Engineering (Post 870413). BOOY,E. NRC No Detailed Attitution Given. 1p. 47799-267-47799-269.
- --8812140112 Mod 2 providing incremental funding for FY89 & revising Section C re-description/Specs/work statement,to "Environ Degradation of Overpack Matte" THOMPSON,N.C. Confess Columbus, Inc. HAGAN,T.F. Division of Confracts & Property Management (Post 880516). FIN D-1892. NRC-04-87-089. 88/12/08. 2pp. 47799.288-47799.289.
- 8812150060 Notification of contract execution Mod 5.10 "Workshop on High-Temp & Nuclear Chamical Processes in Severe Reactor Accidents." Contractor:Nati Academy FLEENOR CM Contract Administration Branch NRC-04-87-107. 88/12/06. GUSTAVE.R.P. Program Management, Petrcy Development & Analysis Staff (Post 870413). ELTAWILA,F. NRC - No Detailed Affiliation Given. 1p. 47824-083-47824-084.
- ~8812160066 Mod 5,extending expiration date from 880930 to 981231,to "Workshop on High-Tomp & Nuclear Chemical Processes in Severe Reactor Accidents." HAGAN,T.F., METZGER,N. National Academy of Sciences. NRC-04-87-107, 88/12/ 08 1p. 47824.084-47824:084.

- 8812180159 Notification of contract execution.Mod 14,to "Ofo Moving Svcs." Contractor:SBA Subcontractor.Alfance Moving & Storage Inc. PAGE, M. Contract Administration Branch. NRC-10-86:255. 88/11/29 MATTIA.M.J. Division of Contracts & Property Management (Post 880515). ESTEP,G. NRC No Deta: ed Affiliation Given 1p. 47830.298-47830.300
- -6812160161 Mod 14 extending period of performance through 881031,to. 'Old Moving SWAILES,M.P., Sma'l Business Administration, R'LEY,J.A. All anco Moving & Storage, Inc. EDGEWORTH,P.J. Division of Contracts & Property Management (Post 680515), NRC-10-86-255, 88/11/29, 2pp. 47850-299-47839-300
- 8812190039 Notification of contract execution,Mod 18,to "Technical Assistance in Support of NRC Licensing Activitios." Contractor,Science Applications Intli Corp FIELDS,J. Contract Administration Branch. Filt D-1313-9. NRC-03-87-029. 88/12/12. BAJWA,S.S., WEST,S. Office of Nuclear Reactor Regulation, Director (Post 870411), CORLEY,D. Ofc or Special Projects. 1p. 47840:169-47840-171.
- -8812190040 Mod 18, providing incromental funds 8 adding FIN L-1033-9, to "Technical Assistance in Support of NRC Licensing Activities."

 * Science Applications International Corp (formerly Science Applications, Inc.), EDGEWORTH, P.J. Division of Contracts & Property Management (Post 880515), FIN D-1313-9, NRC-03-87-029, 88/12/12, 2pp. 47840;170-47840;171.
- 8812190269 Notification of contract execution,Mod 2,to "Improved Methods for Predicting Field-Sca"s Contaminant Transport in Helerogeneous Unsaturated Scils." Contractor MIT. ntractor MIT BELL,S. Contract Administration Branch FIN D-2044, NRC-04-88-074, 88/12/09, ARLOTTO,G.A. Division of Engineering (Post 870413), NICHCLSON,T.J. NRC - No Detailed Affiliation Given, 1p. 47852,170-47852,172.
- -8812190282 Mod 2.adding requirements for publication of research results, to "Improved Methods for Predicting Field-Scale Containment Transport in Heterogenous Ungetureted Soils." Unisaturated 300 Massachuselts Institute of Technology, Cambridge, MA. HAGAN,T.F. Division of Contracts & Property Management (Post 880515). FIN 0-2044, NRC-04-88-074, 88/12/08, 2pp. 47852:171-47852:172.
- 8812190296 Notification of contract execution.Mod 8,to "Steam Generator & Steam Line Overfill Issues." Contractor:SBA. Subcentractor:Scientech.inc.
 BELL,S. Contract Administration Branch, NRC-04-97-398, 88/11/29, GUSTAVE,R.
 Program Management, Policy Development & Analys's Staff (Post 870413)
 SHAUKAT,S.K. NRC No Detailed Affiliation Given, 1p, 47851:273-47851:275.
- -8812190300 Mod 9,deleting completion date for Task 5,to "Steam Generator & Steam Line Overfill Issues." BAKER, L.J. Smell Business Admin'stration. YBARRONDA, L.J. Scientech, Inc. HAGAN, T.F. Division of Contracts (970413-880514), NRC 04-87-398. 88/11/29. 2pp. 47851:274-47851:275.
- 8812210134 Notification of contract execution: "ADP Sys Development & Programming Sycs," swarded to CRC Sys.
 BELLS. Contract Administration Branch. FIN D-1428. NRC-39-88-247. 88/05/18
 AMENTA.J. Deputy Director for information Resources Management (Post 870413).
 MCCLENDON,H. NRC No Detailed Affiliation Given, 1p. 47876-280-47877:042
- -8812210140 Contract: "ADP Sys Development & Programming Sycs," awarded to CRC Sys.

 * CRC Sys.

 * CRC Systems, Inc. HAGAN,T.F. Division of Contracts & Property Management (Post 880515). FIN D-1426. NRC-39-88-247. 86/05/18. 121pp. 47876-281-47877-042.
- 8812270269 Notification of contract execution: "Effective Communications Mode Train-Ing Workbook," awarded to CommCore,Inc. HAGEY,H. Contract Negotiation Branch I. FIN 0-2300. NRC-38-89-331, 88/12/21. GOLDMAN,P. Ofto d Personnel (Post 870413). HARWELL,M. NRC - No Detailed Affiliation Given: 1p. 47927:147-47927:181.
- --8612270280 Confract: "Effective Communication Media Training Workbook," awarded to CommCore,Ince. GILMAN, A.D. CommCore, Inc. WIGGINS, E.J. Division of Contracts & Property Management (Post 880516). FIN D-2300. NRC-38-89-331, 88/12/21, 45pp. 47927;148-47927;149-47927;148-47

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

- 8812010003 FOIA request for into re-physiological effects of exposure to high levels of ionizing radiation including radiation induced injuries suffered by victims of Chernobyl nuclear eccident.
 CHIU.R. Affiliation Not Assigned, 88/11/08, FELTON,J, NRC • No Detailed Affiliation Given, 1p. 47682:127-47682:127.
- 8812010005 Final response to FOIA request for info Computer printout of records avail-B120 booth Final response of Fork tedees to line computer primited of fectors are able in PDR re Chernobyl encl. W/O encl.
 GRIMSLEY,D.H. Division of Freedom of Information & Publications Services (Post 880516), 88/11/28. CHIU,R. Affiliation Not Assigned. 1p. 47682:128-47682:128.
- 6812010008 FOIA request for Eastman Kodak technical proposal for RFP RS-ARM-88-NEWBY,C.T. Interleaf, Inc. 88/10/10. ROBINSON,L. NRC - No Detailed Affiliation Given. 1p. 47683:127-47683:127.
- 8812010010 Partial response to FOIA request for documents.App A document partially withheld (ref FOIA Exemption 5). PHILIPS J. Division of Freedom of Information & Publications Services (Post 880515). 88/11/29, NEWBY,C.T. Interleaf, Inc. 3pp. 47683:128-47683:131.
- --8812010013 Patially withheid "Evaluation Rept of Operational Capability Demonstrations for RFP ARM-880231, "Electronic Publishing Sys."
 NRC No Detailed Affiliation Given, 88/11/28, 1p. 47683:131-47683:131.
- 8812050109 FOIA request for records re 881109 decision to carify to Commission appeal of QL-3 decision to dismiss govis in licensing proceeding. BELAIR, R.R. Kirkpatrick & Lockhart. BELAIR, R.R. Surjoutick & Lockhart. BELAIR, R.R. Surjouk County, NY. 88/11/17. NRC No Detailed Affiliation Given. 2pp. 47729.066.47729.066.

- 8812050113 Final response to FOIA request No agency records subjets request located Licensing. Board decision not certified to Commission Commission chose through exercise of discretionary authority. In take jurisdiction over sanctions GRIMSLEY,D.H. Division of Freedom of Information & Publications Services (Fos 890515). 88/12/01. BELAIR,R. Kirkpainck & Lockhart BELAIR,R. Suffok County, Med. 47729. 887-4729. 887-1p. 47729.087-47729.087.
- 8812050123 Second partial response to FOIA request App D documents available PDR Records subj to request referred to Dopt of Labor for review & direct response GRIMSLEY, D.H. Division of Freedom of Information & Publications Schools (Pos 880515), 88/12/01, BAUMAN, L. Government Accountability Project 2pp. 47729 088 47728 091.
- 8812050128 FOIA request for records showing offerts on part of NRC or Congress to impose Price-Anderson requirements on malt Processes
 FELTON,JM. Nuclear Liconsing Reports. 887/10/19. GRIMSLEY,D.H. NRC No Oxitated Affiliation Given 1p. 47729/025-47729/025.
- 8812050277 Final response to FOIA request for documents Forwards App. A. & documents App. B. documents partially withheld (ref. FOIA Exemption 5) Documents also evalvable in PDR. also avarable in PDA. GRIMSLEY,D.H. Division of Freedom of Information & Publications Services (Po-880515)_88/11/28. FELTON,J.M. Nuclear Licansing Reports App 47729 28
- -8811040169 SECY-88-284 Requests Commission approval of format & scheduto to Price-Anderson negotiated rulemaking PARLER,W.C. Office of the General Counsel 88/10/05, 20pp. 47729-052-47729-07
- ~8812050279 Requests total number of licensees In listed categories.pcf Price-Ande son program actions.

 LUBENAU,J.O. Assistant Director for State Agreements Program 88/19/04, Afrikate, Not Assigned 22pp. 47729.030-47729.051.
- -8812050285 Discusses schedule for Price-Anderson program for radiophaim license:
- -8612050287 Forwards notice of intent to conduct negotiated rulemaking, pro invival draft NRC position statement & NMSS addit text, into partially withhold MCELROY, M. Medical, Academic & Commercial Uso Safety Branch, 6371071 THOMPSON,H.L., BERNERO,R.M., CUNNINGHAM,R.E. Office of Nuclear Mater. Safety & Safeguards, Director, 5pp. 47729.074-47729.078.
- 8812050278 Appeals denial of FOIA request for documents containing protection advise between Commissioners & staff Documents do not contain adjuctation retirements.
- or other decision of Commission RHODES,J. Ponnsylvania, Commonwealth of, 88/10/24, NRC No Deta ed Affiliatin Given: 1p. 47729:187-47729:187.
- 8812050283 Responds to appeal of denial of FOIA request for documents. Forward portions of Eleasser 880505 memo. Marcus 871222 memo withhold (ref FC A Exemples 5).

 CHILK, S.J. Office of the Secretary of the Commission, 88/11/30 RHODES J. Perosylvania, Commonwealth of, 2pp. 47729.188-47729.201.
- -8812050288 Trip rept of Commissioner Carr & T Elsasser 871215 sto visit to utal 871218 attendance at Region I periodic regional resident counterpart muching. ELSASSER, T. NRC No Data fed Affiliation Given. 88/01/05. NRC No Data/ed Affiliation Given. 3pp. 47729:199-47728:201.
- 8812050303 FOIA request for Otc of Enforcement 681003 proposal to Commissioned recommending fines for TVA re S White inaccurate, written sworn statements to IVF POWELSON,R. Scripps-Howard Newspapers. 88/10/25. GRIMSLEY,D. Onision Freedom of Information & Publications Services (Post 880515), 1p. 47729.07 47729.079
- 6612059306 Final response to FOIA request for records App A document end. & evaluation in PDR App B documents completely withhold (ref FOIA Exemption 5). GRIMSLEY, D.H. Division of Freedom of Information & Publications Sonical (Pc 880515), 88/12/02. POWELSON,R. Scripps-Howard Newspapers. 4pp. 47729-084.
- -8812050311 Staff requirements memo on notice of violation & proposed imposition
- ckil penalties re communication.
 CHILK,S.J. Office of the Secretary of the Commission. EA-88-263 69/10/2
 STELLO,V. Ofc of the Executive Director for Operations. 1p. 47729.084-47/29.084.
- 8812050326 FOIA request for documents to incidents or investigations of products first containing nuclear mails mig by either NRD div of Mark IV Industries or Nerbert Pro-VAVRA.A. SIMCO Co., Inc. 88/04/05, POOLE,M.J. Office of Administration & Fi sources Management, Director (Post 870413). 1p. 47729.092-47729.092.
- 8812050327 Final response to FOIA request for documents. Forwards App B documer & releasable portions of records identified in App C. Documents listed in App C. partily withheld (ref FOIA Exemptions 4 & 6). App AB & C records in PDR.
 GRIMSLEY.D.H. Division of Freedom of Information & Publications Services (Pc 880515). 68712702. VAVRA,A. SIMCO Co., Inc. 5pp. 47729:093-47729:186
- -9812050330 Trip rept of J Lubensu & D Mackenzie 880209 site visit of NID Inc Assurveys w/State of NY planned.
 DENTON,H.R. Office of Governmental & Public Affairs (Post 870413) 897-037;
 ZECH, ROBERTS, BERNTHAL Commissioners. 1p. 47729.098-47729.098.
- -8812050333 Advises that on 880413,metal particles found in bottles blow molded press in facility & nuclear ionizer containing Po-210 found missing Caused by accide lat grinding of static eliminator containing 3.5 mCI Po-210. KEATING L. NRD, Inc. 68/04/14. Region 1, Ofc. of the Director. 6pp. 47729.05 47729.104.

- -8812050337 Advises that an 880413 metal particles found in bottles blow molded on blow molder at facility & nuclear lonizar w/Po-210 found missing Caused by accidental grading of static of manator Purging of pross & ground mail disposal planned PELCR A Eventio Crater. 88704714 Rog on 1, Otc of the Director. 2pp. 47729.105. 47729:108
- -8612050339 Forwards 24 samples of polycarbonate bottles for analysis. Bottles prior to accidental grinding of Pol-210 tonizer & after accidental grinding of radioactive matterarked 3/98.8 6/20/88, respectively.
 PELC.R.A. Eventle Crater 88/08/20. TAYLOR.M. Region 1, Ofc of the Director. 40pp
- -8812050342 Forwards partially deleted documents re 3M static eliminator problem for NUSSBAUMER,D.A. Assistant Director for Stato Agreementa Program 88/03/14. Affiliation Not Assigned 11pp. 47729 172-47729 186.
- 8812060013 FOIA request for documents re 1986 nuclear accident at Chernobyl & studies comparing & contresting subjlaccident to TMI 780328 accident. DEKOK,D. Patriol, Herrisburg, PA 88/11/14. NRC No Deteited Affiliation Given. 2pp. 47729:325-47729:326.
- 8612060020 Final response to FOIA request for documents Forwards computer printout of records evallable in PDR re-Charnobyl accident & listing of repts available through US GPO & NTIS Identified during 881130 telcon w/ D Levins W/o printout.

 GR MSLEY,D.H. Division of Freedom of Information & Publications Services (Post 660515). 88/12/02. DEKOK,D. Patriot, Harrisburg, PA. 2pp. 47729.327-47729.328.
- 6812060051 Final response to FOIA request for documents. Forwards App B & partially defeted App C documents (rof FOIA Examption 6) App B documents also available in PDR. GRIMSLEY,D.H. Division of Froedom of Information & Publications Services (Post 880515), 88/12/01, GUILYARD,R.A. Ridgway Record, Ridgway, PA. 6pp. 47730.038-47730-242
- -8812060056 Trip rept of 610313 proficensing visit to Atlantic Rolling Co re qualifications of radiography personnel & institution of training program proposed in JK Deichler 601006 & 1202 tris.

 HOPKINS.DR. NRC No Dete
- --8812060067 Provides commants on 591023 application for I.cense to use Ir-102 sealed source & requests for addl into re E Blumberg & LC Shaw radiological experience. Requests to roviso procedures to include Items described in comments BASS:N,N. Atomic Energy Commission 22084, 69/11/06. DEICHLER,J.K. Atlantic Richfield Co. (ARCO), 2pp. 47730-046-47730.047.
- -8812060070 Requests revised procedures described in 600118 application for amend to License 37-01048-04 & clarification of location of signs described in Item 5(d) in subj amend request
 BASSIN,N. Atomic Energy Commission, 60/02/11, DEICHLER,J.K. Atlant.c Richfield
 Co. (ARCO), 1p. 47730-048-47730-048.

- -9812060076 Application for amend to Licunse 37-01048-04 naming ME Blumberg & NF McBride as supervisors for use of byproduct matl. DEICHLER,J.K. Altantic Richfield Co. (ARCO). 24486. 80/02/25 BASSIN,N. Atomic Energy Commission. 1p. 47730.049-47730.049
- --8812080081 Application for amend to License 37-01048-04,making changes to "Administrative,Operating & Emergency Instructions," governing use of Ir-192 DEICHLEFI,J.K. Arlantic Richibid Co. (ARCO), 25531, 80/04/11, BASSIN,N. Atomic Energy Commission, 1p. 47730.050-47730.050.
- -8812060087 Forwards Amond 3 to Liconse 37-01048-04 ro use of Ir-192 sealed Bource,W/o encl.
 MILLER,W.O. Atomic Energy Commission. 60/05/13. DEICHLER,J K. Atlantic Richfield Co. (ARCO). 1p. 47730 051-47730.051.
- --8612060099 Application for amend to License 37-01048-04,naming RH Moore,ME Blumberg & NF McBride,as supervisors for use of byproduct mall W/partially deleted
- DEICHLER, J.K. Atlantic Richteld Co. (ARCO). 27716. 60/07/05. MILLER, W.O. Atomic Energy Commission. 6pp. 47730.052-47730.059.
- -8612960108 Responds to 600705 request for amend to License 37-01048-04, requesting detailed into an iscense training program for radiographers.

 BASSIN,N. Atomic Energy Commission. 27716. 60/08/01. DEICHLER,J.K. Atlantic Richfield Co. (ARCO). 1p. 47730:060-47730-060.
- -8612060113 Responds to 601006 request for amend to License 37-01048-04 & requests to submit name, training & experience in radiation floid of instructors in hoensee radiography training program.

 BASSIN N. Atomic Energy Commission. 27716. 60/11/14. DEICHLER, J.K. Atlantic Richfield Co. (ARCO). 1p. 47730 061-47730 061.

- --9812060119 Denies 601006 request for amend to Licenso 37-01048-04 in view of in-appropriate minimal training of NF McBride & ME Blumberg in radiation field. MASON, J.R. Atomic Energy Commission. 27718. 61/02/01. DEICHLER, J.K. Atlantic Richfield Co. (ARCO). pp. 47730-062-47730-062.
- -8812060123 Informs that no response received from NRC re-licensee application for amend to License 37.01048.04 referred to in NRC 601114 fir & licensee 601202 re-
- Sponse Its.

 DEICHLER, J.K. Atlantic Richfield Co. (ARCO). 0869. 61/02/16. BASSIN,N. Atomic Energy Commission. 1p. 47730:063-47730:063.
- -8812060130 Forwards Amend 4 to License 37-01048-04,authorizing use of byproduct matl by persons w/satisfactory completion of training program described in licensee 810328 fit & individual satisfying 10CFR31.201 provisions.W/o encl MILLER.W.O. Atomic Energy Commission. 61/04/07. DEICHLER,J.K. Atlantic Richfield Co. (ARCO). 1p. 47730:064-47730:084.
- --8812060132 Application for ronewal of License 37-01048-04,authorizing use of 100 Ci ir-192 sealed sources for Tech Ops Model 498-A projector for industrial red-ography SHAWLCC. Atlantic Richfield Co. (ARCO). 38944. 81/11/09. 2pp. 47730.068-47730,089
- -8812060138 Forwards application for renewal of License 37-01048-04.
 ZACHOW,W.C. Atlantic Richfield Co. (ARCO). 38944. 81/11/20. Atomic Energy Commission. 1p. 47730:070-47730:070.

- -8812080140 Forwards application for renewal of Liconse 37-01048-04, authorizing uso of Ir-192 Sources W/o encl HIGGINS.R B Atlantic Richhe'd Co. (ARCO). 5\$519 63/11/18 CUNNINGHAM.R.E. Atomic Energy Commission 1p. 47730.071-47730.071.
- -8812080146 Application for renewal of License 37-01048-04 authorizing use of Ir-192 MCBRIDE,N.F. Atlantic Flichfield Co. (ARCO), 90684, 68/11/28, 2pp. 47730,072-47730.073
- -8812060153 Forwards application for renewal of License 37-01048-04, authorizing use of Ir-192 sources
 HIGGINS,R B. Atlantic Richilotd Co. (ARCO). 90684 66/11/30. Atomic Energy Com-misson. 16pp. 47730.074-47730.089.
- -8812060155 Forwards application for renowal of License 37-01048-04, authorizing use of Ir-192 sources. HICKEY,K J. Atlantic Richiloid Co. (ARCO). 18416. 69/11/12. Atomic Energy Commission. 1p. 47730.090-47730.090.
- -8812060169 Application for renewal of License 37-01048-04,authorizing use of 100,000 mCl Ir-192 sealed sources for Tech Ops Model 498A projector. MCBRIDE,N.F. Atlantic Richilleld Co. (ARCO). 16416. 69/11/12. 3pp. 47730-091-47730 094
- --6812080164 Inquires whether licensee 741106 ftr re application for renewal of License 37-01048-04 acceptable for license renewal or submittal of completed AEC Form 313R required
 MCBRIDE,N.F. Atlantic Richfield Co. (ARCO). 4868, 74/11/13. Atomic Energy Commission. 1p. 47730 095-47730:095
- -8812060169 Advises to submit revised application for renewal of License 37-01048-04 on Form AEC-313R, containing complete info on Item 6 of subj Form 313R w/o rol to previous's submitted info W/part a'ly delieted enct. BASSIN, N Atomic Energy Commission, 37141, 74/12/16. MCBRIDE,N.F. Attantic Richfield Co. (ARCO), 40pp. 47730.096-47730:135.
- -8812060178 Partially deloted litr providing list of ME Blumberg experience received from T Marino & Snyder of United Engineers per V McDonald request DEICHLERJ.K. Atlantic Richfield Co. (ARCO). 69/11/24. BASSIN,N. Atomic Energy Commission. 2pp. 47730:136.47730.137.
- -8812060180 Provides comments in response to questions raised in N Basein 691106 for the licensee 591023 application for byproduct matil license. W/partially defeted encit. DEICHLER, JK Allantic Richield Co. (ARCO). 59/11/13. BUCHANAN.C. Atomic Energy Commission. 6pp. 47730:138-47730:143.
- --8812060189 Partially deleted application for amend to License 37-01048-04,amending litens 4,5-8-18 is "Administrative, Operating, & Emergency Instructions." OEICHLER,J.K. Allantic Richner'd Co. (ARCO) 23782. 60/01/18. BASSIN,N. Atomic Energy Commission. 5pp. 47730.144-47730:148.
- --8812060192 Partially deleted response to AEC 600211 ftr relicensee 600118 request for amond to License 37-01048-04 Partially deleted proposed procedures including changes to administrative operating & emergency instructions and. DEICHLER.J.K. Atlantic Richiloid Co. (ARCO). 0917. 60/02/12. BASSIN,N. Atomic Energy Commission. 4pp. 47730:149-47730:162.
- --8812060200 Partially deleted response to AEC 600801 request for additinfoire licensee 600705 request for amond to License 37-01048-04.Requests additions to subjili-DEICHLER, J.K. Atlantic Richfield Co. (ARCO). 27716. 60/10/06, BASSIN, N. Atomic Energy Commission. 11p. 47730.153-47730:163.
- --8812060203 Partially deleted response to AEC 601114 re Licenso 37-01048-04.providing records supporting claim of complete understanding of isotope handling by NF McBride & all men involved.

 DEICHLERJIK Atlantic Richfleid Co. (ARCO). 8542: 60/12/02. BASSIN.N. Atomic Energy Commission. 10pp. 47730:164-47730.173.

- -8812060205 Partially deleted response to AEC 601114 ltr re License 37-01048-04.Forwards delaied outline of licensee Haling program & revised operating & emergency instructions for inclusion in licensee amend request. DEICHLER, JK. Atlantic Richfield Co. (ARCO). 27716. 61/03/28. Atomic Energy Commission. 12pp. 47730-174-47730-185.
- --8812060209 Ack receipt of 831016 itr informing AEC of exposure of five employees to radiation. Prompt resubmission of rept of sub) employee exposure per enc. 10CFR9, "Public Records," & 10CFR20, "Stds for Protection Against Radiation" requested. PRICE, E.R. Atomic Energy Commission. 20545. 63/10/23. BRISSON,R.J. Martin Marielta Corp. 1p. 47730.186-47730.186.
- --8612060211 Forwards partially withheld rept re employee radiation exposure. BRISSON,R.J. Martin Marletts Corp. 729, 63/10/18. Atomic Energy Commission, 10pp, 47730:187-47730:196.
- →8812060215 Application for renewal of License 37-01048-04,authorizing use of 100 Ci Ir-192 sources, SHAW,L.C. Atlantic Richfield Co. (ARCO), 55519, 63/11/15, 8pp. 47730.197-
- -8812080220 Partially deleted response to AEC 650629 ltr re proposed amend to Li-cense 37-01048-04,clarifying Items 5(b),17 & 22 of "Operating & Emergency Instruc-tions," Rev 9. HIGGINS, R.B. Allantic Richfield Co. (ARCO). 65/07/13. MILLER, W.O. Atomic Energy Commission. 8pp. 47730:205-47730:210.
- --9812060223 Requests clarification of licensee procedures for physical security of unattended devices per 10CFR31 & info a model numbers of leak test kits.
 MILLER,W.O. Alomic Energy Commission. 65/06/29. HIGGINS,R.B. Attentic Richfield Co. (ARCO). 1p. 47730.211-47730.211.
- --8812060225 Forwards partially withheld application for renewal of License 37-01048-04 & requests amend to change Items 1(b) & 14. HICKEY,K.J. Atlantic Richiteld Co. (ARCO). 53025. 74/11/06. Atomic Energy Commis-sion. 1p. 47730 212-47730:212.

- -8812060228 Application for renewal of License 37.01048.04,authorizing use of 100,000 mC ir-192 sealed sources W/partially deleted encl MCBRIDE.N.F. Atlantic Richfield Co. (ARCO). 53025, 74/11/06 7pp 47730 213-47730:219
- --8812060233 Advises that premature application for renewal of License 37-01048-04 made in error & requests to disregard subj 730417 application. HICKEY,K.J. Attentic Richfield Co. (ARCO), 2167, 73/05/25, VASSIN,N. Atomic Energy Commission. 1p. 47730-220 47730-220
- --8812060240 Responds to licenses 730417 application for renewal of License 37-01048-04 & advises that ficensor not expired until 741231. BASSIN,N. Atomic Energy Commission. 37414. 73/05/16. HICKEY,K.J. Atlantic Richfield Co. (ARCO). 1p 47730:221-47730 221.
- --8812060245 Forwards application for renewal of License 37-01048-04, authorizing use of fr-192 sources W/o renewal application. W/partielly deleted ericl. HICKEY,K.J. Atlantic Richfeld Co. (ARCO) 73/04/17. Atomic Energy Commission. 21pp. 47730-222-47700:242.
- 881206D283 FOIA request for records re B&W Mount Athos plantincluding rept that led B&W to be fined in 1985 for violations of NRC radiation protoction requirements. BHANDT,S.G. Affiliation Not Assigned 88/11/01. ROBINSON,L.L. NRC No Detailed Affiliation Given 1p. 47729 329-47729 329.
- 8812060265 Final response to FOIA request for records App A documents end & avail-BBIGHTPH. Division of Freedom of Information & Publications Services (Post 880515), 88/12/01. BRANDT,S.G. Affiliation Not Assigned. 2pp. 47729.330-47730.037.
- -8812060270 List of notices of violation for Inspa w/transmittal dates of Jan 1978 to present * Region 2, Otc of the Director, 88/11/15, 38pp, 47729,332-47730.037.
- 8812070010 Partial response to FOIA request for documents Forwards partially withheld App A documents (ref FOIA Exemption 4). GRIMSLEY, D.H. Division of Freedom of Information & Publications Services (Post 880515), 88712701. JOHNSON, G.E. Swidler & Berlin. 4pp. 47729.202-47729.324.
- --8812070016 Partially de'eled memorandum re alop work order at util. Encl. Info re events leading to liconsee decision to stop certain work being performed by contractor employees et p'ent include deterdiration in reflation protection & security. GWYNN,P. NRC No Deteiled Affiliation Given. 88/11/11. ADER.C., MILLER.C., ELSASSER,T. NRC No Deteiled Affiliation Given. 116pp. 47729:208-47729.324.
- 8812080128 Appeals denial of FOIA request re NRC safety insp of H&G Insp Co. BAUMAN, L. Gardo, B.P. 86/10/24. STELLO, V. Oic of the Executive Director for Operations. 1p. 47763:351-47763:357.
- 8812080129 Denies appeal of donial of 880725 FOIA request for documents re NRC safety insp of H&G insp Co. STELLO,V. Ofto of the Executive Director for Operations, 88/12/05, BAUMAN,L. Garde, B.P., tp. 47763:358-47763:359.
- 8812090173 FOIA request for documents re emergency response plans for reentry of reactor aboard Cosmos 1900.

 AFTERGOOD,S. Committee to Bridge the Gep. 88/10/04. Federal Emergency Management Agency, 2pp 47785;149-47785;150.
- 8812090174 Final response to FOIA request for documents Forwards App A documents PLULYI,J. Division of Fraedom of Information & Publications Services (Post 880515); 88/12/07. AFTERGOOD,S. Committee to Bridge the Gap. 2pp. 47785:151-47785:156.
- --8810140048 Discussos possible NRC regional Involvement In reentry of Cosmos 1900.Plans developed for how govt will respond if rådioactive debris landed in US & procedures to suppl Federal Radiological Emergency Response Plan cnct. JORDAN, E. L. Office for Analysis & Evaluation of Operational Date, Director, 88/09/26, RUSSELL,W.T. Region 1, Oic of the Director, GRACE,J.N. Region 2, Ofc of the Director, DAVIS,A.B. Region 3, Ofc of the Director, 6pp. 47785:157-47785:162.
- 8812090259 FOIA request for draft or advance copy of Commission paper, requisition policy statement, reg guide, technical position, or similar policy document made available to state official or agency prior to publication in FR or availability in
- PDR. FELTON,J.M. Nuclear Licensing Reports. 88/10/06. GRIMSLEY,D.H. NRC No Detailed Affiliation Givon. 2pp. 47764.001-47764:002.
- 8812090279 Final response to FOIA request for documents Forwards App A Items 1,2 & 3 App A, Items 4-11 available in PDR App B documents totally withheld. GRIMSLEY, D.H. Division of Freedom of Information & Publications Services (Post 890515), 88/12/02. FELTON, J.M. Nuclear Licensing Reports. 4pp. 47784:003-47786:046.
- 8807140281 Draft "Technical Position on Financial Assurances for Reclamation, Stabilization, Decontamination & Long-Term Surveillance & Control of U. Roccovery Facilities."

 Division of Low Level Waste Management & Decommissioning (Post 870413), 88/06/30, 78pp. 47765:288-47768:005. -8807140281
- --8812090290 Forwards NRC memo to NRC Regions re licensing of byproduct matt at nonpower reactors.

 NUSSBAUMER,D.A. Assistant Director for State Agreements Program. 88/03/24, Af-filiation Not Assigned. 6pp. 47764:007-47784:015.
- -8812090301 Forwards draft "Technical Position on Alternate Concentration Limits for U Mills Std Format & Content Guide & Std Review Plan for Alternate Concentration Limit Application," for info & comment. NUSSBAUMER,D A. Assistant Director for State Agreements Program. 86/04/12. Col-orado, State of. 2pp. 47784:018-47784:017.
- --8812090308 Draft "Technical Position on Alternate Concentration Limits for U Mile Std Format & Content Guide & Std Review Plan for Afternate Concentration Limit Applica-
 - Technical Branch, 88/04/30, 48pp, 47784:018-47784:065.

- -8812090317 Forwards draft "Technical Position on Alternate Concentration Let's by U Mills" dtd June 1988 & FR notice re "Tachnical Position on Info Needs to Deticn strate Compliance W/EPA Groundwater Protection Stds "NUSSBAUMER,D.A. Assistant Director for State Agreements Program, 88/06/24 Colorado, State of, 1p. 47764/066-47764:110.
- ~8812090333 Forwards principal documents re-rev-of-NRC radiation protection stds in 100FR20. NUSSBAUMER, D.A. Assistant Director for State Agreements Program, 68/06/24 As-filiation Not Assigned, 1p. 47764:120-47784,120.
- -8812090339 "Stds for Protection Against Flaciation," 10CFR20 8 10CFR2 19:30,31,32,34,39,40,50,81 8 70,Commission rev of stds for protections against carry radiation,incorporating changes suggested in public comments,as appropriate. *NRC No Detailed Affiliation Givon, 88708/24, 495pp. 47764:121-47785255
- ~8812120042 Forwards 880420 proposal to establish database on medificenses sits undergoing decommissioning for into & comments. Recomments to establish similar database to track activities of licensees, compatible w/NRC questions NUSSBAUMER, D.A. Assistant Director for State Agreements Program @8706127, Affiliation Not Assigned, 1p. 47765:256-47785.256
- -8812120053 Informs of Region III initiative to establish list to track decommissioning sites where long-lived redenuclides used & of NRC plan to extend subjictable to comments country-Forwards data outline for comments CUNNING-LAM,R.E. Division of industrial & Medical Nuclear Sately [Post 870729] KNAPP,M.R. Division of Low Level Waste Management & Decommissioning (Post 870413), 88/04/20, MARTINT. T. Region 1, Ofc of the Director 27018/3.P. Region 2, Ofc of the Director NORELIUS,C.E. Region 3, Ofc of the Director 2pp 47765/257
- --8812120062 Forwards list of NRC licensees undergoing decommissioning in Region LI where licensees used long lived radionuclidos, involved significant decommissioning setted to this. PAPERIELLO,C.J. Region 3, Oto of the Director. 88/02/12 THOMPSON H.L. Office of Nuclear Material Safety & Safeguards, Director. 26pp. 47765-259-47765-284.
- --8812120065 Provides comments on 880420 proposal re-mattiticenses sites undergoing decommissioning.

 NORELUSICE. Region 3, Oic of the Director. 88/05/12. CUNNING 4AVIPE.

 KNAPP.M.R. Division of Industrial & Medical Nuclear Safety (Post 870725) 259

 47765:285-47765:288.
- -8812120070 Forwards linal draft "Technical Assurances for Reclamation, Stab lization, Decontamination & Long-Term Surveillance & Control of U Peccyce, Facilities," for Intio & review. Document Intended for 10CFR40 implementing guidance NUSSPAUMER, D.A. Assistant Director for State Agreements Program 89/07/06 Cctorado, State of. 1p. 47765:287-47765:287.
- ~8812120091 Forwards advance copy of temporary NRC insp procedure on safety per-formance evaluation factors for mails licensees (TI 2800/15). Recommends that each agreement state develop plan to implement & evaluated performance of subj proce-
- NUSSBAUMER,D.A. Assistant Director for State Agreements Program. 88/07/21 At Idlation Not Assigned. 1p. 47768.006-47768:012.
- -8812120098 Forwards Temporary Insp Procedure 2800/15, "Establishment of Pegonal Trial Program for Early Identification of Matt Licenses Nooding More NRC Attention," & encourages to follow & implement subjiprocedure on Irial basis NUSSBAUMER, D.A. Assistant Director for State Agraements Program &8/08/16 Affiliation Not Assigned 1p. 47766:013-47766:023.
- --8812120111 Forwards notice of proposed rulomaking on custody & long term care of U mill tailings sites for comment. Comment period expires 881024. NUSSBAUMER.D.A. Assistant Director for State Agreements Program 68/08/25. Texas, State of. 1p. 47786.024-47786.024.
- -8612120122 "Custody & Long-Term Care of U Mill Tallings Situs." Advance not se of proposed rulemaking needed to provide procedure that ensures maint of closed sites in manner sufficient to protect public health & safety & environ CHILKS_J. Office of the Secretary of the Commission 88/08/19, 14pp 47766.025-
- --8812120128 Forwards summary of 870224 meeting on large irradiators. Provides guidance on licensing of large irradiators & es supplomentary ref document to sid review plan for applications for licenses for use of different irradiators. LUBENAU,J.O. Assistant Director for State Agreements Program, 88709/19 Affiliation Not Assigned, 8pp. 47766.039-47766:046.
- 8812120044 Final response to FOIA request for documents.Forwards documents Israd in App C.App D totally withheld (ref FOIA Exemption 6).
 GRIMSLEY,D.H. NRC No Ostalled Affiliation Given. 88/11/28. EDER,T.8 Gam.to, Galex & Cantor, 12pp. 47789;207-47789;318.
- ~7905030213 Forwards application for renowal of Matt/Byproduct License 29 C423s-92 JOHNSON,D.B. Burroughs Corp. 99401, 79/03/22. Radiolsolopes Licensing Branch (Pre 790501), 2pp. 47790:006-47790.073.
- --8005070350 Informs that verification data re radioactive content for display devices under License 29-13377-015, will be sent by 800505. REESE, H.E. Burroughs Corp. 0806, 80/04/10. BASSIN,N. Materials Licensing Branch 1p. 47790:074-47790:123.
- -3812120072 Informs of notification of package containing redicactive matt apparently damaged aboard Delta flight. Related info enci.

 SUTHERLAND.J.T. Atomic Energy Commission. 65/03/30. Atomic Energy Commission. 67pp. 47790.124-47790.180.
- 88 12120157 FOIA request for SECY-88-101A,SECY-88-127 & document re joint internity gence community assessment of domestic vehicle-bomb threat to nuclear reactors, RUPERMAN,A J. Nuclear Control Institute, 88/07/18. ROBINSON,L. NRC No Obtailed Affiliation Given. 2pp. 47636:331-47836:332.

- 8812120159 Final response to FQIA reguest for documents Forwards releasable portions of App A documents (ref FOIA Exemption 5) App B documents totally withheld (ref FOIA Exemption 5)
 - PHILIP J NRC No Detailed Affidation Given 88/12/09 KUPERMAN,A J Nuclear Control had tale 4pp 47836 333-47836 344
- -8812120162 SECY-86 101A Partially defeted Commission paper advising Commission of recept of add intelligence into & corresponding change in staff recommendation per SECY-86-101.
 STELLOY Ofcid the Executive Director for Operations. 86/06/12, 4pp. 47836-337-
- -6812140224 SECY-98-127 Partially deleted Commission paper providing Commission whitenge of options for consuderation on contingency planning to counteract possible surface vehicle threat STELLO,V. Old of the Executive Director for Operations, 88/05/10, 4pp, 47838,339-47836 344
- 8812120167 FOIA request for recuments re implementation of US-Japan agreement for nuclear coopuration KUPERMANIA J. Nuclear Control Institute 88/10/20 ROBINSON, I. NRC - No De
 - tailed Affiliation Given 2pp 47836,320-47836,321
- 8812120169 Final response to FOIA request for documents.Forwards partially defeted App A document sub, to Category 4 of request (ref FOIA Exemption 5) No records sub) to Categories 1.2.8.3 of request located GRIMSLEY,DHI Division of Frooton of Information & Publications Sorvices (Post 880515), 88/12/09, KUPERMANIA J. Nuclear Control Institute 3pp. 47836-322-4338-319.
- 47636 330
- -8812140222 SECY-88-302 Partially deleted Commission paper informing Commission of staff condition about Murkowski amend requirements, re-discussions w/Japanese, 8 miles steps in implementing amond STELLO,V Ofc of the Executive Director for Operations 88/10/25 6pp. 47836/325
- 8812120189 Partial response to FO:A request for documents Forwards App T & partially deleted App U documents (ref FOIA Examption 5).App S & T also available in FCR App V documents totally withhold (ref FOIA Examption 5). GRIMSLEY.D.H. Division of Freedom of Information & Publications Sorvices (Post
 - BB3515) 88/12/08. JOHNSON,G E Swidler & Berlin. 14pp 47790.261-47791:170
- -8705290224 Forwards comments to draft containment response to WB Golden et al. 860715 2 206 pot-on Comminment of statt rosources on high priority requested Target date of 870605 for draft response requested TAC 82080 assigned VAHGAS A Duston of Reactor Projects - 17th (Post 870411) TAC 62080 87/05/21 SHAOL Dussin of Engineening & Systems Technology (Post 870411). 2pp 47791.017-47791.018
- -8803300034 Requests review of ancil Insp. Rept 50-293/87-53 on 871116-20 re loss of clisite power event on 871111 for determination of any generic implications resulting from event Response requested within 30 days.

 VARGA,S.A. Division of Reactor Projects - 1/III (Post 870411), 88/03/21, SHAO,L. Division of Engineering & Systems Technology (Post 870411), 88/03/21, SHAO,L. Division of Engineering & Systems Technology (Post 870411), 1805.), C.E. Division of Operational Events Assessment (Post 870411), 1005.), W. Division of Licensee Perfections of Post 1870411, 1905.
 - formance & Quality Evaluation (Post 870411), 1p. 47791.081-47701-086
- -8812120239 Summarizes observations re CV Barry "Rept to Governor on Emergency Preparedness for Accident at Pogrim Nuclear Power Station." BELLAMY, R.R. Region 1, Old of the Director, 87/01/21, MARTIN, T.T. Region 1, Old
- al the Director 23pp 47790 278-47703 359. -8812120246 Discusses testimony before special joint committee on investigation &
- study of util on 870202 KERR,G W. NRC No Detailed Affiliation Given 87/02/10, NRC No Detailed Affilia ation Given. 16pp 47791:001-47791.016
- -8812120262 Forwards util biweekly status rept for period 870804-17.
 WIGGINS, J.T., Region 1, Ofc of the Director. 87/96/19. COLLINS,S.J. Region 1, Ofc of the Director. 11pp. 47791:018-47791:048
- -8812120268 Summarizes minutes of util restart assessment panel 870921 meeting re status of NRC & Leansae activities associated w/ proposed plant restart Outstanding actions as of end of 870903 panel meeting discussed COLLINS.SJ Region 1, Ofc of the Director. 87/10/07. RUSSELL,W.T. Region 1, Ofc of the Director 3pp. 47791:049-47791:051.
- --8812120289 Summarizes minutes of whi restart assessment panel 871008 meeting to status of NRC & Iconese activities associated w/ proposed plant restart Quetarding actions as of end of 870921 panel mooting discussed CCLLINS,S J. Region 1, Olc of the Cirector 87/10/21. RUSSELL,W.T. Region 1, Olc of the Director 47/10/21. RUSSELL,W.T. Region 1, Olc of the Director 47/10/21.
- -8812120270 Summarizes minutes of 871023 meeting w/project manager re proposed schedule & approach to response to State of MA 871015 2:206 potation. BOSERIA A Assistant Director for Pagion I Reactors 2:206, 8710/26. MIRAGLIAF. Odice of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 47781:058-47791:061
- --9812130087 Discusses milnutes of util restart assessment panel 871208 meeting re status of NRC & heensoo activities associated w/ proposed plant restart. COLLINS. J. Region 1, Ofc of the Director 87/12/29. RUSSELL.W.T. Region 1, Ofc of the Director. Spp. 47791.062-47791.068
- ■9812130073 Forwards util biweekly status rept for period 880101-15 BLOUGH,A.R. Region 1, Ofc of the Director, 1-98-11, 98/01/22 WIGGINS,J.T. Region 1, Ofc of the Director, 3pp. 47791:067-47791:069
- -9812130078 Discusses minutes of util restart assossment panel 880202 te/con re status of NRC & Loonseo activutes associated w/ proposed plant restart. COLLINS,S J. Region 1, Otc of the Director 88/02/09. RUSSELL,W.T. Region 1, Otc of the Director 8pp. 47/91.070.47/91.080.
- -8812130082 Forwards responses to questions raised by Senator Kennedy during 890107 hearing on proposed plant restert.

 MURLEY,T.E. Cifice of Nuclear Reactor Regulation, Director (Post 870411), 88/04/
 01. REHM,T.A. Ofc. of the Executive Director for Operations 31pp. 47791.087. 47791:125

- -8812130086 Discusses minutes of util restart assessment panel 880428 moeting re-status of NRC & I censee activities associated w/ proposed plant restart. COLLINS.S.J. Region 1, Otc of the Director 88/05/09 RUSSELL,W.T. Region 1, Otc of the Director, 6pp. 47/91-126-47791 131
- ~8812130087 Discusses minutes of util restart assessment panel 880519 telcon re-status of NRC & Licenson activities associated w/ proposed plant restart. COLLINS.S.J. Region 1, Oic of the Director. 88/05/25 RUSSELL,W.T. Region 1, Oic of the Director. 5pp. 47791.132-47791:146
- -8812130090 Discusses minutes of util restart assessment panel 880630 meeting restatus of NRC & licensee activities associated w/ proposed plant restert.
 COLLINS,S J. Rogion 1, Otc of the Director 88/07/12 RUSSELL,W.T. Region 1, Ofc of the Director, 7pp 47791 147-47791-157
- --8812130092 Discussos minutes of util restart assessment panol 880811 tolcon restatus of NRC & licensee activities associated w/ proposed plant restart. COLLINS.S.J. Region 1, Olc of the Director 88/08/15 RUSSELL.W.T. Region 1, Olc of the Director. 6pp. 47791-158-47791-168.
- --9812130106 Partially deloted lit re proposed agenua for restart assessment panel 680825 meeting in King of Prussia.PA Messachusetts, Commonwealth of 87/09/29 MILLER,M. NRC No Dotaled Affiliation. ation Given 2pp 47791:169-47791:170.
- 8812130135 Partial response to FOIA request for documents informs that App E documents available in PDR GRIMSLEY.DH Division of Freedom of Information & Publications Services (Post 8805151 88/12/12 BAUMAN, L. Government Accountability Project 2pp 47790.257-47790 260
- 8812130154 FOIA request for documents re nuclear mails production complex of India BURROWS.AS Natural Resources Detense Council. 87/09/16. State, Dept. of. 3pp. 47790.247-47790.249.
- 8812130163 Final response to FOIA request for documents Forwards partially doleted App A documents (ref FOIA Exemption 4). GRIMSLEY.D.H. Division of Freedom of Information & Publications Services (Post 880515), 89712712. BURROWS,A.S. Natural Resources Defense Council. 3pp. 47790-250-47790.256
- -8812130187 Partially delated ftr & enct to NRC 660526 briefings to State & ACDA on safety operation of Tarapur reactors SHEA,J.R. NRC No Detailed Afficiation Given 63/06/27. DEVINE,J.B. State, Dept. of. 4pp 47790;253-47790;256.
- 8812130203 FOIA request for documents generated re 880817,22 & 24 meetings on Cosmos 1900. AFTERGOD),S. Committee to Bridge the Gap. 88/09/26. NRC - No Detailled Athil-ation Given 3pp. 47780-181-47790-186.
- -8812130208 FOIA request for documents filed in NRC Incident Response Branch elec-AFTERGOOD,S. Committee to Bridge the Gap. 88/10/08. NRC - No Dotalled Affiliation Given. 3pp. 47790 184-47790.196
- 8812130210 Final response to FOIA request for documents. Forwards NRC records subj GRIMSLEY, D.H. Division of Freedam of Information & Publications Services (Post 880515). 88/12/12. AFTERGOOD, S. Committee to Bridge the Gap. 1p. 47790;197-
- --BB10140084 Forwards communication on COSMOS 1900 re predictions for data & time of reantry Predictions not confirmed but specific astimates will be provided when JORDAN, E. 1. Olfice for Analysis & Evaluation of Operational Data, Director. 88/99/ 28. STELLO, V. Ofc. of the Executive Director for Operations. 3pp. 47790;201-47790 207
- -8812130212 Lists & discusses actions taken by Region IV to ensure read-ness for possible NRC regional involvement in COSMOS 1909 reantly.

 MARTIN,R D. Region 4, Otc of the Director. 88/09/30. JORDAN,E.L. Office for Analysis & Evaluation of Operational Data, Director. 2pp. 47790:198-47790 199.
- --8812130214 Requests to pass info re COSMOS 1900 reentry to staff membera Lated. ZECH,G. Incident Response Brench. 88/09/30. NRC No Detailed Affiliation Given. 1p. 47790.200-47790-200.
- -8812130220 Forwards briefing papers providing into for E Jordan use on stetus of COSMOS 1900 planning & current situation w/Natt Sys for Emergency Coordination & passible impact on NRC. WEISS,B. Incident Response Branch. 88/09/09. PRIEBE,R. Incident Response Branch. 30pp. 47790.208-47790.246.
- -8810140084 Forwards communication on COSMQS 1900 re-predictions for date & time of reentry Predictions not confirmed but specific estimates will be provided when available. JORDAN,E.L. Office for Analysis & Evaluation of Operational Data, Director, 88/09/ 26. STELLO,V. Ofc of the Executive Director for Operations, 3pp. 47790:201-

47790:207.

- -8812130212 Lists & discusses actions taken by Region IV to ensure readiness for possible NRC regional Involvement in COSMOS 1900 reentry. MARTINIA D. Region 4, Ofc of the Giractor. 88/09/30. JORDAN,E.L. Office for Analysis & Evaluation of Operational Date, Director. 2pp. 47790 198-47780:199.
- -8812130214 Requests to pass info re COSMOS 1900 reentry to staff members fisted. ZECH,G. Incident Response Branch. 88/09/30, NRC No Detailed Affiliation Given. 1p. 47790:200-47790:200.
 - -8812130220 Forwards briefing papers providing into for E Jordan use on status of COSMOS 1900 planning & current situation w/Natt Sys for Emergency Coordination & possible impact on NRC. WEISS,B Inclident Response Branch. 88/09/08. PRIEBE,R. Incident Response Branch. 30pp. 47790.208-47790.246.

- 881219U154 FOIA request for inspirepts from 1956-1980 & application for renewel of leense did 850523 REINERT,S Boston Business Journal, 88/11/23 NRC No Delated Afficiation Given 1p. 47841 202-47841 202
- 8812190161 Final response to FCIA request for records App A documents end & evalable in Fun PHILLIPS_J. Division of Freedom of Information & Publications Services (Posl 880515) 88/12/15. REINERT,S. Boston Business Journal 2pp. 47841-203-
- -8802250453 Forwards application for renewal of License SUB-238, authorizing possession & use of U-238 for alloy fabrication, research development & prototype purposes & thorium exides for high temp vacuum meiting TARAS_DN Aumy, Dept. of, 03878-85/05/23 Region 1, Ofc of the Director. 2pp. 47841,205-47841 288.
- --8602250459 Application for renewal of License SUB-236,authorizing use of U-236 for aloy fabrication, research, development & prototype purposes & thorium oxide for high
- temp vacuum melting WAIGHT,E.S. Army, Depy ct, Metanats Technology Laboratory, 03878, 85/03/29, 71pp 47841-207-47841:288.
- 8812190210 FCIA request for W Butler 8 G Lainas 780515 fir to KV Seyfrit re-requirements for Type C testing effet valve maint, Seyfrit 780522 memo to Operating Branches & ret to Listed documents.
 WILLTAM S.O.G. JRA Associates OGW-88-099 88/11/30. GRIMSLEY, D.H. NRC No Octated Affiliation Given 2pp. 47806 327-47808:328
- 8812190214 Final response to FOIA request for records No records subj to request to PHILLIPS J. Division of Freedom of Information & Publications Services (Post 880515), 88/12/15, WiLLIAMS, O.G. JRA Associates 1p. 47806 329-47806 329.
- 8812190280 FOIA request for list of places in US ficensed to generate low level nuclear wasie BENANTI M.A. Ganneit News Service, Washington, DC 88/11/22, ROBINSON NRC-No Detailed Mitiation Gren 1p. 47841.200-47841:200.
- 8812190283 Final response to FO!A requestin/a encl listed.NRC cannot provide list pHtttps://doi.org/10.1009/10.1
- 8812190289 Final response to FOIA request for records Nonproprietary portions of App Bidocuments enci GRIMSLEY,DH Dryslon of Freedom of Information & Publications Services (Post 880515) 88712713. NEWBY,C.T. Interleaf, Inc. 2pp. 47841.059-47841:199.
- -8812190293 Forwards best & final offer for electronic publishing sys in response to BOTATHOUSEN FORWARDS DOTA THIS ATTACK DE BECCOME DUB STRING SYSTEM OSSOCIATION TO SOCIETY OF THE STRING SYSTEM OS TO THE SOCIETY OF THE STRING SYSTEM OF THE SYSTEM OF THE STRING SYSTEM OF THE SYSTEM OF THE SYSTEM OF THE SYSTEM OF THE SYSTEM
- -8812190297 Partially deleted its torwarding best & final offer for electronic publishing
- * Eastman Kodak Co. 88/08/26. MCLEAREN,T. Division of Contracts & Property Management (Post 880515). 2pp. 47841:063-47841:064.
- --8812190301 * Electronic Publishing Sys," proposal.
 * Eastman Kodak Co. 88/08/26, 160pp. 47841:965-47841:199.
- 8812190381 FOIA request for access to nuclear mail transaction rept designating country of origin of U hexaflourde from South Africa. KUMAGAI,T. Japan, Govt. of. 88/12/07. 255/fL.W. Commissioners. 2pp. 47840,193-47840:194.
- 8812190364 Final response to FOIA request for records No agency records subj to request located.
 PHILLIPS,J. Division of Freedom of Information & Publications Services (Post 880515), 88/12/15. KUWAGALT, Japan, Gort of 1p. 47840:195-47840:195.
- 8812190378 Appeals denial of FOIA request for records.Requests release of App C documents. AIROZO,D. Inside N.R.C. (McGraw-Hill Publication), 88/11/01, HOYLE,J. Office of the Secretary of the Commission. 1p. 47868-002-47868-002.
- 8812190384 Response to 881101 appeal of derial of FOIA request.App C records con-tinue to be withheld (ref.FOIA Exemption 5). CHILK S.J. Office of the Secretary of the Commission, 88/12/13. AIROZO,D. Inside N.R.C. (McGraw-Hill Publication) 2pp, 47868 003-47868 009.
- 8812210065 Second partial response to FOIA request for records.App C documents encl & available in PDP.
 PHILLEPS.J. Drisslon of Freedom of Information & Publications Services (Post 880515) 88/12/14. PARRISH,D. Attiliation Not Assigned. 2pp. 47874;128-47874;190.
- -9812210077 Forwards Acosta response to 880715 order suspending license & denying renewal due to drug use. Related info, including press release encl.W/o response. LIEBERMAN.J. Of of Enforcement (Post 870413), 88/07/11, MRAGLIA,F. Associate Director for Projects (Post 870411), 11pp. 47874:131-47874:141.
- -8812210080 Forwards procedures per telcon w/K Baskin.
 MEOFORD,M. Southern California Edison Co. 88/09/20, ZWOLINSKI,J. NRC No Detailed Affiliation Given. 4pp. 47874:142-47874;145.
- --8812219087 Rev 1 to Site Directive NGS D-006, "Alcohol & Drug Use." RAY,H.B. Southern California Edison Co. 88/11/14, 9pp. 47874;146-47874;154.
- -8812210091 Rev 1 to General Administrative Procedure SO123-XV-6.0, "Fitness for Duty."

 * Southern California Edison Co. 88/11/14, 12pp. 47874;165-47874;166
- --8812210096 Temporary Change Notice TCN 1-2 to Rev 1 to General Administrative Procedure SO123-XV-7.0, "Drug Testing Program for Protected Area Access."

 ' Southern California Edison Co. 88/11/14, 16pp. 47874:189-47874:190.

- -8812210185 Temporary Change Notice TCN 1-3 to Roy 1 to 7.
 Procedure SO123.XV-7.0, "Drug Tosting Program for Protecting 2.
 * Southern California Edison Co. 88708719, 2pp. 47874 167 4781.
- 8812210107 FCIA request for all closed seesions 8/or meetings of botween Jan 1980 & Dec 1985 to plant. SCHMEGE.P.A. O Melveny & Myers 887,44/86, NRC No C. 2pp. 47874 057-47974 056.
- 8812210118 Partial response to FOIA request for closed Com-scripts between Jan 1980 8 Dec 1985 re plant App A do -PDR App B partially withhold & App C documents completely a Act. RIMSLEY,D.H. Division of Freedom of Information & Publication 880515) 88/12/19, SCHMIEGE,P.A. O Molveny & Myers, 7pp, 415-4
- -8812210120 Partially withheld transcript of 810331 closed Cc-Washington,DC to discuss plant order.Pp 1-16. * Commissioners 81/03/31, 13pp 47874-066-47874-078
- --8812210122 Partially withhold transcript of 810825 closed Cc Washington,DC reipending adjudicatory precondings Pp 1-83 * Commissioners 81/08/25, 16pp 47874,079-47874,123.
- --8812210128 Partially withhald transcript of 821021 closed Communication, DC repending investigations Pp 1-71.

 **Commissioners 82/10/21 4pp. 47874:124-47874:127
- 8812210291 FOIA request for records identified in encl GC Peters . . site emergency plans & properedness
 BELAIR,R.R. Suffelk County 1000 No Detailed Afritation Given 4pp. 47874 045-47874 048
- GRIMSLEY,D.H. D.vis'on of Franciom of Information & Publicating 880516) 88/12/20 BELAIR,R.R. Kirkpatrick & Lockhart BELAIR R.F. NY. 2pp. 47874.049-47874.056.
- -8812210298 "Shoreham-Seabrook Expicise History." * NRC - No Data led Affiliation Givon, 88/12/20, 4pp 47874 051-4/4/4
- 8812230102 FOIA request for NRC internal policy or manual pro-agency employees to submit differing prot opinions PARRISH, ft. A. Afrikason Not Assigned 88709729. GRIMSLEY, Oir Sch Afrikation Given. 1p. 47011:139-47011:139
- 8812230105 Final response to FOIA request for records App A records GRIMSLEY,D.H Division of Frundom of Information & Publicate 3 - 880515). 88/12/21. PARRISH,R A. Affiliation Not Assigned 3447911;141.
- 8812270213 FOIA request for listing in state order, of NRC FY88 Phase (i.e., innovation research proposals.

 SAMET,K.S. Small Business High Technology Institute 88/12/06 Am.

 Affiliation Given: 1p. 47911;142-47911;142.
- 8812270221 Final response to FOIA request for documents Forwards by 315 ness innovation research proposals received during FY88 GRIMSLEY,D.H. Division of Freedom of Information & Publications 980516), 80712722 SAMET,K. Sma'l Business High Technology 47911:143-47911:164.
- -8812270227 Packago of listing of partially withhold small business www.spogram proposals received during FY88.

 * NRC No Detailed Afficiation Given, 88/12/31, 11pp, 47911-144-479**
- 8812290228 FOIA request for SECY 88-323 re possible geological rep.'s posal of high level waste. PICKETT,E.H. Newman & Holtzingur. 88/11/11. GRIMSLEY,D.H. Des-of Information & Publications Services (Post 880515). 1p. 47875 140-41-
- 8812290228 Final response to FOIA request for documents Forms 1 documents App A documents also available in PDR. PHILIPJ. Division of Freedom of Information & Publications Services if 88/12/27. PICKETT E.H. Nowman & Holtzinger. 2pp. 47875-138-47875.2
- --8611170087 SECY-86-323 Informs Commission of evaluation of posset 4 & . * --to licensing geologic repository for disposal of high level waste PARLER,W.C. Office of the General Counsol STELLO,V. Ofc of the Error for Operations, 88/10/30, 140pp, 47975;141-47975;277.
- 8812290261 FOIA request for documents re TE Murley and qualifications, stds, guidence, instructions or procedures used by NRC in table 8 ciding on petitions filed under 10CFR2.206 & OCRE 880122 petitions filed under 10CFR2.206.
- HIATT,S.L. Ohio Citizens for Rosponsible Energy, 88/08/03. GR: USLE / No Detailed Affiliation Given, 3pp. 47962;183-47962;185.
- 8812290286 Final response to FOIA request for documents Forwards A.; documents App. A. & B. available in PDR.App. C. & D. parta ; & withheld, respectively (ref FOIA Exemptions 8 & 5, respectively). GRIMSLEY, D.H. Division of Freedom of Information & Publications 5.890515). 88712/20. HIATT, S. ONO Citizons for Responsible Energy 831.47882.389.
- ***B609040334 SECY-86-243 Proposed change to procedures for providing # /**
 of 2.06 decisions at staff & Commission Toval Each Commission of well receive 2.06 decisions & secretary will track decisions to ensure views * ***
 PARLER, W.C. Office of the General Counsel. 2.206. 86/08/19. 507

- ~8609090425 Rev 3 to Ofc Etr. 17,establishing procedures for assuing prompt & appropriate notification, & distribution of actions handled per 10CFR2 206 (Director's deci-
- sions)
 DENT(DN,H.R. Office of Nincleur Reactor Regulation, Director (851125-870411), 2,266 85/08/21 Office of Nuclear Regulation, Director (851125-870411) 6cp 47962 233-47962 259
- ~8703110292 Forwards "Quarterly Progress Ropt Chivoland Electric Euminibing Sessive Montering Program for Northeastern Onto 861015-870115," per request REITERL Risk & Reinbil ty Assessment Branch. 87/03/09 AHMAD,M. Obly Univ., Athens OH. 19. 47962 263-47962 263.
- ~8605030507 Forwards SFH denying OCRE 2,206 potition for immediate action to reliève undue risk posed by Inadequate seismic design of plant.Suspension of Leense pending act; studies (geological & geophysical) & engineering review uswarranted BAGCHLG Structural & Geoscionces Branch 2 205 88/04/28 PERKINS,K E. Project Directorate III-3 5pp 47862 320-47962 324
- ~8808310058 Forwards "Curthquakes Injuction Wolls & Perry Nuc'ear Power Plant,C'evoland,QH" which appeared in Aug 1988 Geo'ogy magazine Article conclusions w/o basis & merely used to attract attention.

 REITEHL, Sinculural & Gooscionocos Branch 68/08/29 BAGCHI,G, RIC; IARDSON,J., SHAO,I. NRC No Detailed Athilation Given. 1p. 47982 354-3569.

47932 358

- 8608310128 "Earthquakes,Injection Wolls & Perry Nuclear Power Plant, C'avefand.OH," reprinted from Aug 1988 Goo'ogy magazine AHMAD M.U. Ohio Univ., Athons, CH. 88/C8/31, 4pp. 47982:355-47862:358
- ~6812290273 "Recent & Historic Seam city in Northeastern Oblo. Reactivation of Pre-cambrian Faults & Role of Deep Fluid Infection." SEEBER,L. Columbia Univ., New York, NY, 88/12/20, 27pp. 47962 194-47062 220
- -8812290289 Recommends that director 2 206 denials should explain why necessary to take action right away in addit on to explaining why not necessary to take action at a Lifer completerous 8 to avoid need for formal Commission review.

 MURRAY, P. NRC No Dataled Affliation Given 2 208 88/05/29, NRC No De-1a 'ed Alfil ation Givon 1p 47962-221-47962-221.
- ~8812290291 Forwards revised special distribution requirements form for use in advising staff when 2 206 decision to be issued CUOCO,L. NRC - No. Dota led. Affiliation. Given: 2 206 84/09/17. HQEFLING,D., CYR,K., CHIDAKEL S. NRC - No. Datalled. Alfiliation. Given: 1p. 47862 222-47062.222
- ~6812290292 Forwards new procedures for processing 2 206 politicals & coordinating
- such petitions w/Otc of General Counsel
 LIEBERMAN,J NAC No Dotated Affiliation Given 2206 85/11/19 RURNS,S,
 CYRK, HOEFLING,D NRC No Dotated Affiliation Given 3pp. 47862 223-
- -9812290294 Informs of now heading for FR notices, "Receipt of Publion for Director Decision Under 100:FR2:206," officially amined atoly. BURNS,S NRC No Detailed Afficiation Gwon 2 206 86/07/17, NRC No Detailed Affil ation Gwon 2pp 47962 226-47902 227.
- ••8812290298 Informs that DID number must be entured on DD Indox cards upon gwing out next DD cumber Failure to do so results in different decisions receiving same DD rumber & must be avoided at all costs. ILEBERMANJ, NRC No Data led AIII ation Given, 2 206, 86/10/17, NRC No Detailed Afficiation Given, 3pp. 47862,260-47062,262.
- -8812200299 Forwards outling of ofe procedures for completing director decision in responding to position field per 10CFR2.208 SOI INAIGS M. Assistant Goneral Counsel for Enforcement 2 208, 87/08/24. Assistant General Counsel for Enforcement, 58pp. 47862-264-47962.319.
- -9812300014 Forwards corrected copy of 880622 forwarding fir of Director Docision DD-88-10 to replace Incorrect distribution copy of subjitr. PESHKINS, K.E. Project Directorate III-3 2.208. 88768/29. MURLEY, T., SNIEZEK, J., M RAGLIÁ, ZNRC-No Dotaflod Affriction Given 1p. 47962:325-47962.341.
- ~8812300022 Forwards por 880701 tolcon request,Director Decision DD-86-10 re alloged seismic inadequacies at plant HOEFLING RK Office of the General Counsel 2 206 88/07/06. SILBERG,J E Shaw, Pittman. Potts & Trowbridge. 12pp. 47962 342-47982 353

GEN TEC IS GENERIC TECHNICAL ISSUES

- 8807220389 Notification of 660727 mouting in Rockville,MD to exchange into on findings of EPRI emergency diesal generator rotability simulation calculations & how findings rotate to resolution of B-56, "Diosel Generator Rotability." SERKIZAW Reactor & Plant Safety Issues Branch 89/07/20. ROSA,F., KN:GHT,J., TONDI,D. Electrical Systems Branch. 2pp. 47024:203-47924:204.
- 8807250041 Notification of 880728 meeting w/NUMARC/NUGSBO working group in Rocky [e,MD to discuss station blackout rule (100FR50 63). SERKIZ, A.W. Roactor & Plent Safety Issues Branch, 80/07/20 ROSA,F., KNIGHT,J., GILL,P. Electrical Systems Branch, 1p. 47813.276-47813.276
- 8811280048 Goneric Ltr 68-20 to all licensoos holding Otis & CPs for nuclear power reactor facilities re individual plant exam for sovere accident vulnerabilities.Svc list encl. CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728.303-47729.024.
- 6811290524 Forwards regulatory analysis of resolution of Genoric Issue 125.II.7, "Re-ovaluate Provision to Automatically Isolate Feedwater From Steam Generator During Line Brosk
- BECKJORD,E.S Office of Nuclear Regulatory Research, Director (Post 860720), 88/ 09/00, STELLO,V. Ofc of the Executive Director for Operations, 2pp. 47668.042-47668 067
- 8811300167 Forwards addl info on ATWS mitigation design per 881013 meeting & sub-sequent telcons Util working to resolve remaining issues in timetrame to support in-stal at on in upcoming refueling outage. Widno oversize figure. WIDELL,R.C. Florida Power Corp (subs. of Florida Progress Corp.) 3F1188-11 88/ 11/22 Document Control Branch (Document Control Desk) 17pp. 47697:125-47697.141

- 8811300482 Forwards NUMARC responses to comments re-emergency diesel genera-
- Billioned Fundamental Computer States of the Research Belling Rosal F. Electrical Systems Branch FLACK J. Advanced Reactor & Generic Issue Branch. LOFGREN,E.V. Science Applications, International Corp. (formerly Science Applications, Inc.). 2pp. 47681 047-47681.059
- -8811300489 Forwards responses to NRC comments on EPRI graded approach to morlior ig al emergancy dissel generator reliability por commitment during 881.102 macing Concept of accelerated testing conflicts w/.ntent of reliability based program. MARION,A Nuclear Management & Resources Council (NUMARC) (formerly Nuclear Unity Manage 88/11/21. SERKIZ,A W D.vision of Safety Issue Resolution (Post 880/17) 11pp. 47631.049.47681.059.
- 8812020013 Provides responses to review of resolution of USIs & generic safety issues for RESAR 5P/90.ppr 881027 request. BAGCHLG Structural & Geosciences Branch 88/11/18. MILLER,C.L. Standard attom & Non-Power Reactor Project Directorate. 2pp. 47722:188-47722:189.
- 8812070201 Forwards evaluation approving Issuance of Generic Ltr 88-20 re Individual plant exam for severe accident vulnerabilities per 10CFR50.54(i) requirements SHERON,R.W. Divisor of Systoms Research (Post 880717). GL-88-20. 88/12/01. SPEIS.T.P. Office of Nuclear Regulatory Research, Director (Post 860720). 1p. 47246-203. 47746-203. 47746 275 47746 291.
- --9812070202 "NRC Staff Evaluation in Support of 10CFR50.54(f) Generic Ltr Requiring Individual Plant Exam at Nuclear Power Plants "
 * NRC No Dele led Affriation Givon 88/12/01, 16pp. 47746 278-47746 291.
- 8812070217 Summanzes 881025 meeting w/8WR Owners Group re Terget Rock 2 stage safety/rel of valve selpoint drift Attendoes list & handout enct. CHERNY,F.C. Engineering Issues Branch. 68/11/29. BAER,R. Engineering Issues Branch. 41pp. 47757-037-47757-077.
- 8812210194 Discussos Issue of RHR air ingostion & vortex formation during mid-loop operations per USI A-43, "Contairment Emergency Sump Performance," Extrapolations of USI A-43 results indicate vold fractions could be as high as 6%. SPANO, A.H. Reactor & Plant Safety Issues Branch. 87/06/08. KNIEL,K. Reactor & Plant Safety Issues Branch. 0pp 47874:210-47874:218
- 8812220037 Submits background into re-potential problem concerning proper use & protection of Westinghouse proprietary into in connection w/proposed resolution of USI A-46 Policy in SECY documents should be followed WIESEMANN, R.A. Westinghouse Electric Corp. NS-RAW-88-018. 88/12/05. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 3pp. 47003-012-47003-012-47003-013-4 47903:017-47903 019.

IAE INSPECTION AND ENFORCEMENT

- 8811160211 NRC Into Notice 88-090, "Unauthorized Removal of Industrial Nuclear Gauges." Svc ist end: CUNNINGHAM,R E. Division of Industrial & Modical Nuclear Safety (Post 870720). 88/11/22. Consolidated Edison Co. of New York, Inc. 99pp. 47708:255-47708:257.
- ~8409130075 Submits I st of problems encountered following review of repts re gauges installed in locations where environ conditions exceed mlg specs.

 CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety (Pie 870413). 84/06/13. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 4pp. 47708:258-47708:358.
- 8811180487 NRC Into Natice 88:091, "Improper Administration & Control of Psychological Tests" Svc list enci.
 ROSSI.CE Division of Operational Events Assessment (Post 870411), 88/11/22, Consolidated Edison Co. of New York, Inc. 101pp. 47708:042-47708:142.
- 8811280060 PNO V-88-081 on 881107 reactor cavity sump fevel inside containment observed to increase slightly & on 881116, reactor trip occurred due to low steam generator water level Caused by failure of main feed water pump. RICHARDS,S., POLICH,T. Region 8, Ofc of the Director. 88/11/16. 1p. 47854;162-47654:162
- 8811290030 NRC Into Notice 88-093, "Totelthorapy Events." Svc list enct.
 CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729),
 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp 47811:103-47811:215.
- 8811290370 PNO-III-88-096 on 881118,marsture density gauge storon from open bed of truck while parked Gauge had not been placed in locked container or secured to truck bed as required Licensee reported theft to Sherill dept. SRENIAWSKI,D.J. MALLETT,B.S. Region 3, Ofc. of the Director. 88/11/21, 1p. 47650:031-47650.031.
- 8811290422 PNO-I-88-120:on 881117,misadministration occurred involving remote after loading brachytherapy device.M-sadministration resulted in 2.4 times prescribed dose Dose received by endopronchial timer within std treatment protocols. TRIPP,L M. Region 1, Old of the Director. 88/11/18. 1p. 47802:303-47802:303.
- 8811290452 PNO-IV-88 091:on 881123,hot particle was identified by portal monitor as worker was exiking non-red ological work area located on turbine bidg roof Licensee conducting investigation to determine origin.

 MURRAY,B Region 4, Otc of the Director, 88/11/25, 1p. 47648:200-47848:200.
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valve Actuators." Svc list ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/12/02. Consolidated Edison Co. of New York, Inc. 121pp. 47708:143-47708:254.
- 8911300075 PNO IV-88-090.on 881123,accountability loss of 5 Model 8605-00161-6337 Insatic compasses containing 190 mCr tritium gas reported.Permitee investigating loss & will provide 30 day rept. SPITZBERG,D.B. Region 4, Ofc of the Director. 88/11/23. 1p. 47668:295-47668:295.

- 8811300187 PNO-V-88 083 on 881121, Iconsoe dec'ared unusual event as result of entry into Tech Spec 3.0.3 & pending reactor shuldown Action occurred due to inoperable relays Re'ay tosting completed & unit returned to power.

 JOHNSON,P. BOSTED,C. Region 5, Ofc of the Director. 88/11/21. 1p. 47676:238-47876-238.
- 8811300219 PNO.IV-88-083 on 881121, seven people externally contaminated when low temp_reactor_coolent_inadvertenity_sprayed_from_top_of_reactor_vessef All_work_stopped pending decontamination of reactor bidg Causa under Investigation, HOWELL,A.T. Region 4, Oic of the Director, 89/11/21, 2pp. 47701.319 47701.329
- 8811300261 EN-88-101 on 8811/23 natice of proposed imposition of civil penalty in amount of \$75,000 will be issued to licenses Action based on talluros to adequately implement environ qualification requirements of 10CFR50.49. LUEHMAN_J_LIEBERMAN_J_Ofc of Enforcement (Post 870413). EA-88-101. 88/11/18. 1p. 47677:322-47677.322.
- 8811300262 EN.88-102 on 881123, notice of proposed imposition of civil penalty in amount of \$150,000 will be issued to licensee. Act on based on violations of requirements for environ qualification of certs in items of electrical equipment. WONG, H., LIEBERMAN, J. Ofc of Enforcement (Post 870413). EA-68-138-88/11/18. 1p. 47670-360.
- 8812020287 NRC Info Notice 88-095, "Inadequate Procurement Requirements Imposed by Licensees on Vendors," Svc list encl. ROSSI C E. Division of Operational Events Assessment (Post 870411). IEIN-88-035. 88/12/08. Consolidated Edison Co. of New York, fre. 112pp. 47807.191-47807:302
- 8812020302 PNO-IV-88-092 on 881129 discovered that vortex breakers not installed in any of three emergency containment sumps till investigating why vortex breakers not installed & Initiated steps to fabricate replacement vortex breakers HOLLER,G. Region 4, Otc of the Director 88/11/30, 2pp. 47718:307-47718:308.
- 8812070002 PNS-V-88-008.on 881126, icenses sectived telcon alleging that nonlicensed equipment operator observed using itegal drugs. Individual submitted to urinalysis test & showed positive for merijuana individual terminated on 881130. SCHUSTER, D. Region 5, Oto of the Director. 88/11/30. 1p. 47746.237-47746:237.
- 8812070073 EN 88-103:on 881201,notice of proposed Imposition of civil penalty in amount of \$250,000 will be issued to licensee based on problems in areas of plant operations & radiological controls. LUEHMAN J., LIEBERMAN J. Oic of Enforcement (Post 870413). EA-88-182. 88/11/29. 2pp. 47746 081-47746:082.
- 8812070190 Forwards biweekly fisting of generic communications being considered or under development by NRC List includes all communications reported by 881115. BERLINGER.C.H. Generic Communications Branch. 88/11/17. JACOBS.R. Institute of Nuclear Power Operations. 8pp. 47755;172-47755-177.
- 8812070285 PNS-V-88-007:on 881130.sen'or resident informed of possible tempering events. Caused by chaning person not being able to completely secure associated valving after work activities. Enhanced walkdown performed. SCHUSTER.M., MCQUEEN.A. Region 5, Otc of the Director. 88/12/01. 2pp 47749:228-47749 229.
- 8812080023 PNO-V-88-064 on 861130 unusual event declared & reactor shutdown intiated due to determination that leakage from suppression pool vacuum broaker valve CSP-V9 in oxcess of Tech Spec limit. Valve will be repaired CALOWELLC. BOSTED,C. Region 5, Old of the Director. 88/12/01.

47783 226.

- 8812980053 PNO-I-88-122.on 881292,commencement of reactor shuldown to support main turbine generator detuning planned to correct resonant frequency at normal operating speed of low pressure turbine rotor. Rotor will be detuned.

 SCHMIDT, W., JOHNSON, J. Region 1, Ofc of the Director. 88/12/02 1p. 47783:226-
- 8812080203 PNO-I-68-121 on 881128, apparent loss of sealed source containing 1 Cl Gd-153 discovered. Source noticed missing from hot leb on 881128. Licensee made surveys & Interviewed personnel in effort to locate source. COURTEMANCHES, GLENN, J. Region 1, Oic of the Director. 88/11/30. 1p. 47750:133-47750:133.
- 8812090332 PNO-II-68-068:on 881120, spurious actuation of 19 out of 30 alort & notification sizens occurred Preiminary Info indicated that spurious felse activation caused by o'd activation sys decommissioned later on same day. DANCE, H. Flegion 2, Orc of the Director. 88711/30. 1p. 47762:069-47762:069.
- 8812120177 EN-88-104 on 881207,notice of proposed imposition of civil penalty in amount of \$2,000 issued to licensee. Action based on several violations, including exposure to radiation in excess of applicable limits. FLACK, E., LIEBERMAN, J. Ofc of Enforcement (Post 870413). EA-88-256. 88/12/02. 1p. 47785-213-47785-213.
- 8812130153 PNO-I-88-121A on 881202,update on sealed source containing 1 Ci Gd-153 lost Elforts to tocate source unsuccessful Addition from mtg indicates that brass cylinder has sted cap placed.
 COURTEMANCHES, GLENN,J. Region 1, Otc of the Director, 88/12/02. 1p 47794:309-47794:309.
- 8812130243 PNO-IV-88-095:employees accidentally electrocuted while preparing to clean well intake screen on site water well. One employee declared deed.Caused by truck boom contacting 13.8 kV electric in One employee 1.0 p. HUNNICUTT, D. Region 4, Ofc of the Director 88/12/09. 1p. 47798:129-47798:129
- 8812140044 PNO-III-88-098:on 881121,pinhole leaks in control rod drive hydrautic lines identified Caused by chloride externally induced stress corrosion cracking Leaking hydrautic lines removed 8 replacements planned. DANIELSON,D. HARRISON,J. Region 3, Oic of the Oirector. 88/12/06. ip. 47797:220-47797:220.

- 8812140055 PNS-V-88 007A on 881201.actuation alarm received from reactor cooland pump fire protection deluge sys at Unit 2. Causad by contract watchman who denied any intent to cause damage to plant Two watchman terminated.

 SCHUSTER,M.D. Region 5, Ofc of the Director. 88712707. 1p. 47800:323,47800-329
- 8812140076 PNO-III-88-099 on 881207 nuclear gaugh damaged at Trensco Harrison Steel plant Caused by motion steel spiking onto gauge No detectable contain nation noted trensed seeking consultant to assist w/handling incident WIEDEMAN,D, MALLETT,B Region 3, Ofc of the Director IEIN-89-090 88712707. 1p. 47800-164-47800-164.
- 8812140118 EN-88-106 on 881213, notice of violation & proposed imposition of chul penafty in amount of \$2,500 will be issued Action based on failure to partorm losk to sis at required frequency & to purform dose call bracturacy tests JOHANSENJ, LIEBERMANJ, Oft of Enforcement (Post 870413) EA 68 257 68/12/ 08. 1p. 47814:188-47814 189
- 8812140122 EN-88-105 notice of violation & proposed imposition of cry. penalty in amount of \$25,000 will be issued on 881213. Action based on accesse faile to provide adequate procedural guidance to ensure HPSI remain operable. LUEHMANJ, LIGBERMANJ, Office of Enforcement (Post 870413). EA-68-228, 88/12/08, 1p. 47800.213-47800.213.
- 8812140217 PNO-IV-88 094:on 881207.onsite release of toxic chibino gas occurred Caused by melting of fuelblo safety plug in gas cylindor containing approximate 150 lb of chlorine gas due to close proximity of heater to cylinder Chibin Director 88/12/08 2pp 47814-055 47814-056
- 8812150040 PNO-IV-88-093 on 881205 NRC informed of plans to discort rula facility operations on or before 900630 w/no final date selected Plans include power coastdown using fuel presently in reactor w/no fourth refuc
- 8812160064 PNO-I-88-123.cn 881207,two Army vehicles used to transport employees were contaminated w/H-3 Six employees riding in vehicles determined to have contaminated shoo soles. Possible areas of contamination are being surveyed MILLER_J_WHITE_J_Region_1, Ofc_of_the_Director_88/12/07._ 1p_47924_176-47824.176.
- 8812200093 PNO-III-88-100 on 881207.package containing 75 mCl Tc 99m soler from vehicle parked in front of technologist residence in Twin Rivers,WI Caused by vehicle not being locked 8 package not secured SRENIAWSKI,D., MALLETT,B. Region 3, Ofc of the Director 957:2707, 1p 47863 071-47863.071.
- 8812200134 PNO-III-88-097 on 881205, tube feek identified in Steam Generator B Unit shut down Outage planned to repair loak & perform other maint, including replacement of primary colornt pump seel & repair of primary safety valvo loak. BURGESS,B., AXELSON,W. Region 3, Ofc of the Director, 88/12/06 1p. 47669 146-47868:148
- 8812200139 PNO-III-88-101:on 881207,util & Bochtal announced signing of agreements for jointly owned company to acquire facility & to resolve autstanding claims assezzuated w/Midland Nuclear Plant const project State of MI will be informed BURGESS,B., AXELSON,W. Region 3, Ofci of the Director. 88/12/08 1p. 47670 340-47670-340.
- 8812200147 PNO-III-88-103:on 881212.patient received 15.5 mCl rather than prescribed 8.0 mCl I-131 therapeutic dose for treatment of Graves disease Physician of patient notified of error Circumstances withto reviewed during special insp. WIEDEMAN,D. MALLETT,B. Region 3, Old of the Director. 88/12/14 1p. 47865-285-47868-285.
- 8812200275 PNO-V-88-066 on 881212.toedwater flow significantly reduced due to steam pressure fluctuations to main foedwater pump B (MFP) Fluctuations caused by operator actions. Util located unexpected steam demand from auxiliary stem supply MILLER, D'ANGELO,A. Region 6, Old of the Director. 88/12/13, 2pp. 47850-334.
- 8812210040 PNS-V-88-008 on 881212.discovered lesser quantity of SNM in configuration and stored under tempersaling than Indicated on mail accounting records because to process of opening each of 20 contenties to assure accuracy of SNM count. NORDERHAUGL. SCHUSTER,M. Region 5, Otc of the Director. 86/12/13. 2pp 47881:161-47881:162.
- 8812210133 PNO-III-88-102 on 881210 unit shut down to inspect Raychein heat shurix tubing on about 170 safety-related electrical splices & penetrations to assure that tubing installation meets environ qualification requirements DEFAYETIE, R., KNOP,R. Region 3, Ofc of the Director. 88/12/12 ip 47877.055-47877.055.
- 8812220185 PNO-I-88-125 on 881209 facility removed from svc due to high contausable gas (acetylone) concentrations on Phase C of mein power transformer. Lecresoly plans to replace transformer w/sparo GIBSON,K., SWETLAND,P. Region 1, Ofc of the Director. 88/12/12, 1p. 47892-242-47892-24.
- 8812230052 PNO-1-88-124:on 881200,worker broke 1 1/2-inch natural gas line whit'd removing tree stumps from clearing Gas loak immediately isolated & gas line with a off-Fachity evacurated & local line company called to site.

 ROTHJ, PASCIAK,W. Region 1, Ofc of the Director. 88/12/09. 1p 4/314-350-4/7914:350.
- 8812270195 PNO-I-98-127.on 881212,Model 3411B portable moisture/density gauge missing Caused by missing person possessing gauge. Mishap suspected. DAVIS.J., WHITE.J. Region 1. Ofc of the Director. 88/12/19. Ip 47922 357-47022.357.
- 8812270288 PNO-I-88-126:on 881215.plant shutdown in excess of 48 h to investigate cause of high flow in Number 1 seal leak off line for reactor coolent pump 10.Damaged O-ring found & replaced.Outage expected to tast 7-8 days Press and formed.

 JOHNSON,D., BETTENHAUSEN,L. Region 1, Ofc of the Director. 88/12/16. 1p 47926.006-47926.006.

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 8811230054 Trip rept of 880923 visit to Central Electricity Generating Board, Gloucoster, England to British essential sys status monitor. FISCHER, D.C. Technical Specifications Branch 88/11/08 BUTCHER, E.J. Fechnical Specifications Branch 49p. 47675, 179-47675, 211
- -8811230065 "Essential Sys Status Monitor for Hoysham 2 Nuclear Power Station." HCRNE.B.E. International Atomic Energy Agency. 88/06/13 28pp 47675:183-
- 8812050237 Notification of 881101 moeting w/RM Parsons in Rockville,MD to discuss dry spent tudi storage ROBERTS, JP Fuel Cycle Safety Branch. 88/11/03. ROUSE,L.C. Fuel Cycle Safety Branch. 1p. 47755-046-47755-046
- 8812060071 Forwards response to 881022 ltr ro extent to which NRC examines com-marcial nuclear power plant control rooms. Recommends EPRI "Control Room Deficiencies, Remed at Options & Human Factors Research Needs," dtd May 1988 W/ g enc. ECKENRODE,RJ Human Factors Assessment Branch 88/11/10. WHITE,K.M Affili-ation Not Assigned. 2pp. 47743 142-47743.143.
- 8812090276 "Backlit Analysis in Support of Proposed Generic Ltr 'Loss of DHR'"
 * NRC No Dotatlod Affiliation Given, 88/09/20, 22pp, 47757;272-47757;293.

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

- 8811100222 Forwards addit comments to comments summarized by Rules & Procedures Branch cover memologisisting of editorial or format corrections necessary to make package suitable for FR notice publication,por Regulatory History AC56-1. HAISFIELD.M. NRC - No Dotalled Affiliation Given. AC56-1. 13, 88/11/03, NRC - No Dotale d Affiliation Given. 1p. 47520.027-47520.138.
- -8611100295 Approves continuation of rulemaking re-criteria for licensing long-term custody 8 meint of U mill tailings sites,por 840213 memo NRC regulatory agends, NUREG-0936, sliculd be modified to ruled rulemaking status.
 STELLO,V. Ofc of the Executive Director for Operations AC56-1 19. 88/11/03 DAVIS_J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 47520:112-4750-139. 47520 138
- 8811110039 Forwards NRC assessment of environ radioactive contamination in vicinity of plant & NUREG CR-4286, "Evaluation of Radioactive Liquid Effluent Releases from Rancho Seco...," Evaluations concluded differ environ contaminated STOLZJ, PWR Project Directorate 6, TAC 64735, 89/11/11, RODRIGUEZ,R J. Sacramento Municipal Utility District. 7pp. 47682.086-47682.092.
- 8811160467 NRC Info Notice 88-091, "Impropor Administration & Control of Psychological Tests. Svc list enct. ROSSICE Division of Operational Events Assessment (Post 870411), 88/11/22. Consolidated Edison Co. of Now York, Inc. 101pp. 47708:042-47708 142.
- 8811280046 Generic Ltr 88-20 to all ficonsoes holding OLs & CPs for nuclear power reactor facilities re individual plant exam for severe accident vulnerabrilles.Svc list CRUTCHFIELD,D. Associate Director for Projects (Post 670411). 88/11/23. Consolidated Edison Co. of New York, Inc. 81pp. 47728-303-47729.024.
- 8911280174 Application for amond to Licenso DPR-28,rovising Tech Spacs re NUREG-0737,tiems II K 3.13 & II K 3.22,per GL-83-02.Fee paid. MURPHY,W.P. Vormont Yankeo Nuclear Power Corp. GL-93-02. 88/11/18 Document Convol Branch (Document Control Dask). 10pp. 47653:310-47653:332.
- 8811290147 Forwards proprietary responses to NRC questions re-methodology to analyze SRP Chapter 15 events for PWRs Rept withheld (ref. 10CFR2 790). CCPELAND.R A Advanced Nuclear Fuels Corp. (formarly Exxon Nuclear Co., Inc.) RAC.054:88 18/11/16, Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 47667:009-47667.009
- 8311290219 Forwards "CRDR Summary Rept," per Suppl 1 to NUREG-0737 & NRC 850812 Issuance of rev to 840612 order Human engineering discrepancy corrections scheduled for four consoculive refuting outages beginning w/darly 1981 outage. MROCZKA, E. J. Connocticut Yanken Atomic Power Co. MROCZKA, E. J. Northoast Utilities. TAC 56128, 887:0731. Document Control Branch (Document Control Dask). 3pp. 476.19.201. 47240.19.20. 4764B 240-47849 157
- -8611290222 "CRDR Summary Rept," per Suppl 1 to NUREG-0737.
 * Connecticut Yankeo Atomic Power Co. 88/10/31. 278pp. 47648-243-47649.167.
- 6811290310 Forwards Emergency Operating Procedure Insp Rept 50-263/88-200 on 889711-22 Deficiencies noted. Executive summary of insp w/overview of Insp team The ngs in areas reviewed encl.

 HOLAHAN CA. Division of Reactor Projects - III,IV.V & Special Projects (Post 870411) 88711/14 LARSON C. Northern States Power Co. 8pp. 47867:295-47667:256
- -6811290314 Insp Rept 50-263/88-200 on 880711-22. Deviations noted. Major areas aspected program for implementing emergency operating procedures,por NUREG. 9737, Suppl 1.

 GUTHERIES. Division of Reactor Inspection & Sateguards (Post 870411).

 HARTMANN,P.L., VANDERNET,C.L. Office of Nuclear Reactor Regulation, Director (Post 870411). IEB-86-064. 88/11/08. 44pp. 47667:213-47667:256
- 6611260467 Revises util 801219 commitment made in response to NUREG-0737, item I C 2, "Shift & Rellet Turnover Procedures." Util will meintein sys which evaluates effectiveness of shift & relief turnover procedure on periodic basis. FRISCHLR R. Consumers Power Co. 80/11/21, Document Control Branch (Document Control Dask). 2pp. 47651;198-47651;200.
- 8911290541 Updates status of recommendations per NUREG-1257.List of pending recommendations assigned to Olc of Special Projects and. STELLO,V. Ofc of the Executive Director for Operations, 88/11/25, ZECH Commissioners 4pp 47657:357-47657:360.

- 8811290561 LER 98 029-00 on 881024 containment isolation valves V-38-9, 10, 16,17,22 & 23 foliot to meet NUREG-0737 design criterion. Caused by personnel error, Mod of subj vatvos planned W/881121 lir. CERVENKA,P., FITZPATRICK,E. Generat Public Utilities Corp. - GPU Service Corp. 88/11/21 4pp. 4766/213-4766216
- 8611300130 Forwards safety evaluation accepting util 881021 submitted re-operation w/ deficiency in pressurizer heater power supply until restart from next scheduled refuel
 - ing outage SILVER H. Project Directorate II-2. TAC 69833 88/11/22. WILGUS W.S. Florida Power Corp. (subs of Florida Progress Corp.). 2pp. 47676 302-47676 306.
- ~8811300134 Salety evaluation accopting operation w/existing pressurizer heater power supply design until next refuering outage.

 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/22 3pp. 47676.304-47676.306.
- 8811300157 Forwards additinfo on ATWS mitigation design per 881013 meeting & subsequent telcons.Ut1 working to resolve remaining issues in timeframe to support installation in upcorring refueling outage W/one oversize figure
 WIDELL,R.C. Flordat Power Corp. (subsidiary Florada Progress Corp.). 3F1188-11 68/
 11/22, Document Control Branch (Document Control Dosk) 17pp 47697.125-
- 8811300175 Forwards addl into re u.t. response to MUREG-0737, from if D.1, per util 880630 commitment Complete responses will not be available until 890110. MORRIS, K.J. Omaha Public Power District, LIC-88-1020, 88/11/22. Document Control Branch (Document Control Desk) 4pp. 47676:314-47676:317.
- 8811300438 Ack recept of 881028 ftr informing NRC of sleps taken to correct violations noted in Insp Riepts 50-338/88-24 & 50-338/88-24 Ack util intent to submit emergency plan rev by 891120 which will address violation re staffing Ilmo Power (Virginia Electric & Fower Co.) 1p. 47881.042-47681.042. Power (Virginia Electric & Power Co.) 1p. 47881.042-47681.042.
- 8812010047 NUREG/CR-2007 V07 RADIOACTIVE MATERIALS RELEASED FROM NUCLEAR POWER PLANTS. Annual Report For 1986 TICHLERJ, NORDENIK, CONGENIJ, Brookhaven National Laboratory, FIN B-2234. BNL-NUREG-51581. 88/11/30. Office of Administration & Resources Management. Director (Post 870413), 305pp. 47684:034-47684:338.
- 8812010080 NUREG/CR-5133 A COMPUTATIONAL MODEL FOR CRITICAL FLOW THROUGH INTERGRANULAR STRESS CORROSION CRACKS. SCHROCK, V.E., REVANKAR, S.T., LEE, S.Y. California, Univ. of, Burkeley, CA. FIN B-3043 LBL-21987, 88/11/30. Division of Systems Rosearch (Post 880717) 103pp. 47684 339 47685 081.
- 8812010069 NUREG/CR-5240 COMPARATIVE EVALUATION OF SELECTED CONTIN-UUM AND DISCRETE-FRACTURE MODELS Emphasis On Dispersivity Calculations For Application To Fractured Geologic Media, Croston Study Area, Eastern Washing-KUNKEL, J. R., WAY, S.C., MCKEE, C.R. In-Situ, Inc. FIN D-1163-88/11/30. Division of Engineering (Post 870413): 69pp. 47685-082-47685-153.
- 8812010073 NUREG/CR-4960 CONTROL ROOM HABITABILITY SURVEY OF LI-CENSED COMMERCIAL NUCLEAR POWER GENERATING STATIONS. DRISCOLL,J.W. Argonno National Laboratory, FIN A 2328 ANL-97-22, 88/10/31, Dr-vision of Engineering & Systems Technology (Post 870411), 202pp. 47683;132-47884 033
- 8812010086 NUREG/CR-5053 OPERATING EXPERIENCE AND AGING ASSESSMENT OF MOTOR CONTROL CENTERS
 SHIER,W., SUBUDHI,M. Brookhaven National Laboratory FIN A-3270. BNL-NUREG-62118. 88/06/30. Division of Engineering (Post 870413) 85pp. 47685-164-47685:238.
- 8812010098 Forwards documentation re-technical support ctr.operational support ctr. & gmorgancy operations facrity in response to NUREG-0737,tfoms. III A 1.2 & III A.2.2. MECREDY.R.C. Rochester Gas & Electric Corp. 88/11/23. STAHLE,C. NRC No Detailed Affiliation Given. 20pp. 47698 021-47698 051.
- 8812010250 Forwards Emergoncy Operating Procedure Insp. Ropt 50:219/98:200 on 880908:15 Insp. verified that procedures technically corroct & conformed to owners group guidelines. Safety significance item re-containment venting noted. VARGA, S.A. Division of Reactor Projects I/II (Post 870411). 88/11/20. FITZPATRICK,E. Goneral Public Utiatles Corp. GPU Service Corp. 8pp. 47708:348-4310.000
- -8812010262 Insp Rept 50-219/88-200 on 880908-15.Deficioncies noted. Major areas Botto 1258: Inspected licensee program for implementing amorgancy operating procedures,per NUREO-0737,Suppl 1.
 GUTHIRLE S., WECHSELBERGER, LEW.O. Division of Reactor inspection & Safeguards (Post 870411). 88/11/23. 34pp. 47700:358-47710.029.
- 8812010333 NUREG/CR-5232 UNCERTAINTIES IN MODELING AND SCALING IN THE PREDICTION OF FUEL STORED ENERGY AND THERMAL RESPONSE. WULFF,W. Brookhaven National Laboratory. FIN A-3952. BNL-NUREG-52184. 88/09/30. Division of Systems Research (Post 880717). 53pp. 47680:303-47690:352.
- 8812010343 NUREG/CR-5248 PRIORITIZATION OF TIRGALEX-RECOMMENDED 812010343 NUREO/CH-3249 PHIOMITICATION OF HINGALEA-RECOMMENDED COMPONENTS FOR FURTHER AGING RESEARCH.
 LEYY,1.S., JARREU, D.B. Battole Momoriel Institute, Pacific Northwest Laboratory.
 COLLINGE, P. Science Applications International Corp. (Lornerly Science Applications, Inc.), FIN B-2865, PNL-8701, 88/11/30. Division of Engineering (Post 870413). 206pp.
- 8812010349 NUREG/CR-5180 CLOSEOUT OF IE BULLETIN 80-14: DEGRADATION OF BWR SCRAM DISCHARGE VOLUME CAPABILITY. FOLEY W.J. DEAN,R.S., HENNICK.A. Perameter, Inc. FIN B-8729, PARAMETER IE172, 88/11/30, Division of Reactor Projects III,IV,V & Special Projects (Post 870411) 30pp 47690 233-47890 251
- 8812010353 NUREG/CR-5219 THE MIXING OF IMMISCIBLE LIQUID LAYERS BY GAS SUC-ANTTILA A. Sandia National Laboratories FIN A-1019. SAND88-7118. 8B/11/ 30. Division of Reactor System Satety (860720-870413). 55pp. 47690:252-47690:302.

NONDOCKETED ITEMS 206

- 8812010358 NUREG-1214 R04 HISTORICAL DATA SUMMARY OF THE SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE.
 ALLENSPACH,F. Division of Licensee Performance & Quality Evaluation (Post 870411), 88/10/31, 83pp 47690,158-47690,232
- 8812010366 NUREG-0540 V10 ND8 TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE, August 1-31,1988.

 **Division of Freedom of Information & Publications Services (Post 680515) 88/11/30.435cp.47691.073-47692.147.
- 8812020157 NUREG-0750 V28 NO3 NUCLEAR REGULATORY COMMISSION IS-SUANCES FOR SEPTEMBER 1986, Pages 271-417 Division of Freedom of Information 8 Publications Services (Post 860515), 80/11/
- 30. 156pp 47687.337-47688:132 8812020159 NUREG/CR-5220 V02 DIAGNOSIS OF CONDENSATION-INDUCED
- WATERHAMMER Case Studies IZENSON,M.G., ROTHE,P.H., WALLIS,G.B. Creare, Inc. FIN 0-1703 CREARE TM-1189, 88/10/31, Division of Systems Rosearch (Post 880717) 133pp. 47690 018-

- 8612020164 NUREG/CR-5220 V01 DIAGNOSIS OF CONDENSATION-INDUCED WATERHAMMER Methods And Background IZENSON,M.G., ROTHE,P.H., WALLIS,G.B. Creare, Inc. FIN D-1703 CREARE TM-1180, 98/10/31. Division of Systems Research (Post 880717). 157pp. 47688:133
- 8812020166 NUREG/CR 5183 A USER'S MANUAL FOR THE CONTAMINANT TRANS-PORT MODULE OF THE MIGRAT CODE. NESTOR, C.W., PIN,F.G., REISTER,D.B. Oak Ridge National Laboratory. FIN B-0279. ORNL/TM-10830 80710/31. Division of Low Level Waste Management & Occommis-stanling (Post 670413). 243pp. 47686 290-47689 172.
- 8812020170 NUREG-0333 S08 A PRIORITIZATION OF GENERIC SAFETY ISSUES EMRIT,R., RIGGS,R., MILSTEAD,W. Division of Regulatory Applications (Post 870413). 88/11/30. 212pp 47687:125-47687.336
- 8812020172 NUREG-1272 VO2 NO2 REPORT TO THE U.S. NUCLEAR REGULATORY COMMISSION ON ANALYSIS AND EVALUATION OF OPERATIONAL DATA 1987 Nonreactors Office for Analysis & Evaluation of Operational Data, Director, 88/10/31, 80pp.
- 47690 353 47691 072. 8812020177 Summary of 881024 meeting w/util in Rocky, le,MD re_status of TVA fulfiling commitments made to NRC during restart of plant, recluding Phase II programs & status of next update of plant FSAR.

 DONOHEW, J.N. Cic. of Special Projects 88/11/28 Ofc of Special Projects 21pp.
- 47722:190-47722:210
- 8812020179 NUREG/CR-5135 THE THERMAL HYDRAULICS OF SBLOCAS RELATIVE TO PRESSURIZED THERMAL SHOCK THEOFANDUS,T G. Calfornia, Univ. of. Santa Barbara, CA. LA. CHANCE,J.L., WILLIAMS,K.A. Scrence Applications international Corp. (formetly Science Applications, Inc.). FIN A-7049, LA-UR-88-2871, 88/10/31, Division of Systoms Research (Post 880717), 55pp. 47685:239-47685.282.
- 8812020180 NUREG-0020 V12 N10 LICENSED OPERATING REACTORS STATUS SUMMARY REPORT.Data As OI Soptembor 30,1988 (Gray Book I) SCHWARTZI. Policy & Program Management Staff (Post 870413) 88/10/31, 562pp. 47665 283-47687;124.
- 8812020308 NUREG/CP-0099 PROCEED:NGS OF THE PUBLIC WORKSHOP FOR NRC RULEMAKING ON MAINTENANCE OF NUCLEAR POWER PLANTS. TABATABAI,A. SCOTT,W. Battelle Memorial Instituto, Pacific Northwest Laboratory, DEY,M. NRC No Detailed Affiliation Given. FIN B-2916. PNJ-SA-16308. 88/11/30. Owlsion of Regulatory Applications (Post 870413). 372pp. 47692 304-47693.315.
- 8812020311 NUREG-1333 DRFT FC MAINTENANCE APPROACHES AND PRACTICES IN SELECTED FOREIGN NUCLEAR POWER PROGRAMS AND OTHER U.S. INDUSTRIES. Review And Lessans Learned Craft Report For Comment. DEY,M.K. Division of Regulatory Applications (Post 870413) 88/11/30 156pp. 47692.148-47692.303.
- 8812020316 Advises that replacement of new SPOS will necessitate complete re-review when installed & operational NRC should be informed of new developments. HAYES JJ. Project Directorate II-1. TAC 51287, 88/11/23. BRADHAM,O.S. South Caroline Electric & Gas Co. 2pp. 47711:122-47711:123.
- 8812050338 Forwards comments on draft NUREG/CR-4554, "Puncture of Shipping
- 912400338 Formation Commission of Cask," per 881003 request 8URNETT.R.F. Division of Safeguerds & Transportation (Post 870413), 88/11/14, BOSNAK,R.J. Division of Engineering (Post 870413), 8pp. 47740;250-47740.257.
- 8812060026 Confirms that Preoperational Tost 2:38B-05 completed Util considers Con-Hirmstory from 28 resolved.

 BAILEY,J.A. Georgia Power Co. GN-1518. 88/11/30. Document Control Branch (Document Control Desk). 1p. 47734.238-47734:238.
- 8812060069 Responds to 880415 request for add info re NUREG-0737,tiem II.K.3.5, "Reactor Coolant Pump Trip." Emergency operating procedures encl. SMEDLEY,R.W. Consumers Power Co. TAC 49700, 88/12/01. Document Control Branch (Document Control Desk), 11pp, 47740.334-47741039.
- 8812070201 Forwards evaluation approving Issuance of Generic Ltr 88-20 re individual plant exam for severe accident vulnerabilities per 10CFR50.54(f) requirements. SHERONIB W. Division of Systems Research (Post 980717). GL-89-20. 88/12/01. SPEIST.P. Office of Nuclear Regulatory Research, Director (Post 860720). 1p. 47746.275-47746:291.
- --8812070202 "NRC Staff Evaluation in Support of (ICCFR50.54(f) Generic Lit Requiring Individual Pfant Exam at Nuclear Power Plants " NRC - No Detailed Affiriation Given 80/12/01, 16pp. 47746:276-47748:291.
- 8812080134 Requeste notification of any public meetings to be held on nuclear plant license renewal.per NUREG-1317, "Regulatory Options for Nuclear Plant Licenso Renewal." HAAG,F.G. New York, State of, 53FR32019, 68/10/11, Docketing & Services Branch.

- 8812090097 Forwards SEH re-uitl 831109 & 840629 responses to Generic Ltr. 53-28.ltem 21 (Part 2) which involves continuation of vendor interface program w/NSSS vandor for components required for reactor trip function Responses asceptation. LABARGE, D.E. Project Directorate 1-1 GL-83-28, 88/12/06, BRICKSDJC, New York Power Authority (formerly Power Authority of the State of New York), 3pp. 47762-244-4726-38-6.
- 47762:255
- ~8812090098 SER supporting util response to Generic Lir 89.28, item 2.1 (Part 2) re-confirmation that vendor interface program exists w/NSSS vendor for components that are required for performance of reactor trip function. **NRC No Detailed Allihation Given GL-83-28 89/12/06. 3pp. 47762-247-47762-255.
- 8812090178 Informs of nomination of Ci Grines & RT Neville for Congressional Award
- for exemplary svc to public Nominating statements for each nominge end ZECH,L.W. Commissioners 88/11/30. Office of Personnel Management 669 47791:317-47791:338 --8812090198 Requests copy of NUREG-0980,per 870225 telcon Extends approciation for support & cooperation over lest several wks. KUNISH,B. Miller, Cantield, Paddock & Stone. 87/02/26 WARD,M. Public Document Branch. 1p. 47791-329-47791-329.
- 8812090239 Forwards safety evaluation religit 870403 religibility analysis for additional feedwater sys Util should ensure that sys mods do not result in net reduction in sys DE AGAZIO,A.W. Project Directorato III-3 DB-88-064 88/12/08 SHELTON, D C Tolado Edison Co. 3pp. 47762-256-47762-273
- 8812120017 Forwards SSER 20 (NUREG-0707) re implementation of Comanche Peak Rosponso Toam program plan & issue-specific action plans Utili assessment of root causes for design deliciencies acceptable W/o enci GRIMES.C.I. Ofc of Special Projects 88/12/06. COUNSIL.W.G. TU Electric (formerly Texas Utilities Generating Co.). 2pp. 47789:151-47789:152.
- 8812120033 Forwards request for addl Info re will 080930 Intention to combine emergency operations facilities for plants at single Coatswire see bidg lacity. Straight line, direct & driving distances between plants & Coatswire see bidg requested. BUTLERWIR. Project Directorate 1-2 88/12/06. HUNGER,G.A. Philadelphia Efectic Co. 4pp. 47785:184-47785:187. 8812120076 Forwards corrected Page 2 to util 881201 ltr re response to NUREQ-0737,ttem fl K 3.5 re reactor coolant pump trip. Correct statement is "nominal post trip steam generator pressure expected fin range of 800 psia to 980 psia." SMEDLEY,R.W. Consumers Power Co. 1AC 49700, 89/12/06, Decument Control Branch (Document Control Dosk), 2pp. 47788;168,47788,169.
- 8812120267 Concludes that corrective action establishes acceptable program for resolving technical concerns associated w/ structural design of HVAC sys Suppl 18 to NUREG-0797 and W/o end! GRIMES.C.I. Of a Special Projects. 88/12/06. COUNSIL,W.G. Toxos Listes Co 2pp. 47787:120-47787:121.
- 8812130006 Forwards request for addition or steam generator tube repture enalysis to resolve proposed License Condition 18 of SSER 12 to NUREG-0797 Into requested by 881123. GRIMES,C.I. Ofc. of Special Projects. TAC R00413, 88/12/05. COUNSE, W.G. TU Electric (formerly Texas Utilities Generating Co.). 15pp. 47799, 172-47799 188.
- 8812130014 LER 88:027:00 on 881108 found satpoint of two switches in excess of ellowable selpoints prescribed in Tablo 3.2 B of Tech Specs Trip salpoints resort to within Tech Spec tolorances & re-vanty switch operability. W/881208 ftr. REEVES, DL., HORN, GR. Nebraska Public Power District. CNSS088430, 88/12/08 5pp. 47792 276:47792:280
- 8812130044 Forwards Emergency Operating Procedure (EOP) Insp Rept 50:331/68-200 on 860801-12.Executive summary encl giving everyword insp findings in each area reviewed Response w/ firm commitments for Issuing revised EOPs requested HOLAHAN,G. Division of Reactor Projects III,V.V. & Special Projects (Post 8704.11) 89/12/02. LIU,L. lows Electric Light & Power Co. 6pp. 47792;159-47792.192
- - --8812130046 Emergency Operating Procedure Insp Rept 50:331/88:20 or 880301-12.No violations noted Mejor areas inspected.licerised program for implementing amergency operating procedures as required by NUREG-0737, Suppl 1. DYERJ-E., SMITHJD., HALLJ.B. Division of Reactor Inspection & SafoguarJ9 (Post 870411), 88/11/22, 28pp. 47702:165-47792.192.
 - 8812130172 LER 88-014-00:on 881009, found both rotaining block study for each check valve RHR-2-8740A to be broken Caused by mtg Incorrect heat treatment of check valve-Search made to locate valves w/potential for stud failure, W/981118 tr. MOLAN, JC, SIFFER, JD. Pacific Ges & Efectric Co. DCL-88-281, 88/11/18, 11pp. 47794:240-47794:250.
 - 8812130246 Forwards environ assessment & finding of no significant impact re 860115 request for exemption from 10CFR50 App J. Evaluation published in SSER 3 (NUREG-0781).
 CALVOJJA Project Directorate IV. 88/12/07. GOLDBERG,J.H. Houston Lighting & Powor Co. 5pp. 47796 252-47796-260.
 - 8812150082 Forwards Rev 1 to NUREG-1308, "Summary Rept on Radioactive Matt in West Lake Landiet," per 881206 request.W/o encl. LARIOCHE,G. Fuel Cycle Safety Branch. 88/12/12. BURNS,M E. Association of American Rai/roads. 1p. 47826:311-47828:311.
 - 8812150121 Advises that methodology described in Rev 5 to offsite dose calculation manual within guidelines of NUREG-0133 & acceptable EG&G commonts end. CLARK, R.J. Project Directorate 1-2. TAC 68018, 88712709. HUNGER, G.A. Philadelphila Electric Co. 4pp. 47823:004-47823.012.
 - -8811280118 Discusses evaluation of Rev 5 to offsite dose calculation manual for plant Methodology considered within guidelines of NUREG-0133,but listed discrepancles noted. SIMPSON.F.B. EG&G Idaho, Inc. (subs. of EG&G, Inc.). SIMPSON.F.B. Idaho National Engineering Laboratory. SIM 69-88. 89/07/06. POLK.FI.E. NRC • No. Detahed Aftir

- Owners Group Tech Space Improvement (W/Demonstration for BWR ECCS Actuation nature rentation) Part 2." Rept provides acceptable basis for extending survertance iest nichrals ROSSI.C.E. Dwiston of Operational Events Assessment (Post 870411) 88/12/09 GRACE,O.N. BWR Owners Group. 2pp. 47869.071-47869.124.
- 8812160069 Summary of 881205 ineating w/util & JD Stavanson & Assoc reid rectigen-eration response spectre & snubber reduction program Util committed to provide I sted into discussed consistent w/schedule for snutiber removal W/attendance list _ABECURK N Project Directorate II-3. TAC 67360 88/12/13 Project Directorate II-3. 7pp. 47832-338-47832.344.
- 8812160099 Forwards "DCRDR Second Suppl Summary Rept," per stated review.conducted to ensure satisfaction w/NUREG-0737, published by Generic Ltr 82-
- SIEBER, J.D. Duquesne Light Co., Gt.-82-33, 89/11/15, Document Control Branch [Document Control Desk], 2pp. 47831:010-47831:244.
- 8812180141 Forward Insp Repts 50-424/88-47 & 50-425/88-62 on 881031-1104.No world.ons or deviations identified.

 DECKER,T.R. Region 2, Olc of the Director. 88/12/02 HAIRSTON,W.G. Georgie Power Co. 2pp. 47832-283-47832-295.
- -8812180144 Preoperational Insp. Repts 50-424/68-47 8 50-425/68-62 on 881031-1104 No violations or deviations noted. Weakness noted Major areas inspected radiation protection organization & training & external exposure control GLOERSEN.W.B. Region 2, Otc. of the Director. IEIN-89-063 88/12/02 11pp. 47632 265-47632.295.
- 8812180177 NUREG-0797 S17 SAFETY EVALUATION REPORT RELATED TO THE CPERATION OF COMMNCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2 Dockel Nos 50-445 And 50-446 (Texas Utilities Generating Company) NORKIN, DP Oile of Special Projects 184/11/30, 200pp. 47836.345-47838.020
- 8812180176 NUREG-0797 S18 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF COMANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2 Oocket, Nos. 50.445 And 50-446 (Texas Unitios Generating Company) TERAC, D. Oic of Spocial Projects 88/11/30 98pp 47898/921-47838/120
- 8812160181 NUREG-0797 S19 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF COMANCHE PEAK STEAM ELECTRIC STATION UNITS 1 AND 2 Dochet Nos. 50-445 And 50-446 (Texas Utifiles Generating Company) HUBBARD, G. MALLOY, M. Ofc. of Special Projects. 887/11/30 64pp. 47838 121-47039.188
- 8812190018 NUREG/CR-4638 VO3 P1 NUCLEAR COMPUTERIZED LIBRARY FOR AS-SESSING REACTOR RELIABILITY (NUCLARR) Guide To Data Processing And Rovi-GLMORE, W.E., GERTMAN,D.J., GILBERT,B.G., EG&G Idaho, Inc. (subs of EG&G, Inc.), FIN A-8850, EGG-245B, 88/11/30, Division of Systems Research (Post 880717). 480p. 47806:108-47806:155
- 8812180037 NUREG/CR-4638 VO3 P2 NUCLEAR COMPUTERIZED LIBRARY FOR AS-SESSING REACTOR RELIABILITY (NUCLARR). Guido To Data Processing And Rovison. Part 2: Human Error Probability Data Entry And Revision Procedures. GILMORE.W.E., GERTMAN.D.I., GILDERT, B.G. EG&G Idaho, Inc (subs. of EG&G, Inc.). Fix) A-6850. EGG:2458. 88/11/30. Division of Systems Rosearch (Post 880717). 168pp. 47808.156:47806.326.
- 8912190092 Forwards Amend 147 to License DPR-50 & safety evaluation. Amend Incorporates requirements for operability & calibr frequencies for reactor coolant inventory fronding sys in Tach Specs,per NUREG-073/Itlen II.F.2.

 HERNÁN,R.W. Project Directorate 1-4. TAC 64205. 89/12/13. HUKILL,H.D. General Pub's Utilities Corp. GPU Service Corp. 2pp. 47850 255-47850:276.
- 8812190066 NUREG/CR-4639 VO3 P3 NUCLEAR COMPUTERIZED LIBRARY FOR AS-SESSING REACTOR RELIABILITY (NUCLARR) Guide To Data Processing And Revision Part 3. Hardware Component Failure Data Entry And Rovision Procedures GILMORE,W.E., GERTMAN,D.I., GILBERT,B.G. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6850. EGG-2458. 88/11/30. Division of Systams Research (Post 880717). 92pp. 47804:154-47804:249.
- 88 12190076 NUREG/CR-4527 VO2 AN EXPERIMENTAL INVESTIGATION OF INTER-NALLY IGNITED FIRES IN NUCLEAR POWER PLANT CONTROL CABINETS.Part firRoom Effects Tests.

 CHAVEZ.J.M., NOWLEN,S.P. Sandle National Laboratories. FIN A-1010. SAND86-0336. 88/11/30. Division of Engineering (Post 870413), 68pp. 47804:249-47804:307.
- 8812190085 NUREG-1275 VO3 OPERATING EXPERIENCE FEEDBACK REPORT SERVICE WATER SYSTEM FAILURES AND DEGRADATIONS.Commercial Power Reactors
 LAMP, LEEDS,E. Office for Analysis & Evaluation of Operational Data, Director, 88/11/30, 185pp. 47804:308-47805:103.
- 8812190088 NUREG-0797 S20 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF COMANCHE PEAK STEAM ELECTRIC STATION,UNITS I AND 2. Docket Nos 50-445 And 50-446 (Texas Utilities Generating Company) MCKEEP. BROWN,C. Ofc of Special Projects. 88/11/30. 360pp. 47840.196-47841:056.
- 8812190094 NUREG/CR-5225 AN OVERVIEW OF BWR MARK-I CONTAINMENT VENTING RISK IMPLICATIONS.
 WAGNER,K.C., DALLMAN,R.J., GALYEAN,W.J. EG&G Idaho, Inc. (subs. of EG&G, Inc.), FIN A-6878. EGG-2548, 88/711/30. Division of Safety Issue Resolution (Post 880717), 83pp. 47805:236-47805:319.
- 8812180096 NUREG-0020 V12 N11 LICENSED OPERATING REACTORS STATUS SUMMARY REPORT Data As Of October 31, 1988 (Gray Book I) SCHWARTZ, Division of Contracts & Property Management (Post 880516), 88/12/
- 8812190120 NUREG/CR-5171 FLOW VISUALIZATION STUDY OF POST CRITICAL HEAT FLUX REGION FOR INVERTED BURBLY, SLUG AND ANNULAR FLOW RE-GIMES.
 - DENTEN,J.G., ISHII,M. Argonne National Laboratory. FIN A-2026. ANI,-88-27. 89/11/30. Division of Systems Research (Post 860717). 85pp. 47605:148-47605:235.

- CRACKS IN PRESSURE VESSEL AND P.PING STEELS AN Environment Results CULLEN,W H , JOLLES,M R Materials Engineering Associates, Inc. FIN B-8800. MEA-2198. 88/10/31. Division of Engineering (Post 870413). 64pp. 47805-320-47806.015 ONO 1111 OF
- 8812190133 NUREG/CR-2000 VO?N10 LICENSEE EVENT REPORT (EER) COMPILATION For Month Of October 1988

 *Oak Ridge National Labbrationy, FIN A-9135, ORNIL/NSLIC-200 88/11/30 Office for Analys's & Evaluation of Operational Data, Director, 91pp. 47806.018-47806 107.
- 8812190163 NUREG/CR-5180 CHEMICAL DECONTAMINATION AND CHEMICAL CLEANING OF LWR COMPONENTS AND POSSIBLE INTERACTIONS WITH METAL-
 - LURGICAL AGING EFFECTS.
 DIERCKS,D.R. Argonne National Leboratory. FIN A-2259. ANL-88-30. 88/11/30. Division of Engineering (Post 870413). 52pp. 47805-104-47805-147.
- 8812190168 NUREG-0366 D04 R10 UNITED STATES NUCLEAR REGULATORY COM-MISSION STAFF PRACTICE AND PROCEDURE DIGEST Commission, Appeal Board And Licensing Board Decisions, July 1972 December 1987. * Office of the General Course! 88/11/30 495pp. 47843:122-47844:259
- 8812190181 Forwards SSER 19 (NUREG-0797), presenting safety evaluation on matters re corrective action program associated w/equ pment qualification NRC should be ad-wised as to when util sat cipate reaching 90% completion point Walenct GRIMES.C.I. Old of Special Projects 88/12/09. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generaling Co.). 3pp. 47851283-47851:285.
- 8812190268 Forwards FEMA analysis of prompt alert & notification sys test on 860807 for plant FEMA determination that sys installed around plant satisfies requirements of NUREG-0864/FEMA-REP-1, Rev 1 & FEMA-REP-10 noted.

 DECKER,T.R. Region 2, Oic of the Director, 88/12/08 WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.), 2pp. 47852 178-47853.063.
- 8812190322 NUREG/CR-4916 HECTR ANALYSES OF THE NEVADA TEST SITE (NTS) PREMIXED COMBUSTION EXPERIMENTS WONGC C Sandla National Laboratories SAND87-0856 88/11/30. Division of Systems Research (Post 880717). 174pp. 47841:289-47842 104.
- 8812190333 NUREG-0540 V10 N09 TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE September 1-30,1988
 Division of Freedom of Information & Publications Services (Post 880515), 88/11/
- 30. 376pp 47842.105-47843:121 8812190336 Forwards Insp Repts 50:315/68:25 & 50:316/68:29 on 881031-1104.No violations noted has team conclusion that util moeting commitments to improve re-
- qualification treining program noted. WRIGHT,G.C. Rogion 3, Ote of the Director. 88/12/14. ALEXICH,M.P. Indiana. Michi-gan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 47853:231-47853.249.
- -8812190340 Insp Repts 50-315/68-25 & 50-316/88-29 on 681031-1104.No violations or deviations noted Major groups inspected licensed operator requal-hoation freining.including evaluation of commitments to improve program. HQPKINS_J.A. Region 3, Ofc of the Birector. 50-316/88-29. 88/12/14. 17pp. 47853
- 8817200012 Responds to Generic Ltr. 88-14, "Instrument Air Supply Sys Problems Af-tecling Safety-Related Equipment." Util reviewed generic Itr. & NUREG-1275,Vol. 2 & performed dosign & operations verification of Instrument arrays for plant. GOLDBERG.J.H. Houston Lighting & Power Co. Gl.-88-14. 88/12/13. Document Con-trol Branch (Document Control Dask). 8pp. 47871:348-47871.355
- 8812200052 Forwards Safety Insp. Rept 50-483/88-18 on 881031-1130.No violations noted GREGER,L.R. Region 3, Oic of the Director. 88/12/12. SCHNELL,D.F. Union Electing Co. 2pp. 47862.222-47882:244.
- -8812200055 Insp Rept 50-483/88-18 on 881031-1130.No violations or deviations noted Major areas inspected and align profession radwaste mgt programs, including or-ganization 8 mgt controls, training 8 qualifications 8 external exposure controls. GILL.C.F., KUNOWSKIM.A., GREGERL R. Region 3, Olc of the Director. GL-82-12. 88/12/12. 21pp. 47862.224-47862.244.
- 8812200119 Forwards updated listings of outstanding licensing requests for plant,for NRC review & approval including Generic Ltr 83-28 Items & NUREG-0737,Item
- HAIRSTON,W.G. Georgia Power Co. ELV-00084, 88/12/14, Document Control Branch (Document Control Desk), 6pp. 47871.048-47871:053.
- 8812200187 Monthly operating rept for Nov 1988 for Perry Nuclear Power Plant Unit 1.W/981215 ltr.
 DUNN,G.A., KAPLAN,A. Cleveland Electric Illum/nating Co. PY-CEI/NRR-0951. 88/11/30, 7pp. 47859:344-47859.350.
- 8812200386 Forwards upgraded procedures generation package,including Rev 1 to Administrative Procedure NPP-PR1-03, "Emergency Operating Procedures Development Process" & WG-APP-E, "Farml Writers Guide App E-Emergency Operating Procedures Proc
 - SYLVIA,B.R. Detroit Edison Co. NRC-88-0209, 88/12/12. Document Control Branch (Document Control Desk), 4pp. 47883:081-47884:172.
- 8812210033 Application for amends to Licenses NPF-2 & NPF-8, Incorporating provisions for reactor vessel level indicating sys,per Generic Ltr 82-28 & NUREG-0737, Item II.F.2. Fee paid.
 HAIRSTON,W.G. Alabama Power Co. GL-82-28. 89/12/14. Document Control Branch (Document Control Desk), 2pp. 47881:082-47881.099.
- -8812210038 Proposed Tech Specs/incorporating provisions for reactor vessel level indicating sysper Generic Lir 82-28 & NUREG-0737, Item II.F. 2.

 * Alabama Power Co. GL-82-28. 88/12/14. 16pp. 47681:084-47681:099.
- 8812210126 Forwards proprietary & nonproprietary BAW-1915A & PA, "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/Ft Limits W/Use of FLEC-SET." NRC acceptance fit & setoly evaluation encil.BAW-1915PA within

11/30, 130pp. 47939.002-47939.131.

- 8812210236 Forwards proprietary Rev. Lto NEDC-30259, "Technique for Evaluation of BWR MSIV Leakage Contributions to Radiological Dose Calculations." Rev responds to recommendations in NUREG-1169-Affidavt encl. Rept withheld GRACE, D.N. BWR Owners Group SWPNG-8839, 801/2/15, MIRAGUA,F.J. Associate Director for Inspection & Technical Assessment (Post 8704-11), 5pp. 47878.207-47278-21.
- 8812220080 Requests approval of encl proposed revs to augmentation times in Table 5.1 of emergency plan in response to Insp Repts 50:338/88-24 & 50:339/88-24 Justification for proposed revs also encl. CARTWRIGHT W. R. Virginia Power (Virginia Electric & Power Co.). 88:662A 88/11/30. Document Control Branch (Document Control Desk). 14pp. 47903.022-47903.035

- 8812220384 Forwards License NPF-78 authotizing operation at up to five percent full power. Technical basis included in SER, Suppls 1-6 (NUREG-0781) HOLAHAN.G.M. Division of Reactor Projects III, III, V. & Special Projects (Post 670411), 88/12/16. GOLDBERG.J.H. Florida Power & Light Co. 5pp. 47903 244-47903 281.
- 8812270307 Advises that author will respond to NRC 881018 request for addition of performance testing of reflet & salety valves prior to 890224 Response delayed in order to obtain necessary vendor Info. TUCKER, H.B. Duke Power Co. 68/12/13 Document Control Desk). 1p. 47925-304-47925-304.
- 8812280060 NUREG-0750 V28 N04 NUCLEAR REGULATORY COMMISSION IS-SUANCES FOR OCTOBER 1988. Pages 419-497.

 * Division of Freedom of Information & Publications Services (Post 860515), 88/11/30, 171pp 478(1:155-47811:244.
- 8812280076 NUREG-1330 PERSONNEL AND VEHICLE BARRIERS AT FUEL FABRI-CATION FACILITIES USING OR POSSESSING STRATEGIC QUANTITIES OF SPE-CIAL NUCLEAR MATERIAL. RENTSCHIER.R.P. Division of Safeguards & Transportation (Post 870413). 88/12/ 31, 28pp. 47911:245-47911:272
- 8812280087 NUREG-1329 ENTRY/EXIT CONTROL AT FUEL FABRICATION FACILITIES USING OR POSSESSING FORMULA QUANTITIES OF STRATEGIC SPECIAL NUCLEAR MATERIAL.

 DWYER,PA. Division of Safeguards & Transportation (Post 670413). 88/12/31. 17pp. 47911:295-47911:311.
- 8812280105 NUREG-1328 USE OF PERIMETER ALARMS AT FUEL FABRICATION FACILITIES USING OR POSSESSING FORMULA QUANTITIES OF STRATEGIC SPECIAL NUCLEAR MATERIAL. DWYER,P.A., GASKIN.C.E. Division of Sefeguards & Transportation (Past 870413). 68/12/31, 22pp. 47911:273-47911:294.
- 8812280114 NUREG/CP-0095 PROCEEDINGS OF THE FOURTH WORKSHOP ON CONTAINMENT INTEGRITY.
- COCHRELL.R. Sandia National Laboratories. FIN A 1249. SAND88-1836. 88/11/30. Division of Engineering (Post 870413), 684pp. 47912:001-47913-279.

ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

- 8811160211 NRC Into Notice 88-090, "Ungulharized Removal of Industrial Nuclear Gauges." Svc list enci CUNNINGHAM, R. Division of Industrial 8 Medical Nuclear Safety (Post 870728), 88/11/22. Consolidated Ed.son Co. of New York, Inc. 99pp. 47708-255-47708-257.
- 8811160467 NRC Info Notice 88-091, "improper Administration & Control of Psychological Tests," Syc List encl. ROSSI, CE. Division of Operational Events Assessment (Post 870411) 88/11/22. Consolidated Edison Co. of New York, Inc. 501pp. 47708.042-47708:142.
- 8811230053 Request for OM8 review & supporting statement re 10CFR50, "Domestic Licensing of Production & Utilization Facilities." Estimated respondent burden 0 h. MACDONALD,W.G. Office of Administration & Resources Management, Director (Post 870413). OMB 3150-0011. 88/11/17. 6pp. 47652-092-47652-098.
- 8811230326 Request for OMB review & supporting statement re-pilot program on OA concerning medical use of byproduct meth. Estimated respondent burden is 3,500 h. MCDONALD,W.G. Office of Administration & Resources Management, Director (Post 37043), 69/11/06, 1 (pp. 47652;136-47652;146.
- 8811280044 Forwards final rept for 871014 exercise of offsite radiological emergency response plans for plant Nineteen desciencies observed in exercise. EMA reserves right to Invoke 44CFR350.13 pending results of 881116 exercise. KRIMM,R.W. Federal Emergency Management Agency 88/11/16. CONGEL,F.J. Division of Radiation Protection & Emergency Preparedness (Post 870411). 2pp. 47652:305-47653:267.
- --8811280051 Forwards memo re status of corrective actions for 871014 exercise of off-site plans & preparedness for plant. KRIMM R.W. Federal Emergency Menagement Agency, 88/04/19. Division of Rad-etten Protection & Emergency Preparedness (Post 670411). 4pp. 47652:307-
- -8811280059 Final rept of 871014 exercise of offsite radiological emergency response plans for plant.
 • Federal Emergency Management Agency, 88/06/30, 313pp. 47652:311-47653:267.
- 8811280128 Forwards transcript of Workshop on Rules for Exemption From Regulatory Control in Washington,DC on 881017-19.

 LAHS,W. Regulation Development Branch. 88/11/28. NRC No Detailed Athitiation Given, 1p. 47844:345-47848.022.
- ~8811280130 Transcript of 881017 proceedings of 881017-19 workshop on rules for exemption from regulatory control in Washington, D.C.Pp 1-211.

 **Commissioners. 89/10/17, 359pp. 4764/346-4746/344.

- -8811280132 Transcript of 881018 proceedings of 881017-19 workshop ca rufes for ca emption from regulatory control in Washington,D.C Pp 212-412 ' Commissioners. 88710718. 350pp. 47645,345-47646,338
- -8811280134 Transcript of 881010 proceedings of 881017-19 workshop on attes for ex-emption from regulatory control in Washington,D C Pp 414-480 * Commissioners, 88/10/19 | 350pp | 47646 339-47648 022
- 8811290030 NRC Info Notice 88-093, "Tolothorapy Events." Svc list end. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Salety (25st. 970729) 88/12/02 Consolidated Edison Co. of New York, Inc. 112pp. 47811 (6) 47811 (1)
- 8811290183 Forwards final rept of 880504 full participation exercise of offsite radio tog cal emergency response plans No delicioncies observed & eight areas requiring corrective action identified KRIMMA W. Federal Emorgency Management Agency 88/11/02 CONGSt F J Oss sion of Redigtion Protection & Emergency Proparedness (Post 670411) 1p 47664 071 47664:158
- ~8811290191 "Final Rept of 880504 Perry Nuclear Power Plant Joint Exerctso"
 Federal Emergency Management Agency 88/10/20, 88pp 47664072476€4 158
- 8811290538 NRC Info Notice 88-094, "Potentially Undersized Valvo Aduators ** Syc 4s ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/12/02 Consolidated Edison Colof New York, Inc. 121pp. 47708.143-47708.254
- 8811300106 Advises of three issues of current registary significance, including no-role announcing presence of NRC inspector at nuclear power plantics to NRC in-forcement policy & proposed enforcement actions to operator nationswings at plant STELLOV. Offic of the Executive Director for Operations, 88/11/17. En exclaims fixed tric Co. 35pp. 47709:020-47709.068.
- 8811300110 Trip rept of 881010-14 visit to Japan re-sefety review 8 licersing of advanced BWR Supporting methenol. SCALETTI, DC. Standardization & Non-Power Reactor Project Directorate 68/11/14 RUBENSTEIN, L.S. Assistant Director for Region IV Reactors & Special Projects 112pp, 47673:340-47674.091.

- 8811300162 Forwards revised memorandum of agreement (MOA) w/NPO, effective 81130162 Forwards forward and the properties of a light state of the s 47697:306.
- --8811300207 Memorandum of Agreement between INPO & NRC releastance of experioncounts & data released of nuclear power plants STELLOV. Ofcort the Executive Director for Operations PATE,Z.T. Instituted house Power Operations 88/10/20, 15pp. 47697 292-47697.308
- 6811300 193 Summary of Operating Reactor Events Meeting 88-36 on 851122 LANNING,W.D. Events Assessment Branch, QREM-88-046, 88/11/25, ROSSI,C.€. O vision of Operational Events Assessment (Post 870411), 11pp. 47680-20147680-21.
- 8811300276 Request for OMB review & supporting statement re 10051372, "Licensia Requirements for Independent Storage of Sport Nuclear Fuel & High Lovel Raswaste" Estimated respondent burden is 13,092 h MCOONALD,W.G. Office of Administration & Resources Management, Director (Por870413), OMB 3150-0011, 88/11/18, 21pp. 47697;267-47697;288.
- 8811300331 Summary of Operating Roactors Events Meeting 88-45 on 851115 List of attendees & handouts end.
 LANNING W.O. Events Assossmont Branch. OREM-88-045. 88/11/25. FOSSIC E Civision of Operational Events Assessment (Post 870411). 16pp. 47674.141-47674. 154
- 811300670 Forwards congressional rept on "Threat From Substandar Fasteners:America Losing Grip." for into Response enct. GRIMES,B.K. Division of Reactor Inspection & Safeguards (Post 870411) 88/11/2 MCDONALD.D.J. National Board of Boilor & Pressure Vessel Inspectors 36pt 47671:017-47673:057.
- 8812020231 Forwards plant restart approval guidelines/including general colorial of issues to be considered during ovaluation.

 STELLOV. Oil: of the Executive Director for Operations, 88/11/23, NRC No. (Natleb Affiliation Given, 6pp. 47707;220-47707;225.)
- 8812020287 NRC Into Notice 88-095, "Inadequate Procurement Requirements (mphose by Licensees on Vendors," Syc list end. HOSSI,C.E. Division of Operational Events Assessment (Post 870411) IEII&88-03-88112(08, Consolidated Edison Co. of New York, Inc. 112pp. 47807;191-47607-30
- 8812050025 Forwards Congressional rept, "Threat From Substandard Fasiences America Losing Its Grip." GRIMES,B.K. Division of Reactor Inspection & Satoguards (Post 870411) 89/11/2 GREEN,M.R. American Society of Mechanical Engineers, 36pp. 47734:027 47734, 06
- 8812050054 AEOD/E708 Engineering evaluation ropt, "Depressurization of Relact Coolant Sys in PWRs." ISRAEL,S. Office for Analysis & Evaluation of Operational Data, Director, 87/08/3 17pp, 47733;281-47733;277.
- 8812070046 Forwards Standardization & Non-Power Reactor Project Directorate may ear assessment of region implementation of NRR programs during Jul 1936 Jul 1939. MILLER.C.L. Standardization & Non-Power Reactor Project Directorate 69/11/2 HOLAHANG.M. Division of Reactor Projects - III,IV,V & Special Projects (Pd 870411), 3pp. 47747:081-47747:083.
- 8812070119 Summary of Operating Reactors Events Meeting 88-47 on 681129 List attendoes events discussed & eignificant elements of events, two events suggested long-term followup & summary of reactor scrams encl. LANNING,W.D. Events Assessment Branch. OREM-88-047. 88/12/01. ROSSI.C E. vision of Operational Events Assessment (Post 870411). 14pp. 47747.093-47747.10

-8312070202 "NRC Staff Evaluation in Support of 10CFR50.54(f) Generic Ltr Requiring Indudual Plant Exam at Nuclear Power Plants."
NRC - No Detailed Affiliation Given, 88/12/01, 16pp. 47746 276-47748:291.

8812070213 Trip rept of 881017-21 visit to Vienna, Austria for IAEA Technical Commit-Report of the Programs of the

e812090075 Forwards comments re Draft 5 of "Design for Safety Research Reactors"

Word misspellings & phrase changes listed.

ADAMS A Standardization & Non-Power Reactor Project Directorate 88/11/05.
BYSZEWSKI,W International Atomic Energy Agency. 3pp. 47775.080-47775.082.

8812090106 Forwards Commission blacebly notice of applications & amends to OLs in-volving NSHCs published in FR on 881018 for into W/o enci. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/11/ 17. BREAUX,J.B. Senate, Environment & Public Works. UDALL,M.K. House of Rep., intend. & Insular Allairs. SHARP,P.R. House of Rep., Energy & Commerce. 2pp. 47762 202 47782 203.

6812160059 Notification of 881109 meeting w/NUMARC & EPRI in Washington,DC to discuss candidate human factors projects. COFFMANF.D. Human Factors Branch 88/10/28. SHERON,B.W. Human Factors Branch. 2pp 4/832258-4/832255.

8812190114 Notification of 890110 meeting w/INPO in Rockville,MD re human perform-

ance evaluation sys.
SHANKMAN,S.F. Human Factors Assessment Branch. 88/12/12 REGAN,W.H.
H. man Factors Assessment Branch. 2pp. 47840.178.47840.179.

8812200304 Comments on SER input on hydrogen control for advanced LWR requirements document,per 881101 request.

8ECKNERW, Severe Accident Issues Branch, 88/12/14, HOUSTON,R.W. Division of Safety Issue Resolution (Post 880717), 3pp. 47863.072-47863:074.

8812210168 Forwards FEMA & Regional Assistance Committee final exercise rept of clisic emergency preparedness plans for facilities Deficiencies noted nonparticipation of Lower Paulon Township & distribution of desimality kits.

KRIYM R.W. Federal Emergency Management Agency. 88/12/12. CONGEL,F.J. Division of Redigition Protection & Emergency Preparedness (Post 870411). 1p 47888.120-47888:212.

-8812210173 "FEMA & Regional Assistance Committee Exercise Rept of 871022 Exerc se. * Fedoral Emergoncy Management Agency, 88/11/04, 92pp. 47888:121-47888.212.

8912210194 Discussos issue of RHR air ingostion & vortox formation during mid-loop operations per USI A-43, "Containment Emergency Sump Performanco" Extrapolations of USI A-43 results indicate vold (rections could be as high as 6%. SPANOA H. Reactor & Plant Safety Issues Branch. 87/06/08. KNIEL,K. Reactor & Plant Safety Issues Branch. 87/06/09. KNIEL,K. Reactor & Plant Safety Issues Branch. 8pp. 47874:210-47874:218.

8812220059 Summary of Operating Reactors Events Meeting 88-48 on 881206.Agenda & Lst of attendees enct.

LANNING.W.D. Events Assessment Branch. OREM-88-048, 88/12/07, RQSSI.C E. Divison of Operational Events Assessment (Post 870411). 16pp. 47922:881-47822:015.

8812220278 Corrected notification of 890110 meeting w/INPO in Rockville,MD for INPO briding re human portormance evaluation sys.
SHANKMAN,SF. Human Factors Assessment Branch 88/12/16. REGAN,W.H.
Human Factors Assessment Branch. 2pp. 47903.020-47903.021.

8912270887 Motion in Limine of Commonwealth of MA atty general re FEMA post-exer-cise avaluation & assessment rept. Board should grant motion & direct FEMA to pro-yde details of destruction documents. W/supporting documentation & Certificate of

TRAFICONTE, J.M. Massachusetts, Commonwealth of. #488 7703, Ot., 88/12/13. Atomic Safety and Licensing Board Panel. 22pp. 47872:327-47872:348.

6812280002 Lit.CO response to intervenors motion for reconsideration of CLI-88-9.* Motion should be deried on basis of no good reason offered & motion on wrong premise that intervenors should be permitted to use 2-yr oxorcise regulation. IRWIN.D.P. Long Island Lighting Co. IRWIN.D.P. Hunton & Williams. #488 7717. OL-5. 88/12/19. Commissioners. 26pp. 47885.001-47885.077.

--8612280012 Requests fectual & logistical into necessary to enable govis to participate in plant 880607-09 exercise Supporting documentation enci. MILLER,M.S. Suffolk County, NY, MILLER,M.S. New York, State of. MILLER,M.S. Southempton, NY, OL.5. 88/05/31. BACHMANN,R.J. Agsistant General Counsel for Hoarings. IRWIN,D.P. Hunton & Williams. CUMMING,W.R. Federal Emergency Management Agency. 24pp. 47885,046-47885:069.

8612280115 Preliminary answer of Commonwealth of MA atty general to applicant motion for schedule. Applicant motion should be derived on basis that LLCO plan a ready fully hillgated. Supporting documentation & Certificate of Sve encl. IRAF/CONTE, J. Massachusettis, Commonwealth of. #488 7728. CLI-88-09, 88/12/19. Atomic Safety and Licensing Board Panel. 59pp. 47885.078-47885:135.

PR PROPOSED RULE

8811100222 Forwards addit comments to comments summarized by Rules & Procedures Branch cover memo, consisting of editorial or format corrections necessary to make package suitable for FR notice publication, per Regulatory History AC56-1, HAISFIELD,M. NRC - No Detailed Attillation Given. AC56-1 13, 88/11/03. NRC - No Detailed Attillation Given. AC56-1 13, 88/11/03. NRC - No Detailed Attillation Given. -8811100281 Requests publication of advance notice in FR re-proposed rulemaking for amends to 10CFR40 on custody & long-term care of U milli tailings sites Notice environ assessment & add documents supporting Commission action

BECKJORD,E.S. Office of Nuclear Regulatory Research, Director (Post 860720), AC55-1-14, 88/08/08 PHILIPS,J.D. Regulatory Publications Branch, 1p. 47520.028-47520 029

-8811100283 Advises that Commission has agreed to proceed w/attached advance notice of proposed rufemaking re proposed amends to 100FR40 for general ficenses for custody & long-term care of U m.il fail ngs sites,per SECY-88-83.

CHILK,S.J. Office of the Secretary of the Commission. AC56-1 15. 88/07/26, STELLO,V. Ofc of the Executive Director for Operations 26pp. 47520:030-47520:055.

--8811100291 Notities that Commission has sent ench proposed amend to Commission rules in 10CFR40 Amend would provide procedure to License custody & long-term care of decommissioned U or thorium mill tailings sites
BECKJORD,E.S. Office of Nuclear Regulatory Research, Director (Post 860720).
ACSS-1 17. 88/02/09. BREAUX_JS. Sanate, Environment & Public Works.
SHARP,PR. House of Rep., Energy & Commerce. UDALL,M.K. House of Rep., Interior & Insular Alfairs 8pp. 47620:102-47520:109.

-8811100293 Forwards advanced notice of proposed rulemaking re licensing for mactive U mill tailings site subsequent to completion of remedial action by DOE. BRIGGS,W.H. Office of the General Counset. AC56-1 18. 88/08/31. MANSMANN,J.J. Mansmann, Cindrich & Titlus. 294 7520 110-47520 111.

-8811100295 Approves continuation of rutemaking re-criteria for licensing long-term custody & maint of U mill tailings sites,per 840213 memo.NRC regulatory agends.NUREG-0938, should be modified to reflect rutemaking slatus.

STELLO,V. Ofc of the Executive Director for Operations. ACS6-1 19. 88711/03.

DAVIS,J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 47520:112-47520.

8811220341 Comment endorsing NUMARC comments on proposed rule 10CFR26 re fit-

ness for duty rulo.

KEISER,H.W Pennsylvan'a Power & Light Co. 53FR36795 00374, 88/11/17.

CHILK,S.J. Office of the Secretary of the Commission, 3pp. 47721:050-47721:052.

8811290018 Informs that 881108 request for extension of public comment period on proposed fitness for duty rule dealed Ample response time provided. GRIMES.B.K. Division of Reactor Inspection & Sateguards (Post 870411), 53FR38795, 88/11/16, CINTRON,J.A. Southorn California Edison Co. 1p. 47668:088-47668.089

8611300360 Commonts on technical position on alternative concentration limits for U mills Expresses concern that approach appears to be most applicable to Title II elles. SHINGOITEWA,L. Hopi Tribe, 53FR24820 00007, 88/11/08. Office of Administration & Resources Management, Director (Post 870413). 8pp. 47833:145-47833:149

8811300611 Responds to 881116 request for Commission to extend public comment period on proposed finess for duty rulo.

GRIMES,B.K. Division of Reactor Inspection & Safeguards (Post 670411). 88/11/28.

HICKS,M.M. Utity Workers Union of America. 1p. 47677.026-47677:028.

8811300529 Responds to 881112 request for Commission to extend public commont period on proposed finess for-duty rule Comments should be submitted by 881121. GRIMES B.K. Dwiston of Reactor Inspection & Safeguards (Post 670411), 53F338795. 88/11/28. RICHWINE.J.R. Affiliation Not Assigned. 1p. 47696 255.

8811300539 Rosponds to 881112 request for Commission to extend public comment period on proposed Fitness for Duty rule Comments received after 881121 will be considered if practical.

GRIMES,B.K. Division of Reactor Inspection & Safeguards (Post 870411), 53FR36795 88/11/28, JOKUMATO,J. Southern California Edison Co. 1p. 47680:172-4768

47660:174

8811300556 Denies 981112 request for Commission to extend public comment period on proposed Friness for Duty Program.
GRIMES,8.K. Division of Reactor Inspection & Safeguerds (Post 870411), 88/11/28.
BARBRE.G L. Southern California Ed son Co. 2pp. 47678:155-47876.167.

8811300679 Denies 881112 request for Commission to extend public comment period on proposed filness for duly rule GRIMES,BK, Division of Reactor Inspection & Safeguards (Post 870411), 88/11/28, LUQUE,H.E, Athitation Not Assigned, 1p. 47677.029-47677.031.

8811300583 Denies 881112 request for Commission to extend public comments period on proposed fitness for duty rule.

GRIMES,B.K. Division of Reactor Inspection & Safeguarde (Post 870411), 53R38795. 88/11/28. WATSON,R.C. Southern California Edison Co. 1p. 47709.089-47709 071.

8812010025 Comment apposing proposed rule 10CFR26 re Fitness for Duty Program which includes random drug testing. Significant burden would be Imposed on non-power facilities in establishing & maintaining separate program. VERNETSON,W.G. Florids, Univ. of, Gainesville, FL. 53FR36795 00292. 88/11/17. Docketing & Services Branch. 2pp. 47678:232-47678:233.

8812010027 Comment opposing proposed rule 10CFR26 re Fitness for Duty Program which includes random drug testing. BOLTON.E.P. Affil alion Not Assigned. 53FR36795 00291. 88/11/18. Document Control Branch (Occument Control Branch (Occument Control Desk). 3pp. 47678:234-47678:236.

8812010029 Comment opposing proposed rule 10CFR26 re Fitness for Duty Program which includes random drug testing.
CATANOJL Affiliation Not Assigned. 63FR36795 00288. 88/11/18. Docketing & Services Branch. 2pp. 47678:237-47878:238.

8812010033 Comment opposing proposed rule 10CFR26 re Fitness for Duty Program.Permission requested to continue util fitness for duty programs already in FOGARTY E.P. Philade phila Electric Co. 53FR36795 00269. 68/11/17. CHILK,S.J. Office of the Secretary of the Commission. 14pp. 47678:239-47678:252. 8812010035 Comment opposing proposed rula 10CFR28 re Filness for Duty Program which includes random drug testing. PUCK J. Aff ligiton Not Assigned. 53FR36785 00286. 83/11/13. Docketing & Services Branch. 1p. 47678:296-47678:296.

- 8812010036 Comment supporting proposed rule 10CFR28 re Fitness for Duty Program which includes random drug testing. Consistency must exist among licensees as to fitness for duty rules & reg./fat.ors.NUMARC comments and. SIEBER, JD. Duquesne Light Co. 53FR36795 00272. 88/11/18. CHILK,S.J. Office of the Socretary of the Commission. 43pp. 47678 253-47678 285.
- 8812010041 Donies 881112 request for Commission to extend public comment period on proposed fitness-for duty ru'e.Commission has provided ample opportunity for public awareness of 8 participation in rulemaking process. GRIMES,B.K. Division of Reactor Inspection & Saleguards (Post 870411) 88/11/28, DOM-NGUEZ,D. Afficiation Not Assigned, 1p. 47698:285-47698 287.
- 6812010045 Denies 881112 request for Commission to extend public comment period on proposed filness-for-duty rule. Commission has provided ample apportunity for public awareness of 8 participation in rulemaking process GRIMES,BIK, Division of Reactor Inspection & Safeguards (Post 970411) 88/11/28. MITCHELL,S.C. Alfiliation Not Assigned 1p. 47703-016-47703-018
- 8812010050 Denies 881112 request for Commission to extend public comment period on proposed Fitness For Duty Program
 GRIME_B.K. Office of Nuclear Reactor Regulation, Director (Post 870411)
 63FR36705 88/11/28. TOFELL S. Southern California Edison Co. 1p. 47709.072-
- -8812060289 Requests addl 90-day extension of penod to submit public comment on proposed rule 10CFR26 re Frinces For Duty Program TOFELL.C. Afficiation Not Assigned, 53FR36785 88/11/12, Docketing & Services Branch 1p. 47709-074-47709-074.
- 8812010055 Comment supporting proposed rule 10CFR26 ra fitness-for-duty program MROCZKA,E.J. Northeast Utilities MROCZKA,E.J. Northeast Niclear Energy Co. (subs. of Northeast Utilities) MROCZKA,E.J. Connecticut Yankee Atomic Power Co. 53FR36795 00318 89/11/21. CHILK,S.J. Office of the Secretary of the Contribusion 9pp. 47679 046-47679:054.
- 8812010057 Danies 861112 request for Commission to extend public comment period on proposed Fitness For Duty program GRIMES, B.K. Division of Reactor Inspection & Safeguards (Post 870411), 53FR36795 68/11/28, ROBINSON,J. Afficiation Not Assigned 1p. 47703:327-
- 8812010067 Comments on rule 10CFR26 relituess for duty program rule. Recommends that NRC include rule stating that NRC regulations preempt state &/or local laws & regulations to ensure no conflict over juristiction develops. WEIGAND.G.J. Vermont Yankee Nuclear Power Corp. 53FR36785-00324, 88/11/18. CHILK,S.J. Office of the Secretary of the Commission. 2pp. 47678:131-47678:132.
- 8812010070 Comment opposing proposed rule IOCFR26 to proposed futness for duty rule. Believes that rule violates rights of workers rule applies to & fails to accomplish goal of protecting health & satisty of general public.
 WILL_D.J. Affiliation Not Assigned. 53FR36795 00323. 88/11/19. Docketing & Services Branch. 3pp. 47678:133-47678:135.
- 8812010071 Comment supporting proposed rule 10CFR26 re proposal to require (censes to implement fitness-for-duty program applicable to nuclear power reactor sites. RADER,I.M. Conner & Wetterbahn. 53FR36758 00309, 88/11/21, CHILK,S.J. Office of the Secretary of the Commission. 50pp. 47678 297-47678:348.
- 8812010076 Comment opposing proposed rule 10CFR26 re random drug test for employees allowed unascorted access at generating stations WARREN.M. Afficiation Not Assigned. 53FR36795, 00243, 88/11/13, Docketing & Services Branch. 1p. 47679:304-47679:304.
- 8812010077 Comment opposing proposed rule 10CFR26 to Fitness for Duty Program TURNER, J.A. Utifity Workers Union of America 53FR36795 00229, 88/11/16, Docketing & Services Branch, 4pp. 47879,305,47679,309,
- 8812010089 Comment opposing proposed rule 10CFR26 re random testing provision to be included in Fitness for Duty Program. Supports testing program based on behavior-al observation & testing for cause. WALTERS.X. International Brotherhood of Electrical Workers. 53FR36795 00137, 88/ 11/14. Docketing & Services Branch. 1p. 47679.310-47679.310.
- 8812010093 Comment supporting proposed rule 10CFR26 to liness-for-duty program. Urgos Commission to include in final rule statement preempting state laws which preclude employers from requiring drug tests & retural to discipline employees. NORRIS, J.A. Affination Not Assigned 53FR36785 00307. 88/11/21. CHILK,S. J. Office of the Secretary of the Commission 8pp. 47879.055-47879.082.
- 8812010096 Commant opposing proposed rule 10CFR26 re random testing provisions to be included in Fitness for Duty Program. Supports testing program based on behavioral observation & testing for cause.

 HARBISON,R H. International Brotherhood of Electrical Workers. 53FR36795 00212.

 80/11/14. Docketing & Services Branch. 1p. 47679;311-47679:311.
- 8812010101 Denies 881112 request for Commission to extend public comment period on proposed Fitness For Duty program.
 GRIMES.B.K. Division of Reactor Inspecton & Safeguards (Post 870411).
 63FR36795. 88/11/28. REEVES.W.H. Affiliation Not Assigned. 1p. 47698 291-
- 8812010104 Denies 861112 request for Commission to extend public comment period on proposed Friness For Outy program. GRIMES.B.K. Dwission of Reactor Inspection & Safeguards (Post 870411), 63FR36785. 88/11/28. GRAHAM,S Mr. Affiliation Not Assigned. 1p. 47700.035-
- 8812010107 Denies 881112 request for Commission to extend public comment period on proposed Fitness For Outy program GRIMES.B.K. Division of Reactor Inspection & Safeguards (Post 870411), 53FR38785. 89/11/28. DAVISON.D. Affiliation Not Assigned. 1p. 47698.268. 47696:290.

- 8812010108 Comment opposing proposed rule 10CFR26 to proposed Firess for DV Program Believes that subjitude unconstitutional & should be withdrawn 8 redia?te3 to Irmit rule application only to legitimate concerns of Commission. ELLISON,J.J. Gregory, Moore, Jeakle & Heinen. 53FR36795 00325 68/11/21. Doc4 ating & Services Branch. 6pp. 47678 107-47676:112
- 8612010113 Comment on proposed rule 10CFH26 re-extension of filess ici duty reg. lations to non-power reactors

 CARTER,R.S. National Institute of Standards & Technology (formerly National Buries of Standar 55/R36795 00321 88/11/18. Office of the Secretary of the Commission
- 8812010114 Requests extension of 90 addl days in submitting comment on FR notice in thress-for-duty issue for nucloar power plant workers. ALBERS.K.L. Southern Celtorate Edson Co. 53FR36795. 88/11/12 Docketing & Services Branch. 1p. 47678:130-47678.130

1p. 47678 136-47678.136

- 8812010115 Comment opposing proposed rule 10CFR26 re random drug testing the Ferness for Duty for everyone allowed unescorted access at plants
 BOHMS.G.L. Alfaliation Not Assigned, 53FR36795, 00242, 88/11/13, Docketing &
 Services Branch, 1p. 47679.312-47679.312
- 8812010120 Requests extension of 90 addl days to submit comment on FR notice in fitness for duty issue for nuclear power plant workers DOYLE,W. Affiliation Not Assigned, 535R36795 88/11/12, NRC No Cotated Afficiation Given 1p. 47678:231-47678.231.
- 8812010126 Comment opposing proposed rule 10CFR326 to drug tosting to ensure fill ness-for-duty at nuclear power plants. ENDERMANN,G. M. Athitation Not Assigned. 53FR36795 00322 88/11/17. NRC N. Detailed Afficiation Given 1p. 47678/219-47678;219.
- 8812010130 Comment supporting proposed rule 10CFR26 to NRC 1:ness for an program Recommendations listed. FIRLIT_IJF. Sacramonto Municipal Utility District. 53FR36795 00320 68711718 KNIGHTON.G. Document Control Branch (Document Control Desk) 40pp 47678 164
- 8812010132 Comment on proposed rule 10CFR26 re fitness for duy. Endorse NUMARC comments Recommendations for specific changes to rule; responses in questions in discussion & app of rule & comments to backin analysts are CONWAY.W.F. Florida Power & Light Co. 53FR38795 00330. 88/11/21. CHILK,S. Office of the Secretary of the Commission. 30pp. 47679 313:47679.342.
- 8812010142 Requests addl 90-day extension of deadling for himg comments on pro-pased rule 10CFR26 to Fitness for Duty Program. MITCHELL, SC. Affiliation Not Assigned, 53FR36795, 88/11/12, Dockeling & Service Branch, 1p 47678,343,47679,343
- 8812010152 Comment on proposed rule 10CFR26 re random drug testing to ensure fit ness-for-duty & safety & security of workplace in nuclear power industry. BENISINGER, P.B. Bensinger, DuPont & Associatos, Inc. 53FR36795 00319, 68/11/21BUSH,L. Reactor Safeguards Branch. 4pp. 47678:215-47678:219
- 8812010155 Comment supporting proposed rule 10CFR26 to NRC rulemaking on 19 ness for duty programs Endorses NUMARC 881118 comments on sub) proposed rules suggests Incorporation of NUMARC suggested changes. CAMPBELL, T.G. Arkanses Power & Light Co. 53FR36795 00327 88/11/12 CHILK, S.J. Office of the Secretary of the Commission. 8pp. 47676:223-47676:230.
- 8812010156 Comment opposing proposed rule 10CFR26 re random drug testing in Fr ness for Duty Program
 BRIODY,E.T. Utility Workers Union of America, 53FR36795 00332 88/11/21. Cocketing & Services Branch, 6pp. 47679:344-47679:348.
- 8812010159 Comment supporting proposed rula 10CFR26 to NRC fitness for dut program Bolloves that subj rule white adequate in many regards, contains deficience undermining overall intent of rule Recommendations listed. MARKEY, E.J. House of Rep. 53FR36795 00328. 88/11/21. Dockaling & Service Branch, 3pp. 47678:220-47678:222.
- 8812010180 Forwards comment on proposed rule 10CFR140 re indemnification of 8 canseos that mtg.produce.possoss or use radiotsotopes for modical purposes Certificate of Sve and ROSS,R.J. Ross & Smith. ROSS,R.J. Mallinckrodt, Inc. ROSS,R.J. E.I. du Port de Namours & Co., Inc. 53FR40233 00006, 88/11/07, CHIL.K.S.J. Office of the Secretary of the Commission. Apr. 378(0.02) 47500.018 the Commission. 4pp. 47680:003-47680:018.
- -8812020202 Commont on proposed ru/o 10CFR140 re indemnification of licensee that mfg.produce.possess or use radiopharm or radiolsolopes for medical purpose ROSS,R.J. Ross & Smith. ROSS,R.J. Mall nckrodt, Inc. ROSS,R.J. E.I. du Port de Nimours & Co., Inc. SDFR40233 00006. 88/11/07, Docketing & Services Branch. 12pq 47680.007-47680.018.
- 88 12010161 Comment opposing proposed rule 10CFR26 re random drug testing for f. ness-for-duty at nuclear power reactors.

 * Affiliation Not Assigned, 53FR36795 00315, 68/11/22, Docketing & Service Branch, 11pp. 47878;204-47678;214.
- 8812010163 Comment supporting proposed rule 10CFR140 re negotiated rulemaking for Indemnification of medical licensees under Price Anderson Act.Supports extension at Act to include medical licensees. BORCHERT.H.R. Nebraska, State of: 53FR40233 00007, 88/11/17. Docketing Services Branch. 1p. 47679:063-47679:063.
- 8812010185 Commant re proposed rule 10CFR26 concerning fitness for dur program Random drug testing provisions opposed. KOLL.RF. International Brotherhood of Electrical Workers, 53FR36795 00241, 68711 14. Docketing & Services Branch, 1p. 47679.064-47679:064.
- 8812010167 Comment on proposed rule 10CFR26, "Fitness For Duty Program." Coccurs w/comments submitted by NUMARC on behalf of nuclear utility industry. SULLIVANJ.L. General Public Utilities Corp. GPU Service Corp. 53FR36795 CO32-88/11/21. Docketing & Services Branch. 27pp. 47878:137-47678:163.

8812010177 Commont supporting proposed rule 10CFR28 re Fitness for Duty Program Inclusion of basic requirements for alcohol testing supported MEDFORD.M.O. Southern Catifernia Ed.son Co. 53FR38795 00317. 88/11/21 CHLK,5 J. Office of the Secretary of the Commission. 20pp 47678 347-47679.006

- 8812010181 Comment opposing proposed rule 10CFR26 re-random drug testing Petition MCGGWAN,N.C. International Brotherhood of Electrical Workers. 53FR36795 00333. 88/11/23. Docketing & Sorvices Branch. 38pp. 47679:007-47679:045.
- 8812010185 "Price-Anderson Negotiated Rulemaking Position Statement of NRC

Stall. TREBY,S.A. NRC - No Detailed Affiliation Given 88/11/07, 41pp. 47878.076-

- 6812010191 Comment opposing proposed rule 10CFR26 re times for duty program Ru's falls to get at root causes of drug abuse impairment. GORMANE J. United Brotherhood of Carpentors & Joiners of America 53FR36785 00314 88/11/21. CHICK, S.J. Office of the Sacrefary of the Commission. 33pp 47678 074-47878 108
- 8812010200 Comment on proposed rule 10CFH26 re Fitness for Duty Program.Random drug tosting would cause unnecessary inconvenience to employee & unnecessary duplication of efforts by Icensees.

 REYNOLDS N.S. 68top., Cook, Purcell & Raynolds. 63FR36705 00311. 88/11/21.

 CHILK,S.J. Office of the Secretary of the Commission. 16pp. 47675:328-47675:343
- 8612010204 Comment on proposed rule 10CFR26 re filness for duty program. Body fluid tosting for substance abuse opposed.
 STANLEY,W.S. Alfilation Not Assigned. 53FH36795 00336. 88/11/21. Dockoting & Services Branch. 3pp. 47678.118-47678.120.

- 8812010206 Comment opposing proposed rule 10CFR26 re Fitness for Duty ProgramBelleves that NRC should adopt NUMARC proposed approach re random drug tosting TUCKER,H.B. Duke Power Co. 53FR36795 00313, 88/11/21, CHILK,S.J. Office of the
 - Secretary of the Commission, 8pp, 47675;344-47675;351.
- 8812010207 Comment on proposed rule 10CFR26 re Fitness for Duty Program Random drug testing opposed.
 STANLEY,M.A. Affiliation Not Assigned. 53FR38785 00334, 88/11/20. Office of the Secretary of the Commission. 3pp. 47679:121-47679.123.
- 8812010217 Comment opposing proposed rule 10CFR28 re litness for duty program NRC has already prepared required backfitting analysis & no basis to determine that proposed regulation within adequate protection exception.

 REYNOLDS,N.S. Nuclear Utility Backfitting & Reform Group, 55FR36795 00312, 88/ 11/21, CHILK,S.J. Office of the Secretary of the Commission 5pp. 47675:357-47855-31 47875 361
- 8812010222 Comment on proposed rule 10CFR26 to Filinoss for Duty Program.Util endorses comments submitted by NUMARC & encourages Commission to revise proposed rule.
 BURSKI,R.F. Louislana Power & Light Co. 53FR36795 00318. 88/11/18. CHILK,S.J.
 Office of the Secretary of the Commission 2pp. 47675.355-47675.356.

- 8812010227 Comment on proposed rule 10CFR26 re fitness for duty program Alcohol-shou'd be included in testing procedure & employee assistance program should not be expected to ofter assurance of continuing employee fitness for duty. RICKENBACKERB, Ceroline Power & Light Co. 53FR36795 00337. 88/11/21. Dock-eting & Services Branch, 2pp. 47679:124-47679:125.
- 8812010233 Comment opposing proposed rule 10CFR26 re titless for duty program Strongly objects to unreasonable program that invades privacy of workers who never engage in any activities that would impair ability to perform. HICKS,M.M. Utility Workers Union of Amortics, 53FR36795 00308, 88/11/21, Docketing & Services Branch, 27pp. 47678:047-47678:073.
- 8812010239 Comment on proposed rule 10CFR26 re fitness for duty program. Rule would inappropriately place responsibility for contractors used by NRC on licensee All NRC contractors should be covered by NRC random drug testing program. WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.) 53FR36795 00335. 88/11/17. CHILK,S.J. Office of the Secretary of the Commission. 3pp. 47679:126-47678.126.
- 8812010255 Comment on proposed rule 10CFR26 re fitness for duly program. Concerns re accuracy of drug tests, slow procedure of appeals tollowing false positive test & tack of constraint on number of times Leensee may test individual expressed. DOMINGUEZ, D. Affiliation Not Assignod. 53FR38795 00338. 88/11/14. Docketing & Services Branch. 2pp. 47679:129-47679:130.
- 88 120 10266 Comment on proposed rule 10CFR26 re fitness for duty program. Util in agreement w/majority of comments submitted by NUMARIC & Nuclear Util Backfitting & Reform Group.
 KAPLAN,A. Cloveland Electric lifuminating Co. 53FR36795 00339, 88/11/18. Docketing & Services Branch. 8pp. 47679.131-47679.138.

- 8812010272 Comment on proposed rule 10CFR52 re early site permits, std design certifications & combined (icenses for nuclear power reactors Adoption of detailed recommendations in NUMARC comments rocommended.

 DAVIS.E.M. American Nuclear Energy Council 53FR32080 00074, 88/11/07.

 ZECH,L.W. Commissioners. 3pp. 47679.148-47679:150.
- 8812010283 Request for 60-day extension for triing comments on proposed rule 10CFR52 re one step licensing Press release enct.
 GARDINIER,T., GARDINIER,R. Artillation Not Assigned. 53FR32060. 88/10/16. Docketing & Services Branch. 7pp. 47879, 151-47679:157.

- 8812010334 Comment on proposed rule 10CFR26 re Fitness for Duty Program. Supports
- NUMARC comments on rule
 SELMAN,M. Consolidated Edison Co. of New York, Inc. 53FR36795 C0320, 89/11/21.
 CHILK,S. Office of the Secretary of the Commission 1p. 47679:163-47679.163.
- 8812010348 Comment opposing proposed rule 10CFR150 re reassorting NRC jurisd c-tion over onsite disposal of low level waste SALESKAS, Public Chizen's Critical Mass Energy Project 53FR31888 00044, 88/11/ 18. Office of the Secretary of the Commission, 2pp. 47878;164-47879,165
- 8812010355 Comment opposing proposed rule 10CFR20 re-onsite Incinoration of stightly contaminated waste ors generated at Loonsed nuclear power plants.

 SALESKAS Public Citizon's Critical Mass Energy Project 3SFR32814 00325
- 8812010356 Commont apposing proposed rule 10CFR26 re-random drug testing in Fitness for Duty Program
 MCDONOUGH,S.P. Intercational Brotherhood of Electrical Workers 53FR36795
 00363. 88/11/28 Decketing & Services Branch 1p. 47679 168-47679 168
- 8812010363 Comment opposing proposed rule 10CFR26 re random drug testing in Fitness for Duty Program.
 International Brothorhood of Electrical Workers 53FR36795 00362 68/11/28.
 Occketing & Services Branch 1p 47679.169-47679.169.
- 8812010382 Comment on proposed rule 10CFR26 to Friness for Duty Program. Expressos concern on implementation to balance between public safety & profistd.

 ESPOSITO,G. Society for Crinical Social Workers, 53FR36795 00341, 88/11/18 Docketing & Services Branch, 2pp. 47679.170.47679,171.
- 8812010384 Comment supporting proposed rule 10CFR26 re F.Iness for Duty Program per NUMARC position. BIRD,R.G. Philadorphia Electric Co. 53FR36795 00357. 88711721. CHILK,S.J. Office of the Secretary of the Commission. 2pp. 47679:172-47679:173.
- 8812010387 Commont supporting proposed rule 10CFR26 ro Fitness for Duty Program.per NUMARC comments,wistated recommendations BAILEY, A. Wolf Creek Nuclear Operating Corp. 53FR36795 03348, 68/11/21. Docketing & Services Branch. 3pp. 47679:174-47679:176.
- 8812010391 Comments on proposed rule 10CFR26 re Friness for Outy Program for nu-clear power reactors Util endorses specific NUMARC recommended wording changes w/exceptions to Items 2 & 24.
 DEDOENS.J.C. Guif States Utilities Co. 53FR36795-00343, 88/11/21. Office of the Secretary of the Commission, 15pp, 47679 177-47679 191.
- 8812010393 Comment supporting proposed rule 10CFR26 to Fitness for Outy Program. WILLIAMS,R.O. Public Service Co. of Colorado. 53FR36795 00349, 88/11/21. Dockeling & Services Branch. 15pp. 47879:192-47679 206
- 8812010400 Comment opposing proposed rulo 10CFR26 to random drug lesting MUNYAN,R A. International Brotherhood of Electrical Workers. 53FR36795 00352 68/11/18. Docksting & Services Branch 2pp. 47679:207-47678 208.
- 8812010404 Comment on proposed rule 10CFR26 re Fitness for Duty Program including random drug testing Util endorses NUMARC comments on rule.

 * Detroit_Edison_Co_53FR36795_00356_88/11/17. Docksting & Services_Branch 10pp. 47679:209-47679:240
- 8812010405 Comments on proposed rule 10CFR26 re Fitness for Duty Program for nu-clear reactor operators.Opposes random drug screening of nuclear plant employees WHITEHEAD.G G International Brotherhoad of Electrical Workers 58736795 00345. 88/11721, Docketing & Services Branch. 2pp. 47678:250-47670:251.
- 8812010408 Commont supporting proposed rule 10CFR26 re Fitness for Duty Program per NUMARC comments, w/listed exceptions. BRADHAM, O.S. South. Carolina. Electric & Gas. Co. 63FR36795 00353. 88/11/21, Office of the Secretary of the Commission. 3pp. 47679:252-47679.254.
- 8812010410 Comments supporting proposed rule 10CFR26 re Fitness for Duty Program re substance abuse. Urges Commission to adopt suggested specific changes indicated by NUMARC comments. SCHROUDER,W.J., SMITH,R.E. Rochester Gas & Electric Corp. 53FR36795 00347. 88/11/21, CHILK,S.J. Office of the Secretary of the Commission. 4pp. 47679 255-47879 250
- 8812010411 Comment opposing proposed rule 19CFR28 to Fitness for Duty Program PROBST, J.R. Affiliation Not Assigned 53FR36795 00342, 88711717, Docketing & Services Branch, 10pp. 47679;259-47679.268
- 8812010413 Commont supporting proposed rule 10CFR26 to Fitness for Duty Program.per NUMARC comments Addi comments provided. STEINHARDT.CR. Wisconsin. Public Service Corp. 55FR36795 00340. 88/11/21, Docksting & Services Branch. 7pp. 47679.269-47679:275.
- 8812010419 Notification of QA Subcommittee of Advisory Committee on Madical Uses of Isotopes 881107 meeting in Bethosda,MD & request for comments re 10CFR35, BATES.A.L. Advisory Committee on Medical Uses of Isotopes 53FR39145, 88/10/12. Advisory Committee on Medical Uses of Isotopes 7pp 47079 276-47679:282.
- 8812010420 Comment supporting proposed rule 10CFR26 re Fitnoss for Duty Program Uni agrees w/NUMARC proposed approach. TUCKER,HB, Duke Power Co. 53FR36795 00346, 88/11/21, CHILK.S.J. Office of the Secretary of the Commission, 8pp. 47679.283-47679:290.

- 8812010421 Comment opposing proposed rule 10CFH26 to random (trug testing provision in Fitness to: Duty Program Local 142 members can accept & work under Pliness for Duty Program that contains only just cause drug testing provision provision SPEAKMAIR, J. International Brotherhood of Electrical Workers 53FR30795 00361 88/11/28 Obcketing & Services Branch | 1p. 47679/281-47679 291.
- 8812010423 Comment on proposed rule 10CFR26 re Filness for Duty Program Util has constitutional concerns re proposed random tosting which should be ruly addressed prior to rule being promulgated Endorses NUMARC & EEL comments BRONSJ C New York Power Authority (formerly Power Authority of the State of New York) 53FR36795 00359, 88/11/16. Dockoting & Services Branch, 12pp. 47679 292-47679 2010.
- 8812020001 Comment supporting proposed rufe 10CFR140 reindemnity agreements w/ persons I censed by NRC or Agreement State for milg production,passession or use of radiopharms for medical purposes BROWN.M.P. American College of Nuclear Physicians 53FR40233 00004 88/11/07. Docketing & Services Branch. 1p. 47879.356-47879.356
- 8612020007 Comment on proposed rule 10CFR26 re Fitness for Outy Program Policy of yearly testing & testing for cause backed up by training for drug prevention supported PATTERSON, J. T. Athlabon, Not Assigned, 53FR36795,00344, 88/11/25, ROBERTS NRC No Date: od Affiliation Given, 1p. 47680,049,47680,049.
- 8812020020 Comment on proposed rule 10CFR26 is litness for duly Fact that person must take random drug test to prove innocence contrary to fundamental rights afforded citizens of country. Policy should require testing only w/reasonable grounds ST JOHN,KE Affatan No: Assigned SSFR38795 00380. BB/11/22 Office of the Secretary of the Commission, 2pp. 47880:001-47680.002.
- 8812020023 Comments on proposed rule 10CFR26 re Fitness for Duty Program.NUMARC recommendation that proposed 300% sample size excessive & that 100% annual sample size will be sufficient supported COCKFICED.D W Portland General Electric Co 55FR36795 00354, 88/11/21, Docketing & Services Branch, 4pp. 47679 352-47679 355
- 8812020030 Comment opposing proposed rule 10CFA26 re-random tosting provision of Fitness for Duty Program Mombers of Local 142 at pfinit can accept & work under Pitness for Duty Program that contains only just causo drug testing provision MINSINGER,W.J. International Bretherhood of Electrical Workers 53FA36795 00364. 88/11/28 Docketing & Services Branch. 1p. 47689 018-47680:019.
- 8812020054 Substitute Page 2 to A Ruitonberg 881121 comments on Federal Duty Program corrocting error.

 GORMAN,E J. United Brotherhood of Carpenters 8: Joiners of America 53FR36795
 00389. 88/11/22 CHILK,S. Office of the Secretary of the Commission. 3pp. 47079 357-47679 359
- 8812020057 Comments on proposed rule 10CFR35 re QA Subcommittee of Advisory Committee on Modical Uses of Isotopes.
 SIMON_TR. Hoellih & Human Sorvices, Dept of, U.S. Public Health Service.
 53FR39745 00001. 88/10/28 Docketing & Services Branch. 3pp. 47680.020. 47680.022.
- 8812020064 Commant on proposed rule 10CFR28 re Fitness for Duty Program Generally agrees w/NUMARC comments & mode Believes unnecessarily burdensome to require separate contractor & vendor employee assistance programs at ZACCARIA,A Bechtel Power Corp. 53FR36795 00368 88/11/16 CHILKS J. Office of the Secretary of the Commission. 3pp. 47680 023-47680:025
- 8812020077 Comment on proposed rule 10CFR26 re Fitness for Duty ProgramLocal 142 members apposed to proposed rendom drug testing Supports just cause drug testing provision.

 NOWAK,J.M. International Brotherhood of Electrical Workers. 53FR36705 00365. 08/
 11/28. Docketing & Sorvices Branch. 1p. 47680-026-47680-026.
- 8812020088 Comment opposing proposed rule 10CFA26 re Fitness of Duty Program Implemention of rule will ensure that reverse of Intention of rule will happen LEWIS,M. Lewis, M. 53FR38795 00350, 88/11/25 Office of the Secretary of the Commission, 2pp. 47680.027-47680.028
- 812020093 Comment on proposed rule 10CFR28 re Fitness for Duty Program Endorses NUMARC comments including recommendation that random testing begin w/max enrural testing level equal to 100% w/incvatuation after 3 yrs CARTWRIGHT,WR Virginia Power (Virginia Electric & Power Co.) 53FR36795 00366 88/11/21, CHILK,S.J. Office of the Socretary of the Commission 2pp. 47680 029-47680 039. 8812020093
- 8812020103 Comment on proposed rule 10CFR26 to littless for duty. Endorses NUMARC comments Believes that 100% annual testing frequency appropriate as adequate deterrent & more than 100% would install burdon of excess for certain employ-
- MORRIS,K.J. Omaha Public Power District. 53FR36785-00367, 88/11/21, CHILK,S.J. Office of the Secretary of the Commission, 2pp. 47680:031-47680.032.
- 812020107 Comment on proposed rule 10CFR28 re Fitness for Duty Program Collective comments & recommendations of NUMARC endorsed inclusion of option for util to include breath analysis testing for alcohol recommended COLINSIL,W.G., WOODLAN,O.R. TU Electric (formerly Texas Uhritiss Generating Co.). 63FR36795 00355. 88/11/21. Docketing & Sarvices Branch 5pp. 47680,033-47690,035.
- 8812020119 Comment on proposed rule 10CFR26 re Fitness for Duty Program Just cause drug testing provisions only recommended
 * International Brother/hood of Electrical Workers. 53FR36795 00361 88/11/18. Office of the Secretary of the Commission. 1p, 47680 038-47680.038.
- 8812020129 Comment on proposed rule 10CFR26 re Filness for Duty Program General concurrence w/NUMARC comments expressed. Exceptions to NUMARC comments & addl comments encl. SHELTON,D.C. Tollado Edison Co. 53FR36785 00358, 88/11/22. Docketing & Services Branch. 8pp. 47680.039-47680:046
- 8812020279 Requests that comment period on proposed rule 10CFR50 he extended
- 120 days in order to provide effective response.
 LEE,ay, Nuclear Management & Resources Council (NUMARC) (formerly Nuclear Utility
 Menago 53FR47822, 88/11/28, ZECH,L.W. Commissioners 1p. 47680,048-

- 8812050015 Commonl on proposed rule 10ct-right relativess for duty pregams General waws on proposed rule being represented in comments submitted by NUMARIC SOMENSEN GIC Washington Public Power Supply System 53FR38785 00372 68* 11/21 CHILKS J. Office of the Secretary of the Commission. 2pp. 47695 259 47695 260.
- 8812050022 Comment on proposed rule 100.F16/h to lithess for fully program 5 per for requirements NRC proposes, especially random drug testing are of questionable constitutionally, dubous practically & good root.

 GORMAN,E. J. United Brothorthood of Carpenters. & Johney of America, 50.F1936795, 00370, 88711728. CHILKS J. Office of the Secretary of the Commission, 28pp. 47695, 261-47695, 286.
- 8812050034 Comment on proposed rele 10CEH26 relititues for duly program Supports concept of drug tosting in workplace but concerned w/portions of proposed 1.76 WHITTIER, G.D. Maine Yankon Monro Power Co. 53FR36795 66371 88711721 Docketing & Services Branch, 10pp., 47695-287, 47695-296
- 8812050056 Submits polition to immediately restitute registations that require multiplication to NRC all instances of drug Allaholiof use by workers on duty \$ ret using to repute three all instances or entry & Birchlot use by workers on duty \$ repotents of each tree's facility programs.

 GORDON,J Public Citzen's Criscel Mass Energy Project POLLARD,B. Usen of Concorned Scientists. TUCKFR K. Health & Energy Installe 87/06/04 0LNTON,HOffice of Nuclear Reactor Angulation, Orestor (Post 876411), 2pp. 17695-332 47695.934.
- -8812050057 Responds to 870604 fit from a Contour rulf thesis for they program of no clear power plant personnel NRC taking no further action on request for proposed resmaring Communits with lowever be taken into consideration. GRIMSLEY, D.H. Division of Tudes & Hudderfor (R70413-860514) 697027C3 BOSSONG,K. Pubnic Citizen's Citizal Mass Emergy Project. 1p. 47095-334-47695-338.
- 8812050989 Comment on proposed role 10CHH26 to littings for duty program. Data to comments on rule and ROTHERT,W.C. Ipwa: Electric: Light: 8: Power: Co., 531 R36/U5, 603/3, 88/15/29 CHILK,S.J. Office of the Secretary of the Commission, 4ph, 47695,335,47635,332
- 8812050992 Proposed rulu 10057350, "Ensuring Effectiveness of Meint Programs to Nuclear Power Plants." Bullo would require plant maint programs to include specifi-activities, including mendioning of effectiveness of plant maint. CHLKAS J Office of the Secretary of the Commission, 50F847022, 82/11/21, 25pp 47895;207-47695;325.
- 8812080238 Proposed rule 10CFR19, "Sorpostration of Withouses Interviewed Units Suppored" Rule world clerify difficulties encountered by NRC in conducting levels gative interviews in atmosphere free of entsets influencing CHLK,S.J. Office of the Sucretary of the Commission 53f FH9768, 88/11/03, 13pp 47723.1B4-47723.106
- 8812070032 Requests extension of comment period for proposed rolb 100FR50 r LEE,B Nuclear Management & Hesonicos Connett (NUMARC) (formely flude at Utel Manage 53FR47822 68/11/28 ZECE),L.W. Commissioners. 1p. 17723 21 47723 215
- 8812080134 Requests notification of any public operangs to be held on sectes: p?e. license renewal, per NUREG-1312, "Reg./atery Options for Nuclear Plant License Re
- HAAGEG Now York State of, 53(1)(2)(19) (0)(10)(1) Deckoting & Services Braik! 1p. 47753.110-47753 110
- 8812080140 Commont opposing proposal rate 1000-Rto re proposty tasular to code or monts for NRC licensed nuclear power plants. BRANDEBURG BL. New York NY. 49ER44645 (00016), 88706/30. Office of the Scratary of the Commussion. 15pp. 47751 039 47751 059.
- 8812080176 Forwards constituent flJ Peny comments opposing proposed to 10CFR50 to emergency planning & propercities requirements for receive year plant fuel loading & military power operations. HUMPHREY,G J. New Hampshire, State of 5:5:4110-435-03681, 88/11/03-ZECF-,CV Commissioners 4pp 47749-357-47749.060
- 8812080187 Commont supporting proposed rule 10CFR26 re "Fitness For Dady program Wzerots GRIDLEY,R.I. Tennossee Valloy Authority 53I R36705 00375 88711730 MRC 1 Dotallad Affiliation Given, 7pp. 47749 350 47749 356
- 8812080198 Comment on proposed rule 10CF1126 re "Fittioss For Duty Program".

 ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan E≥214€ Co.
 53FR36795 00376 08711/23. CHILK,S.J. Office of the Sucretary of the Control sec
- 8812080219 Proposed rule 10/CFR55, "Commission Policy Statement On Family Qualification of Nuclear Power Plant Personnel." Bute amended to act who recitive experience w/industry accreditation & to change entercement section CHiLK,S.J. Othice of the Secretary of the Commission 53FR46603, 80/31/14 4p 47750 003-47750,008
- 8812080240 Forwards commont of constituent D Harrison opposing proposed in 10CFR52 reliably site permits strictlescent outfloations & continued licenses for max ar power reactors, for response BENTSEN, L. Sonate 53FR32060 R8/11/01 KAMMERER, C.C. Office of Congresional Affairs (pre 870413), 2pp. 47750 C07 47750 010.
- -8812080242 Comment opposing proposed rula 10CFB52 rolearly site permits disign contineation & combined licenses for michiar power reactors. HARRISON,D. Attrabon Nut Assignant 5:1FR32060 00075, 88/10/05. Docketing Services Branch 2pt. 47750-009, 47750-010.
- 8812090037 Comment supporting proposed rule 1LCFR26 re Fitness Ict D Program.NRC emphasis on drug abuse should not be made at expense of effect, regulations dealing w/alcohol abuse BOLEY.K. Public Cutzen's Chilical Mass Energy Project 53FR36795 00377, 68/127/ Docketing & Services Branch 5pp. 47780.089-47780.092

- 8812090041 Requests that comment period to extended from 60 days to 120 days on proposed rule 100-Ft60 in maint in authern power plants. MLSONLK 9 For da Power Corp. (subs. of 1 binda Progress Corp.), 53FR47822 591-7-02. Chtt.K S.J. Office of the Shutetary of the Commission up 47780 087-7535.
- 6812030044 Comment opposing proposed rule 10CFR2 re-submission & mgt of records & documents re-ficensing of goologic repository for disposal of high level redwaste Change would cost exorb tonil amount of money. KADAK C Yankie Atomic Rectal Co. 53FR444411, 00003, 88712705, Dockstog & Services Branch, 249, 47780,033-47780,084.
- 8812090050 Comment opposing proposed rule 10CFR2 re-submission & mgt of records 8 documents related to licensing of geologic repository for disposal at high leval red SISGEL FR. US Council for Frangy Awareness. 53FR44411-00001-89/12/05. Dock chig & Services Branch. 2pp. 47789-085-47783-086
- 8812090058 Comment opposing proposed rota 100/FR2 re-schimission & right of records & economis related to licensing of godfond repository for disposal of high level rad-

FUFRERIAIA, KOSER,H W. Archester Gas & Electin Corp. \$195844411 00002 887-12705. CHILK,S.J. Ollice of the Secretary of the Germinsson 5pp. 47780 078-

8812090085 Franscript of HB1114 treaming in Rockvide,MD to Price. Anderson

- aransenga or mittital hearing בי Bockviče,MD ro Price- Anderson ručenaštrig Pp 1-69 י NRC No Detailed Afflintain Given 53/-П40230 88//11/14 71pp 47/50/011-47/50/031
- 8812090255 "Sategoards Requirements for Fuel Facilities Possissing Formula Quantiles of Strategic SNM," 100T/12,70 & 75 final inities Regulator's amonded to require protection equaverint to that in place at comparable DOS fuel facilities CHILKS 1 Office of the Secretary of the Commission, 53F045447, 8871,1714, 30pp. 47757 242-47757 271
- 8512120036 Comment on proposed rule 10CLR71 adopting IAEA regulations NRC regulations differing from IAEA regulations also further escalation to restrictions being placed in contain alpha emitters w/o adequate justilication DORUFF MIA Amerishum Corp. 52FTR/1550-00071, 68F12705, Danketing & Services

Biar.ch. 3pp 47763 340-47763 350

8812120050 Comment opposing proposed rulo 10CFR2 re-satimasion & mgt of recerds & documents rotated to Leanwing of High level radwaste geologic repository Util supports EEL comments to be submitted to NRC HARSTON,V.G. Alabama Power Co. 501 [144411-00005 88/12/05 CIBLK,S.J. Office

of the Secretary of the Commission 1p. 47798 086-47708 086

- 8612120059 Comment opposing proposed rulo 160FR2 rul records related to licensing high level radwaste geologic repository Util anderses EEs comments to be submitted
- HARISTON W.G. Georgia Power Co. 53f H44411 00004, 88712705, CHILK,S.J. Office of the Secretary of the Co. maississ. 25pt. 47798 007-4778 008
- 8812120071 Requests 2-wk extension to comment time on preposed rule 10CFR2 resubmission 8 liigt of records 8 documents related to Licinsing of geologic repositivy for disposal of high level radivasta. BLANCHARDS Interior, Digit of SFR44411 88/12/85 Dacketing 8 Services Dranch 1p. 47/98/889-47/20/889

8012160147 Deries 801112 request for Commission to extend public comment period on proposed rule 10CFH26 to littless-for-duty. Ample opportunity was provided to par-

Tepado GRIMFS,U.K. Division of Reactor Inspection & Safeguards (Post 670411) 53FR36795 HB/12707. AUBERIS,K.L. Albation Not Assigned Ip. 47873 359

- 8812160151 Denies 881112 request for Commission to extend public comment period on proposed rule 10CFR28 to fitness-for-duly GRIMES.B.K. Dwission of Beactor Inspection & Safeguards (Post 870411), 53FR36795 88712707, DOYLE,W. Attention Not Assigned 1p. 47835,169-47835-169.
- 8812220305 Forwards proposed rule 19CFR140, "Financial Protection Requirements & Informity Agreements Miscellaneous Amenits Necessitated by Changes in Price-Anderson Act." Changes recommended by recipient incorporated HOMASCO Policy Development & Technical Support Branch (Post 870411), 53°F5120. 88712 47901 083-47901:092
- 8812230054 Forwards for workpapers in support of notice of final rulomaking for nOCFR170 & 171.

HOLLOWAY, C.J. License Fee Management Branch, 88/12/20, BLANTON, J.O. Document Control Branch (Document Control Dask), 220pp. 47915 001-47915 220

PAM PETITION FOR RULEMAKING

- 8812010268 Comment opposing petition for ruteinaking PRM-50-52 re-reinstatement of timenoial guartications as consideration in treatings on Issuance of OL for nuclear power roactors RADER,R.M. Conner & Wetterhalbii 53FR32913 00023, 88711/17 CHILK,S.J. Office
- of the Secretary of the Commission, 9pp, 47679:139-47679.147 8812010303 Comment apposing periods for rulemaking PRM-50-52 re-consideration of financial fluel feation during OL review NRC insp. & enforcement program more direct & officient way of assuring safe operation GRIDLEY,R.L. Tennesson Valley Authority, 55F B32913-09024, 88/11/02 Document Control Branch (Document Control Seek), 2pp. 47-771-158-47679-158
- 8812010322 Comment supporting partition for rule, eating PRM 50-51 filed by EEF & NUMARC. Other two flungs consistent w/EEF/NUMARC pointon & can be accommodated by adopting changes along the out amond: I approach in EEF/NUMARC partition. KNOTTS J.B. Bishop, Cords, Purcell Finghords not 136:335 00004 88/11/15. Docketing & Sorvices Branch: 1p. 47:179 47:279-160.

- 8812060298 Forwards petition for regenating PRIM 20:18 to classifying disposal of solid-bomodical wastes containing P(3) & C(14) is below regulatory condoin as reasonable alternative to burial at commercial low love; rartwaste site GERSITEY.ELL Rockergler Univ. New York, NY, 53FP43896 00001 88/08/16 Docketing & Sorvices Branch 11pp 47723 197-47723 207.
- 8812060305 Requests expansion of radioisotope List where contaminated an incl to sups may be considered de minimus & make unregulated disposal of fissuus practice us which all fund clons must comply GERSHEY,E.1. Rockefelor Univ., New York, NY 53FR44014 00001, ft8/07/22 LAHS,W NRC - No Datared Affaton Glyon Tp. 47723.213-47/20.213
- 8812060323 Notices of receipt of position for rulernaking filed by Flocketatlar Univiru amend to regulations to permit (censed to dispose of solid biomedical waste containing small amounts of radioactivity by ansitu incinoration CHILK,S.J. Office of the Secretary of the Commission, 53F743896, #8710725. Office of the Secretary of the Commission, 559, 47723-208, 47723-212.
- 8812060333 Comment on petitions for rulemaking IPRM-20-18 & PRM-20-17 to Rocko-feller Univ request for permission to incinerate animal radioactive bodies Oppusus change. NEMETHY,E. Ecology/Almi. 53FR43896-00002-88/11/14. Docknting & Services Branch. 1p. 47723-214-47723-214
- 8812070020 Petrion for rulomaking PRM-20-17 to disposal of animal tissue confidingly small amounts of tottoactivity w/o regard to raid pactivity by expanding Let of raidbactivity. The Isotopes for which unregulated disposal permitted
 CIJILK,S.J. Office of the Secretary of the Commissioners, 4pp. 47723 216-47723 219
- 8812080228 Comment supporting partions for rulomaking 20-17 & 20-18 re-radioactive SUMMERS,J. Winlhop Univ. Hosp., Long Island, NY. 53FR44014-00003-007/11/25 Docketing & Sorvices Branch. 2pp. 47750-003-47750,002

PROJ PROJECTS - PREDOCKET LICENSING

- 8909130261 Forwards Rev 0 to "Topinal SARI for CASTOR X Cask for ISES) (Dry Storlage)," for review W/o uncl ANDERSON,R.T. General Nuclear Systems, Inc. 24470, 88707701, ROUSE,L.C. funt Cycle Safety Branch, 2pp. 48826 040-46826 841
- 8809130261 Forwards Rev 0 to "Topical SAR for CASTOR X Cask for ISESI (Dry Storago)," for roview ANDERSON,R 7 General Nuclear Systems, Inc. 24470 BB/97/01, RGUSF,L.C. Funt Cyclo Safuty Branch 4pp 47759.196 47761 065
- ~8812080072 Santized version of Flov 0 to "Topical SAR for Caster X Cank for ISESI (Dry Storago) " " General Nuclear Systems, Inc. 88/06/30 | 586pp. 47750 200 47761 065
- 8811280186 Forwards ropt summariting status, progress & expenditures of Wort Valley Demonstration Project for quarter ending 880630 in respected to 11.0.87-177 require BUNCH,D.F. Energy, Dept. of. 24941, 897/10703, ROE,R.A. Hause of Fiep., Sakii Space & Technology (formuly Science & Technology), 7pp. 47652:225-47652,231
- 8811290058 Advisos that Soction 30 D.2 of EPRI-advanced LWR requirements documont. Chapter 1 open flow re suppression pool loads needs further clarification Section not close on whether proposed leak-before break consistent w/ LONG.W.O. Standardization & Non-Power Reactor Project Oroclorate 68711717 KINTNER,E.E. General Public Utilines Corp. - GPU Service Corp. 2pp. 47648:172-
- 8811290064 Submits guidence re-acope of design & scope of statt review of CESSAFF-DC,Sys 80 i Nobilication of intentions of matter & schoolder for automating application,including FSAR, requested Potential review subjector stat plant classiques enci. CRUTCHFIELD.D. Associate Director for Projects (Post 870411), 00/11/21. SCHERER,A.E. Combession Engineering, Inc. 8pp. 47649:205-47649:272
- 8811300213 Forwards into re-scope of SAR for future std design applications & NAC review of applications into useful in proparation of advanced LWR util requirements CRUTCHFIELD D CRUTCHFIELD,D. Associate Director for Projects (Post 870411). 88/11/22 KINTNER,E.E. ALWR Ulinty Steering Committee KINTNER,E.E. General Public Use, ites Corp. - GPU Service Corp. 7pp. 47676:107-47676.313
- 8812050149 Provides supplemental qualification data re-committed low level waste form 8 reaffirms project position on long-term mgt of subj weste BIXBY,W.W. Energy, Dopt. of 887/1/29 KNAPP,M. NGC No Detailed Affiliation Given 3pp 47719-011-47719-179.
- --8812050160 "Corrent Waste Form Qualification Rept WVDP Purex Decontaminated Supernatant Rept of Work Performed for Perford 1983 Through 1086." MCVAP,CW, MARCHETTISS, STIMMELUR, Wost Valley Nuclear Services Co., Inc. 88/08/31, 166pp. 47719 014-47719-179
- 8812050189 Notification of 881220 meeting w/C-E in Reckville MD to discuss setsmic issues involved in containment dosign for CESSAR-DC Sys 80e re-sol/fetructure interaction phase
 VISSING.G.S. Standardization & Non-Power Reactor Project Directorate 88/11/28,
 MILLER.C.L. Standardization & Nort-Power Reactor Project Directorate 4pp.
- 47732:300-47732:303
- 8812060315 Forwards status rept for Nov 1988 related plant design technical reviews MILLER.C.L. Standardzellon & Non-Power Reactor Project Directorate 69/11/29 SHAO.I. Division of Engineering & Systems Technology (Post 870411) GHIMES Division of Reactor Inspection & Safeguards (Post 970411). CONGEL,F. Division of Radiation Protection & Emergency Proparedness (Post 870411), 15pp. 47742:200-47742:211 47742:214

ance & dedicated use of GA Technologies digital instrumentation & control consolain confluetion w/US Air Force reactor facilities per 860408 request ADAMSA Standardization & Non-Power Reactor Project Directorate 68/11/14. NELSON,R.C. Air Force, Dept. of 4pp. 47748.094-47748.097.

8812090284 Forwards "Cement Soudi cation of Decontaminated Supernatent Waste for West Valley Project" technical evaluation replifor infolinto & results from proposed short. & fong-term testing programs requested.

KNAPP,M.B. Division of Low Level Waste Management & Dacominissioning (Post 870413), 88/11/29 BIXBY,W.W. Energy, Dept. of, Idaho Operations Office, 2pp. 47751 054-47751 077

~8812090277 "Coment Solidification of Decontaminated Supernalant Wasto for West Valley Project," technical evaluation rept
• Office of Nuclear Material Safety & Sateguards, Director. 88/11/29 22pp.

47761.056-47751 077.

- 8812130094 Forwards proprietary addl Into re NUH-002,per SAIC requestinfo withhold (ref 10CFR2.970).
 MCCONAGHY.W.J. NUTECH Engineers, Inc. 24989, 88/12/07, ROBERTS,J.P. Fuel Cycle Safety Branch Spp. 47792/082-47792/086
- 8812160147 Forwards proprietary supplemental into re response to NRC 881109 Question 6 on NUHOMS-24P Topical Rept NUH-002 into withheld (ref 10CFR2 780). MCCONAGHY, W.J. NUTECH Engineers, Inc. DUK-03-319, 88712701, ROBERTS, J.P. Fuot Cycle Safety Branch. 5pp. 47833 001-47893.005
- 8812150012 Requests technical assistance in reviewing radiological safety section of SAR for facility submitted by licensee 881202 its Suggestions & comments requested by 880129.

 MILLER.C.L. Standardization & Non-Power Reactor Project Directorate, 88/12/08

 CUNNINGHAM,L.J. Radiation Protection Branch, 2pp. 47873;233-47673;234.
- 8812180076 Notifies NRC of NUTECH receipt of US Patent 4,780,269 for NUHOMS design Copy of patent encl. Requests that proprietary status of all info submitted on subj projects be maintained MCCONAGHY, W.J. NUTECH Engineers, Inc. WJV-86-257, 88/12/07, ROBERTS, J.P. Fuol Cycle Safety Branch. Opp. 47834-228-47834-238.
- 8812160121 Forwards Roy 0 to "Advanced LWR Requirements Document, Chapter 6-Bidg Design & Arrangement," for review. KINTNER,E.E. ALWR Unity Steering Committee KINTNER,E.E. General Public Utili-ties Cop. GPU Service Cop. 88/11/18. Document Control Branch (Document Con-trol Desk), 1p. 47833-083-47833.317.
- -8812160124 Ruy 0 to "Advanced LWR Requirements Documents,Chapter 6 Bidg Design & Arrangement" * Bechtel Group, Inc. * Combustion Engineering, Inc. * Commonwealth Edison Co 88/11/30, 400pp, 47633-084-47833-317.
- 8812190060 Requests technical assistance in reviewing end emergency plan for facility submitted by licensee 881202 ltr. Completion for review projected for 890120.W/o
- MILLER,C.I. Standardization & Non-Power Reactor Project Directorate, TAC 67921, 89/12/08 TRAVERS,W.O. Emergency Preparedness Branch, 2pp. 47850,359-47850,359-47850,359-47850,359-47850,359-47850,359-47850,359-47850,359-4
- 8812190073 Requests technical assistance in reviewing App C of SAR for SNRS TRIGA reactor facility submitted by 681202 is Review should be completed by 680120. MILLER,C.L. Standardization & Non Power Reactor Project Directorate TAC 67921. 68/12/08 BARRETT,R.J. Risk Applications Branch. 2pp. 47840;180-47840;181.
- 8812200046 Forwards ALWR Requirements Document Chapter 6, "Bidg Design & Arrangoments," for use in chapter review.
 KINTNER,E.E. ALWR Utity Steeling Committee, KINTNER,E.E. General Public Utilities Corp. GPU Service Corp. 80/11/18, LONG,W. Standardization & Non-Power Resctor Project Directorate, 2pp. 47858;288-47858;290.
- 8812220242 Forwards request for additinto re ARSAP Topic Paper 3, including Item 3.1, "External Events," Item 3.2, "Success Chitoria & Mission Time" & Item 3.3, "Accident Sequence Selection " Response requested within 60 days. VISSING.G.S. Standardization & Non Power Reactor Project Directorale, 88/12/15. SCHERER,A.E. Combustion Engineering, Inc. 14pp. 47909,220-47900,233.
- 8812230099 Forwards "Run Rept.Supernatant Treatment Sys," for Campaigns 3 & 4.dtd Jul & Aug. 1988.respoctively.In future campaigns, sing'o run rept will be issued to include all four subsys.
 BIXBY,W.W. Energy, Dept. of, Idaho Operations Office. 25018 98/12/02. HURT,R.D. NRC No Detailed Affiliation Given. 2pp. 47914:241-47914:286.
- --8312230107 "Run Rept Supernatant Treatment Sys," Campaign 3 for Jul 1988. SKILLERN.C.G. Energy, Dept. of, 88/08/10, 26pp. 47914 243-47914;268.
- --8812230100 "Run Ropt Supernatant Trealment Sys," Campaign 4 for Aug 1988 HOSS,C.F. Energy, Dept. of. 08/11/10, 18pp. 47914;260-47914;286.
- 881230265 Requests review of end instrumentation & control section of SAR for TRIGA reactor Although Incliny will not be NRC licensed Air Force requests assistance W/o stated onci.
 - MILLER,C L Standerdization & Non-Power Reactor Project Directorate, TAC 67921, 88/12/08 NEWBERRY,S. Instrumentation & Control Systoms Branch. 2pp. 47916:145-47916:146

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

- 8811230288 Part 21 rept re defect in design of component mig by Cooper Energy Svockhittelly reported on 861115.Uni became aware of problem on 881103.Div i emergency deset generator declared inoperable & valva reclassified.

 TERRY,C.D., Niagara Mohawk Power Corp NMP21 1181, 68/11/21. RUSSELL,W.T. Region 1, Otc of the Director, 3pp. 47652:063-47652.065.
- 8811290140 Trip ropt of 881028 site visit re nunconforming parts received from Sample-Webtrol for Masonailan valves.Related into oncl. GUILLENJ. Generic Communications Branch. 88/11/23. BERLINGER,C.H. Generic Communications Branch. 8pp. 47850 238-47850-245.

DIV 1 & 11 emergency diesor generators inton-category 15 components disconnected from generator start crouits Plant mod planned.
TERRY.C.D. Neggara Mohawk Power Corp. PT21 88-117-030 88/10/05 RUSSELL,W.T. Region 1, Ofc of the Director 3pp. 47802-318-47602-320.

- 8611290574 Part 21 rept re-nonconforming equipment All planned & required actions have been completed to close rept.

 SMITH, J.A., STAFFORD, K.E. Victoreen, Inc. (subs. of Sheller-Globe Corp.) P[21 88115 000. 88/10/31. Region 3, Ofc of the Director. 1p. 47648;193-47648 183
- 8811300033 Part 21 rept re potentially defective intercocter inici adapters installation Encl Svc Info Momo 365,Rev 2,sent to all affected sites GUNTRUM, B.C. IMO Dotaval, Inc. PT21 86-114-000 86/11/11, Office of twolvar Feactor Regulation, Director (Post 870411), 10pp. 47697:114-47697:124.
- 8811300526 Forwards Part 21 rept re-breaker trip causing spurious undervotago rola;
- RIFE STATE OF THE PROPERTY OF
- 8812010197 Part 21 Rept 88-018-00 re-binding problems w/Telemecan que Gould MCC AB21 & AB22 Inestendre Initially reported on 881123. Etuven linestarters repaired 8 te maining linestarters will be inspected during lists refuel ig outage. NOONAN,T.P. Duquesne Light Co. 88-018-00. 88/11/28. Document Control Branch (Document Control Dosk), 4pp. 47709 245-47709-249.
- 8812010199 Part 21 rept re defect in GE Type 180 Indicating type meters. hally reported on 861027 NSSS inc Identified as firm supplying component Meters will not be authorized for use in safety-related applications pending resolution.

 BURKHAROT, L. Niagara Mohawk Power Corp. NMP1L 0327 86/11/23 RUSSELL,W.T. Region 1, Otc of the Director. 3pp. 4/707:146-47707:148
- 8812050065 Part 21 rept re potential for counterfeit Masonalan valve parts being sup-plied to commercial nuclear facilities. All Identified parts from plant named in 65:02: ropt segregated & replaced independent investigation underway.

 ALLEN,W.1. Dresser industries, Inc. 88/11/18. GRIMES,8. Division of Reactor Inspection & Safuguards (Post 870411). 2pp. 47723;103-47723;104
- 8812060298 Part 21 & final deficiency rept to ESF divisol generator gallury damage initially reported on 881026.Damaged parts on divisol generator 2 replaced Deficiency is solally attributable to Cooper-Bessimor maint activities GOLOBERG.J.H. Houston Lighting & Power Co. ST-HL-AE-2668 88/11/23 Document Control Branch (Document Control Dock). 4pp 47742:196-47742:169
- 8812140171 Part 21 & final deficioncy rept to potential falluro of operator-to-valvo congagement of Xomox supplied valves. Inflinity reported on 871204. On 880711, Xomo: provided reptacement pairs for 24 valvos identified GRIDLEYR. Transessee Valley Authority, 88/12/09. Document Control Branch (Document Control Desk). 4pp. 47796:145-47796, 148.
- 8812200286 Part 21 & final deficiency rept to containment hydroge analyzers. Remaining Unit 1 flow regulator replaced w/ regulator containment hydroge steel disphragm (SSD) Unit 2 regulators w/SSDs Installed GOLDBERG, J.H. Houston Lighting & Power Co. ST-HL-AE-2090, 68/12/13 Document Control Branch (Document Control Dosk), 5pp. 47860.288-47860:292
- 8812200267 Final deficiency & Part 21 rept to Class 1E battery cables Int ally reported on 881109.Util completed qualification of other jumper cables for use & unqualified cables replaced w/ qualified cables. GDLDBERG.J.H. Houston Lighting & Power Co. ST-HL-AE-2893. 88/12/13. Occument Control Branch (Document Control Dask). 4pp. 47860 208-47860 211.
- 8812210214 Informs that licensee currently fabricating basic component for nucleal facility.per requirement of 10CFR21. SCRUTON,G.S. PX Engineering, L/2336, 88/09/02, Region 4, Ofc of the Director, 1147831:210-47881:210.
- 8812220129 Part 21 rept ro cracks found in Wostinghouse 20-Inch gate valve biscs roturned to Westinghouse for metallurgical evaluation Cracks do not represent set startial safety hazard. Diagram of cracks encl.

 PAPANIC, G. Yankee Alomic Electric Co. FYR 88-163, 88/12/14, MURLEY, I.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 4pp. 47914.084-47914.667
- 8812220328 Advisos that RO Kulchak reappointed responsible officer to ect in behall author for company re 10CFR21 activities & is authorized to provide nel-fication and quired by 10CFR21, Paragraph 21.21.

 ADAMS,F.M. Mortson-Knudsen Co., Inc. 88/12/01. Oic of Enforcement (Pc. 870413). 3pp. 47916:186-47916:187.

QA999 QUALITY ASSURANCE INSPECTIONS

- 8812010095 Forwards itr to be issued to customers re incorrect valve weight & ctr gravity. MAYS,D.R. Copos Vulcan, Inc. 88/11/22, GRIMES,B. NRC - No Detailed Affina. a Glven. 2pp, 47702:310-47702:311.
- 8812050065 Part 21 rept re-potential for counterfeit Masonellan valve parts being supplied to commercial nuclear facilities. All Identified parts from plant named in 98102 rept segregated & reptaced-independent Investigation underway.

 ALLEN,W.T. Drasser Industries, Inc. 88/11/18. GRIMES,B. Division of Reactor & spection & Saleguards (Post 870411), 2pp. 47723:103-47723:104.
- 8812210310 Forwards Insp Rept 99900880/88-01 on 880926-30 & notices of roncor formance & violation.
 BRACH,E.W. Vendor Inspection Branch. 88/12/16 WINDT,W.E. Toxas Bell Co. 2p 47881:212-47681:230.
- --8812210317 Notice of violation from Insp on 630926-30.Violation noted 10CFH21 r quirements not imposed on Purchase Orders 10/3, 39696,40026,38148 & 38653.

 **Office of Nuclear Reactor Regulation, Director (Post 870411), 88/12/16, 14/881:214-47881:214.

repts to Carolina Power & Light not included in OA program
* Office of Nuclear Reactor Regulation, Director (Post 870411) 89/12/16 4pp 47881 215-47881.218.

- --\$312210321 Insp. Ropt 99900888/86-01 on 8899926-30 Violations & noncomptance roted Mejor areas inspected implementation of licensee QA program to fabrication of lasteness for nuclear factities. CONWAY_JT., BARER,ET., PARKER,L. Vendor Inspection Branch. 88/12/09. 12pp. 47681-219-47681-230.
- 8912210324 Forwards Insp Rept 99903105/98-01 on IRR0912-18 & natice of nonconfor-BRACHE.W. Vendor Inspection Branch 88/12/16 BUZBEE,T.D Fisher Controls International (subs of Monsanto Co.) 2pp 47875 102-47875 116
- -8842210328 Notice of nanconformatice from Insp. on 860912-16. Nanconformatice noted three measuring 8 tost equipment (M8TE) out of callat, M8TE callat history record not found for Flow Rate Tester CRB.144.8 Callar Programme 213 madequate. Office of Nuclear Regulation, Cirector (Post 870411). 88/12/16. 1p. 2016. 47875:104-47875:104.
- ~8812210329 Insp. Repl. 99900105768-01 on 880912-17 Noncompliance noted. Major areas inspected directistances surrounding Duko Power Co problem reliconsed valve. Art operator sizing
 PETROSINO,J.J. BAKER,ET Vendor Inspection Branch 88/11/30 12pp. 47875:105-47875:116
- 8812210334 Forwards Insp. Rept. 99901115/08-01 on 886815-19 & notices of nonconformance & violation Fature to Invokujas applicable, provisions of 10CFH21 on vendors supplying safety-retaind matt & sixes identified as most significant violation BRACH&W. Vendor Inspection Branch 38712/16 BENNING.W. Anchor/Darling Valve Co. (subs. of Anchor/Darling Industries, Inc.). 2pp. 47875-271-47875-285.
- -8812210338 Notice of violation from map on 880815-19 Violation noted licensee putchase orders to vendors for select/re/ated components or svcs up through early 1938 failed to specify provisions of 10CFH21
 - NRC No Detailed Affiliation Given 89/12/16 1p. 47875 273 47875 273
- -8812210339 Notice of honconformance from inspion 880815-19. Nonconformance/de-Valion noted:W Banning certification as registered prof engineer performed over 2 yrs after required from leaf route date. **
 NRC - No Detailled Africation Given 88/12/16 2pp 478/5/274-478/5/275
- -8812210340 Insp Rept 99901115768-01 on 880815-19 Violations & nonconformances noted Major grees inspected ticensel OA program to design mig & assembly of com-ponent sid supports (snubber) supplied to nuclear industry.

 PETTS.R.L. POTAPOVS,U. Veridor Inspection Branch. 8B/12/06. 10pp. 47875.276 47875 285.

REGGO REGULATORY GUIDES

- 8811230025 Notifies of typo in Page 2 of IM Johnson 881110 ftr rolut Commitment fer providing Indication for reactor water level in order to meet NRC Reg Gizile 197 Correct value for Reg Gizile 197 comprished is + 57".

 JOHNSON,IM Commonwealth Edison Co. 5350K 887/11/17, MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 47651.323.47651.323
- 8811290072 Special Rept 88 008 on 881026, deset generator Train B d.d. not reach rated voltage 8 frquency within required time, per Reg Guita 110ft, Socion C.2 E.2 Caused by lack of fuel in the upon diesel start due to personnel error. HA/RSTON, W.G. Georgia Power Co. ELV-00020 88/11/23 Document Control Branch (Document Control Desk). 2pp. 47649:251-47649.252.
- 88 11290 103 Advises that now heatup 8 cooldown curves will be generated after analysis of next surveillance capsule data at approx 6 EPPY, per Generic Ltr 88-11.Ref temps for all plant reactor vessel matts at and-of-lide are below screaming criteria HARSTON,W.G. Alabama Power Co. GL-89-11, 86/11/23. Document Control Branch (Document Control Desk). 2pp. 47849.253-47649.254
- 8811290309 Responds to Generic Ltr 88.11, "NRC Position on Radiation Embrillement of Reactor Vessel Mail & Impact on Plant Operations," per Rev. 2 to Reg Guide 1.99 Pressure temp wit be rovised by ord of second refucifiq
- 88 11290335 Responds to Generic Ltr 88-01, "NRC Position on Radiation Embrittement of Reactor Vessel Mails & Impact on Plant Operations." Util determined that nother unit will exceed criteria, por Reg Guide 1.99,Rov 2,through end of I.te CONWAY,W.F. Florida Power & Light Co GL-88-11, 88/11/23, Document Control Branch (Document Control Dosk), 3pp. 47665 273-47685:275.
- 8811290350 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embritlement of Reactor Vessel Malls 8 Impact on Plant Operations" Submitted dates for Tach Spec amends 8 results of fracture toughness analyses for plants stated.

 GALLAGHERJ.W. Philadelphia Electric Co. 88/11/23, WURLEY, T. Office of Nuclear Reactor Regulation, Director (Post 670411), 3pp. 47665-276-47665 322.
- -8811290355 SASR 88-84 RD1 Rev 1 to "Impact of Reg Guido 199,Rev 2 on Peach Bottom Atomic Power Station Unit 3." CANE,T A., PAPANDREA,C.J., RANGANATH,S. General Electric Co. 88/10/31, 19pp. 47665 2/9-47665:297.
- -8811290357 SASR 88-82 R01 Rev 1 to "Impact of Reg Guide 1.99,Rev 2 on Limerck Generating Station Umit 1.

 PAPANDREA.C.J., CAINE, T.A., RANGANATH, S. General Electric Co. 88/10/31, 25pp
- 8811290479 Discusses impact of Reg Guide 1.99, Rev 2 on operations in response to Genefic Ltr 88-11. SMEDLEY, R.W. Consumers Power Co. GL-88-11 88/11/21. Document Control Branch (Document Control Desk) 2pp 47650.139-47650.140

- Clude provisions from NRC SHP 8 Reg Guide 1.70 Fee paid BERRY K W. Consumers Power Co. 88/11/22 Document Control Branch (Document Control Desk) 3pp. 47697 195-47697 197
- 8811300228 Responds to Generic Etr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Malls 8 Impact on Plant Operations." New pressure temp implements be impremented on by June 1989.
 TUCKER, H.B. Duke Power Co. GL-88-11, 88/11/21, Document Control Branch (Document Control Desk). 3pp. 47698-277-47693-278.
- 8811300282 Informs that util shall propose new plant Tech Spec pressure-temp fimits derived using Rev 2 to Reg Guido 199, per Geberic Ltt 88-11 before 891231. SMEDLEY,R.W. Consumers Power Co. GL-88-11 89/11/23. Document Control Branch (Document Control Dask) 2pp. 47696.204-47696.205
- 8812010021 Responds to Generic Lir 88-11, "NRC Position on Radiation Embritilement of Reactor Vesse! Make & Impaction Plant Operations " Utili currently evaluating new hostup & cooldown curves Technical enalysis encl SIEBER, J.D. Duquesne Light Co. GL-88-11 88/11/23 Document Control Branch (Document Control Dosk) 20pp 47702/345-47703/013
- 812010117 Concurs in NRC proposal to issue Reg Guide 19,Rov 3, "Selection,Dosign,Qualification,Tosting & Rehability of Diesel Genorator Units as Onsite Electric Power Sys at Nuclear Power Plants" REMICK,F. J. ACRS. Advisory Committee on Reactor Saleguards 88/11/22. STELLO,V. Oto of the Executive Director for Operations 1p. 47699/312-47699/312.
- 8812010121 Requests NRC position re classification of emergency cliesel generator velid demands Chiloria re emergency dissol generator run "stedii ChiRZANOWSKI,R Commonwealth Edison Co. 5327K. 88/11/22 MULLER, D.R. Office of Nuclear Reactor Regulation, Director (Post 870411). 2pp 47703.014-47703.015.
- 8812010215 Forwards environ assessment 8 triding of no significant impact re util 860701 aniend request to change schedule for implementing recommendations of Reg Guide 1 97 for monitoring neutron turn reactor following accident. KINTNER, L.L. Project Directorate II.1 TAC 68675 88711729. COTTLE, W.T. Systam Energy Rosources, Inc. 3pp. 47901:126 47801 132.
- -8812010220 Environ assessment & finding of no significant impact to 880701 amend application, chaning school/de for implementing recommunications of Fleg Guide 1.97 for monitoring neutron flux in reactor following accident VERRELLI,D.M., ADENSAM, E.G. Project Directorate II-1, 80/11/29, 4pp. 47901:129 47901:132
- 8812010305 Providos enalysis of Reg Guide 1.90,Rov 2, "Radiation Embrittlement of Reactor Vessel Malls" for impact on proseure-temp heatup & cooldown curves contained in Toch Specs por Gonoric Ltr 88-11.

 RICHTER,MH Commo
- 8812010350 Forwards comparison of roll nil ductifity transition temp values calculated utilizing Reg Guido 1.99,Rov 2 vs values provided in util 880902 ltr.per Generic Ltr 68-HAIRSTON,W.G. Georgia Power Co. Gt. 88-11. 88/11/28. Document Control Branch (Document Control Desk). 3pp. 47710-094-47710-096.
- 8812020028 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vesse' Matis & Impact on Plant Operations." Chenges to heatup & cooldown limits needed for conservative operation up to 10 EFPY.por Rog Guide 1.99 TUCK.ER.J.H.B. Duke Powor Co. 61.88-11 88/11/28. Document Control Branch (Document Control Desk). 2pp. 47711.136-47711.137.
- 8812020000 Forwards response to Generic Ltr 88-11, "NRC Position on Rediation Embittlement of Reactor Vessel Matts & Impact on Plant Operations." Pressure temp curves determined more conservative than Roy 2 to Reg Quide 1.99 requirements GOLOBERG.J.H. Houston Lighting & Power Co. Gl.-88-11-88/11/22. Document Control Branch (Document Control Dass). 3pp. 47711-129-47711-131.
- 8812020296 Provides summary of results of fechnical analyses in response to Generic Lif 88-11 did 880712 Pressure/Temp I mits need to be updated & schedule proposed for updated 7 feb. Specs TERRY C 0. Niagara Mohawk Power Corp. NMP2L 1182 88/11/28. Document Control Branch (Document Control Branch (Document Control Desk) 3pp. 47718-283-47718-265.
- 8812050041 Forwards response to Generic Ltr 88-11, "Radiation Embrittlement of Reactor Vessel Matis." Util will submit I cense amend requests to incorporate new heatup & cooldown curves in Toch Specs for Salam Units 1 & 2 by Dec 1988. MILTENBERGER, Public Service Effectic & Gas Co. of New Jersey. GL-98-11, 98/11/28. Document Control Branch (Document Control Desk). 7pp. 47732:021-1328
- 8812050140 Confirms NRC Reg Guldo 1.07 Insp on 881212-16 re post-accident monitoring instrumentation established during telecon between B Shingleton & MJ Kopp Requests to submit documents listed HARRISON, J. Reg on 3, Otc of the Director, 88/11/29, SHELTON, D. Toledo Edison Ca 2pp. 47733 282-47733 289
- 8812050302 Forwards response to Generic Ltr 88-11, "NRC Position on Radiation Embritlement of Reactor Vossol Matla & Impact on Plant Operations" using methodology In Rev 2 to Reg Gu de 190 COCKFEELD, W. Portland General Electric Co. GL-88-11, 88/11/30, Document Control Branch (Document Control Deak), 14pp. 47740,263-47740;276.
- 8812050307 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Matls & Impact on Plant Operations" Temp Imits revised in Amend 118 to License NPF-3 based on draft Rev 2 to Reg Gulde 1.99 SHELTON, DC. Toledo Edison Co GL-88-11, 88/11/28. Document Control Branch (Document Control Desk). 1p. 47734:152-47734-152.
- 8812060016 Responds to Generic Ltr 85-11 re radiation ambrittement of reactor vessel mails Util utilizes draft Rev 2 to Rog Guide 1 99 methodology to practic effect of neutron radiation on reactor vessel mails. SCHNELL, D.F. Julion Electric Co. ULNRC-1867. 88/11/30. Document Control Branch (Occument Control Desk). 4pp. 47741.052.47741.055.

- 8812060085 Responds to Generic Ur 88-11 re datails of implementation of Reg Guide 1.99 Rev 2 in energies, other than PTS Uni implementing methodology of reg guide into healup & cooldown curves for unit Proposed Tech Specs on such being prepared CARTWRIGHT, W.R. Virginia Power (Virginia Electric & Power Co.). 88-4924, 88/11/30. Document Control Branch (Document Control Desk) 2pp. 47743.068-47743.069
- 8812060088 Advises that Reg Golde 1.99.Rov 2 methodology has no immediate impact on plant operations,per encil evaluation of plants for Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Matis & Impact on Plant..."
 GRIDLEY,R. Tennessee Valley Authority, 61-88-11, 88/11/30, Document Control Branch (Document Control Desk), 20pp. 47752-203-47752-222
- 8812080102 Responds to Generic Ltr 88-11 re embrittlament of reactor vessel belltine malls per Reg Guide 1.99,Rev 2 Proposed Tech Specs which implement Rev 2 to Reg Guide 1.99 under NRC review.

 CARTWRIGHT,W R Virginia Power (Virginia Electric & Power Co.) 89-492, 88/11/30 Document Control Branch (Document Control Desk) 2pp. 47734:354-47734:355.
- 8812060295 LER 88:033:00 on 88:101,discovered unacceptable electrical regiation between facility Cress 1E Drv II dic power source & D22 bus dic circuits Caused by personnel error All non-Class 1E circuits removed from Div II dic source W/881201 tr. GALLAGHER,J.W. Philiadelphila Electric Co. 88/12/01. 7pp. 47735:009-47735.018
- 8812060320 Informs that l'censee contracted Westingtiouse to provide technical basis for response to Generic Ltr 88-11 & Intends to respond by 890122.Generic ltr discusses implementation of Reg Guide 1.99.

 WECREDY,R.C. Rochester Gas & Electric Corp. GL-98-11, 98/11/29 STAHLE,C. Document Control Branch (Document Control Dask) 1p 47741.063-47741.063
- 8812090036 Responds to Generic Ltr 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Matts & Impact on Plant Operations."

 ALEXICH,MP. Indiane Michigan Power Co. (formerly Indiana & Michigan Electric Co.) GL-88-11. 88/12/05, MURLEY,T.E. Document Control Branch (Document Control Desk). 8pp. 47775:321-47775:351.
- -8812090060 "Assessment of Reg Guide 1.99,Rev 2 Upon D.C. Cook Units 1 & 2 Adjusted Ref Temps & Pressure Temp Curves" IDDINGS,F.A., CROSS,B.T., American Electric Power Service Corp. 88/11/30 23pp. 47775-329-47775-351.
- 8812090090 Responds to Generic Ltr 88-11, "Analysis of Embrilliament of Reactor Vessel Boltline Matls." Impact of Reg Guide 199, Rev 2 on pressure temp limits low temp overpressure protective sulpoints & PTS screening calculations e.c.l. FAY,C.W. Wisconsin Electric Power Co. Gl-86-11, 88/11/29, Document Control Branch (Document Control Desk), 33pp. 47761081-47761:113.
- 8812090164 Forwards Amend 156 to Ucense OPR-49 & safety evaluation Amend revises Tech Specs by changing setpoint for uninterrupt ble ac & instrument ac sys undervoltage refeys to reflect mod of power supplies per Reg Guide 1.97. HALL, J. R. Project Directorate III-3, 88/12/07, LIU,L. Towa Electric Light & Power Co. 3pp. 47781:332-47781:344.
- --8812090167 Amend 158 to License DPR-49,revising Tech Specs by changing set-points for uninterruptible ac & Instrument ac sys undervoltage relays to reflect mod of sys power supplies to conform to Reg Guide 1.97. HANNON,J.N. Project Directorate III-3, 88/12/07, 7pp. 47781:335-47781:341.
- 8812120092 Responds to Generic Ltr 68-11 re Reg Gu'do 1.99,Rev 2, "Radiation Embrittlement of Reactor Vessel Malts." Util plans to submit proposed license amend to extend reactor pressure vessel pressure temp limits beyond 10 EFPYs. BIRD,R G. Boston Edison Co., GL-68-11. 88/12/02. Document Control Branch (Occument Control Desk). 1p. 47792.001-47792:001.
- 8812130001 Responds to NRC 681103 ltr re violations noted in Insp Ropt 50:333/86-17.Corrective actions fuel reloading stopped & critique held when inadvertent red insertion occurred.

 CONVERSE,R.J. New York Power Authority (formerly Power Authority of the State of New York). JAFP-88-1068. 88/12/05. Document Control Branch (Document Control Deak). 4pp. 47792:299-47792-302.
- 8812130091 LER 88-009-00.on 881108,two excore neutron flux monitor cable assembiles falled milg pressure test & developed leaks in cable assembly Affected cable as-sambles repaired & pressure tested to ensure proper qualification W/88 1207 ftr. MCGRATH, S., WHITTIER, D. Maine Yankee Atomic Power Co. MN-88-120. 88/ 12/07. 3pp. 47791:358-47791:360.
- 6812130133 Forwards Safety Insp Repts 50:373/88-27 & 50:374/88-26 on 881017-24 8. notice of violation.

 MILLER, M.J. Region 3, Ofc of the Director. 88/12/05. REED, C. Commonwealth Edison Co. 2pp. 47797:100-47797:115.
- --8812120136 Safety Insp Repts 50:373/86:27 & 60:374/86:26 on 881017-24. Violation noted Major areas inspected plant instrumentation sys for assessing plant conditions during & following accident as specified in Reg Guide 1.97, Rev 2. GARDNER, R.N., GAUTAMA. S. Region 3, Oto of the Director, 50:374/88/26, 88/11/30, 13pp. 47797:103-47797:115.
- 8812130228 Forwards Amend 53 to License NPF-29 & safety evaluation. Amend revises Attachment 1 to OL by extending implementation date for meeting Reg Guide 1.97 recommendations for neutron flux monitoring instrumentation until Aug 1990. KINTNERI,L.L. Project Directorate II-1. TAG 68875, 88/12/06. COTTLE,W.T. System Energy Resources, Inc. 3pp. 47793:079-47793.090.
- --8812130228 Amend 53 to License NPF-29, changing Attachment 1 to OL to extend implementation date for meeting Reg Guide 1.97 recommendations for neutron flux monitoding instrumentation until fourth refueling outage in Aug 1990. ADENSAM,E.G. Project Directorate II-1. 88/12/08. 4pp, 47783:082-47793:085.
- —8812130232 Notice of issuance & availability of Amend 52 to License NPF-29.Amend changes Attachment 1 to OL to extend implementation date for meeting Reg Guide 1.97 recommendations for neutron flux monitoring instrumentation. ADENSAM,E.G. Project Directorate II-1. 88/12/06. 2pp. 47793:089-47793:090.
- 3812140176 Responds to Generic Lir 88-11, "NRC Position on Radiation Embrittlement of Reactor Vessel Matts & Impact on Plant Operations" to comply w/Rev 2 to Reg Guide 1.99. Neutron dosimater will be removed during first refuelling outage. HOLT 25CHER.D.L. Wirnois Power Co. Gt. 68-11. 89/12/05. Document Control Branch (Document Control Desk). 3pp. 47800.201-47800.203.

- 8812150184 Comments on second proposed Rev 1 to Reg Guide 7.8 "Load Commations for Structural Analysis of Shopping Casks for Redunctive Mail." Glad should be expanded to include addictition from IAEA 1985 Ed. ton Safety Series 6 regulators GRICLEY,R. Tennessee Valley Authority 88/12/12, Office of Actinic station & Fe sources Management, Orector (Post 870413). 4pp. 47826:266-47826.239
- 8812190061 Responds to Generic Ltr 88-11 re reevaluation of effects of radiation or reactor vessel mails Util in process of updating Tech SPocs based on Reg Guita 1.99 Rev 2 to be effective through 10 EFPY.

 MEDFORD,M.O. Southern California Edison Co. GL-88-11, 88/12/12 Document Control Branch (Document Control Desk). 2pp. 47840,189-47840,190
- 8812190248 Forwards response to Generic Ltr 88-11, "NRC Position on Radiation Embritionment of Reactor Vessel Matis & Impact on Plant Operations," presented in Ris Guide 1.99 flev 2. Subj. reg guide not directly applicable to facility.

 MILLIAMS, R.O. Public Sorvice Co. of Colorado GL.88-11, 88/12/07. Document Control Branch (Document Control Desk), 11pp. 47849-055-47849-065.
- 8812190343 Forwards Salety Insp Ropts 50-254/88-27 & 50-265/88-28 on 861114 1213 & notice of violation
 MILLER, H.J. Region 3, Oic of the Director. 88/12/13. REED, C. Commor west's
 Edison Co. 2pp. 47855 029-47855:043
- ~8812190350 htsp: Repts: 50-254/88-27 & 50-265/88-28 on 8811114-1213 We above noted. Mejor areas inspected instrumentation sys for assessing plant conducts defining accident & icensee action on proviously identified 10CFR50491-13ing GAUTAMA S. GARONER, R.N. Region 3, Ofc of the Director 50-265/8824 88/12/13, 12pp. 47855:032-47855.043
- 8812190377 Responds to Generic Ltr 88:11 re calculation of pressure: temp curves using equations presented in Reg Guide 1.99.Rev 2.Technical evaluation performed & naw pressure-temp curves developed as result of analysis Technical evaluation and KEISERJEW. Pennsylvania Power & Light Co. GL-98-11. 88/12/12. BUTLER_WA Project Directorate I-2. 40pp. 47849.093-47849.132.
- 8812200232 Advises that 881014 Rev 88-2 to radiological emergency plan consistent w/planning side of 10CFR50.47(b) & acceptable. Change re motion/degleal coupment not consistent w/Rog Guide 1.23. DECKER, F.R. Rejon 2, Old of the Director, 88/12/12, TUCKER, H.B. Direc Power Co 2pp. 47868:302-47868:303.
- 8812210005 Summary of 881013 meeting w/util re long-standing safety issues not sing Generic Ltr 83-28 Items,SPDS,Rog Gurde 1.97 safety evaluation open trans 8 1M. Action Item II.K.2.16.
 HARBUCK,C.C. Project Directorato IV. GL-83-28. 88/12/13. CAMPBECL,T.G. Alkarsas Power & Light Co. 17pp. 47889.035-47889.051.
- 8812210265 Forwards results of analysis done for 16 EFPY of operation for reactor vessel matts per Rev 2 to Reg Guide 1.90 & Generic Ltr 88-11. Changes ret collusers to cation-specific fluences in reovaluating adjusted ref temps MEDFORD,M.O. Southern California Edison Co. Gt -88-11. 88/12/18 Decument Control Desk). 3pp. 47875:215-47875.217.
- 8812220136 Forwards financial disclosure Info,including 1997 enrural 10 K Stpt. 1958. 10-Q & bit statement of internal cash flow excluding relation openings for 12 months ending Sept. 1989, per 10CFR140.21 & Reg. Guide 8.4. CONWAY,W.F. Florida Power & Light Co. 88/12/14. Document Centrel Brench (Document Centrel Desk). 91pp. 47886:195-47888.285.

REVIEW GRP NAC RESEARCH REVIEW GROUPS

- 8807220389 Notification of 880727 mosting in Rockville,MD to exchange info on find ings of EPRI emergency dieset generator reliability simulation calculations & how find ings relate to resolution of B-56, "Diesel Concretor Rotlability." SERKIC,A.W. Reactor & Plant Safoty Issues Branch. 88/07/20. ROSA,F. KNIG-1T J TONDI,D. Electrical Systems Branch. 2pp. 47924:203-47924:204.
- 8807250041 Notification of 880728 mooting w/NUMARC/NUGSBO working group in Rockville, MD to discuss station blackout rule (10CFR50.63).
 SERKIZ,AW. Reactor & Plant Safety Issues Branch, 88/07/20, ROSA,F. Kr.tGHT,J. GILL, P. Electrical Systems Branch, 1p. 47813 276-47813 276.
- 8911280190 Notification of revised agenda for CRGR 881117 Monting 151. Abornate JORDAN,E.L. Committee to Review Generic Requirements 68/11/15
 BERNERO,R.M. Office of Nuclear Material Safety & Safeguards, DroctivGOLDBERG,J.R. Assistant General Counsel for Enforcement PAPERIELLO,C.J.
 Region 3, Ofc of the Director. 2pp. 47854:027-47654:028.
- 8811290100 Notification of 881130 meeting w/NUMARC working group in Rockello,MO to discuss Tech Spec improvement program.
 REINHART,M. Technical Specifications Branch. 88/11/21 BUTCHER,CJ Technical
- Specifications Branch. 2pp. 47768:001-47768:003. 8811290206 Summary of CRGR Maeting 148 on 881012 re review of limited roy to 10CFR50,App J.of proposed generic litr addressing licensee implementation of SPCS requirements & of proposed generic litr on satisfy-related motor-operated valva bestong JORDAN,E.L. Committee to Review Generic Requirements 88/11/07, STELLO.V. C'c of the Executive Director for Operations. 2pp. 47651:274-47651:275.
- 8811290210 Summary of CRGR Meeting 149 on 881027 re proposed generic itr on SPDS implementation & proposed mode to SRP sections on fission product removal &
- retention.

 JORDAN,E.L. Committee to Review Generic Requirements. 88/11/07. STELLO,V. O'c of the Executive Director for Operations. 2pp. 47850,029-47650,030.
- 8811290224 Forwards final draft NSAC-126, "Guidelines for 10CFR50 59 Safety Evalua-Unitive Manage 88/11/07 ROSSI, C.E. Division of Operational Events Assessment (Post 87941). 1p. 47667:142-47667:191.
- --8811290229 Final draft, "Guidelines for 10CFR50.59 Safety Evaluations."

 Nuclear Management & Resources Council (NUMARC) (formorly Nuclear Ut-Yy Manage. * Electric Power Research Institute. 88/12/31, 49pp. 47667.143-47667.19*.

- 8811300482 Forwards NUMARC responses to comments relemergency diesel genera-
- tor reliability monitoring SERKIZ,A,W. Reactor Plant Safety Issues Branch. 88/11/23. ROSA F. Electrical Systems Branch. FLACK,J. Advanced Reactor & Generic Issue Branch. LOFGHENE V. Science Applications Informational Corp. (formorly Science Applications, Inc.). 2pp. 47681.047-47681.059.
- -8811300489 Forwards responses to NRC comments on EPRI graded approach to monitoring of energency deset generator reliability.per commitment during 881102 meeting Concept of accelerated testing conflicts withilant of reliability based program MARIGNA Nuclear Management & Resources Counci (NUMARC) (formatly Nuclear Unity Manage 88/11/21: SERKIZ.A.W Division of Safety Issue Resolution (Post 850717), https://doi.org/10.1009/10.10
- 8612010003 FO'A request for info re physiological effects of exposure to high levels of ionizing radiation, including radiation induced unjuries suffered by victims of Chernobyl nuclear accident. CHUR Althation Not Assigned 88/11/08. FELTON, J. NRC No Detailed Affiliation Green 1p. 47682:127-47682:127.
- 88 12010005 Final response to FOIA request for Into Computer printout of records availatte in PDR re Chornobyl encl W/o encl GR MSLEY,DH Division of Freedom of Information & Publications Services (Post 863515) 88/11/28 CHIU,R. Affiliation Not Assigned 1p. 47682 128-47682 128
- 8812010074 Summary of NRC 881028 meeting w/NUMARC task group re now STS tor cortleinment sections concerning early astimate of anticipated technical changes. BUTCHERE J. Technical Specifications Branch. 88/11/28. ROSSICE Dwiston of Operational Events Assessment (Post 870411). 5pp. 47703-169-47703-173.
- 8812010234 Forwards into re-defective static eliminators mfg by 3M, including list of 3M 6 Stock of Forwards and to detective stems of minitarias may by sain, including as 5 and districtions outside US REGI 65,316 & 328 encl.
 HAUBER R.D. Assistant Director for International Cooperation. REGI 101, 88/02/12.
 Assistant Director for International Cooperation. 14pp. 47682 093-47682 108.
- 8812010417 Recommends that regions take action similar to Region 3 & also that GPA transmit enclidecuments to Agreement States w/suggestions that they take action similar to Region 3 or flost Po-210 static similaritors mitg by 3M AUSTIN JH. Medical, Academic & Commercial Use Safety Branch 88/11/23 JOYNEH JH Region 1, Otto of the Director FISHER.WIL Region 4, Otc of the Director, 1pp. 47811.318-47812.039.
- -8812140145 Forwards I sting at devices re-brand static eliminators classified as lost duting recall WISSINK,R.G. Minnesota, Mining & Manufacturing Co., 3M Co. 88/10/03. Rogion 3, O'c of the Director, 79pp. 47811:320-47812 038.
- -8105080393 Forwards rept on Intium contamination on 3M static meter Requests
 - menue of ination in nots scheduled insp.

 MEYER,R Radiological Safoty Br,Div of Safoguards & Radiological Safoty Br,Div of Safoguards & October Safoty Br,Div of Safoguards & Radiological Safoty Br,Div of Safoguards & Radiological Safoty Br,Div of Safoguards & Safoty Br,Div of Safoguards & Safoty Br,Div of Safoguards & Safoty Br,Div of Safoty Br 47682 109-47682-116
- -8105080397 Forwards rept on Tritium contemination on 3M static moter. State of CA has been requested to investigate Model 18-2, U. Shepherd irradiator methodic NUSSBAUMER.D.A. Assistant Director for State Agreements Programs REGIV 003 81/03/12 HIGGINBOTHAM,L. Rediological Safety Br.D.v. of Safeguards & Radiological Safety Br.D.v. of Safety Br.D.v
- ~8409180384 Informs of incident involving leakage of several Po-210 static eliminators distributed to general ficensee. Contaminated equipment used during cleanup placed in proper container wilabels & returned to St Paul,MN,Withtoki KUNZRJ, Minnesota, Muring & Manufacturing Co., 3M Co. REGIV 007, 84/09/07, KEPPLERJG, Ofc. of Inspection & Enforcement, Director (820201-870413), 3pp. 47882-117-47892-119.
- ~8812010309 Forwards 3M 881102 ltr ro organizational changes at company. Since proposed order does not sportly organizational structure & names of individuals. It believed to not affect order before Commission.

 THOMPSON

47682:117-47682:119.

- 47662 120 47682:120.
- -8812010320 Advises of organizational changes affecting static & d'ectromagnetic control div at 3M. W SSINK,R.G. WISSINKIRG. Minnesote, Mining & Manufacturing Co., 3M Co. MALLETT, B.S. Rogron 3, Ofc of the Director, 4pp. 47682:121-47682:124-3M Co 88/11/02.
- --8812010417 Recommends that regions take action similar to Region 3 re lost Po-210 static diminators mig by 3M.W/o stated encis
 AUSTIN.J.H. Medical, Academic & Commercial Use Safety Branch. 88/11/23
 JOYNER.J.H. Region 1, Ofc of the Director. CLINE.W.E. Region 2, Ofc of the Director.
 FISHER.W.L. Region 4, Ofc of the Director. 2pp. 47682:125-47682
- -8812140155 Notifies of violation of NRC requirements per 3M 880610 litrie loss of nuclear ionizer Model 902. WIEDEMAN,D.G. Region 3, Old of the Director, 88/10/12, CHESTER,F. Vacuum Orne-Metal Co. 1p. 47812:038-47812:039.
- 8812020227 Urges Commission to act on Citizens for Fair Uni Regulation pelition & deny petition w/o further delay. Served on 881017.
 LEE, B. Nuclear Management & Resources Council (NUMARC) (formerly Nuclear Util by Manage, #488-7257. OL. 88/10/07 ZECH, L.W. Commissioners. 3pp. 47679.349-47679.351.
- 8612050181 Notification of 681202 meeting w/NUMARC in Rockville.MD to discuss proposed methods to develop new STS for RCS & discern proposed technical changes that may require review effort outside new STS review process
 REINHART,M. Technical Specifications Branch. 88/11/29 BUTCHER,E J. Technical Specifications Branch. 2pp. 47731:351-47731:352.
- 8812050105 Notification of 881213 meeting w/NUMARC in Rockvite,MD to discuss NUMARC comments on fitness for duty proposed rule.
 GRIMES,B.K. Division of Roactor Inspection & Saloguards (Post 870411), 88/11/30 McPtEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 4pp 47740.187-47740:190.

- 8812050187 Notification of 891202 maeting w/NUMARC in Rockville MD to discuss pro-posed methods to develop now STS for grant sys & discern proposed Toch Spec changes that may require lewaw often outside now STS review process. REINHART,M Technical Specifications Branch 86/11/29 BUTCHER,E J Technical Specifications Branch 2pp 47740 181-47740.192
- 8812070055 Summary of 881122 meeting w/NUMARC in Rockville,MD ro into exchange on substandard o'ectrical equipment List of attendees & handouts enci.
 STONE_J.C. Project Directorate II-3, 88/11/30. LAINAS,G.C. Region 2, Otc of the Director, 14pp. 47748-098-47748-111.
- 8812070100 Submits comments on NUMARC/Nuclear Safety Analysis Ctr 10CFR50 59 gu Janca documonts per 881117 request.Guldance provided in final draft of NSAC-125 seriously llawed. Documont should be returned w/p NRC endorsement W/p end. VARGA S D. Distion of Reactor Projects - I/II (Post 87041), 88/12/01 ROSS, CE Dws on of Operational Events Assessment (Post 870411), 4pp. 47749:250-47749, 253.
- 8812080074 Summary of 881108 meeting w/NUMARC & EPRI re accident mgt programs List of attendees & related into encl SCLBERGLD. Reactor & Plant Systems Branch 89/12/01. SHOTKIN,L.M. Reactor & Plant Systems Branch 186pb. 47783:192-47783:207.
- 8812090033 Summary of 881020 meeting w/NUMARC in NUMARC writing of new STS for ECCS concerning enticipated technical changes.

 BUTCHERE J. Technical Specifications Branch. 88/12/02. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 7pp. 47775 352-47775 358.
- 8812090063 Summary of 881109 CRGR Meeting 150 In Rockvilla,MD re proposed rule change to 1DCFR72 to provide for storage of spent fuel at power reactors sites & draft SER of 8&W Topical Rept 8AW-10167 & Suppl 1.

 JORDAN,E L Committee to Review Generic Regultements 88/11/23. STELLO,V. Ofc of the Executive Director for Operations. 2pp. 47762:294-47762:295
- 8812130303 Discusses lessons learned from 3M static elimination device case in response to 860609 memorandum. KNAPP, MR Region 4, Off of the Director, 601, 88/06/17, CUNNINGHAM,R E. Division of Industrial & Medical Nuclear Safety (Post 870729), 1p. 47791:180-47791:180.
- 8812130305 Recommends Issuance of notice of violation & transmittal ftr similar to enci-to resolve concerns re-unauthorized disposal of byproduct matticental in 3M static oliminator dovicos acquired under provisions of general license. GROBE, JA Rogion 3, Oto of the Director. SE682, 88/08/05. LIEBERMAN,J. Ofc of Enforcement (Post 870413). 9pp. 47781.171-47791:179.
- 8812180048 Notification of 881108 meeting w/NUMARC in Rockvilla,MD to discuss NRC & industry accidentingt activities & how activities should be coordinated. Agenda
 - LAUBEN,G N. Roactor & Plant Systoms Branch, 88/10/25, SHOTKIN,C.M. Reactor & Plant Systoms Branch, 2pp. 47830;288-47830;289.
- 8812160081 Notification of 881215 & 16 meetings w/NUMARC & EPRI in Rockville,MD to continue axchange of Info re monitoring emergency diesel generator reflability levels & programs currently utilized.
 SERKIZ,A W. Reactor Plant Sately Issues Branch. 88/12/01. BURNS,J. Electrical & Mechanical Engineering Branch (Post 880717). BUTCHER,E. Technical Specifications Branch CHIRAMAI, M. Office for Analysis & Evaluation of Operational Date, Director. 2pp. 47873 226 47873;227.
- 8812190147 Notification of 881216 meeting w/NUMARC STS Improvement coordination group at Westinghouse Owners Group ofc in Rockville,MD to discuss progress on Toch Spec Improvement program.
 8UTCHER,E. J. Technical Specifications Branch. 88/12/12. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 2pp. 47853:253-47853:254.
- 8812190328 Responds to 880719 ltr requesting comment on draft "Interim 3M Lessons Learned" rept.Comments listed.
 KAMMERER.C. State, Local & Indian Tribe Programs. SE680, 88/08/11.
 CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729), 1p.
- 47868 010 47868 010
- 8812190359 Requests that info contained in Incoming 3M 30-day regits of users failing to return Po-210 static elimination devices per NRC 880218 order be monitored & that appropriate agreement states & NRC be notified of user names NUSSBAUMER,D.A. Assistant Director for State Agreements Program. SLITP 04. 687 02/22. ADAM,W. Region 3, Old of the Director. 1p. 47868.001-47868.001.
- 8812200175 Requests NRC expand orders re 3M static eliminators to require 3M to recall all models of static eliminators that pose health risk & in possession of general
 - licenses LASH.T.R. III.nols, State of IP-2. 88/02/18. ZECH,I.,W. Commissioners 2pp. 47874.040-47874.041.
- 8812200221 Advisos 3M brand nuclear static eliminators customers of Po-210 detected in vicin'ty of chemical company (hat used 3M fonizers Requests fonizers returned to 3M for coffection. Credit memo for unexpired portion of leased will be issued. CHOW.T. 3M Far East, Ltd. 1P-5. 88/02/26. LAM.C.K. Affiliation Not Assigned. 1p. 47874:037-47874:037.
- 8812200255 Responds to 880809 memo re Interim 3M lessons learned rept. Manuel chapter should be established describing criteria for conducting major team efforts in response to major problems which cover multiple regulatory jurisdiction. NORELIUS,C.E. Region 3, Otc of the Director. IP-1, 88/06/24, CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 2pp. 47874:038-
- 8812200280 Expresses appreciation for 880321 ltr providing update on 3M static elimi-

47874:039.

- nator problem
 TAM,A. Hong Korg, IP 07, 88/04/08, HAUBER,R.D. Assistant Director for International Cooperation 1p. 47874:030-47874:030.
- 8812200289 Expresses appreciation for 880212 & 19 firs re defective static eliminators mig by 3M Board instructed that 3M should withdraw particular static eliminators from users & conduct random checks on users premises for radiation contamination. TAMA, Hong Kong, IP 06. 88/03/17. HAUSER,R.D. Assistant Director for International Cooperation. 2pp. 47874:035-47874:036.

SIR MONDOCKETED HEWS

- 8812200303 Requests more detailed into re technical analysis & causes of problems on 3M static elimination devices per NRC 880201 into concerning detective devices BREEST Germany, Foderal Republic of IP 04, 88/10/02 HAUBER NRC No Detailed Affidation Green. In 47874:001-47874:001.
- 8812200306 Responds to 880308 lif re 3M static of minators NRC has granted temporary use of devices only where devices considered crucial to worker safety & appropriate redistion surveys & control measures instituted DENTON, H.R. Office of Governmentals & Public Affairs (Post 870413) SUITP 01, 887 04/11, LASH, T.R. Illinois, State of, 1p. 47874 034-47874,034
- 8812200309 Ack receipt of British repl entitled, "Assessment of Hazard to Public From Antistatic Brushes Conteining Po-210 in Form of Coramo Microsphieres." Rept will be useful for reviewing 3M responsiveness on static eliminators. THOMPSON, HL. Office of Nuclear Material Safety & Safeguards, Director. IP 09 887 06/27. DENTON, H.R. Office of Governmental & Public Affairs (Post 870413). To
- 47074:033-47874:033 8812200313 Responds to 880727 ltr re info on regulatory assessment of 3M Incident Informs that comments on rept provided to NMSs for inclusion in NRC 3M rept Additinto on Comment 6 re coordination between NRC 8 FDA requested LUBENAUJU,O. Assistant Director for State Agreements Program SE684, 65/09/09. SHEALY,H G. South Carolina, State of, 1p. 47874 025-37874,025.
- 8812200325 Expresses appreciation for into sent re 3M static eliminators w/Po-210. HANNIBAL,L. Denmark, Goyt. of. SE681, 88/08/16, HAUBER,R.D. Assistant Director for International Cooperation, 3pp. 47874,027-47874;029
- 8812200327 Submits daily man of interest. On 880331, meiling held w/3M re export of 3M Pc-210 static eliminators 3M agreed to NRC issuance of order, effective immediately, under which 3M would not be permitted to export devices under general
- International Programs, IP 10, 88/04/01 International Programs, Ip 47674.032-47874.032.
- 8812200328 Informs that 3M static eliminator devices containing Po-210 w.l be collected by CNEN & stored property.

 DAMASCENO,E. Brazil, Govt. of. IP 08 68/04/30. HAUBER,R. NRC No Detailed Affiliation Given. 1p. 47874-031-47874-031.
- 8812200329 Responds to 880729 fir re info on regulatory assessment of 3M incident.Requests add* info on Comment 8 Lincluding concentration of dissolved Po-210 in wash water,methods of measurement & locations of static of minators LUBENAUJ.O. Assistant Director for State Agreements Program. SE695, 88/09/09 TEDFORD.C.F. Arizons, State of. 1p. 47874.026-47874.026
- 8812200332 Informs that only one case of imported 3M static eliminators discovered according to survey Equipment found faulty & returned to 3M Austin Ctr.USA CARVALTO,A.M. Portugal, Govt. pt. 1973, 88/06/24, HAUBER,R.O. Assistant Director for Informational Cooperation. 1p. 47874:044-47874.044.
- 8812200333 Ack receipt of 880218 itr expressing concerns & recommendations re 3M Po-210 static eliminators NRC issued order modifying 3M licenses to suspend use of devices.
 DENTON,H R. Office of Governmental & Public Affairs (Post 870413). SLITP 02. 88/03/23. LASH,T.R. Illinois, State of. 1p. 47874.002-47874.024.
- -8812200350 Forwards orders suspending 3M authority to transfer Po-210 static elimination devices to general licensees & modifying general license,per 10CFR31.5,to suspend use of devices NUSSBAUMER,D.A. Assistant Director for State Agreements Program. 88/02/19. General. 2pp. 47874.003-47874.024.
- 8812200382 Forwards copyrighted United Kingdom Natl Radiological Protection Board Rept NRP8-R36, "Assessment of Hazard to Public from Anti-Static Brushes Containing Po-210 in Form of Caramic Microspheres," did Aug 1975. DENTON,H-R. Office of Governmental & Public Affairs (Post 870413). SE605. 88/08/17. THOMPSON,H-L. Office of Nuclear Material Safety & Safeguards,Director. 1p. 47874:042-47874:043.
- 8812220181 Advises that CRGR Meeting 152 will be he'd on 881214 Agenda listed.
 JORDAN,E.L. Committee to Review Generic Requirements. 88/12/07.
 BERNERO,R.M. Office of Nuclear Material Selety & Safeguards, Director.
 GOLDBERG,J.R. Assistant General Counsel for Enforcement. PAPERIELLO,C.J.
 Region 3, Ofc of the Director. 2pp. 47914 223-47914;224.

SECY POSITION PAPERS BEFORE THE COMMISSION

- 8804120011 SECY-88:083 Recommends that Commission approve for publication in FR, proposed amends to 10CFR40 for general licenses for custody & long-term care of U mill tallings sites Related Info encl. STELLOV, Ofic of the Executive Director for Operations. AC58-1 16. 88/03/17. 54pp. 47520:058-47520:101.
- 881280026 SECY-88-039C Provides Commission w/Querterly Progress Rept for Aug-Oct 1988 on pre-ticensing phase of DOE civilian high level redwaste mgt program. STELLOV. Ofc of the Executive Director for Operations. 88/11/16, 31pp. 47710.031-
- 8812010056 Forwards SECY-88-039C, "Quarterly Progress Rept on Prelicensing Phase of US DOE Civilian High Levet Radwaste MgI Program," to be placed in PBR 8ATES A. Operations Branch. 88/11/28. SHELBURNE,B. Public Occument Branch. 1p. 47710.030-47710.081.
- 8812050277 Final response to FOIA request for documents.Forwards App A & B documents.App B documents partially withheld (ref FOIA Exemption 5).Documents also available in PDR.
 GHIMSLEY,DH. Division of Freedom of Information & Publications Services (Post 880515). 88/11/29. FELTON,J.M. Nuclear Licensing Reports. 4pp. 47729.026-4729.0328
- --8811040189 SECY-88-284 Requests Commission approval of format & schedule for Price-Anderson negotiated rulemaking. PARLER,W.C. Office of the General Counsel. 88/10/05, 20pp. 47729-052-47729.071.

- 88 12120159 Final response to FOIA request for documents Forwards releasable por tions of App. A documents (ref. FOIA Exemption 5). App. B documents talaly with visite (ref. FOIA Exemption 5).
 PHILIPJ. NRC No Dotated Attiliation Given 88/12/09, KUPERMAN A.J. Nutrie Control Institute, 4pp. 47836 333-47836.344
- -8812129162 SECY-86-101A Partially deleted Commission paper advising Commission of receipt of additional igence into 8 corresponding change in stell recommendation per SECY-86-101.
 STELLOV Ofc of the Executive Director for Operations 86/06/12 4pc, 47936-331. 47836-338
- ~8812140224 SECY-88-127 Partially deleted Commission paper providing Commission w/ range of options for consideration re-contingency planning to confluence possible surface vehicle threat
 STELLO,V. Oic of the Executive Director for Operations, 88/05/10, 4pp, 47836,375 47838 344
- 8812120169 Final response to FOIA request for documents Forwards parisity decress App A document sub; to Category 4 of request (ref FOIA Exemption 5) No records sub) to Categories 1,2 & 3 of request located GRIMSEEV, D.H. Division of Freedom of Information & Publications Services (Post 880515) 88/12/09. KUPERMAN, A.J. Nuclear Control Institute, 3pp. 47836-322-47896-320 47838 330
- -8812140222 SECY-88-302 Partially deleted Commission paper Informing Commission of staff conclusion about Murkowski amond requirements, or discussions wheapaness 8 initial stops in implementing amend.
 STELLO.V. Old of the Executive Director for Operations 88/10/25 5pp. 47836 325
- 8812290228 Final response to FOIA request for documents Forward. App A documents App A documents also available in PDR PHILIP.1, Dwiston of Freedom of Information & Publications Services (Post 880515) 88/12/27, PICKETT,E H. Newman & Holtzinger, 2pp. 47975-138-47975-277.
- ~8611170087 SECY-86-323 Informs Commission of evaluation of possible approaches to ficensing geologic repository for disposal of high level waste PARLEA, W.C. Office of the General Course. STELLOV Ofc of the Executive O
- 8812290266 Final response to FOIA request for documents.Forwards App. 8.8.2 documents.App. A. 8.8 available in PDR.App. C. 8. D. pathally 8. totally withhelid,respectively (ref.FOIA Exemptions 8.8.5, respectively). GRIMSEEV, D.H. Division of Freedom of Information 8. Publications. Services. (Foot. 880515), 88712720. HIATT, S. Ohio Citizens for Responsible Energy. 8pp. 47562-155-47682-237.
- --8809040334 SECY-88-243 Proposed change to procedures for providing legal review of 2,200 decisions at staff & Commission level Each Commission of ewicontinue to receive 2,206 decisions & secretary will track decisions to ensure views of Secretary W.C. Office of the General Counsel 2,206 86/09/19, 5pt. 47362-224-47982 232

STATE PROG STATE PROGRAMS

- 8911220017 Requests permission for disposal of expired potassium locide stockpule in Summit Landfull Special waste data collection form & stated data sheet for tablets
 - encl. SCHMIERBACH,M. Tonnessee Valley Authority. 86/10/26 MOOSE,G.M. Tornessee. State of 8pp. 47663-054-47863-082.
- 8811290187 Forwards comments on 880610 Nuclear Waste Project Oto OA Manua ซี ข้ 880810 re statement of OA Policy,QA Program, QA Procedures & glossary of dicfine
- LINEHAN.J.J. Repository Liconsing Project Directorate (881013-981119), 58/11/25 LOUX,R.R. Nevada, State of, 10pp. 47851.102-47851:111.
- 8811300451 Expresses appreciation for time taken to comment on advanced LWR ucl requirements document executive summary.

 BERKOW,H.N. Standardization & Non-Power Reactor Project Directorate. 87/06/05

 JAGER,L.E. Michigan, State of. 2pp. 47680.216-47880.217.
- 8812010163 Comment supporting proposed rule 10CFR140 re negotiated rulemaking for indemnification of medical licensees under Price Anderson Act Supports extension of Act to Include medical licensees. BORCHERT,H.R. Nebraska, Stale of. 53FR40233 00007, 88/11/17 Docketing & Services Branch 1p. 47679.063-47679.063.
- 8812010389 Confirms discussion w/J Hornor on 881028 following NRC review of State of WA radiation control program Program for regulating agreement matte adequate to protect public health & safety & compatible w/Commission program. KAMMERER,C. State, Local & Indian Tribe Programs. 88/11/25. ROLFS,R 9. Westington, State of, 7pp. 47703:184-47703:200.
- 8912020012 Responds to 881124 ltr re restant of Pilgrim Nuclear Power Station Notification of 881209 meeting in Rockville MD restatus of emergency planning zone & reception ctr communities re public protection.
 - ZECH.L. Commissioners. 88/11/28. KIRBY,E.P. Massachusetts, Commonwealth of 7pp. 47717:198-47717:204.
- -8812020014 Requests withhold of approval of operation at Pilgrim Nuclear generating plant. kIRBY,E.P. Massachusetts, Commonwealth of 88/10/24, ZECH,L. Commissioners. 2pp. 47717:203-47717:204.
- 8812020171 Forwards commonts on "Rept on Progress Made in Emergency Planting for Response to Accident at Pilgrim Nuclear Power Station." Comments not intended to be critical of Commonwealth concerns but explain basis of NRC position. STELLOV. Ofte of the Executive Director for Operations, 88/11/30. BARRY.C.V. Massachusetts, Commonwealth of, 10pp, 47707-265-47708-041.

219

- -6812020175 "Ropt on Progress Made in Emergency Planning for Response to Accident at Pilgrim Nuclear Power Station"

 BARBY C.V. Massachusells, Commonwealth of 88/10/11 115pp 47707:287-47708 041
- 8812050278 Appeals denial of FOIA request for documents containing predecisional advise between Commissioners & staff Documents do not contain adjudication, ruling or other decision of Commission.

RI-CCES J. Pennsylvania, Commonwealth of 88/10/24 NRC - No Detailed Affiliation Given, 1p. 47729 187-47729,187

- 8812080503 Forwards safety evaluation supporting Amend 63 to License DPR-75 re accelerated steam generator habit insps Unit will have to comply w/Toch Spec 4.4.6.3.6 & increase steam generator insp frequency to max 20 months for facility STONE.J.C. Project Directorate 1-2, TAC 71117, 88/12/05, NICHOLLS,G.P. New Jersey, State of, 5pp. 47754:134-47754 (43)
- 8812080108 Notification of 881215-18 miceting wt/DDE, affected local govts. 8. State of MV 15 discuss Italical aspects of study plans for site uttaracterization, including access & purpose QA condoms & DDE & NRC processes for review.

 STABLEN K. Repository Licensing Project Directorate (881013-881110). 88712701. LINETANUU Repository Licensing Project Directorate (881013-881119). 1p. 47754-677-64-7754-677-64-7754-677-64-7754-677-64-7754-677-64-7754-677-64-7754-677-64-7754-677-64-7754-677-64-7754-677-64-7754-677-64-7754-677-64-7754-677-64-7754-677-64-7754-677-64-77-47754 079 47754 079
- 8812660134 Requests notification of any public moutings to be hold on nuclear plant license renewal,por NUREG-1317, "Regulatory Options for Nuclear Plant License Re-

HAAG,F.G. Now York, State of 53FR32919 88/10/11 Docketing & Services Branch 'p 47753:110-47753.110.

- 8812120023 Forwards response to Issues raised in request,per HL Thompson 681026
- response to request CUNNINGFAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 83/11/30 BARNETT,J.R. Oklahoma, State of 4pp. 47780-107-47780.110.
- 8812130253 Ack receipt of 801104 ftr re-dept of health svcs actions, per NRC appraisal findings SCARANO,R A Region 5, Ofc of the Director, 88/12/05, KIZER,K.W. California, State of, 3pp. 47797-230-47797-235
- -8812130255 Ack receipt of 881012 ltr ro NRC appraisal of activities performed by CA
- dept of health sycs R/2ER,K W. Calfornia, State of, NRC-32-83-684-88/11/04, SCARANO,R A. Region 5, OK of the Director, 3pp. 47797:233-47797:235
- 8812140160 Ack recept of 881011 ftr re Massachusetts Public Interest Research Group rept actressing mgt issues.Concludes that rept contains no new info to reconsider previous conclusions drawn in Decision DD-88-16 MURLEY, I.E. Office of Nuclear Reactor Regulation, Director (Post 870411). DD 88-16, 88/11/18. GOLDEN,W.B. Massachusetts, Commonweelth of, 8pp. 47821:127-47831-16.
- 8812190196 Forwards updated FSAR for Byron Station Units 1 & 2 & Braidwood Station Lnits 1 & 2. HUYSAOER,S.C. Commonwealth Edison Co. 88/12/14. MURLEY,T.E. Office of Nuclear Regulation, Director (Post 876411). 2pp. 47980-001-47889:156.
- -8812190345 "Observations Mode By State of It. Geological Survey Staff During Visit to Praktiwood Site on 7603+1."
 "Illinois, State of 77703708, 3pp. 47993.091-47903.093
- 8812190349 * Onsite Water Wall Borcholo Log."
 TREWORGY, J.D. Idrools, State of: 77704711, 3pp. 47993.097-47993.090.
- 89.12200306 Responds to 680308 ftr re 3M static of ministers NRC has granted temporary use of devices only whore dovices considered crucial to worker safety & appropriate radiation surveys & control measures instituted DENTON-H-TL Office of Governmental & Public Affairs (Post 870413). SUITP 01: 68/64/11. LASTI,T.R. Hinois, State of, 1p. 478/4-034-47874-034.
- 8812200313 Responds to 880727 lift to into on regulatory assessment of 3M incident. Informs that comments on rept provided to NMSS for inclusion in NRC 3M rept Addition on Comment 6 re-coordination between NRC 8 FDA requested. LU3ENAU, J.O. Assistant Director for State Agreements Program SE684. 88/09/09 ShEALY, H.G. South Carolina, State of. 1p. 47874.025-47874.025
- 8812200329 Responds to 680729 ftr re-Into-on-regulatory assessment of 3M incident Requests additinfolon Comment 6.1,Including concentration of dissolved Po-210 at wash water,methods of measurement & locations of static eliminators, LUGENALL, O. Assistant Director for Stato Agrooments Program SE685, 68/09/09, TEOFORO, C.F. Arizona, Stato 6. 1p. 47874.026-47874.026.
- 8912200333 Ack receipt of 880216 fir expressing concorns & recommendations to 3M Po-210 static oliminators NRC issued order modifying 3M licenses to suspend use of DENTON, H. R. Ott.co of Governmental & Public Attains (Post 970413), SLITP 02, 897 03723, LASH, T.R. Illinois, State of, 1p. 47874-002-47874-024.
- ≈8812200350 Forwards orders suspending 3M authority to transfer Po-210 static climinallon devices to general licensees & modifying general license,per 10CFR315,to suspend use of devices.
 NUSSBAUMFEI,DA Assistant Director for State Agreements Program 88/02/19. General, 2pp. 47874:003-47874.024.
- 8612210159 Advises that fisted guestions & recommendations must be addressed
- before 80901 discharge plan can be approved, including summary of public participa-fon & afforts to inform public of operation LAMBERT,K. New Mexico, State of. 68/12/01. PELIZZA,M.S. Hydro Resources, Inc. 3pp. 47892 031-47882 033.
- 8812210348 Requests review of encl draft paraul NE0122611 relicensee 871107 appli cation for paint for in situ mining in Dawes County Comments & responses requested by first wk of January. GIDLEY, W.C. Nebtaske, State of: 88/11/30, KONWINSKI,G. Uranium Recovery Field Ok., R4. 37pp. 47881:231-47881:287.

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

- 8809130261 Forwards Roy 0 to "Topical SAR for CASTOR X Cask for ISFSI (Dry Sterage)." for review Wide onci. ANDERSCN.R.T. General Nucles: Systems, Inc. 24470-88/07/01. ROUSE, L.C. Fuel Cycle Safety Branch. 2pp. 46826.040-46826.041.
- 8809130261 Forwards Rev 0 to "Topical SAR for CASTOR X Cask for ISFSI (Dry Storage)," for review. ANDERSON,R.T. General Nuclear Systems, Inc. 24470, 80/07/01, ROUSE,L.C. Fuel Cycle Safety Brench, 4pp. 47759 196-47761 065
- -8812080072 Samilted version of Rev 0 to 1 Topical SAR for Caster X Cask for ISFSI
- (Dry Storage) "
 Gonerat Nuclear Systems, Inc. 89/08/30 586pp. 47759 200-47761:085 8811220017 Requests permission for disposal of expired potassium todide stockpile in Summit Landilli Special waste data collection form & stated data shoot for tablets
- SCHMIERBACH,M. Tennossee Valley Authority, 88/10/26, MOOSE,G.M. Tennessee, State of 9pp. 47693:054-47663:062
- 8811230214 Provides comments on draft NRC bulletin on molded case circust breakers, did 881012 More appropriate time frame for purchase records reviewed by sicensees would be 3 yrs & adequacy of testing should be endorsed by industry MARRIOTT, P.W. Genoral Fectic Co. MTK88-69, 867-10728 GRIMES, B.K. Division of Reactor Inspection & Safeguards (Post 870411), 4pp. 47641 272-47641:275
- 8011280038 Forwards Sept 1988 update of portions of 88W Owners Group "Recommendation Tracking Sys Rept," applicable to safety & performance improvement pro-
- MUTHERFORD, N.A. Babcock & Wilcox Operators Plants Owners Group, OG-316, 867-10/18 CRUTCHFIELD, D. Associate Director for Projects (Post 870411) 6pp. 47656 0 19 47656 297
- -8811280040 47-1169743-17 *Recommendation Tracking Sys Rept **
 * Babbook & Wilcox Operating Plants Owners Group, 88709730 274pp. 47656.02547656.207
- 8811280108 Forwards Rev 0 to WCAP-11816, "Loss of RHR Sys Cooling Winta RCS Partially Filled," per Generic Lir 87-12.Rept describes results of Ruid sys evaluations performed to provide analytical into replanamena of air ingestion into RHR sys. NEWTON.R.A. Westinghouse Operating Plants Owners Group, OG-86-41, 86/11/21, HODGES,M.W. Reactor Systems Branch, 2pp. 47654;326-47656, 266.
- --8811280117 WCAP-11918 R03 "Loss of RHR Sys Cooling White RCS Partially Filled." ANDIREYCHEK, T.S., DUDEK, D.F., FRANTZ, E.R.: Westinghouse Electric Corp. 88/07/31, 299pp. 47654 328-47655-268.
- 8811290147 Forwards proprintary responses to NRC queutions to mothedology to analyze SRP Chapter 16 events for PWris Ropt withhold (ref 10CFR2.780). COPELAND,R.A. Advanced Nuclear Fuels Corp. (formarly Exxon Nuclear Co., Inc.). RAC 054,98. 08714 6. Office of Nuclear Reactor Regulation, Director (Post 8704.11).
- 8811290228 Forwards proprietary Addends 2-P to CF.N.320-P, "Steam Generator Tube Roper Using Loak Tight Sleeves," for review to establish use of periphoral sleeves Rept withhold (red 10CFR2 790(b)(4)). MECREDY,R.C. Rochester Gas & Electine Corp. 99/11/18 STAHLE,C. Project Directorale I-1. 5pp 47668.070-47668 074.
- 8811290250 Forwards proprietary & nonproprietary D.EVR/RED-1-NP.A.& D.EVR/HED-1-NP.A. "Topical Rept for Enhanced Vol. Reduction/ Heat Enhanced Dewatering Systor Treatment of Nuclear Power Reactor Waste Lindds." LESTERW. Duratok Corp. 88/11/14. NCRIBERG.J.A. Division of Engineering & Systems Technology (Post 870411). 1p. 47667:257-47068-041.
- -8811290301 "Topical Rept for Enhanced Vol Reduction/Hoat Enhanced Dowatering Sys for Treatment of Nuclear Power Reactor Waste Liquids." "Duratic Corp. 68/11/14. 127pp. 47667-258-47668-0-1.
- 8811290468 Forwards Rev 1 to Part 2 of "C-6 Nuclear Fuel Integrated Improvemen Progem," w/status of commitments as of 881024. SCHERER, 4. E. Combuston Engineering, Inc. CAL-88-23, 88/11/09, RUSSELL, W.T. Region 1, Otc of the Director, 97pp. 47663;186-47663;282
- 8811300033 Part 21 rept re potentially defective intercooler inter adaption installation Encl Svolato Mama 365, Rev 2, sont to all attacted sites GUNTRUM, BC IMO Delaval, Inc. PT21 89-114-000, 687-1171, Office of Nuclear Reactor Regulation, Director (Post 870411), 10pp. 47697;114-47897;124.
- 8811300101 Forwards Westinghouse, C.E. & B&W Owners Groups draft use & application chapters of proposed new STS.

 RUSSI, C.E. Division of Operational Events Assessment (Post 670411) 88/11/23

 VARGA, S.A. Division of Reactor Projects I/II (Post 870411), HOLAHAN, G.M. Division of Reactor Projects IIII. V.V. & Special Projects (Post 670411), SHAOL, Division of Engineering & Systems Technology (Post 870411), 31pp. 47671:058-47671:170.
- -8812050271 Draft "C-E Owners Group Rustructured STS Front Mater & Use & Appli
- cations Div 1."

 * C.E. Operating Plants Owners Group, 88/10/30, 56pp. 47671.089-47671:145
- -8612050264 Draft 0 to "Chapter 1 Revised Tech Spec"

 * Baboock & Wilcox Operating Plants Owners Group 68/11/30, 25pp. 476/1-146
- 8811300238 Natification of 831130 meeting w/CE in Rockville,MD to present fus design criteria for future liconsing applications WU,S.I. Reactor Systems Branch 88/11/22 HODGES,M.W. Reactor System Branch. 2pp. 47676:122-47676.123.
- 8811300584 Discusses NRC concerns relfailures of Westinghouse circuit breakers du to tack of QC MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411): 88/11 22 CASO,C.L. Westinghouse Electric Corp. 4pp. 47696 273-47696 276

MONDOCKETED TEMS

- 8812020200 Forwards prophetary response to request for additinte rai Topical Hept BAW-10169P, FRSG Plant Safety Analysis " TAYLORJIH Balcock & Wicox Co. JHT/88-214, 88/317/23 NORBERG J.A. Duysion of Engineering & Systems Technology (Post 870411), 1p. 47707,172-47707 172.
- 8812080052 Forwards proprietary ECE-38 (988, "Source Range Monitor Count Rate vs S/N Ratio for Peach Bottom Units 2 & 3" & ECE-44-1088, "Source Range Monitor ." in support of 891021 application Affidavit oncl Repts withheld (ref. 10CFR2 790) HUNGER, GA. Philade Phila Electric Co. 88/11/30 MARTIN, R.E. Project Broctorate (-2 5pp. 47743 007-47743 011.
- 8812060335 Forwards Amend 9 to License NPF-36 & safety evaluation Amend revises Attachment 3 to plant license relimant & surveillance for TDI emorgency diesel gen-8/411/98 BUTLER, W.R. Project Directorale (-2 TAC 65506, 68/11/30 LEONARD, J.D. Long Island Lighting Co. 5pp. 47744 341-47744 359
- -8812080338 Amend 8 to License NPF-36,revising Attachinent 3 to plant I cense remaint & survivillance program for TDI diasol generators BUTLER,W.R. Project Directorate I-2 88/11/30, 9pp. 47744:347-47744:355
- 8812060340 Safety evaluation supporting Amend 9 to License NPF-36
 Office of Nuclear Reactor Regulation, Director (Post 670411). 88/11/30. 3pp 47744;356-47744-358
- 8812070984 Application for amend to License NPF-A supporting operation w/revised heatup & cooldown curves varid to 10 EFPY, WCAP-11791, "North Anna Unit 1 Reactor Vessel Heatup & Cooldown Limit Curves for Normal Operation," enci Fee paid CARTYRIGHT, W.R. Virging Power (Virging Efection & Power Co.) 88-2024 68/11/30. Document Control Branch (Document Control Desk) 3pp. 47748 187-47748 275
- --8812070182 WCAP-11781 "North Anna Unit 1 Reactor Vessel Heating & Cooldown Limit Curves for Normal Operation."
 SCHMERTZ, JC., YAN'CHKO, SE., PALUSAMY, S.S. Westinghouse Electric Corp. 88/ 05/31. 38pp. 47748 240 47748 275
- 8812070127 Notification of 881122 meeting w/GE & BWR Owners Group in Rocky, lie MD for GE presentation of preliminary results of 8WR inschafon calcula-RICHINGS,H. Reactor Systems Brench, 88/11/18. HODGES,M.W. Reactor Systems Brench, 2pp. 47750-082-47750-083.
- 8812070217 Summanzes 881025 meeting w/BWR Owners Group re Target Rock 2 stage salety/relief valve setpolar drilf Attondees ist & handout erct. CHERNY,F.C. Engineering Issues Branch 489/11/29, BAER,R. Engineering Issues Branch 41pp. 47757037-47757077.
- 6812080056 Forwards Rev 1 to nonpreprietary RDS-25505-01-NP-A & proprietary RDS-25505-01-P-A, "RDS-1000 Radwaste Dewatering Sys," topical repts Rev 1 acceptable for rat in future licensing actions Proprietary rept with
- -8812080060 RDS-25566-01-AP-A R1 Nonproprietary Rev 1 to "RDS-1000 Radwaste
- Dewatering Sys "
 Chem Nuclear Systems, Inc. 68/03/31, 72pp. 47763 002-47763 092.
- 8812080186 Summary of 880929 meeting w/B&W Owners Group re-thermal stratifica-tion in pressurizor surgo line Viowgraphs & list of attendees end CHAN,T.L. Project Directorate V 88/11/16 Project Directorate V 30pp 47754 050-47754:077.
- 8812090082 Forwards NNFO Rev 2 to "Nuclear Salety Performance Improvement TETRAULT,R.E. Bebcock & Wilcox Co. 88-212 88/11/28 EFINST,M.L. Region 2, Ofc of the Director 1p. 47784-331-47784-338
- -8812090086 Rev 2 of NNFD "Nuclear Safety Performance Interovement Plan"
 * Babcock & Wilcox Co. 88/11/28 Spp. 47784 332-47784 336.
- 8812090281 Forwards proprietary Addendum 2 to Rev 1 to WCAP-10924.P. 8 nonproprietary WCAP-12071, "Westinghouse Large Break LOCA Bost Estimate Methodology," In support of 880826 request for Tech Specichange Proprietary rept withhold (ref 10CFR2.790).
 FAY,C.W. Wisconsin Electric Power Co. VPNFD-88-581, 88711730. Document Control Branch (Document Control Desk). 3pp. 47781:121-47781.327.
- ---8812090285 WCAP-12071 V02 ADD02 Addendum 2 to Vol 2 to WCAP-12071, "Wes-tinghouse Large-Break LOCA Bost Estimate Methodology,Vol 2: Application to Two-Loop PWRs Equipped W/Upper Plenum Injection,Addendum 2: PBNP Piant Specific
- Analys 3.
 DEDERER, S.I., HOCHREITER, L.E., SCHWARZ, W.R. Westinghouse Electric Corp. 68/12/31. 183pp 47781:145-47781.327.
- 8812120127 Application for amend to License NPF-29,revising Tech Spec to support Cycle 4 refoad for fac-try-Fee paid Repts to refoad forwarded.ANF-88-183(P) withheld COTTLE.W.T. System Energy Resources, Inc. AECM-88/1024. 88/12/06. Occument Control Branch (Document Control Desk). 12pp. 47787:200-47788:005
- -8812120145 ANF-88-149 "Grand Gulf Unit 1 Cycle 4 Reload Analysis"
 REYNOLOS,R S., GRUMMER,R.G. Advanced Nuclear Fuels Corp. (formetly Exxon Nuclear Co., Inc.) 88/11/11, 45pp. 47787.287-47787.311.
- --8812120147 ANF-98-150 "Grand Gu't Unit 1 Cycle 4 Plant Transient Analysis."
 REYNOLDS.R.S. Advanced Nuclear Fuels Corp. (formerly Exxon Nuclear Co., Inc.)
 88/11/11. 40pp. 47787.312-47787.351.
- 8812130031 Summary of 880930 meeting w/C-E Owners Group re thermal stratification in pressurizer surge line.
 CHAN,T.L. Project Directorate V. 89/11/18. Project Directorate V. 9pp. 47793 091-47793:099
- 8812140010 Provides into re history & resolution of discrepancy concerning 100% rated thermal power level parameter used in BAW-10015, "Multinode Analysis of Small Breaks for B&W 177- Fuel Assembly Nuclear Plants W/Raised Loop Arrangement..." SHELTON,D.C. Toledo Edison Co. 1612, 88/12/05, Document Control Branch (Document Control Desk), 3pp. 47799.298-47799.298.

- 8812150086 Requests that Bouing Water Reactor Owners Group not be pressed in commitment to ATWS diversity discussions until analysis results reviewed life story in early 1989 recommended to discuss issue in more details. GRACE,DIN BWR Owners Group BWRICG-9887 88/12/08 MIRAGUAF Associate Director for Projects (Post 870411), 2pp. 47873,214-47873,215.
- 8812160092 Application for amond to License DPR-36.consisting of Proposed Crinise 145 to combined Ineatip.cooldown.proseure & temp limitations Fee paid RNNDAZAJ B Man Yankse North Combined Best 12/02 December Co. MN 88-116-68-12/02 December Control Branch (Document Control Dosk). 9pp. 47806-330-47807-180
- -8812150107 "Summary of Fast Neutron Exposure Evaluations for Maine Yar Yes Reactor Pressuro Vossel."

 ANDERSON,S.L., LIPPINCOTT,E.P., LAU,F.L. Westinghouse Electric Corp. ##152-116.86/11/30.81pp. 47807:001-47807:082.
- 8812150147 Forwards propriotary supplemental info re response to NEC 681109 G.83 ion 8 on NUI-IOMS-24P Topical Root NUH-002 Info withheld (ref 10CFR2 790). MCCONAGHY,W.J. NUTECH Engineers, Inc. DUK-03-319 88712701. ROBERTS JF Fuel Cycle Satoty Branch. 5pp. 47833 001-47833.005.
- 8612150268 Forwards proprietary WCAP-11594 & comproprietary WCAP-11535 1W:5 illighouse improved Thermal Design Procedure Instrument Uncertainty Calculations for Dable Cangon Units 1 & 2" & application for withholding proprietary are SHIFFER, J.D. Pacific Gas & Electric Co. DCL-88-296 88/12/09 Deciment Control Branch (Document Control Desk). 3pp. 47816;297-47816;354.
- --8812150289 Application for withholding proprietary WCAP-11594, "West highouse in-proved Thormal Design Procedure Instrument Uncertainty Calculations for ⊃abor Canyon Units 1-8-2." WIESEMANNIR A Woslinghouse Electric Corp. CAW-89-128-88/11/17 Office of the clear Reactor Regulation, Director (Post 870411), 10pp, 47816-300-47816-300
- -8812160270 WCAP-11595 "Westinghouse Improved Thermal Dosign Procedure Insta-ment Uncertaintly Calculations for Diable Canyon Units 1-8-2." TULEY,C.R. Westinghouse Electric Corp. 87/09/30 | 44pp | 47816-310-47016, 354
- 8812160014 Forwards propriotary WCAP-11312.Hev 1-8 monproprietary WCAP-11966 "Westinghouse Owners Group Tech Spec Subcommittee Reactor Frip Breaker Miller Surveillance Opinitzation ..." WCAP-1312.Rev 1 withhold (ref 10CFH2795) SHIFFER J.D. Pacific Gas & Becterio Co. DCL-88-303-88/12/12 Decement Co. Branch (Document Control Dosk) 3pp. 47834:276-47834,336
- -8812160018 WCAP-11865 "Wostinghouse Owners Group Toth Spic Subcomming Reactor Trip Breaker Maint/Survollance Optimization Program." MCCUTCHAN,D.A., PEFFER,D.R., MAGUIRE,H. Wostinghouse Electric Corp. 68710. 31 49pp 47834 289 47834 336
- 8812160037 Forwards safety evaluation accepting NEOC 30936P, Threewort RWT Owners Group Tuch Specs Improvement (W/Demonstration for BWH ECCS Actions Instrumentation) Part 2.1 Rept provides acceptable basis for extending survey level test Intervals ROSSI,C.E. D.vision of Operational Events Assessment (Past 670411) 60.712769 GRACE,D.N. BWR Owners Group, 2pp. 47809 071 47609 124
- -9812160039 Safety evaluation accepting analyses presented in NEDC 3531347, 1811, it Owners Group Tech Space Improvement Part 2..." Analyses provide constructure bases for extending ECCS actuation instrumentation from 31 days to 92 days.

 Office of Nuclear Reactor Regulation, Director (Post 870411) 88712709, 4pp. 47669 073-47869 076.
- --8609130095 SAIC-88/3029 P102 "Review of BWR Owners Group Tech Spec Improvement Methodology (W/Demonstration for BWR ECCS Actuation Instrumentation) Part 2."

 --School Applications (Alexandrum) Care (Instruction Science Applications Instrumentation) * Science Applications Informational Corp. (formorly Science Applications, Inc.), 1440-03-87-029, 88/09/07, NRC - No Dotated Affination Given 48pp 47/469-077
- 8812200080 Forwards propriotary info in support of NRC review of BAW-1015€P to CHF correlation, including discussion of philosophy & effects of outlier rejection & nasture-tion of normality on design firm finfo withheld TAYLOR_JH Babcock & Wilcox Co. JHT/88-222. 88/12/09 NORDERG JA. Da. 555 of Engineering & Systems Tochnology (Post 870411). 3pp. 47874-207-47574-203
- 8812200270 Forwards changes to Rovs 11 & 7 to QA Topical Repts WCAP £ 370 & WCAP-7800,respectively.per 681 104 telecommunication & 681208 meeting JOHNSON,W.J. Westinghouse Electric Corp. NS-NRC-88-3387 89712714 GCNDY, A 1
- 8812200375 Forwards NEDC-30851P-A,Suppl 1, "...Tech Spec Improvement Analisa for BWR Control Rod Block Instrumentation." Affidavit also encl Rept without (ref. IDI GWA COMMINITOR OF THE STATE OF THE STATE
- 8812210029 Forwards prognetary WCAP-12087 & nonproprietary WCAP-12037. Sector Taxas Units 1 & 2 Pressurizer Surge Line & RHR Line Stratification." Proprietary 4:11 withheld (set 10CFR2.790). MCBURNETT.M.A. Houston Lighting & Power Co. ST-HL-AE-2900. 93/12/99. Deciament Control Branch (Document Control Desk). 3pp. 47887;156-47896.075
- -8812210031 Requests withholding of WCAP-12067, "South Toxas Units 1 & 2 Prosestiver Surgo Line & RHR Line Stratification," por 10CFR2.780.Affidavit end WIESEMANN.R A. Westinghouse Electric Corp. CAW-88-128, 88712703 MURLEY,TOlficto of Nuclear Reactor Regulation, Director (Post 870411) 10pp 47687.153-47887.168.
- -- 8812210034 WCAP-12087 Nonproprietary "South Texas Units 1 & 2 Prossurator Surgo Line & RHR Line Strattication."

 BAMFORD,W.H., BRICE-NASH,R.L., CARLSON,R.W. Westinghouse Electric Corp. 827

8812210128 Ferwards prognetary & nonprepriotary BAW-1915A & PA, 1 Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/Ft Limits W/Use of FLEC-SET 1 NRC acceptance fit B safety evaluation uncil BAW-1915PA withhold TAYLCR, JH Babook & Wicox Co. JHT/88-213 88/11/23 NORBERG, JA NRC No Detailed Afficiation Given Tip. 47939 001-47939 131

- -8812210130 BAW-1915A *Bounding Analytical Assessment of NUREG 0030 Medois on LOCA kW/ff Limits W/Use of FLECSET ** PALJUGJ, SCHOMAKER, Babcock & Wilcox Operating Plants Owners Group 88/
- 11/30 130pp 47939 902-47939 131
- 8812210236 Forwards proprietary Rov 1 to NEDC-30259, "Technique for Evaluation of 6WR MSIV Leakage Contributions to Radiological Dose Calculations." Reviresponds to recommendations in NUREC 1168 Altiduvit each Right withhold GRACE_DIN BWR Owners Group, BWROCE-8899 R97122115, MIRAGLIA,F. J. Associate Crector for Inspection & Technical Assossment (Post 670411) Spp. 47878.207-
- 8812210400 Forwards Amend 16 to GA Topical Rept GA-A13010A, "GA OA Program,"
- Constall review & approval.

 LEWIS J.H. General Atomics (formuly GA Tuchnologins, Inc./General Atomic Co.).

 GA/RRC-001-88-88/12/06 WFISS 5 Cuality Assurance Branch (870411-881231)
- 1p 47880 269-47880 339.
- -8812210403 GA:A13010A A 10 "GA QA Program"
 * General Atomics (formerly GA Technologies, Inc / General Atomic Co.). GA-LTR-11, e8/12/31. 70pp. 47883:270:47880.339
- 8912220007 Submits background into re-potential problem concerning properties 8 protects of Westinghouse proprietary into in connection wiproposed resolution of USI A 66 Proty in SECY documents should be followed:
 WESEMANN,RIA Westinghouse Electric Corp. NS-HAW-88-016 88712/05
 MCREEY,TE Office of Nuclear Reactor Regulation, Director (Post 870411). 3pp.
 47607-017-47903-019
- 8812220049 Forwards propuetary thatt WCAP-12967, "South Texas Unit 2 Pressuiter Surge Line 8 RHR Line Stratification Presentation to NRC 881139. Rept withhold (ref. 18CFR2,790). BURNETT, M.A. Houston Lighting & Power Co. ST.HL-AE-2894, 88711729, Document Control Branch (Document Control Dosk), 2pp. 47903 282-47903 283
- 881220125 Folwards fifth semiantical rept for 6 month period ending 860830 which highlights synthesia investigative raidit 8 other schwites W/o and ZIGROSSI,N A Tennessee Valley Authority. 80/12/06 ERNST,N L. Region 2, Oic of the Durector 1p. 47903 243-47903 243
- 8812220163 Forwards portions of firs to utils utilizing traffir um rod cluster control assembles & synopsis of info provided to NRC in 881123 tolcon Potential safety issue concerns mechanical functionality of rod Captur control assembles JOHNSON,W J. Westinghouse Efective Corp. NS-NRC-86-3384 88/12/08 ROSSIC E. Division of Operational Events Assessment (Post 870411), 13pp. 47692:181-47892 193
- 8812220206 Forwards proprietary & nanproprietary NFSR-0030, "VIPFLE7 WRB-1 DNBR Thermal Limit for Westinghouse OFA Fuel" Affidavit & application for writhholding propretary replication of the resion withhold (ref. 10CFR2 799). TRZYNA G.E. Commonwealth Edizon Co. 88/12/15. Cthice of Nuclear Reactor Regulation, Director (Post 870411). 4pp. 47892-257-47892-330.
- ~8812220214 NFSR-0033 R00 Rev 0 to "VIPRE/WRB-1 DNBH Thurnal Limit for Wes-Laghause OFA Fuat" BCERGER,J.C., GRIFFIN,J.L., KIM,H-S. Commonwealth Edison Co., 88/10/14, 59pp

47892 272-47892 330

- 8812220328 Forwards recoproprietary ANF-88-88(NP), "Dusign Rept for Millistone Point Unit 2 Relead ANF-1" Rept includes description of fuel design analytical basis,design citional drawings & results of fool dosign analysis

 MROCZKA,E.J. Northaast. Nuclear Energy Co. (subs. of Northans) Utilizes).

 MROCZKA,E.J. Northaast. Utilities 813100, 89/12/16. Dacument. Control Branch.
 (Document Control Cosk). 3pp. 47901.230-47901.283
- -8812220341 ANE 88-88(NP) R00 Rev 0 to "Design Root für Millstand Paint Unit 2 Matter Country Country
- 8812230260 Notification of 881216 meeting in RockylloMD w/B&W Owners Group,Operations Subcommittee to emergency procedures & generic technical guide-
- Eres. LYON.W.C. Reactor Systems Branch 88/12/08 HODGES,M.W. Reactor Systems Branch, 2pp 47916 143-47818 144
- 8812270163 PGE-1043 A 02 Amend 2 to PGE-1043, "Accident Monitoring Instrumenta-
- * Portland General Electric Co. 88/12/31 195pp. 47923 148-47923.345 6612270166 Forwards summary of C.E containment reliability goals for mitigation of
- Severe accidents SCHERER, A E SCHERER, A.E. Cambustion Engineering, Inc. LD-88-160, 89/12/21. CRUTCHFIELD,D Associate Director for Projects (Post 870411). 3pp. 47926-260-
- 47926:262
- 8811090114 Forwards "Prototype License Application SAR.Earth Mounded Concrete Bunker" 8 "Prototype License Application SAR.Bellow Grade Vauri "W/o encis. COLEMANJA. Energy, Dapt of 88/11/07. KNAPP, M. Dw.son at Low Leve! Weste Management & Docommiss.oning (Post 870413). 3pp. 47491-070-47491:072.

WASTE MGT NUCLEAR WASTE MANAGEMENT

- 8811090114 Forwards "Prototype License Application SAR.Earth Mounded Concrete Bunker" 8 "Prototype License Application SAR: Belowgreund Yauti "COLEMAN, JA Energy, Dept of 88/11/07. KNAPP, M. Division of Low Lovel Waste Management & Decommissioning (Post 870413). 3pp. 47776:001-47780.077
- --8812050102 DDE/LLW-73T Vois I & II to "Prototypo License Application SAR Earth-Wounded Concrete Bunker."
 - Ebasco Services, Iric (subs. of Enserch Corp.) 88/11/30 425pp. 47776:004-

- -9812050107 DOE/Ltw-737 V02 Vol II to "Prototype License Application SAR Below-ground Vault:Appendices A.H." W/13 oversize drawings * Rogers & Associates Engineering Corp. 88/10/30: 869pp. 47777 069 47779 217.
- --8812050114 DOE/LLW-72T V03 Vol III to "Prototype License Application SAR Bellow ground Vault Sons-tw-ry Analysis Right" MERRELLG B. ROGERS.V.C. Rogers & Associatos Engineering Corp. 88/10/01/18/5/pp. 47779.218-47780.042.
- ~8812050119 DOE/LLW-72T V04 Vol IV to "Prototyne License Application SAR Below ground Vault Meast-rements of Concrete Properties for Low Level Waste Disposal Fa
- SHUMAN,F., ROGERS,V.C., NIELSON,K.K. Rogers & Associates Engineering Corp 88/10/31, 35pp. 47780:043-47780.077.
- 8811140164 Forwards draft DOE/EA-0388, "Environ Assessment (EA) of Remnd a Action at Monument Valley U.M.I.Talings Site, Monument Valley,AZ." EA currently undurgoing 45-day review & comment period by cooperating agencies ARTHUR,W.J. Energy, Dopt. of 88/11/08 SMITH.D. Uranium Recovery Field Otc. R4, 1p. 47528 186-47527-329
- --8811140171 DOE/EA-Q368 "Environ Assessment of Remedial Action at Monument Valley U Mill Tailings Site, Monument Valley, AZ " ** Energy, Dept. of. 867(1730) 350pp. 47526;167-47527;329.
- 8811280056 Forwards Yucca Mountain Project site rept for the month of Oct 1989 PRESTHOLT,P.T. NRC No Detailed Affiliation Green 88/11/18 LINEHAN,J.J. Drvi. sign of High Level Wasto Management (Post 870413), 132pp. 47648:023-47648 154
- 8811280089 Rev 0 to "NNWS1 Project Sys Engineering Mgt Plan" "Energy, Dept. of: 68/07/31, 53pp. 47658 001-47658-051
- 8811280104 Requests analysis of legal implications of access to program architecture data base being devoloped by CNWRA by 881231. THOMPSON H. Office of Nuclear Material Safety & Saleguards Detector 88/11/21. PARLER,W.C. Office of the General Counsel: 2pp. 47644.338-47644.339
- 8811280131 Forwards Rev 2 to NNWSI/88-9, "NNWSI OA Plan," for review 6 comments Requests high priority for foviow of plan 8 meating achieduled for 881201 STEINR Energy, Dept of 88/11/23, LINEFIAN, Repository Licensing Project Directorate (881013 881119), 1p. 47654 168-47654 282. -8611260137 Draft Rev 2 to "NNWS1 QA Plan" " Energy, Dept. of, 88/11/22 114pp 47654:169-47654:282
- 8811280189 Forwards commonts on CNWRA TOP-001 as applied to GWTT part of
- 10CFR60-113(a)(2)
 BROWN,A Center for Nuclear Waste Regulatory Analyses 88/11/15, ROSS,F. NRC
 Na Deterlod Affiction Given 4pp 47656 304-47656 309.
- 8811280204 Informs of need to set up more facused technical interactions between NRC & DCE as addressed in one NRC quarterly status copt re-pro-Leonsing phase of DCE civilian high level radwasta mgt program. W/o ropt THOMPSON, HL Office of Nuclear Material Safety & Safequantia, Director 88/11/22 ROUSSO, S. Energy, Dept. of. 1p. 47854.051-47054.051
- 8811280208 Requests to Inform DOE of need to arrange access to data hashs perform to sting of repository at Vicca Mountein & to negotiate w/DOE acceptable schedule & protocols for access to subjidate bases CHERY, D.L. Geoscience & Systems Performance Stanch (Post 880911) 89/11/22 STABLEIN, N.K. Repository Licchsing Project Directorate (881013-881119). 2pp. 47655 352 47665 353
- 8811290089 Discusses plans for monthly meetings between DOE,NRC & other organizations interested in DOE,Oto of Cryban Redwaste Mgt QA program development & Implementation Planning for meetings will be concurrent w/QA program review meeting. STEIN,R. Energy, Dept. of. 88/11/18. LINEFIANUL Repository Licensing Project Di rectorate (881013-881119). 1p. 47684-184-47664-184.
- 8811290098 Comments on NRC "Draft Review Plan tor NRC Staft Review of OOI Study Plans & Procedures." Plan provides logical explanation of process that NRC wit utilize for review of OOI study plans & procedures Specific communis and. STEIN,R. Energy, Oopt. of 88/10/20. YOUNGBLOOD,B.J. Division of High Love Waste Management (Post 870413). Opp. 47649:259 47649:264.
- 8811290113 Notification of 881208 Oic of Civilian Radwaste Mgt OCRWM QA Program meeting In Las Vogas NV for DOE & program partic pants to review status of OCRWF QA program development Agenda end.
 STEIN,R. Energy, Dopt of 88/11/18 LINEHAN,J J. Repository Licensing Project Directorate (881013-881119) 2pp. 47650-250-47650:251.
- 8811290145 Forwards draft Ray 1 to CNWRA OA Manual,Section 19, "Decision Suppo Sys," for info prior to inclusion into subj manual per NRC 880915 & 0719 lits LATZ,JE. Center for Nuclear Waste Regulatory Analyses 89411/23 BUNTING,J.C Division of High Level Wasto Managoment (Post 870413) 1p 47651.266.47651:274
- -8811290178 CNWRA OA Manual Socilion 19, "Decision Support Sys."

 * Content for Nuclear Waste Regulatory Analyses: 88/11/23, 4pp, 47651;26, 47651;270.
- 8811290154 Forwards updated "Ctr Expertise & Experience," table & numerical tabut ton of current & planned professional & support staffling. PATRICK,W.C. Center for Nuclear Weste Regulatory Analyses. 98/11/2 FORTUNA,S. NRC No Dotated Affiliation Given 6pp 47649 185-47649 180.
- 8811290186 Forwards, "NNWSI Conceptual Model Update NNWSI Repository Proje Subtask 1.4" Reptitioniffies fisted items to hydrogeologic systinc uding what is know t LOGSDON M.J. Nuclear Waste Consultants, Inc. FIN D-1021, 293, 88/11/1 POHLEJ. Division of High Level Waste Management (Post 870413). 2pp. 47690:00
- --8811290176 "NNWSI Conceptual Model Update.NNWSI Repository Project Subta 1.4." Witwe qversize drawings. SNIFF,T.L., CARMIEN,M.C., DAVIS,L.A. Water, Waste & Land, Inc. 88/11/30, NRC No Detailed Affiriation Given. 175pp. 47696.003-47696-195

47696, 195.

222 NONDOCKETED ITEMS

- 8811290187 Forwards comments on 880610 Nuclear Waste Project Ofc QA Manual dtd 880610 re statement of QA Policy,QA Program, QA Procedures & glossary of defini-
 - LINEHAN, J.J. Repository Licensing Project Orectorate (881013-881119), 88/11/25. LOUX, R.R. Nevade, State of: 10pp, 47651:102-47651:111
- 8811290193 Forwards notice of upcoming NRC/DOE technical/programmatic meetings re NRC high level wasts mgt program.per 680827 NRC FR notice.Informs of weakly updates of subj notice & of weakly announcements by telephone recording svc. LINEHAN, J. Repost toyr ticensing Project Directorate (881013-881119), 88/11/28, NRC No Detailed Alfrication Given, 2pp. 47651 253-47651-254
- 8811290198 Ack receipt of "Review & Approval of Technical Repts," instruction Issued under Technical Operating Procedure-002, dtd 881025 BUNTING_JO Engineering Branch (Post 980911), 88/11/25, WritTING,A.R. Center for Nuclear Waste Regulatory Analyses 1p. 47651:112-47651:112
- 8811290213 Forwards "Audit Observation Rept for Yucca Mountain Project Ofc Audit 88-05 of LUL" NRC determined audit acceptable. Requests DOE ensure tab response tine deficiencies found in program.

 LineHan,J.J. Repository Licersing Project Orectorate (881013-881119), 88/11/25.

 STEIN,R. Energy, Dept. of. 2pp. 47888 107-47668:119.
- ~8811290218 "Audit Observation Rept for YUCCA Mountain Project Ofc Audit 88-05 of
- HOLONICH, J.J., KENNEDY, J.E. Repository Licensing Project Directorate (881013-881119), 88/11/21, 11pp. 47688:109-47668:119
- 8811290252 Notification of 881201 meeting w/DDE,State of NV & Clarke, Nye & Lin-coln Countiles in Ricky te,MD to discuss NRC review of DDE proposed changes to NRWSI OA plan. HOLONICH,JJ, Repository Licensing Project Directorate (881013-881119), 88711/25, LINEHAN,JJ, Repository Licensing Project Directorate (881013-881119), 1p 47687/087-47687/087.
- 8811290262 Forwards pretminary draft update of user need statement for high level 811290282 Forwards pre-minery oran operations to be indeed to be seen that the waste research support.

 8ALLARO,R L. Geoscience & Systems Performance Branch (Post 880911), 88/11/25
 LINEHAN,J.J. Repository Licensing Project Directorate (881013-881119), 8UNTING,J.O. Engineering Branch (Post 880911), 18pp. 47867:012-47867, 029.
- 8811290498 Requests input on proposed table of contents & disposition of waste mgt policies for development of Drv of High Lovel Waste Manual Linchan, J.J. Repositor, Licensing Project Directorate (881013-881119), 88/11/28 BALLARD, R.L. Geoscience & Systems Particinance Branch (Post 880911), BUNTING, J.O. Engineering Branch (Post 800911), TREBY, S. Assistant General Counsel for Rulemaking & Fuel Cycle, 14pp. 47665, 159-47665, 172
- 8811290507 Comments on "Ctr Recommended Approach to R8 Milestone Ropt." Recommends ctr proceed w/rept in manner most appropriate & consistent w/current con-
- BUNTING.J.O. Engineering Branch (Post 880911) 88/11/23 PATRICK.W.C. Center for Nuclear Waste Regulatory Analyses 1p. 47850/032-47850.032.
- 8811290516 Forwards comments on "Evaluation & Compilation of DOE Waste Package Test Data," monthly ropt for Aug 1988,FIN A-4171. Actions considered to be within scope of FIN A-4171. Engineering Branch (Post 890911). FIN A-4171. 88/11/25. INTERRANTE,C.G. National Instituto of Standards & Technology (formerly National Bureau of Standa, 7pp 47655;103-47665.109.
- 8811290542 Clanfies last paragraph on Page 10 of Sandra observation audit rept. HOLONICH,J.J. Repository Ucensing Project Directorate (881013-881119), 88/11/28, Repository Ucensing Project Directorate (881013-881119), 2pp. 47650:170-Repository 47650.171
- 6811300141 Forwards comments re NRC draft "Technical Position on Std Format & Content for Documentation of Remed at Action Selection at Title I U Miti Tallings Sites (SF&C)." DOE technical approach document takes procedence over SF&C ARTHUR, V.J. Energy, Dopt. of "11/29", LOPHAUS.Ph. Drivison of Low Lavel Waste Management & Decommissioning (Post 870413), 21pp. 47677:323-47677:343.
- 8811300192 Notification of 881208 meeting in Rockville,MD w/DOE, State of NV & Clark & Nye Countes re design accoptablety analysis for exploratory effect Hactity,Agenda enci.

 HOLONICH,JJ Repository Licensing Project Directorate (881013-881119), 88/11/29, LINEHAN,JJ, Repository Licensing Project Directorate (881013-881119), 2pp. 47677-299-47677-309.
- 8811300200 Requests confirmation of 881215-16 for meetings to discuss DOE/YMPO study plans to resolve (saues contained in NRC 680805 ftr.per 881028 telcon.Topics for discussion would include clarification of purpose & content of study plans STEIN,R. Energy, Dopt of 86/11/18. UNEMAN,JJ. Division of High Level Waste Management (Post 870413). 2pp. 47697 232-47697:233.
- 8811300208 Forwards Regulatory Requirement Topics E17 & E36 to be used to demonstrate hullitiment of element/subetament Milestones A3 & A4,for review & comment by 881206.W/o and.

 ALTOMARE,P.M. Engineering Branch (Post 880911). 88/11/28. BUNTING,J., FORTUNA,S. Engineering Branch (Post 880911). THOMAS,B. Office of Nuclear Material Safety & Safeguards,Director. 2pp. 47697;190-47697.191.
- 8811300230 Forwards Task Order 23 to Contract NRC-02-84-001, "Technical Assistance in Geophysical Methods for Sita Characterization," to assist NRC in ruslewing final site characterization plan & associated situdy plans. ISBRAHIM,A.K. Geosciance & Systoms Performance Bianch (Post 660911), NRC-02-84-001, 88/11/29, MEEHAN,8, NRC No Detailed Afhiliation Given, 5pp. 47671,312-
- 8812010293 Forwards schedule for completion of outstanding fit repts documenting status of work at present on FIN A-1756.per 88 i 117 request NRC should modify contract reflecting rev in scope of work & compresson of outstanding repts by 800331. BONANO,E.J. Sandia National Laboratories. FIN A-1756 88/11/21, MO,T. Geoscience & Systems Performance Branch (Post 880911), 2pp. 47709:192-47709:193.
- 8812010396 Forwards SECY-88-039C, "Quarterly Progress Rept on Prelicensing Phase of DOE Civillan High Lovel Radwasto Mgt Program," for Info. TANA.E.T. Repository Licensing Project Oractorate (881013-681119). 88/11/21, NRC No Detailed Affiliation Given. 1p. 47709-316-47708-347.

- 8812010412 Advises that licensee should modify proposed plan to accommodate or reduce excessive flow velocities in response to 881013 request for approval of 5° embankment slopes proposed by Conoco for Conquista tailings project HAWKINS.E.F. Uranum Recovery Field Ofc, R4. 86/11/18. LACKER.O.K. Texas State of 3pp. 47700.040-47700.042.
- 8812010415 Forwards summery info format developed for use in collecting inventory info & hat of action items identified for interface requirements discussed in 860526 meeting Meeting will be scheduled on 881215 to compile info collected ALTOMARE,P. Office of Nuclear Material Safety & Safeguards,Director, 8871123, DELLIGATTIM, FORTUNAS L., STILTENPOLE,B. Engineering Branch (Post 860913; 5pp. 47899.357-47699.360.
- 8812010422 Comments on draft Ltr Rept 1.38. "Processos Which Should Be Independently Evaluated By NRC." Rept contains several fundamental aspects that need further consideration & rev BROOKS.P. Geoscience & Systems Performance Branch (Post 880911) Filt A.1155 88/11/29. BONANO,E.J. Sandia National Laboratories. 13cp. 47703 063-47703 075
- 8812020073 Forwards background into & questions for 881201 briefing of Commission by State of NV.

 BLAHA,J.L. Ofc of the Executive Director for Operations, 88/11/29. Commissioners, 20pp. 47718:316-47718:335.
- 8812020082 Forwards notice of upcoming NRC/DOE technical/programmatic meetings re NRC high level waste mgt program Weekly update of notice & telephone recording ave for upcoming meetings to NRC waste mgt program available LINEHANUJ Repository Licensing Project Directorate (891013-981119) 66/12/CS NRC No Detailed Affiliation Given. 2pp. 47711:354-477(1:355.
- 6812050061 Vol.1 to "Yucca Mountain Project Site Atlas." W/74 oversize drawings. * Energy, Dept. of. 88/10/31, 559pp. 47700.051-47701:249.
- 8812050186 Forwards DOE rept for wk ending 881118.
 PRESTHOLT,P.T. NRC No Detailed Affihation Given 88/11/29. LINEHAMUJ Cression of High Level Waste Management (Post 870413), 6pp. 47732.015-47732.020
- 8812050248 Forwards monthly activity schodules for UMTRAP sites, reflecting current & future key project activities in areas of attendering content a development remedial action const certification, it consing surveitlance & maint ARTHUR, W.J. Energy, Dept. of. 88/12/01. LOHAUS, P. NRC. No Detailed Aff attending AKEMA, K.L. Utah, State of. SHINGOITEWAL Hopt Tribe. 35;p 47740.202-47740.236.
- 8812050295 Rev 1 to Quality Mgt Procedure QMP-06-02, "Document Control SPAETH, BLAYLOCK, J., GERTZ, C.P., Energy, Dept. of. 88/11/17, 20pp. 47730 337-
- 8812050304 Forwards update for list of Las Vogas,NV library.
 PRESTHOLT,P.T. NRC No Deteriod Affiliation Given 88/11/30, TANA,E. Repository Licensing Project Directorate (881013-881119). 5pp. 47730 357-47730 381.
- 8812050308 Forwards rev of comments, quositions & requests for additintly to topical rebt, "Weste Form Certification Program-Rept III: Cemant Blinder Chemistry." SISKINDB. Brookhaven National Laboratory, FIN A-3174, 88/12/02. Document Control Branch (Document Control Branch (Document Control Branch (Document Control Branch).
- -8812060014 Forwards reviol commonts, questions & requests for additinto relication, "Waste Form Certification Program-Ropt III. Coment Binder Chemistry." SISKINDB. Brookhaven National Laboratory, FIN A-3174, 98/12/01, MCDANIEL, K. Technical Branch, 9pp. 47731:192-47731:200.
- 8812050314 Forwards comments on draft ropt, "Review of Uncertainties Re'evant in Performance Assessment of High Level Radwaste Respositiones"

 BROOKSP, Geosclance & Systems Porformance Branch (Post 680011) FIN A 1165-88/12/02. BONANO,E.J. Sanda National Laboratories. 9pp. 47740:193-47740:201.
- 8812060187 Responds to 881018 ltr ro review of two wasto acceptance process documents, "Draft Waste Acceptance Preliminary Specs for Defense Waste Processing Facility (DWPF)," & "DWPF Waste Form Compliance Plan." LINEHAN.J.J. Repository Licensing Project Directorate (881013-881119), 88/12/05 STEIN,R. Energy, Dopt of, 2pp. 47743-108-47743-109.
- 8812060231 "Performance Assessment of Low Level Radwaste Sites," annual summary project rept for FIN 8-2485.Cost info in Central Files.
 BERGERONMP. Battelle Memorial Institute, Pacific Northwest Laboratory. FiN 8-2485.88/11/30. DEFRINGL. Office of Nuclear Material Safety & Safeguards (Nicctor. 8pp. 47745:001-47745:008.
- 8812060262 Forwards draft repts "CNWRA Participation in Holmes & Narver NRC Auc.t Observation Team,881101-04" & CNWRA Participation in Fennix & Scisson SRC Audit Observation Team,881107-10." LATZ.J.E. Center for Nuclear Wasto Regulatory Analyses. 88/12/02. MACE.W.II. (24. sion of Contracts & Property Management (Post 880515). pp. 47734:178 47734:183.
- -8812060264 Draft ropt of "CNWRA Participation in Holmes & Narvor NRC Aud I Observation Team.881101-04."
 MABRITO.B., WHITING.A.R. Center for Nuclear Waste Regulatory Analyses 88/12/
 02. 8pp. 47734:177-47734:184.
- -8812060268 Draft rept of "CNWRA Participation in Fennix & Scieson NRC Audit Observation Team,8811(07-10." MABRITO,8., WHITING A.R. Center for Nuclear Waste Regulatory Analyses 09/12/ 92. 9pp. 47734:185-47734:193.
- 8812070184 Forwards transcript of 981116 briefing Identifying Commission conceins re-overall high level waste program.DOE should address concerns noted in transcript in upcoming briefing of Commission on 881220. THOMPSON.H.L. Office of Nuclear Material Sefety & Safeguards, Director. 88/12/02 ROUSSO,S. Energy, Dept. of. 2pp. 47747:308-47748.017.
- 8812080068. Forwards summary of 881123 meeting on exploratory shaft facility design acceptability analysis.

 LINEHAM,J.J. Repository Licensing Project Directorate (881013-881119) 88/12/01.
 STEIN,R. Energy, Dept. of. 35pp. 47750:134-47750:180.

BrAYLOCK,J. Energy, Dopt. at. 88/08/04, 12pp, 47750-169-47750-160 8812083073 Forwards review pran 8 associated attachments for evaluating prehitinary architecture. "E" indestones to be submitted by CNWRA in accordance w/plan for acceptated development of program architecture. BUNTING J.O. Engineering Branch (Post 880911). 18412707. LINEHAN, J.J. Repository Usensing Project Directorate (881013-881119). BALLARD, R.L. Googcience & Systems Performance Branch (Post 880911). THEBY, S.A. Office of the General Countries and Architecture.

- sel 11pp 47783 083-47783 152 ~8612130194 Forwards Technical Operating Procedure TOP 001-02, "Program Architecture Reliational Data Base, Work Instruction" in Tuffil ment of CNWRA Mifestones D7
- 8 D8 8 D8 WH.T.N.G.A.H. Conier for Nuclear Waste Regulatory Analysias. 88/08/15 AUTOMARE P.M. Division of High Lovel Waste Management (Post 870413). 2pp. 47783.111 47783 112
- -8312130201 "Program Architecture Rolet anal Data Base, Working Instruction."

 **Center for Nuclear Wasto Regulatory Analyses 88/08/15 39pp 47783:113-47783:152.
- 8912080101 Transmits comments on "Draft Outline for Waste Sys Engineering & Inte-gration Militatore R8" Ropt strougles renamed as stated ALTOMAPEPM Engrooting Brench (Post B80911), 88712706 WHITING, A.R. Center to Nuclear Waste Regulatory Analyses. 4pp. 47756:232-47756-235.
- 8312880102 Requests status mauling to discuss transitional licensing support sys operation & Latert related items on 881215.
 BERNERO,R A. Olfico of Nucleur Material Safety & Safeguards, Director, 88/12/05.
 AMENTA, A. Deputy Director for Information Resources Management (Post 870413).
 4pp. 47756:227-47756.230.
- 88120801DB Netrication of 881215-16 moeting w/DOE, affected local govts & State of NV to discuss listed aspects of study plans for site characterization, including scope & perpose, OA concerns & DOE & NRC processos for review.

 STABLEINK Repository Licensing Project Directorate (861013-881119), 88/12/01 UNEYIAN J.J. Repository Licensing Project Directorate (861013-881119), 1p. 47754-079-47754-079
- 8812080239 Forwards executed Mod A007 to Cooperative Agreement DE-FC04-82AL20536 between DOE & Navajo Tribu of Indians CIXSON,G.R. Energy, Dopt of 88/12/05, L014AUS.P.11 Office of Nuclear Material Safety & Shfeguerids,Director 3rp. 47763-251-47763-253.
- 8812090024 Comments on 881101 CNWRA moeting rept re-program architecture-dovelopment Milostonas A37A4 & E17 program includecture input ALTOMART, PM Engineering Branch (Post 8/0011), 88/11/25, WHITING,AR Center for Nuclear Wasta Regulatory Analyses, 4pp. 47702,299-47782,302. 8812090032 Forwards notice of upcoming NRC/DOE technical programmatic meetings re NRC Figh lovel waste mgt program. LINEHAN, J.J. Repository Licensing Project Directorate (881013-881119). 88/12/12 NRC - No Dataked Allüstich Grven. 2pp. 47761-067-47761-068
- 8812090003 Transcript of low level waste disposal regulatory meeting on 881116 in Rocky Le,MD Pp 1-129
 * NRC No Dote led Affiliation Given, 88/11/16, 133pp, 47754:239 47755.011. 8812090139 Forwards Vots 1 & 2 to DOE/FIS 0136, "Special isotope Separation Project," FES DOE decision to proceed w/const & operation of project will be decumented in publicly available record expected to be available in Jan 1989.

 OFFE,D Energy, Dopt of, Idaho Operations Office. 88/12/06. TOKARI,M. NRC - No Delaited Aftilabon Given. 2pp. 47807 303-47811:102
- 8812090239 Forwards for review & retention, rept entitled "Evaluation of As Constructed Piprep for Shiprock, New Mexico Site." Rept & calculations present retional that In-place erosion protection toyers at site most design requirements ARTHUR, W.J. Energy, Dopt. of, 86/12/05 LOHAUS, P. Division of Low Level Waste Management & Decommissioning (Post 870413) 45pp. 47782-232.47782:276.
- 8812090248 Forwards draft rept entitled, "Level of Retrieval Demonstration Needed Our.ng Site Characterization for Geologic Repository."

 CUMMINGS,R A. Engineers Internetional, Inc. FIN D-1004. 1148-09-01. BB/12/03.

 BUCKLEY,J.T. NRC - No Detailed Affiliation Given 1p. 47775:204-47775:235
- -8812090248 Draft "Level of Retrieval Demonstration Needed During Site Characterizafor for Geologic Repository."
 * Engineers International, Inc. FIN D-1004. NRC-02-84-002. 88/12/31. NRC - No Detailed Affiliation Given 31pp 47776.205-47775.235.
- 8812990268 Responds to J Kennady 881118 request ro description & justification of DCE proposed changes to App HiRev 1, "Requirements for Computer Software Used to Support High Level Nuclear Repository License Application." STEIN,R. Energy, Dopt of 88/11/29 LINELIAN,J. Division of High Level Waste Management (Post 870413), 11pp. 47782 279-47782 289.
- 8812090300 Advisos that study plans re water movement test & excavation invostiga-tion should be modified per NRC 860805 comments Mode should resolve most of NRC concerns by providing additionation on several topics. STEINR Energy, Dept of 89/12/01. LINEHANJ. Division of High Level Waste Man-egement (Post 870413). 2pp. 47785:036-47785.037.
- 812099310 Forwards,for review & acceptance,OCRWM OA requirements document,Rev 1 Document reflects changes made based on resolution meeting held on 880928. STEIN,H Energy, Dept. of 88/11/23 YOUNGBLOOD,B J Dwision of High Level Waste Management (Post 870413) 2pp. 47785-074-47785-138.
- -8812090316 Rev 1 to QA requirements for civilian radwaste mgt program. BARRETT,L, KAY,C.E. Energy, Dept. of. 88/11/03, 63pp. 47785,078-47785;138.
- 8812090325 Ray 0 to Work Instruction 1-02-2, "Regulatory Requirement General Subj." HAGERNAN, J.P., MABURITO, B., WHITING, A.R. Center for Nuclear Wasto Regulatory Analyses, 88/12/02, 5pp. 47785.069-47785.073.

- Checking to specific conditions of sito LOUX,R.R. Novada, State of, 88/12/07, LINEHAN,J.J. Program Management & Quality Assurance Branch (880911-881012), 9pp. 47785 251-47785:259. 8812120089 Forwards "Prototype Underground Goologic Mapping."
 PRESTHOLT, P.T. NRC - No Dotellod Affiliation Given 88/12/07, CARDONE,T LINEHAN,J.J. Repostory Licensing Project Directorate (881013-981119). 3p. 47788-041-47789-067.
- 8812120095 Press release announcing State of WA 881216 Nuclear Waste Board & Nuclear Waste Advisory Council ingellings in Ladey,WA to discuss disposal of low leve commercial radvaste at Hanford 4 Washington, State of 88/12/01 4pp 47785 207-47785 210.

Unsaturated Medium." Applicant should take responsibility to apply NRC performance

- 8812120102 Summary notes from State of WA 881021 Nuclear Waste Board Meeting * Washington, State of .88/10/21, Washington, State of .13pp. 47788.088-47788.100

- 8812120106 Summary of 881021 joint meeting of State of WA Nuclear Waste Board & Nuclear Waste Advisory Council in Lacey,WA re Hanford dose recons project,northwest hazardous waste ROSD ctr 8 joint State of WA & CR position of 1990 funding. Washington, State of. 88/10/21, Washington, State of. 24pp. 47788 187-47788 210
- 8812120109 Requests mooting w/Waste Mgt Review Group to bring to closure Issue, re integrated waste package experiments research project plan Summary of cir technical position on use of Hateroy C-22 as essential benchmark mait end:
 PATRICK,W.C. Center for Nuclear Waste Regulatory Analyses 88/11/23 FORTUNA.S.L. NRC No Detailed Affiliation Given 6pp 47792.066-47792.070.
- 47789.065

- - 8812130085 Forwards meeting repts from NRC/DOE 881019-21 meeting on explorator shaft facility open items List of attendess enc.l. HSIUNG S. Center for Nuclear Waste Regulatory Analyses. 88/12/06 PEARRING_IR. Division of High Level Waste Management (Post 870413). 18pj
 - 8812130077 Forwards DOE rept for wix ending 881125 to Yucca Mountain Project weekly highlights.
 PRESTHOLT.P.T. NRC No Detailed Affiliation Given, 88712705, LINEHAN, J.J. Division of High Level Waste Management (Post 870413). Spp. 47792:243-47792:247.
- - 8612130039 Forwards revised interim rept to Congress re Quam Commonwealth & comments of Interagency Task Force.

 MCCOY,J.J. Interior, Dept. of. 88/12/09. BOYLE,B. NRC No Detailed Affiliatio Given. 7pp. 47792:121-47792:127.

47794:091-47794:108.

- lectrifical position.
 ARTHUR W.J. Energy, Dept. of. 88/12/05, LOHAUS,P. Division of Low Level Wast Management & Decommissioning (Post 870413), 2pp. 47789.078.47789.079.
- 8812120259 Provides into for roylew & approval to Green River,UT remodual action has plant submitted under fit did 680901 containing test method not covered by NRC state.

- 8812120244 Requests amended responses to Yucca Mountain Project OA Sid Delicien cy Repts 170,172 & 179,Rev 0,generated as result of Yucca Mountain Project Ofc O/ 88-06 of labs BLAYLOCK J. Energy, Dept of 88/12/05. STIEGLER,J E. Sendia National Leberato des. 9pp. 47788:109-47788:117.

- for replacement.
 PRITCHETT,R.F. Reynolds Electrical & Engineering Co., Inc. 88, KENNEDY,J.E. NRC No Detailed Afficiation Given 4pp. 47788:202-47799.054 -8812120238 Rev 6 to "OA Program Plan for NNWSI Project"
 FRASER D.L., PRITCHETT,R F. Reynolds Electrical & Engineering Co., Inc. 88/10/31
 121pp. 47788.294-47789 054.
- re in situ testing. CUMMINGS.R.A. Engineers International, Inc. FIN. D-1004, 143, 88 BUCKLEY,J.T. NRC No Detailed Aftitiation Given: 4pp. 47798.005 47798:008. 8812120235 Forwards Roy 6 to 568-DOC-115, "OA Program Plan for NNWSI Project,"

- 8812120224 Publicly available portion of trip rept of 881121-22 maeting in Rockville,MI

- 8812120218 Forwards revised Page 3 of final dreft "Status of Lode- Quartz Claims of Yucca Mounta n,Nya County,Ny." WELDIN,R.D. Infarior, Dept. 0, Bureau of Mines FIN D-1018. NRC-02-85-004, 88/12-07. ABRAMS,C NRC No Detailed Affrication Given. 2pp. 47786-069-47788-061.
- 8812120143 Discusses State of NV Nuclear Waste Project Oic observations & concern re DOE/YMPO QA audit of Holmes & Narver on 881101-04 QA program found to be marginally offective.
 ZIMMERIMAN,S. Nevada, State of. 88/12/01, Nevada, State of. 2pp. 47785.211

8612140119 Forwards final repts for Subtasks 02, "Appropriate Models, Tests & Assumptions for Predicting Vontilation Requirements During Retrieval," & 04, "Analys of Ventilation Pian Contained in CD-SCP." HUCK, P. J. Engineors International, Inc. FIN D-1004, NRC-02-84-002, 88/12/13 BUCKLEY, J.T. NRC - No Detailed Affiliation Given, 11pp. 47814:195-47814:348.

--8812140123 "Appropriate Models,Tests & Assumptions for Predicting Ventrallien Requirements During Retrieval," final rept. HUCK,P.J., LAURITO,A.W. Engineers International, Inc. NRC-02-84-002 86/12/3 Engineering Branch (Post 980911): 29pp. 47814:206-47814 233

- 8812120134 Discusses State of NV Nuclear Waste Project Otc concerns & observations to DOE/YMPO OA audit of Los Alamos Natl Lab on 881003-07-QA program appear confused that confused that profuse work current work & future work is questionable. ZIMMERIMANS. Nevada, State of. 88/11/28. Nevada, State of. 3pp. 47785-214
- 8612120129 Discusses State of NV Nuclear Weste Project Oto observations of 881024 28 DOE/YMPO QA audit of LLL. ZIMMERMAN,S Nevada, State of 88/12/01. Novada, State of 2pp 47789.064

88/11/30

88/12/08

- 8812140134 Forwards final draft of "Roview of NNWSI Site Characterization Plan Conceptual Cesign Rept for Repository at Yucca Michiam,NV," per Task Order 07. CLMMM: GS,R A. Engineers International, Inc. FIN 0-1004, 1146-07. 88/12/12. BUCKLEY,J.T. NRC No Detailed Affiliation Given 19. 47614-349-47816-137.
- --8812140140 "Review of NNWSI Site Characterization Plan Conceptual Design Ropt for Repository at Yucca Mountain,NV," final rept.

 Engineers International, Inc. F. N. D-1004 NRC-02-84-002 88/12/31, NRC No Detailed Affi
- 8812140166 "Licensing Methodology Assistance," monthly rept for Nov 1988 Encl in
- Contral Files
 BONANO,E J. Sand a National Laboratories FIN A-1165 86/12/15. TIKTINSKY,D.H.
 Drivision of High Level Waste Management (Post 870413). 11pp. 47829:054. 47828 084
- 8812140173 Forwards "Technical Rept on Const Specs for Exploratory Shaft Faculty," final rept CUMMINGS R.A. Engineers International, Inc. FIN D-1004 1148-09 05 88/12/09 BUCKLEY,J.T. NRC - No Detailed Affiliation Given, 1p. 47799 187-47799:212.
- -8812140179 "Technical Reption Const Specs for Exploratory Shalt Facility," final reption Engineers International, Inc. FIN D 1004, NRC 02-84-002, 88/12/31, NRC No Detailed Affiliation Given, 25pp. 47799;188 47799 212.
- 8812140199 Forwards "Lessons Learned from Analysis of 'Safoty Issues at Defenso Production Reactors," for info BARRETT, H. Fenergy, Dept. of 88/12/12, KENNEDY,J., LINEHAN,J. NAC No Detailed Alfidation Grean, GERTZ,C. Energy, Dept. of 2pp. 47828-065-47828-081.
- -8812140201 100 110.11258 "Lessons Learned from Analysis of 'Safety Issues at De-tense Production Reactors'."
 * CER Corp. 88/11/30. 15pp. 47828 067-47828 081.
- 8812150166 Provides first of several periodic updates & briefings for upper mgt re high level performance assessment modeling activities, por commitment confirmed in 880001 MOU between NMSS & RES BALLARD, R.L. Geoscience & Systems Performance Branch (Post 880911) SILBERBERG, M. Division of Engineering (Post 870413), 88712709 BROWNING, R.E. Division of High Level Waste Management (Post 870413), ARLOTTO, G.A. Division of Engineering (Post 870413), 14pp. 478241099.47824112
- 8812150171 Forwards rept for Dec 1988 outlining current status of all CNWRA element/ subelement milestones. LEE,MP. Engineering Branch (Post 880911) THOMAS,BC Repository Licensing Project Directorate (881013-891119) 89/12/09 NRC - No Detailed Afficiation Given. 12pp. 47828 014-47826 025.
- 8812150218 Requests assistance in establishing meeting within 3 wks between NRC & DOE to idently CNMRA kilo needs & discuss how best to obtain Info ROUSSOS Office of Nuclear Material Safety & Safetyards Director. 88/12/07 THOMPSON,H L. Energy, Dept. of. 5pp. 47833 047-47833 051
- 8812150230 Focwards site characterization program review plan (SCPRP) for use in reviewing DOE site characterization plan SCPRP developed by revising COSCP review plans to incorporate lessons from COSCP review & site characterization analysis BROWNING,R.E. Division of High Level Waste Management (Post 870413), 1p. 47828.102-47829.305.
- -9812150236 "Review Plan for NRC Review of DOE Site Characterization Plan"

 * Division of High Level Weste Management (Post 870413), 88/12/12, 224pp. 47628:103-47628:325.
- 8612150242 Rev 5 to OAPP-002, "NNWSI OA Manual."
 * Fenix & Scisson, Inc. 88/08/23 121pp 47629:217-47829:337.

47828:325

- 8812150246 Forwards drafts of regulatory requirement Topics E17, "Adverse Condition-Geochemical Processes" & E36, "Structures Sys & Components Important to Safety-Protection Against Natural Phenomena...," for completing review.
 BUNTING.J.O. Engineering Branch (Post 880911) 88/12/09, BUNTING.J. Engineering Branch (Post 880911) ALTOMARE.P. Geoscience & Systems Performance Branch (Post 880911) TREPY.S. Assistant General Counsel for Rulemaking & Fuet Cycle, 3pp. 47829.338.47830.128.
- --8812060275 Forwards items to fulfill Intermediate Milestones A3 & A4, Including finalized program architecture support systorganization structure Intermediate Milestone A5 will be demonstrated on 881201.
 WHITING,A.R. Center for Nuclear Wasto Regulatory Analyses 88/11/20, ALTOMARE,P.M. Division of High Level Waste Management (Post 870413), 148pp. 47829.341-47830:128.
- 8812150247 Comments on program architecture development Miestones A3 & A4.Two draft regulatory requirement topics submitted in fulfilment of A3/A4 milestones satisfy intent of two A0P milestones in demonstrating data base structure for PASS. ALTQMARE,P.M. NRC. No Detailed Affiliation Given. 88/12/12, WHITING,A.R. Center for Nuclear Waste Regulatory Analyses. 1p. 47830;231-47830;231.
- 8612150256 Requests review & comment on program architecture Milestones A5,A6 & 812190/200 Frequous review a common on program a common of program as a common of the first Program as a common of program as a common of the first Program as a common of the first Program of the fi
- -8812150258 Forwards briefing packet & explanatory items in fulfillment of subject intermediate Milestones A5 & A6 & major Milestone R7,as defined in J Latz 880726 memo to M Mace. LATZ,JE. Center for Nuclear Waste Regulatory Analyses. 88/12/07. MACE,M H. Division of Contracts & Property Management (Post 880515). 2pp. 47849,242-47849:243.
- --8612180263 "Proof of Sys Demonstration for Program Architecture & Program Architecture Support Sys (Milestona 7)." W/3 oversize drawings.

 **Conter for Nucloar Wasto Regulatory Analyses. NRC-02-88-005, 88/12/01, 375pp. 47849:244-47850:130.

- 8812160187 Forwards "Profurinary Review of Low Sun Angle Air Profus From Yucca Mountain Area "Technical Itrings." CHUNG,DH Lawrence Electrocal National Laboratory Fift A-0297, L-193, 59/12/10 BLACKFORD,ME Division of High Lovel Waste Management (Post 878413), 1p 47832-296-47832-306.
 - →8812190023 "Preliminary Review of Low Sun Angle Air Photos From Yucca Mountain APBA.
 MCKAGUE,H.L., CARPENTEH,D.W. Lawrenco Tivermore National Laboratory FIN A-0297, 88712/10. NRC - No Delaited Afficiation Gived. 10pp. 47832 297-47832 336
 - 8812190131 Publicity available portion of "Performance Assessment Methodology Covel-opment Lew Level Waste 0 sposal Safety Assassment," monthly rept for New 1638 BONANO,E J. Sandia National Laboratones FIN A-1764 88/12/15 DEERING,L Technical Branch. 4pp. 47879 001-47879 004
 - 8812190149 "Evaluation, Validation, Ventroation & Documentation of IMPACTS CRC Computer Code," monthly rept for Nov 1988 Cost info withheid CRANWELLR M. Sandia National Laborations. FIN A-1783 88/12/06 GLENN, C. Regulatory Branch. 3pp. 47835-170-47835-172.
 - 8812190169 Forwards "Level of Retrieval Demonstration Ninoded During She ("resector-ization for Geologic Repository" & "Representativeness of Host Rock Parameter Values Throughout Geologic Repository," per Contract NRC 02-84-092 CUMMINGS A Engineers International, Inc. FIN D.-1004 1146-09-03 88/12/15 BUCKLEY J.T. NRC No Detailed Affiliation Given 1p. 47849 177-47849:233
 - -8812190167 "Representativeness of Host Rock Paramuter Values Throughout Geologic Repository Site."

 * Engineers International, Inc. FIN D-1004_NRC-02-84-002_88/12/31_NRC-No Detailed Affiliation Givon. 25pp. 47849 178-47849 202
 - -8812190169 "Lovel of Retrieval Demonstration Neudod Dering Site Characterization for Geologic Repository"
 Engineers International, Inc. FIN D-1004 NRC-02-84-002 88/12/31, NRC No De-
 - tailed Affiliation Given, 31pp, 47849,203-47849,233. 8812190163 Geochemical Evaluation of Contaminant Production & Transport at U Re-
 - covery Operations," monthly rept for Nov 1988 Financial into withhold HOSTETLER.C.J. Batto'in Momorial Institute, Pricitic Northwest Laboratory FIN B-2482-88/12/15 DEERING. Office of Nuclear Material Safety & Safetyards, Director. 17pp 47869.335 47869.351
- 8812190173 Hospands to 881104 ftr from K Draycentte re Rockfeller Univ BRC Petition FRM 20-18 Ltr requested review of polluterers use of code, and 8 expalls personers solution of data parameter, re-run 8 code using polluterers input data. CRANNELL, R.M. Sanda, National Laboratories. FIN A-1763, 88/12/14 GLENN, C. Regulatory Branch. 63pp. 47848-343-47840-045.
- 8812190177 Forwards DOE wouldy rupt for week ending 881202
 PRESTHOLT.P.T. NRC No Detailed Affiliation Given 88712713 LINEPANUJ Repository Licensing Project Directorate (881013-881119) 4pp 47853 255-47853 258
- 8812190186 "NRC Technical Assistance for Dusign Reviews," Progress Rept 40 for Nov 1989 Financial into with-old HART-RD ITASCA Consulting Group, Inc. F/N D-1016 NRC-02-85-002 85/12/12 TANIOUSN. Office of Nuclear Material Safuty & Safeguards, Proctor Gpt. 47663-352-352-352-352-352-352
- 8812190192 Forwards Draft Topical Ribpt 06:01-17, "Soluction of Sual Mails for thight Level Waste Repository Soaling," por Task Order 006 HART.RD. ITASCA Consulting Group, Inc. FIN D-1016 NRC-02-85-002 88/12/14. TANIOUS,N NRC No Detailed Afficience Given: 1p. 47855-067-47855:100
- -8812190201 008-01-17 "Selection of Seal Malls for High Love! Waste Repository Soaling DAEMEN,J., LORIG,L. HART,R.D. ITASCA Consulting Group, Inc. FIN D.1816. NRC-02-85-002 88/12/31 NRC · No. Detailed Affiliation Given 39pp. 47655.068-47855-106
- 8812190197 Ferwards notice of upcoming NRC/DOE meetings for 831220 & 890105 Notice 1ats tentative & firmly established meetings & will be updated *cekty. LINEHANJ.J. Repository Licensing Project Directoratic (881013-881119), 86/12/19. Afficiation Nat Assigned. 2pp. 47853 358-47853 359
- 8812190217 Requests no-cost extension of period of performance for Contract NBC-92-85-009, "Technology Assistance in Hydrogeology-Project B." due to incompatible schedule for rept assosang centract. Proposed schedule has de to incompatible schedule for rept assosang centract. Proposed schedule has de to incompatible schedule for rept assosang centract. Proposed schedule has de to incompatible to incompatible for rept association of the proposed schedule for the proposed schedule fo 8812190226 Confirms transmittal dates for revised research project plans discussed
- duning Nov 1988 project mgi mesting. Distorial of transportation risk study operations plan until 88 1219 recommanded.
 LTZ_JE Contas for Nuclear Washin Regulatory Analysis NRC-92-88-005, 88/12/07 MACEMH. Dission of Contracts & Property Management (Post 880515) 3pp 47850:131-47850:133
- 8812190234 Forwards Rev. 2 to "NNWSI QA Plan." Plan revised to address six oper-liams listed in NRC 881014 safety evaluation, including changes made for clarty & Improvement of program per 881118 meeting & subsequent conference de la STEUN,R. Energy, Oper of 88/12/13, YOUNGBLOOD,BJ Division of High Lowel Waste Management (Post 870413), 1p. 47854.138.47854.317.
- -8812190239 Rev 2 to "NNWS! OA Plan" BLAYLOCK,J., GERTZ,C. Energy, Dept. of. 88/12/07, 178pp. 47854;139.47654;317.
- 8812190273 Responds to 881206 ftr re delays in delivering camera-ready copy of groundwater that model rept Rept will be delivered by 881219 & camera-ready copy by 990125.
- BONANOE J. Sand'a National Laboratories. FIN A-1158 88/12/12. COLEMAN M.M. Geoscience & Systems Performance Branch (Post 880911). 1p. 47853335-47853:335.

- 8812193284 Forwards scope of proposed technical position on geologic mapping of
- salis & drifts of geologic repository.

 BALLARD,R.L. Geoscience & Systems Performance Branch (Post 880911), 08/12/15
 BROWNING,R.E. Dwiston of High Level Waste Management (Post 870413) 8pp
 47853:300-47853:307
- 8312190304 Forwards summary of 881208 meeting w/DOE re exploratory shall design acceptability analysis list of attendees & prosentation on status of flowdown analysis also encl
 - LINEHAN, J.J. Operations Branch (870413-880910), 88/12/15, STEIN,R. Energy, Dept of, 71pp, 47860-125-47860:196.
- 8812190307 Forwards summary of 881019-21 meeting w/DOE, State of NV, Nye County Util Nuclear Waste Mgt Group & GAO re exploratory shell facility Agenda, ist of extendeds & handouts also encl. INELIAN, J. Repository Licensing Project Directorate (881013-881119), 88/12/14. STEIN, R. Energy, Dopt of 300pp. 47839.122-47840:123.

- 8812190324 Forwards scope of technical position dealing w/use of alternative conceptual tectonic mode's in performance allocation & performance assessment of geologic
- repository.

 BALLARD,R.L. Geoscience & Systems Performance Brench (Post 860911) 86/12/15.

 BROWN NG,R.E. Division of 1/gh Lovel Waste Management (Post 870413). 12pp. 47653:282-47853:29.
- 8812219042 Ack receipt of 881101 Ill transmitting "Assessment of Potential Effects of Fazardous Wastes in Ambrosia Leke Tailings" Large vols of liquide should be minimixed prior to disposal in failings pond.

 HAWKINS,E.F. Uranium Rocovery Floid Otc., R4 89/11/30. ARTHUR,W.J. Energy.
 Dept. of 2pp. 47876 048 47876 049.
- 8812210060 Provides results of 880327-29 field Investigation in vicinity of Mexican Hat UMTRAP site Purpose was to identify locations & origin of three seeps previously
 - DUPUY, J., RICE, G. Jacobs Engineering Group, Inc. 88/05/10. AGOGINO,K. Jacobs Engineering Group, Inc. 9pp. 47876 029-47876.037.
- 6812210067 Forwards analytical data for past two quarters of water sampling by location parameter & unit of measure. BOS.UEVAC.F. Energy, Dept of: 88/11/23. OLSEN,T. Uranium Recovery Field Ofc, R4.7pp 47882-005-47882-011.
- 8812210101 Provides certification concurrence on vicinity proporty completion rept for property Location CA-1335 in Canonsburg, PA, per 881027 request. SMITH,R D. Uranium Rocovery Field Otc, R4. 88/11/28. ARTHUR,W.J. Energy, Dept. of 3pp. 47881:274-47881:276
- 8812210124 Forwards calculations for radon barrier thickness for UMTRA site, Tuba City AZ Calculations demonstrate that 3.5 it barrier thickness proposed in remedial action plan more than adequate to satisfy EPA sitt for radon omission ARTHUR, W.J. Energy, Dept. of. 88/11/16 HAWKINS, E.F. Urantum Recovery Field Cit, R4, 112pp, 47807.077-47907:188.
- 8812210192 Requests meeting bewtween NRC & State of NV within next few months to lidessly into required by CNWRA.

 BROWNING.R.E. Division of High Lovel Weste Management (Post 870413) 88/12/19. LOUX.R. Nevada. State of. 2pp. 47874:359-47874:360.
- 8812210220 Forwards site characterization plan ref list.
 PRESTHOUT,P.T. NRC No Dotated Affiliation Given, 88/12/16, UNEHAN,J.J. Repository Licensing Project Directorate (881013-881118), 1p. 47878:311-47879.167.
- →8812270215 Forwards most recent ref list for site characterization plan for Yucca
 - Mountain,por request BLANCHARD,M.B. Energy, Dept. of. 88/12/07. PRESTHOLT,P.T. NRC No Detailed Aff. et an Given. 200pp. 47878:312-47879:167.
- 8812210225 "Assessment of NMSS Financial Assurance Regulatory Framework," monthly progress rept for Nov 1888 Financial data evallable in Central Fires. BAILEY, P.E., KOLSKY, K.B. ICF, Inc. FIN D-1047. NRG-02-87-002. 88/11/30. NRG-No Detailed Althalton Given. 4pp. 47888:078-47888 079.
- 8812210231 Forwards Rev 1 to alto "Remedial Action Insp Plan," for review & concur-rence within 21 days of receipt of litr. ARTHUR,W.J. Energy, Dept. of. 88/08/02. HAWKINS,E.F. Uranium Recovery Flotd Otc, R4. 1p. 47881:107-47881:121.
- -8812210233 Rev 1 to Remodial Action Insp Plan 1, "Tosting & Insp." CATE, P.D. MK-Ferguson Co. 87/07/01, 14pp, 47881;108-47881;121.
- 8812210318 Submits into for review & approval re 880812 Mexican hat remedial action Insp plan which contained test method not covered by NRC staff technical position. ARTHUR, W.J. Energy, Dept. of. 88/11/29. HAWKINS, E.F. Urentum Recovery Fle'd Otc, R4. 2pp. 47875;140-47875;141.
- 8812210375 Requests addituming to cover operations for Second Quarter FY89 re Fin A 4171-9, "Evaluation & Compliction of DOE Weste Package Test Date."

 BUNTING, J.O. Engineering Branch (Post 880911). FIN A 4171, 98/12/20. FUNCHES, J.L. Program Management, Policy Development & Analysis Staff (Post 670413). 34pp. 47886:231-47888:264.
- 8812210399 Comments on items of concern Identified by NRC re-technical assistance request notice provided by OOE at 881208 meeting on exploratory shaft (actify design acceptability analysis, per 881214 telcon Response to comments requested. UNEHAN,J.J. Repository Licensing Project Directorate (881013-881119), 88/12/19. STEIN,R. Energy, Dept. of. 4pp. 47876.018-47876.021.
- 8812210406 Forwards "Review Plan for NRC Staff Review of DOE Site Characterization
- Flati. LINEHAN.J.J. Repository Licensing Project Directorate (8B1013-861119). 88/12/21. STEIN.R. Energy, Dopt. of. 1p. 47877:344-47878:206.
- 8812220048 "Delinition of Solute Transportation Mechanisms at Low Lovel Waste Disposel Sitos in Support of Transport Modeling," monthly progress rept for Nov 1988.Fl-nancial into available in Central Files. RRUPKA,K.M. Battelle Memorial Institute, Pacific Northwest Laboratory. Fin B-2483. 88/12/14. DEFRING,L.F. Office of Nuclear Material Safety & Safeguards,Director. 4pp. 47892:331-47892:334.

- 8812220060 Forwards revised draft rept. Design of Impoundment & Disposal Factities for U Mill Tarlings & Rehabilitation of Taring Piles," per TCM on 881107-11 Comments welcomed FERADAY,M.A., International Alomic Energy Agency, 842-1 GNUGNOLI,G Operations Branch, 44pp. 47809;258-47910 102. 642-T2-TC-668 89/12/13
 - -8812220064 0622Y DRFT F04 Orati Rev 4 to "Design of Impoundment & Disposal Facilities for U Mrt Teilings & Rehebilitation of Teiling Pros."
 * International Atomic Energy Agency, 88/12/02, 168pp. 47909,300-47810 102
 - 8812220307 Forwards notice of upcoming NRC/DOE technical/programmatic meetings re NRC high level waste migl program.

 LINEHAN,J.J. Repository Licensing Project Directorate (881013-881119), 88/12/27

 NRC - No Detailed Athliet on Given: 2pp. 47692 227-47892:228

 - 8812220311 "Analyses of Special Wasto Problems," monthly mgt ropt for Nov 1988 under Fith A-3175 Financial into available in Central Files only. BARI,R.A. Brookhaven National Laboratory: FIN A-3175. 68/12/19 WIDMAYER,D Technical Branch. 6pp. 47945-178-47945-183
 - 8812220316 Publicly available portion of "Development of Low Lovel Waste Form Crite-na License Fees," monthly mgt root for Nov 1988 BARLR A. Brookhaven National Laboratory, FIN A-3174 88712719, TIKTINSKY,D, Technical Branch, 9pp 47914:232-47914 240.
 - 8812220329 "Development of Criteria for Matts Used in Engineered Components 8 Waste Forms at Near-Surface Low Level Waste Faculies," monthly ingt rept for Nov 1988 Financial Into withhold BARLR A. Brookhayen National Laboratory. 88/12/19 TIKTINSKY.D. Technical
 - Branch, 4pp 47916;164-47916;167
- 8812220347 Forwards completed Yucca Mountain Project Oic QA Audit 88 05 chocklist.per J Ho'on'ch request during audit on 880725-0903. STEIN.R. Energy, Dopt. of 881/2/18 LINEHAN.J. D.vision of High Level Waste Management (Post 970413) 228pp 47902.001-47902.281.
- 8812220367 Forwards Roy 1 to QA program description for civilian radwaste mgt program.per 881118 resolution meeting among NRC,DQE Ofc of Cryltan Radwaste Mgt Ofc of QA,Licensing Branch & reprosentative from State of NV. APPEL,G. Energy, Dept. of 88112/21, LINEHAN,J J. Repository Licensing Project Directorate (881013-681119), 1p. 47913/317-47914.040.
- -8812220371 Rev 1 to "OA Program Description for Civitian Redwaste Mgt Program BARRETT,L., ROUSSO,S. Energy, Dept. of. 88712720, 83pp. 47913:318-47914.040

WASTE RES WASTE MANAGEMENT RESEARCH REPORTS

- 8811280115 "Risk Assessment & Cost Estimation For Cleanup of Rad pactive Materia"," monthly copt for Oct 1988 Findocal estimate available in Contral Files CRANWELL,RM, Sandia National Laboratories FIN A-1761, 88/11/14 BYKOSKIL, Regulatory Branch, 3pp. 47655 267-47655 269.
- 8811290166 Forwards, "NNWSI Conceptual Model Update:NNWS! Repository Project Sublask 1.4." Rept. dentifies listed tiems to hydrogeologic systematic what is known
- to Hought to be known about each elament to hydrogeologic systems of the top of thought to be known about each elament LOGSDON,M.J. Nuclear Waste Consultants, Inc. FIN D-1021, 283, 88/11/18 POHLE,J. Division of High Level Waste Management (Post 870413), 2pp. 47696.001-47696 195
- ~8811290176 "NNWSI Conceptual Model Update:NNWSI Repository Project Subtask 1.4." W/livo oversize drawings SNIFF, T.L., CARMIEN, M.C., DAVIS, LA. Water, Wasie & Land, Inc. 88/11/30. NRC -No Detailed Albi airon Given. 175pp. 47698-003-47898-195.
- 8811290516 Forwards comments on "Evaluation & Compilation of DOE Waste Package Test Data," monthly rept for Aug 1986,FIN A-4171. Actions considered to be within scope of FIN A-4171. PETERSON,C.T. Engineering Branch (Post 880911). FIN A-4171. 88/11/25. INTERRANTE,C.G. National Institute of Standards & Technology (formarly National Bureau of Standa, 7pp. 47665-103-47605-109.
- 8811300230 Forwards Task Order 23 to Contract NRC-02-84-001, "Technical Assistance in Geophysical Methods for Site Characterization," to assist NRC in reviewing final site characterization plan 8 nesociated study plans IBRAHIM,A.K. Geoscience & Systems Porformance Branch (Post 880911). NRC-02-84-001-88/11/29, MEEHAN,B. NRC No Deteiled Affiliation Given, 5pp. 47671:318.
- 8812010293 Forwards schedula for completion of outstanding fit repts documenting status of work at present on FIN A-1756.per 881117 request NRC should modify contract reflecting rev in scope of work & completion of outstanding repts by 890331. BONANO.E.J. Sandla National Laboratorios. FIN A-1756. 89/11/21. MO.T. Geosci ence & Systems Performance Brench (Post 860011). 2pp. 47709:192-47709:193
- 8812010422 Comments on draft Ltr Rept 1.3B, "Processes Which Should Be independ ently Evaluated By NRC." Rept contains several fundamental aspects that need further consideration & rev. BROCKS,P. Geoscience & Systems Performance Branch (Post 880911). FIN A-1165 86/11/29, BONANO,E.J. Sanda National Laboratories, 13pp. 47703.083-47703.075
- 8812050240 "Analyses of Special Waste Problems," monthly mgt rept for Oct 1986 under FIN A-3175. BARI,R.A. Brookheven National Laboratory, FIN A-3175. 88/11/18, WIDMAYER,D Technical Branch. 4pp, 47860.001-47880.008.
- -8812050244 "Analyses of Special Waste Problems," monthly mgt rept for Oct 1988 SISKIMD,8. Brookhaven National Laboratory, F/N A-1175, 68/11/18. Technica Branch, 2pp. 47660.005-47660.008.
- 8812050308 Forwards rev of comments, questions & requests for addition or topics rept, "Waste Form Cortification Program-Rept III: Cement Binder Chemistry." SISKIND,B Brookhaven National Laboratory, FIN A-3174, 88/12/02. Document Control Branch (Document Control Branch (Document Control Desk), 2pp. 47731:190-47731:200.

- ≈8812080014 Forwards roy of comments,questons & requests for additinto to topical rept, "Weste Form Certification Program-Rept III. Comont Binder Chemistry."
 SIKINDA Brockhaven Natural Laboratory, Fitt A:3174, 88/12/01 MCDAN-EL,K Technical Branch. Spp. 47731:192-47731.200
- 8812050314 Forwards comments on draft rept, "Review of Uncertainties Relovant in Performance Assessment of High Loyal Radwasto Respositories" BROOKS,P. Geoscience & Sysiema Performance Branch (Post 880911). FIN A-1105-88112702. BONANO,E.J. Sand a National Laborationes 9pp. 47740.193-47740.203.
- 8812060231 "Performance Assessment of Low Level Radweste S.tes," annual surrowary project rept for FIN B-2485 Cost info in Central Files BERGERDN MP. Battette Momortal Institute, Pacific Northwest Laboratory. FIN B-2485
- 8812090246 Forwards draft rept entitled, "Level of Retrieval Demonstration Noeded During Site Characterization for Geologic Repository." CUMMINGS,RIA Engineer's International, Inc. FIN D-1004, 1148-09-01, 88/12/03, BUCKLEY,JT, NRC No Octated Attiliation Given 1p. 47775-204-47775.255.
- -8812090248 Draft "Level of Retrieval Demonstration Needed During Site Characterization for Geologic Repository"

 Engineers International, Inc. F:N 0-1004, NRC-02-84-002, 88/12/31, NRC No Detailed Affiliation Given, 31pp, 47775-205-47775-236.
- 8812120218 Forwards revised Page 3 of final draft "Status of Lode- Quartz Claims on Yucca Mountain,Nye County,NV."
 WELDINJR D Interior, Dept. 01, Butteau of Mires FIN D-1018, NRC-02-85-904, 86/12/07. ABRAMS,C NRC No Detailed Affit atton Given 2pp. 47786-060 47785-061
- 8812120224 Publicly available portion of trip rept of 881121-22 meeting in Rockyllo,MD re in ellu testing CUMMINGS,R.A. Engineers International, Inc. FIN D-1004. 143 88/11/30 BUCKLEY,J.T. NRC - No Deta led Affiliation Given. 4pp. 47798-005-47798-008
- 8812140119 Forwards final repts for Subtasks 02, "Appropriate Models, Tests & Assumptions for Predicting Ventilation Requirements During Retrieval," & 04, "Abalysis of Ventilation Plan Contained in CO-SCP," HUCK, P.J. Engineers International, Inc. FIN D-1004, NRC-02-64-002 88/12/12, BUCKLEY, J.T. NRC No Delaired Afficiation Gwen. 11pp. 47814 195-47614:348.
- --8812140123 "Appropriate Models,Tasta & Assumptions for Predicting Ventilation Fla-quirements During Rethoval," linet rept. HUCK,P.J., LAURITO.A.W. Engineers International, Inc. NRC-02-84-002 88/12/31 Engineering Bracch (Post 880811) 29pp. 47814 208-47814 233.
- --8812140125 "Analysis of Verhielion Plan Contained in CD-SCP," final rept HUCK,P.J., LAURITO,A.W. Engineers International, Inc. NRC-02-84-002, 86/12/31 Engineering Brench (Post 889911), 115pp. 47814-234-47814-348
- 8812140134 Forwards final draft of "Review of NNWSI S.te Characterization Plan Con-ceptual Design Rept for Repository at Yucca Mountain NV," per Task Order 07 CUMMINGS.R.A. Engineers Internal onal, Inc. FIN. D-1004, 1148-07, 88/12/12 DUCKLEY,J.T. NRC No Data led Attribution Given. 1p. 47814-349-47835;137.
- -8812140140 "Review of NNWSI Site Characterization Plan Conceptual Design Rept for Repository at Yucca Mountain,NV," 1 hal rept * Engineers International, Inc. FIN. 0-1004, NRC-02-84-002, 88/12/31, NRC No Ostelled Affiliation Given, 148pp. 47814-350-47815;137.
- 8812140156 "Licensing Methodology Assistance," monthly rept for Nov 1988.Encl in Central Fres.

 BONANO,E J. Sandia National Laboratories FIN A-1165 88/12/15. TIKTINSKY D.H.

 Division of High Level Waste Management (Post 870413) 11pp 47828 054-
- 8812140173 Forwards "Technical Ropt on Const Specs for Exploratory Shaft Facility," PRBI 100E. CUMMINGS,R.A. Engineers International, Inc. FIN D-1004 1148-09-05 88/12/09. BUCKLEY,J.T. NRC - No Dotel ed Affil atlon Given. 1p. 47799.187-47799.212.
- -8812140179 "Technical Rept on Const Specs for Exploratory Shaft Facility," final rept

 * Engineers International, Inc. FIN 0-1004, NRC-02-84-002, 88/12/31, NRC No Oetalled Alt.liation Given 25pp. 47799:188-47799.212.
- 8812160187 Forwards "Prefirmary Review of Low Sun Angle Air Photos From Yucca Mountain Area," technical tit rept. CHUNG, D.H. Lawrence Livermore National Laboratory, FIN A-0297, L-198, 88/12/10 BLACKFORD, M.E. Division of High Level Waste Management (Post 870413), 1p. 47832.286-47832:306.
- -8612190023 "Proliminary Review of Low Sun Angle Air Photos From Yucca Mountain Area."
 MCKAGUE H L CARPENTER D.W. Lewronce Livermore National Laboratory, FIN A. 0297, 88/12/10, NRC - No Detailed Affiliation Given 10pp, 47832,297-47832,306.
- 8812190131 Publicty available portion of "Performance Assessment Methodology Development Low Level Waste Disposal Safety Assessment," monthly rept for Nov 1988 BONANO,E J. Sand a National Laboratories FiN A-1764. 88/12/15. DEER:NG,L. Technical Branch. 4pp. 47870-001-47870-004.
- 8812190149 "Evaluation, Validation, Verification & Documentation of IMPACTS-BRC Computer Code," monthly rept for Nov 1988 Cost Info withheld. CRANWELL, R.M. Sandia National Laborations. FIN A-1783. 88/12/06. GLENN, C. Regulatory Branch. 3pp. 47835:170-47835:172.
- 8812190169 Forwards "Level of Reinaval Demonstration Needed During Site Characterization for Geologic Repository" & "Representativeness of Host Rock Parameter Values Throughout Geologic Repository," per Contract NRC-02-84-002. CUMMINGS.R.A. Engineers International, Inc. FIN D-1004. 1148-09-03, 88/12/15. BUCKLEY,J.T. NRC No Detaled Affiliation Given. 1p. 47849-177-47849-239.
- -8812190167 "Representativeness of Host Rock Parameter Values Throughout Geologto Repository Site."

 * Engineers International, Inc. FIN D-1004. NRC-02-84-002. 88/12/31. NRC - No Detailed Affiliation Given. 25pp. 47849:178-47849.202.

- -8812190169 "Level of Retneval Demonstration Needed During Site Characte Izeloc 86 (2190 foot - French of French of
- 8812190163 "Geochemical Evaluation of Contaminant Production & Transport at U.Re-covery Operations," monthly right for Nov-1988 Financial in to with heigh HOS's ETLERIC J. Battellin Memorial Institute, Product Northwest Laborator, FP4 8-2482, 88/12/15, BEERING L. Office of Nuclear Material Safety & Safeguads, Director 17pp 47869 335 47869 351
- 8812190173 Responds to 891104 fir from K Dragonolle re Flockleffer Unit 8RC Petition PRM-20-18 Lit requested review of politioners use of code, verify & explain politicides selection of data parameter, or min & code using politioners input data. CHANWELL, RIM. Sand a National Laboratories FIN A-1763 88/12/14, GLERRIC, Regulatory Branch 63pp. 47848 343-47849 045
- 8812190186 "NRC Technical Assistance for Design Reviews," Progress Rept. 40 for P12190186 NIGO TOCHICAN ASSISTANCE OF COMPLET CONTROL OF CONTROL O 47889 357
- 8812190192 Forwards Draft Topical Rept 05 01-17, "Selection of Sea Mail's for High Level Waste Repository Souting," per Task Order 038 HART,R D. ITASCA Consulting Group, Inc. FIN D-1016 NHC-02-85-592 68/12/14 TANIOUS,N NRC No Datating Affirmation Given 1p 47855:067-47855-106
- -9812190201 006 01-17 "Selection of Seal Mails for High Level Wasta Repository Spanig **
 DAEMEN,J, LORIG,L, HAHT,R D. ITASCA Consulting Group, Inc. FIN D-1816, MRC 902-85 002, 887/12731 NRC No. Dotated Attitution Given 38pp. 47855 068-47855,106.
- 8812190217 Requests no cost extension of period of performance for Contract NEC (2-85-009, "Technology Assistance in Hydrogeology Project B." due to mompatible schedule for rept assessing contract Proposed schedule field LOGSDON,M.J. Nuclear Waste Consultants, Inc. NRC 02-85-009 88712714 PORLE,J. NRC No Dutafud Affiliation Given 3pp. 47853-250-47853-252
- 8812190273 Respects to 881206 ltr re detays in delivering camera reary copy of groundwater flow model rupt Rept will be delivered by 861219 & camera rear by 660120 BONAND,E J. Sanula Nutlonal Laboratorios FIN A-1158, 88/12/12 CO:EMAN.A.M. Goosciooco & Systems Purformanco Branch (Post 880911) 1p 47853-335 47853 335
- 8812210225 "Assessment of NMSS Financial Assurance Regulatory Francowork, morthly progress right for Nov. 1088 Financial data evaluated in Control Fres BAILETY FE., KOLSKYK B. ICF, Inc. FIN Q-1047, NRC Q2-87-002, 88/11/30 NRC NO Detailed Affiliation Given, 4pp. 47888 076-47888 079.
- 8812210375 Requests additionally to cover operations for Second Quarter FY69 for Fw A-4171-9, "Evaluation & Complication of DOE Wuste Package Tost Date" BUNTING, J.O. Engineering Branch (Post 880911) Filt A-4171 63/12/20 FUNCHES, J. Program Management, Policy Development & Analysis Staff (Post 870413) 34pp. 47888,231-47888,264.
- 8812220048 "Definition of Solute Transportation Mechanisms of Low Level Wasto Osposal Sites in Support of Transport Medeling," monthly progress replifer New 1938 Function for swillable in Central Fres.

 KRUPKA,K.M. Bettel's Memorial Institute, Pacific Northwest Leberatory FIN 8 2483
 88/12/14, DEFENIOLE, Office of Nuclear Material Safety & Safeguards, Circetor 4pp. 47892/331-47992/334
- 8812220311 "Analyses of Special Weste Problems," monthly right rept for the 1988 under FIN A-3175 Financial into available in Contral Files only. BARILA. Brockhoven National Laboratory FIN A-3176. 88/12/19. WIDMAYER,D Technical Branch. 6pp. 47945;178-47945;183.
- 8812220316 Publicly available portion of "Development of Low Level Wasta Form Criteria" License Foos," monthly mgt rept for Nov 1998. 8ARILRA, Brookhaven National Labcratory, FIN A-3174, 88/12/19 FIKT NSKY,O Tochnical Branch. 9pp. 47914 232-47014:240.
- 8812220329 "Development of Criteria for Matts Used In Engineered Components S Waste Forms at Neer-Surface Low Lovel Waste Facilities," monthly mgt rept for Nev 1998 Financial Info withhold.

 BARILITA Brookhavon National Laboratory. 88/12/18. TIKTINSKY,0. Tochnica
 Branch. 4pp. 47916:184-47916:187.

XPORTLIC EXPORT AND IMPORT LICENSES

- 8811300128 Requests Executive Branch position to DOE Richfand Operators O'd application for license to expert six irradiated FFTF fuel rods to Japan PETERSONM R. Assistant Director for international Security. 38711718 THORNE,C.E. State, Dopt. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs 1p. 47697.351-47697.355.
- --8811300132 Application for license to export six triadiated fuel rods, crepped t, ramove hardware containing Pu deptated U mixed existence fuel pollote, to Japan HUNTER, J.R. Energy, Dopt of WR-F824, 88/11/17, 20pp. 47753:137-47753 156.
- -8811300136 Forwards application for ticense to export six irradiated fuel rods. Japan W/o stated enct. HUNTER J.R. Energy, Dept. of. 88/11/17. MOORE,R N. International Programs. 324 47897-353-47697-355.
- 8811300380 Forwards Advanced Nuclear Fuels supplemental application for amend a license to export Canadian origin mail to West Germany Lit of assurance required PETERSON.M.R. Assistant Director for international Security. 88/11/23 HART, Energy, Dept. of. 1p 47897.258-47897:261.

- it 1300417 Supplemental application to amend I conso to export 2,500 kg total U,to lest Germany,revising 881020 application to Indicate that load assemblies will originate from Canada.

 18. (DP) C. W. Advancod Nuclear Fuels Corp. (formarly Exxon Nuclear Co., Inc.), 88/1/15 PETERSON,M.R. Assistant Oiroctor for International Security, 1p. 47697,259-
- 2080078 Forwards DOE 881117 ltr re addl info to support 881118 application for Acort Litense XSNM-2419.
 EFERSONMIR: Assistant Director for International Security. 88/12/02.
 HORNE, C.E. State, Dept. of, Bureau of Oceans & Intl. Environ & Scientific Affairs.
 p. 47753 134-47753-136.
- 2080C06 Forwards application for Ecense to export enriched UF6 to Spain. ISK R.F., Ediow International Co. 88/11/30, WRIGHT,B. NRC No Detailed Attiliation (ren. 1p. 47757-001-47757:002.
- kt2030087 Application for license to export 15,620 kg emiched UF6,to Spain. ISK.3 H., Edlow International Co. ENUSA E.4. 88/11/30. 1p. 47757.002-47757.002. 2030600 Forwards application for license to export fisson chamber to older's a Views on wholf-er export mosts criteria requested.
 6: ERSCN,M.R. Assistant Oriector for International Socurity, 86/12/02.
 10DPHE,C.E. State, Dopt. of, Bureau of Oceans & Intl. Environ & Scientific Affairs p. 47783-315.
- 1208C093 Application for fleense to export one neutron flux monitor w/essociated ectronics to Bogots,Colombia. SWIJSEN K.E. General Atonics (formerly GA Technologies, Inc./Genoral Atomic.o.) IEL-1301 88/11/23. 1p. 47783.316.47783:316. 12080098 Forwards application for export license for neutron flux modifier to be report to institute D E ASUNTOS NUCLEARES, Bogota Colombia SNUSSEN,K.E. General Atomics (formorly GA Technologies, Inc / General Atomic o) EL-1301, 88/11/23. PETERSON,M.R. International Programs 2pp. 47783-317-7763-316
- 2280142 Forwards application for export I cense for low enriched U for use as fuel in amacke Unit 2 Ltr of assurance requested. ETERSON,M.R., Assistent Director for International Security, 89/12/02. HORNECE State, Dept of Bureau of Oceans & Intl. Environ. & Scientific Atlet's. p. 47754/219-47754/220.
- I12080148 Application for license to export UF6.containing 717 kg U-235.to Japan. TECA, V Milsur & Co. (USA), Inc. (augs. of Mitsul & Co., Ltd.). MBK-H2-R10 (A). 88/1721. 1p. 47754:220-47754:220.
- 2080151 Application to amend licenses to export listed matts to Korea & Germany. EDRGE,M. Franshuclear, Inc. 88/11/22. PETERSON,M.R. NRC No Detailed Affiliation Given 1p. 47783:184-47783:184.
- 2080160 Provides Executive Branch position to C-E application to export irradiated let elements & associated hardware to Canada Recommends that license be Issued TRATFORD.A.J. State, Dopt. of, Bureau of Oceans & Infl. Environ. & Scientific After Sept. 1725. SHEA.J.R. NRC No Detailed Affiliation Given. 2pp. 47753 209-7753:210
- 2080 17.1 Furwards fir from Misul & Co to Item 22 in application for amond to carso Country of origin of source mall being changed from Canada to nknown Request should be considered in conjunction w/original application. ETERSCN,M.R. Assistant Director for International Security. 88/12/02 HOPNEC.C. State, Dept. ot, Bureau of Oceans & Intl. Environ. & Scientific Affors. p. 47756:206-47756:209.
- 112090173 Informs of revito 880722 application for amend to license. Country of right changed to unknown. &DAIM MILSU & CO. (USA), Inc. (subs. of Milsut & Co., Ltd.): 89/11/29. NRC No lecalled Alf-hation Given. 1p. 47756:207-47758:209.
- 2080185 Forwards application for license to export low enriched U for use as fuel in larracka Unit 2 Lir of assurance required. ETERSCN,M R. Assistant Director for International Security. 88/12/02 HORNE, C.C. State, Dopt. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs o. 47783 249-47783:250.
- 312080188 AppFication for license to export 286 kg U-236,88 UF6 to Japan. KEDA,M. Mitsui & Co. (USA), Inc. (subs. of Mitsui & Co., Ltd.), B8/11/21, 1p. 7783:250-47783:250.
- 2080199 Forwards application for export license for low enriched U for use as fuel in 'mariar-1.Lir of assurance required. ETERSON,MET Assistant Director for International Security, 88/12/02, ROONEY,J. (nergy, Dept. of. 1p. 69578:163-69578:163.
- 2080226 Application for license to export 9,061 kg UF8,contained in 286 kg U-235,to
- อกลา <a>CDA,M, Milsui & Co. (USA), Inc. (subs. of Milsul & Co., Ltd.). MBK-H2-R10 (B). 68/ 1/21. 1p. 47750.084-47750.084.
- 12120067 Requests route plan for 1988 from east coast port of Portsmouth,VA to INCE Savannath River plant in Alken,SC. RAVENSCHOFT,N, Edlow International Co. 24981, 88/11/16, HILLMAN,C. Office of Luctear Material Safety & Safeguards,Director. 2pp. 47780:150-47780:150.
- 2130061 Forwards application for export license for low enriched U for use in South Grea Ur of assurance required ETERSON,M.R. Assistant Director for International Security, 88/12/06, ROONEY,J. Inergy, Dept. of. 19. 47797;118-47797;121.
- 812130082 Application for license to export 8,342 kg U,containing enriched U-235,to
- South Korga. CUAIN.P.B. Transnuclear, Inc. RBU-488, 88/10/10, 2pp. 47797;117-47797;118.
- 812130064 Forwards three license applications for handling as listed. CUAIN,P.B. Transnuclear, Inc. RBU-486, 88/10/13, NRC No Detailed Affiliation 3 ven 1p. 47787:118-47797:119.
- 812130065 Forwards 881111 telex re License XSNM-2408. QUAIN,P.B. Transnuclear, Inc. 88/11/14. NRC No Detailed Attiliation Given. 2pp. 17797-120-47797:121.

- 8812130068 Forwards application for export license for low enriched U for use in Japan Lir of assurance required:
 PETERSON,MR. Assistant Director for International Security 88/12/07
 THORNECE State Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs
 1p. 47792 303-47792 304.
- --8812130074 Application for license to export 29,125 kg U,containing enriched U-235,to Japan UEMIYA,S Marubeni America Corp (subs. of Marubeni Corp.) 58/12/05 1p 47792:304-47792:304
- BB12130075 Forwards application for export Idense for low enriched U for use in Japan Lir of assurance required PETERSON,M.R. Assistant Director for International Security, 88/12/07. THORNE,C.E. State, Copt. of, Bureau of Oceans & Intl. Environ & Scientific Affairs 1p. 47796/055-47798/058.
- -8812130080 Application for license to export 38,122 kg U,containing 1,316 kg U-235.to Japan.
 * Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5489 08. 88/12/01 1p. 47796 058-47796 056
- -8812130088 Forwards application in triplicate for licence to export slightly enriched MARIUYAMA, T. Milautrishi International Corp. (subs. of Mitsubishi Corp.). HSA-5489-06-88/12/02, NRC - No Detailed Affiliation Given, 2pp. 47798:057-47788.058.
- 8812130184 Forwards application for export Iconse for low enriched U for use in Japan Ltr of assurance required.
 PETERSON,M.H. Assistant Director for International Security 88/12/07. THORNE, C.E. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs 1p. 47794:066-47794:067.
- -8812130186 Application for Leanse to expert 7,585 kg U,containing 248 kg U-235,to Japan.
 UEMIYA S. Maruboni America Corp. (subs. of Maruboni Corp.). JJ5701-88/12/05. 1p.
 47794-087-47794-087.
- 8812130188 Forwards application for expert Idense for low enriched U for use in Japan Lir of assulance required.

 Japan Lir of assulance required.

 PETERSON M.R. Assistant Director for International Security 86/12/07.

 THORNE, C.E. State, Dopt. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs.

 1p. 47794.092-47794.065.
- -8812130193 Application for license to export 1,508 kg contained in 75 kg U-235,to Japan.
 • Misubishi International Corp. (subs of Misubishi Corp.) HSA-7649-00 88/12/02. 1p. 47794.063-47794.063
- --8812130195 Forwards application for license to expert slightly enriched UF6 MARUYAMA,T, Missurshi International Corp. (subs. of Missurshi International Corp. (subs. of Missurshi Corp.) NY-HSA-116-00. 88/12/02. NRC No Detailed Affiliation Given 2pp. 47784:084-47784-085.
- 8812130252 Application to ronew license extending expiration date to 921031. ASMUSSEN,K.E. General Atomics (formerly GA Technologies, Inc./General Atomic Co.) IEL-1280, 88/09/27, PETERSON,M.F. International Programs, 1p. 47797.314-
- 8812130254 Application to renew license extending expiration data to 930101.
 ASMUSSEN, K.E. General Atomics (formarly GA Technologies, Inc./General Atomic
 Co.) IEL-1297. 88/11/18. PETERSON, M.R. International Programs. 1p. 47795-358-
- 8812150022 License for C-E to export reactor control red assembly, non-fueled red & fuel element assembly cage to Canada. PETERSON.M.R. Assistant Director for International Security. ITP2905-2 89/12/09. 1p. 47807 182-47807.182.
- 8812150034 Forwards application for license to export 7,210 kg enriched U hexafluoride to Japan.
 FISK,R.H. Ediow International Co. 88/12/05 WRIGHT,B. International Programs 1p 47800 258-47800:259.
- -8812150104 Application for ficonse to export 7,210 kg enriched U hexafluoride to
- FISK,R.H. Ediow International Co. KLK-48, 88/12/05, 1p. 47800:259 47800:250
- 8812150036 Application for Foonse to export 126,795 kg UF0.contained in 902 kg U-235,to Japan. IKEDA,M, Mitsul & Co. (USA), Inc. (subs. of Mitsul & Co., Utd.), MBK-DP-2, 88/12/05, 2pp. 47800:250-47800:251.
- 8812150054 Approves route to be used for transport of scent reactor fuel from Portsmouth,VA to Alken,SC,per 881116 ftr. Notification requirements of 10CFR73.37(f) & 73.72 for each shipment apply. Approved route encl MACDONALD,CE Transportation Brench 88/12/02. RAVENSCROFT,N. Edlow International Co. 10pp 47825.013-47825.022.
- 8812150100 Requests that 881122 application for iccense to export nuclear mati & equipment to Japan,as amended by 881123 ltr, be accorded expedited handling. IKEDA,M. Mitsul & Co. (USA), Inc. (subs. of M:tsul & Co. ; Ltd.), MRK-F3/F5/2F3, 88/12/07, NRC No Detailed Affiliation Green. 1p. 47833:073-47833:075
- 8812150115 License for C-E to export 72.7 g U-235,0 00002 g U-233,302 g Pu & 23.4 g Np.237,contained in 24.604 kg of total U,to Canada. PETERSON.M.R. Assistant Director for International Security. RP2905:2, 88/12/09. 2pp. 47824:081-47824:082.
- 8812150221 Forwards Safety Light Corp 881205 & 0503 lins relicionse to export Applicant attached request from Argentina Air Force for demonstration of gaseous tritium self-luminous airfield lights Request should be considered w/880503 request PETERSON,MR Assistant Director for Infornational Security. 88/12/09. THORNE,C.E. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs. 1p. 47851:238-47851:244.

- -8812150235 Forwards applications for ticenses to export gascous tritium self-luminous safety products for use in airfield landing lights, heliport landing lights, taxiway signage, edge markers & safety signs to listed countries MILLER_J_Safety_Light_Corp. 88705703. WAIGHT_8 International Programs, 2pp 47851:243-47851:244
- 8812190022 Farwards Milsui & Co 881207 ftr expressing concernire long delay in issuing requested export license Request should be considered in conjunction wilding. application forwarded on 88/309
 PETERSON,M.R. Assistant Director for International Security. 88/12/09.
 THORNE,C.E. State, Dopt. of, Bureau of Oceans & Init. Environ & Scientific Affairs.
 - 1p. 47861 280-47851:283
- 8812190046 Forwards application for amend to Licenso XB-1264,requesting permission to export 150,000 Critifium solf-lum nous airfield lights MILLER.J. Satety Light Corp. 88/12/05 WRIGHT,8 NRC No Detailed Affitiation Given 3pp. 47840:172-47840:177.
- 8812190049 Amend 3 to Leense for Braunkoh's Transport USA,Inc, extending expiration date from 980101 to 901231 & reflecting change in licenses address PETERSON,M.R. Assistant Director for International Security, 88/12/14, 1p 47651:250-47851:250.
- 8812190065 License for GE to export 442 kg U-235,contained in 16,174 kg U,lo Japan PETERSON,M.R. Assistant Director for International Security. FDF:68-128 88/12/14 2pp. 47840 191-47840 192
- 8812180063 Forwards Mitsubishi Intl Corp 881208 request for change to Licenso XU-8668,reflecting correct name & address in Item 14,for consideration w/original application torwarded on 980622. PETERSON,M.R. Assistant Director for International Security, 88/12/14 THORNE,C.E. State, Dopt. of, Bureau of Oceans & Intl. Environ & Scientific Affairs 1p. 47852.152-47852.153.
- -8812190065 Requests that info in Ilconsee 860614 export ficense application be corrected to reflect stated name 8 address in Item 14, LENGJAK,B. Mitsubishi International Corp. (subs. of Mitsubishi Corp.) NY-HSA-118-00. 88/12/08, NRC - No Detailed Affiliation Given. Ip. 47852-153-47852:153.
- 8812190070 License for GE to export 8 g U-235 & 5 65 g Pu,contained in 698 13 g U,to
- Assistant Director for International Security 88/12/14, 2pp 47855 044 47855 045 8812190084 Application for amend to license, extending expiration date to 901231 &
- changing address
 GAVLICK.G. Braunkohte Transport USA, Inc. 88/12/07. MOORE,N. NRG No De-tal od Affiration Given, 1p. 47852:139-47852.139.
- 8812190089 Discusses Executive Branch position to GE application to export 400 kg of natural thorium to Brazil-Licenso recommended to be issued.
 STRATFORD, BJ. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs. 88/12/05. SHEA,J.R. International Programs. 1p. 47840,168-47840:168.
- 8812190115 Requests Executive Branch position re-encl Mitsul & Co. (USA) Inc 881205 application for hicense to export 12,795 kg U as UF6 for enrichment in Japan. PETERSON M.R. Assistant Oroctor for International Security. B8/12/09. THORNE, C.E. Stels, Dept. of, Bureau of Oceans & Intl. Environ & Scientific Affairs 1p. 47850-342-47850:344.
- 8812190124 License for GE Lighting to export 500 kg thorium, as oxide, in form of slurry mixture, to Brazil
 PETERSON,M.R. Assistant Director for International Security. SMB-191. 88/12/09.
 1p. 47851:332-47851:332.
- 8812190140 Forwards application for license to export low enriched U to Japan.Ltr of assurance required.

 PETERSON,M.R. Assistant Director for International Security. 88/12/09
 THORNE,C.E. State, Dept. of, Bureau of Oceans & Infl. Environ. & Scientific Affairs.

 1p. 47840-127-47840-128.

- 8812200054 Amend 1 to Leense for Transnuclear,fnc to export 2,756 kg U.2.35 contained in 88,900 kg U.to korea PETERSON,M.11 Assistant Director for International Security 88/12/15 250 47864-173-47864,176
- -8812200063 Apphication for amend to License XSNM 2391 designation Transpuctear, find as licensee FISK,R.H. Edfow Informational Co. 88/12/13 WRIGHT,B. NRC No Detailed Aff. also Given 2pp. 47864 175-47664-176
- 8812200072 Amend 3 to license for Braunkohle Transport USA,Inc,changing address to extending expiration date from 890101 to 901231
 PETERSON,M.R. Assistant Director for International Security 69/12/14 1p
- 47864.231-47864.231
- 8812200095 Application for amond to licensulassigning licensulate Transmicterinc a Fronsee Transmicterinc 881208 fit to Elow Intil Colenci FISK.R H. Editow Intonetonal Co. 88712713 WRIGHT.B. NRC No Detect Affiliation Cover 2pp 47868-233-47868-234
- 8812200129 Forwards application for Fooriso to expert 52 kg U-215 as most pieces, contained in 260 kg U,to Canada QUAIN P.B. Transnuclear, Inc. MIS-480, 88712707 WHIGHT, BINEC 65 Detailed Affiliation Given. 1p. 47871-006-47871 070
- -9812200132 Application for license to expert 268 kg U in tain of meti-pleces, onriched to max of 19.95% U-235, to Canada. QUAIN,P.B. Transnuc'ear, Inc. MIS 490, 88712707, 4pp. 47871,067-47871,070.
- 8812220188 Requests authorization, in writing, that NRC add Transtructoar, inclass tidens ee to export Loanse MANGUS!,J. Transnuc'dar, Inc. 88/12/08. FISK,R. Editow International Co. 1p 47892 212 47892 212
- 8812270116 Amend 11 to Iconse for Advanced Nuclear Fue's Corp to erect 983,14 kg Ullo France, Botglum & Wost Germany, PETERSON,MR Assistant Director for International Security 85/12/23 266
- 47027.053 47927.054.
- 8812270124 Forwards 881216 ftr from Transnuction, incide reguest for with travial coxport License XSNM-2408 amond application. PETERSON, MR. Assistant Director for International Society, 88712723 INCOMES, Energy, Oopt. of 1p. 47845 113-47945 114.
- 8812270129 Forwards Transmictear, Inc. application for amount to license discreasing quantity of mail by 7,829 kg Request should be considered in conjunction without as forwarded to recipient on 881101.1W/open. PETERSON,M.R. Assistant Director for international Security 83/12/2. THORNE,C.E. State, Dopt of, Bureau of Oceans & Intl. Environ. & Security Affacts by 47926-173-47926-173.
- 8812270284 Application for Econise to export 136 kg U.contalling 4 kg 17:33515 Cer 11, VOTAW,E F. Westinghouse Hanford Co. BR-1826 88712713 to 47925 325 47025 350
- -8812270285 Forwards application for ficense to expert law enriched U march atest fur rods to Canada. HUNTER J.R. Energy, Dept. of 88/12/13, MOORE, R.N. Assistant Dicctor for Internal Illonal Security. 2pp. 47925-328-47925-330
- -8812270287 Requests authorization for encl Std Work Order 60-89 023 to 3N MU & SHERON,B.W. Division of Systems Research (Post 880717) 83710/2: LAWRENCE,M.J. Energy, Dupt. of 8pp. 47925-331-47925-339
- -8812270298 Agreement between NRC & AECL re-participation in NRC program of sovere accident research
 STELLO,V. Ofc of the Executive Director for Operations GHEFN,RE As and Errory
 of Canada, Ltd. 88/10/11, TIpp. 47925.340-47925.350

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example,50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in the index indicates that the document is an enclosure another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION	SUBJECT	AUTHOR	ACCESSION	SUBJECT	AUTHOR	ACCESSION	SUBJEC1
	NUMBER	CATEGORY		NUMBER	CATEGORY		NUMBER	CATEGOR
ADAMOVITZ, SIS	8811200567*	50-250 Q	AMATO,C.G	8812090191*	50-57 O	AZUA,A.V.	8812150228*	50-498
ADAMSIA	8811280123	50-163 P	ANANDAPPA,A	8912200205	50-249 S	BACHMAN,R G	8812140035	50-322
ADAMSIA	8812010198	50-297 F	ANDERSON,C.J.	8811290553*	60-333 O	BACHMANN,R G	8812270090	50-322
ADAMSIA	8912010205	50-297 F	ANDERSON,C.J.	8011290567*	50-277 O	BACHMANN,R G.	8812280075	50-322
ADAMSIA	6812010212	50-297 V	ANDERSON,C.J.	8611300312*	50-367 O	BACKUS,R A.	6812020060	60-443
ADAMS,A	8812010219	50-287 P	ANDERSON, C.J.	8811300346*	60-277 O	BACKUS,R A	8612020060	50 443
ADAMS,A	8812050104	50-224 P	ANDERSON, C.J.	8812080154*	50-247 O	BACKUS,R.A.	8812270093	60 443
ADAMS,A	8812050117	50-297 P	ANDERSON, J.D	8812060049	50-440 F	BACKUS,R A.	8812270093	50 443
ADAVS,A	8812070087	PROJ	ANDERSON, R.T.	8809130261	PROJ	BACKUS,R A.	8812270093	50 443
ADAVS,A	8812070213	ORG	ANDERSON, S.L.	8812160107*	50-309 P	BACKUS,R A	8812270093	50 443
ADAMS A	8812090075	ORG	ANDREYCHEK,TS	8811280117* 6812050318 8811290087 8812140265 6812140266	TOPREP	BACKUS,R A	8812270093	50-443
ADAMS A	8812150240	50-356 P	ANDRUS,NJ.		40-4492	BACKUS,R A,	8812280024	50-443
ADAMS A	8812160040	50-297 P	ANTHONY,P.		50-341 \$	BACKUS,R A	8812280024	50-443
ADAMS A	8812200029	50-131 F	ANTHONY,P.		50-341 \$	BAER,R.É.	8811299580°	50-285
ADAMS A	8812200186	50-224 P	ANTHONY,P		50-341 \$	BAER,R.É.	8811300257°	50-313
ADAMS A	8912210183	50:398 P	ANTHONY,P.M.	8812200300°	50-341 R	BAER,R.E	0812050196*	50-298
ADAMS A	8812220014	50:102 P	ANTHONY,P.M.	8812270098°	50-341 R	BAER,R.E.	8812130132*	50-205
ADAMS F M	8812220320	PT21	APPEL,G.	8812220367	WASTE MGT	BAER,R.E	6812210347*	50-313
ADAMS S FI	8912070082	27:48	ARCHITZEL,R.E.	8812020163°	50-277 Q	BAGCHI.G	8805030507*	50-440
ACENSAME G.	8912010220'	50:416 P	ARILDSEN,J.	8812000142°	50-424 V	BAGCHI.G	8812020013	50-601
ADENSAME G	8812010267*	50-416 P	ARTHUR,W,J.	8811140164	WASTE MGT	BAILEY, J.A.	8811280185	50-482
ADENSAME G	8812010301*	50-416 P	ARTHUR,W,J.	8811700141	WASTE MGT	BAILEY, J.A.	8611290002	60-482
ADENSAME G	8812020009*	50-416 P	ARTHUR,W,J.	8812050248	WASTE MGT	BAILEY, J.A.	8811290402	50-482
ADENSAME G	8812070160*	50-416 P	ARTHUR,W,J.	6812090236	WASTE MGT	BAILEY, J.A.	6811290556	50-424
ADENSAME G	8812070162*	50-416 P	ARTHUR,W,J.	8812120259	WASTE MGT	BAILEY, J.A.	8811300300	50-482
ADENSAV,E G	8812130228*	50-416 P	ARTHUR,W J	8812130063	40-6500	BAILEY, J.A.	8811300404	50-482
ADENSAM,E G.	8812130232*	50-416 P	ARTHUR,W.J.	6812150267	40-6500	BAILEY, J.A.	9811300483	50-482
ADENSAM,E G.	8812130240*	60-416 P	ARTHUR,W.J.	6812190160	40-6500	BAILEY, J.A.	8812010387	PR
ADENSAM,E G.	8812130242*	50-416 P	ARTHUR,W.J.	6812190302	40-6500	BAILEY, J.A.	8812050091	50-425
ADENSAV,E.G.	8812140082	50-324 P	ARTHUR,W.J.	6812210124	WASTE MGT	BAILEY, J.A.	8812050128	50-425
AFTERGOOD, S	8812080173	FOIA	ARTHUR,W.J.	6612210231	WASTE MGT	BAILEY, J.A.	8812050148	60-425
AFTERGOOD, S.	8912130203	FOIA	ARTHUR,W.J.	6612210318	WASTE MGT	BAILEY, J.A.	8812080026	50-425
AFTERGOOD, S.	8812130208*	FOIA	ASHLEY,J.	6612130197	50:295 S	BAILEY, J.A.	8812080202	50-425
AHMAD, M. U.	8808310128*	50-440 P	ASMUSSEN,K.E.	6812070026	70:734	BAILEY, J.A.	8812080202	50-425
AHO, G. D.	8812210279	40-8714	ASMUSSEN,K.E.	6812050093*	XPORTLIC	BAILEY, J.A.	8812180379	50-425
AIROZO,O.	8812180378	FOIA	ASMUSSEN,K.E.	8812080095*	XPORTLIC	BAILEY, J.A.	8812190385	50-425
ALBERS K.L.	8812010114	PR	ASMUSSEN,K.E.	8812130072	71-6346	BAILEY, J.A.	8812200202	50-425
ALEXANDER, P. J.	8911290117	50-165 S	ASMUSSEN,K.E.	8812130252	XPORTLIC	BAILEY, J.A.	8812210142	50-425
ALEX-CH, M.P.	8812050036	50-315 P	ASMUSSEN,K.E.	8812130254	XPORTLIC	BAILEY, J.A.	8812210154	50-425
ALEX.CH, M.P.	8812080146	50-316 S	ASMUSSEN,K.E.	8812130293	70-734	BAILEY, J.A.	8812220047	50-425
ALEXICH M.P.	8812080196	PR	ASMUSSEN,K.E.	6612140208	70-734	BAILEY, J.A.	8612230077	50-425
ALEX CH.M.P.	8812090036	50:315 P	ASMUSSEN,K.E.	8812220301	71-6346	BAILEY, J.A.	8812230097	50-425
ALEXICH M.P.	8912090051	50:316 O	AUSTIN,G.	8812200126*	50-295 R	BAILEY, J.A.	8812230101	50-425
ALEXICH M.P.	8812120240	50:315 Q	AUSTIN,J.H.	6812010417*	REVIEW GR P	BAILEY, J.N.	8812270106	50-499
ALEXICH M.P.	8812130032	50:315 P	AXELSON,W.	8812200134	50-265 S	BAILEY, J.N.	8812200138	50-499
ALEX.CH.M P.	8812190011	50-316 Q	AXELSON,W.	8812200139	50-255 S	BAILEY,J.N.	8812200250	60-498
ALEXION,T.W.	8812020199	50-483 P	AXELSON,W.L.	8812020143	50-258 Q	BAILEY,J.N.	8812200268	60-499
ALEXION,T.W.	8812060336	50-483 P	AXELSON,W.L.	8812020145	50-331 Q	BAILEY,J.N.	8812270291	60-499
ALGER.D.M.	8812070159	50-186 P	AXELSON,W.L.	8812020182	50-331 Q	BAILEY,P.E.	8812210225	WASTE RE
ALLEN,W.T.	8812050065	50-255 S	AXELSON,W.L.	8812020213	50-282 Q	BAKER,E.T.	8812210321*	QA999
ALLENSPACH, F.	8812010358	NUREG	AXELSON,W.L.	8812020215°	60-282 Q	BAKER,E.T.	8812210329*	OA989
ALTOMARE, P.	8812010415	WASTE MGT	AXELSON,W.L.	8812140240	50-316 D	BAKER,A.	8812020189*	40-8902
ALTOMARE, P.M.	8811300208	WASTE MGT	AXELSON,W.L.	8812140242°	50-315 Q	BAKER,L.J.	8612190300*	CONTRAC
ALTOMARE, P.M.	8812080101	WASTE MGT	AXELSON,W.L.	8812210404	50-155 Q	BAKER,S.J.	8811280053	40-1162
ALTOMARE, P.M.	8812090024	WASTE MGT	AXLINE,J.S.	8812140232	50-331 S	BAKER,S.J.	8812050174	40-1162
ALTOMARE,P.M.	8812150247	WASTE MGT	AXLINE J.S.	8612140254	50-331 S	BAKEA,S J.	8812050309	40-1162
ALTOMARE,P.M.	8812150256	WASTE MGT	AYALA,C.A.	8812020087	50-498 S	BALL,J	8812190323'	50-361
AMATO,C.G.	8811230010*	50-213 O	AYALA,C.A.	8812210011	50-498 S	BALLARD,A,L.	8811290262	WASTE M
AMATO,C.G.	8612080212*	50-244 O	AZUA,R.V.	8811300166*	50-313 Q	BALLARD,R.L.	8812150158	WASTE M

230 FEROOF	ME AOTI	IOII IIIDEX						
AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BALLARD,R L.	8812190284	WASTE MGT	BELLAMY,R R	8811290392	50-333 Q	BLACK,S	8812020245*	50 328 P
BALLARD,R.L	8812190324	WASTE MGT	BELLAMY,R R.	8811300296	50-213 Q	BLACK,S	8812020274*	50 260 P
BAMFORO,W.H.	8812210034*	50-498 P	BELLAMY,R R.	8812060023	50-334 Q	BLACK,S	8812060235	50 259 P
BANDHAY,W.K.	8812270176	60-302 F	BELLAMY,R.R.	8812060260	50-333 Q	BLACK,S	8812060243*	50 259 P
BANGART,R.L.	8812140142*	50-274 Q	BELLAMY,R.R	8812060303	50-219 Q	BLACK,S.	8812090222	50 390 A
BARI, R.A. BARI, R.A. BARI, R.A. BARI, R.A. BARKHURST, R.P.	8812050240 8812220311 8812220316 8812220329 8812010116	WASTE RES WASTE RES WASTE RES WASTE RES 50-382 P	BELLAMY, R.R. BELLAMY, R.R. BELLAMY, R.R. BELLAMY, R.R. BELLAMY, R.R.	8812080209 8812090187 8812090192 8812090194 8812090292	50-244 Q 50-57 Q 50-334 F 50-219 Q 50-220 F	BLACK,S. BLACK,S. BLACK,S. BLACK,S. BLACK,S.	8812090236* 8812120237 8812130054 8812130143 8812130153*	50 390 A 50 259 P 50 260 P 50 259 P
BARNES,I. BARNES,I. BARNES,I. BARNES,J.T. BARR,K.P.	8811300160* 8812050299* 8812210200* 8812190005*	50-313 Q 50-285 Q 50-313 Q 50-260 P 50-390 Q	BELLAMY,R R BELLAMY,R R BELLAMY,R.R. BELLAMY,R.R. BELLAMY,R.R	6812090295 6812120034 6812120199 6812120239* 6812210013	50-219 F 70-687 50-289 O 50-293 F 50-317 Q	BLACK,S. BLACK,S. BLACK,S. BLACK,S. BLACK,S.C.	8812130279 8812130281' 8812190193 8812190199' 8811300455	50:327 P 50:327 P 50:327 P 50:327 P 50:260 P
BARRETT,L.	6812090316*	WASTE MGT	BELLAMY, R.R.	8912210407	70-1703	BLACK,S.C.	8812010186	50-269 3
BARRETT,L.	8812220371*	WASTE MGT	BELLAMY, R.R.	8812220400	50-289 Q	BLACK,S.C.	8812010240	50-327 F
BARRETT,L.H.	8812140199	WASTE MGT	BENANTI, MA	6812190280	FOIA	BLACK,S.C.	8812020255	50-259 G
BARRY,C.V.	8812020175*	50-293 F	BENNETT, LA	8812190409°	60-312 P	BLACK,S.C.	8812070050	50-259 F
BARTH,C.A.	8812270090	50-322 G	BENNETT, W.R.	8811300248°	50-298 Q	BLACK,S.C.	8812140029	50-259 F
BARTLETT,B L.	8812140166°	50-482 Q	BENSINGER,P.B.	6812010152	PR	BLACK,S.C.	8812140042	60-260 9
BARTON,J.J.	8812200024	50-210 F	BENSON.D.L.	8811230272	50-280 S	BLACK,S.C.	8812220113	60-260 0
BASKIN,K.P.	8812120200	60-206 P	BENSON.D.L.	8811280072	50-280 S	BLAHA,J.L.	8811300266	COMM SS CN
BASKIN,K.P.	8812120203°	50-206 P	BENTSEN.L.	8812080240	PR	BLAHA,J.L.	8812020073	WASTE MGT
BASKIN,K.P.	8812210323	50-361 P	BERGER,J.D	8812090101	70-734	BLAHA,J.L.	8812050036	COMM-SS CN
BASKIN,K.P.	8812210325°	50-361 P	BERGER, J.D.	6812190054* 6812060231 6812190002 6812190113 6812020174	70-925	BLAHA,J.L.	8812120125	COMMISS ON
BASKIN,K.P.	8812230044	50-361 P	BERGERON, M.P.		WASTE RES	BLAKE,J.J.	8812200364	COMMISSION
BASKIN,K.P.	8812270112	50-361 P	BERGOUIST, S.A.		50-443 G	BLAKE,J.J.	8812050267*	50 280 C
BASKIN,K.P.	8812270117°	50-361 P	BERGOUIST, S.A.		50-443 G	BLAKE,J.J.	8812070248*	50-260 C
BASSETT,C.H.	8812080184°	50-260 Q	BERGSTROM, P.D.		40-8902	BLAKE,J.J.	8812080012*	50-260 C
Bassin,n. Bassin,n. Bassin,n. Bassin,n. Bassin,n.	6812060067* 8812060070* 8812060108* 8812060113* 6812060169*	FOIA FOIA FOIA FOIA FOIA	BERKOW,H.N. BERKOW,H.N. BERKOW,H.N. BERKOW,H.N. BERKOW,H.N.	8811300451 8812070120* 6812080034* 8812080041* 8812130120*	STATE PRO G 60-336 P 50-338 P 50-338 P 50-338 P	BLAKE,J.J. BLAKE,J.J. BLAKE,T. BLANCHARD,B.	8012080054* 8812080193* 8012160169* 8811210133 8812120071	50-250 G 50-250 G 50-363 G 71-665 FR
Bassin,n.	6812060240*	FOIA	BERKOW,H N.	8812150195	50-336 P	BLANCHARD,M.B.	8812270216*	WASTE MGT
Bastin,j.J.	6812210145	71-24	BERKOW,H.N.	8812160061	60-280 P	BLAYLOCK,J.	8812050295	WASTE MGT
Bastin,j.J.	6812210152*	71-24	BERKOW,H.N.	8812160093*	50-338 P	BLAYLOCK,J.	8812120165*	WASTE MGT
Bates,a,	6812010056	SECY	BERKOW,H.N.	8812200204*	60-389 P	BLAYLOCK,J.	8812120244	WASTE MGT
Bates,a,	6812010210	50-293 P	BERKOW,H.N.	6812220224*	50-338 P	BLAYLOCK,J.	8812150274	WASTE MGT
BATES.A.L.	8812010419	PR	BERKOW,H.N.	8612220258*	50-389 P	BLAYLOCK,J.	8812190239*	WASTE MGT
BATES.G.S.	8811290272*	50-267 S	BERLINGER,C.H.	8612070190	I&E	BLISS,H.E.	8810050121	50 450 0
BATES.J.W.	8812210360*	70-27	BERNARD,J.A.	8812050134	50-20 P	BLISS,H.E.	8011280014	50 254 0
BAUDON.N.	8812210296	40-2259	BERNERO,R.A.	8812080102	WASTE MGT	BLISS,H.E.	8812050324	50 455 1
BAUER.T.L.	8812210296	50-802 A	BERRY,F.M.	8812070052	50-295 S	BLISS,H.E.	8812060282	53 456 0
BAUMAN,L.L. BAUSER,M.A. BAUSER,M.A. BAUSER,M.A. BAUSER,M.A.	8812080126 6812020102 6812020102 6812020102 6812260009 8612280009	FOIA 50-335 G 50-335 G 50-335 T 50-335 T	BERRY,O A BERRY,O A BERRY,O A. BERRY,O A. BERRY,O.A.	8812140020 8812140023 8812190016 8812270137 8812280194	60-443 G 50-443 G 50-322 G 50-443 G 50-443 G	BLISS,H.E. BLISS,H.E. BLOCH,P.B. BLOCK,M.L. BLOSSER,J.D.	8812120028* 8812150131* 8812270167 88122701019 88122050040	50-265 50-254 50-320 50-267 50-483
BAX,R.L.	8812190375	60-265 S	BERRY,K.W.	8811300178	50-155 P	BLOSSER, J.D.	8812210057	50 483
BAXTER,T.A.	8812190107	50-320 G	BERRY,K.W.	8812050270	50-155 Q	BLOSSER, J.D.	8812210057	50 483
BAXTER,T.A.	8812190107	50-320 G	BETTENHAUSEN,L.	8811290024	50-320 Q	BLOSSER, J.D.	8812210197	50 483
BAXTER,T.A.	8812190121	60-320 G	BETTENHAUSEN,L.	8811300493	50-245 Q	BLOSSOM, J.N.	8812200308	40 8452
BAXTER,T.A.	8812190121	50-320 G	BETTENHAUSEN,L.	8812120039	60-213 Q	BLOUGH, A.R.	8811300284	50 203
BAXTER,T.A.	6812190138	50-320 G	BETTENHAUSEN,L.	8812230020	50-244 Q	BLOUGH, A.R.	8811300338*	50 337
BAXTER,T.A.	6612190138	50-320 G	BETTENHAUSEN,L.	8812230020	50-336 Q	BLOUGH, A.R.	8812130073*	50-293
BAXTER,T.A.	6612270037	50-320 G	BETTENHAUSEN,L.	9812230035	50-219 Q	BLOUGH, A.R.	8812150005	50-293
BAXTER,T.A.	6812270037	50-320 G	BETTENHAUSEN,L.	8812230082	50-244 Q	BLOUGH, A.R.	8812200114*	50-372
BAXTER,T.A.	8812270044	50-320 G	BETTENHAUSEN,L.	8812270277	50-423 Q	BLUBAUGH, R.E.	8811280088	40-3453
BAXTER, T.A. BEAN, C.D. BECHHOEFER, C. BECKER, D. BECKJORD, E.S.	8812270044 6812200295 8812280226 6812090195 6811100281	50-271 G COMMISSION	BETTENHAUSEN,L. BEVAN,R. BEVAN,R. BEVAN,R.B. BEVERLY,R.L.	8812270288 8811300253 8811300258* 8812070234 8812070107*	50-289 S 60-344 P 50-344 P 50-344 P 50-499 Q	BLUBAUGH,R.E. BLUMBERG,N.J. BOCKHOLD,G. BOERGER,J.C.	8812060004 8812080166' 8812270235' 8812090145' 8812220214'	40:3453 50:244 50:286 50:424 50:295
BECKJORD,E.S.	8611100281	PR	BIBB.H.E.	8812090322*	50-335 Q	BOGER B.A.	8811230182	50-333
BECKJORD,E.S.	8611290524	GEN TEC I S	BICHARDS,S.A.	8812210286	50-344 V	BOGER B.A.	80121202701	50-293
BECKNER.W.	8612200384	ORG	BIDINGER,G.H.	8811290528	70-143	BOHMS G.L.	8812010115	FR
BEDESEM.P.	8812180233	50-275 R	BIDINGER,G.H.	6811300018*	70-3054	BOLEY K.	8812090037	PA
BEHNKE,C.	8812200201	50-317 R	BIDINGER,G.H.	8811300411	70-143	BOLTON E.P.	8812010027	PA
BELAIR, R. R. BELAIR, R. R. BELAIR, R. R. BELAIR, R. R. BELDEN, S.	8812050109 8812050109 8812210291 8812210291 8812210368	50-322 P 50-322 P 50-322 F 50-322 F 40-8452	BIDINGER,G.H. BIDINGER,G.H. BIDINGER,G.H. BIHLMAN,L.E. BINNINGTON,W.A.	8812080316* 8812120019 8812270212 8812150250 8812220323*	70-2932 70-371 40-3392 50-237 S 50-265 Q	BONANO,E.J. BONANO,E.J. BONANO,E.J. BONANO,E.J. BONETT,D.M.	8812010293 8812140156 8812190131 8812190273 8812200013*	WASTE RES WASTE RES WASTE RES 50-250
BELISLE,G A. BELISLE,G A. BELISLE,G A. BELL,C.D. BELL,S.	8812160127 8812200167 8812220026 8812280049 8812010281	50-260 Q 60-280 Q 50-277 H	81RD, R. G. 81RD, R. G. 81RD, R. G. 81RD, R. G. 81TTER, S.D.	8812010384 8812070174 8812120092 8812190164 8811230219*	PR 50-293 Q 60-293 P 60-293 F 60-445 Q	BONETT,D.M. BONGIOVANNI,A. BOOKER,J.E. BOOKER,J.E. BOOKER,J.E.	8812200015* 8812270040* 8811300196 8811300231 8811300267	50-250 50-346 50-458 50-458 50-458
BELL,S. BELL,S. BELL,S. BELLAMY,R.R. BELLAMY,R.R.	8812190269 8812190296 8812210134 8811210067 8811220324	CONTRACT CONTRACT 50-293 P	BITTER,S.D. BIXBY,W.W. BIXBY,W.W. BLACK,S. BLACK,S.	8812200011* 8812050149 8812230099 8812010277 8812020181	50-445 Q PROJ PROJ 50-260 P 50-260 P	BOOKER, J.E. BOOKER, J.E. BOOKER, J.E. BOOKER, J.E. BOOKER, J.E.	8811300286 8811300318 8812010232 8812010235 8812020260	50-458 50-458 50-456 50-458 50-458
BELLAMY, R.R.	8811290007	50-272 Q	BLACK,S.	8812020185	50-259 P	BOOKER J.E.	8812060154	50-458
BELLAMY, R.R.	6811290034		BLACK,S.	8812020186	50-259 P	BOOKER J.E.	8812060183	50-458
BELLAMY, R.R.	6811290372		BLACK,S.	8812020244	50-328 P	BOOKER J.E.	8812060310	50-458

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJEC CATEGOR
BOCKERIJE BOACHERT, HIR BOADENICK, BIM BOADENICK, BIM BOADENICK, BIM	8812220073 8812010153 8812190105 8812190119 8812190136	50-458 O PR 50-603 G 50-603 G 50-603 G	BROWN,H.H. BROWN,K BROWN,K J. BROWN,K J BROWN,M P	8812280033* 8812080198* 8812080201* 8812020001	50-322 G 40-8592 40-8592 40-8592 PR	CALDWELL, G CALDWELL, G W CALL, K CALLAN, LJ. CALLAN, LJ.	8812080023 8812200090* 8812230086 8811220457 8811290271	50-397 50- <i>206</i> 50-322 50-458 50-313
BORDENICK,B M	8812199211	50-503 G	BROWN,R.E.	8812140181	50-213 F	CALLAN, LJ.	8611290328	50-482
BORDENICK,B M	8912280134	50-603 G	BROWNING,R.E.	8812150230	WASTE MGT	CALLAN, LJ.	8811290459	50-298
BORDENICK,B M,	8912280165	50-603 G	BROWNING,R.E.	8812210192	WASTE MGT	CALLAN, LJ.	8811290469	50-267
BORDENICK,B M,	9812280166	50-603 G	BROWNLEE,V.L	8811290036	50-413 Q	CALLAN, LJ.	8811290474	50-392
BORST,S G	6812180278	50-528 R	BROWNLEE,V.L	8811290043*	50-413 Q	GALLAN, LJ.	8811290483	50-392
BOSILLEVAC,F BOSTED,C. BOSTED,C. BOWWAN,S.W BOWSER,R.W.	8812210067 5811300187 8912080023 8912050210 8811300019	WASTE MGT 50:397 S 50:397 S 50:344 S 50:312 S	BROWNLEE, V.L BROWNLEE, V.L BROWNLEE, V.L. BROWNLEE, V.L. BROWNLEE, V.L.	8812050280 6812080001 8812080006* 8812160163 8612160167*	50-269 Q 50-424 Q 50-424 Q 50-369 Q 50-369 Q	CALLANIL J CALLANIL J CALLANIL J. CALLANIL J. CALLANIL J.	8511290579 8811300066 8811300169 8811300161	50-285 50-458 50-313 50-313 50-313
30XER B.	8811300423*	50·275 U	BROWNLEE, V.L.	8812190006	50-424 Q	GALLAN, L.J.	8811300210	50-382
80Y0,C.C	8812140212	70·27	BROWNLEE, V.L.	6812190110	50-413 Q	CALLAN, L.J.	8811300239	50-298
80Y0,C.C	8812200320	70·27	BROWNLEE, V.L.	6812200233	50-321 Q	CALLAN, L.J.	8811300254	50-313
80Y0,C.C	8812200322	70·27	BROWNLEE, V.L.	6812200238*	50-321 Q	GALLAN, L.J.	8811300327	50-267
80Y0,C.C	881220076	70·27	BROWNLEE, V.L.	6812200269	50-413 Q	CALLAN, L.J.	8811300382	50-458
BOYD,C.	8812220078	70-27	BROWNLEE,V.L.	8812200271* 8811280116 8812220341* 8812220078 8812210263	50-413 Q	CALLAN, L.J.	8811300434	50-382
BOYD L.W.	8812210302*	50-390 A	BRUNET,J.H		50-255 F	GALLAN, L.J.	8811300560	50-267
BOYLE M.L	8811290215	50-245 P	BRYAN,K.A		50-338 P	GALLAN, L.J.	8812010004	50-313
BOYLE M.L	6912220262	50-246 P	BUCKLEY,B		50-280 P	GALLAN, L.J.	8812010009	50-313
BRACH,E W.	8812210310	QA999	BUCKLEY,B C.		50-280 P	GALLAN, L.J.	8812010111	50-287
BRACH, E.W	8612210324	OA899	BUNCH,D.F.	8911280186	PROJ	CALLAN, L.J.	8812010122	50-285
BRACH, E.W	8812210334	QA999	BUNDY,H.F.	8912130141*	50-458 O	CALLAN, L.J.	8812010128	50-287
BRACH, W.	8812140166*	60-283 P	BUNDY,H.F.	8912150226*	50-498 O	CALLAN, L.J.	8812020303	50-382
BRACH, W.	8812080019*	50-320 P	BUNDY,H.F.	8912220027*	60-482 O	CALLAN, L.J.	8812020306	50-313
BRACHORD, W.H.	8812060271*	50-400 Q	BUNTING,J.O.	8811290198	WASTE MGT	CALLAN, L.J.	8812020310	50-128
BRADFUTE, J	8812190323*	50-361 Q	BUNFING.J.O.	6911290507	WASTE MGT	CALLAN, L.J.	8812020312	50-267
BRADFUTE, J O.	8812150222	50-390 A	BUNTING.J.O.	6812080073	WASTE MGT	CALLAN, L.J.	8812020313	50-285
BRADFUTE, J O.	8812150225	50-400 A	BUNTING.J.O.	6812150246	WASTE MGT	CALLAN, L.J.	8812050192	50-298
BRADHAM, O.S.	8811300271	60-395 Q	BUNTING.J.O.	6812210375	WASTE RES	CALLAN, L.J.	8812050297	50-285
BRACHAM, O.S.	6611300428	50-305 Q	BURDICK.T.M.	6812160340*	50-315	CALLAN, L.J.	8812050305	50-313
ERADHAM,OS.	8811300448	50:305 P	BURDOIN, J.	8812200098*	50:344 O	CALLAN, E.J.	0012060230	50-298
ERADHAM,OS.	8812010002	60:305 S	BURDOIN, J. F.	8812210035*	50:528 O	CALLAN, E.J.	6812060253	50-482
BRADHAM,OS	8812010408	60:395 H	BURGER, C. W	8812080000*	50:424 O	CALLAN, E.J.	6812060269	50-482
BRADHAM,OS	8812060077	50:395 F	BURGESS, B	8812020216*	50:282 O	GALLAN, E.J.	6012060274	50-285
BRADHAM,OS	8812120084	50:395 Q	BURGESS, B.	8812200134	50:255 S	GALLAN E.J.	6812090328	50-288
BRADHAM,O.S.	8812130124	60-395 P	BURGESS,B.	8812200130	60-255 S	CALLAN, LJ	0812130127	50-285
BRADHAM,O.S.	8812140028	60-395 R	BURGESS,B.L.	8612020144*	50-255 Q	CALLAN, LJ	8812130139	50-458
BRACHAM,O.S.	8812270271	60-395 Q	BURGESS,B.L.	8612140244*	50-315 Q	CALLAN, LJ	6812140027	£0-267
BRAN,J	8812130016	50-247 S	BURKHARDT,L.	8812010199	50-220 S	GALLAN, LJ	8812140060	50-482
BRAN,S	8812120093	50-247 Q	BURKHARDT,L.	8812070205	50-220 P	CALLAN, LJ	8812140066	50-458
BRAM,S	8812120097	60-247 S	BURKHARDT,L.	8812090303	50 220 Q	CALLAN, LJ.	8812140069	50-285
BRAM,S 6	8811290020	60-247 Q	BURKHARDT,L.	8812090314	60:410 Q	CALLAN, LJ.	8812140152	50-482
BRAM S 6.	8612010336	50-247 P	BURNETT,M A	6812220049	50:498 P	CALLAN, LJ.	8812140207	50-298
BRAM S B.	8812020011	50-247 P	BURNETT,P.T.	6812230019*	50:400 Q	CALLAN, LJ.	8812140214	50-285
BRAM,S B.	8812020236	60-247 S	BURNETT,P.T.	6812080020*	50:395 Q	CALLAN, LJ.	8812140216	50-382
ERAM, S.B.	8812070263	50-247 P	BURNETT, R.F.	8812020293	70-27	CALLAN, L.J	8812140217	50-285
BRAM, S.B.	8812080002	50-247 Q	BURNETT, R.F.	8812050338	NUREG	CALLAN, L.J	8812150067	50-482
BRAM, S.B.	6812080110	50-247 S	BURNS, S.	8812290294'	FOIA	CALLAN, L.J	8812150076	50-458
BRAM, S.B.	8812090012	50-247 P	BURRIS, S.P.	8811230219'	50-445 Q	CALLAN, L.J.	8812150097	50-298
BRAM, S.B.	8812130047	50-3 F	BURRIS, S.P.	8812200011'	50-445 Q	CALLAN, L.J.	8812150101	50-498
BRANDEBURG.B.L. Brandt,s.G. Breest Brennan,c.	8812080140 8812080140 8812060263 8812200303 8812190398	50-247 P PR 70-824 REVIEW GR P 50-354 P	BURROWS,A.S BURSKI,R.F. BURSKI,R.F. BURSKI,R.F. BURSKI,R.F.	8812130154 8812010222 8812020027 8812070143 8812200053	FOIA PR 50-382 Q 50-382 F 50-382 R	CALLAN,L J. CALLAN,L J. CALLAN,L J. CALLAN,L.J. CALLAN,L.J.	8812150102 8812150112 8812150123 8812150193 8812160206	50-313 50-458 50-285 50-267 50-285
BRESLAU,B.	8812080118*	60.400 Q	BURSKI,R.F.	8812210148	50-382 R	CALLAN,L.J.	8812150224	50-498
BREY,H.L.	8812200149	50.267 Q	BURSKI,R.F.	8012270294	50-382 Q	CALLAN,L.J.	8812160024	50-482
BRICE-NASH,R.L.	8812210034*	50.498 P	BUTCHER,E.J.	8812010074	AEVIEW GR P	CALLAN,L.J.	8812160031	50-298
BRIGGS,L.	8812150016*	50.213 Q	BUTCHER,E.J.	8812090033	REVIEW GR P	CALLAN,L.J.	8812200107	50-285
BRIGGS,W.H.	8811100293*	PR	BUTCHER,E.J.	8812190147	REVIEW GR P	CALLAN,L.J.	8812200345	50-285
BRINKMAN,C.B.	8612200181	50:470 A	BUTCHER,R.C.	8812080050*	50-250 Q	CALLAN,L.J.	0812210301	50-313
BRIODY,E.T.	8612010156	PR	BUTLER,W.R.	8811280215	50-387 P	CALLAN,L.J.	8812210308	50-205
BRISSON,R.J.	8612060211*	FOIA	BUTLER,W.R.	8811280217*	50-387 P	CALLAN,L.J.	8812210331	50-482
BROCHARDT,R.W.	8611290412*	50:272 Q	BUTLER,W.R.	8811300484	50-354 Q	CALLAN,L.J.	0812210346	50-313
BROCK,B.L.	8812010287*	70:734	BUTLER,W.R.	8812010182*	50-277 P	GALLAN,L.J.	6812220010	50-313
BROCK,M.T.	8812020081	50-443 G	BUTLER,W.R.	8612060335	60-322 P	CALLAN,L.J.	8812220025	50-482
BROCK,M.T.	8812020081	50-443 G	BUTLER,W.R.	8612060338*	60-322 P	CALLAN,L.J	8812220128	50-208
BROCK,M.T.	8812020081	50-443 G	BUTLER,W.R.	8612090202	60-387 Q	CALVO,J.A.	8811280213*	50-458
BROCKMAN,K.E.	8812090120*	60-63 V	BUTLER,W.R.	8612120033	50-277 F	CALVO,J.A.	8811300043*	50-458
BROCKMAN,K.E.	8812190222*	50-324 V	BUTLER,W.R.	8812120037	60-322 P	CALVO,J.A.	8811300064	50-498
BRONS J.C.	8812010423	50-286 P	BUTLER,W.A.	8812120040*	50-322 P	CALVO JA	8812020234*	50-482
BRONS J.C.	8812130003	50-286 P	BUTLER,W.A.	6812120241	60-354 P	CALVO JA	8812020288*	50-498
BRONS J.C.	8812130007	60-286 P	BUTLER,W.R.	6812120242*	50-354 P	CALVO JA	8812050141*	50-458
BRONS J.C.	8812130060	50-286 P	BUTLER,W.R.	8812160105*	50-352 P	CALVO JA	6812090004*	50-458
BROOKS,P.	8812010422	WASTE RES	BYRAM,A.G.	6812080205	50-367 S	CALVO JA	8812090159*	60-382
BROOKS,P.	8812050314	WASTE RES	BYRAM,R.G.	8812130053	50-387 S	CALVO, J.A.	8812090309*	50-462
BROWN,A.	8811280169	WASTE MGT	BYRAM,R.G.	8812210008	60-387 S	CALVO, J.A.	8812090329*	50-499
BROWN,B.W.	8710140219*	50-275 O	BYRAM,R.G.	8812210010	50-388 S	CALVO, J.A.	8812120256	50-298
BROWN,B.W.	8710140231*	50-276 O	BYRD,R.W.	8811280107	50-418 S	CALVO, J.A.	8812130034	50-285
BROWN,B.W.	8710140322*	50-463 O	BYRNE,S.T.	8812150110*	50-309 P	CALVO, J.A.	8812130246	50-400
BROWN,B.W.	8710140322*	60-483 Q	CAINE,T.A.	8811290355*	60-277 P	CALVO, J.A.	8812130247*	50-499
BROWN,C.	8812190088	50-445 E	CAINE,T.A.	8811290357*	50-277 P	CALVO, J.A.	8812130256*	50-499
BROWN,H.H.	8812288033*	50-322 G	CAINS,N.S.	8812070143	50-382 F	CALVO, J.A.	8812160032*	50-482

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CALVOJ A CAVIAO GALOVIAO ALOVI	8812160135* 8812160155* 881221093 8812210208* 8812220068*	50-285 F 50-313 P 50-482 P 50-458 P 50-382 P	CESARE JG CESARE JG CESARE JG CESARE JG CESARE JG	8812050281 8812060017 8812090168 8812090204 8612090348	50-416 P 50-416 S 50-416 F 50-416 P 50-416 P	CLEVELAND, J.E. CLINE, W.E. CLINE, W.E. CLINE, W.E. CLINE, W.E.	8812200383 8811230163 8811330576 8812050120 8812060148	40 8905 70:143 50:359 70:2910 70:1201
CALVO, J A CALVO, J. A CAMERON, D. F CAMERON, D. F CAMERON, D. F	8812220090' 8812230109' 8811290510' 8811300298' 8812220401'	50-382 P 50-313 P 50-220 Q 50-213 Q 50-269 Q	CESARE J.G. CESARE J.G. CESARE J.G. CHAVBERLAIN,D CHAVBERLAIN,D	8812130145 8812160013 8812200231 8811290278' 8812020305'	50-416 P 50-418 V 50-416 R 50-313 Q 50-382 Q	CLINE,WE CLINE,WE CLINE,WE CLINE,WE CLINE,WE	88 12070242 88 12080241 88 12080243 88 12090103 88 12090126	70-27 50-335 50-269 70-2910 70-143
CAMBLLERI,T J. CAMPBELL,G G CAMPBELL,G G CAMPBELL,G G CAMPBELL,G G	8812060279 8811300008 8811300070 8812010024 8812120018	50-461 S 50-269 R 50-269 S 50-259 S 50-259 S	CHAMBERLAIN,D. CHAN,E.I. CHAN,E.I. CHAN,T.L. CHAN,T.L.	8812140166* 8812020117 8812190152 8812070135 8812080188	50-482 O 50-443 G 50-443 G 50-528 P TOPREP	CLINE,W.E CLINE,W.E CLINE,W.E. CLINE,W.E. CLINE,W.E.	8812130265 8812130265 8812150146 8812160045 8812160052	50-425 50-424 50-250 50-335 50-416
CAMPBELL, G. G CAMPBELL, G. G. CAMPBELL, G. G. CAMPBELL, G. G. CAMPBELL, G. G	8812140234 8812140236 8812200145 8812200222 8812200244	50-260 S 50-296 S 50-259 S 50-259 S 60-259 S	CHAN,T L. CHANDLEY,C A CHARNLEY,J E. CHARNLEY,J S. CHARNLEY,J S.	8812130031 8812210302* 8811290580' 8812070146' 8812050172*	TOPREP 50-390 A 50-285 Q 50-220 Q 50-440 P	CLINE,W.E. CLINE,W.E. CLINE,W.E. CLONINGER,T.H. CLONINGER,T.H.	8812190027 8812200324 8812210356 8812130295 8812200028	70 143 70 1151 70 27 50 116 50 416
CAMPBELL.G G CAMPBELL.G G CAMPBELL.T.G CAMPBELL.T.G CANTRELL.F.	8812210051 8812210064 8812210074 8912010155 8812060173*	50-259 S 50-266 S 50-259 S 50-313 H 50-260 O	CHASE.G CHASE.G H. CHAUDHARY,S.K CHAVEZ.J.M. CHENG.C Y.	8812210354 8812090182* 8811290576* 8012190075 8811170057*	40-8452 COMMISSIO N 50-293 C NUREG 50-316 Q	COCHRELL,R. COCKFIELD,D.W. COCKFIELD,D.W. COCKFIELD,D.W. COCKFIELD,D.W.	8812280114 0811290023 8912020023 8012050176 8812050302	NUPEG 50 344 50 344 50 344 50 344
CANTRELL,F.S CAPRA,A A. CAPRA,A A CAPRA,R A CAPRA,R A.	8812080162* 8812010258* 681205058 8812070112* 8812080130*	50-280 Q 50-220 P 50-333 Q 50-317 P 60-317 P	CHERNY, F.C. CHERY, D.L. CHESNUTT, S.W. CHEUNG, L CH.LDS, V.W.	8812070217 8811280208 8812190354 6811290567* 8812130301	TOPREP WASTE MGT 50:287 S 50:277 Q 50:333 S	COCKFIELD, D.W. COCKFIELD, D.W. COCKFIELD, D.W. COCKFIELD, D.W. COCKFIELD, D.W.	8812050313 8812070066 8812090177 8812140174 8812160046	50:344 50:344 50:314 50:344 50:344
CAPSTICK, R.W. CARGILLE M. CARLSON, J.D. CARLSON, R.W. CARMEN, W.C.	8812090308 8812020250 8812190409* 8812210034* 6811290176*	50-271 P 50-458 R 50-312 P 50-498 P WASTE RES	CHILDS,W.V. CHILDS,W.V. CHILDS,W.V. CHILK,S.J. CH-EK,S.J	8811300503 8812010145 8812080013 8811100283' 8611300578	50-333 S 50-333 S 50-333 S PR 10CFR	COCKFIELD, D.W. COE, D. COFFMAN, F.D. COLBURN, T.G. COLBURN, T.G.	8812210349 8812210023' 8812160059 8812090091 8812090270	50:344 50-528 03G 50:440 50:440
CARNS, M.S. CARNS, N.S. CARNS, N.S. CARNS, N.S. CARNS, N.S.	8812020233 8612010189 8812130013 8812150035 8812150039	60-382 S 50-382 S 50-382 S 60-382 S 50-382 S	CHILK'S T CHILK'S T CHILK'S T CHILK'S T	8912010026 8812010030 8812020037 8812020178 8812050092	10CFR 10CFR 50-322 G 50-482 P PR	COLBURN,T.G. COLE,R E COLEMAN,C.E. COLEMAN,C.E. COLEMAN,J.A.	8812130202* 0811300272* 0812230173 8812230163 8811090114	50:346 50:458 27:48 27:46 WASTE !JGI
CARPENTER D.R. CARPENTER D.W. CARPENTER S.A. CARPENTER S.A. CARRIK M.	6812200355* 6612190023* 8612230165 8612230195 8812130093	50-259 O WASTE RES 27-48 27-48 50-390 Q	CHILK,S.J. CHILK,S.J. CHILK,S.J. CHILK,S.J.	8812050257 8812050263 8812050311* 8812060238 8812060250	10CFR 50-171 P 50-390 Q PR 10CFR	COLLINGS,S.P. COLLINGS,S.P. COLLINS,D.M COLLINS,D.M COLLINS,D.M.	8812050001 8812210252 8811300430 8811300571 8811300573*	40 9829 40 8829 50 039 50 424 50 424
CARRASCOJ. CARRIONAR. CARTER.R.S. CARTER.T.H. CARTWIGHT,W.R.	8811290576* 8812080054* 8812010113 8812270048* 8812270201	50-293 Q 50-250 Q PR 50-346 Q 50-280 P	CHILK, S.J. CHILK, S.J. CHILK, S.J. CHILK, S.J.	8812060323 8812070020 8812080219 8812090255 8812120122	PAM PAM PR PR FOIA	COLLINS,D.M COLLINS,D.M. COLLINS,D.M. COLLINS,D.M. COLLINS,D.M.	8812180262 8812180045 8812180050* 8812180050*	70-1151 50-280 50-424 50-424 50-280
CARTWAIGHT,W.R. CARTWAIGHT,W.R. CARTWAIGHT,W.R. CARTWAIGHT,W.R. CARTWAIGHT,W.R.	6811230387 8811290019 8811300374 8811300394 8812010031	50-280 P 50-338 Q 50-289 P 50-280 F 50-338 P	CHILK,S J. CHILK,S J. CHILK,S J. CHILK,S J.	8812130257 8812140032 8812140067 8812140084 8812190384	50-322 F 50-322 G 50-322 G 10CFR FOIA	COLLINS,D.M. COLLINS,D.M. COLLINS,E.P. COLLINS,S.J. COLLINS,S.J.	8812210021 8812210068 8812010343 8811290378 8811290378	50 400 50 269 NUREG 50 263 50 260
CARTWRIGHT,W.R. CARTWRIGHT,W.R. CARTWRIGHT,W.R. CARTWRIGHT,W.R. CARTWRIGHT,W.R.	6812010037 8612020093 6612050105 6812060065 6812060102	50-280 F PR 50-281 P 60-336 P 50-280 P	CHLK,S.J. CHILK,S.J. CHILK,S.J. CHIU,R. CHOW,T.	8812210178 6812270171 6812270172 6812270172 6812010003 8812200221	50-293 F 50-443 G 60-443 G FOIA REVIEW GR P	COLLINS,S.J. COLLINS,S.J. COLLINS,S.J. COLLINS,S.J. COLLINS,S.J.	8811300287 8811300292 8811300335 8811300347 8811300419	50 293 50 293 50 293 50 293 60 293
CARTWRIGHT, W.R. CARTWRIGHT, W.R. CARTWRIGHT, W.R. CARTWRIGHT, W.R. CARTWRIGHT, W.R.	8812070084 8812130066 8812130071 8812130081 8812150135	50-338 P 50-280 F 50-280 F 50-280 F 50-280 P	CHRISTANSEN,H. CHRISTMAN,J.N. CHRISTMAN,J.N. CHRISTMAN,J.N. CHRISTMAN,J.N. CHRISTMAN,J.N.	8812160136* 8812140070 8812140070 8812270049 8812270049	50-416 Q 60-322 G 50-322 G 50-322 G 50-322 G	COLLINS,8 J. COLLINS,8 J. COLLINS,8 J. COLLINS,8 J. COLLINS,8 J.	8811300474 8811300478 8811300485 8811300520 8811300577	50 293 50:293 50:293 50:293 50:293
CARTWRIGHT, W.R. CARTWRIGHT, W.R. CARTWRIGHT, W.R. CARTWRIGHT, W.R. CARTWRIGHT, W.R.	8812200067 8812200104 8812200157 8812200170 8812220060	50-280 Q 50-280 R 50-338 R 50-280 Q 50-338 F	CHRISTOFFER,G. CHRISTOPHER,T. CHRZANOWSKI,R. CHRZANOWSKI,R. CHRZANOWSKI,R.	881 1300542° 881 2210152° 881 1300444 881 2010121 881 2010228	50-373 Q 71-24 50-454 Q 50-454 P 50-454 P	COLLINS,S.J. COLLINS,S.J. COLLINS,S.J. COLLINS,S.J.	0612120268* 8812120269* 8812130067* 8812130076* 8812130086*	50 293 50 293 50 293 50 293 50 293
CARTWAIGHT,WA CARTWAIGHT,W.R. CARVALHO,A.M. CASTO,C. CAT,N.	8812230275 8812270232 8812200332 8812220352 8812010369	* 50-335 V 50-327 F	CHRZANOWSKI,R. CHRZANOWSKI,R. CHRZANOWSKI,R. CHUNG,D.H. CICOTTE,G.R.	8812090286 8812200274 8812230162 8812160187 8812190415*	60-454 P 50-454 P 50-454 P WASTE RES 50-528 Q	COLLINS,S.J. COLLINS,S.J. COLLINS,S.J. COLLINS,T.R. COMWAY,W.F.	8812130087* 8812130090* 8812130092* 8812090315* 8811290141	50-233 50-233 50-233 50-302 50-259
CATANO J.I. CATCHPÔLE G.J CATCHPOLE G.J. CATCHPOLE G.J. CATCHPOLE G.J.	8612010029 8611300379 8811300381 8812200311 8812210106	40-8958 • 40-8958 40-8958 40-8926	CILLIS,M. CLARK,L.B. CLARK,R.J. CLARK,R.J. CLAY,E.L.	8812050204* 8812190143 8812150121 8812160104 8812210380*	50-322 G 50-352 P 50-352 P	CONGEMI,J. CONKLIN,C. CONKLIN,C.J. CONLON,T. CONLON,T.E.	8812010047 8811210020* 8812140030* 8812050255* 8812050245*	60-443 60-424
CATE.P.D. CENTOLANZI,P. CERVENKA,P. CESARE.J.G. CESARE,J.G.	8812210233 8812200053 8811290561 8811280107 8811290438	50-382 FI 50-219 S 50-416 S 50-416 P	CLAY,W.L. CLAYTON,B. CLAYTON,B. CLAYTON,B. CLAYTON,B.	8811300222* 8811280073 8811300446* 8812010171 8812140255	50-454 Q	CONLON,T.E. CONLON,T.E. CONNER,J.V. CONNORS,H.J CONSTABLE,G.L.	8812080343° 8812200341° 8812010313 8812160029° 8811300248°	50-338 50-458 60-275
CESARE,J.G. CESARE,J.G. CESARE,J.G.	8811290549 8811300283 8812020299	50-416 P	CLAYTON,B. CLAYTON,B. CLAYTON,B.	881214D258° 8812190365 8812190370°	50-254 Q	CONSTABLE,G.L. CONTE,R. CONVERSE,R.J.	8812140083° 8811200026° 6811290039	

CONVERSE R J. CONVERSE R J. CONVERSE R J. CONVERSE R J. CONVERSE R J.	8811300503 8812010145 8812080013 8812130001 8812130301	50-333 50-333 50-333 50-333 50-333	5 5 5 5 5 5 5	COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G	8812200065 8812200066 881220083 8812200143 8812200156	50-445 50-445 50-445 50-445 50-445	55555	CUNNINGHAM,R.E. CUNNINGHAM,R.E. CUNNINGHAM,R.E. CUNNINGHAM,R.E. CUNNINGHAM,R.E.	8811290030 6812120023 6812120053* 6812190098* 9812220045*	50-3 40-8027 FOIA 50-603 50-603
CONVERSE, R.J. CONVERSE, R.J. CONVERSE, R.J. CONVERSE, R.J.	8912150126 8812190010 8812200073 8812200155 8812210262	50-333 50-333 50-333 50-333 50-333	araac	COUNSIL,W G. COUNSIL,W G. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G.	8812200179 8812200184 8812210073 9812210078 8612210031	50-445 60-445 50-445 50-445 50-445	E S Q Q	CLOCO,L CURRAN D. CURRAN,D. D'ANGELO,A D'ANGELO,A	8612290291° 8812020084 8812020084 8812120003° 8812200275	FOIA 50:443 50:443 50:387 50:312
CONWAY,UT. CONWAY,WE. CONWAY,WE. CONWAY,W.F. CONWAY,W.F.	8812210321* 8811280041 8611230275 8811280064 8811280199	OA999 50-250 50-250 50-250 50-389	R S S P	COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G.	8812210129 8812210135 8812210157 8812210163 8812220011	50-445 50-445 50-445 50-445 60-445	s s s	D'ANGELO,A.J. DAEMEN.J DAHL.G DALLMAN.R.J DAMASCENO,E	8812180342* 8812180201* 8812080110 8812180094 8812200328	50-312 WASTE RE 50-247 NUREG REVIEW G
CONWAY,W.F. COMWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F.	8811290335 8811290367 8812010132 8812060114 8812070138	50-335 50-250 PR 50-250 50-250	P R P	COUNSIL,W.G. COUNSIL,W.G COUNSIL,W.G COUNSIL,W.G. COUNSIL,W.G.	8812220018 8812220071 8812270170 9812270174 8812270175	50-445 50-445 50-445 50-445 50-445	A A S S	DAMON D J. DANCE, H. DANCE, H.C. DANCE, H.C. DANCE, H.C.	8812190340* 8812090332 8812050262* 8812050290* 8812160136*	50-315 50-416 50-395 50-348 50-416
CONWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F.	8812080149 8812080233 8812090125 8812120186 8812120180	50-335 50-335 50-250 50-250 50-250	Q G F P S	COUNSIL W G COUNSIL W G COUNSIL W G COUNSIL W G COUNSIL W G	8812270177 8812270184 6812270189 8812270190 8812270224	50 445 50 445 50 445 50 445 50 445	S A A S	DANCE,H.C. DANIEUSON D DANIEUSON,D.H. DANIEUSON,D.H. DAV:OSON,B.	0812200206* 8812140044 8812020206* 88122100109*	50-395 50-331 50-263 50-316 50-317
CONWAY,W F CONWAY,W F CONWAY,W.F CONWAY,W.F CONWAY,W.F	8812140198 8812150042 8812160034 8812160071 8812190129	50-251 50-335 50-250 60-250 50-335	О Р Р Я	COURTEMANCHE,S, COURTEMANCHE,S, COWGILL,C, COWGILL,C,J, COWGILL,C,J,	8812080203 6812133153 6811290026' 8611300269 8811300519	18 E 18 E 50 320 50 244 50 289	О Ф Я	DAVIDSON,B.S. DAVIS,A.B. DAVIS,A.B. DAVIS,A.B. DAVIS,A.B.	8812080027* 8811300406* 8811300406* 8811300534 8811300540*	50-334 50-456 50-456 50-255 50-255
CONWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F.	8812200008 8812200131 8812200197 8812200203 8812200352	50-250 60-250 60-250 60-260 60-250	R P S F	COWGILL,C.J. CRAMPTON,S. CRANWELL,R.M. CRANWELL,R.M. CRANWELL,R.M.	8812150080° 8812130311 8811200115 8812190149 8812190173	50-244 CONTRAC WASTE RI WASTE RI	ES ES	DAVIS A.B DAVIS A.W. DAVIS,A M DAVIS,E.W DAVIS,G M.	8812080222 8812050027 8812050073 8812010272 8812010189	50-254 40-8907 40-8907 PR 50-382
CONWAY,W F CONWAY,W.F. CONWAY,W.F. CONWAY,W.F.	8812200362 8812220136 8812230027 8812270272 8812190010	50-335 60-250 60-250 50-335 50-333	S P Q R	CRAWFORD, J.D. CRAWFORD, M.L. CRECINE, J.P. CREED, J.R. CREED, J.R.	8811306008 8812090348 8812160053 8811290008*	50-259 50-416 50-160 50-409 50-346	R P Q Q	DAVIS J DAVIS LA DAVIS M J. DAVIS S J. DAWES G.W.	6812270195 8811290176* 8811300138 8812200041* 6811300275	I&E WASTE RE 50-528 50-416 40-8778
COCPER R.W. COCPER R.W. COCPER T. COPELAND R.A COPPOLA A.	8811300062* 8812140238* 8812160127* 8811280147 8811160327	50-341 60-461 50-324 TOPREP 60-286	000	CREED, J.R. CREED, J.R. CREED, J.R. CREWS, J. CRIBBE, Y.E.	8811300542° 8812060145° 8812210244° 8812210023° 8812018144	50-373 50-456 50-282 50-528 50-277	Q Q Q Q S	DAWSON,M DAWSON,M DAWSON,M DE AGAZIO,A.W. DE AGAZIO,A.W.	8811280116 8812010195 8812120254 6812090239 8812130159	50-255 50-255 50-255 50-346 50-346
COPPOLA A. COPPOLA A. COTTEN P. R COTTEN B P. COTTEN B P.	8811180341 8811180348 8812090104* 8812140038 8812140045	50-352 50-245 70-734 50-604 60-803	Q Q G	CRIBBE,T.E CRIBBE,T.E CRIBBE,T.E. CRIBBE,T.E. CRLENJAK,R.	8812010157 8812120247 8812150275 8812200121 8812090296	50-277 50-277 50-277 50-277 50-302	s s s s	DE AGAZIO,A W. DE AGAZIO,A W DE AGAZIO,A.W. DEAGAZIO,A DEAGAZIO,A W.	8812130277 8812130278* 9812220337* 8812150089 8812130200	50-346 50-346 50-346 50-346 50-346
COTTER,B.P. COTTER,B.P. COTTLE,W.T. COTTLE,W.T. COTTLE,W.T.	8812140078 8812190150 8811290339 8812070017 8812080104	50-250 60-335 60-416 50-416 50-416	G G P K	CRLENJAK,R. CRLENJAK,R.V. CRLENJAK,R V. CRLENJAK,R V. CROCKER,D.M.	8812200176* 8911290010 8812080059* 8812280003*	50-302 50-250 50-250 60-335 50-322	0 0 0 0 0	OEAGAZIO,A W. DEAN,G B DEAN,J.L DEAN,R.S DECKER,T.R.	8812220326 8812270042 8812080021* 8812010348 8811160217	50-346 50-271 50-320 NUREG 50-416
COTTLE W.T. COTTLE W.T. COTTLE W.T. COTTON S.R. COUCHC.	8812120127 8812200380 8812210251 8812090168 8811300118	50-416 50-416 50-416 50-416 40-8027	Р Р Р	CROCKER, L.P. CROCKER, L.P. CROCKER, L.P. CROCKER, L.P. CROCKER, L.P.	8B11300090 8B12050063 8B12050069 6B121B0035 8B12200037	60-321 50-321 60-321 60-321 50-321	9999	DECKER,T.R. DECKER,T.R. DECKER,T.R. DECKER,T.R. DECKER,T.R.	8811150221* 8811230266 8811230267* 8811280210 8811300460	50-416 70-1151 70-1151 50-338 70-1151
COUNSIL W.G. COUNSIL W.G. COUNSIL W.G. COUNSIL W.G. COUNSIL W.G.	8811230007 8811230007 8811230044 8811230248 8811290042	50-445 50-445 60-445 50-445 50-445	5 8 8 0	CROCKER, L.P. CROLEY, B.G. CROLEY, B.G. CROSS, B.T. CROSS, B.T.	8612220032 8811290346 8812210141 8812090013* 8812090060*	50-321 50-312 50-312 50-247 60-315	թ F P	DECKER,T.R. DECKER,T.R. DECKER,T.R. DECKER,T.R. DECKER,T.R.	8811300565 6811300574* 6812050296 8812080181 6612080182*	50-250 50-424 70-27 50-280 50-280
COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G.	8811300172 8812020034 8812020107 8812020219 8812020221	60-445 60-445 PR 50-445 60-445	A F A Q	CROSS.J.E. CROSS.J.E. CROTEAU,H. CRUNK,S.L. CRUTCKFIELÐ,D.	8812090125 8812200352 8812160170 8812200124 8811260048	50-250 50-250 50-369 60-312 50-3	F Q P P	DECKER,T.R. DECKER,T.R. DECKER,T.R. DECKER,T.R. DECKER,T.R.	8812090263 8812090273 8812090278* 8812090299 8812090312	50-424 50-324 50-324 50-424 50-302
COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G.	8812050205 8812050211 8812050216 8812050220 8812050329	50-445 50-445 50-445 50-445 50-445	s 0 9 8	CHUTCHFIELD,D. CHUTCHFIELD,D. CRUTCHFIELD,D. CRUTCHFIELD,D. CULBERSON,D.G.	8811290064 8811300213 8811300223 8811300135 8812070255	PROJ PROJ 50-601 50-605 70-364	A A	DECKER,T.R. DECKER,T.R. DECKER,T.R. DECKER,T.R. DECKER,T.R.	8812160231 8812160132 8812160141 8812160171 8812190190	70-143 70-1201 50-424 50-321 70-27
COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G.	8812060007 8812060012 8812060032 8812060035 8812060152	60-445 50-445 50-445 50-445 50-445	5 0 0 5 8	CULBERSON,D.G. CULLEN,J.F. CULLEN,J.F. CULLEN,J.F. CULLEN,W.H.	8912150209 8812050180 8812050184* 8812050186* 8812190123	70-364 40-8911 40-8911 40-8911 NUREG		DECKER,T.A. DECKER,T.R. DECKER,T.R. DECKER,T.A. DECKER,T.R.	8012190195 8812190203 6812190243 8812190244 8812190257	50-261 50-160 50-302 50-280 60-424
CCUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G.	8812060158 6812060166 8812120013 8812130271 6812150055	50-445 50-445 50-445 50-445 50-445	S G A S	CUMMINGS,R.A. CUMMINGS,R.A. CUMMINGS,R.A. CUMMINGS,R.A. CUMMINGS,R.A	6B12090246 8B12120224 6B12140134 6B12140173 8612190169	WASTE R WASTE R WASTE R WASTE R	es es es	DECKER,T.R. DECKER,T.R. DECKER,T.R. DECKER,T.R. DECKER,T.R.	8812190268 8812200006 8812200032 8812200159 8612200232	50-302 50-297 50-400 50-302 60-259
COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G.	8812200038 8812200040 8812200044	50-445 50-445 50-445	S A S	CUNNINGHAM,A L. CUNNINGHAM,R.E. CUNNINGHAM,R.E.	8811300574° 8409130075° 8811160211	50-424 I&E 50-3	o o	DECKER,T.R. DECKER,T.R. DEODENS,J.C.	8812200245 8812210055 8811300191	50-302 70-1151 50-458

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBLECT CATEGORI
DEDDENS, J.C. DEDDENS, J.C. DEDDENS, J.C. DEDDENS, J.C.	8812010391 6812060006 6812060172 6812060229 8812140103	PA 50-458 H 60-458 P 50-458 Q 60-458 F	DRISCOLL,J.W. DRISCOLL,M.J. DROMER:CK,A.W. DROMER:CK,A.W. DROMER:CK,A.W.	8812010073 8812050139° 8812010141 8812130283 8912130289°	NUREG 50-20 P 50-219 P 50-219 P 50-219 P	ERICKSON,P.B ERNST,M. ERNST,M.L ERNST,M.L ERNST,M.L	8811300112 8812190277 8811230091 8011230116 8811280066	50-171 50-425 G 50-250 F 50-150 G 50-370 P
DEDDENS, J.C. DEDERER, S.L. DEELSNYDER, L. DEFAYETTE, R.W. DEFAYETTE, R.W.	6812140107	50-458 F	ORUGA,A J.	6811300509	50-334 R	ERNST,M.L	8811280216	50-413 Q
	6812090285*	50-266 P	DUDEK,O.F.	6811280117*	TOPREP	ERNST,M.L	8811290151	50-26 Q
	6812200010	60-254 R	DUDLEY,N.F.	6811290139*	50-247 P	ERNST,M.L	8811290366	70-27
	6812210133	50-483 S	DUGSTAD.D.	6812140253	50-282 R	ERNST,M.L	8811290368	70-27
	6811290344*	60-348 Q	DUNN,G A.	6811220208*	50-440 S	ERNST,M.L	8811290559	50-269 Q
DEFAYETTE.R.W.	8811299374*	50-346 Q	DUNN,G A	8811290107	50.440 S	ERNST,M.L	8811300045	50-400 Q
DEFAYETTE.R.W.	8811299377*	50-346 Q	DUNN,G A	8812050067*	50.440 S	ERNST,M.L.	8811300209	50-250 Q
DEFFERDING.L.	8812209335*	50-528 V	DUNN,G A	8812190356*	50.440 S	ERNST,M.L.	8812050312	50-259 Q
DEICHLER.J.K.	8812069075*	FOIA	DUNN,G A	8812200187	50.440 R	ERNST,M.L.	8812060006	50-359 Q
DEICHLER.J.K.	8812069081*	FOIA	DUNN,G A.	8812270062*	50.440 S	ERNST,M.L.	8812060128	50-359 Q
DEICHLER,J.K.	8812060093°	FOIA	DUPREE.D.C.	8811290082	50-327 R	ERNST,M.L.	8812060170	50 260 -0
DEICHLER,J.K.	8812060123°	FOIA	DUPUY,J,	8812210060	WASTE MGT	ERNST,M.L	8812080113	50 460 -0
DEICHLER,J.K.	8812060178°	FOIA	DURA,J.	8811300147	50-220 Q	ERNST,M.L	8812080118*	50 460 -0
DEICHLER,J.K.	8812060183°	FOIA	DURA,J.	8812120049*	50-309 Q	ERNST,M.L.	8812090369	50 355 -0
DEICHLER,J.K.	6812060189°	FOIA	DURA,J.P	8811290059	50-247 Q	ERNST,M.L.	8812090100	50 362 -0
DEICHLER,J.K. DEICHLER,J.K. DEICHLER,J.K. DEICHLER,J.K. DEKOK,D.	8812060192° 8812060200° 8812060203° 8812060205° 8812060013	FOIA FOIA FOIA FOIA	DURR, J.P. DURR, J.P. DURR, J.P. DURR, J.P. DUTT O N, J.W.	8811290548 8811300307 8812080153 8812220306 8812140213*	50:333 Q 50:387 Q 50:247 Q 50:353 Q 50:298 V	ERNST.M.L ERNST.M.L ERNST.M.L ERNST.M.L ERNST.M.L	8812090335 8812150170 8812190125 8812190142 8812190272	50 269 H 50 395 O 50 502 P 50 280 O 50 425 A
DELGEORGE,L.O.	8811300037	60-254 Q	DWYER, P.A.	8812280087	NUREG	ERNST,M.L	8912200307	50 269 0
DELLA RATTA,A	8812120035*	70-687	DWYER, P.A.	8812280105	NUREG	ERNST,M.L.	8812200314	50 260 P
DELLA RATTA,A	8812210408*	70-1703	DYAS, K.E.	8812210062	40-8502	ERNST,M.L.	8812200348	50 321 0
DELPERCIO,J.G	8812120097	60-247 S	DYER, J.E.	8912130046*	50-331 Q	ERNST,M.L.	8812210059	50 321 0
DEMIRANDA,O.	8812190009*	60-424 Q	DZIADOSZ, D.	8812270243*	50-280 P	ERNST,M.L.	8812210237	50 330 0
DEMOSS.G.	8812010343	NUREG	EAPEN,P K.	8811280076*	50-247 Q	ERNST,M L.	8812210257	50 363 Q
DEMPSEY,T.M.	8812270141°	60-219 S	EAPEN,P.K.	8812220397*	50-353 Q	ERNST,M L.	8812220021	50 263 Q
DENNISON,W.F.	8812220005	71-3005	EARNEST A B.	8812150105*	50-498 Q	ERNST,M.L.	6812220041	50 416 Q
DENTEN,J.G.	8612190120	NUREG	EBNETER,S.D.	8811290177	50-247 F	ERNST,M L	6812220112	50 424 Q
DENTON,H.R.	8609090425°	FOIA	EBNETER,S.D.	8811290364	50-272 Q	ESELGROTH,P.W.	6811290359	50 223
DENTON,H.R.	8812050330°	FOIA	EBNETER, S.D.	8811290504	60-220 Q	ESELGROTH,P.W.	8812090152	50-399 Y
DENTON,H.R.	8812200306	REVIEW GR P	EBNETER, S.D.	6812230030	50-309 Q	ESELGROTH,P.W.	881215016*	50-213 Q
DENTON,H.R.	8812200333	REVIEW GR P	ECKENRODE, R.J	6812060071	MISC	ESPOSITO,G.	881210382	PR
DENTON,H.R.	8812200382	REVIEW GR P	ECONOMOS, N.	6812050267*	50-280 Q	EVANS,D.	8812096007	50-170 A
DESAI,B.	8812160116°	50-424 Q	ECONOMOS, N.	6812070248*	50-280 Q	EVERETT,R.J.	8811290460*	50-200 Q
DEV.M. DEWEASE,J.G. DEV.M. DEV.M.K.	8812080156* 8812120105 8812200032 8812020308 8812020311	50-244 Q 60-382 P 50-382 K NUREG NUREG	EDGE,W.E EDGEWORTH,P.J. EDGEWORTH,P.J. EDGEWORTH,P.J. EDGEWORTH,P.J.	8812200231 8812010282° 8812130171° 8812140096° 8812160161°	50-416 R CONTRACT CONTRACT CONTRACT CONTRACT	EVERETT, A J EVERETT, R. J FAIRTILE, M. FAIRTILE, M. B. FAIRTILE, M. B.	8812150105* 6612210304* 6811280092 8811200455 8812130149	50-498 C 50-313 C 50-29 F 50-29 C 50-29 F
DEYOUNG G.L.	8811300450	50-237 P	EDGEWORTH,P J.	8912190040*	CONTRACT	FAIRTILE,M.B.	6812130205	50-29 F
DICHARRY, R.D.	8811290336	71-102	EDISON,G E.	8812050118	50-251 P	FAIRTILE,M.B.	6812140072	50-271 G
DICHARRY, R.D.	8811300028	71-102	EDISON,G E.	8812130198	50-250 P	FAIRTILE,M.B.	6812160130*	50-271 G
DICK, G.F.	8811290322	50-499 A	EDISON,G.E.	8812130211	50-250 P	FANNON,M.	6812010276*	CONTRACT
DICK, G.F.	8812020283	50-498 P	EENIGENBURG,E	8812010151	50-237 S	FANTACCI,C.L.	6812020250	60-458 F
DICK.G.F.	8812070192	50-498 P	EENIGENBURG,E	8812080031	50-237 S	FARBER,M.J.	8811200377*	50-345 C
DICK.G.F.	8812080061	50-498 P	EENIGENBURG,E	8812160250	50-237 S	FARRELL,C.W.	8812210147	40-5973
DICK.G.F.	8812080070	50-498 P	EENIGENBURG,E	8812190416	50-237 R	FARRELL,R.E.	8811300563*	50-267 C
DICK.G.F.	6812080076	50-498 P	EENIGENBURG,E	8812200205	50-249 S	FAULKEN,M.	8812130052	50-493 F
DICK.G.F.	6812090305	50-499 A	EENIGENBURG,E	8812210280	60-237 S	FAY,C.W.	8811290021	50-266 C
DICK,G.F.	8812090324	50-499 J	EGAN, L.G.	8812090207*	COMMISSIO N	FAY.C.W.	8812010006	50-266
DICK,G.F.	8812130250	50-499 A	EGER, W.H.	8812130118	50-213 S	FAY.C.W.	8812050121	50-266
DICK,G.F.	8812220391	60-499 P	EICK, S.	8812090262*	50-341 Q	FAY.C.W.	8812050188	50-266
DIEDERICH,G.J.	8811300427	50-374 S	EISENHUT, D.G	8812080044*	50-294 P	FAY.C.W.	8812050221	50-301
DIEDERICH,G.J.	8812060021	50-373 S	ELIN, J.O.	8812060082*	50-397 V	FAY.C.W.	8812090090	50-266
DIEDERICH,G.J. OIEDERICH,G.J. DIEDERICH,G.J. DIEDERICH,G.J. DIERCKS,D.R.	8812070211 8812070214 8812200049 8812270237 8812190153	50-373 S 50-373 S 50-373 R 50-373 S NUREG	ELIN.J.O. ELLEMAN,T.S. ELLERSHAW,L.E. ELLISON,J.J. ELLWANGER,J.	8812200335* 8812350108 8812150108 8812130016	60-528 V 50-207 O 50-313 Q PH 60-247 S	FAY,C.W. FAY,C.W. FAY,C.W. FAY,C.W. FAY,C.W.	8812090281 8812100218 8812200173 8812210095 8812270234	50-266 50-266 50-266 50-266 50-266
D.ETZ.C.R.	8811300173	50-498 P	ELMS,A.L.	8812160097	50-423 R	FELTON,J.M.	6612050126	FOIA
DIETZ.C.R.	8812160007		ELSASSER,T.	8612050288*	50-171 P	FELTON,J.M.	6612090269	FOIA
DIFFERENT,P.M.	8812060017		ELWARD,T.W.	8612130304	50-165 R	FENN,K.W.	8612140250	50:328
DIGGS,R.M.	8811300492		EMRIT,R.	8612020170	NUREG	FERADAY,M.A.	8612220060	WASTE MOT
DIGGS,R.M.	8812070028		ENDERMANN,G.M.	8812010126	PR	FERDINAND,B.	8812050019	40:8905
DIGNAN,T.G. DIGNAN,T.G. DIIANNI,D.G. DILWORTH,S.C: DINGELL,J.D.	8812140037 8812140037 8812120005 8612200001 8612130096	50-443 G 50-282 Q 50-424 R	ENGLANDILA ENGLANDILA ENGLANDILA ENGLANDILA ENGLANDILA	8811300196 8811300287 6811300286 8811300318 8812010232	50-458 S 50-458 S 50-458 S 50-458 S 50-458 S	FERSTER,A. FERSTER,A. FERSTER,A. FERSTER,A. FERSTER,A.C.	8812280058 8812280058 8812280065 8812280065 8812180227	50-271 50-271 50-271 50-271 50-271
DIPIET RO,R.R. DIXSON,G.R. DOMINGUEZ,D. DONOHEW,J.N. DORSEY,M.	8812010325 8812080239 9812010255 8812020177 8812010226	WASTE MGT PR 50-327 P	ENGLE, L. ENGLE, L.B. ENGLE, L.B. ENGLE, L.B. ENGLE, L.B.	8812130144 8812010164 8812070118 8812080032 8812080038	50-338 P 50-338 P 50-338 P 60-338 P 60-338 P	FERSTER, A.C. FEY, F.L. FIEDLER, P.B. FIEDLER, P.B. FIELDMAN, J.	8812190227 6812210198 8812010019 8812010039 8611300041	50-271 50-262 50-210 50-210 50-254
DORUFF, M.A. DOUGHTY, J. DOUGHTY, J. DOWD, P.A. DOWNS, W.E.	8812120036 8812190044 8812190080 8812070245 8812200103	50-443 G 60-443 G 50-293 H	ENGLE,L B. ENGLE,L.B. ENGLE,L.B. ENGLE,L.B. ENGLE,L B.	8812120078 8812130119 8812160092 8812220222 8812220228	50-339 P 50-338 P 60-338 P 50-336 P 50-338 P	FIELOMAN,J. FIELDS,J. FIELDS,J.S. FIERCE,A.R.	8812270202 8811290203 6812190039 6811300321 6812140128	50-254 CONTRACT CONTRACT 50-387 50-443
DOYLE,W.	8812010120	. 20-355 C	ERICKSON,P.B.	8811290429	50-409 J	FIORELLI,G.	8812120003*	60:397
DRAGOUN,T.	8811290011		ERICKSON,P.B.	8811290444	50-16 J	FIORELLI,G.	8812210023*	50:528
DREY,K.	8811300224		ERICKSON,P.B.	8811290462	50-133 J	FIRLIT,J.F.	8811280091	50:312

	NUMBER	CATEGORY		NUMBER	CATEGORY		NUMBER	CATEGO
FIRUTUF. FIRUTUF. FIRUTUF. FIRUTUF.	8811290343 8811300013 8811300019 8811300020 8811300244	50-312 P 50-312 Q 50-312 S 50-312 S 50-312 P	FUNK,O.F. FURIA,J. FURIO,P. FURIO,P.	8811290008° 8811300326° 8812210022° 8812220138 8812270226	50-408 Q 50-333 Q 60-317 Q 50-317 S 50-317 S	GILL, C.F. GILL, C.F. GILL, C.F. GILMAN, B.D. GILMAN, B.A.	6612020201° 8812090183° 8812200655° 8812270260° 8811300290°	50-254 40-7604 50-483 CGNTRAC 50-3
FIRLUTUE	8812010130	50:312 H	GAD,R K.	8812140075	50-271 G	GILMAN,B.A	8812090238*	COMMISSI
FIRLUTUE	8812060009	60:312 P	GAD,R K	8812140075	50-271 G	GILMORE,W.E	8812190018	NUREG
FIRLUTUE	8812190408	50:312 P	GAD,R K	8812140086	50-271 G	GILMORE,W.E.	8812190037	NUREG
FIRLUTUE	6812200130*	50:312 P	GAD,R K.	8812140086	50-271 G	GILMORE,W.E	6812190086	NUREG
FISCHERID C.	8811230054	MISC	GAD,R K.	8812140093	50-271 G	GLEASON,E J	8812020130*	50-322
FISHA	8812010287* 8811290032* 8812210058 8811210082 8812080088	70-734	GAD,A K	8812140093	50-271 G	GLEASON,E J.	8812020130*	50-322
FISHAF.		50-206 Q	GAD,A.K.	8812140111	50-271 G	GLEASON,E J.	8812020130*	50-322
FISHAF.		50-312 F	GAD,A.K.	8812140111	50-271 G	GLEASON,J P.	8812020017	50-322
FISHEAJE.		50-280 Q	GADDIE,K.	8812010190	50-255 F	GLEASON,J P.	8812020024	50-322
FISKAH		XPORTLIC	GAGLIARDO,J E.	8811300214*	50-382 Q	GLEASON,J P.	8812140092	50-322
FISK AH FISK AH FISK AH FISK AH FISK AH	8812080087* 8812150034 8812150104* 8812200063* 8812200095	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	GAGLIARDO,J.E. GAGLIARDO,J.E GAINES,C.R. GALLAGHER,J. GALLAGHER,J.W.	8812210313* 8812210342* 8812130013 8812120093 8811020184	50-285 O 50-482 O 50-382 S 50-352 S 50-352 F	GLENN.J. GLENN.J. GLOERSEN,W.B. GOLOBERG,J.H.	8812080203 8812130153 8812080039* 8812160144* 8911290164	18E 18E 60-280 60-424 60-498
FITZPATRICK, E.	8811280114	50-219 S	GALLAGHER, J.W.	8811290350	50-277 P	GOLOBERG,JH	8811300456	50 499
FITZPATRICK, E.	8811290557	50-219 S	GALLAGHER, J.W.	8012020225	50-277 S	GOLOBERG,JH	8812020090	50 498
FITZPATRICK, E.	8811290581	50-219 S	GALLAGHER, J.W.	8612060295	50-352 S	GOLDBERG,JH	8812060296	50 499
FITZPATRICK, E.	8812010022	60-219 Q	GALLAGHER, J.W.	8812120206	50-277 F	GOLDBERG,JH	8812090346	50 499
FITZPATRICK, E.	8812020262	50-219 P	GALLAGHER, J.W.	8812210292	50-352 H	GOLDBERG,JH	8812130287	50 499
FITZPATRICK,E. FITZPATRICK,E. FITZPATRICK,E. FITZPATRICK,E. FITZPATRICK,E.	8812160058 8812160157 8812160166 8812210048 8812210109	50-219 S 50-219 F 50-219 P 50-219 R 60-219 S	GALLAGHER, J.W. GALLAGHER, J.W. GALLEGOS, R.C. GALLO, R. GALLO, R.M.	0812220020 0812220056 8812060330* 8811290238 8811300281	60-171 P 60-362 P 70-822 50-352 Q 60-247 V	GOLDBERG,J.H. GOLDBERG,J.H. GOLDBERG,J.H. GOOD,G.M	8812200012 8812200016 8812200266 8812200267 8611290032*	50-498 50-499 50-498 50-499 50-206
FITZPATRICK,E	8812210355	50-219 S	GALLO,R.M.	8812050008	50-352 V	GOODEN,A	8812160134*	70-1201
FITZPATRICK,E.	8812270260	50-219 S	GALLO,R.M.	8812080155	50-244 Q	GORALSKI,G.	8812140261	50-255
FLACK,E	8812120177	I&E	GALLO,R.M.	8812120228	60-247 V	GORDON,J.	8812050056	PR
FLEENOR,C	8812010284	CONTRACT	GALLO,R.M.	8812150014	50-213 Q	GORE,B.F.	8811180288	60-317
FLEENOR,C.M.	8812150060	CONTRACT	GALLO,R.M.	8812270233	50-286 Q	GORMAN,E.J.	8812010191	PR
FLYNNHJ. FLYNNHJ. FLYNNHJ. FLYNNHJ.	8812020089 8812020149 8812100001 8812100004* 8812190007*	50-443 G 50-443 G 50-443 G 50-443 G 60-443 G	GALYEAN,W J. GAMBLE,O.C. GARCIA,P.J. GARCIA,P.J. GARCIA,P.J.	8812190094 8812210353 8812210071 8812210170 8812210230	NUREG 71-9107 40-8902 40-8905 40-8902	GORMAN,E J. GORMAN,E J GRACE,D.N GRACE,D.N GRACE,S.R.	8812020054 8012050022 8812150086 8812210236 8812010398	PR PR TOPREP TOPREP 40-8904
FOBES.R.L	8812020187*	50-265 S	GARCIA, P.J.	8612210235	40-8903	GRACE,S.R	881220290	40-8904
FOBES.R.L	8812020190*	50-255 S	GARCIA, P.J.	8812210374	40-8903	GRAHAM,P.D.	8812110396	50-458
FOGARTY.E.P.	8811300432	50-352 P	GARCIA, P.J.	6812220108	40-8907	GRANT,W.B	8812210396	50-454
FOGARTY.E.P.	8812010033	PR	GARCIA, P.J.	6812220114	40-8905	GRAVES,D.N.	8812210396	60-298
FOGARTY.E.P.	8812050048	60-352 S	GARDINIER, T.	6812010263	PR	GREBEL,T.	8812200096	50-275
FOGARTY, E.P.	8812200009	60-352 P	GARONER, R. N.	8812050214*	50-263 Q	GREBEL,T L.	8812270205	50-323
FOGARTY, E.P.	8812200195	50-352 S	GARDNER, R. N.	6812120087*	60-341 Q	GREEN,R E.	8812270298*	XPORTLIC
FOGARTY, E.P.	8812210357	60-352 S	GARDNER, R. N.	8812130136*	60-373 Q	GREENSLATT,M.	8812010294*	CONTRAC
FOLLEY, W.J.	8812010349	NUREG	GARONER, R. N.	8812190350*	50-254 Q	GREENMAN,E.G.	8811290373	50-348
FORD, C.A.	8812270243*	50-280 P	GARNER, B.	8812200157	50-338 R	GREENMAN,E.G.	8811290376	50-348
FORDEJ FORDJR. FORJW.L. FOXERJ.	8812140083° 8812010359 8812010190 8812200075° 8812120201°	50.458 Q 50.327 F 50.255 F 50.341 Q 50.280 Q	GARNER, L.W. GARNER, L.W. GASKIN, C.E. GAUTAM, A.S. GAUTAM, A.S.	8811280096* 8812200338* 6812280105 8812130136* 8812190350*	50-261 Q 50-261 Q NUREG 60-373 Q 50-254 Q	GREENMAN,E G. GREENMAN,E G. GREENMAN,E G. GREENMAN,E G. GREENMAN,E G	8811290424 8811300547 8812020248 8812050206 8812060286	50-331 50-456 60-254 60-456 50-341
FRANCE,G.M. FRANCO,F.F. FRANTZ,E.R. FRANTZ,S.P. FRANTZ,S.P.	8812090183*	40.7604	GAYLICK,G.	8812190084	XPORTLIC	GREENMAN.E.G.	8812060308	50-346
	8812070056	60.285 F	GAYLEY,R.B.	8811280114	50-219 S	GREENMAN.E.G.	8812080158	50-255
	8811280117*	TOPREP	GAYLEY,R.B.	9812150058	50-219 S	GREENMAN.E.G.	8812090293	50-341
	8812140079	50.250 G	GEARS,G.E.	8812090210	50-260 P	GREENMAN.E.G.	8812160072	50-440
	8812140079	50.250 G	GEIGER,J.	8812010161	50-237 S	GREENMAN.E.G.	8812190386	50-456
FRANZWA.	8812220001	71-9200	GELB,M.	8812020135	50-224 G	GREENMAN,E.G.	8812270074	50-440
FRASER,DL.	8812120238*	WASTE MGT	GELB,M.	9812020141*	50-224 G	GREENMAN,E.G.	8812270253	50-263
FRECRICKSON,P.	8812050275*	50-324 Q	GEORGE,M.	9812080151	XPORTLIC	GREER,L.B.	8812280118	50-443
FRECRICKSON,P.	8812060271*	50-400 Q	GEORGIAN,E J.	9812200162	50-246 S	GREGER,L.R.	8811280083	60-165
FRECRICKSON,P.	8812200338*	60-261 Q	GEORGIEV,G.B.	8812220215*	50-259 Q	GREGER,L.R.	8811280094	50-295
FREEMAN,P.A.	8812200287	50-423 S	GEORGIEV G.B.	8812270245* 0812060298 8812060305 8612190018 8812190037	60-269 O	GREGER, L.R.	8811280102	50-305
FREEMAN,R.D.	8812020226	50-461 S	GERSHEY,E.L.		PRM	GREGER, L.R.	8811280105	50-305
FREEMAN,R.D.	8812220133	50-461 S	GERSHEY,E.L.		PRM	GREGER, L.R.	8811290006	60-409
FRESCO,A.	8811180327	50-266 Q	GERTMAN,D.I.		NUREG	GREGER, L.R.	8811300487	50-305
FRESCO,A.	8811180341	50-352 Q	GERTMAN,D.I.		NUREG	GREGER, L.R.	8811300526	50-346
FRESCO,A.	8811210080	50.322 Q	Gertman,d.i.	8812190068	NUREG	GREGER, L.A.	6811300536	50-373
FRICCI.M.	8812160029*	50.276 P	Gertz,c.	8812150274	WASTE MGT	GREGER, L.A.	8812020186	50-295
FRIEDMAN,L.F.	8812210384	40.8406	Gertz,c.	8812190239*	WASTE MGT	GREGER, L.R.	8812020188	50-254
FRISCH,R.R.	8811290467	50-265 P	Gertz,c.p.	8812050295	WASTE MGT	GREGER, L.R.	6812020201	50-254
FRISCH,R.R.	8812050317	50.265 S	Geyer,a.	8812060307*	50-219 Q	GREGER, L. R.	8812080129	50-255
FRISCH,R.R.	8812220188	50-255 P	GIBBS,R.	8612200167*	\$0.250 Q	GREGER, L.R.	8812060137	50-155
FRISCH,R.R.	8812220308	50-255 Q	GIBO,E.Y.	8812070146*	\$0.220 Q	GREGER, L.R.	8812060142	50-456
FRIZZLE,C.D.	8811290056	50-309 Q	GIBSON,A.F.	8812150198	\$0.269 Q	GREGER, L. R.	8812060144	50-409
FRYE,J.H.	8612020031	50-322 G	GIBSON,A.F.	6612220343	\$0.335 V	GREGER, L. R.	8812060149	50-282
FUIERER,A.A.	8812090058	PR	GIBSON,K.	6812220165	\$0.311 S	GREGER, L. R.	8812080108	50-440
FULLER,CH.	8811300083	50-267 F	GIBSON,K.H.	8811290412*	50-272 Q	GREGER, L.R.	8812090280	50-255
FULLER,CH.	8811300424	50-267 F	GIDLEY,W.C.	8812210348	40-8943	GREGER, L.R.	8812140237	50-282
FULLER,CH.	8812020109	60-267 F	GIITTER,J.G.	8812160001	50-305 Q	GREGER, L.R.	8812190265	50-456
FULLER,CH.	8812180354	50-267 S	GILBERT,B.G.	8812190018	NUREG	GREGER, L.R.	6812200052	50-483
FULLER,CH.	8812200019	60-267 R	GILBERT,B.G.	8812190037	NUREG	GREGER, L.R.	8812200055	50-483
FULLWOOD,A.	8811180348	50-245 Q	GILBERT,B.G.	8812190066	NUREG	GREGER, L.R.	8812200068	60-341
FUNK,O	8812060151*	50-282 Q	GILBERT,E.	8812200113	50-245 S	GREGER, L.R.	8812210369	50-315
FUNK DE.	8812210244*	50-282 Q	GILBERT,L.D.	8812050299*	50-285 Q	GREGER, L.R.	8812210371	50-155

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY
GREGER,L R GREGER,L R GREGER,L R GREGER,L R GREGER,L R	8812210387 5812210390 8812210393' 8812210396' 8812270123	50-331 F 50-454 Q 50-454 Q 50-454 Q 50-440 Q	GRIMSLEY,D H GRIMSLEY,D H GRIMSLEY,D H GRIMSLEY,D H	8812010005 8812050057* 8812050113 8812050123 8812050277	FOIA PR 50:322 P FOIA FOIA	HAIRSTON,W.G HAIRSTON,W.G HAIRSTON,W.G HAIRSTON,W.G HAIRSTON,W.G.	8812120011 8812120050 8812120059 8812120133 8812120180	50-321 4 50-348 4 50-321 4 50-424 5 50-321 5
GREGER, L. R.	8812270127*	50-440 Q	GRIMSLEY,D H	8812050306	50:390 O	HAIRSTON, W.G.	8812120183	50 321 C
GREGER, L. R.	8812270151	50-454 F	GRIMSLEY,D H	8812050327	FOIA	HAIRSTON, W.G.	8812120264	50 424 6
GREGG, B. R.	8811290557	50-219 S	GRIMSLEY,D,H	8812060020	FOIA	HAIRSTON, W.G.	8812130055	50 364 5
GREGG, B. R.	8812210109	50-219 S	GRIMSLEY,D,H	8812060051	FOIA	HAIRSTON, W.G.	8812130263	50 349 5
GREGG, R. E.	6811180299	50-213 Q	GRIMSLEY,D,H	8812060265	FOIA	HAIRSTON, W.G.	8812130268	50 424 6
GREGG,R.E	8811180299	50-213 Q	GRIMSLEY,D.H	8812070010	50-293 F	HAIRSTON,W.G	8812140062	50:424 50:424 50:424 650:321 50:424 6
GREGG,R.E.	8811180354	60-423 Q	GRIMSLEY,D.H	8812090279	FOIA	HAIRSTON,W.G	6612140120	
GREGG,R.E	8811180354	50-423 Q	GRIMSLEY,D.H	8812120044	FOIA	HAIRSTON,W.G	6612140269	
GREGG,R.E.	8811210082	50-280 Q	GRIMSLEY,D.H	8812120169	FOIA	HAIRSTON,W.G	6612150081	
GREGG,R.E.	8811210082	50-260 Q	GRIMSLEY,D.H	8812120189	50-293 P	HAIRSTON,W.G	6812160117	
GREGG,A.I	6811230226	70-371	GRIMSLEY,D,H	0812130135	FOIA	HAIRSTON,W.G.	8912160138	50:354 C
GREGG,A.J	6811230240	70-371	GRIMSLEY,D,H	0812130163	FOIA	HAIRSTON,W.G.	8812190116	50:424 I
GREGG,A.J	6812070221	70-371	GRIMSLEY,D,H	0812130210	FOIA	HAIRSTON,W.G.	8812190260	50:321 F
GRIDELY,A.	8812010324	50-259 P	GRIMSLEY,D,H	0812190289	FOIA	HAIRSTON,W.G.	8812190266	50:346 F
GRIDLEY,A	8812120271	50-327 O	GRIMSLEY,D,H	0812210110	50-275 T	HAIRSTON,W.G.	8812190275	50:354 F
GRIDLEY, R	8811290512	50-259 F	GRIMSLEY,D.H	8812210294	50-322 F	HAIRSTON,W G	0612190292	50:384
GRIDLEY, R	8811300140	50-259 Q	GRIMSLEY,D.H	8812230105	FOIA	HAIRSTON,W G	8612200001	50:424
GRIDLEY, R.	8811300243	60-327 P	GRIMSLEY,D.H	8812270221	FOIA	HAIRSTON,W G	8612200033	50:346
GRIDLEY, R.	8812010042	50-390 S	GRIMSLEY,D.H.	8812290266	50-440 P	HAIRSTON,W G	8612200112	50:321
GRIDLEY, R.	8812010310	50-260 P	GROBE,JA	8812130305	REVIEW GR P	HAIRSTON,W G	8612200119	50:424
GRIDLEY,R	8812010330	50-327 P	GROSS,K W.	0611280064	50-250 S	HAIRSTON,W.G	8912280160	50-321
GRIDLEY,R	8812010341	50-518 O	GROSS,K W	6812200203	50-250 S	HAIRSTON,W.G.	8812200213	50-424
GRIDLEY,R	8812060086	50-259 P	GRUMMER,R G	6812120145*	50-416 P	HAIRSTON,W.G.	8812200219	50-424
GRIDLEY,R	8812060112	50-259 P	GRUNSEICH,R.W.	6811300012	50-322 S	HAIRSTON,W.G.	8812200227	50-424
GRIDLEY,R	8812080133	50-260 P	GRUNSEICH,R W	6812060046	60-322 S	HAIRSTON,W.G	8812200236	50-424
GRIDLEY,R.	8812080145	50-327 P	GRUNSE:CH,R.W.	6812090054	50-322 S	HAIRSTON,W.G	8812200243	50-424
GRIDLEY,R.	8812080200	50-327 R	GUBERSKI,J.	6812210061	50-344 S	HAIRSTON,W.G.	6612200250	60-424
GRIDLEY,R.	8812120236	50-327 F	GUBERSKI,J D	6812210365	50-344 S	HAIRSTON,W.G.	6612210033	50-348
GRIDLEY,R.	8812130022	50-259 P	GUILLEN,J	6811290140	50-255 S	HAIRSTON,W.G.	8612210046	50-424
GRIDLEY,R	8812140165	50-259 P	GUNTHER,W.	8811160327	50-286 Q	HAIRSTON,W.G.	8612220078	60-424
GRIDLEY,R	8312140171	50-390 S	GUNTHER,W	8811210080	50:322 Q	HAIRSTON, W.G.	8812220081	59.424
GRIDLEY,R.	8812150103	50-327 Q	GUNTRUM,B.C.	8811300033	PT21	HAIRSTON, W.G.	8812220266	69.384
GRIDLEY,R	8312150164	REGGD	GUPTA,D	8812130311	CONTRACT	HAIRSTON, W.G.	8812220269	69.348
GRIDLEY,R.	8812160091	50-259 F	GUTHERIE,S	8811290314*	50:263 Q	HAIRSTON, W.G.	8812270071	59.321
GRIDLEY,R	8812200079	50-259 F	GUTHAIE,S	8812010252*	50:218 Q	HAIRSTON, W.G.	8812270217	60.424
GRIDLEY,R.	8812200177	50-259 P	GUTIERREZ,J.	8612220026°	40-2259	HAISFIELD,M.	8811100222	PR
GRIDLEY,R.	8812200323	70-2917	GWYNN,P.	8812070016°	50-293 F	HALE,M.W.	8812200117	50-400 (
GRIDLEY,R.	8812210199	50-260 P	HAAG,F.G	8812060134	PR	HALL,D.P.	8812210009	50-461 (
GRIDLEY,R.	8812210206	60-259 F	HAAG,R.C.	8811290278°	50-313 Q	HALL,J.M.	8812160029*	50-275 (
GRIDLEY,R.	8812230017	50-259 P	HADFIELD,J.D.	8811230086°	50-293 F	HALL,J.R.	8812010123	50-301
GRIDLEY,R.	8912230198	50-390 A	HAFFER,E A.	8812190206	50-443 G	HALL,J.R.	8812010211	50-331
GRIOLEY,R.L.	8812270104	50-259 P	HAGAN,J.	8812130178	50-354 S	HALL,J.R.	8812090164	50-331
GRIDLEY,R.L.	8809290002	50-259 O	HAGAN,J.	6812130239	50-354 S	HALL,J.R.	0812130046*	50-331
GRIDLEY,R.L.	8811300164	50-259 P	HAGAN,J.	6812190398	50-354 R	HALL,J.R.	8812200215	50-331
GRIDLEY,R.L.	8812010303	PHM	HAGAN,J.	6811290237	50-354 S	HALL,J.P.	8812070681	50-461
GAIDLEY, A.L. GAIDLEY, R.L. GAIDLEY, A.L. GAIDLEY, A.L. GAIFFIN, J.L.	8812020022 8812070258 8812070258 8812060187 8812210195 8812220214*	50-327 F 70-2917 PR 50-259 F 50-205 P	HAGAN,JJ HAGAN,JJ HAGAN,TF HAGAN,TF HAGAN,TF	8812080047 6812090364 6812010221* 6812010237* 6812010278*	50-354 S 50-354 S CONTRACT CONTRACT CONTRACT	HALPAUS,P. HALTIWANGER,J. HAMADEH,A.C HAMILTON,P. HAMLETT,M.A.	8812130070 8812140076 8812070245* 8812190224 8812200240	70-3041 50-335 50-233 50-233 50-263
GRIFFIN,R.L.	8812270149	50-445 G	HAGAN,T.F.	6812010266*	CONTRACT	HAMLETT,M A	8812200246	50-260
GRIFFIN,R.L	8812270149	50-445 G	HAGAN,T.F.	6812010294*	CONTRACT	HAMLETT,M.A	8812200253	50-263
GRIME.B.K.	8812010050	PA	HAGAN,T.F.	6812140112*	CONTRACT	HAMMELMAN,J.E	8812120055	50-604
GRIMES,B.K	8811290016	50-361 H	HAGAN,T.F.	6812150066*	CONTRACT	HAMRICK,J.S.	8812210250	40-5561
GRIMES,B.K	8811300511	PA	HAGAN,T.F.	6812190282*	CONTRACT	HAMRICK,J.S.	8812210287	40-8581
GRIMES, B.K.	8811300529	PR	HAGAN,TF.	6812190300*	CONTRACT	HAMRICK,N.P.	8812130171*	CONTRACT
GRIMES, B.K.	8811300539	50-208 H	HAGAN,T.F.	6812210140*	CONTRACT	HANNEN,J.N.	8812210283	50-493
GRIMES, B.K.	8811300556	50-361 H	HAGERNAN,J.P.	6812090326	WASTE MGT	HANNEN,R.L.	8811280564	50-531
GRIMES, B.K.	8811300570	ORG	HAGEY,H.	6812050006	CONTRACT	HANNEN,R.L.	8812020210	50-531
GRIMES, B.K.	8811300579	PR	HAGEY,H.	6812270269	CONTRACT	HANNEN,R.L.	8812070250	50-531
GRIMES, B.K. GRIMES, B.K. GRIMES, B.K. GRIMES, B.K. GRIMES, B.K.	8811300583 8812010041 8812010045 8812010057 8812010101	50-362 H PR PR PR PR	HAGINS, E.E. HAIRSTON, W.G. HAIRSTON, W.G. HAIRSTON, W.G. HAIRSTON, W.G.	8812020050 8811230241 8811280028 8811280055 8811280144	50-322 G 50-424 F 50-424 F 50-424 F 50-424 O	HANNEN,R.L. HANNEN,R.L. HANNEN,R.L. HANNIBAL,L. HANNON,J.N.	8812140232 8812140254 8812230153 8812200325 8812010124*	50-331 50-331 FEVIEW GR 50-331
GRIMES, B.K.	8812010104	PR	HAIRSTON,W.G.	8811290072	50-424 S	. M. L, NONNAH	8812010213*	50-331
GRIMES, B.K.	8812010107	PR	HAIRSTON,W.G.	8811290103	50-348 P	. M. L, NONNAH	8812060337*	50-483
GRIMES, B.K.	8812050025	ORG	HAIRSTON,W.G.	8811290292	50-424 S	. M. L, NONNAH	8812090167*	60-331
GRIMES, B.K.	8812050185	REVIEW GR P	HAIRSTON,W.G	6811290309	50-321 P	. M. L, NONNAH	8812090271*	60-440
GRIMES, B.K.	8812160147	PR	HAIRSTON,W.G	6811290572	50-424 S	. M. L, NONNAH	8812130165*	50-346
GRIMES.B.K.	8812160151	PR	HAIRSTON,W.G.	6911290575	50-424 S	HANNON,J.N.	8812140189	50-440
GRIMES.C.I.	8811300023	50-445 A	HAIRSTON,W.G.	8812010342	50-321 S	HANNON,J.N.	8812210032	60-331
GRIMES.C.I.	8812070117	50-445 A	HAIRSTON,W.G.	8812010344	50-424 S	HANNON,J.N.	8812220330°	60-346
GRIMES.C.I.	8812120017	50-445 E	HAIRSTON,W.G.	8812010350	50-424 P	HANBISON,R.H.	8812010098	FA
GRIMES.C.I.	8812120096	50-445 Q	HAIRSTON,W.G.	8812020115	50-424 S	HANBOUR,J.	8812190048	60-443
GRIMES,C.I. GRIMES,C.I. GRIMES,C.I. GRIMES,C.I. GRIMES,C.I.	8812120099° 8812120287 8812130008 8812150232 8812150234°	50-445 A 50-445 E 50-445 A 50-445 A	HAIRSTON,W.G. HAIRSTON,W.G. HAIRSTON,W.G. HAIRSTON,W.G. HAIRSTON,W.G.	8812020218 8812020241 8812020265 9812060181 8812060273	60-424 P 50-348 Q 50-424 P 50-424 P 50-424 S	HARBOUR, J. HARBUCK, C.C. HARBUCK, C.C. HARBUCK, C.C. HARBUCK, C.C.	8812270053 8812020173 8812020239 8812160153 8812210005	50-443 50-313 50-313 50-313 50-313
GR:MES,C.I.	8812150238	* 50-445 A	HAIRSTON,W.G.	8812090254	50-424 Q	HARBUCK,C.C.	8812230104	50 313
GR:MES,C.I.	8812190181	50-445 E	HAIRSTON,W.G.	8812090261	50-424 Q	HARLOW,D.S.	8812280008*	50 322
GRIMES,C.I.	8812200251	50-445 A	HAIRSTON,W.G	8812120004	50-366 S	HARLOW,D.S.	8812280008*	50 322

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	·	AUTHOR	ACCESSION NUMBER	SUBJEC
MARLOW,DS MARLOW,DS MARNESS,II MARNESS,II MARNESS,II	0812200070 0812280078 8811230294 8911290031 8012050210	50:322 G 50:322 G 50:324 O 50:325 S 50:325 S	HAWKINS, E.F. HAWKINS E.F. HAYES, J.J. HAYES, J.J. HAYES, J.J.	6812220298 8812219109* 881220316 6812080092 8812219044	40-6920 40-8857 50-395 50-395 50-395	P P	MIGHFILL K.L. HILDENBRAND,P. HILL K.J. HILL WHILTON,R. HILL-WHILTON,R.	8912190224 9812210052 0812190375 8912270031 8812270101	50-283 40-8857 50-285 50-443 50-443
HARMESS JL HARMESS JL HARMESS JL HARMESS JL HARMESS JL	8812050225 8612060157 9812060242 881209D112 8812130017	50 324 Q 50 324 Q 50 325 S 50 324 F 50 326 S	HAYNES, J G HAYNES, J G HAYNES, J G HAYNES, J G HAYNES, J G	8011290358 6811300281 8611300284 8012130041 6812130306	50-528 50-528 50-629 50-528 50-529	\$ \$ \$ \$	HILL WHILTON, A. HINDS, J.M. HINDS, J.M. HINDS, J.M. HINDS, J.M.	8812280148 8811280078* 8811300442 8811300449* 8811300551*	50-443 50-454 50-295 50-295 60-458
HARNESSUL MARNESSUL	8912130137 8812130161 8812140247 8812210090 8812210097	50 324 S 50 324 S 50 324 H 50 325 S 50 325 S	HAYNES,J.G. HAYNES,J.G. HAYNESWORTH,V. HEFFNER,G HEHL,C.W.	88122100278 8812210144 6812140262 6812050292 8812120171	50-528 50-528 50-261 50-440 50-261	ค ร ก ค ค	HINDS, J.M. HINTON,M.F. HINTON,M.F. HINTZ,D.C. HINTZ,D.C.	6812140257* 6811180312 8811180312 8812060030 6812090107	50-456 50-247 50-247 50-305 50-305
HARNESSJI HARNESSJI HARNESSJI	0012210103 0012210111 0012210131 0012210305 0012210409	50-325 S 50-324 S 50-324 S 50-325 S 50-324 S	HEITNER,KI, HEITNER,KI, HEITNER,KI, HEITNER,KI, HELWIG,D:R	6811290391 6811290400 9611300069 88113C0074 8812026217	60-267 50-267 50-267 50-267 50-277	Р Р О Р	HIRT,J.A. HIRT,J.A. HOBE,M.A. HOCHBRUECKNER	8611230306 8612080205 6812200299 6812200315 8812080005*	50-387 50-387 50-155 50-155 50-322
HARRIGAÑ D.J. HARRIS, J.Ř. HARR S.W.S	0812270199 0812100282* 0812200341* 8811100208 8812060115	50-324 O CONTRACT 50-338 Q 50-317 Q 50-340 F	HELWIG, D.R. HENDRICKSON, R HENNANT, C.S. HENNICK, A HENSLEY, K.D.	8812030143 8012010319 8011300521° 8012010349 8812140013	50-353 50-116 50-400 NUREG 70-143	A P F	HOCHREITER, L.E. HODGDON, A.P. HODGDON, A.P. HODGDON, K. HODGDON, K.	8812090285* 8812190059 8812190127 8812090008* 8812090009*	50-266 50-224 50-271 50-170 50-170
HARRIS,R J. HARRIS,T HARRIS,T.	8812200346* 8811300554* 8812139137 8812210090 8812080242*	50-205 Q 50-207 B 50-324 S 50-325 S PB	HENSLEY,K.D. HENSLEY,K.D. HENSLEY,K.D. HENSLEY,K.D. HENSLEY,K.D.	8812200191 9812200228 8812200319 8812200377 8812220050	70-143 70-143 70-143 70-143 70-143		HODGDON,K, HOEFLING,R.K. HOFFMAN,D.P. HOFFMAN,B.L HOGAN,R	8812080011* 6812300022* 8812050278 8812020194 8811210031*	50-170 50-440 59-155 40-299 60-293
HARRISONJ. HARRISONJ.J HARRISONJ.J	8812140247 8812140044 8812020204 8812050140 8812050213	50-324 R 50-331 S 50-360 O 50-346 Q 50-260 O	HENSLEY,K D. HENSLEY,K D. HERDT,A.D. HERDT,A.R. HERDT,A.R.	0812220069 0812220109 0812090253 0811230016 0612050241	70·143 70·143 50·425 50·400 50·425	000	HOGAN,R. HOGAN,R. HOGAN,R. HOGAN,R. HOGAN,R.	8811210036* 0811210039* 0811210041* 8811210042* 8811210046*	50-293 50-293 50-293 50-293 50-293
HARRISON,JU. HARRISON,JU. HART,H.C.	0812090262* 0812120065 6812200108 0812220100* 0812190106	50-341 O 50-341 O 50-316 O 70-687 WASTE RES	HERDT A.R. HERDT A.R. HERDT A.R. HERDT A.R. HERDT A.R.	8812050260 8812050265 8812060001 8812060043 8812070247	50-424 50-280 50-335 50-324 50-280	00000	HOGAN,R. HOLAHAN,G. HOLAHAN,G.M. HOLAHAN,G.M. HOLAHAN,G.M.	8811210081° 8812130044 8611290310 8811290433° 8811290449°	50-293 50-331 50-263 50-409 50-16
HARTIR D HARTMANN,P.L. HARVEY,S	8812190192 8812190201* 8811290314* 8812060033 8812210372	WASTE RES WASTE RES 50-263 Q 50-403 F 50-483 F	HERDT,A R HERDT,A R HERDT,A R HERDT,A R HERDT,A R.	8612080010 8012080017 8012080050 8612080051 8012080163	50-424 50-395 60-260 50-250 50-260	00000	HOLAHAN,G.M. HOLAHAN,G.M. HOLAHAN,G.M. HOLAHAN,G.M. HOLAHAN,G.M	6811290464* 8811300114* 8812010080 6812120281* 8812130036*	50-133 50-171 50-409 50-298 50-285
HASSLER,D.V. HAUBER,D.D. HAUGHEY,M.F.	8811290991 8812929136 8812910234 8811290448 9812910256	50-304 S 50-269 S REVIEW GR P 50-220 Q 50-220 P	HERDT A.R HERDT A.R. HERDT A.R. HERDT A.R HERDT A.R	8612080192 8812090323 8812090341 6612090342* 8812160108	60-250 60-425 60-305 50-395 60-424	00000	HOLAHAN, G.M. HOLAHAN, G.M. HOLDER, A.L. HOLLAND, W.E. HOLLER, G.	8812130050 8812220384 8812150039 6812080162* 8812020302	50-254 50-499 50-382 60-280 50-498
PAUGHNEY,C.J. RAUGHNEY,C.J. HAUGHNEY,C.J	8812130219 8812010252* 8812020153* 8812020196*	50-220 P 50-219 O 50-277 Q 50-353 Q 50-331 O	HERDT,A.R. HERDT,A.R HERDT,A.R. HERDT,A.R. HERDT,A.R.	0612160140 8812160162 6812160166* 6812100249 8812190411	50-250 50-369 50-369 50-424 60-302	9999	HOLLINGSED,M.W. HOLLINGSED,M.W. HOLLOWAY,C.J. HOLLOWAY,C.J. HOLMES-RAY,P.	6812070238 0812130016 8812200290 6812230054 6812090120*	50-285 60-285 60-322 Pf1 50-83
HAVENKAMP.D.R. HAVENKAMP.D.N.	8812130051* 8811300052 8012140104* 8812220338* 8812270230*	50-254 Q 50-29 V 50-443 Q 50-271 Q 50-28 Q	HERDT, A.A. HERDT, A.A. HERDT, A.A. HERNAN, R.W. HERNAN, R.W.	8612200284 8812200339 8812210229 9811290443 8812010178	60-425 50-338 60-280 60-289 50-219	GGGGC	HOLMES RAY,P. HOLMES RAY,P. HOLONICH,J.J. HOLONICH,J.J. HOLONICH,J.J.	8812090296* 8812200176* 8811300182 8811290218* 8811290252	50-302 50-302 WASTE M WASTE M WASTE M
HAWKINS,E.F. HAWKINS,E.F. HAWKINS,E.F.	8810100204 8812010360 9812010371* 9812010385 6812010412	40-8502 40-8943 40-8943 40-8904 WASTE MGT	HERNAN,R.W. HERNAN,R.W. HERNAN,R.W. HEYER,R.S. HEYER,R.S.	8812020142 8812100062 8812220239 8811300516* 6612020050*	50-289 50-289 60-289 40-4492 40-288	P P	HOLONICH, J.J. HOLTZMAN, R.B. HOLTZMAN, R.B. HOLTZSCHER, D.L. HOLTZSCHER, D.L.	88112800542 8811280097* 8812210376* 8812020226 8812050049	WASTE M 50-295 60-155 60-461 60-481
FAWKINSE.F. HAWKINSE.F. HAWKINSE.F.	8812010418 8812020045* 8812020096 8812020106 8812020114	40-3453 40-8102 40-8452 40-8905 40-1162	HEYER,R S HIATT,S L. HICKEY,K.J. HICKEY,K.J. HICKEY,K J.	6812020128 6812290261 6812060155* 6812060225*	40-1162 FOIA FOIA FOIA FOIA		HOLTZSCHER,D.L. HOLTZSCHER,D.L. HOLTZSCHER,D.L. HOLTZSCHER,D.L. HOLTZSCHER,D.L.	8812060279 8812140178 8812140231 8812150128 8812180228	60-461 60-461 50-481 60-461 50-461
HAWKINS,E.F. HAWKINS,E.F. HAWKINS,E.F.	8812020131* 8812020162* 8812020235 8812210037 8812210042	40-8857 40-4402 40-8907 40-8904 WASTE MGT	HICKEY,K.J. HICKMAN,D.E. HICKMAN,D.E. HICKMAN,D.E. HICKMAN,D.E.	6812060245* 8811230221 6811300270 6812050111 8812070001	FOIA 60-206 60-361 50-361 60-361	Q P P	HOLTZSCHER,D.L. HOLTZSCHER,D.L. HOLTZSCHER,D.L. HOLTZSCHER,D.L. HOCKER,C.	8812190274 8812200101 8812200268 8812220133 8812200098*	50-461 50-461 60-461 50-461 50-344
HAWKINS,E.F. HAWKINS,E.F. HAWKINS,E.F.	8812210105 0812210150 8812210182 8812210189 8812210228	40-8943 40-8452 40-8973 40-8911 40-8857	HICKMAN, D.E. HICKMAN, D.E. HICKMAN, D.E. HICKMAN, D.E. HICKS, M.M.	8812070007 8812070021 8812070071 8812160095 8812010233	50-361 50-361 50-361 50-361 PR	P Q Q P	HOPKINS,D.R. HOPKINS,J.B. HOPKINS,J.B. HOPKINS,J.B. HOPKINS,J.B.	0812060056* 8812190340* 8811280106 8811290302 8811300126	FOIA 60-316 60-424 60-424 60-424
HAWKINS,E.F. HAWKINS,E.F.	8812210288 8812210359 8812210367 8812210377 8812220102	40-8084 40-8684 40-4492 40-8904 40-3453	HIGGINS,J. HIGGINS,J. HIGGINS,P. B. HIGGINS,P.B.	8811180341 8811180340 8811210080 8812060140* 0812060153*	50-362 50-245 50-322 FOIA FOIA	000	HOPKINS, J.B. HOPKINS, J.B. HOPKINS, J.B. HOPKINS, J.B.	8812020207 8812090163 8812130296 8812130296 8812130296	50-425 50-424 50-424 50-424 60-424
HAWKINS.E.F. HAWKINS.E.F. HAWKINS.E.F.	8812220106 8812220142 8812220290	40-8943 40-8681 40-8904	HIGGINS,R.B. HIGGINS,W.B. HIGHFILL,K.L.	8812060220° 8812010002 8811300518	FOIA 50-305 50-203	S P	HOPKINS, J.B. HOPKINS, P.C. HOPKINS, P.C.	8812220127* 6812050262* 8812200296*	50-424 50-395 50-395

ROHTUA	ACCESSION NUMBER	CATEGORY	AUTHUR	ACCESSION RUMBER	CATEGORY	AUTHOR	ACCESS!(NUMBER
HOPKINS,A J.	6611230243	40-6622	IRWIN,DP.	8812020032	50-322 G	M.I,NOZNHOL	881123002
HORN,G R.	6612130014	50-239 S	IRWIN,DP.	8812020038*	50-322 G	M.I,NOZNHOL	881128015
HORN,M.	6612140036	50-209 R	IRWIN,DP.	8812020038*	50-322 G	M.I,NOZNHOL	881129015
HORN,M.	6612140018*	70-3054	IRWIN,DP.	6812020061	50-322 G	M.I,NOZNHOL	881207003
HORN,M.L.	6612020016	70-820	IRWIN,DP.	8812020061	50-322 G	M.I,NOZNHOL	881212602
HORN,M.L.	8612270274	70-371	IRWIN,DP.	8812020083	50-322 G	M.I.NORNHOL	881227015;
HORNE B.E.	6611230065*	MISC	IRWIN,DP.	8812020083	50-322 G	L.NORNHOL	861208005;
HOSEY,C.M.	8812080184*	60-280 O	IRWIN,DP.	8812140115	50-322 G	I.NORNHOL	861227025
HOSEY,C.M.	8812090315*	60-302 O	IRWIN,DP.	8812140115	50-322 G	I.L.NORNHOL	861205021;
HOSEY,C.M.	8812160144*	50-424 Q	IRWIN,DP.	8812140121	50-322 G	R.L.NORNHOL	881209025;
HOSEY,C M, HOSE J.E. HOUSE,W.B HOUSH,W.B	8812190053* 8812190163 8812270131* 8812080058 8812070249	50-424 O WASTE RES 50-440 O TOPREP 71-4909	IAWIN, D.P. IAWIN, D.P. IAWIN, D.P. IAWIN, D.P. IAWIN, D.P.	8812140121 8812180103 8812180103 8812270069 8812270069	50-322 G 50-322 G 50-322 G 50-322 G 50-322 G	H. MOSNIIOL P. MOSNHOL P. MOSNHOL P. MOSNIIOL	881227016; 68122702? 681130017; 681130018 681215015;
HOWARD,D.R.	6811290182	50-313 P	IRWIN, D.P.,	8812280002	50-322 G	H.9, MORNHOL	#81220009
HOWARD,D.R.	6812190240	50-358 R	IRWIN, D.P.,	8812280002	50-322 G	H.9, MORNHOL	#81206003
HOWARD,D.R.	6812190247	50-313 R	IRWIN, D.P.,	8812280005*	50-322 G	H.9, MORNHOL	#81221028
HOWARD,D.R.	8812200252	50-313 P	IRWIN, D.P.,	8812280005*	50-322 G	G.W, MORNHOL	#81129027
HOWARD,J.E.	6812020233	60-392 S	IRWIN, D.P.,	8812280070	50-322 G	L.W, MORNHOL	#81220027
HOWARDS,D.A.	6812210167	50-313 Q	IRWIN,D.P.	0812280070	50-322 G	L W,NORNHOL	U81221014
HOWEP.W.	6812190207	50-324 V	ISHII,M.	8812190120	NUREG	L.W,NORNHOL	881222016
HOWELL,A.T.	6811300219	50-462 S	ISRAEL,S.	8812050054	ORG	B,NOTRNHOL	881220033
HOYLE,J.C.	6812080014	50-320 P	IVORY,B.J.	8811290205*	CONTRACT	R L,NOTRNHOL	881213033
HOYLE,J.C.	6812080016*	50-320 P	IZENSON,M.G.	8812020160	NUREG	N,NOTRNHOL	881220009
HOYLE,J.C.	0812080022*	50-320 P	IZENSON,M.G.	8812020164	NUREG	JOHNSTON,K.E.	881213024
HOYLE,J.C.	0812280164	50-445 G	JABBOUR,K.N	8812010223	50-413 P	JOLLES,M.R.	881218012
HOYLE,J.C.	0812280190	50-322 G	JABBOUR,K.N.	8812050066	50-413 P	JONAS,S.A.	881202002
HOYLE,J.C.	0812280217	50-443 G	JABBOUR,K.N.	8812160069	50-413 P	JONAS,S.A.	881202004
HS:UNG,S.	0812130095	WASTE MGT	JABLONSKI,F.J	8812270048*	50-346 O	JONAS,S.A	881219020
HUBBARD,G HUBBARD,G.T. HUCK,P.J. HUCK,P.J. HUCK,P.J.	8812160181 8812220105* 8812140119 8812140123* 8812140125*	50-445 E 60-259 Q WASTE RES WASTE RES WASTE RES	JACKIW,I N. JACKIW,I.N. JACKS,J D. JACKS,J.D.	8812020148* 8812020163* 8812210405* 8812210043 8812210068*	60-331 Q 50-331 Q 50-155 Q 50-313 S 50-313 S	JONAS,S A. JONAS,S A. JONAS,S A. JONAS,S A. JONAS,S A.	881219026 881219026 881219020 881219021 881216021
HUDSPETH,J.B. HUEY,F.R. HUEY,R. HUGHEY,C.A. HUKILL,H.D.	8812120227 8812150159* 8811300178 8811300268* 8811300430	50-346 F 50-206 Q 50-208 S 50-424 Q 60-289 P	Jacks.jd. Jacks.jd. Jackson.g Jackson.g.	8812210193* 8812220243 8011280220* 8812050106* 8812140220*	50-313 S 50-313 S 71-24 71-665 40-8027	JONAS,S A JONAS,S A JONAS,S A. JONES,H.F. JONES,P.E.	881218021 881218021 981228096 881215011 881129020
HUKILL,H.D. HUKILL,H.D. HUKILL,H.D. HUKILL,H.D. HUKILL,H.D.	8812020136 6812080143 8812120107 8812130177 8812130180	50-289 S 50-289 Q 50-289 P 60-289 P 50-289 P	JACKSON,G. JACKSON,R. JACOBSON,J.M. JACOBY,D.L. JACOBY,D.L.	8012220104 *8812120035* 8812200109* 8812020045* 6812020114	70-687 70-607 60-316 Q 40-8102 40-1162	JONES, S. B. JONES, S. B. JONES, S. B. JONES, T.	881130007 681212001 681220014 681220022 881213001
HUKILL, K.D. HUKILL, H.D. HUMPHREY, G.J. HUMPHREY, G.J. HUMPHREY, P.	0812140176 8812200174 8812080175 0812210311* 0812060190*	60-289 Q 50-289 R 60-443 H 50-443 H 60-327 Q	JACOBY,D.L. JAFFE,D.H. JAFFE,D.H. JAMES,W.R. JANG,J.	6812210150 8812090163 8812190394* 8812210029	40.8452 50.336 P 50.336 P 70.143 50.317 Q	JONES,T.M. JONES,T.M. JONES,W.B. JONES,W.C. JORDAN,E.L.	881221011 881221013 881214008 881219029 881014004
HUNGER G.A.	8812060052	50-277 P	JANUSKA,A.	8812060151*	50-282 Q	JORDAN,E.L	881014066
HUNNICUTT D.	8812130243	50-499 S	JANUSKA,A.G.	8811300494*	50-305 Q	JORDAN,E.L	881128016
HUNSADER, S.C.	8811290081	50-456 P	JAPE,F.	8811230019*	50-400 Q	JORDAN,E.L	881129026
HUNSADER, S.C.	8812020197	50-456 R	JAPE,F.	8812080020*	50-395 Q	JORDAN,E.L	881129021
HUNSADER, S.C.	8812070057	50-456 P	JAPE,F.	8812080165*	50-280 Q	JORDAN,E.L	88129908
HUNSADER,S.C. HUNSADER,S.C. HUNSADER,S.C. HUNSADER,S.C. HUNSADER,S.C.	8812090297 8812140141 8812190196 8812200091 8812220382	50-456 S 50-456 P 60-454 K 50-454 F 50-456 Q	JAPE F. JAPE F. JAPE F. JAPE F. JAPE F.	8812180185* 8812080258* 8812160115* 8812160156* 8812180251*	50-327 Q 50-425 Q 50-424 Q 50-250 Q 50-424 Q	JORDAN,E.L. JORDAN,P. JORDAN,P. JOSIGER,W.A. JOSIGER,W.A	881222018 881221030 8811230022 881130022
HUNSTAD,A A,	6611300044	50-282 S	JAPE, J.	8812090327* 8812010343 8812270080 8812270086 8812280128	60-425 O	JOSIGER,W.A.	881206010
HUNSTAD,A A,	6812020094	50-282 S	JARRELL, D.B.		NUREG	JOSIGER,W.A.	881212023
HUNSTAD,A A,	6812070209	50-282 S	JEHLE, P.A.		60-335 G	JULIAN,C.A.	881201001
HUNSTAD,A.A,	6812200056	50-282 S	JEHLE, P.A.		50-250 G	JULIAN,C.A.	881208011
HUNT,M.D.	6812050245*	50-425 Q	JEHLE, P.A.		50-335 G	JULIAN,C.A.	861209011
HUNTER,D.R.	6812210313*	50-285 Q	JEHLE P.A.	8812280257	50-335 G	JULIAN,C.A.	881209013
HUNTER,J.R.	6811300132*	XPORTLIC	JENISON,K.	8812080170*	50-327 Q	JULIAN,C.A.	881216004
HUNTER,J.R.	6811300136*	XPORTLIC	JENISON,K.	8812080190*	50-327 Q	JULIAN,C.A.	881216014
HUNTER,J.R.	6812270285*	XPORTLIC	JENISON,K.	8812210102*	50-327 Q	JULIAN,C.A.	881216013
HURLEY,J.	6812090168	50-418 F	JENSEN,H.	8812190398	50-354 R	JULIAN,C.A.	881219023
HUTCHINSON,W.B.	8612080064°	50-341 U	JOHANSEN, J.	8812140118	1&E	JULIAN,C.A.	881219030
HUTCHISON,L.B.	8612200086	50-397 R	JOHNSON, A.D.	8812150002°	50-397 O	JULIAN,C.A.	881220010
IBRAHIM,A.K.	6811300230	WASTE RES	JOHNSON, A.G.	8811290448	50-243 F	JULIAN,C.A.	881220010
IBRAHIM,D.W.	8612060034	50-457 S	JOHNSON, A.R.	8811290477°	50-382 O	JULIAN,C.A.	881222003
IBRAHIM,D.W.	6612210001	50-457 S	JOHNSON, A.R.	8812020309°	50-313 O	JULIAN,E.L.	881214000
IDDINGS,F.A. IDDINGS,F.A. IKEDA,M. IKEDA,M. IKEDA,M.	8812090013* 8812090060* 8812080148* 8812080173* 8812080188*	50-315 P XPORTLIC XPORTLIC	JOHNSON, A.R. JOHNSON, B.D. JOHNSON, B.D. JOHNSON, B.D. JOHNSON, B.D. JOHNSON, B.D.	8812160073* 8810070105* 8811280019 8812020187 8812020220	60-482 Q 50-255 P 60-265 S 60-265 S 60-266 S	JURY,K. KADAK,A.C. KAHLE,J.B. KAHLE,J.B. KAHLE,J.B.	86122001 86120900 8613005 86120600 86120902
IKEDA,M.	8812080228	XPORTLIC	JOHNSON, B.O. JOHNSON, B.D. JOHNSON, B.D. JOHNSON, B.D. JOHNSON, C.E.	8812060105	60-255 8	KAHLE,J.B.	88121601
IKEDA,M.	8812150036	XPORTLIC		8812130126	50-255 8	KAHLE,J.B.	88121902
IKEDA,M.	8812150100	XPORTLIC		8812140047	50-255 S	KALMAN,G.	88121501
IMBRO,E.V.	8812020196*	50:353 Q		8812220029	60-255 R	KAMMERER,C.	88120103
INGLE,S.	6811230021	40:8857		8812140077*	50-285 Q	KAMMERER,C.	88121903
INGLE,S.	8612050095	40-8964	JOHNSON,D.	8811290026°	50-320 O	KANE.G.E.	88120101
IRELAND,A.E.	8611300329*	50-267 Q	JOHNSON,D.	8812270288	50-289 S	KANE.G.E.	88120600
IRWIN,D.P.	8612020032	50-322 G	JOHNSON,D.B.	7905030213°	FOIA	KANE.G.E.	88121903

KAPLAN,A. 8812060240 50-440 F KIRSCH,D.F. 8812120185 60-206 Q KUBICKID. 8612190323* 50-361 KAPLAN,A 8812060280 50-440 Q KIRSCH,D.F. 8812120180 50-206 Q KUMAGAI,T. 8612190361 FOIA KAPLAN,A 8812200082 50-440 Q KIRSCH,D.F. 8812130182 50-312 Q KUNCL,L.G. 8812140213* 50-298 KAPLAN,A 8812200187 60-440 R KIRSCH,D.F. 8812130244 50-275 Q KUNCL,L.G. 8812200128 60-208 KAPLAN,A 8812270067 50-440 S KIRSCH,D.F. 8812150001 50-397 Q KUNCL,L.G. 8812220208 50-208 KAPLAN,A 8811300067 60-160 Q KIRSCH,D.F. 8812150001 50-391 Q KUNCL,L.G. 8812220208 60-208 KAPLAN,R.A. 8811300067 60-160 P KIZER,K.W. 8812130255* STATE PROG KUNKEL,J.R. 8812010060 NUREG KARAN,R.A. 8812070015 50-528 J KLAPPROTH,J.F. 8812070146* 50-220 Q KUNOWSKI,M.A 8812200955* 50-483	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC
MARCATON 081720175 05.77 0	KANE,WF. KANE,WF. KANE,WF.	8812060015 8812210373 8812230134	50-170 Q 50-247 Q	KINTNER,L L. KINTNER,L.L. KINTNER,L L.	8611300240 8811300416 8812010215	60-416 P 50-416 P 50-416 P	KOZUP,C.S. KOZUP,C.S. KOZUP,C.S.	8812120243 8812120254 8812130128	50-255 50-255 50-255
MATERIAL 881 12000 50 40 0 MINTERIAL 891 2007 94 6 MINTERIAL 891 2007 94 94 94 MINTERIAL 891 2007 94 94 94 MINTERIAL 891 2007 94 94 94 94 94 94 94 9	KANE,W.F. KANSLER,M.R. KANSLER,M.R.	8812290126 8812060281 8812070206		KINTNER,L.L. KINTNER,L.L. KINTNER,L.L	8812020008 8812060313 8912070157	50-416 P 50-416 P 50-416 P	KRASOPOULOS,A KRASOPOULOS,A KRAUSE,C.W.	8811300348* 8812080154* 8812180218	50-277 50-247 50-266
MAPLANA	KANTOR,É. KAPLAN,A. KAPLAN,A	88112090284* 8811230277 8811290060	50-280 S 50-324 Q 50-440 Q 50-440 Q 50-440 S	KINTNER,L.L. KINTNER,L.L. KINTNER,L.L	6912130237 6812160157 8812200198	50-416 P 50-416 P 50-416 P	KAEH,J L KRICH,R M. KRICH,R M	6812150233° 6812050046 6812120080	70-143 60-352 50-352
MAPLAIN	KAPLANIA KAPLANIA KARLANIA	8812010288 8812050013 8812050060	50-440 H 50-440 P 50-440 S	KIRBY,E.P. KIRSCH,D.F. KIRSCH,D.F.	8812020014* 8811290352 8811300233	50-293 F 50-397 S 50-206 P	KRIMM,R,W. KRIMM,R,W. KRIMM,R,W.	6811280044 6611260051* 8611290163	50-344 50-344 50-440
MAPLINA	KAPLAN,A. KAPLAN,A. KAPLAN,A	8812060049 8812060240 8812060280	50-440 F 50-440 P 50-440 Q	KIRSCH D.F. KIRSCH D.F. KIRSCH D.F.	8812070089 8812120185 8812120188	50-312 O 60-206 O 50-206 O	KRUPKA,K M. KUBICKI,D. KUMAGAI,T.	8812220048 8812190323* 6812190361	WASTE R 50-361 FOIA
MAYOE 812000316* MASTE MOT MEEN ACT WASTE MASTE MA	KAPLAN,A. KARAM,FI A. KARAN,FI A.	8812270057 8811300067 8812140008	50-440 S 60-160 Q 50-160 F	KIRSCH D.F. KIRSCH D.F. KIZER K.W.	8812150001 8812190321 8812130255*	50-397 O 60-381 Q STATE PRO G	KUNCL, L.G. KUNISH,B. KUNKEL,J.R	8812220208 8812090198* 8812010069	50-298 COMMISS NUREG
KEMAG FR	KAY.CE KAY.M. KEATING.L.	8812090316* 8812050008 8812050333*	WASTE MGT 40-8820 FOIA	KLEIN,D, KLEINSORGE,W.D. KLEINSORGE,W.P.	8812080065 8812080054' 8812160169'	50-602 A 50-250 Q 50-369 Q	KUPERMAN,A.J. KUPERMAN,A.J. LA CHANCE,J.L.	8812120167 8812120167 8812020178	FOIA FOIA NUREG
P. MIGGER M.	KEINIG,F.R. KEIM 3,R.A. KEIM.G,R R	8811290398* 8811290510* 8811300298*	50-333 Q	KNAPP,M.R. KNAPP,M.R. KNAPP,M.R.	8812090264 8812120053* 8312130303	PROJ FOIA REVIEW GR P	LABARGE,D.E. LABONTE,W.T. LABRUNA,S.	8812090097 8612150035 8812220055	50-333 60-382 50-354
KESERH W. 8812000297 50-387 P KNIGHT SP. 881220024 40-8760 LANCASTER W.K. 8811200289 60-213 KESERH W. 8812100127 50-387 F KNIGHT SP. 881220024 40-8760 LANCASTER W.K. 881200027 50-309 KESERH W. 8812100127 50-387 F KNIGHT SP. 881220024 40-8760 LANDIG MR. 881120026 40-874 KESERH W. 8812100235 50-387 F KNIGHT SP. 881120027 40-876 LANDIG MR. 881120026 40-874 KESERH W. 8812100235 50-387 F KNIGHT SP. 881120027 50-288 P LANDIG MR. 881120026 50-247 KESERH W. 8812100235 50-387 P KNIGHT SP. 8811200457 50-208 P LANNIG W.D. 8811300183 60-277 KESERH W. 881210027 50-387 P KNIGHT SP. 8811200457 50-208 P LANNIG W.D. 8811300183 60-277 KESERH W. 881210027 50-387 P KNIGHT SP. 8811200457 50-208 P LANNIG W.D. 8811300183 60-273 KESERH W. 881220038 60-387 F KNIGHT SP. 8811200457 50-208 P LANNIG W.D. 8811300183 60-273 KESERH W. 881220038 60-387 F KNIGHT SP. 8811200457 50-208 P LANNIG W.D. 8811300183 60-273 KRIGHT SP. 8811200457 50-208 P LANNIG W.D. 8811200313 60-273 KRIGHT SP. 8811200457 50-288 P LANNIG W.D. 8811200459 60-322 KRIGHT SP. 881120045 50-387 KRIGHT SP. 881120045 50-387 KRIGHT SP. 881120045 50-388 KRIGHT SP. 881120045 50-389 KRIGHT SP. 881120045 50-348 KRIGHT SP. 881120045 50-389 KRIGHT SP. 881120045 50-348 KRIGHT SP. 881120045	KEMIG,R.R. KEISER,H.W. KEISER,H.W.	6812220401* 8811220341 8811230306	60-269 O 60-387 P 60-387 R	KNIGHT B.E. KNIGHT S.P. KNIGHT,S.P.	8612270223 8811300113 8812050028	70-143 40-8027 40-8027	LAGOE,L.J. LAGOE,L J. LAHS,W.	8612060234 8812060318 8811280128	50-410 60-410 ORG
RESERTITION	KEISER,H.W. KEISER,H.W. KEISER H.W.	8812020097 8812090282 8812120172	50-387 Q 50-387 P 50-387 F	KNIGHT, S.P. KNIGHT, S.P. KNIGHT, S.P.	6812210239 8812210241 8812210280	40-8768 40-8768 40-8027	LANCASTÉR,W.K. LANCASTER,W.K. LANDIS,M.R	8811300298* 6812230032* 8811290577	50-213 50-309 40-7604
KELLY.J.A. 881220304 50.313 G KNIGHTON.G.W. 6912150227 50.206 P LANPHER,L.C. 8812020113 60.322 KEWPER.J.S. 881200380 60.363 A KNOP.R.C. 8611220342 50.346 O LANPHER,L.C. 8812020121 60.322 KEWPER.J.S. 8812000137 50.353 O KNOP.R.C. 8611200342 50.346 O LANPHER,L.C. 8812020121 60.322 KEWPER.J.S. 8812000219 50.353 A KNOP.R.C. 8611300050 50.341 O LANPHER,L.C. 8812020168 60.322 KEWPER.J.S. 881200022 60.353 A KNOP.R.C. 8611300060 50.341 O LANPHER,L.C. 8812020168 60.322 KEWPER.J.S. 8812000232 60.353 A KNOP.R.C. 8611300060 50.341 O LANPHER,L.C. 8812020168 50.322 KEWPER.J.S. 8812000232 60.353 A KNOP.R.C. 8612140225 50.461 O LANPHER,L.C. 8812020168 50.322 KEWPER.J.S. 881200016* COMMISSION KNOP.R.C. 8612140225 50.461 O LANPHER,L.C. 8812020168 50.322 KEWNEDY,E.M. 8812000016* COMMISSION KNOTTS.J.B. 8612010325 FRM LARA.J.F. 8811200332* 50.387 KENNEDY,E.M. 8812202039 WASTE MGT KOBER.R.W. 8811200047 50.244 O LARA.S.C. 861270261 60.454 KENNEDY,I.E. 881220039 50.601 A KOBER.R.W. 881200047 50.244 O LARA.S.C. 861270261 60.454 KERCH.H.W. 8812200346 50.265 O KOHISE.G. 881220165 PR LARCCHE.G. 8812100018* 70.3054 KERGH.H.W. 8812200346 50.285 O KOHISE.G. 881220167 50.445 G LARCCHE.G. 8812100018* 70.3054 KERGH.H.W. 8812200346 50.285 P KOLIGH.F. 88120010165 PR LARACCHE.G. 8812100018* 70.3054 KERGH.H.W. 8812200346 50.285 P KOLIGH.F. 88120010165 PR LARACCHE.G. 8812100018* 70.3054 40.8754 KERGH.H.W. 8812200346 50.285 P KOLIGH.F. 88120010165 PR LARACCHE.G. 8812100018* 70.3054 40.8754 MERGH.H.W. 88121020346 50.285 P KOLIGH.F. 8812001016 PR LARACCHE.G. 8812100016* 50.285 P KOLIGH.H.J.E. 8812001016* PR LARACCHE.G. 881210016* 50.285 P KOLIGH.H.J.E. 8812001016* PR LARACCHE.G. 881210016* 50.285 P KOLIGH.H.J.E. 8812001016* PR LARACCHE.G. 881210016* 50.285 P KONIKIN.J.E. 881201016* PR LARACCHE.G. 881210016* 50.285 P KONIKIN.J.E. 881210016* PR LARACCHE.G. 881210016* 50.285 P KONIKIN.J.E. 881210016* PR LARACCHE.G. 881210016* 50.285 P KONIKIN.J.E. 881210016* 50.305 P LARACCHE.G. 881210016* 50.305 P LARACCHE.G. 881210016* 50.305 P KONIKIN.J.E. 8812100016*	KEISER,H.W. KEISER,H.W. KEISER,H.W.	8812190235* 8812190377 8812200196	50-387 P 50-387 P	KNIGHTON, G.W. KNIGHTON, G.W. KNIGHTON, G.W.	8811290457* 8812060074* 8812060091*	50-206 P 50-206 P 60-206 P	LANNING,W.D. LANNING,W.D. LANNING,W.D.	8811300331 8812070119 8812220059	50-313 50-220 50-325
KEMPERJS. 8812270165 60:352 P KNOP.R.C. 861240235 50-461 Q LARA.J. 881128053° 50:333 KENNEDY,E.M. 881200018° COMMISSION KNOTTS.J.B. 8812100222 PRM LARA.J.F. 8812100212° 60:454 WASTE MGT KOBER.R.W. 8811280047 50:244 O LARA.S.C. 8812070281 60:454 MENT.A.P. 8812200127 50:486 R.W. 8811280047 50:244 S LARCCHE.G. 8812070281 60:454 MENT.A.P. 8812200309 60:801 A KOBER.R.W. 88112800586 PR LARCCHE.G. 881216082 40:884 MEDICAL MED	KELLY, J.A. KEMPEN, T.V. KEMPER, J.S.	8812210304* 8812090188* 8811290360	COMMISSION 50-353 A	KNIGHTON,G.W. KNIGHTON,G.W. KNOP,R.	8812150127* 8812150227 6812210133	50-206 P 50-206 V 50-483 S	LANPHER, L.C. LANPHER, L.C. LANPHER, L.C.	8812020113* 8812020121*	50-322 50-322 50-322
KERRY, J.F. 8812080018' COMMISSION KOLSKY, K.B. 6612210225 WASTE RES LARSON, C.E. 8812180398 50-282 KERSHULB. 8811200581 50-344 S KONKLIN, J.E. 8812010252' 50-219 Q LARSON, C.E. 8812200241 50-282 KENTER, D.R. 8811300256 50-312 S KONKLIN, J.E. 8812130051' 50-254 Q LATHAM, S.B. 8812020046 50-322 KEUTER, D.R. 8812400017 50-312 S KONWINSKI, G.R. 8812010024 40-8502 LATHAM, S.B. 8812020046 60-322 KEUTER, D.R. 88122700485 50-312 S KONWINSKI, G.R. 8812020162' 40-4492 LATHAM, S.B. 8812020104 50-322 KIDO, C. 88122700485' 50-346 O KONWINSKI, G.R. 8812201059 40-4492 LATHAM, S.B. 8812020104 50-322 KIDO, C. 88122700485' 50-346 O KONWINSKI, G.R. 8812210359 40-4492 LATHAM, S.B. 88122020113' 50-322	KEMPEH,J.S. KENNEDY,E.M.	8812090232 8812270165 8812080016*	COMMISSION	KNOP,R.C. KNOP,R.C. KNOTTS,J.B.	8811300060° 8612140235 8812010322	50-341 Q 50-461 Q PRM	LANPHER,L.C. LARA.J. LARA.J.F.	8811290553° 8811300312° 8812070261	50-333 60-387
KEUTER, D.R. B811300256 60-312 S KONKLIN, J.E. 881210061 50-324 Q LATHAM, S.B. B812020048 60-322 KUTER, D.R. B812140017 50-312 S KONWINSKI, G.R. B81202082 40-8502 LATHAM, S.B. B812020048 60-322 KUDO, B812270048 50-348 Q KONWINSKI, G.R. B812210182 40-891 LATHAM, S.B. B81202014 50-322 KUDO, B812270048 50-348 Q KONWINSKI, G.R. B812210189 40-891 LATHAM, S.B. B812020113 50-322 KUDO, B812270048 50-348 Q KONWINSKI, G.R. B812210195 40-891 LATHAM, S.B. B812020113 50-322 KUDO, B812270048 50-322 KUDO, B812270048 50-325 KUDO, B812220214 50-295 P KONWINSKI, G.R. B812210159 40-894 LATHAM, S.B. B812020113 50-322 KUM, H.S. B812220214 50-295 P KONWINSKI, G.R. B812220208 40-8920 LATHAM, S.B. B812020113 50-322 KUM, S.B. B812220214 50-295 P KONWINSKI, G.R. B812220208 40-8920 LATHAM, S.B. B812140058 50-322 KUM, S.B. B81221021 50-390 A KONTAN, J.J. B812280131 50-335 G LATHAM, S.B. B812140058 50-322 KUM, S.B. B81221027 50-390 A KONTAN, J.J. B812280131 50-335 G LATHAM, S.B. B812140058 50-322 KUM, S.B. B8121021 50-390 A KONTAN, J.J. B812280131 50-335 G LATHAM, S.B. B812140068 50-322 KUM, S.B. B81210021 50-390 A KOWALSKI, S.J. B811280131 50-353 A LATHAM, S.B. B812140078 50-322 KUM, S.B. B81210049 50-390 A KOWALSKI, S.J. B812280139 50-353 A LATHAM, S.B. B812140071 50-322 KUM, S.B. B812140073 50-322 KUM, S.B. B812140073 50-322 KUM, S.B. B812140073 50-3	KEOUGH,E.J. KERCH,H.W.	8812140151° 8812200346°	50-601 A 50-443 G 50-265 O	KOBËR,R.W. KOHN,S.M. KOHSE,G.E.	6812090056 6812270167 8812050139*	PR 50-446 G 50-20 P	LAROCHE,G. LAROCHE,G. LARRAGOITE,L.S.	8811300018' 8812150082 8812210234 8812120258 8812080147	40-8724
KILGORE B.E. 8812070207 bo.327 bo.327 bo.327 bo.327 bo.327 bo.327 bo.327 bo.322 kim.h.s. KONWINSKI, G.R. bo.322 bo.325 bo.325 bo.322 bo.325 bo.322 bo.325 bo.322 bo.325 bo.322 bo.325 bo.322 bo.325 b	KERSHUL,B. XERSHUL,B. KEUTER,D.R.	8811290581 8812050207 8811300256	50-344 S 50-344 S 50-312 S	KONKLIN,J.E. KONKLIN,J.E.	8812010252* 8812020163* 8812130051*	50-219 Q 50-277 Q 50-254 Q	LARSON,C.E. LASH,T.R. LATHAM,S.B.	8812020046	REVIEW
KINTNER.E.E. 8812160121 PROJ KOZUP.C.S. 8812010195 50-255 F LATHAM.S.B. 8812140073 50-322 KINTNER.E.E. 8812160121 PROJ KOZUP.C.S. 8812020220 50-255 S LATHAM.S.B. 8812140073 50-322 60-325 S LATHAM.S.B. 8812140073 50-325 S LATHAM.S.B. 88121400	KIDO,C, KIDO,C, KILGORE,B.E.	8812270048* 8812270048* 8812070207	50-312 S 50-346 O 50-346 O 50-327 S 60-295 P	KONWINSKI,Ğ A. KONWINSKI,Ğ.R KONWINSKI,Ğ.R.	8812210188 8812210359 8812220102	40-8911 40-8684 40-3453	LATHAM,S.B. LATHAM,S.B. LATHAM,S.B. LATHAM,S.B.	0812020113*	50-322 50-322 50-322 50-322 50-322
KNTNER.E. 8812160121 PROJ KOZUP.C.S. 8812020220 50-255 S LATHAM.S.B. 8812140073 50-322	KINGSLEY,O.D. KINGSLEY,O.D.	8812210217 8812210297 8812230012	50-390 A 60-390 A	KOTTÁN,J.J. KOWALSKI,S.J KOWALSKI,S J.	8812060027* 8811280139 8812070044	50-353 A 50-353 S	LATHAM,S.B. LATHAM,S.B. LATHAM,S.B. LATHAM,S.B. LATHAM,S.B.	8812140068 8812140071	50-322 50-322 50-322
	KINTNER,E.E.	8812160121	PROJ	KOZUP,C.S. KOZUP,C.S. KOZUP,C.S.	8812020220	50-255 S	LATHAM,S.B.	8812140073	50-322

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORI
LATHAM,S B. LATHAM,S B LATHAM,S B LATHAM,S B LATHAM,S B	8812140139 8812190156 8812190156 8812270014 6812270014	50-322 G 50-322 G 50-322 G 50-322 G 50-322 G	EETSCHEIK J LETSCHEIK J LETSCHEIK J LETSCHEIK J LETSCHEIK J	8812270033 0812270052 8912270052 8812270068 0812270068	50 322 G 50 322 G 50 322 G 50 322 G 50 322 G	LOFLIN,L I LOFLIN,L I LOFLIN,L I LOFLIN,L I LOFLIN I I	8811290523 8811300042 8812020235 8812110069 8812130268	50 400 50 261 50 261 50 261
LATHAMS B. LATHAMS B LATHAMS B LATHAMS B LATHAMS B	6812270024* 8612270024* 8612270033 8812270033 8812270052	50-322 G 50-322 G 50-322 G 50-322 G 50-322 G	LEUGERS.M J LEUGERS.M J LEUGERS.M J LEVIN.H A LEVINE.J M	8812140054 8812180112 8812190112 6812090212* 8811280021	50:322 G 50:322 G 50:322 G COMMISSIO N 50:313 Q	LOFLIN,L I LOFLIN,L I LOGSDON,M I LOGSDON,M J. LONG A R	0812160114 8812190407 8611290165 8612190217 8812210059*	50 761 60 324 WASTE RES WASTE RES 50 327
LATHAM,S.B. LATHAM,S.B. LATHAM,S.B. LATTA,R.M. LATZ,J.E.	8612270052 8612270068 8612270066 8611260096* 8611290145	50-322 G 50-322 G 50-322 G 50-322 G 50-261 Q WASTE MGT	M.Faukan W.Faukan M.Eaukan M.Eaukan M.Eaukan M.Eaukan M.Eaukan	8811300119* 8812010012* 8812130043 8812180295 6812200211*	50:313 Q 50:313 Q 50:313 S 50:368 P 50:366 S	LONG, LA LONG JA LONG, JA LONG, JA LONG, JU	8812020256 8812140202 8812190225 9812200343 88122070227	70 142 70 143 70 143 70 143 56 327
LATZ,J.E. LATZ,J.E. LATZ,J.E. LAU,F.L. LAUBEN,G N	8612060262 8612150256* 8612190226 8612150107* 8612160048	WASTE MGT WASTE MGT WASTE MGT 50-309 P REVIEW GR P	M.L.BYNYBJ M.C.BYNYBJ M.C.BYNYBJ M.L.BYNYBJ M.L.BYNYBJ	8812210043 8812210085 6812210160 8812210184 8812210211	50-313 S 50-313 S 50-313 S 50-368 S 50-313 S	FONG'R', FONG'B F FONG'R'O FONG'R' FONG'R' FONG'R'	8812200144 8812080042 8811180260 8811290058 8812020180*	50 127 50 219 50 287 PFQU 40 6902
LAUER M.T. LAURITO A.W. LAURITO A.W. LAWLER R.A. LAZARUS,W.	8812180053* 8812140123* 8812140125* 8812050047* 8811210031*	50-424 O WASTE RES WASTE RES 50-293 F 50-293 P	LEVINE J M LEVINE,J M LEVIS,W LEVYJ S. LEW,D	8812220243 8812230177 8812050275* 8812010343 6812010252*	50-313 S 50-368 S 50-324 O NUREG 50-219 O	LORE,S D LORIG,I. LORION J LOUTHT,G J LOUX,R H	8612210302* 8812190201* 8812270110 8812270169 8812120036	50 300 WASTE MES 50-250 40-7455 WASTE MGT
LAZARUS,W. LAZARUS,W. LAZARUS,W. LAZARUS,W. LAZARUS,W.	8811210036* 6811210033' 8811210041* 8811210042* 8811210045*	50-283 P 50-283 P 50-283 P 50-283 P 50-283 P	LEWAND,JM LEWIS,G LEWIS,JH. LEWIS,M LEWIS,S,H	8811290161 8812210153 8812210400 8812220088 8812280250	50-457 S 40-8904 TOPHEP PH 50-320 G	L UEUNAUSUU O L,UANSBUJ O L,UANSBUJ O L,UANSBUJ L UANSBUJ L UANSBUJ O L,UANSBUJ O L,UANSBU	8812050279* 89121201128* 8912200113 8612200329 8912190040	FOW FOW REVIEW GR FEVIEW GR 50 443
LAZARUS,W. LAZARUS,W. LAZARUS,W. LAZARUS,W.J. LAZARUS,W.J.	8811210077* 8811210081* 8812130276* 8811230010* 6812060212*	50-293 P 50-293 P 50-293 H 50-213 O 50-244 Q	LIAW,B D. LIAW,B D. LIEBERMAN,J LIEBERMAN,J LIEBERMAN,J	8812220216* 8812270245* 8811290544 8811300065 8811300098	50-259 Q 50-250 Q 50-456 Q 50-302 Q 50-346 P	LUEHMAN,J LUEHMAN,J LYON,W C LYONS,E	8811390261 8812070073 8612140122 851223\\\ 260 6812120180	50 153 50 528 50 267 7081359 57 250
LAZARUS,W.J. LAZARUS,W.J. LAZO,R.M. LE,N.B. LEBARGE,D.E.	8812080191* 8812120201* 0812180078 8812130169 8812220062	50-57 Q 50-269 Q 50-275 G 50-324 P 50-333 P	LIEBERMAN,J LIEBERMAN,J LIEBERMAN,J LIEBERMAN,J LIEBERMAN,J	8811300261 8811300262 8812080065 8812070073 8812090055	50-458 Q 50-255 Q 50-265 Q 50-528 Q 70-1100	LYONS, J.FT LYONS, T. LYONS, T. MAACK, K.L. MAATCHETT, S.D.	8812210221* 8812200153 8812200282 8812280007*	50 300 50 423 50 423 50 05 50 372
LEE,B. LEE,B. LEE,H.W. LEE,MP.	8012020227 8012020279 8012070032 8012220333 8012150171	50-445 H PR PR PR 71-9218 WASTE MGT	LIEBERMAN,J LIEBERMAN,J LIEBERMAN,J LIEBERMAN,J LIEBERVAN,J	8812120177 8812120274 8812130008 8812130011 8812140118	I&E 50-413 O 50-302 Q 50-331 Q I&E	MABRIFO,B MABRIFO,B MABURIFO,B MACDONALD,C.E MACDONALD,C.E	8812060201* 6912060266* 8812090325 8811230514 8811230519*	WASTE MG* WASTE MG* WASTE MG* 71 6420 71 6420
LEE,S.Y LEE,T.D LEE,T.D. LEEDS.E. LEGETTE,F.L.	8312010060 8812150233* 6812190033* 6812190085 8812200148	NUREG 70-143 70-143 NUREG 60-261 S	LIEBERMAN J. LIEBERMAN,J. LIEBERMAN,J LIEBERMAN,J LIEBERMAN,J	6012140122 0812150018 8012210077* 0812220110 8812220291	50-269 Q 70-1718 50-206 Q 50-293 Q 50-280 Q	MACDONALD,C F. MACDONALD,C E MACDONALD,C.E MACDONALD,C F. MACDONALD,C F	8912010208 6812050926 8812050150 881205915X 8812059336	71 (643) 71 (60) 50 (61) 70 (24/6) 70 (173)
LEGETTE,F.L. LEHMAN,L.L. LEHMAN,L.L. LEHNERT,R.A. LENAHAN,J.J.	8812270241 8811289120 8812050334 8812190031* 8812080165*	50-261 S 50-285 S 50-265 S 50-354 P 50-200 Q	LIEBERMAN,J. LIEBERMAN,J. L'EBERMAN,J. LIM,T.H. LINEHAN,J.J	8812220299 8812290292* 8812290298* 8812200137 8812020082	50:302	MAGDONALD,C.E. MAGDONALD,C.F. MAGDONALD,C.E. MAGDONALD,C.E. MAGDONALD,C.F.	#812060007 8812060018 8812150050 8812150054 #812150253	71 500 71 5147 70 2170 XPORTLYO 71 6601
LENAHAN, J.J. LENAHAN, T.J. LENGJAK, B. LEONARD, J.D. LEONARD, J.D.	8812080195* 8812190251* 8812190685* 6804210209 8811300001	60-327 Q 50-424 Q XPORTLIC 50-322 Q 60-322 F	LINEHAN,J J. LINEHAN,J J. LINEHAN,J J. LINEHAN,J J. LINEHAN,J J.	8811290187 8811290193 8811290213 8811290498 8812060187	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT	MACDONALD,C E MACDONALD,C E MACDONALD,C E MACDONALD,C E MACDONALD,C E	8812150256 8812150257* 8812150261 8812150262* 8912160657	71 576 71 506 71 619 71 619 50 201
LEONARD, J.D. LEONARD, J.D. LEONARD, J.D. LEONARD, J.D. LEONARD, J.D.	8812070103 8812080089 8812090157 8812140059 8812140168	50-322 H 50-322 K 50-322 Q 50-322 P 60-322 Q	LINEHAN,JJ. LINEHAN,JJ. LINEHAN,JJ. LINEHAN,JJ.	8812090068 8812090032 8812190107 8812190304 8812190307	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT	MACDONALD,C E. MACDONALD,C E. MACDONALD,C.E MACDONALD,C E MACDONALD,C.F.	8812166058 8812160053* 8812220170 8812220172	71:9130 75:3180 71:3107 71:5971 71:6336
LEONARD, J.D. LEONARD, J.D. LEONARD, J.D. LEONARD, R. LEONARD, R.	8812160259 8812160273 8812200204* 8811230278 8812060106	50-322 P 50-322 F 50-322 P 50-369 P 50-369 F	LINEHAN, J.J. LINEHAN, J.J. LINEHAN, J.J. LINENBERGER, G. LINVILLE, J.	8812210389 8812210406 8812220307 8812278053 8812130021	WASTE MGT WASTE MGT WASTE MGT 50-443 G 50-352 Q	MACDONALD,C E MACDONALD,C E MACDONALD,J.A MACDONALD,W G MACDOUGALL,E	8812220177* 8012220317 8812140002 8811230053 8811210050	71 6336 71-5984 50 443 OPS 50-277
LEONARD,R. LEONARD,R. LEROY,S.E. LEROY,S.E. LEROY,S.E.	8812090162 8812210386 8811290589 8812020047 0812090247	60-360 F 50-369 F 50-369 S 50-369 S	LINVILLE, J.C. LINVILLE, J.C. LINVILLE, J.C. LINVILLE, J.C. LIPPINCOTT, E.P.	8612060019* 8812090151 8812230141* 8812270180 8812150107*	50-170 Q 50-277 R 50-277 Q 50-352 P 50-309 P	MACE,M MACE,M H MADDEN,J MADDEN,P.M MADEDA,T J.	8812140105 8812010276 8811290498* 8812050276* 8811300542*	COMPACT COMPACT 50 333 50 324 50 375
LEROY, S.E. LEROY, S.E. LESAR, M.T. LESSER, M.S. LESSER, M.S.	8812140233 8812140270 8812220367* 8811290049* 8812200273*		LIPPOLD.W.J. LITTLE.C.C. LITTLE.W.S LIU.W.C. LIVERMORE,H.H.	8812270085 8812220139 8812200109* 8812200006*	50-317 Q 71-9229 50-259 Q 50-316 Q 50-445 Q	MADEDA,T.J. MADISON,J.R. MADSEN,A M MAGUIRE,H MAHDAVY,H	8812060145° 8812070081 8812190117° 8812160018° 8911280136	56-456 56-451 56-322 50-275 50-336
LESTER,W. LETSCHE,KJ. LETSCHE,KJ. LETSCHE,KJ. LETSCHE,KJ.	8811280250 8812140071 8812140071 8812140073 8812140073	TOPREP 50-322 G 50-322 G 50-322 G 50-322 G	LORH LORH LORH LORH LORH	8812010246 6812070232 6812120148 6812160123 6812160125*	50-261 P 50-261 P 50-261 P 50-261 P 50-261 P	MALINOSKI, J.W MALLETT, B. MALLETT, B. MALLETT, B. MALLETT, B.S.	8812209202 8812140076 8812200093 8812200147 8811250370	71 421 186 186 186 186
LETSCHE,K.J. LETSCHE,K.J. LETSCHE,K.J.	6812140113 6812140113 8812270633	50-322 G 50-322 G 60-322 G	LO,R.H. LOCH,E P. LOFLIN,L I.	8812220278 8812130111 8811230004	50-261 F 70-1151 50-324 F	MALLETT B.S. MALLETT B.S. MALLOY,M.	8812090179 8812090183* 8812010139	40 7601 40 7601 50 445

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGONY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR
VALLOY M.	8812120060	50-445 A	MATTHEWS, I A	8812180293°	FOIA	MCDONALD, W.G.	6611300276	OFIG
VALLOY M.	8812160181	50-445 E	MAUCK, C.J	8812050147	71-9218	MCDONOUGH, S.P.	8612010356	PFI
VALOD Y C. W.	8811300417*	XPORTLIC	MAXWELL, D.C	8812190416	50-237 R	MCDUFFIE, M.A.	8612050263	50-261
VALOD Y C. W.	8812230068	70-1257	MAXWELL, G.F.	8812050290°	50-348 Q	MCELH:NNEY, T.F.	8612080059*	50-250
VALONE, D. D.	8812160008	50-275 S	MAYS, D.R.	8812010095	QA999	MCELROY, N.	8612050207*	FOIA
VALCNE,D L	8812210200*	50-260 P	MAYS,W.M	8612020126	40-8857	MCELROY,N.L.	8812050285°	FOIA
MAISCH M.G.	8812080004	50-322 G	MAYS,W.M	8812050138*	40-6064	MCGOVERN,J.J.	8812200321	50-54
MAISCH M.G.	8812190176	50-322 G	MAYS,W.M	8812060003	40-8857	MCGOWAN,N.C.	8812010181	PR
MAISCH SI.J	8812220188	XPORTLIC	MAYS,W.M	8812210149	40-8857	MCGRATH,R.S.	8812130091	50-309
MAISCH,B.D.	8812270243*	50-280 P	MAYS,W.M	8912210156	40-8857	MCGRAW,J.A.	8812050040	50-483
UARBAUSH,K.E	8811290117	50-155 S	MAZZAFERRO,P.	8812140243	50 410 S	MCGUIRE,D R	8611280046*	50-438
VARBAUSH,K.E	8812050316	50-155 P	MAZZAFERRO,P.A.	6812210110	50-220 S	MCGUIRE,D R	8611280057*	50-390
UARBAUSH K.E	8912120217	50-165 O	MCALPINE,E.J.	6811230186*	70-143	MCGUIRE,D R	8812890132*	70-143
VARBAUSH K.E	8812130238	50-165 P	MCALPINE,E.J.	8812070246*	70-27	MCGUIRE,D R	8812990140*	50-425
VARSHETTI,S.S	8812050160*	PROJ	MGALPINE,E.J.	8812190033*	70-143	MCINNES,I.D.	6812190031*	50-354
MARGULIES, M.B. MARGULIES, M.B. MARGULIES, M.B. MARGULIES, M.B. MARGULIES, M.B.	8812020067 8812020072 8812140019 8812140025 8812190041	50 603 G 50 603 G 50 603 G 50 603 G 50 603 G	MCALPINE,E J. MCANALLY, J t. MCBREARTY, R. A. MCBREARTY, R. A. MCBRIDE, N. F.	8812210360* 8812210185 8812120869* 8812600146*	70-27 60-269 F 50-220 Q 50-333 Q FOIA	MCINTYRE,A.C. MCKAGUE,H.L. MCKEE,C.R MCKEE,P. MCKEEIYAN,R.S.	8812070107* 8812190023* 8812010069 8812190088 8812210221*	50-499 WASTE RES NUREG 50-445 60-390
A NO FAM M STIC PAM M STIC PAM L S,YS - FAM M,YSJ - TOIFFAM ,W,Y,TTOIFFAM	8811300489* 8812140097 8812010159 8811200011* 8811230214	REVIEW GR P 50-445 G PR 50-322 Q TOPREP	MCBRIDE,N.F. MCBRIDE,N.F. MCBRIDE,N.F. MCBURNETT,M.A. MCBURNETT,M.A.	8812060153' 8812060164' 8812060228' 8811290363 8812060294	FOIA FOIA FOIA 50-493 P 60-493 F	MCKERNON,T.O. MCKIBBEN,J.C. MCKIBBEN,J.C. MCLAUGHLIN,J.E. MCLAUGHLIN,J.E.	8812140215* 8812070159 8812150007 8812220002 8812220003*	50-265 50-166 50-166 50-142 50-142
MARPIOTT, P.W.	8812050172*	50-440 P	MCBURNETT,M A	8812080152	50-498 P	MCLAUGHLIN,P.	8812200098°	50-344
MARPIOTT, P.W.	8812130262	50-605 A	MCBURNETT,M.A.	8812080202	50-498 P	MCLEAREN,T.	8812020003	CONTRACT
MARSHALL, J. S.	8812200066	50-445 S	MCBURNETT,M.A.	6812090337	50-490 P	MCLELLAN,T.	8812220216°	50-259
MARSHALL, J. S.	8812200156	50-445 S	MCBURNETT,M.A.	8812130115	50-490 P	MCMURRAY,C.M.	8812140058	50-322
MARSHALL, J. S.	8812210129	50-445 S	MCBURNETT,M.A.	8812130207	50-400 P	MCMURRAY,C.M.	8812140058	60-322
MARSHALL J S	8812210135	50-445 S	MCBURNETT,M A	8812130231	50-490 Q	MCMURRAY.C.M.	8812140068°	50-322
MARSHALL J S	8812210157	50-445 S	MCBURNETT,M A.	8012130300	50-490 P	MCMURRAY.C.M	8812140068°	50-322
MARSHALL J S.	8812210163	50-445 S	MCBURNETT,M A.	8812140003	50-490 P	MCMURRAY.C.M	8812140139	50-322
MARSHALL J S.	8812270170	50-445 A	MCBURNETT,M A.	8812150095	50-490 P	MCMURRAY.C.M.	0812140139	50-322
MARSHALL J S	8812270174	50-445 S	MCBURNETT,M.A.	8812200127	50-490 P	MCMURRAY.C.M.	6812190156	50-322
MARSHALL J.S. MARSHALL J.S. MARSHALL J.S. MARSHALL J.S. MARSHALL J.S.	8812270175 8812270177 8812270184 8812270189 8812270190	50-445 S 50-445 S 50-445 A 50-445 A	MCBURNETT,M A. MCBURNETT,M A. MCCABE,E C. MCCABE,E C. MCCABE,E.C.	8812210020 8912210397 8811300495* 8812120041* 8812230022*	50-498 P 50-498 P 60-245 Q 50-213 Q 60-336 Q	MCMURRAY,C.M MCMURRAY,C.M. MCMURRAY,C.M. MCNAMARA,A.E. MCNEIL,S.A.	8012190156 8812190172* 8812190172* 8812190387 8812070110	50-322 50-322 50-322 50-244 60-317
MARSHALL J.S.	8812270224	50-445 S	MCCABE, E.C.	8812270278*	60-423 C	MCNEIL,S.A.	8612080128	50-317
MARSHALL,W.	8812210076	50-302 F	MCCALL, J.K.	8811230104*	50-390 A	MCNEILL,C.A.	8812020298	50-277
MARSHALL,W.	8812210166	50-302 F	MCCALLUM, E.J.	8811230213	71-8639	MCNEILL,W.M.	8812130141*	50-458
MARSTON,R.R.	8812080030*	60-280 Q	MCCANEE, W.T.	8812140161	60-213 F	MCNEILL,W.M.	8812150109*	50-313
MARSTON,R.R.	8812160174*	60-321 Q	MCCANN, R.J.	6812130291	50-463 R	MCQUEEN,A.	8812070265	50-206
MARTIN J.G.	8812120001	50-397 Q	MCCARTHY C.B.	8811230311	50:206 P	MCVAY,C.W.	6812050160°	PROJ
MARTIN J.G.	8812120001	50-397 Q	MCCAUGHEY D.A.	8811300016*	70:3054	MEAD,J.J.	8812200150°	50-369
MARTIN J.B.	8812120002*	50-397 Q	MCCAUGHEY D.A.	8812150068*	70:2032	MEAD,J.J.	8812200279°	50-413
MARTIN J.B.	8812150133	50-206 Q	MCCONAGHY W.J.	8812130094	PROJ	MEAD,J.J.	8812200283°	50-413
MARTIN J.B.	8812150156	50-206 Q	MCCONAGHY W.J.	8812150147	PROJ	MEAD,J.J.	8812200190°	50-369
OLUTRAL OLUTRAL OLUTRAL OLUTRAL OLUTRAL	8812190171 9812190174* 9812190178* 8812200088 8812200089	50-528 Q 50-528 Q 50-528 Q 50-312 S 50-344 Q	MCCONAGHY,W.J. MCCORKLE,G.W. MCCORMICK,M.J. MCCORMICK,A.D.	8812160076 8609020051* 8810190472* 8812150090 0810120268*	PROJ 70-622 70-622 50-352 S 50-458 P	MEADE,K.E. MEADE,K.E. MEADE,K.E. MEADE,K.E. MEADOWS,T.R.	8812140234 8812140236 8812200244 8812210074 88122060082*	50-260 50-296 50-259 50-259 50-397
MART N.J.B.	8812200094*	50-344 Q	MCCORMICK,R.D.	8810120268*	50-458 P	MECREDY, R.C.	8811290226	50-244
MARTIN,P.D	8812020176*	50-313 P	MCCOY,F.R.	8811280042	50-439 Q	MECREDY, R.C.	8811300527	50-244
MARTIN,PI.D.	8812050017	40-8857	MCCOY,F.R.	8811280054	50-390 Q	MECREDY, R.C.	8812010098	50-244
MARTIN,PI.D.	8812090320	50-498 Q	MCCOY,F.R.	8812080167	50-327 Q	MECREDY, R.C.	8812060320	60-244
MARTIN,PI.D.	8812090326*	50-498 O	MCCOY,F.R.	8812080168*	60-327 Q	MECREDY, R.C.	8812070183	60-244
WARTIN',R (). WARTIN',R E. WARTIN',R E. WARTIN',R E. WARTIN',R E.	8812130212* 9811300310 9811300322 8812010180 8812010279	FOIA 50-277 Q 50-277 P 50-277 P 50-277 P	MCCOY,F.R. MCCOY,F.R. MCCOY,F.R. MCCOY,F.R. MCCOY,F.R.	6812080189 6812080194 6812090002 6812090005 6812090008	50-327 Q 50-327 Q 50-390 Q 60-390 Q 60-269 Q	MECREDY,R.C. MECREDY,R.C. MEDFORD,M. MEDFORD,M.O. MEDFORD,M.O.	8912180248 8812190387 8812210080° 8812210081 8811230271 8811290263	50-244 50-244 60-206 60-361 50-361
MATTIN,T.T.	8811290563	60-277 Q	MCCOY,F.R.	8812090014	50-390 Q	MEDFORD,M.O.	8811290388	50-361
MARTIN,T.T.	8811200573	60-293 Q	MCCOY,F.R.	8812090018	50-259 Q	MEDFORD,M.O.	6811300057	50-361
MARTIN,T.T.	8811300342	50-277 Q	MCCOY,F.R.	8812090031	50-390 Q	MEDFORD,M.O.	6812010177	PR
MARTIN,T.T.	8811300412	50-293 P	MCCOY,F.R.	881209004D	50-390 Q	MEDFORD,M.O.	6812050050	50-206
MARTIN,T.T.	8812120048	50-309 Q	MCCOY,F.R.	8812090046	50-327 F	MEDFORD,M.O.	6812060040	50-206
MARTIN,T.T.	8812120066	50-333 Q	MCCOY, F.R.	8812090074	50-259 Q	MEDFORD,M.O.	8812060121	60-206
VARTIN,T.T.	6812220342	50-443 P	MCCOY, F.R.	8812090114	50-259 Q	MEDFORD,M.O.	8812080124	50-361
VABUYAMA,T.	8812130086*	XPORTLIC	MCCOY, F.R.	8812180041	50-259 V	MEDFORD,M.O.	6812060128	50-206
MARJYAMA,T.	8812130195*	XPORTLIC	MCCOY, F.R.	8812190003	50-390 Q	MEDFORD,M.O.	8812130142	50-361
MASNYK,O.M.	8811290398*	50-333 Q	MCCOY, F.R.	8812100005*	60-390 Q	MEDFORD,M.O.	8812130266	50-361
MASMYK,O.M.	8812090132*	70-143	MCCOY,F.R.	8612200347	50-327 Q	MEDFORD,M.O.	6812190061	50-361
MASON J.R.	8812060118*	FOIA	MCCOY,F.R.	8912200351	50-269 Q	MEDFORD,M.O.	8612210216	50-361
MATCHETT,S.D.	8812280007*	50-322 G	MCCOY,F.R.	8812200353*	50-269 Q	MEDFORD,M.O.	8612210265	50-206
MATHEW,FI.	8812080154*	60-247 Q	MCCOY,F.R.	8812200369	50-327 Q	MELFI,J.	6812190342*	50-312
MATH'S,J L	8812180136*	60-416 Q	MCCOY,F.R.	8812210047	60-327 Q	MELLEN,L.S.	9812220026*	60-260
MATTHEWS, D.B. MATTHEWS, D.B. MATTHEWS, D.B. MATTHEWS, D.B. MAYTHEWS, D.B.	8611280108* 8812020211* 8812020315 8812050072 8812050076	60-424 P 50-425 A 50-269 P 60-269 Q 50-413 P	MCCOY, F.R. MCCOY, F.R. MCCOY, J.J. MCCOTCHAN, D.A.	6812210099 9812210293 8812220226 8812130039 9812160018'	60-327 Q 60-327 Q 50-327 Q WASTE MGT 60-276 P	MELLOR,R.A. MENDEZ,R. MENDEZ,R. MENDEZ,R. MENDONCA,M.M.	8812210411 8811300517* 8811300558* 8812160075* 9812060201*	50-29 60-262 50-346 50-265 60-275
PATTHEWS.D.B. MATTHEWS.D B. VATTHEWS.D.B.	8812080027	50-269 P	MCDONALD,R.P.	8812270097	50-424 Q	MENDONCA,M.M.	8812130245*	50-276
	8812090087*	60-269 F	MCDONALD,R.P.	8812210249	60-424 Q	MENGE,R.C.	8811300572	50-316
	8812090154*	50-424 P	MCDONALD,W.G.	8811230328	ORG	MENNING,J.E.	8812200242*	60-321

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR'		AUTHOR	ACCESSION NUMBER	CATEGO		NOHTON	ACCESSION NUMBER	SUBJECT CATEGORY
MERRELL,A MERRELL,A. MERRELL,A.M. MERRELL,A.M. MERRELL,G.B.	8812080047 8812090304 8812130176 8812130239 8812050114*	50-354 50-354 50-354 50-354 WASTE MG	ន ទ ទ ទ	MINOR,G C. MINOR,G C. W.NOR,G C MINOR,G C MINS'NGER,WJ	8812020123* 8812020123* 8812020123* 8812020123*	50-322 50-322 50-322 50-322 50-334	G G G H	MORZENTI,S P. MOXLEY,M MOZAFARLB MRCOZKA,E J MROCZKA,E F.	8811280065 8812210020 8812200172 8812050325 8812220042	42-8657 40-4492 50-324 50-423 50-213
MERRIWEATHER,N. MESERVE,R.A. MESERVE,R.A. METCALF,P.D. METZGER,N	8812090343* 8812190076 8812190076 8812210221* 8812150066*	50-395 40-2061 40-2061 50-390 CONTRACT	a A	MITCHELLS.C MIZNER,JH MIZNER,JH MIZNER,JH MIZNER,JH	6812010142 8812020074 8812270075 6812270087 6812280091	PR 50-443 50-443 50-443 50-443	G G G	MROCZKĄĘ F. MROCZKĄĘ J MROCZKĄĘ J MROCZKĄ E J MROCZKĄĘ J	8812220042 8811280101 8811280101 8811290027 8811290027	50-213 50-336 50-336 50-213 50-213
MEYER,R. MICHAELS,T.S. MICHAELS,T.S. MICHAELS,T.S. MICHAELS,T.S.	8105080333* 8811320199 8812010194 8812050129 6812220015	REVIEW GR 50-139 50-113 50-2 50-112	ь Б Б	MOFFATT, L W MOFFATT, L W. MOFFATT, L W. MOFFATT, L.W. MOFFATT, L W.	8811280062 8811280157 6812010153 8812050182 8812190371	50-302 50-302 50-302 50-302 50-302	s s s s	MROCZKA,E.J. MROCZKA,E.J. MROCZKA,E.J. MROCZKA,E.J. MROCZKA,E.J.	8811290027 8811290219 8811290219 8811300072 8811300072	50-213 50-213 50-213 50-213
MICHALK,P. MICHAUD,P.W. M!LANO,P.D. MILANO,P.D. MILANO,P.D.	8812200211* 8811300563* 6812050093 8812060191 8812160133	60-368 60-267 50-285 60-285 50-285	5 Q P F	MOFFATT, L.W. MOLAN, J.C MOLZER, D. MONAGHAN, J.A MONAGHAN, J.A.	8812190381 8812130172 8812010347 6812280006* 6812280006*	50-302 50-323 50-285 50-322 50-322	s s g g	MROCZKA,E J MROCZKA,E.J. MROCZKA,E.J MROCZKA,E.J. MROCZKA,E.J.	8011300093 8811300093 8812010034 8812010034 8812010055	50-213 50-213 50-423 50-423 50-213
MILANO,P.D. MILANO,P.D. MILLARO,H.T. MILLER,C.L. MILLER,C.L.	8812200057 8812220174 8812150010 8811280125* 8811300202*	50-285 50-285 50-274 50-163 50-139	P P P P	MOOREJE MOOREJE MOOREM MOOREM MORAN,D.H	8612190068 6812190111 6812090008* 8612090009*	50-250 50-250 50-170 50-170 50-259	G G P P	MROCZKĄĘ J. MROCZKĄĘ J. MROCZKĄĘ J. MROCZKĄĘ J. MROCZKĄĘ J.	8812010055 8812010055 8812020125 8812020125 8812020222	50-213 50-213 50-213 50-213 50-336
MILLER, C.L. MILLER, C.L. MILLER, C.L. MILLER, C.L. MILLER, C.L.	8812060315 8812070046 8812160012 8812190060 8812190073	50-601 ORG PROJ PROJ PROJ	R	MORAN,D.H. MORAN,D.H. MOREY,D.N. MOREY,D.N. MOREY,D.N.	6812120068 8612160129 8612130055 8812130263 0312190266	50-259 50-259 50-364 50-348 50-348	P S S R	MROCZKA,E J. MROCZKA,E J. MROCZKA,E J. MROCZKA,E J. MROCZKA,E J.	8812050325 8812000038 8812060038 6812060277 8812060277	50-423 50-213 60-213 50-213 50-213
MILLER, C.L. MILLER, C.L. MILLER, D.B. MILLER, D.B. MILLER, D.E.	8812220019* 8812230265 8812230118 8812190255 8811280105*	50-112 PROJ 50-213 60-213 50-305	P S R Q	MOREY, D. N. MOREY, D. N. MOREY, D. N. MORGAN, H. E. MORGAN, H. E.	8812190275 8612220266 8612220269 8811280110 8812020242	50-364 50-364 50-348 50-361 50-361	A S S S S S	MROCZKA,E.J. MROCZKA,E.J. MROCZKA,E.J. MROCZKA,E.J. MROCZKA,E.J.	8812070076 8612070076 6812070076 8812070078 8812120063	50-213 50-213 50-245 50-245 50-245
MILLER,D.E. MILLER,F. MILLER,F.L. MILLER,G.D. MILLER,H.B.	6812270048* 6811230220 6812230174 6811300552 6811300024	50-346 40-7455 40-7455 60-297 60-213	Q R F	MORGAN,H.E. MORGAN,H.E. MORGAN,H.E. MORGAN,H.E. MORGAN,H.E.	8812060290 8812060321 6812120007 8812130258 8612130280	50-361 50-206 50-361 50-381 50-206	S S S S	MROCZKA,E J. MROCZKA,E J. MROCZKA,E J. MROCZKA,E J. MROCZKA,E J.	8812120178 8812120178 8812120178 8612120214 8812120214	60-245 60-423 60-421 60-245 60-245
MILER,HJ. MILLER,HJ. MILLER,HJ. MILLER,HJ. MILLER,HJ.	8811290428 8812090260 8812130133 6812130134* 6812160073	50.255	P 0000	MORGAN,H.E. MORGAN,H.E. MORGAN,H.E. MORGAN,H.E. MORGAN,H.E.	8812130290 8812200152 8812200163 8812210146 8B12210410	50-206 60-361 60-206 50-361 50-206	S R S S	MROCZKA,E J. MROCZKA,E.J. MROCZKA,E.J. MROCZKA,E.J. MROCZKA,E.J.	8812130113 8812130113 8812130289 8812130289 8812210054	50-336 50-336 50-336 50-336 50-423
MILLER,H.J. MILLER,H.J. MILLER,H.J. MILLER,H.J. MILLER,J.	8812190343 8812190346* 8812270040 8812270045* 8812150064	50-254 50-254 50-346 50-346 1&E	0 0 0	MORGAN,H.E. MORGAN,H.E. MORGAN,R.E. MORGAN,R.E. MORGAN,R.E.	6812220128 6812220130 6811260070 6812060293 6812140262	60-206 50-362 50-261 60-261 60-261	អ ទ ទ ព	MROCZKĄĘ J. MROCZKĄĘ J. MROCZKĄĘ J. MUDLIN,J.D. MUDLIN,J.D.	8812210054 8812220328 8812220328 8710140231° 8710140322°	50-423 50-336 50-336 50-276 50-463
MILLER,J. MILLER,J. MILLER,L. MILLER,L.F. MILLER,L.F.	8812150235* 8812190046 8812200275 8812070070* 0812190342*	XPORTUC XPORTUC 50-312 50-312 50-312	s Q Q	MORGAN,R.E. MORGAN,R.E. MORGAN,R.E. MORGAN,R.E. MORGAN,R.E.	8812150088 8812200148 8812200340 8812200342 8812270241	50-261 50-261 50-261 60-261 50-261	O S S F S	MUIRHEAD,D.M. MULDER,R.U. MULLER,D.R. MULLER,D.R. MULLER,D.R.	8811210074* 8812010059 8811290415* 6811300168 6811300295*	60-293 60-396 60-454 60-461 60-461
MILLER,L.K. MILLER,L.K. MILLER,L.K. MILLER,L.K. MILLER,L.K.	8811290494 8811290550 8811290554 8812070065 8812070069	50-311 50-311 50-311 50-272 50-311	S S S S S S	MORGAN,W.E. MORGAN,W.E. MORGAN,W.E. MORRIS,J.K.	8811290291 8812070040 8812070229 8812200335* 6812010340	50-10 50-373 50-374 50-528 50-285	P P V F	MULLER,D.R. MUNRO,J.F. MUNRO,J.F. MUNRO,J.F. MUNYAN,R.A.	8812070035 8812090008* 6812090142* 8812220352* 8812010400	50-295 50-170 50-424 50-335 50-219
MILLER,L.K. MILLER,L.K. MILLER,L.K. MILLER,L.K. MILLER,M.S.	8812130114 8812190256 8812190271 8812190306 8812280012*	60-272 50-311 50-272 60-311 60-322	S R R G G	MORRIS,K.J. MORRIS,K.J. MORRIS,K.J. MORRIS,K.J. MORRIS,K.J.	8811230038 8811260120 8811280124 8811300095 8811300175	50-285 50-285 60-285 60-285 50-285	S S P P	MURLEY,T.E. MURLEY,T.E. MURLEY,T.E. MURLEY,T.E. MURLEY,T.E.	8811300584 8812020147 8812020150* 8812020154* 8812070105	TOPREP 50-440 50-440 50-440 50-348
MILLER,M.S. MILLER,M.S. MILLER,M.S. MILLER,M.S. MILLER,M.S.	8812280012* 9812280012* 9812280012* 9812280088 8812280088	50-322	G G G	MORRIS,K.J. MORRIS,K.J. MORRIS,K.J. MORRIS,K.J. MORRIS,K.J.	8812010347 8812020103 8812020314* 8812050334 8812060126	50-285 50-285 60-285 50-285 50-285	S H Q S P	MURLEY,T.E. MURLEY,T.E. MURLEY,T.E. MURLEY,T.E. MURLEY,T.E.	8812070118 6812070122 6812070132 8812070155 8812070158	60-346 60-305 60-261 60-483 50-316
MILLER,M.S. MILLER,M.S. MILLER,W.H. MILLER,W.O. MILLER,W.O.	8812280088 8812280088 8812050290* 8812060087* 8812060130*	60-322	9 9 9	MORRIS,K.J. MORRIS,K.J. MORRIS,K.J. MORRIS,K.J. MORRIS,K.J.	8812060237 8812070056 8812070238 8812080035 8812090147	50-285 50-285 50-285 60-285 60-285	G # SP Q	MURLEY,T.E. MURLEY,T.E. MURLEY,T.E. MURLEY,T.E. MURLEY,T.E.	8812070168 8812070168 8812070195 8812070218 8812070220	50-395 50-468 50-266 60-272 50-317
MILLER,W.O. MILSTEAD.W. MILTENBERGER,S. MILTENBERGER,S. MILTENBERGER,S.	8812060223* 8812020170 8811280024 8811300351 8812010282	FOIA NUREG 50-311 50-272 50-354	P Q P	MORRIS, K.J. MORRIS, K.J. MORRIS, K.J. MORRIS, K.J.	8812090150 8812130015 8812130217 8812130224 8812130234	60-285 50-285 50-285 60-285 60-285	P 8 8 8 Q	MURLEY,T.E. MURLEY.T.E. MURLEY,T.E. MURLEY,T.E. MURLEY,T.E.	8812070228 8812070235 8812080029 8812080069 8812080080	50-247 50-286 50-289 60-213 50-269
MILTENBERGER,S. MILTENBERGER,S. MILTENBERGER,S. MILTENBERGER,S. MILTENBERGER,S.	8812010338 8812050041 8812090078 8812140012 8812150004	50-272 50-272 50-272 50-354 50-272	Q P Q P P	MORRIS, K.J. MORRIS, K.J. MORRIS, K.J. MORRIS, K.J. MORRIS, K.J.	8812140016 8812190399 8812200282 8812210277 8812210330	50-285 50-285 50-285 50-285 60-285	Q R S F	MURLEY,T.E. MURLEY,T.E. MURLEY,T.E. MURLEY,T.E. MURLEY,T.E.	8812080109 6812080111 8812080114 8812080122 8812090077	60-334 60-424 60-255 60-282 50-382
MILTENBERGER,S. MILTENBERGER,S. MILTENBERGER,S.	8812150034 8812190026 8812200106	50-272 50-354 50-272	P P P	MORRIS, K.J. MORRIS, K.J. MORRIS, K.J.	8812230069 8812230071* 8812270211	60·285 50·285 50·285	P S	MURLEY,T.E. MURLEY,T.E. MURLEY,T.E.	8812090108 8812090224 8812090229	ORG 50-462 50-313

ROHTUA	ACCESSION NUMBER	SUBJECT	,	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR
WALEY,TE. WALEY,TE WALEY,TE WALEY,TE	8812000233 8812120079 8812120123 8812120137 8812120226	50-280 50-302 50-250	ե 6 6	NIELSON, B.H. NIELSON, B.H. NIELSON, K.K. NIMITZ, R.L. NIMITZ, R.L.	8812020052 8812020052 8812050119* 8811290040* 8311200365*	50-322 G 60-322 G WASTE MGT 50-272 O 50-272 O	ORSER,W S ORSER,W S. ORTICELLE A. OSBORN,T G OSBORN,T G	8812270300 8812270303 8812190256 6812020192 8812210258	50-341 50-341 50-311 40-6904 40-8904
VUALEY,TE VUALEY,TE VURLEY,TE VURLEY,TE VURLEY,TE	8812120231 8812120232 8812120233 8812130082* 8812130275	50-29 50-443 50-293	Н Р Р	NIR,I. NOBLE,T. NOGEE,A NOLAN,D J. NOLAN,J.	8812120151* 8812010359 6812140168* 8812080024 8812160233	50-416 P 50-327 F 50-293 P 71-0233 50-275 R	OSBORNE, J.M. OTT, M.C. PACKARD, G.C. PAGE, M PAGE, M	8812069213 8611210074* 6812140261 8312010214 8312010280	50-317 50-293 50-255 CONTRACT CONTRACT
VURLEY,TE. VURLEY,T.E. VURLEY,T.E. VURLEY,T.E. VURLEY,T.E.	8812140160 8812150172 8812150134 8812150139 8812150229	50-528 50-206 50-312	ե Ե Ե	NOONAN,T.P. NOONAN,T.P. NOONAN,T.P. NOONAN,T.P. NORDEN,K.	8812010197 6812050300 8912200194 8812210201 8812010047	50-412 S 50-412 S 50-412 S 50-334 S NUREG	PAGE M. PAGE M PALJUG J. PALOM NO.F.G. PALOMINO,F.G	8812130168 8812160169 8812210130 8812140071 8812140073	CONTRACT CONTRACT TOPREP 50-322 50-322
WURLEY,T.E. WURLEY,T.E. WURLEY,T.E. WURLEY,T.E. WURLEY,T.E.	0812210383 0812210394* 0812210398* 0812220348 0812220368*	50-312 50-312 50-275	ս Գ Պ	NORDERHAUG,L NORELIUS,C.E. NORELIUS,C.E NORELIUS,C.E. NORELIUS,C.E.	8812210040 8811300144 8811300352 8811300440 8812090267	70-734 50-493 F 50-348 Q 50-461 P 50-295 F	PALOMINO, F.G. PALOMINO, F.G. PALOMINO, F.G. PALUSAMY, S.S PAOLINO, F.J.	8812270033 8812270052 8812270068 8812070182* 8811200553*	50-322 50-322 50-322 50-338 50-333
DURPHY,KE. NURPHY,ME MURPHY,ME. DURPHY,ME. NURPHY,W.P.	8812200284 8811300329* 8812130141* 8812140215* 8811280174	50-267 50-458 50-285	8 Q Q Q P	NORELIUS,C.E. NORELIUS,C.E. NORELIUS,C.E. NORELIUS,C.E. NORELIUS,C.E.	0012120024 8812120065* 6812160130 8912200255 8012200312	50-295 Q FOIA 50-254 F REVIEW GR P 50-255 P	PAPANDREA,C J PAPANGREA,C J PAPANIC,G. PAPANIC,G. PAPANIC,G.	8811290355* 8811290357* 8811300109 8812060208 8812060276	50-277 50-277 50-29 50-29 60-29
MURPHY,W.P. MURPHY,W.P. MURPHY,W.P. MURPHY,W.P. MURPHY,W.P.	8812070029 8812070133 8812090298 8812120915 8812140264	50-271 50-271 50-271	K P Q Q R	NORELIUS,C.E NORELIUS,C.E. NORKIN,D.P. NORRIS,J.A NORTH,H.S	6812210232 8812270136 0812160177 8812010033 6812050204*	50-265 Q 50-266 Q 50-445 E PR 60-528 Q	PAPANIC,G PAPANIC,G PAPANIC,G. PAPANIC,G. PAPANIC,G.	8612090062 8612160063 8612210004 8812220129 8812270055	60-29 50-29 60-29 50-29 50-29
MURRAY,B MURRAY,B. MURRAY,B. MURRAY,B. MURRAY,B.	8811290452 8811300257* 8812130132* 8812140136 8812140142*	50-285 60-274	\$ Q Q Q	NORTH,H.S. NORTH,P.J. NORTON,C.L. NORTON,C.L. NOWAK,J.M	8812190415* 6812080119 6812020046 8812020046 6812020077	50-526 Q 50-269 S 50-322 G 60-322 G 50-334 H	PAPERIELLO, C.J. PAQUIN, P.L. PARKER, C. PARKER, L. PARKH, LL, R, W.	8812120062* 8812010381 8812090228* 8812210321* 8812020186*	FOIA 71-9105 COMM:SSIO QA999 50-353
NURRAY,B. MURRAY,B. MURRAY J.P. MUSOLF,D. MUSOLF,D.	8812140211 8812210347* 8812290289* 0811290345 8811300044	60-313 FOIA 50-282	F Q Q S	NOWLEN,S P. NUSSBAUMER,D A. NUSSBAUMER,D A. NUSSBAUMER,D.A. NUSSBAUMER,D.A.	8812100076 8105080397* 8812050342* 8812090290*	NURED REVIEW GR P FOIA FOIA FOIA	PARLER,W.C PARLER,W.C PARLER,W.C. PARRISH,R.A. PARTLOW,J.G.	8609040334* 8611170087* 8811040189* 6812230102 8811290270	FOIA FOIA FOIA FOIA 50-259
VUSOLF,O. MUSOLF,O. MUSOLF,D. MUSOLF,D. MUSOLF,D.	0812020094 0812070209 0812120110 0812140249 0812140253	50-263	8 8 0 R R	NUSSBAUMER, D.A. NUSSBAUMER, D.A. NUSSBAUMER, D.A. NUSSBAUMER, D.A. NUSSBAUMER, D.A.	88120903317' 8812090333' 8812120042' 8812120070' 8812120091'	FOIA FOIA FOIA FOIA FOIA	PARTLOWJ.G. PASCIAK,W. PASCIAK,W. PASCIAK,W.J. PASCIAK,W.J.	8912210016 8911300326* 8812230652 8812060027* 8812210022*	50-445 50-333 70-1100 50-334 50-317
MUSOLF,0 MUSOLF,0, MUSOLF,0, MUSOLF,0, MUSSER,R.A.	8812200056 8812200240 8812200246 8812200263 8812200242*	50-263 60-263 60-263	9 9 9 9 9 9	NUSSBAUMER, D.A. NUSSBAUMER, D.A. NUSSBAUMER, D.A. NUSSBAUMER, D.A. NYKAZA, P.	0812120098* 0812120111* 0812100359 0812200350* 0812210007	FOIA FOIA REVIEW GR P REVIEW GR P 50-458 S	PASTERNAK,R PASTIS,H.N. PASTIS,H.N. PASTIS,H.N. PASTIS,H.N.	8812010139 8811280196 8812010274 8812070149 8812090085	50-220 50-269 50-269 50-269 50-269
MYERS C.J. MYRABO,A L. MADER G. MAIK.J.A NAIK.J.A	8912190342* 8812140249 8812200285 8811290110 8812070223	50-263 50-341 50-327	Q R S S S	O'BRIEN,J. O'BRIEN,J.P. O'CONNELL,P.V. O'CONNELL,P.V. O'CONNOR,P.W.	8812200008* 8012050201* 8011290040* 8812060261* 0811200209	50-344 O 50-275 O 50-272 Q 60-333 O 60-298 P	PASTIS,H N, PASTVA,M J. PASTVA,M J. PASTVA,M J. PASTVA,M J	8812220310 0811290031 0812060242 8812130161 0812210007	60-269 50-325 50-325 50-324 50-326
NAIK,JA NAIK,JA NAIK,JA NAIK,JA NA'X,JA	8812070226 6812070230 8812140246 8812140248 8812200061	60-327	S S S S S	O'CONNOR,P.W. O'CONNOR,P.W. O'CONNOR,P.W. O'CONNOR,P.W. OCONNOR,P.W.	8811300063 6812050084' 8812150091' 8812160020 8812140259'	50-298 P 50-265 P 60-285 J 50-298 P 50-298 J	PASTVA M.J. PASTVA M.J. PASTVA M.J. PATE,R. PATE,R J.	8812210103 8812210365 8612210409 8812140241 8812060080	50-325 50-326 50-324 50-362 50-397
NA K, J A, NAN DY, E.R. NAN DY, E.R. NARBUT, P.P. NARDI, A J	8812200151 8811200085 8812010345 8812130245* 8812200317	60-206	S P Q	ODEGAARDEN,R.H. ODEGAARDEN,R.H ODEGAARDEN,R.H. ODELL,L.D. ODELL,W.H.	8812010271 8812010316 6812010328 8812220341* 8812010313	71-9218 71-9202 71-9010 50-336 P 50-458 R	PATE,R J. PATE,R J. PATE,R.J. PATE,R.J. PATE,R.J.	6812130196 6812140046 8812140052 6812140056 6812140061	60-344 60-276 50-312 50-344 50-397
NASHID A NAVE,E.O. NAVE,E.D. NEIGHBORS,J.D. NEIGHBORS,J.D.	8811300469 8812010024 8812210084 8811280163 8811290420	50-262 50-259 50-296 50-266 50-286	2 2 2 5 6 6	OFTE,D. OKONIEWSKI,C. OLIVERI,M.A. OLMSTEAD,C.A. OLMSTEAD,C.A.	8812090139 8812090225* 8812200348* 8811290581 8812050207	WASTE MGT COMMISSION 50-285 Q 50-344 S 50-344 S	PATE R.J. PATE R.J. PATE R.J. PATE R.J. PATE R.J.	8812140065 8812140085 8812140088 8812140090 8812140095	50-528 60-106 50-133 60-206 60-27
NEISLER J.H. NELSON,O. NEMETHY,E. NERICCIO,M.W. NERON,O.	8812050214* 8812180170* 8812060333 8812140181 8812190412	50-369 PRM 50-213	Q Q F R	OLMSYEAD,C.A. OLMSTEAD,C.A. OLMSTEAD,C.A. OLSEN,A.F. OLSEN,T.T.	8812050210 8812210061 8812210365 8811300185 8812020131*	50-344 S 50-344 S 50-344 S 70-824 40-8857	PATE,R.J. PATE,R.J. PATE,R.J. PATE,R.J. PATE,R.J.	6812140100 6812140104 8812140109 6812140133 8812140138	60-113 50-89 50-139 60-224 50-288
NESTOR,C.W, NETZEL,I NETZEL,I. NETZEL,I. NEWBURGH,G.	8812020166 8812150085 8811280188 8812190362 8812140021	NUREG 60-304 60-295 60-295 60-245	8 8 8 8	OLSEN,T.T. OLSEN,T.T. OLSEN,T.T. OLSEN,W.P. OLSHAN,L.N.	8812210108* 6812210228 6812220142 8812230032* 6811290408	40-8857 40-8657 40-8681 50-309 60-454 P	PATE.R.J. PATE.R.J. PATE.R.J. PATE.R.J. PATE.R.J.	8812140143 8812140147 6812140153 6812150002* 8812150093	50-326 50-32 50-18 50-397 50-276
NEWBY,C.T NEWMAN,N.J. NEWSOME,R.W. NEWSOME,R.W. NEWTON,R.A.	8812010008 8812010099 8812080012* 8812080193* 8811280108		g G	OLSHAN,L.N. ORDERS,W.T. ORDERS,W.T. ORSER,W.S. ORSER,W.S.	8811300443 8811290049* 8811290087 8811290087 8812140265	50-454 P 50-413 Q 50-413 Q 60-341 S 60-341 S	PATE,R.J. PATE,R.J. PATE,R.J. PATE,R.J. PATE,R.J.	8812150239 8812200098* 8812210017 8812210019* 8812210066	50-397 50-344 50-528 50-528 50-528
NICHOLAS,J.B. NICHOLS,B.W. NICHOLSON,L.E.	8812050196° 8811280160 8812080162°		G S G	ORSER,W.S. ORSER,W.S. ORSER,W.S.	8612140266 6812200265 6812270091	50-341 S 50-341 S 60-341 R	PATÉ Z.T. PATÉL.C.P. PATÉL.C.P.	8811300207* 9811280175 9811280246	ORG 50-281 50-280

PATRICK, W.C. PATTERSON, C.A. PATTERSON, J. PATTERSON, J. T. PATTISON, R.S.	8811290164 8812120109	WASTE MGT	D1 1100 T 11					
PATTISON, R.S.	8812190009* 8811300531* 8812020007	WASTE MGT 60-424 O 50-346 O 50-483 H	PHIFEA,T K, PHILIP,J, PHILIP,J, PHILIPS,J, PHILLIPS,J.	8812210143 9812120159 8812230220 8812010010 8812190161	50 327 S FOIA FOIA FOIA 40-2253	QUAIN,P.B QUALLS,P. QUALLS,P.M QUAY,T. QUAY,T.	8812130200* 8812130321* 8812130342* 8812130200*	XPORTUG 50:361 C 50:312 C 50:316 F 50:315 F
PATTISON,R.S. PATTON,J.D. PATTON,J.D.	8812050014 8812060002 8812050133 8812050135* 8812050176	40-8084 40-8084 40-8084 40-8064 40-8102	PHILLIPS, J. PHILLIPS, J. PHILLIPS, J. PHILLIPS, J. PHILLIPS, M.P.	0812180214 8812190283 8812190364 8812210065 8811390517*	FOIA FOIA FOIA 50-206 P 50-202 Q	OUAY, I QUAY, T QUAY, T R QUERIO, P QUERIO, R E	88122702181 88122702181 88121601091 8812210007 6811280161	50-263 F 50-341 F 50-265 F 50-456 S 50-457 S
PAULK.G.L. PAULSON.B.F. PAULSON,W.A.	8811280105* 8812090322* 8812070081 8811280212 8811300040	50:305 O 50:335 O 50:461 F 50:458 P 50:458 P	PHILLIPS,M.P PHILLIPS,M.P. PHILLIPS,M.P. PICK,G.A PICKETT,D.V.	8611300550* 0812133005* 8812160075* 8811300248* 8611290202	50:246 O 50:315 O 50:255 Q 50:299 Q 50:482 O	QUERIO, IT (: QUERIO, R.C. QUERIO, R.E. QUERIO, IT E. QUERIO, IT E.	8012050010 0812060011 6812060034 8812150217 8812210001	50 457 S 50 456 S 50 457 S 50 456 F 50 457 S
PAULSON,W.A. PAULSON,W.A. PAULSON,W.A. PAULSON,W.A. PAULSON,W.A.	8811300046* 8811300056 8811300099 8811300241 8812050127	50-458 P 50-458 P 50-458 P 50-458 P 50-458 P	PICKETT O V. PICKETT D.V. PICKETT D.V. PICKETT D.V. PICKETT D.V.	8011300059 8012020232 8012030318* 8012160023	50-492 P 50-482 P 50-482 P 50-482 P 50-402 P	QUERIO,R E HADER,R M FIADER,R M HAMSEY,C RANDAZZA,J (I.	6812210003 6812010071 6012010268 8812190323* 6311200115	50-457 8 PR PRM 50-361 C 50-363 C
PAULSON,W.A.	8812090003	50-458 P	PICKETT,D.V.	8812160030	\$0:482 P	RANDAZZA, J B	8812050291	50-309 F
PAULSON,W.A.	8812200354	50-458 P	PICKETT,E H.	8012290226	FOIA	RANDAZZA, J B.	0812150092	50-309 F
PAULSON,W.A.	8812210204	50-458 P	PIERSON,R C	8812220105*	50:259 Q	RANGANATH, S	6811290355*	60-277 F
PAULSON,W.A.	8812210210*	50-458 P	PIERSON,R C.	8812220119*	50:327 Q	HANGANATH, S	8811290357*	50-277 F
PAYNE,D.C.	8812190222*	50-324 V	PIGOTT,D.R.	8012020135	50:224 G	HANGE, D M	68112210000	40-8102
PEARSON J.T	6812010133	50-271 I	P.GOTT,D.A.	8812020135	50-224 G	RANGE,D M	8812210356	40 8064
PEDERSON R L.	6811300257*	50-313 Q	PIN,F.G	8812020166	NUREG	HANKIN,W H	8811230269*	70-1161
PEEBLES, T A	6811290048*	50-413 Q	PIRTLE,G.L	8812210244*	50-282 O	BANKIN,W.H	6812080028*	70-1151
PEEBLES, T A.	6812200273*	50-413 Q	PITTMAN,J.	8812020170	NUREG	RANKIN,W.H	0812090284*	50-324
PEFFER.O.R.	6812160018*	50-4275 P	PLANTE,P.J	8812150110*	50-300 P	RANKIN,W.H	U812150233*	70-143
PELC, R.A	8812050337*	FOIA	PLENIEWICZ,R	8812080248	50:455 S	HANKIN,W H.	8812160134*	70-1201
PELC, R.A.	8812050339*	FOIA	PLENIEWICZ,R	8812080248	50:454 S	RANIGIN,W H	8812190245*	60-302 C
PELIZZA, M.S.	8811280050	40-8786	PLENIEWICZ,R	8812080205	50:454 R	RANKIN,W.H	8812190263*	50-260 C
PELIZZA, M.S.	8812210282	40-8968	PLENIEWICZ,R	8812200027	50:454 H	RAVENSCROFT,N	8812120087	XPORTLIC
PELLET, J.L.	8812140209*	50-298 V	PLIML,G.J.	8811280168	50:295 S	RAY,H.B.	8812210087*	50-206 F
PENNINGTON,W.S.	8812070047	70-1257	PLIML,G J.	881290091	50 304 S	RAY,M J.	8812050198	50-327 (
PENNINGTON,W.S.	6812070268	70-1257	PLIML,G J.	8812060029	50:295 S	RAY,M J.	4812050242	50-327 (
PENNINGTON,W.S.	8812210247	40-8027	PLIML,G J.	8812070052	50:295 S	RAY,M J.	8912050289	50-328 (
PERKINS,K.E.	8812300014*	60-440	PLIML,G.J	8812130197	60:295 S	RAY,M J.	8812060055	50-327 (
PERKINS,N.B.	8812090184*	COMMISSION	PLIML,G.J	8812150085	50:304 S	RAY,M J.	8812080072	50-327 (
PETERSON.C.T. PETERSON.M.R. PETERSON.M.R. PETERSON.M.R. PETERSON.M.R. PETERSON.M.R.	6811290516	WASTE RES	PLIML,G J.	0912190362	50-205 S	RAY,M J.	8812070237	60-327 6
	6811300128	XPORTLIC	PLIML,G J.	0812200141	50-304 S	RAY,M.J.	8812070256	50-327 5
	6811300380	XPORTLIC	PLIML,G.J.	8812230081	50-205 R	RAY,M.J.	8812080227	50-327 5
	6812080078	XPORTLIC	PLOSKI,T.	8811300531*	50-346 Q	RAY,M.J.	8812140157	50-259 5
	6612080090	XPORTLIC	PLOSKI,T.	8012190267*	50-456 Q	REAVEAU,B K.	8812210274	40-6081
PETERSON,M.R. PETERSON,M.R. PETERSON,M.R. PETERSON,M.R. PETERSON,M.R.	8812080142	XPORTLIC	PLOTYCIA, G.D	8812050172*	50:440 P	REBELOWSKI,T A	8812270235*	50-238 (
	8812080171	XPORTLIC	PLULYI, J.	8812090174	FOIA	REECE,W.J	8812190016	NUREG
	8812080185	XPORTLIC	POERTNER, W.	8812080190*	50:327 Q	REECE,W.J	8812193037	NUREG
	8812080199	XPORTLIC	POGUE, B.D.	8812050236	50:275 S	REECE,W.J.	8812190066	NUREG
	8812130061	XPORTLIC	POLICH, T.	8811280960	60:529 S	REEC,C	8811300190	50-454 (
PETERSON,M.A. PETERSON,M.A. PETERSON,M.A. PETERSON,M.R. PETERSON,M.R. PETERSON,M.A.	8812130068	XPORTLIC	POLICH,T.	8812210023*	50-520 Q	REESE,H.E.	8005070350*	FOIA
	8812130075	XPORTLIC	POLLACK,M.J	8811290550	50-311 S	REEVES,D.L	8812130014	50 268 5
	8812130184	XPORTLIC	POLLACK,M.J.	0811290554	50-311 S	REEVES,E A	8812200071	60 348 6
	8812130180	XPORTLIC	POLLACK,M.J.	0812070065	50-272 S	REID,D.A	8812140111	50 271 6
	8812150022	XPORTLIC	POLLACK,M.J.	0812180306	60-311 S	HEINERT,S	8812190154	40 2253
PETERSON,M.A. PETERSON,M.A. PETERSON,M.A. PETERSON,M.R. PETERSON,M.R. PETERSON,M.A.	8812150115 8812160221 8812190022 8812190049 8812190055	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POLLARO,B. PORTER,E.C. POTAPOVS,U. POWELSON,R. POWERS,C.M	8812050056 8812140229 8812210340* 8812050303 8812020098	PR 50:271 F QA009 50:390 Q 50:397 P	REINHART,M. REINHAHT,M. REINHART,M REIS,E.J. REIS,E.J.	0811280100 8012050181 8812050187 8812190008 8812280021*	REVIEW OR I REVIEW OR I REVIEW OR I SU-322
PETERSON,M.R. PETERSON,M.R. PETERSON,M.R. PETERSON,M.R. PETERSON,M.R. PETERSON,M.R.	8812190063 8812190070 8812190116 8812190124 8812190140	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POWERS,C.M. POWERS,C.M. PRENDERGAST,K PRESCOTT,P. PRESTHOLT,P.T.	8812080124 8812200086 8812010287* 8812120003* 8811280056	60-397 S 50-397 R 70-734 50-397 Q WASTE MGT	REIS,E J. REIS,E J. REIS,E J. REISTER,U B. REITER,L.	8812280026* 8812280026* 8812280064 6812020166 8703110292*	50-322 6 50-322 6 50-322 6 NUREG 50-440
PETERSON,M.R. PETERSON,M.R. PETERSON,M.R. PETERSON,M.R. PETERSON,M.R.	8812200054 8812200072 8812270116 8812270124 8812270129	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PRESTHOLT, P.T. PRESTHOLT, P.T. PRESTHOLT, P.T. PRESTHOLT, P.T. PRESTHOLT, P.T.	8012050166 8812050304 6812120089 6812130077 8812190177	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT	REMICK,F.J. REMICK,F.J. REMICK,F.J. REMICK,F.J.	8808310058* 8812010110 8812010117 8812010143 8812220004	60-440 ACRS ACRS ACRS 71-3005
PETERSON,M.W. PETROSINÓ,J.J. PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J.	8812150217 6812210329* 8811300505 8611300516* 8812010365	60-456 R QA999 40-4492 40-4492 40-8084	PRESTHOLT P.T. PREVATTE R.L. PREVATTE R.L. PRICE E.R. PRICE J.C.	8812210220 8812050282* 8812200296* 8812210189*	WASTE MGT 50-395 O 60-395 O FOIA 40-8027	REMLEY,M.E. REMLEY,M.E. RENTSCHLER,R.R. REVANKAR,S.T. REYES,L.A.	8812220008 8812230283 8812280076 6812010060 8812080057	71-3005 71-5071 NUREG NUREG 60-250
PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J.	6812010366	40-1162	PAITCHETT, A.F.	8812120235	WASTE MGT	REYES,LA.	8812080058*	50 250
	6812010414	40-8027	PAITCHETT, A.F.	8812120238*	WASTE MGT	REYES,LA.	8812080159	50 280
	8812020085	40-8622	PAIVIDY, L.J.	8811290076*	50-247 Q	REYES,LA	8812090027	50 324
	8612020128	40-1162	PAOBST, J.A.	8812010411	PR	REYES,LA.	8012190102	50 395
	88122210071	40-6902	PAOBST, J.A.	8812020210	50-331 S	REYES,LA.	8812200337	50 261
PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J.	8812210138	40-3453	PUCK,J.	8812010035	PR	REYNOLDS,N.S.	8812010200	PR
	8812210230	40-8902	PUCKO,T.G.	8811300289	50-443 S	REYNOLDS,N.S.	8812010217	PR
	8812210235	40-8903	QUAID,D L.	8812130292*	50-293 H	REYNOLDS,R.S.	8812120145*	50-416
	8812210242	40-8907	QUAIN,P.B.	8812120061	70-1426	REYNOLDS,R.S.	8812120147*	50-416
	8812210374	40-0903	QUAIN,P.B.	8812130062*	XPORTLIC	RHOADS,E.W.	8811300526	50-352
PETTIS,R.L.	8812210340°	OA999	QUAIN,P.B.	8812130064*	XPORTLIC	RHODES, J.	8812050278	FOIA
PEVEAR,R.C.	8812020062	50-443 G	QUAIN,P.B.	8812130065*	XPORTLIC	RICE, G.	8812210060	WASTE MGI
PEVEY,L.E.	8811300398	70-398	QUAIN,P.B.	8812200129	XPORTLIC	RICE, P.D.	8811230238	50-425

AUTROR	ACCESSION NUMBER	SUBJECT CATEGORY	,	AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	SUBJEC
RKE P.O RKE P.O RKE P.O RKE P.O RKE P.O	8911238244 8811300566 8812010103 8812050009 8812153146	50 425 50-424 50-425	Q S K F Q	ROTHERT,W.C. ROTHERT,W.C. ROUGHAN,C. HOUGHAN,C. ROUMELIOTIS,G	8912010017 8912050089 8811300002 0811300003 8612070211	50-331 50-331 71-9187 71-9165 50-373	O H S	SCACE,S.E. SCACE,S.E. SCACE,S.E. SCACE,S.E. SCACE,S.E.	8812200122 8812200133 8812200162 8812200162 8812200264	50-245 50-423 50-245 50-245 50-245
RICE, P.D RICE, P.D RICHARDS, S RICHARDS, S RICHARDS, S.	6812210191 6812230273 6611260360 6812100323* 6812210023*	50-425 (50-529 (50-361 (5 P S Q Q	ROUMELIOTIS,G. ROUNTAFE,H. ROUSE,L.C. ROUSE,L.C ROUSE,L.C	8912070214 8812210003 8611306014 8611306015* 8811306017*	\$0:373 \$0:457 70:3054 70:3054 70:3054	S S	SCACE S.E. SCACE S.E. SCACE,S.E. SCACE,S.E. SCACE,S.E.	8812200264 8812200287 8812200287 8912210083 8812210083	50-245 50-423 50-423 50-423 50-423
AKEHARDS SA RICHARDS SA RICHARDS SA RICHARDS OF S RICHARDS OF ST RICHARDS OF ST R	8812120003* 88122000334 8812210028 8812050294 8812060139	50-528 C 50-528 C	0 V Q Q	ROUSE,L.C. ROUSE,L.C. ROUSE,L.C. ROUSE,L.C. ROUSE,L.C.	8012060312 8812080314* 8812060317* 6812060322 8812060327*	70-2932 70-2932 70-2932 70-822 70-622		SCALETTI, D.C. SCARANO, R.A., SCARANO, R.A., SCARANO, R.A., SCARANO, R.A.,	0811300110 0811290347 0812050202 0812070009 0812130253	ORG 50-312 50-528 50-528 STATE PRO
RICHARDSON,S D RICHARDSON,S D RICHARDSON,S D RICHARDSON S D RICHARDSON,S D	8812220101 8812220101 8812220115 8812220212 0812270244	50-259 C 50-327 C 50-259 C	±0000	ROUSE, L.C. ROUSE, L.C. ROUSE, L.C. ROUSE, L.C. ROUSE, L.C.	BB12080231 BB12140009 BB12140154 BB12150008 BB12159038	50-603 40-8778 70-925 40-8027 70-27	1	SCHALLER,R.F. SCHALLER,R.F. SCHALLER,R.F. SCHAUBROECK,D. SCHAUBROECK,D.	8812050049 8812140231 8812200101 8812190240 8812190247	50-461 50-461 60-401 60-368 50-313
RICH NGS H RICHTER M.H. RICKENBACKER,B. RICKER J.L. RICKETSON L.T	8812070127 8812010305 8912010227 8811290381* 8011290580*	PR	e G	ROUSE,L.C ROUSE,L.C ROUSE,L.C. ROUSE,L.C. ROUSE,L.C.	8812150043* 6812159049* 8812159061 8812159065* 8812159071*	70-27 70-27 70-2932 70-2932 70-2932		SCHENBLI, G.A. SCHEPENS, R.J. SCHERER, A.E. SCHERER, A.E. SCHERER, A.E.	8812080059* 8812080009* 8811230185 6811290458 8811390425	50-250 50-424 71-6078 70-1100 71-6078
RICKETSON L.T. RICKETSON L.T. RIDLEY,J RIDLEY,J RIDLEY,J	6911300257* 6612210347* 6612210105 6612120254 6812140223	50-255 E 50-255 E	Q G F F	ROUSE, L.C. ROUSE, L.C. ROUSE, L.C. ROUSE, L.C. ROUSSO, S.	6812190003 6812270238 6812270240* 6812270248* 6812150218	50 603 70 386 70 398 70 398 WASTE MS	A GT	SCHERER, A.E. SCHERER, A.E. SCHERER, A.E. SCHERER, A.E. SCHERER, A.E.	8811300491 8812020201 6812060247 8812080237 8812090256	50-470 70-1100 70-38 70-38 70-1100
RECKTA RGGSR RLEY,JA RNGMA RNGMA	8812140063 6812020170 8812160161* 6812010175* 0812190376*	50-304 C NUREG CONTRACT 60-237 C 50-254 C		HOUSSO,S. ROYACK,M.J RUITER,GTI RULAND,W.H RUNYAN,M.F.	8912220371° 0912200335° 8812140040 8812050276° 8812200005°	WASTE MO 50-528 50-305 50-324 50-445	GT V P Q Q	SCHERER, A.E. SCHERER, A.E. SCHERER, A.E. SCHERER, A.E. SCHERER, A.E.	8812150015 8812200082 8812210027 8812220040 8812270186	50-470 70-1100 50-470 70-1100 TOPREP
RITTENSERG,R B. RIVENBARK,G. RIVENBARK,G. RIVENBARK G.W. ROBERTS J.P.	8812150151 8811300537 0812020036 6812010302 8812050237	50-354	P O O	RUNYON,M. RUSANOWSKY,P.P. RUSCITTO,D.G. RUSSELL,L.B. RUSSELL,L.B.	8811300183 8812130053 8812140030* 8812020258 8812020258	50-300 50-387 50-443 50-317 60-317	G S P	SCHEUERMAN, J.T. SCHMERTZ, J.C. SCHM: DT, D. SCHM. DT, W. SCHMIEGE, P.A	8812140036 8612070182* 8612020189* 8812080053 8812210107	50-298 50-338 40-8302 50-333 50-275
ROBERTS, J.P. ROBEYRA ROBEYRA ROBINSON,C. ROBINSON,C,	8812140130 8812190386 8812200010 8812060316* 8812270246*		R D	RUSSELLL B. RUSSELL B. BUSSELL B RUSSELLW.T. RUSSELLW.T.	0812120258 8812200201 6812270228 8811020340* 6611210084*	50-317 50-317 50-317 50-203 50-203	S R S P	SCHMERBACH,M. SCHMERBACH,M. SCHMERBACH,M. SCHNEIDER,R.A. SCHNEIDER,R.A.	8811220017 8811300355 8811300486 8812210299 0812220094	TOPREP 50-327 50-327 70-1257 70-1257
POBINSONICH POBKINIMA POCHEMB, ROCHEMB, ROCHEMB,	8912060328* 8912190140 8812010000 8012010091* 8012050087	50-320 F	F P P R	AUSSELL,W.T. AUSSELL,W.T. AUSSELL,W.T. RUSSELL,W.T. AUSSELL,W.T.	8811290490 0811300317 0611300507 8611300550 8312090321	50-286 50-333 70-135 60-277 60-293	0 0 P 0	SCHNELL D.F. SCHNELL D.F. SCHNELL D.F. SCHNELL D.F. SCHOMAKER,R	6811300334 8811300581 8812060018 6812270203 8812210130*	50-483 50-483 60-483 60-483 TOPREP
RODDY,L RODE J A ROGERS,D.W. ROGERS,V.C. ROGERS,V.C.	8812220084 6812220084 6812210199 8012050114 8812050119	70-36	۸ ۴	RUSSELL,W.T. RUSSELL,W.T. RUTHERFORD,N.A. RUTTER,S. RYDER,T.S.	8812220138 8812220179 6811280038 8811300020 8812210010	50-317 50-213 TOPREP 50-312 50-388	5 Q S S	SCHROCK,V.E. SCHROUDER,W.J. SCHRUM,D.L. SCHUMACHER,M. SCHUMACHER,M.	8812010060 8812010410 8812020148* 8611300494* 8812060161*	NUREG 50-244 60-331 50-305 50-262
ROGGE J.F. ROLAND,M. ROLAND,M ROMBERG,W.D. ROMBERG,W.D.	8812080009* 8812150160 8812190082 8811280101 0612120178	50-341 I 60-336 I	Q F F P Q	SAINT ANDRE,B. SAINT PIERRE,B. SAINT PIERRE,B. SALESKA,S. SALESKA,S.	8812020092 8312270097 8812270097 8812010348 8812010355	60-443 50-443 60-443 PH PFI	G G	SCHUMACHER,M.C SCHUMACHER M.C. SCHUMACHER M. SCHUSTER,D. SCHUSTER,M,	8611280087* 8812270131* 8812210376* 8812070002 8812070265	50-295 50-440 50-165 50-312 60-206
ROOOH ROOOH ROOOH, ROOOH, ROOOH,	8811230225 8811230227* 8811290434 8811290441* 8812200230	50-275 1 50-275 1 50-275 1	թ թ թ	SALISBURY,W.C. SAMET,K.S. SAMWÖRTH,R. SAMWORTH,R.B. SAMWORTH,R.B.	8812210162 8812270213 8812120003* 6811230215 0812060120	40-4492 FOIA 50-397 50-397 50-397	О Р Р	SCHUSTER,M. SCHUSTER,M.D. SCHWABENBAUER SCHWARTZ,I. SCHWARTZ,I.	6812210040 9812140055 8612010218 8812020180 8812190096	70-734 50-208 60-400 NUREG NUREG
ROODH, ROSERD ROSEONEICD J. ROSSEF, ROSSIJ J.	8812230121 8811300516* 8812210277 8812230100* 8812010160	40-4492	o s	SAMWORTH, R.B. SAMWORTH, R.B. SAMWORTH, R.B. SANDS, S.P. SARSOUR, B.	8812080120 0812160083 0812160136 8812070239 0812200272	50-397 50-397 50-397 50-454 60-346	P P P R	SCHWARZ,W. fl. SCINTO,J.F. SCOTT,W. SCOTT,W. SCOTT,W.	8812090285* 8812020044 8811280148 8812020308 8812130204	50-268 50-443 60-316 NUREG 60-316
ROSSRJ ROSSRJ ROSSRJ ROSSRJ ROSSRJ	8812010160 8812010160 8812020202* 8812020202* 8812020202*	PA PH PA PA PA		SAHTOR,W.M. SARTOR,W.M. SARTOR,W.M. SAYRE,D. SCACE,S E.	6812090264* 8812190245* 8812190263* 8811280070 8811280136	50-324 50-302 50-260 50-261 50-336	Q Q Q S S	SCOTT,W. SCOTT,W.E. SCOTT,W.E. SCOWLL,V.R. SCOVILL,V.R.	8812150265° 8812020026 8612200025 8812010352 8812010365	60-316 50-155 60-165 40-8084 40-8084
ROSS,T. ROSS,T.M. ROSSI,C.E. ROSSI,C.E. ROSSI,C.E.	99 12070243 88 12070030 88 11160467 69 11290538 08 11300101	50-254 50-254 50-3 60-3 TOPHEP	P P Q Q	SCACE, S.E. SCACE, S.E. SCACE, S.E. SCACE, S.E. SCACE, S.E.	8811280136 8811280160 8811280150 8812070178 8812140021	50-336 50-423 60-423 60-245 50-245	8 8 8 8 8	SCOVILL, V.R. SCOVILL, V.R., SCOVILL, V.R., SCRUTON, G.S., SEARS, C.F.,	8812210138 8812210175 8812210242 8812210214 8812010034	40-3453 40-8084 40-8907 PT21 60-423
ROSSICE ROSSICE ROTELUAL ROTHJ ROTHEPA	8812020287 8812160037 8812090193* 8812230062 8812020169	50-3 TOPREP COMMISSION 70-1100 NUREG	Q N	SCACE,S.E. SCACE,S.E. SCACE,S.E. SCACE,S.E. SCACE,S.E.	8812140021 8812160097 8812160097 8812190412 8812190412	50-245 60-423 60-423 50-336 50-336	R R R R	SEARS,C.F. SEARS,C.F. SEARS,C.F. SEBER,L. SEIDLE,W.C.	8812120063 8812120214 8612220042 8812290273* 8811300166*	50-245 50-245 50-213 FOIA 50-313
ROTHERT W.C. ROTHERT W.C.	8812020164 8811300007 8811300502	NUREG 60-331 (60-331 (0	SCACE,S.E. SCACE,S.E. SCACE,S.E.	8812200113 8812200113 6812200122	50-245 50-245 50-245	9 8	SEIDLE,W.C. SEIDLE,W.C. SEIDLE,W.C.	8811300329° 8812130141° 8812140215°	50-267 50-458 60-285

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SEIDLE, W.C. SEIDLE, W.C. SELLECK, K.A. SELLECK, K.A. SELLECK, K.A.	8812150226* 8812240027* 8812020163 8812040163 8812140034	50-498 Q 50-482 Q 50-443 G 50-443 G 50-443 G	SIEBER, J D SIEBER, J D SIEBER, J D SIEBER, J D SIEBER, J D SIEBER, J D	8812080232 8812090272 8812120083 8812140267 0812160099	50-334 Q 50-334 F 50-334 P 50-334 R 50-412 P	SMITH,R.D. SMITH,R.D. SMITH,R.D. SMITH,R.D. SMITH,R.D.	8812020033 8812020041* 8812020048 8812020053* 8812020101	40-8102 40-8102 40-289 40-289 40-299 40-8903
SELLECK, K.A. SELLECK, K.A. SELLECK, K.A. SELMAN, M. SERKIZ, A.W.	8612140034	50 443 G	SEGELB	8811300087	50-237 P	SMITH, A.D.	8812020108	40-8903
	8812270115	50 443 G	SEGELJR	8812090050	PR	SMITH, A.D.	8812020122	40-6857
	8812270115	50 443 G	S'FFERJD	8812130172	50-323 S	SMITH, R.D.	8812020124*	40-8957
	8312010334	PR	SLADYJA	8812010129	50-237 P	SMITH, R.D.	8812020146	40-4492
	8807220389	REVIEW GR P	SLADYJA	8812160056	50-237 P	SMITH, A.D.	8812020155*	40-4492
SERKIZ,A W.	8837250041	REVIEW GR P	S LADY,JA	8812200014	50-237 P	SMITH,R.D.	8812210041	40-1162
SERKIZ,A W.	8811200482	REVIEW GR P	S LBERBERG,M.	8812150158	WASTE MGT	SMITH,R.D.	8812210045*	40-1162
SERKIZ,A W.	8812160081	REVIEW GR P	S:LVER,H.	8811300130	50-302 P	SMITH,R.D.	8812210098	40-8857
SHAFFER,R.	8912050079	40 8961	S.LVER,H.	6812000252	50-302 P	SMITH,R.D.	8812210101	WASTE MOT
SHANBAKY,M.	8811290011	50:322 O	S.LVER,H.	8812130216	50-302 Q	SMITH,R.D.	8812210104*	40-8857
SHANBAKY,M.	8812060261*	50-333 Q	SILVER,H.	8812160112	50-302 P	SMITH, R.D.	8812210139	40-3453
SHANBAKY,M.M.	8811230040*	50-272 Q	SILVER,H	8612210079	50-302 P	SMITH, R.D.	8812210151	40-4492
SHANBAKY,M.M.	8812060307*	50-219 Q	SIMON,S J	8611220337	40-7604	SMITH, R.D.	8812210158	40-8911
SHANKMAN,S.F.	8812190114	ORG	SIMON,T.R	8612020057	PH	SMITH, R.D.	8812210161	40-8064
SHANKMAN,S.F.	8812220270	ORG	SIMPSON,F.B	8611260116*	50-352 P	SMITH, R.D.	8812210170	40-8905
SHANNON,J M	8812140124*	50-443 G	SIMPSON,F B	8611290118*	50-352 P	SMITH, R.D.	8812210171*	40-3453
SHANNON,M.C.	8812060271*	50-460 Q	SINGH,A.	8812140077*	50-285 Q	SMITH, R.D.	8812210175	40-8084
SHAW,L.C	8812060132*	FOIA	SINGH,K.P.	9812280040*	50-335 T	SMITH, R.D.	8812210186	40-8027
SHAW,L.C.	8812060215*	FOIA	SINGH,K.P.	9812280040*	50-335 T	SMITH, R.D.	8812210223	40-8657
SHEA,J.R.	8812130187*	FOIA	SINKULE,M.V	9812080009*	50-424 Q	SMITH, R.D.	8812210224*	40-8857
SHELTON,D.C.	8808020344*	50 346 Q	SINKULE,M V	8812190009*	50-424 Q	SMITH,R.O.	8812210361	40-8684
SHELTON,D.C.	8812020129	PR	SINKULE,M V.	8812200242*	50-321 Q	SMITH,R.D.	6812210362*	40-8684
SHELTON,D.C.	8812050209	50 346 Q	SISKIND,B	8812050244*	WASTE RES	SMITH,R.D.	8812210363	40-8905
SHELTON,D.C.	8812050307	50 346 P	SISKIND,B.	8812050308	WASTE RES	SMITH,R.D.	8812210381	40-8027
SHELTON,D.C.	8812090201	50 346 P	SISKIND,B	8812060014*	WASTE RES	SMITH,R.D.	8812220085	40-3453
SHELTON,D.C. SHELTON,D.C. SHELTON,D.C. SHELTON,D.C. SHELTON,D.C.	9812120028 9812120030 9812120192 8812120249 6812120251*	50-346 P 50-346 P 50-346 P 50-346 P	SKILERN,C.G. SKINNER,P.H. SKOLNICK,F. SKOLNICK,F. SKOW,M.E.	0812238107* 8812050282* 8812270077 8812270077 8812140166*	PROJ 60-269 Q 50-320 G 50-320 G 50-482 Q	SMITH,R.D. SMITH,R.D. SMITH,R.D. SMITH,R.D. SMITH,R.D.	8812220088* 8812220108 0812220114 8812220252 8812220253*	40-3453 40-8907 40-8905 40-8829 40-8829
SHELTON,D.C.	8812140010	50 246 P	SKROVE, J.W.	6812190347*	60-464 K	SMITH,R.D.	8812220254	40-8926
SHEMANSKI,P.C.	8612160101	50 373 P	SLAWINSKI, W.J	8811280088*	60-165 Q	SMITH,R.D.	8812220255*	40-8926
SHERBINI,S.	8812060307*	50 219 Q	SLY, C.D	8812020258	60-317 S	SMITH,R.D.	8812220282	40-8904
SHERON,B.W.	8812070201	ORG	SMEDLEY, R.W.	8811280479	60-255 P	SMITH,R.D.	8812220283*	40-8904
SHERON,B.W.	8812270287*	XPORTLIC	SMEDLEY, R.W.	8811300282	60-155 P	SMITH,R.E.	8811280531	50-244
SKETLERJA	8812050110	50-312 F	SMEDLEY, R.W.	0812050228	50-265 Q	SMITH,R.E.	8811290536*	50-244
SHEWSKI,W.J.	8811220055	50-10 P	SMEDLEY, R.W.	0812050231	50-255 P	SMITH,R.E.	8812010410	60-244
SHIER,W.	6812010086	NUREG	SMEDLEY, R.W.	0812060069	50-265 P	SMITH,R.E.	8812070218	60-244
SHIFFERJ.D	6812050183	50-275 K	SMEDLEY, R.W.	0812120076	50-255 P	SMITH,R.E.	8812070222*	50-244
SHIFFERJ.D	6811300077	50-275 F	SMITH, B.H.	0812060078	50-255 P	SMITH,R.E.	8812220017	50-244
SHIFFER,J.D.	8812050055	50-276 P	SMITH,B.K.	8811290564	60-331 S	SMITH,R.I.	8812080045*	COMMISSIO
SHIFFER,J.D.	8812050236	50-276 S	SMITH,B.K.	8812070250	60-331 S	SMITH,S.J.	8811290082	60-327
SHIFFER,J.D.	8812060094	50-276 Q	SMITH,B.K	8812230163	60-331 S	SMITH,S.J.	0811290110	50-327
SHIFFER,J.D.	8812060117	50-276 P	SMITH,C.N.	8812010196	70-1100	SMITH,S.J.	0812070207	50-327
SHIFFER,J.D.	8812070107	50-276 P	SMITH,C.N.	8812010201	70-1113	SMITH,S.J.	8012070223	50-328
SH.FFER.J.D. SHIFFER.J.D. SHIFFER.J.D. SHIFFER.J.D. SHIFFER.J.D.	6812070100* 6812090313 6812090334 6812130191 6612150248	50-275 P 50-323 P 50-275 F 60-275 Q 50-323 S	SMITH,C.N. SMITH,C.N. SMITH,C.N. SMITH,O. SMITH,O.	8812010203° 8812200310 8812220068 8812220215°	70-1113 70-36 70-1113 60-277 Q 50-269 Q	SMITH,S.J. SMITH,S.J. SMITH,S.J. SMITH,S.J. SMITH,S.J.	8812070228 8812070227 8812070230 0812140248 8012140248	50-328 50-327 60-328 60-328 60-327
SHIFFER, J.D.	8812150268	50 275 P	SMITH,D.M.	8811300462	50-277 S	SMITH,S.J.	8812140260	50-328
SHIFFER, J.D.	8812160008	50 275 S	SMITH,D.M.	8812010144	50-277 S	SMITH,S.J.	8812200061	60-328
SHIFFER, J.D.	8812160011	50 275 P	SMITH,D.M.	8812010157	50-277 S	SMITH,S.J.	8812200144	60-327
SHIFFER, J.D.	8812160014	50 275 P	SMITH,D.M.	8812120247	50-277 S	SMITH,S.J.	6812200151	60-328
SHIFFER, J.D.	8812180026	50 275 P	SMITH,D.M.	8812130084	50-277 O	SMITH,S.J.	6812210143	50-327
SHIFFER, J.D. SHIFFER, J.D. SHIFFER, J.D. SHIMSHAK, R.	8812190072 6812200096 6812270203 8812270205 8812140164*	50-275 P 50-275 S 50-323 Q 50-323 S 50-293 P	SMITH,D.M. SMITH,D.M. SMITH,D.M. SMITH,D.M. SMITH,F.H.	8812130125 8812150275 9812200121 9812210094 9812120161	50-277 Q 50-277 S 50-277 S 50-277 Q 50-416 P	SMITH,T.C. SMITH,W. SMITH,W.F. SMITH,W.G. SMYTH,C.W.	8812090220* 8812210322 8812210379 8811290300	COMMISSIO 50-315 50-382 50-315 50-302
SHINGOITEWA,L.	8611300360	PR	SMITH,G.C.	8612060200°	50-219 Q	SMYTH,C.W.	6612200174	60-289
SHIPLEY,L.E.	8812180409°	50-312 P	SMITH,G.C.	8812220401°	50-289 Q	SNEIDER,C.S.	5812190144	50-443
SHOEMAKEA,C.J.	8812020120	50-322 G	SMITH,I.W.	8812190014	50-443 Q	SNEIDER,C.S.	5812280001	50-443
SHOEMAKEA,C.J.	8812020127	50-443 G	SMITH,I.W.	8812270053	50-443 Q	SNELL,W.	6811300531*	50-346
SHOEMAKEA,C.J.	6812020134	50-322 G	SMITH,J.A.	8811290574	PT21	SNELL,W.	6812140239*	50-282
SHOEMAKER, C.J.	8812140080	50-322 G	BLATIMS	8812020019	60-443 G	SNELL,W.	8812190267*	50-456
SHOEMAKER, C.J.	8812140087	60-443 G	B.LATIMS	8812020019	60-443 G	SNELL,W.	8812200075*	50-341
SHORTRIDGE, R.B.	8812190053*	50-424 Q	B.LATIMS	8812020166	50-443 G	SNIFF,T.L.	8811290176*	WASTE RES
SHRIVER, T.D.	8811300281	50-528 S	B.LATIMS	6812020156	50-443 G	SODEN,B.	6812060029	60-295
SHRIVER, T.D.	8811300284	50-529 S	B.LATIMS	8812140126	50-443 G	SOHINKI,S.M.	8812290299*	FOIA
SHRIVER,T.D.	8812130041	50-321 Q	B.L,HTIM2	8812140126	50-443 G	SOLBERG,D.	8812080074	REVIEW GR
SHRIVER,T.D.	8012210144		B.L,HTIM2	8801030055*	50-443 G	SOLER,A.I.	8812200249°	50-428
SHUMAN,F.	8812050119*		B.L,HTIM2	8801030055*	50-443 G	SOONG,A.L.	8812150046°	70-27
SHYMLOCK,M	8812190305*		D.L,HTIM2	8812130046*	60-331 Q	SOONG,S.	8812220030	70-143
SHYMLOCK,M.	8812080118*		F.LHTIM2	8812090282*	60-341 Q	SOONG,S.	8812220034	70-143
SIACOR,E.R.	8012200162	50-361 R	SMITH,M J.	8812140239°	50-282 Q	SORENSEN,G.C.	8811300235	60-508
SIACOR,E.R.	8812200163	50-206 R	SMITH,P.S.	8812270141°	50-219 S	SORENSEN,G.C.	8812010001	60-397
SIEBER,J.D.	8811230291	50-412 P	SMITH,P.D.	8811230254	40-8971	SORENSEN,G.C.	8812020259	60-397
SIEBER,J.D.	8811300061	50-334 Q	SMITH,P.D.	8811230266°	40-8971	SORENSEN,G.C.	8812050016	PR
SIEBER,J.D.	8812010021	50-334 P	SMITH,P.D.	8811230299	40-8903	SORENSEN,G.C.	8812060084*	60-397
SIEBER, J.O.	8812010036	PR	SMITH,R.D.	8811230301*	40-6622	SORENSEN,G.C.	8812060288	50-397
SIEBER, J.O.	8812010248	50-334 P	SMITH,R.D.	8811230319		SORENSEN,G.C.	8812070045	50-397
SIEBER, J.O.	8812050045	50-334 Q	SMITH,R.D.	8811230324*		SORENSEN,G.C.	8812130130	50-397

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	PICHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC CATEGOR
SOMENSEN,G C SOMENSEN,G C SOMENSEN,G C SOMENSEN,G C SOMENSEN,G C	8812130138 8812160013 8812200185 8812210254 8812220353	50-397 F 50-397 P 50-397 P 50-397 P 50-397 O	STIMMEL, J.R. STODDART, P.G. STOLZ, J. STOLZ, J.F. STOLZ, J.F.	6312050166* 8812190258* 8811116039 8811290425 8812020151*	FBOJ 50 424 G 50 312 F 50 230 F 50 280 F	TA9OR,W F TA BBI,E	8812160115* 8812020308 8812180122 8812140050 8812190220	50-424 NUREG 50-367 50-322 50-322
SFAETH SPANO,A H SPAFKS,S.E. SPEAKMAN,FI J SPINRAD,B.I.	8812050295 8812210194 8812160156* 8812010421 8812010319	WASTE MGT ORG 50-250 O 50-334 H 50-116 P	STOLZ, J F STOLZ, J F, STOLZ, J F, STOLZ, J F, STOLZ, J F,	6812653239 8812080107* 8812089165* 88120890216* 8812140904	50-320 P 50-334 P 50-336 P 50-213 P 50-245 P	TALBOT,P. TALBOT,P TALBOT,P	R812140135* B812140146* B812280304 B812280142 B812280160*	60-443 50-443 50-443 50-443 50-443
SPITZBERG,D.B. SPITZER,D.J SREN AWSKI,D. SREN AWSKI,D.J. SREN'AWSKI,D.J.	8811300075 6612200027 6612200093 6611290370 6812090183*	1&E 50-454 F1 1&E 40-7604	STOLZ,JF, STOLZ,JF, STOLZ,JF, STOLZ,JF, STOLZ,JF,	6812193074* 6812160166 6812220202* 6812220272*	50-289 P 50-320 P 50-334 P 50-245 P 50-334 P	P TAMA. P TAMPS TAMPS	8612200280 8612200289 8612080100 8812100216 8812100204	REVIEW GI REVIEW GI 50-334 50-440
ST JOHN K.E. ST LAUGENT,N.N. STAB-EIN,K. STAFFORD,K.E STANLE,C.	8812020020 8812210411 8812080108 8811290574 8612060258	PR 50-29 S WASTE MGT PT21 50-24-1 P	STONE J.C. STONE J.C. STONE J.C. STONE J.C. STONE J.C.	8811300303 6812020018 6812060222 6812070055 8812080003	60 272 P 60 272 Q 60 272 P REVIEW GR P 50 311 Q	TAMP.S TAMP.S TANA.E.T	8812220268 8812220276* 8812220199 8812010396 8602250453*	50:334 50:334 50:334 WASTE MG 40:2253
STAHLE.C STAKERTR. STANGJ STANLEY,M A STANLEY,W S.	8812130180 8812020305* 8812270214 8812010207 8812010204	50-244 P 50-382 Q 50-341 P PR PR	STONE J.C. STORZ,L.F. STORZ,L.F. STORZ,L.F. STOIZ,J.C.	8812140195 8812140195 881215059 8812250272 8812140195	50-272 P 50-348 S 50-346 S 50-346 R 50-346 S	; TATUVJJ ; TATUVJ⊅E TAYLORJJH	8812220022 8812120003* 8812020200 8812200060	40-6377 50-397 60-205 TOPREP TOPREP
STARKEY,D. STARKEY,R D. STAUTER,J.C. STAUTER,J.C. STEFANO,J.J	8812190305* 8811280096* 8811230008 8812140221* 8811300273	50-321 Q 50-261 Q 40-8027 40-8027 60-263 P	STOVALL,W.D STRATFORD,R J. STRATFORD,R J STRAUSS,P.M. STRAUSS,P.M.	8812010237* 8812080160 8812190089 8812020051*	CONTRACT XPORTLIC XPORTLIC 50 443 G 50-443 G	TAYLOR,JH TAYLOR,JL. TAYLOR,JL. TAYLOR,JL TAYLOR,JL	8812210126 8812270014 6812270014 8912270024*	TOPREP 50-322 50-322 50-322 50-322
STEFANO.J.J STEFANO.J.J STEIGER.R.W. STEIGER.W.E. STEIGER.W.E.	8612140101 8812200048 8812060046 8811300012 8812090054	50-263 P 50-263 P 50-322 S 60-322 S 50-322 S	STROH,D. STROSN:DER,J.R. STROSNIDER,J.R. STROSNIDER,J.R. STROSNIDER,J.R.	8812060011 881120576* 8811300150* 8812120069* 8812200346*	50-456 S 50-293 O 50-220 O 50-333 O 60-285 O	TAYLORÎL A TAYLORÎL A TAYLORÎL A	8812210160 8812210278* 8812210281* 8812210057	60-409 50-313 50-313 50-368 50-483
STEIN,A. STEIN,R. STEIN,R. STEIN,R. STEIN,R.	8811280131 8811290089 8811200088 8811290113 8811300200	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT	STUDDS,G E STURZ,F.C. SUBUDHI,M. SUDNAK,P. SULLIVAN,J.L.	8812060016* 8812190130* 8812016096 8812050319 8012010187	COMM'SSION 50-271 G NUREG 50-469 F PR	TAYLOR,P.A TAYLOR,R G	8812210107 8812000165* 8811300160* 8812000288* 8812200176*	50-483 50-280 50-313 50-302 60-302
STE N.A. STE N.R. STE.N.R. STEIN R. STEIN R	8812090266 8812090300 8812090310 8812100234 8812220347	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT	SUMMER, J SUMMER, T. SUMMERS, J. SUMMERS, R. I. SUO-ANITILA, A.	0812200112 0812000102 6812060224 6812200141 8812010353	60-321 F 50-321 F PRM 50-334 S NUREG	TEMPLE, T.L TEMUS, C.J	8812270040* 8012120151* 8012050155 8812080127 8812270237	50-346 50-416 71-9080 71-9200 50-373
STEINHARDT, C.R. STEINHARDT, C.R. STEINHARDT, C.R. STEINHARDT, C.R. STELLO, V.	8811290038 8812010413 8812140040 8812220132 8611170087*	50-305 Q 50-305 H 60-305 P FOIA	SUTHERLAND, J.T., SUTPHIN, R.N., SWAILES, M.P., SWAILES, M.P., SWAILS, S.L.	0812120072* 0812270048* 0812050010* 0812180161* 0812020224	FOIA 50:346 O CONTRACT CONTRACT 50:331 F	TËRRY,C,D, TERRY,C.D.	8812160178 8811290460* 8811230288 8811230285 8811290185	50-445 50-298 50-410 50-220 50-220
STELLO,V. STELLO,V. STELLO,V. STELLO,V. STELLO,V.	8804120011 8811100295* 8811210016* 8811280026 8811290525	SECY PR 50-203 P SECY 50-341 P	SWARTZWELDER, J SWARTZWELDER, J. SWARTZWELDER, J. SWARTZWELDER, J. SWARTZWELDER, J.	6812120133 6811290292 6811290572 6811290575 6812010344	50-424 S 50-424 S 50-424 S 50-424 S 50-424 S	TERRY CD TERRY CD TERRY CD TERRY CD TERRY CD	8811290547 8811300464 8612020206 6812070141 8612180204	50-410 50-220 50-410 50-220 60-220
STELLO,V. STELLO,V. STELLO,V. STELLO,V. STELLO,V.	8811290541 8811300106 8811300162 8811300207* 8811300421	50-446 A 50-277 Q ORQ ORQ 60-275 U	SWARTZWELDER J. SWARTZWELDER J. SWARTZWELDER J. SWARTZWELDER J. SWARTZWELDER J.	8812020115 6812060273 8812140062 8812140120 8812200213	50-424 S 50-424 S 50-424 S 50-424 S 50-424 S		8812210332 6812210335* 681230269* 6812080028* 8811290454	50-410 50-410 70-1151 70-1151 70-27
STELLO,V. STELLO,V. STELLO,V. STELLO,V. STELLO,V.	8812010168* 8812020171 8812020231 8812080129 8812120162*	50-269 Q 50-293 F ORQ FOIA FOIA	SWARTZWELDER J. SWARTZWELDER J. SWARTZWELDER J. SWARTZWELDER J. SWARTZWELDER J.	6812200218 8812200236 8812200243 8812200259 8812220079	50-424 S 50-424 S 50-424 S 50-424 S 50-424 S	TETRAULT, R.E. TETRAULT, R.E. THADANI, M.C. THEOFANOUS, T.G. THOMAS, B.E.	8812060224 8812090082 8812120074 8812020179 8812150171	70-27 TOPREP 60-387 NUREG WASTE MG
STELLO,V. STELLO,V. STELLO,V. STELLO,V. STELLO,V.	8812140222* 8812140224* 8812210125 8812210306 8812270210	FOIA FOIA 50-803 A 50-443 H 50-259 P	SWARTZWELDER, J SWENSON, W.H. SWENSON, W.H. SWETLAND, P SWETLAND, P	8812220081 8811280206 8612050059 8812130310* 8812830165	50-424 S 60-286 P 60-266 P 50-247 Q 50-311 S	THOMAS,CO THOMAS,GS THOMAS,G,S	8614300293 8812220305 8811280135 8811300149 8811300289	50-461 PR 50-443 50-443 60-443
STELLO,V. STEPHENSON,J.D. STETKA,T. STETKA,T.F. STETKA,T.F.	8812270298* 8812070172 8812150073* 8811290477* 8812020308*	XPORTLIC 50-302 F 50-482 Q 50-362 G 50-313 Q	SWETLAND,P.D. SWETLAND,P.D. SWETLAND,P.D. SWETLAND,P.D. SWIFT,J.J.	8811290139* 8811290412* 8811300559 8812120175 8811300437	50-247 P 60-272 Q 50-247 F 50-272 P 50-603 I	THOMAS G.S THOMAS G.S THOMAS G.S	8812060100 8812060199 8812090155 8812120210 8812120213	60-443 50-443 50-443 50-443 60-443
STETKAT,F. STETKAT,F. STEVENS,J.A. STEVENS,J.A. STEVENS,J.A.	8812140077* 8812160124* 8811230289 8812070130 8812070181	50-285 Q 50-285 Q 60-461 P 50-461 P	SWIFT,J.J. SWIFT,J.J. SYLVESTER,E.D. SYLVESTER,E.D. SYLVIA,B R.	8812190126* 8812280178* 8812090200* 8812230032* 8604250252*	50-603 G 50-603 G 50-219 C 50-309 C 60-341 C	THOMAS,GS. THOMAS,GS. THOMAS,W.V.	8812140002 8812140172 8812060265 8812060261* 8812140150*	50-443 60-443 60-443 50-333 60-293
STEVENS,J.A. A.L. STEVENS,J.A. STEVENS,J.A. A.L. STEVENS,J.A. A.L. STEVENS,J.A.	8812070191 8612070215 8812070253 8612080008 8612080083	50-461 P 50-461 P 50-461 P 60-461 P 50-461 P	SYLVIA B R. SYLVIA B R. SYLVIA B R. SYLVIA B R. SYLVIA B R.	8811230336 8811300458 6812090208 8812090249 8812120100	50-341 F 50-341 P 50-341 P 50-341 F 50-341 F	THOMPSONDH THOMPSONH L. THOMPSONH L.	8811280046* 8811280057* 8811280104 8811280204 8812010309*	50-438 50-390 WASTE MC WASTE MC AEVIEW Q
STEWART, I.P. STEWART, M.A. STEWART, S.A.	8812210313* 8812070107* 8812200206	50-265 Q 60-499 Q 50-302 R	SYLVIA,B.A. SYLVIA,B.A. SZCZEPANIEC,A	8812130028 8812290366 8812090258*	50-341 Q 60-341 F 50-426 Q	THOMPSON,H.L.	8812010373 8812070184 8812200309	60-604 WASTE MO REVIEW GI

AUTHOR	NUMBER	CATEGORY	AUTTION	NUMBER	CATEGOR	٧	AOTAOA	NUMBER	CATEGORY
THOMPSON,N.G THUNSTEDT,J.W. TICHLER.J. TIERNAN,J.A. TIERNAN,J.A	8812140112* 8812200049 8812010047 8812010170 8612070099	CONTRACT 50-373 R NUAEG 50-317 H 50-317 P	TUCKEN,H B. TUCKEN,H B. TUCKEN,H B. TUCKEN,H.B. TUCKEN,H B.	8811290569 8811300145 8811300152 8811300228 0811300431	50-369 50-369 50-369 50-369 50-369	\$ Q P P S	VARGA,S A VARGA,S A VARGA,S A VARGA,S A VARGA,S.A	8603300034* 6011030125* 6811280100* 6812010250 6812020152	60-233 Q 50-22Q Q 60-281 P 50-219 Q 50-277 Q
TIERNAN, J.A. TIERNAN, J.A. TIELMAN, A. TING, P. TINGEN, S.	8812090106 8812210314 8812090140° 8812120035° 8812160115°	50:317 Q 50:317 P 50:425 Q 70:687 50:424 Q	TUCKER,H.B TUCKER,H.B TUCKER,H.B TUCKER,H.B. TUCKER,H.B.	6812010209 6812010351 6812010420 6812020026 6812020035	PR 50-413 PR 50-413 50-413	S P S	VARGA,S A VARGA,S A VARGA,S A VARGA,S A. VASSAR,W.T	8812020193 8812070100 8812220235* 8012270225 8812120174	50-353 O REVEW GR P 50-416 P 50-443 O 70-27
TIPPS, S.B. TIPPS, S.B. TIPTON, T.E. TOBIN, W. TOBIN, W. J.	8812010342 8812150081 8811290224 8812150105* 8811290510*	50-321 S 50-321 S REVIEW GR P 50-498 Q 50-220 Q	TUCKER,H 8 TUCKER,H.B TUCKER,H.B. TUCKER,H.B TUCKER,H.B.	8812020039 8812020043 6612020047 6612020063 9812020237	50-413 50-370 50-360 50-369 50-369	P S Q S	VASSELLO, J.V. VASSELLO, J.V. VAUGHAN, G.E. VAUGHN, G.E., VAUGHN, G.E.	8611230083 8811230084 8812220190 8812020087 8811300032	50 412 F 71-275 50-498 C 50 498 S 50-498 C
TOOD,G A TOOOROVICH,M.M. TOFEL,L.C. TOMLINSON,E. TOMPKINS,B.A.	8811230186* 8812190182* 8812080289* 8812190410 8812140089	70-143 50-322 G PR 50-410 R 50-322 G	TUCKER,H.B. TUCKER,H.B. TUCKER,H.B. TUCKER,H.B. TUCKER H.B.	8812020300 8812050032 8812050103 6812050125 6812050130	50-369 50-413 50-369 50-413 50-269	0 0 0 P F	VAUGHN,G E. VAUGHN,G.E VAUGHN,G E VAUGHN,G E VAUGHN,G E	8911300139 6811300154 6812050122 6812050345 8812120211	50 498 8 50 498 9 50 499 0 50 499 0
TOMPKINS,B.A. TOMPKINS,B.A TOMRE,J.G. TOMRE,J.G. TOMRE,J.G.	6812190069 6812270094 6812010351 6812070023 6812140256	50-322 G 50-322 G 50-413 S 50-413 S 50-414 S	TUCKER,H B TUCKER,H B TUCKER,H B. TUCKER,H B. TUCKER,H B	8812060018 8812080284 8812070012 8812070023 8812070025	50-268 50-369 50-269 50-413 50-369	0 8 9 8 9	VAUGHN,G E VAUGHN,G.E. VAUGHN,G E VAUGHN,G E. VAUGHN,G E	8812140251 8812150098 8812200021 8812210011 8812270262	50-465 6 50-463 6 50-468 0 50-490 5 50-490 5
TORRE, J.G. FOTH, A.D. TOURIGNY, E. TOURIGNY, E.G. TOURIGNY, E.G.	6812270305 6812200098* 6812280131* 6812200189 6812220257	50-413 S 50-344 Q 50-335 G 50-389 P 50-389 P	TUCKER,H B TUCKER,H B TUCKER,H B TUCKER,H B TUCKER,H.B.	8812070064 8812080119 8812090029 8812000247 8812120012	50-260 50-269 50-269 50-269 50-269	\$ F F	VAVRA,A VELASQUEZ,J R VELASQUEZ,J R. VELASQUEZ,J R. VELASQUEZ,J R	8612050326 8612050020 8612050023 6612050096 6612050097*	FO'A 40 8907 40 8907 40 8907 40-8907
TOURIGNY,E.G. TOWNSEND,J.D. TOWNSEND,J.D. TRAFICONTE,J. TRAFICONTE,J.	8812280131° 8811290426 8812190233 8812020110 8812140114	50-335 G 50-276 R 60-276 A 50-443 G 50-443 G	TUCKER,H.B. TUCKER,H.B. TUCKER,H.B. TUCKER,H.B. TUCKER,H.B.	8612120014* 8612120084 8612120112 8612120117 8612120118	60-269 50-369 50-369 50-260 50-269	P 0 0 0	VENNETSON,W.G. VERNETSON,W.G VERNETSON,W.G. VERNETSON,W.G. VERNETSON,W.G.	8611289076 6611200120 6612010025 6612070170 (612090149	50-63 5 50-03 5 50-03 F 50-03 F 50-03 F
TRAFICONTE, J. TRAFICONTE, J. TRAFICONTE, J. TRAFICONTE, J. TRAFICONTE, J.	8812270084 8812270099 8812280099 8812280115 6812280123	50 443 G 60 443 G 50 443 G 50 443 G 50 443 G	TUCKER,H.B TUCKER,H.B TUCKER,H.B. TUCKER,H.B. TUCKER,H.B.	8812130117 8812140200 8812140227 8812140233 8812140252	60-280 60-287 60-413 50-369 50-369	Y Q P S S	VERNETSON,W.G VERRELLI,D.M. VERRELLI,D.M. VERRELLI,D.M VERRELLI,D.M	8612140091 8811280081 8811280208 8811280209	60-63 5 60-261 6 60-261 6 60-324 6 50-416 6
TRAFICONTE, J. TRAFICONTE, J.M. TRAMMEUL, C.M. TRAMMELL, C.M. TRAMMELL, C.M. TRAMMELL, C.M.	8812280137 6812270067 8811230232 8811290149 8811290451	50-443 G 60-443 G 60-206 P 60-206 P 60-206 P	TUCKER,H B TUCKER,H B. TUCKER,H B. TUCKER,H B. TUCKER,H B.	8812140258 8812140270 8812160086 8812200023 8812200099	50-414 60-370 50-413 50-369 50-287	S P R Q	VERRELLI,D.M. VERRELLI,D.M. VERRELLI,D.M. VERRELLI,D.M. VERRELLI,D.M.	8812050259 8812050273 6812050274* 8812050288 8812080287	60 395 C 50-324 C 50-324 C 50-348 C 50-400 C
TRAMMELL,C.M. TRAMMELL,C.M. TRAMMELL,C.M. TRAMMELL,C.M. TRAMMELL,C.M. TRAMMELL,C.M.	6811290562 6812060073 6812060083 6812060096* 8812060110*	50-206 P 50-206 P 60-206 P 60-206 P 60-208 P	TUCKER,HB. TUCKER,HB TUCKER,HB. TUCKER,HB.	8012200212 8012200217 8012200318 8012210063 8012210114	50-269 50-413 50-414 50-269 60-269	П S P P	VERRELLI,D.M. VERRELLI,D.M. VERRELLI,D.M. VERRELLI,D.M. VIRGILIO,M.J.	8812160131 8812200281 8812210009 8812210016 8612180268	50-410 6 50-335 6 50-324 6 50-400 6 50-344 6
TRAMMELL,C.M. TRAMMELL,C.M. TRAMMELL,J.W. TRAMMELL,J.W. TRAMMELL,J.W.	8812160108 8812150125 8812020194 8812050070 8812050315	50-206 P 60-206 P 40-200 40-299 40-299	TUCKER,HB. TUCKER,HB. TUCKER,HB. TUCKER,HB. TUCKER,HB.	8812210328 8812220046 8812270207 8812270254 8812270261	50-269 50-269 50-369 50-269	0 8 0 8	VISSING.G.S. VISSING.G.S. VISSING.G.S. VISSING.G.S. VO.T.V.	8812050180 6812150245 8812220242 8812220286 8811180288	50-470 / 50-508 / 50-470 / 50-470 / 60-317 0
TRAMMELL J.W. TREBY,S.A. TREJO,J. TREVORS,G.A. TREVORS,G.A.	8812210350 8812010185 8811290465 6811300229 8811300483	40-299 PR 50-272 R 50-298 Q 50-298 Q	TUCKER,H.B. TUCKER,H.B. TUCKER,J.E. TUCKER,K. TUCKMAN,M.S.	8812270305 8812270307 8812190260 8812050056 8812050131*	50-413 50-413 50-321 PR 50-269	S P R F	VOGLER,O J. VOIGT,H.H. VOLZA,P. VOTAW,E.F. VRLA,M.P.	8812070246* 6812160137 6812060254 6812270284 6812060021	50-293 50-265 50-410 XPORTLIC 50-373
TREVORS,G.A. TREVORS,G.A. TREVORS,G.A. TREVORS,G.A. FREWORGY,J.D.	8811300488 8811300498 8812140049 8612160049 8812190349*	60-298 O 50-298 J 60-298 J 50-298 G 50-464 K	TUCKMAN,M.S TULEY,C.R. TULON,T. TURK,S.E. TURK,S.E.	8812050132* 8812150270* 8812060248 8812190064 8812190071	50-269 50-275 60-454 60-443 50-443	F P S G	WAGNER,K C. WAGNER,P.C. WAGNER,W. WAGONER,S.R. WAHLQUIST,K J.	8812190094 8812150124* 8812130245* 8812130302* 8812220341*	NUREG 50-285 50-275 50-336 50-336
TRIPP, L.E. TRIPP, L.E. TRIPP, L.M. TROTTIER, E.H. TROUT, J.P.	6812120032* 8812150011* 8811290422 8812020195 8812140028	50-309 O 50-334 O 1&E 50-293 P 50-443 G	TURK, S.E. TURK, S.E. TURK, S.E. TURNER, J.A. TURNER, S.E.	8812280158 8812280158 8812280160 8812010077 8812280088*	50-443 50-443 50-443 PR 60-335	G G T	WALKER,H.A. WALKER,R.D. WALKER,R.D. WALKER,R.D. WALKER,R.D.	8812270048* 8812060152 8812060158 8812060168 8812060168	50-346 50-445 60-445 50-445 50-445
TROUT, J.P. TROUT, J.P. TROUT, J.P. TROUT, J.P. TROUT, J.P. TROUT, J.P.	9812140028 8812140043 8812140057 8812140057 8812270079	60-443 G 60-443 G 50-443 G 50-443 G 50-443 G	TURNER,S.E. TURNER,S.E. TURNER,S.E. UDY,A.C. UDY,A.C.	8812280086* 8812280103* 8812280103* 8811210007* 8811220443*	60-335 50-335 50-336 50-458 50-628	T T P P	WALKER, R.D. WALKER, R.D. WALKER, R.D. WALL, K.C. WALL, N.G.A.	881220004Q 8012220016 8812220071 8812190255 8812140264	50-445 50-445 50-445 50-213 50-271
TROUT,J.P. TROUT,J.P. TROUT,J.P. TROUT,J.P. TROUT,J.P.	8812270079 8812270105 8812270105 8812280085 8812280085	50-443 G 50-443 G 50-443 G 50-443 G	UDY,A.C. UEMIYA,S. UEMIYA,S. USHER,J UTLEY,E.E.	8811220443* 8812130074* 8812130186* 8811210050 8812150052	50-528 XPORTLIC XPORTLIC 50-277 60-261	P Q Y	WALLIS, G.B. WALLIS, G.B. WALTER, W. WALTERS, X. WALTON, G.	8812020160 8012020164 8811300392 8812010080 8812220215*	NUREG NUREG 60-455 PA 50-258
TROUT, J.P. TROUT, J.P. TRZYNA, G.E. TRZYNA, G.E. TRZYNA, G.E.	8812260090 8812260090 8812010046 6812070061 6812220206	50-443 G 50-443 G 50-454 V 60-295 P 60-295 P	VAN KESSEL,H.F. VANDALE,M.T. VANDENBURGH,C. VANDERBEEK,R. VANDERBEEK,R.	8812220397* 8811230191 8812130051* 8811170247* 8811170247*	71-6601 50-254 50-397	Q Q P	WALTON,G.A. WAMBACH,T.V. WAMBACH,T.V. WAMBACH,T.V. WANG,A.B.	8812190005* 8811290505 8812050061* 8812160107 8812090214	50-390 50-255 50-266 50-265 50-213
TRZYNA,G.E. TUCKEA,H.B. TUCKER,H.B.	8812270051 6811290197 6811290264	50-295 Q 50-269 P 50-369 Q	VANDERNEIT, C.L. VANDOORN, K. VARGA, S.A.	8811290314' 8812160170' 8705290224'	50-369	QQP	WANG,A.B. WANG,C-H. WANG,ER,M.E.	8812130273 8812010060 8812230125	50-213 NUREG 71-3006
		•							

	NUMBER	CATEGORY		NUMBER	CATEGORY	7,07.1.0	NUMBER	CATEGOR
AARDIK D.	8812020208*	50-263 Q	WICHERS,DL	8812060210	40-8684	WILSON, J H	8811230210	50-445
AAREMBOURG,D.W.	8811290266	50-267 S	WIDELL,R.C.	8811280062	50-332 S	WILSON, K. R	8812010007	50-302
AAREMBOURG,D.W.	8812230276	50-267 P	WIDELL,R.C	8811260157	50-302 S	WILSON, K. R	8811290333	50-302
AARLAND,HM	8812200111*	71-454	WIDELL,R.C	8811290101	50-302 Q	WILSON, K. R	8812010153	50-302
AARLAND,HM	8812200125*	71-454	WIDELL,R.C	8811300157	50-302 P	WILSON, K. R	8812090041	50-302
#ARNICK,RF.	8811230216	50-445 Q	WIDELL,R.C.	8812050182	50-302 S	WILSON, R.F.	8811280111	50-210
#ARNICK,RF.	8811300294	50-445 Q	WIDELL,R.C	8812150978	50-302 O	WILSON, R.F.	8812210240	50-219
#ARNICK,RF.	8811300368	50-445 Q	WIDELL,R.C	8812189371	50-302 S	WING J.	8812280131*	50-335
#ARNICK,RF.	6812050322	50-445 Q	WIDELL,R.C	8812189381	50-302 S	WING J.	8812280131*	60-335
#ARNICK,RF.	6812060278	50-445 Q	WIDELL,R.C.	8812200206	50-302 R	WINGER	8812140267	50-334
*ARNICK,RF,	8812090257	50-445 Q	WIDELL,R.C.	8812210179	50:302 Q	WINSLOW,T.P.	6812200247	70-1113
ARNICK,RF,	8812200003	50-445 Q	WIDMANN,R.	8811390118	40:8027	WINSLOW,T.P.	6812200262	70-1113
ARNICK,RF,	8812200007	50-445 Q	WIEBE,J.S	8811230219	50:445 Q	WINSLOW,T.P.	6812210002	70-1113
ARREN,LA	8812200104	60-280 R	WIEBE,J.S	8812200011	50:445 Q	WINSLOW,T.P.	8812210303	70-1113
ARREN,M	8812010076	PR	WIEDEMAN,D	8812140076	18E	WISE,R.	6812050196	60-298
AASHINGTON,S.L.	8812080124	60-397 S	WIEDEMAN,D	8812200147	IBE	WISEMAN,G.	8812050255*	50-424
BAS-LIK,J.S	6811300125	50-346 F	WIEDEMAN,D G.	8812140155*	REVIEW GR P	WISSINK,R.G.	8812010320*	REVIEW GR
BATSON,L.	6812080170°	50-327 Q	WIEGAND,C	8812060010	50-457 S	WISSINK,R.G.	8812140145*	REVIEW GR
BATSON,L.	6812080190°	50-327 Q	WIESEMANN,FI A.	8811300582*	50-483 P	WITHERS,D.D.	8810280324*	50-482
BATSON,L.	8612210053°	60-327 Q	WIESEMANN,FI A.	8812090283*	50-266 P	WITHERS,B.D.	8812050043	50-482
AATSON,U.	8812210102* 8811300410 8811300508 8812010218 8812050191	50-327 Q	WIESEMANN,R A.	8812150269*	50-276 P	WITHERS,B.D.	8812050153	50-482
BATSON,PLA		50-400 Q	WIESEMANN,R A.	8812160016*	50-276 P	WITHERS,B.D.	8812050179	50-482
BATSON,PLA		50-400 F	WIESEMANN,R A.	8812160027*	50-276 P	WITHERS,B.D.	8812050258	50-402
BATSON,PLA		50-400 S	WIESEMANN,R A.	8812216031*	60-498 P	WITHERS,B.D.	8812090185	50-482
BATSON,PLA		50-400 Q	WIESEMANN,R A.	8812220037	TOPNEP	WITHERS,B.D.	8812130272	60-482
HATSON, RA	8812050195	50-400 Q	WIESEMANN,R A.	8812220211* 68122000217* 6812230015 6812020005*	50-205 P	WITHERS, B.D.	8812140260	50-482
HATSON, RA	8812050217	50-400 S	WIESS,H J		COMMISS.D.N	WITHERS, B.D.	8812200208	50-482
HATSON, RA	8812050254	50-400 R	WIGGIN,J.T.		50-322 Q	WITHERS, B.D.	8812200349	50-482
HATSON, RA	8812200117	50-400 R	WIGGINGTON,D L.		50-302 P	WITHERS, B.D.	8812210119	50-482
HATSON, RA	8812270134	50-400 Q	WIGGINS,E J.		CONTRACT	WITHERS, B.D.	8812210401	50-482
MATTERSJP. MAY,S C. MECHSELBERGER MEHRY, A R. WEGAND,G J	8812220117 8812010069 8812010252* 8812210008 8812010067	70-1201 NUREG 60-219 Q 50-387 S 50-271 H	WIGGINS,E.J. WIGGINS,E.J. WIGGINS,J.T. WIGGINS,J.T. WIGGINS,J.T.	8812050010* 8812270280* 8812120031 8812120021	CONTRACT CONTRACT 50-387 O 50-309 O 50-203 R	WITTEN, A.J. WOJCIK, J.T. WOLFE, S.J. WOLFORO, A. WONG, C.C.	8812020168 8812210379 8812190048 8812010343 8812100322	NUREG 50-315 60-443 NUREG NUREG
AEMHOLD,E D	8812270028	50-443 G	WIGGINS,J.T	8812140191	50 443 O	WONG, H.	8811300262	50-255
MEINXAM E.J.	8812280116*	50-335 T	WIGGINS,J.T.	8812150096	50 334 O	WOOD, C. L.	8812090209	50-213
MEINXAM,E J.	8812280124*	50-335 T	WIGGINS,J.T.	8812200110	50 322 O	WOOD, R.	8812210075	40-4492
MEISS, B.	8812130220*	FOIA	WIGGINS,J.T.	8812220331	50 271 O	WOODARD, C. H.	8811300312*	50-387
MELDIN,R O.	8812120218	WASTE RES	WIGGINS,J.T.	8812270228	50 20 O	WOODLAN, D. R.	8811230007	50-445
WELLS, A.H.	6812130058	71-8010	WIGGINTON,D.L	8812220065	50-392 P	WOODLAN, D.R.	6811230044	60-445
WENZINGER, E.C.	6811290134	60-247 P	WIGGINTON,D.L	8B12220082	50-382 P	WOODLAN, D.R.	6812020107	PR
WENZINGER, E.C.	6811290404	60-272 Q	WILGUS,W.S	8B12010239	PR	WOODLAN, D.R.	6812130271	50-445
WENZINGER, E.C.	6812130018	50-352 Q	WILGUS,W.S	8B12020068	50-302 P	WOODLAN, D.R.	8812150055	50-445
WENZINGER, E.C.	8812130309	60-247 Q	WILGUS,W.S.	B812020268	50-302 P	WOODLAN, D.R.	6612200030	60-445
MENZINGERIEC. MESCOTT RIG MESSMANIR H. MESSMANIR H. MESSMANIR H.	8812270273 8812220119* 8812130158* 8812130251*	50-286 Q 60-327 Q 60-244 Q 50-20 P 60-29 P	WILKINSON, B.W. WILKINSON, B.W. WILKINSON, B.W. WILKINSON, B.E WILL, D.J.	8012120077 8812190141 8812220198 8812050268 8812010070	50-2 P 60-294 F 60-204 P 60-294 P	WOODLAN,O.R. WOODLAN,D.R. WOODWARD,B. WOODWARD,W.C. WREATHALL,J.	6812200063 8812220011 8812270211 8811280124 8812010343	60-445 60-445 60-285 50-285 NUREG
WESTBERGRA. WESTBERGRA. WESTERMAN,T.F. WESTERMAN,T.F. WESTERMEIER,J.	8812120087* 6812200100* 6811300563* 8812150040 8812090344	60-341 Q 60-316 Q 50-267 Q 50-287 S 50-490 A	WILLAFID, S.C. WILLIAMS, C.C. WILLIAMS, J.H. WILLIAMS, J.H. WILLIAMS, J.H.	6812210051 8812120089* 8812060019* 8812136921* 8812239141*	50-259 S 50-445 Q 50-170 Q 50-352 Q 60-277 Q	WRIGHT,E.S. WRIGHT,G.C. WRIGHT,G.C. WRIGHT,G.C. WRIGHT,G.C.	8602250458* 8811280075 8811300506 8811300512* 8811300513	40-2253 50-151 50-282 50-282 50-186
WESTERMEIR J. WESTERMEIR J. WESTERMEIR J. WESTERMEIR J. WESTERMEIR J. WETZEL BA	8812130236	60-499 A	WIELIAMS, J.L.	8812130083*	60-315 P	WAIGHT,G.C.	6811300553	60-346
	8812130236	60-499 O	WILLIAMS, K.A.	8812020179	NUREG	WAIGHT,G.C	6811300555*	60-346
	8812130287	50-499 Q	WILLIAMS, M.G.	8811300483	60 482 S	WAIGHT,G.C.	8812070059	50-123
	8812200260	50-499 A	WILLIAMS, M.G.	8812090185	60 482 S	WAIGHT,G.C.	8812060160	50-409
	9812130005*	50-315 Q	WILLIAMS, M.G.	8812130272	60 482 S	WAIGHT,G.C.	8812120196	50-263
WHALEY,P.M. WHITAKER,W.E. WHITE J. WHITE,P.	8812070170 8811290578 8812160064 8812270195 8012190256	50-83 R 40-8801 I&E I&E 50-311 FI	WILLIAMS,M.G. WILLIAMS,M.G. WILLIAMS,O.G. WILLIAMS,R.A. WILLIAMS,R.A	8812140280 8812200203 8812190210 8812200146* 6812200277*	50-482 S 50-482 R FOIA 60-369 R 60-413 FI	WR:GHT,G C. WRIGHT,G.C. WRIGHT,G C. WRIGHT,G.C. WRIGHT,G.C.	8812130002 8812140053 8812160062 8812160067 8612190336	60-316 50-456 50-346 50-346 60-316
WHITE P.	8812190271	50-272 R	WILLIAMS,R.A.	8812200297* 8812010393 8812190246 8811300497 8812010064	50-269 R	WR:GHT,G C.	8812210378	50-255
WHITE S.A	8811230101	50-390 A	WILLIAMS,R.O.		50-267 H	WRIGHT,L.	8812210270	40-8907
WHITEHEAD G.G.	8812010405	50-390 H	WILLIAMS,R.O.		50-267 P	WRIGHT,R.E.	8811180299	50-213
WHITENERH	8812090327°	50-425 D	WILLIS,J.L.		50-410 S	WRIGHT,R E.	8811180312	50-247
WHITING AR	8812060264°	WASTE MGT	WILLIS,J.L.		50-410 S	WRIGHT,R E.	8811180354	50-423
WHITHOLAR, WHITHOLAR, WHITHOLAR, WHITHOLAR, WHITTEMORE,W.L.	8812060268* 8812060275* 8812090326 8812130194* 8811280176*	WASTE MGT WASTE MGT WASTE MGT WASTE MGT 50-163	MILLIS,J.L. WILLIS,J.L. WILLIS,J.L. WILLIS,J.L.	8812010139 8812010183 8812060234 8812060254 8812060318	50-220 S 50-410 S 50-410 S 50-410 S 50-410 S	WU,S.L. WULFF,W. YANICHKO,S.E. YBARRONDA,L.J. YORK,J.	8811300238 6812010333 6812070182* 6812160300* 6812220216*	TOPREP NUREG 50-338 CONTRACT 60-269
WHITTERADD. WHITTERADD. WHITTERADD. WHITTERADD. WHITTERADD.	8811290208 8811290220 8811300185 8812050034 8812130091	50-309 Q 50-309 Q 50-309 P PR 60-309 S	MILLIS,J.L. WILLIS,J.L. WILLIS,J.L. WILLIS,J.L.	6812060318 8812140243 8812190410 8812210110 8812210123	60-220 S 60-410 S 60-410 R 50-220 S 50-220 S	YOSHIDA,D.K. YOUNG,A.P. YOUNG,F. YOUNG,K.A. YOUNG,M.A.	6812190031* 6812020004* 8812050158 6812200196 6812020079	50-354 50-293 60-387 60-387 50-322
WHITTIERGD.	8812130121	50-309 P	WILNER,S.M.	8912210113	40-8724	YOUNG,M A.	8812140041	60-322
WHITTIERGD.	8812150012	50-309 P	WILNER,S.M.	8812210344	40-8724	YOUNG,M A.	8812190013	60-322
WHITTLETON,T.R.	8812140096*	CONTRACT	WILSON,B.A.	8811230033	50-302 Q	YOUNG,M A.	8812190024	50-322
WCHERS,D.L.	8811280037	40-8684	WILSON,B.A.	8812050320	50-335 Q	YOUNG,M A.	6812280129	60-326
WCHERS,D.L.	8812050002	40-8502	WILSON,B.A.	8812090288	50-302 Q	YUHAS,G.P.	8811290025	60-206
WICHERS,O.L.	8812050005	40-8502	WILSON,B.A.	8812090291°	50-302 Q	YUHAS,G P.	8811300422	50-206
WICHERS,O.L.	8812050136	40-8502	WILSON,B.A.	8812090319	60-335 Q	YUHAS,G.P.	8812010285	70-734
WICHERS,O.L.	8812060161	40-8502	WILSON,B.A.	8812200171	50-302 Q	YUHAS,G.P.	6812060287	50-397

AUTHOR	ACCESSION NUMBER	CATEGO		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCES NUM
YUHAS,G P. YUHAS,G P.	8812190413 8812190414*	50-528 50-528	Q Q	ZECH L ZECH L	8812020012 8812050044	50-293 F 50-293 F	ZECH,L.W. ZECH,L.W.	8812090 8812140
YUHAS,G.P. ZACCARIA,A.	8812210070 8812020064	50-397 PA	Ō	ZECH L W ZECH L W	8811140247 8811170122	COMMISSION 50-341 U	ZECH,L W. ZEILER.J.	8812270 8812090
ZACHOW,W.C.	8812660138*	FO:A		ZECH, L.W.	8811230077	50-293 F	ZEILER,J.	8812090
ZAHNLEUTER,A.H ZAHNLEUTER,A.J	86122700241 8612020046	50-32 <i>2</i> 50-32 <i>2</i>	G	ZECH,L W. ZECH,L W.	8811300078 8811300081	50-322 U 50-322 U	ZIGROSSI,N A.	8812220
ZAHNLEUTER,R J. ZAHNLEUTER,R J.	8812020104 8812020113*	50-322 50-322	G G	ZECH, L.W. ZECH, L.W.	8811300288 8812070236	50-3 COMMISSION	ZIMMER,A. ZIMMERMAN.A.P.	8812210 8812070
ZARNLEUTER,R J	8812140058	50-322	G	ZECH, L.W.	8812070241	50-293 H	ZIMMERMAN,R.P. ZIMMERMAN,R.P.	8812190 8812190
ZAHNLEUTER,A.J. ZAHNLEUTER,A.J.	8812140068' 8812140139	50-322 50-322	0 6	ZECH, L. W.	8812070259 8812080011	50-348 U 50-293 H		
ZAHNLEUTER,R.J.	8812190156 8812190179*	50-322 50-322	G	ZECH, L.W.	8812080040 8812080048	COMMISSION 50-277 H	ZIMMERMAN,R.P. ZIMMERMAN,R.P.	8912200 8812210
ZAHNLEUTER,A.J	8812270014	50-322	G	ZECH, L. W.	8812080052	COMMISSION	ZIMMERMAN,S. ZIMMERMAN,S.	8812120 8812120
ZECH G ZECH L.	88121302141 8812020002	FOIA 50-293	U	ZECH,L W. ZECH,L W.	8812080055 8812090178	COMMISSION COMMISSION	ZIMMERMAN,S.	8812120

CORPORATE SOURCE INDEX

he subject category column in this index gives the locket number and the symbol for the category of nformation within that docket; for example, 50-232 P. he docket subject categories are defined in Appenlix A.

Subject categories for nondocketed items are also intered in this column by symbol; for example, sCRS.

These categories are defined in Appendix B listed in the Contents. An asterisk following the cession number in this index indicates that the doment is an enclosure to another document, obtain the accession number of the principal doment under which the enclosure is listed, refer to index entitled "Cross Reference of Enclosures Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR
W Far East, Lld LWR Ublity Steering Committee	8812200221 8812160121 8812200046 8811290147	REVIEW GR PROJ PROJ TOPREP	P		8811280183 8811290182 8811290503 8811300119* 8811300119*	50-313 50-313 50-313 50-313 50-313
	8811300417* 8812120145* 8812120147* 8812130302* 8812210209	XPORTLIC 50-418 50-416 50-336 70-1257	Р Р Р		8811300429 8811300435 8811300435 8812010012* 8812010165	50 313 50 313 50 313 50 313 50 313
catama Power Co	8812220094 8012220341* 6812230068 8811290103 8812020241	70-1257 50-336 70-1257 50-348 50-348	Р Р Q		8812130043 8812190240 8812190247 8812190295 8812200211	50-313 50-368 60-313 60-368 60-368
	8612020241 8812060115 6812120050 8812120227 8812130055	60-348 50-348 50-348 50-348 60-384	Q F H F S		8812200252 8812210043 8812210085 8912210088* 8812210160	50-313 50-313 50-313 50-313 60-313
	8812130263 8812160138 6812160139* 6812190266 8812190275	50-348 50-364 50-364 50-348 50-364	S Q R R		6812210184 6812210187 8812210193* 8812210211 8812210278*	50-366 50-313 50-313 60-313 60-313
	6812190292 6812190299* 6812200033 6612200033 6812210033	50-364 50-364 50-348 50-348 50-348	Р Р Р	Armod Forces Radiobiological Rosearch	8812210281* 6812220243 6812230177 8812090007	50-368 50-313 50-368 50-170
	8812210033 8812210038* 8812220258 8812220268	50-348 50-348 50-348 50-364 50-348	ր բ Տ	Army, Dopt of	8812090008* 8812090009* 8812090010* 8812090011* 8802250453*	60-170 60-170 60-170 60-170 40-2253
Al Chernical Isotopa Enrichment, Inc. Litance Moring & Storage, Inc. Litar Resources, Inc. American College of Nuclear Physicians American Electric Power Service Corp.	8812010373 8812160161* 8812210106 8812020001 8812090060*	50-604 CONTRACT 40-8926 PR 50-316	A P	Army, Dopy. of, Materials Technology Loboratory Atlantic Richfield Co. (ARCO)	8812220022 8602260469* 8812060076* 8812060081*	40-6377 40-2263 FOIA FOIA
American Nuclear Corp. American Nuclear Energy Council American Osteopall Nic College of Radiolog	8812130083* 8812050318 6812210162 8812010272 8612010325	50-315 40-4492 40-4492 PR PR	Р		8812060099* 8812060123* 6812060132* 6812060138*	FOIA FOIA FOIA FOIA FOIA
Amersham Corp. Amesbury, MA Anaconca Co (div. of Atlantic Richfield	8811300002 8811300003 8812120036 8812270097 8812020174	71-9187 71-9165 PR 50-443 40-8902	G		8812060146* 8812060153* 8812060155* 8812060159* 8812060164*	FO:A FOIA FOIA FOIA FOIA
Co } Argonne National Eaboratory	8812010073 8812190120 8812190153	NUREG NUREG NUREG			6812060178* 8812060180* 6812060189* 8812060192*	FOIA FOIA FOIA FOIA
Arizona Nuclear Power Project (formerly	8811290358	50-528	S		8812060200*	FOIA
Arzona Public Service Co)	8811300281 8811300284 8812070015 8812070015	50-528 50-529 50-528 50-528	S 5 J J		8812060203* 8812060205* 8812060215* 8812060220* 6812080226*	FOIA FOIA FOIA FOIA FOIA
	8812070016 8812130041 8812130306 6812190278 8812190278	50-528 50-528 50-528 50-528 50-528	J 88 88 88	At'as Corp.	8812060228* 8812060233* 8812060245* 8812210165 8811280086	FOIA FOIA FOIA 40-8902 40-3453
Arkansas Power & Light Co.	8812190278 8812210144 8811280021	50-528 50-529 50-313	A S O	Atomic Energy of Canada, Ltd.	8812060004 8812200125* 66122702 9 8*	40-3453 71-454 XPORTLIC

		9747E001			NUMBER	CATEGOR
Automated Sciences Group, Inc 8&W Fuel Co. BP International Ltd. 8WA Owners Group	8812090164* 8912220117 8811290337 8812150086 8812210236	COMMISSIO 70-1201 40-7604 TOPREP TOPREP	N	Brewster, MA Brookhaven National Laboratory	8812050047* 8811180327 6811180341 8811180348 8811210050	50-293 50-286 50-352 50-245 50-277
Babcock & Wi'cox Co,	8811290454 8811300195 8812020200 8812060224 8812070255	70-27 70-824 TOPREP 70-27 70-364			8811210080 8812010047 8812010086 8812010333 8812050240	50-322 NUREG NUREG NUREG WASTE RES
	8812090082 8812090086° 8812120174 6812140212 8812150209	TOPREP TOPREP 70-27 70-27 70-364			8812050244* 8812050308 8812060014* 8812220311 8812220316	WASTE RES WASTE RES WASTE RES WASTE RES WASTE RES
	8812200080 8812200320 8812200322 6812210128 8812220076	TOPREP 70-27 70-27 TOPREP 70-27		Brown Boveri Corp (subs of Brown Bover & Co., Ltd.) Burroughs Corp	8812220329 8811300526 7905030213*	WASTE RES 50:352 FO!A
Babcock & Wilcox Operating Plants Owners	8812220078 8811280038	70-27 TOPREP		C-E Operating Plants Owners Group	8005070350° 8812050271°	FOIA TOPREP
Group	8811280940* 6811290300	TOPREP 50 302	Р	CACLInc. Federal CER Corp CRC Systems, Inc CYGNA Energy Sorvices	8812090228* 8812140201* 8812210140* 8812190409*	COMMISSIO WASTE MGT CONTRACT 50-312
Backus, Meyer & Solomon	8612050284* 8612210130* 8812020060 8812270093 6812280024	TOPREP TOPREP 50-443 50-443 50-443	G G	California, State of California, Univ. of, Berkoley, CA	8812130255* 8812010060 8812020135 8812020141* 8812200137	STATE PRO NUREG 50-224 50-224 50-224
Baltimore Gas & Electric Co.	8812010170 8812020258 8812060131 8812060136 8812060141	60-317 50-317 50-317 50-317 50-317	H S F F F	California, Univ. of, Los Angoles, CA California, Univ. of, Santa Barbara, CA Carolina Power & Light Co.	8812220002 8812220003* 8812020179 8811230004 8811230004	50-142 50-142 NUREG 60-324 50-324
	8612060143 6612060143 6612060213 6612060213 8812060216*	50.317 50.317 60.317 60.317 50.317	ዩ የ የ		8811230294 6811230294 8811280070 8811280031 8811200523	50-324 50-324 50-261 50-325 50-400
	8812060218* 8612070099 8612070099 8612090196 8812090196	60:317 60:317 60:317 60:317 50:317	P P Q Q		8811300042 8811300173 8811300410 8811300508 8811300521*	50-261 50-261 50-400 50-400 50-400
	8812120156 8812120160 8812120160 8812120245 8812120245	50-317 60-317 60-317 60-317 60-317	F F P		8612010218 8812010227 8812020236 6812050101 8612050105	50-400 PH 60-261 50-400 50-400
	8812120246* 8812120248* 8812120258 6812200201 6812210314	50-317 60-317 50-317 50-317 50-317	P S R P		8812050217 8812050219 8812050225 8812050254 8812050263	50-400 50-325 50-324 50-400 50-261
	8812210314 8812210315* 6812210315* 8812220138 8812270065	50-317 60-317 50-317 50-317 50-317	P P S Q		8812050264* 8812060167 8812060157 8812060242 8812060293	50-261 50-324 50-324 50-325 50-261
Battelle Memoriel Institute, Columbus Laboratorios Battelle Memoriel Institute, Pacific Northwest Laboratory	8812270226 8812010221* 6811180288	60-317 CONTRACT 60-317	s Q		8812090112 8812090112 8812130017 8812130089 8812130137	50-324 50-324 60-325 50-261
	8812010343 8812020308 8812060231 8812080045* 8812190163	NUREG NUREG WASTE RES COMMISSIO WASTE RES	N		8812130181 8812130288 8812140247 8812140247 8812140262	50-324 50-324 50-261 50-324 50-324 50-261
Bear Creek Uranium Co. Bechtel Group, Inc. Bechtel Power Corp.	8812220048 8812200308 8812210354 8812160124* 8812020064	WASTE RES 40-8452 40-8452 PROJ PR			8812150052 8812150089 8812160007 88121600114 8812190207	50-261 50-261 50-261 50-261 60-261 60-324
Bensinger, DuPont & Associates, Inc. Berkeley, CA Bishop, Cook, Purcell & Reynolds	8812010152 8812020135 8812020141* 8812010200 8812010322	PA 50-224 50-224 PA PAM	G G		8812180407 8812200117 8812200146 8812200340	50-324 50-400 50-261 50-261
Boston Business Journal Boston Edison Co.	8812190154 8811300518 8811300522* 8812070174 8812120092	40-2253 60-293 60-293 60-293 50-293	P P O P		8812210090 8812210097 8812210103 8812210111	50-325 50-325 50-325 50-324
Braunkohle Transport USA, Inc Brazil, Govt. of	8812190164 8812190224 6812190084 6812200328	50-293 50-293 XPORTLIC REVIEW GR	F R P		8812210131 8812210385 8812210409 8812270134 8812270199	50-324 50-325 50-324 50-400 50-324

ter for Nuclear Responsibility for for Nuclear Waste Regulatory	8812270119	50-77 50-250 WASTE MGT	G	8811300037 50.2 8811300037 50.2 8911300190 50.4	54 U 54 S
r, ses	8811290154 8811290178* 8812060262	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT		8811300392 50.4 8811300427 50.3 8811300444 50.4 8811300444 60.4 8811300445 60.2	74 S 54 Q 54 Q 37 P
	8612060268* 8812060275* 8812090325 8612120109 8812130085	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT		8811300450 50.2 8811300453' 50.2 8811300463' 50.2 8812010046 53.4 8812010046 50.4	37 P 37 P 54 V 54 V
	8812130194* 8812130201* 8812150258* 8812150263* 8812190226	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT		8812010121 50-4 8812010121 50-4 8812010129 50-3 8812010151 50-4 8812010228 50-3	54 P 237 P 237 S 154 P
atham, MA em-≜aclear Systems, Inc.	8812020004* 8812010381 8812080056 8812080060* 8812210113	50-293 71-9105 TOPREP TOPREP 40-8724	U	8812010228 50- 8812010305 50- 8812010305 50- 8812010305 50- 8812010306 50-	237 P 237 P 237 P 237 P
erneton Corp. Ibchem, Inc Izens lo <u>r</u> Feir Ulfuly Regulation	8812210344 8812200321 8812220100* 8812270149 8811220208*	40-8724 50-54 70-887 50-445 50-440	P G S	8812050324 50-	456 FI 456 FI 456 P 456 P
พื่อไรกซ์ Electric ไม่เกาหลัting Co	8811230277 8811290060 6811290107 8811300255 8812010268	50-440 50-440 50-440 50-440 50-440	о о я о н	8812060011 50 8812060021 50 8812060029 50	457 S 456 S 373 S 295 S 237 S
	8812010266 8812050013 8812050060 8812050067* 8812050169	50-440 50-440 50-440 50-440 60-440	ዝ የ 8 8	83 12060246 50 88 12080282 50 88 12080282 60	457 S 454 S 456 O 456 Q 254 P
	8612050170* 8812050292 8812060049 8812060249	50-440 50-440 50-440 50-440 50-440	P F R Q	8812070034' 50 8812070034' 50 8812070040 50	-254 P -254 P -254 P -373 P -373 P
	8812060280 8812200062 8812200187 8812270057	50-440 50-440 50-440 50-440 50-440	SORSS	9812070042* 56 9812070052 56 8812070057 66	-373 P -373 P -295 S -466 P
Heveland-Cliffs, Inc. Columbia Univ., New York, NY Combustion Engineering, Inc.	8812210279 8812210279 8812290273* 8811230185 8811290458 8811300425	40-8714 FOIA 71-6076 70-1100 71-6078	-	8812070214 5 8812070229 5 8812070231* 5	0:373 S 0:373 S 0:374 P 0:374 P 0:454 P
	8811300436* 8811300491 6812020261 8812020264*	71-6078 60-470 70-1100 70-1100 70-36	٨	8812090206	D-454 P D-454 R D-454 R D-454 R D-454 R
	8812060247 8812080237 8812080258 8812150015 8812150110*	70-38 70-1100 50-470 50-309 50-309	A P P	8812090231' 5 8812090286 5 8812090286	0.454 R 0.454 R 0.454 P 0.454 P 0.456 S
	8812150113* 8812160124* 8812200082 8812200181 8812210027	PROJ 70-1100 50-470 50-470 70-1100	A E	8812120020 8812120021 8812120021 8812120026	60-254 P 60-254 P 60-254 P 60-254 P 60-254 P
CommCore, Inc. Committee to Bridge the Gap	8812220040 8812220084 8812270168 8812270280 8812090173 8812130203	70-36 TOPREP CONTRACT FOIA FOIA		8812140063 8812140141 8812180085	50-295 S 50-304 Q 50-456 P 50-304 S 50-254 F
Conmonwealth Edison Co.	8812130208* 8810050121 8811220055 8811230025		Q P P S	8812150131* 8812150217 8812150250 8812160058 8812180124*	60.254 F 50.456 R 60.237 S 60.237 P PROJ
	8811280188 8811290014 8811290014 6811290081 8811290091	50-254 50-254 50-254 50-456 50-304 50-254	Q Q P \$ P	8812190194 8812190190 8812190196 8812190196 8812190196	60-973 F 60-454 K 50-454 K 50-454 K 50-454 K
	8811290129 8811290129 8811290131 8811290131 8811290153	50-254 60-254 50-254	Р Р С	8812190196 8812190216' 8812190216' 8812190216'	50.454 K 50.454 K 50.454 K 60-454 K

	NOWAEH	CATEGORY		NUMBER	CATEGO
86 88 80 86		50-454 50-454 50-454 50-454 50-454	к к к к к	8812190383* 8812190388 8812190389* 8812190389*	50-454 50-254 50-254 50-454 50-454
98 88 88	12190236* 12190250* 12190250*	50-454 50-454 50-454 50-454 50-454	к к к к к	8812190389° 8812190389° 8812190390°	50-454 50-454 50-454 50-454 50-454
88 88	12190250* 12190254*	50-454 50-454 50-454 50-454 50-454	к к к к	8812190390' 8812190390' 8812190391' 8812190391'	50-454 50-454 50-454 50-454 50-454
68 90 88		50-454 60-454 50-454 50-454 50-454	к к к к к	8812190391° 8812190391° 8812190391° 8812190392° 8812190392°	50-454 50-454 50-454 50-454 50-454
86 83 83	12190331* 112190344* 112190344* 112190351*	50-454 50-454 50-454 50-464 50-454	K K K K K	8812190392' 8812190392' 8812190393' 8812190393'	50-454 50-454 50-454 50-454 50-454
88 89 89	112190351* 112190352* 112190352*	50-454 50-454 50-454 50-454 50-454	к к к к к	8812190393* 8812190393* 8812190393* 8812190395*	50-454 50-454 50-454 50-454 50-454
88 39 88	312190352* 312190352* 312190353* 312190353*	50-454 50-454 50-454 50-454 50-454	к к к к к	8812190395* 8812190395* 8812190395* 8812190400*	50-454 50-454 50-454 50-454 50-454
88 68 68	312190353* 312190353* 312190355* 312190357*	50-454 50-454 50-454 50-454 50-454	K K K K	8812190400' 8812190400' 8812190400' 8812190401'	50-454 60-454 50-454 50-454 50-454
98 89 98	312190357° 312190357° 312190357° 312190360° 312190360°	50-454 50-454 50-454 50-454 50-454	K K K K	8812190401° 8812190401° 8812190401° 8812190402° 8812190402°	50-454 50-454 50-454 50-454 50-454
9.5 98 99	912190360* 312190360* 312190360* 312190368*	60-454 50-454 50-454 50-295 50-454	к к к к к	8812190402° 8612190402° 8812190402° 8812190403° 8612190403°	50-454 50-454 50-454 50-454 50-454
66 88 86	312190366° 912190366° 312190366° 312190366° 312190367°	50-454 50-454 60-454 50-454 50-454	к к к к	8812190403° 8612190403° 8812190404° 8812190404°	50-454 50-454 60-454 50-464 50-464
86 86 86	912190367° 812190367° 812190367° 812190367° 812190369°	50-454 50-454 50-454 50-454 50-454	к к к к	8812190404* 8812190404* 8812190404* 8812190416 9812200010	50-454 50-454 50-454 50-237 50-254
9.6 81 81	812190369° 812190369° 812190369° 812190372°	50-454 60-454 50-454 50-454 50-454	к к к к к	6812200014 6812200014 6812200014 8812200027 6812200027	60-237 50-237 50-237 50-454 60-454
9) 84 84	812190372* 812190372* 812190372* 812190372* 812190373*	50-454 60-484 60-454 50-454 50-454	К К К К	8812200049 8812200091 8812200091 8812200091 8812200091	50-373 60-454 50-454 50-454 50-454
6: 81 81	812190373° 812190373° 812190373° 812190373° 812190375	50-454 50-454 50-454 50-454 50-265	К К К S	8812200091 8812200097* 8812200097* 8812200097*	50-464 50-454 50-464 60-464 50-285
81 84 84	812190380° 812190380° 812190380° 812190380° 812190380°	60-454 50-454 50-454 50-454 60-454	к к к к к	8812200141 8812200205 8812200223' 8812200223'	50-304 50-249 50-454 50-454 50-454
6 8	812190382* 812190382* 812190382* 812190382*	50.454 50.454 50.454 50.454 60.454	К К К К К	8812200223° 8812200226° 8812200226° 8812200226°	50-454 50-454 50-454 50-454 50-454
9 8	812190383° 812190383° 812190383°	50-454 50-454 50-454 50-454	к к к к	8812200226° 8812200226° 8812200234° 8812200234°	50-454 50-454 50-454 50-454

	8812200234* 8812200237*	0-454 0-454 0-454	K K		8812130016 8812130047 8812140016	50-247 50-3 50-247	F P
	8912200237* 8812200237* 8812200237* 8812200237*	50-454 50-454 50-454 50-454 50-454	K K K P	Consumers Power Co	8812190241 88100701051 8611280019 8911280116 8811290117	50-247 50-255 50-255 50-255 50-155	R P S F S
	8812200274 8812200274 8812200274 8812200276*	50-454 50-454 60-454 50-454 50-454	P P P P		8811290467 8811290479 8811300178 8811300282 6812010190	50-255 50-255 50-155 50-155 50-255	р Р Р
	8612200276* 6812200276* 8812200276* 8812210001	50-454 50-454 50-454 50-457 50-457	P P S S		6812010195 8812020167 8812020187' 8912020190* 6812020220	50-255 50-255 50-255 50-255 50-255 50-255	F \$ 5 5 5
	8812210007	50-456 50-10 50-10 50-10 50-10	S F F F		8812050226 8812050231 6812050233* 8812050270 8812050276	50-255 50-255 50-255 50-155 50-155	0 0 0 0
	8812210205 8812210205 8812210280 8812220206 8812220206	60-10 50-10 50-237 60-295 50-295	F F S P		8812050316 8812050317 8812060069 8812050078* 8812060088*	50-155 50-255 50-255 50-255 50-255	P S P P P
	8812220206 8812220206 8812220206 8812220214* 8812220382	60-295 50-295 50-295 60-295 60-458	P P P Q		8812060097* 6812060101* 8812060105 8812070140 8812070140	50-255 50-255 50-255 50-155 50-155	P P S F F
	8812220382 8812220382 8812220382 8812220382 8812220385*	50-458 50-456 50-458 50-458 60-456	90990		8812120076 6812120217 6812120243 0812120254 6812130126	50-255 50-155 60-255 50-255 50-265	P Q F F S
	8812220385* 8812220385* 8812230081 8612230081 8812230084*	50-456 50-456 50-295 50-295 50-295	Q Q R R R		8812130238 8812130304 8812140047 8912140210 8812140223	50-165 50-155 50-255 50-255 50-255	P R S F F
	6812230162 8612230162 8812230162 8812230162 8812230162	50-454 50-454 50-454 60-454 60-454	P P P P		0812140225 8812140281 8812200298 8812200315 8812210100	50-255 50-255 50-155 50-156 50-155	Ř F F
	8812230172* 8812230172* 8812230172* 8812230172* 8812230172*	60-454 50-464 50-454 50-454 50-454	ե ե ե	Copes Vulcan, Inc.	8812220168 8812220168 8812220308 0812220323* 6812010095	50-255 50-255 50-255 50-255 OA999	R P O
enance & Parts Corp.	8812270051 8812270051 8812270163* 8812270237 8812010237*	60-295 60-295 50-454 50-373 CONTRACT	QQFS	CorTest Columbus, Inc. Covington & Burling Creare, Inc. Credit du Nord	8812140112* 8812190078 8812020159 8812020164 8812210296	CONTRACT 40:2061 NUREG NUREG 40:2259	
on akee Alomic Power Co.	8812210353 8811290027 8811290122* 8811290219 8811290222*	71-9107 50-213 60-309 50-213 50-213	Q Q P P	Dairyland Power Cooperative Dames & Moore	6812220028° 6812140182 9612190258° 6612190258° 8812190259°	40-2259 50-409 50-454 50-454 50-464	к К К
	8811300024 8811300072 8811300093 8812010055 8812020125	50-213 50-213 50-213 50-213 50-213	F Q P ዙ F		8812190326* 8812190326* 8812190326* 8812190326* 8812190320*	50-454 50-454 50-454	K K K K K
	8812060036 8812060041* 8812070075 8812090209 8812130118	50-213 50-213 60-213 50-213 50-213	A P P F S		8812190329 8812190330 8812190330 8812190330 8812190332	50-454 50-454 50-454 50-454	K K K
erhahn	8812140181 8812190265 8812220042 8812010071 8812010268	60-213 60-213 50-213 PR PRM	F R F		8812190332 8812190332 8812190335 8812190337 8812190337	* 50.454 * 50.454 * 60.454 * 50.454	K K K
Edison Co. of New York, Inc	8811290020 8812010334 8812010336 6812020011 8812020236	50-247 PR 60-247 50-247 60-247	Q P P S	Denmerk, Govt. of	8812190337 8812190338 8812190338 88121903328	5° 50-454 6° 60-454 6° 50-454 6 REVIEW GR	K K K P Q
	8812070263 8812080002 8812080110 8812080012	50-247 60-247 50-247 50-247	P Q S P	Detroit Edison Co.	880425025 881123033 88112903 881130045	50-341 7 60-341	9 9 9

8612090208 8612090249 8612120100	50-341 50-341 50-341	ь Г		8812090034° 8812090034° 8812090034°	50-269 50-269 50-269
8912130026 6812140265 8812140266 8812150160 8812190082	50-341 50-341 50-341 50-341 50-341	Q S S F F		8612090034* 8612090034* 8612090162 8812030247 8812120012	50-269 50-269 50-369 50-269
8812200265 8812200300* 8812200366 8812200372* 8812200374*	50-341 50-341 50-341 50-341 50-341	S F F F		8812120012 8812120014 8812120014 8812120014 8812120014	50-269 50-269 60-269 50-269 50-269
8812270091 8812270098* 8812270300 8812270302* 8812270303	50-341 50-341 50-341 50-341 50-341	R R P P		8612120014° 8812120014° 8812120014° 8812120014° 8812120004	50-269 50-269 50-269 50-269 60-369
8812270304* 8812050065 8811230276 8811290187 8811290187	50-341 50-255 50-369 50-269 50-269	р Б Р Р		8812120112 8812120117 8812120118 8812120118 8812120118	50-369 50-269 50-269 50-269 50-269
8811290197 8811290264 8811290264 8811290264 6811290264	50-269 50-369 50-369 50-369 50-369	P 0000		8812120118 8812120118 8812120118 8812120118 8812120118	50 289 50 269 50 269 50 269 50 269
8B11290264 8B11290569 8B11300145 6B11300145 8B11300145	50-369 50-369 50-269 50-269 60-269	a saaa		8812130117 8812130117 8812130117 8812130117 8812140200	50-269 50-269 60-269 50-269 50-287
8811300152 8811300228 8811300228 8811300431 8812010206	50-369 50-369 50-369 50-369 PR	Р Р S		8812140227 8812140227 8812140228* 8812140228* 8812140233	50-413 50-413 50-413 50-413 50-369
8812010351 8812010420 8812020028 8812020028 8812020035	50-413 PR 50-413 50-413 50-413	S P S		8812140252 8812140258 8812140270 8812160086 8812200023	50-369 50-414 50-370 50-413 50-369
8812020039 8812020039 6812020043 8612020047 8812020063	50-413 50-413 50-370 50-369 50-369	P S S O		8812200099 8812200148' 8812200149' 8812200150' 8812200190'	50-287 50-369 60-369 50-369 50-369
8812020237 8812020237 8812020300 6812020300 6812050032	50:369 50:369 50:369 50:369 50:413	s 0000		8812200193* 8812200212 8812200212 8812200217	50 369 50-269 60-269 50-269 50-413
8612050103 8612050103 8812050125 8812050130 8612050131*	50-369 50-369 50-413 50-269 60-269	GGbtt		8812200217 8812200277 8812200278 8812200283 8812200297	50-413 50-413 50-413 50-413 50-269
8812050131* 8812050131* 8812050132* 8812050132*	50-269 50-269 50-269 50-269 50-269	ቴ ተ ተ ተ ተ		8812200297' 8812200297' 8812200301' 8812200301'	60-269 50-269 50-269 60-269 50-269
8812060018 8812060018 8812060018 8812060106 8812060108	50-269 50-269 50-269 50-269 50-369	Q Q G F F		8812200318 8812210063 8812210063 8812210063 8812210114	60-414 60-269 50-269 50-269 50-289
8812060264 8812070012 8812070023 8812070025 8812070025	50-369 50-269 50-413 50-369 60-369	\$ \$ \$ \$ \$		8812210114 8812210114 8812210115' 8812210115' 8812210115'	50-269 50-269 50-269 60-269 60-269
8812070025 8812070025 8812070025 8812070027 8812070027	50-369 50-369 50-369 50-369 50-369	6 6 6 6		8812210328 8812210326 8812210326 8812210386 8812220046	50-269 50-269 50-369 50-369 50-287
8812070027° 8812070027° 8812070027° 8812070064 8812070064	50-369 50-369 50-369 60-269 50-269	P		8812270207 9812270207 9812270207 8812270254 8812270261	50-269 50-269 50-269 60-369 50-269
8812070064 8812080119 6612090029 8812090034*	50-269 50-269 50-269 50-269	8 8 F	Duquesna Light Co.	8812270305 8812270307 8811230083 8811230084	50-413 50-413 50-412 71-275

Dresser Industries, Inc. Duke Power Co.

	8611300061 8611300509 8612010021 8812010036	50-112 50-334 60-334 50-334 PR	Р О Я Р		891212025 881213996 831214015 691215026	3 WASTE M 3 40 6500 9 WASTE M	
	8812010197 8812010248 8812010253 8812050045 8812050045	50-412 50-334 60-334 50-334 50-334	0 0 8 6		881219018/ 881219018/ 881219023: 881219023: 881219036:	1" 40 6555 0 40 6555 4 WASTE MS 9" WASTE MS 2" 40 6556	GT GT
	0812050300 8812080232 8812080234 8812080272 8812120083	50-412 50-334 50-334 50-334 50-334	9 0 P		8812210062 8812210124 8812210231 8812210318 8812220347	WASTE MO WASTE MO WASTE MO WASTE MO WASTE MO	51 51 51 51
	8812120170 8812140267 8812160099 8812160113* 8812200194	71-5984 50-334 60-412 50-412 50-412	P P S		8812220367 8812220371 8812230107 8812230108 8812270215 8812270285	WASTE MO LORG LORG LORG EM STEAW	i7
torp. MA	8812210201 6811280250 6811280301* 6811210074* 6812070245*	60-334 TOPREP TOPREP 50-293 50-293	S Р Н	Energy, Dept. of, Idaho Operations Offic Engineers international, Inc	8812090133 8812230039 8812090246 8812090248 8812120224	WASTE MG PROJ WASTE RES WASTE RES	S S
nt de Nemours & Co., Inc. აე ზი, Inc. (subs. of EG&G, Inc.)	8812010160 8812020202* 8812010378* 8710140219* 8710140231*	PR PR 50-604 50-275 60-275	A Q Q		8812140119 8812140123* 8812140123* 8812140134 8812140140*	WASTE RES WASTE RES WASTE RES WASTE RES WASTE RES	
	8710140322* 8810120268* 8811170247* 8811180289 8811180312	50-483 50-458 60-397 50-213 50-247	Gerdd		8812140173 8812140179* 6812190159 8912190187* 6812190169*	WASTE RES WASTE RES WASTE RES WASTE RES WASTE RES	
	8811210007* 8811210082 8811220443* 8811280118*	50-423 50-458 50-280 50-528 50-352	94046	Environmental Protection Agency Evento-Crater	8812050008 6812050027 6812050073 6812210270 68122050337*	49 5829 40 8997 40 6907 40 6907 FO'A	
	8812180018 8812180037 8812190086 8812190094 8812270048	NUREG NUREG NUREG NUREG 50-346	Q	Everest Minerals Corp	8812050339* 8811280065 8812020126 8812050138* 8812050138*	FO'A 40-8857 40-8857 40-8064 40-8064	
allonal, Inc. odak Co. vices, Inc. (subs. of Ensarch	8811300000° 8812100203° 8812190297° 8812190301° 8812060102°	60-331 FOIA FOIA FOIA WASTE MGT	Q		8812060003 8812060003 6812210052 6812210149 8812210156	40 8857 40-8857 40-8857 40-8857 40-8857	
rt ^{ati} onal Co.	8812190228* 9812060333 8812080086 8812080087*	70-143 PRM XPORTLIC XPORTLIC		Exxon Corp	8812050133 8812050133 8812050135* 8812060175 8812210008	40-8064 40-8064 40-8064 40-8102 40-9102	
	8812120067 8812150034 8812150104* 8612200063* 8812200085	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		Federal Emergency Management Agency	8812210358 8811280044 8811280051* 8811280059* 8811290183	40-8064 50-344 50-344 50-344 50-440	F
er Research Institute I. of	8611290229* 8811090114 8811140164 8811140171* 8811230213	REVIEW GR WASTE MGT WASTE MGT WASTE MGT 71-8639	p		8811290191* 8812020089 8812020149 8812190001 8812190001	50-440 50-443 50-443 50-443	F 0000
	6811260069 6811260131 6811280137 6811280166 6811290089	WASTE MGT WASTE MGT WASTE MGT PROJ WASTE MGT			8812190004* 8812190004* 8812190007* 8812190007* 8812210168	50-443 50-443 50-443 50-443 50-289	GGGGF
	8811290098 8811290113 6811300132* 8811300138* 8811300141	WASTE MGT WASTE MGT XPORTLIC XPORTLIC WASTE MGT		Fenix & Scisson, Inc. Ferral Exploration Company of Nobraska, Inc.	8812210173° 8812150242 8812050001 8812210252	50-289 WASTE MGT 40-8829 40-8829	F
	8811300200 8812050081 8812050147 8812050149 8812050248	WASTE MGT WASTE MGT 71-9218 PROJ WASTE MGT		Florida Power & Light Co.	8811230275 8811280041 8811280064 8811280199 8811290141	50-250 50-250 50-250 50-389 50-250	S R S P R
	8812050295 8812080239 8812090236 8812090266 9812090300	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT			8811290335 8811290335 8811290367 8811290367 8812010132	50-335 50-335 50-250 50-250 PR	P P R
	8812090310 8812090316*	WASTE MGT WASTE MGT WASTE MGT WASTE MGT			8812020102 8812060114 8812060114 8812070138	50-335 50-250 50-250 50-250	G Я R

	8812070138 8812080149 8812080149 8812080233 8812080235*	50-250 50-335 60-335 50-335 60-335	P 0000		8812130072 8812130252 8812130254 8812130283 8812140208	71-6346 XPORTLIC XPORTLIC 70-734 70-734	
	8012090125 8812090125 8612120166 8812120166 8812120190	50-250 50-250 50-250 50-250 50-250	F F P S		8812210395 8812210400 8812210403* 6812220301 6812220303*	71-9226 TOPREP TOPREP 71-6346 71-6346	
	8812140079 8812140079 8812140198 8812150042 8812150042	50-250 50-250 50-251 50-335 50-338	6 6 6 6	General Electric Co	8811230214 8811290355* 8811290355* 8811290367* 8811290357*	TOPREP 50-277 50-277 50-277 50-277	
	8812160034 8812160071 8812160071 8812160071 8812190129 8812190129	50-250 50-250 50-250 50-335 60-335	P R F F		8812050172* 8812070146* 8812130262 8812200247 8812200262	50-440 50-220 50-605 70-1113 70-1113	Ş
	8812200008 8812200008 8812200008 8812200013* 8812200013*	50-250 50-250 50-250 50-250 50-250	A A A A A	General Nuclear Systems, Inc.	8812200375 8812210002 8812210129 8812230129 8809130261	TOPREP 70-1113 70-1113 71-3006 PROJ	
	8812200013* 8812200013* 8812200016* 8812200131 8812200131	60-250 60-260 60-260 50-250 50-250	R R R R	General Public Utilities Corp GPU Service Corp.	8812880072* 8811280111 8811280114 8811290557	PROJ 60-210 50-218 50-219	
	8812200197 8812200197 8812200203 8812200352 8812200362	60-250 60-250 50-250 50-250 50-335	8 8 8 8		0811290561 0811300430 0812010019 0812010022 0812010039	50-219 50-289 50-219 50-219 50-219	0
	8912220136 8912220136 8812220136 6812220136 8812230027	60-250 60-250 50-250 50-250 50-250	P P		0812010090 8812010091* 8812010092* 8812010167 8812020136	50-320 50-320 50-320 PR 50-280	F
	8812230027 8812230028* 8812230028* 6812270272 6812270276*	50-250 50-250 50-250 50-335 50-335	PPOO		8812020262 8812020263* 8812050087 8812080042 8812080143	50-219 60-219 60-320 50-219 50-209	, , ,
	8812280009 8812280040* 8812280086* 8812280103* 8812280116*	60-335 60-335 60-335 50-335 60-335	T T T		8812120107 8812130177 8812130180* 8812130221* 8812140178	50-209 60-289 50-289 50-289 50-289	, ,
Florida Power Corp. (subs. of Florida Progress Corp.)	8812280124* 8811280062 8811280157 8811290101	50-335 50-302 50-302 60-302	S O		8812160058 8812160157 8812150166 8812160173* 8812160121	50-219 60-219 50-219 50-219 PROJ	ļ
	8811290333 8811300157 6812010007 6812010153 6812010239	60-302 50-302 50-302 50-302 PR	P P P S		8812190107 8812190121 8812190138 8812200024 8812200046	60-920 60-320 50-320 50-219 PROJ	C
	8812020068 8812020071* 8812020268 8812020270* 6812050182	50-302 50-302 50-302 50-302 50-302	P P P P		8812200174 8812210048 8812210109 8812210240 8812210355	60-289 60-219 50-219 60-219 60-219	F C
	8812070172 8812070178 8812090041 8812150078 8812190371	50-302 50-302 50-302 60-302	F H Q S		8812220185 8812220380 8812270037 8812270044 8812270141*	50-289 60-289 50-320 50-320 60-219	((
Florida, Univ. of, Gainesyllis, FL	8812190381 8812200206 8812210076 8812210166 8812210179	50-302 50-302 50-302 50-302 50-302	S F F O	General Services Administration Georgia Institute of Technology, Atlanta GA	8812270260 8812080021* 8811300067 8812140008	50-219 50-320 50-160 50-160	1
FMAG, Ully, U., Gall-Goylib, FC	8811280076 8811290120 8812010025 8812070170 8812090149	50-83 50-83 50-83 50-83 50-83	S H R A	Georgia Power Co.	8812160053 8811230238 8811230241 8811230244 8811280028	50-160 50-425 60-424 60-425 50-424	((
Fulbright & Jaworski Gannett News Service, Washington, DC Garde, B.P. General Atomics (formerly GA Technologie	8812140991 8812090217* 8812190280 8812080128 8811280176*	50-83 COMMISSIO FOIA FOIA 50-163	S N P		6811280028 8811280055 8811280144 8811290072 8811290292	50-424 50-424 50-424 60-424 50-424	
a, Inc./General Atomic Co.)	8812070028 8812080093* 8812080095*	70-734 XPORTLIC XPORTLIC			8811290309 8811290309 8811290556 8811290556	50-321 50-321 50-424 60-424	1

ĺ					HOMBER	CATEGOR	•
	8811290572 8811290575 8811300566 8812010103 8812010103	50-424 50-424 50-425 50-424 50-424	8 8 8 K K	Gulf States Unities Co.	8811300191 8811300196 8811300231 8811300267 8811300272*	50-458 60-458 50-458 50-458 50-458	Q S R S R
	8812010342 8812010344 8812010350 8812010350 8812020115	50-321 50-424 50-424 50-424 60-424	\$ \$ P P \$		8811300286 8811300318 8812010232 8812010235 8812010313	50-458 50-458 50-458 50-458 50-458	១១១១១
	8812020218 8812020265 8812020266* 8812050009 8812050091	50-424 50-424 50-424 50-425 50-425	P P F A		8812010391 8812020250 8812060008 8812060154 8812060183	PR 50-458 50-458 50-458 50-468	# H P P
	8812050093* 8812050128 8812050148 8812050222* 8812050224*	60-425 60-425 50-425 50-426 50-426	A Q Q		8812060172 8812060228 8812060310 8812140103 8812140107	60-458 50-458 60-458 50-458 50-458	POQFF
	8812060026 8812060181 8812060184* 8812060202 8812080273	50-425 60-424 50-424 60-425 50-424	A P P Q S	Hampton, NH	8812220073 8812020081 8812190205 8812190205 8812190215*	60-458 50-443 50-443 50-443 50-443	00000
	8812070097 8812090102 8812090145* 8812090254 8812090254	50-424 50-321 50-424 60-424 50-424	GE >00	Harmon, Curran & Tousley	8612190215* 8812270093 8812020084 8812190227 8812280058	50-443 50-443 50-443 60-271 50-271	88888
	8812090261 8812120004 8812120011 8812120011 8812120059	50-424 50-366 50-321 50-321 60-321	G to the	Health & Energy Institute Health & Human Services, Dept. of, U.S. Public Health Service Holtec International	8812280085 8812050058 8812020057 8812200249*	50-271 PR PR 50-425	G
	8012120059 8812120059 8812120059 8812120133 8812120180	60-321 60-321 50-424 50-424 60-321	H H 888	Hong Kong	6812280040° 8812280086° 8812280103° 8812280280 8812200289	50-305 50-305 50-305 60-305 REVIEW GR REVIEW GR	7 T T P P
	8812120183 8812120284 8812120265* 8812130268 8812140062	60-321 60-424 50-424 50-424 50-424	QPPPS	Hopi Tribe House of Rep	8811300360 8811300222* 8811300290* 8811300290* 8811300423*	PR 50-289 50-3 50-3 50-275	GOCH
	8812140120 8812140269 8812150081 8812150146 8812160117	60-424 60-424 60-321 50-425 50-424	S Q S Q F	House of Rep., Energy & Commerce	8811300423* 8812010169 8812080005* 8812080016* 8812130096*	60-275 PA 60-322 COMMISSIO 50-390	U G R Q
	8812180117 8812190118 8812190118* 8812190260 8812190379	50-424 50-424 50-424 50-321 50-425	F P R A	House of Rep., Post Office & Crvi Service Houston Lighting & Power Co	8812090238* 8811290164 8811290184 8811290176*	COMMISSIO 50-498 50-498 50-498	N. P&P
	8812180385 8812200001 8812200112 8812200119 8812200119	50-425 50-424 50-321 50-424 50-424	A F P P		8811290176* 8811290363 8811300032 8811300032 8811300139	50-498 50-498 50-498 60-498 60-498	PPQQP
	8812200160 8812200202 8812200213 8812200219 8812200227	60-321 60-425 50-424 50-424 50-424	P A S S P		8811300139 8811300154 8811300456 8812020087 8812020090	50-498 50-498 50-499 60-498 60-498	PSQSP
	8812200236 8812200243 8812200259 8812210046 8812210049*	50-424 50-424 50-424 50-424 60-424	8 8 9 9		8812020090 8812050122 8812060294 8812060294 8812060296	60-498 50-498 50-498 50-498 50-499	P S F F S
	8812210142 8812210154 8812210191 8812210249 8812210249	60-425 60-425 50-425 60-424 50-424	F Q S Q Q		6812070106 6812070107° 8812070173° 8812080162 8812080152	50-499 50-499 50-499 50-498 60-498	GOOFF
	8812220047 8812220079 8812220081 8812230077 8812230097	50-425 60-424 50-424 50-425 50-425	A S A A		8812080202 8812080202 8812090337 8812090337 8812090344	50-498 50-498 50-498 60-498 50-499	P P P A
3ermany, Federal Republic of	8812230101 8812230273 8812270071 8812270217 8812200303	50-425 50-425 50-321 50-424 REVIEW GR	A P Q P		8812090345 8812090346 8812120211 8812120220 8812130115	50-499 50-499 50-499 50-499 50-498	Q A A A P
3:fbert/Commonwealth, Inc. (formerly 3:fbert Associates, Inc.) 3:egosy, Moore, Jeakle & Heinen 3:riffin, R L.	8812010108 8812270149	50-352 PR 50-445	P G		8812130115 8812130207 8812130207 8812130231	50-498 50-498 50-498 50-498	PPPO

	NUMBER	CATEGORY			NUMBER	CATEGOR
	8812130231 8812130236 8812130287 6812130297 8812130300	58-496 50-499 50-499 50-499 50-498	0000P	Pinois, State of	8912200288 8812210089 8812220133 8812190345* 8812190349*	50-461 50-461 50-461 50-454 50-454
	8812140003 6812140003 6812140018' 8812140251 6812140251	50-498 50-498 50-499 50-498 50-498	9 9 9	In Situ, Inc. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.)	8812200175 8812010069 8811290533 8811300480	REVIEW GR NUREG 50-315 50-315
	8812150095 8812150095 6812150099 8812150099 8812200012	50-498 50-498 50-498 50-498 50-498	P P P		8811300572 8812010011 8812010011 8812010014 8812010014	50-315 50-315 50-316 50-315 50-315
	8812200012 8812200016 8812200021 8812200127 8812200138	60-498 50-499 60-498 50-498 50-499	P Q Q R J		8812050036 8812050036 8812050037* 8812050037* 8812080148	50-315 50-315 50-316 50-315 50-318
	8812200250 8812200260 8812200266 8812200266 8812200267	50-499 50-499 50-498 50-498 50-499	A S S S		8812080196 8812080036 8812090036 8812090051 8812120240	PR 50-316 50-316 50-316 50-315
	8812200288 8812210011 8812210029 8812210029 86122100397	50-499 50-498 50-498 50-498 50-498	Q S P P P		8812120240 8812130032 8812190011 8812210322 8812210379	50-315 50-315 50-316 50-316 60-315
	6812210397 6812220049 8812220049 8812220180 8812220180	50-498 50-498 50-498 50-498 50-498	6 6 6	Inside N.R.C. (McGraw-Hill Publication) Institute of Nuclear Power Operations Interior, Dept. of Interior, Dept. of, Bureau of Mines	8812190378 8811300207* 8812120071 8812130039 8812120218	FOIA ORG PR WASTE MGT WASTE RES
Hunton & Williams	6812270262 6812270291 6812020032 8812020036* 6812020061	50.498 50.499 50.322 60.322 50.322	S A G G	Interior, Dept. of, Geological Survey Interleaf, Inc. International Atomic Energy Agency	8812140096° 8812090182° 8812150010 8812010008 8811230065°	CONTRACT COMMISSIO 50-274 FOIA MISC
	6812020083 6812140054 8812140064* 8812140070 8812140116	50-322 50-322 50-322 50-322 50-322	G G G	International Brotherhood of Electrical Workers	6812220060 8812220064* 8812010089	WASTE MGT WASTE MGT PR
	8812140121 8812190103 8812190112 8812270049 8812270069	50-322 50-322 50-322 50-322 50-322 50-322	G G G G G		8812010096 8812010165 8812010181 8612010358 8612010363 8812010400	PR PR PR PR PR 50-210
	8812280002 8812280005* 8812280005* 8812280007* 8812280008*	50-322 50-322 60-322 60-322 50-322	G G G G		8812010405 8812010421 8812010421 8812020030 8812020030	50-390 50-334 50-334 50-334 50-334
Hydro-Eng neering ICF, Inc IMO De'aval, Inc.	8812280070 8812280078 8811300388* 8812210225 8811300033	50-322 50-322 40-8958 WASTE RES PT21	G G	International Freight Forwarders, Inc. International Technical Services, Inc.	8812020077 8812020077 8812020119 8812130079 8811160355*	50-334 50-334 PR 70-3041 50-277
INTERA Technologies, Inc ITASCA Consulting Group, Inc.	8812020192 8812210256 8812190186 8812190192 8812190201*	40-8904 40-8904 WASTE RES WASTE RES WASTE RES		Iowa Electric Light & Power Co.	8811290564 8811300007 8811300502 8812010017 8812020210	50-331 50-331 60-331 50-331 50-331
Idaho National Engineering Laboratory	8710140322* 8810120268* 8811170247* 8811180289 8811180312	50-483 50-458 50-397 50-213 50-247	0000		8812020224 8812050089 8812070250 8812140232 8812140254	60-331 60-331 60-331 50-331 50-331
	8811210082 8811220443* 8811280118* 8812809141*	50-423 50-280 50-528 60-352 WASTE MGT	QQPP	lowa State Univ., Ames, IA JRA Associates	8812230153 6812010319 6812010326* 8812010331* 8812190210	50-331 50-116 50-116 50-116 FOIA
iter Research Institute Ilfinois Power Co.	8812190094 881222001 8812270048* 8812080064* 8812020226	NUREG 71-9200 50-346 50-341 60-461	Q U S	Jacobs Engineering Group, Inc. Japan, Govt. of Jordan, Apostal, Ritter Associates, Inc. KLD Associates, Inc. Kenrob & Associates, Inc.	8812210060 8812190361 8812090193* 8811210070* 8812010282*	WASTE MGT FOIA COMMISSIO 50-293 CONTRACT
	8812050049 8812060279 8812070081 8812140178 8812140231	50-461 50-461 50-461 50-461 50-461	\$ F P \$	Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.) Kerr-McGee Corp.	8812190076 8811300118* 8812140221*	40-2061 40-8027 40-8027
	8812180128 6812190229 8812190274 8812200101	60-461 50-461 50-461 60-461	V R Q S	Kirkpatrick & Lockhart	8812020048 8812020052 8812020104 8812020113* 8812020121*	50-322 50-322 50-322 60-322 50-322

AUTHOR AFFILIATION	ACCESSIÓN NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8812050109 8812140058 8812140068* 8812140071	50-322 50-322 50-322 50-322 50-322	P G G G		8312060291 8812060292* 8812130091 8812130121 8812150012	50-309 50-309 50-309 50-309 50-309	P S P P
	8812140113 8812140139 8812190156 8812190172* 8812210291	50-322 50-322 60-322 50-322 50-322	G G G F	Malapai Resources Co	8812150092 8812150096* 8812150110* 8811280037 8812050002	50-309 50-309 50-309 40-8684 40-8502	P P
	8812270014 8812270024* 8812270033 8812270052 8812270068	50.322 60.322 50.322 60.322 60.322	0 0 0 0		8812050005 8812050138 8812060161 8812060174* 8812060194*	40-8502 40-8502 40-8502 40-8502 40-8502	
r∤n & Associates	8812280012 8812280033 8812280088 8812270167 8812270097	60-322 50-322 50-322 50-446 50-443	60000		8812060197* 8812060198* 8812060201* 8812060210 8812060212*	40-8502 40-8502 40-8502 40-8684 40-8684	
pelman & Paige prence Livernoro National Laboratory Bloods, Lamb, Leiby & MacRae pris, M.	8812160187 8812190023* 8812160137 8812020088 8804210209	WASTERES WASTERES 50-265 PR 50-322	J Q	Mallinckrodt, Inc Mankato Sisto Univ , Mankato, MN Martin Marietia Corp.	8812210062 8812010160 881202020* 8812090220* 8812060211*	40-8502 PR PR COMMISSIO FOIA	N
ong tistaund Lighting Co.	8811300001	50-322	F S	Maruberi America Corp. (subs. of Maruberi	8812130074*	XPORTLIC	
	8811300012 8812020038* 8812020061	50-322 50-322 50-322	G	Corp.) Massachuseits Institute of Technology.	8812130186* 8812050134	XPORTLIC 50-20	P
	8812020083 8812060046 8812070103 8812080089	50-322 50-322 50-322 50-322	G S H K	Cembridgo, MA Massachusotts Pub'ic Interest Resoarch Group	8812190282* 8812140164*	50-20 CONTRACT 50-203	P P
	8812080091° 8812080094°	50-322 50-322	K K K		8812140168* 8812020014*	60-293 60-293	F
	8812090054 8812090157 8812140059 8812140064*	60-322 50-322 50-322 60-322	S Q P G G	Messachusotts, Commonwealth of	8812020025 8812020025 8812020042* 8812020042*	50-443 50-443 60-443 50-443	6 6 6
	8612140070 8612140113 6812140115 8612140121 8812140188	50-322 50-322 50-322 50-322 50-322	G G	G G	8812020051° 8812020110 8812020175° 8812130106° 8812140114	50-443 50-443 50-293 50-293 50-443	0 6 7 9
	8812150259 8812150260* 8812150273 8812190103 8812190112	50-322 50-322 50-322 50-322 50-322	P F G G		8812140114 8812140124 8812140124 8812140128 8812140128	50-443 50-443 50-443 60-443 50-443	G G G
	8812190117* 8812200294* 8812230086 8812270049 8812270069	50-322 50-322 50-322 50-322 50-322	P F G G		8812140135* 8812140135* 8812140148* 8812140151* 8812140161*	60-443 60-443 50-443 50-443 50-443	99999
	8812280002 8812280003* 8812280005* 8812280006* 8812280007*	50-322 50-322 50-322 60-322 50-322	6 6 6 6		8812190144 8812190179* 8812190205 8812190205 8812190215*	60-443 50-322 50-443 50-443 50-443	00000
Louislana Power & Light Co.	8812280008* 8812280070 8812280078 6812010116 8612010119*	60-322 60-322 50-322 50-382 60-382	9 9 P P S		8812190215 8812270042 8812270067 8812270084 8612270084	50-443 50-271 60-443 50-443 50-443	0 6 6
	8812010189 8812010222 8812020027 8812020233 8812070143	50-382 PR 50-382 50-382 50-382	Q SIFP		8812270093 8812270099 8812270099 8812280001 8812280001	60·443 50·443 50·443 50·443 50·443	9
	8812120105 8812120113' 8812130013 8812150035 8812150039	50-382 50-382 50-382	- - - - - - - - - - - - - - - - - - -		8812280004 8812280004 8812280069 8812280069 6812280099	50-443 50-443 50-443	0
MHB Technical Associates	8812200032 8812200053 8812210148 8812270294 8812020051	50-382 50-382 50-382 50-443	R R O G G		881228009 881228011 881228011 881228011 881228011	5 60-443 5 50-443 8 50-443 8 50-443	1
MK-Ferguson Co. MSU Systems Services, Inc. Maine Yankee Atomic Power Co.	8812020123 8812130070 8812210233 8812120151 8811290056	40-6500 WASTE M 50-416 50-309			881228012 881228012 881228013 881228013 881228014	3 60-443 7 50-443 17 50-443 12 50-443	
Medico remonation of and	8811290115 8811290221 8811290221 881130016 881205003	50-309 50-309 5 50-309	000	Materials Engineering Associates, Inc.	881228014 881228016 881201025 881219013	36 50-443 34 CONTRAC	:T

Michigan उ.८७ जा.ү., टक्क दकाख ग्रु, का	8812050269* 8812080067* 5812120077	50-294 50-294 50-2	ь ь		8812060165 8812080013 8012120273	50-286 50-333 60-286
Michigan, Univ. al, Ann Arbar, Mi Miller, Canfe'd, Paddock & Stona	8812190141 8812220198 6812220201 8312200102 8812090198	50-294 50-294 50-294 50-2 COMMISSIO	400#2		8812130001 8812130003 8812130004* 8812130007 8812130009*	60-333 60-286 50-288 60-286 50-286
Minnesota, Mining & Manufecturing Co., 3 Co.	8409180364*	REVIEW GR	P		8812130045* 8812130046*	50-286 60-286
Missouri, Univ. of, Columbia, MO	8812010320° 8812140145° 8812070159	REVIEW GR REVIEW GR 50-186	P P		8812130060 8812130301 8812150126	50-268 60-333 50-333
Missoun, Univ. of, Rolla, MO Mitsubishi International Corp. (subs. of Mitsubishi Corp.)	8812150007 8812130080*	50-186 XPORTUC	P		8812190010 8812200073 8812200155	60-333 50-333 50-333
	881213008B* 8612130193*	XPORTLIC XPORTLIC		New York, NY	8812210262 8812080140	50-333 PR
Misul & Co. (USA), Inc. (subs. of Mitsu & Co., Ltd.)	8612130195° 8612190065° 6812080148°	XPORTLIC XPORTLIC XPORTLIC		New York, State of	8812020046 8812020104 8812020113* 8812020123*	50-322 50-322 50-322 60-322
	8812080173° 8812080188°	XPORTLIC XPORTLIC			8812020130* 8812020168	50-322 60-322
Mobil Cost Producing, Inc	8812080226 8812150036 8812150100 9812050180	XPORTLIC XPORTLIC XPORTLIC 40-8911			8812080134 8812140058 8812140068* 8812140071	PR 50-322 60-322 50-322
Molycom, Inc. (subs of Union Oil of California)	8812050184° 8812050186° 8811300275	40-8911 40-8911 40-8778			8812140073 6812140139 8812190156 8812230089*	50-322 50-322 50-322 50-322
Morrison Knudsen Co., Inc. Morrison Knudsen Engineers, Inc.	8812220320 8812190191*	PT21 40-6500			8812270014 8812270024°	60-322 60-322
NAD, Inc. NUTEC NUTECH Engineers, Inc.	8812050333* 8812190031* 8812130094 8812150147	FOIA 50-354 PROJ PROJ	P		8812270033 8812270052 8812270068 8812280012*	60-322 50-322 60-322 60-322
National Academy of Sciences National Institute of Standards & Technology (formatly National Bureau of	8812180076 8812150066° 8811300398	PROJ CONTRACT 70-398		Newbury, MA	8812280088 8812270031 8612270031 8812270101	50-322 50-443 50-443 50-443
Natural Resources Defense Councit	8812010113 8812130154	PR FOIA			8812270101 8812280146	60-443 60-443
Navy, Dept. of Navy, Dept. of, Navat Sea Systems Comman Nebraska Pub'ic Power District	6812200295* 6812200292 6811300229 6811300463	71-421 71-421 50-298 50-298	0	Newburyport, MA Newman & Holtzinger	8812020092 8812020102 8812140079 8812280009	60-443 60-335 50-250 50-335
	8811300488 6811300498 8812130014 8812140036 9812140049	50-298 50-298 50-298 50-298 50-298	CHSDO	Nagare Mohawk Power Corp.	8612290226 8811230285 8811230288 8611290185 8811290547	FOIA 50-220 50-410 50-220 50-410
	8812140213° 8812160049 8812200128 8812220208 8812220221°	50-298 50-298 50-298 50-298 60-298	9 Q Q P P		8811300464 8811300497 8812010064 8812010139 8812010174*	50-220 50-410 50-410 50-220 60-220
Nebraska, State of Nevada, State of	8812010163 8812210348 8812120038 8812120129 8812120134	PR 40-8943 WASTE MGT WASTE MGT WASTE MGT			8812010183 8812010189 8812010199 8812020296 8812060234	50-410 50-220 60-220 50-410 50-410
New England Coalition on Nuclear	8812120143 8812020081	WASTE MGT 50-443	G		8812060254 8812060318	60-410 60-410
Pollution	8812020081 8812020084	50-443 50-443	G G		8812060319 8812070141 8812070205	50-220 50-220 60-220
	8812020084 8812190205 8812190205 8812190215* 8812190215*	50-443 50-443 50-443 50-443 50-443	6 6 6		8812090303 8812090314 8812140243 8812190204 8812190410	50-220 50-410 60-410 60-220 50-410
New Hampshire, State of	8812190227 8812270093 8812280058 6812280065 8812020062	50-271 50-443 50-271 50-271 60-443	G G G		8812210110 8812210123 8812210332 8812210335* 8812210336*	50-220 60-220 50-410 50-410 60-410
New Mexico, State of New York Power Authority (formerly Power Authority of the State of New York)	8812080175 8812210153 8812210159 8811290039	50-443 40-8904 40-8968 50-333	H H	North Carolina State Univ., Raleigh, NC Northeast Nuclear Energy Co. (subs. of	8811300198 8811300552 9811300554 8811280068	50-297 50-297 60-297 60-245
reacting of the chart of rider (only	8811300221 8811300503 8812010145 8812010423	50-286 50-333 50-333 50-286	8 8 8	Northeast Utilities)	8811280068 8811280068 8811280101 8811280103*	60-245 50-245 60-336 50-336

	01110-0111			нимаен	CATEGORS	
8811280136 8811280150 8811290027 8812010034 8812010055	50-336 50-423 50-213 50-423 50-213	ร 0 0 ห		8812140007 8812140013 8812140202 8812140225 8812200181	70-143 70-143 70-143 70-143 70-143	
8812020222 8812050325 8812060277 8812070078 8812070178	50-336 60-423 50-213 50-245 50-245	P Q P F		8812200228 8812200319 8812200343 8812200377 8812220050	70-143 70-143 70-143 70-143 70-143	
8812070178 8812120083 8812120178 8812120214 8812120250*	50-245 50-245 50-423 50-245 50-246	6 6 6 6	Nuclear Information & Resource Service Nuclear Licensing Reports	8812220069 8812220109 8812270223 8812110087 8812050126	70-143 70-143 70-143 60-4-15 FOIA	G
8812130113 8812130280 8812140021	50-336 50-336	Q P R	Nuclear Management & Resources Council	8812090269 8911200224	FOIA NEVIEW GR	ρ
8812160097 8812190412	50-245 50-423 50-336	A A	(NUMARC) (formorly Nuclear Utility Mana	8811290229°	REVIEW GR REVIEW GR	P P
8812200113 8812200122 8812200133 8812200162 8812200264	50·245 60·245 50·423 50·245 50·245	គ្នា ពេលមានបាន ពេលមានបាន	Nuclear Utr'ty Backfitling & Reform Group	8812020227 6812020279 8812070032 8812010217	50-445 PR PR PR	Н
8812200287 8812210054 8812210083 8812220328 8811280101	60-423 50-423 50-423 50-336 50-338	a a wa a w	Nuclear Wasie Consultants, Inc O'Melveny & Myers Oak Fildge Associated Univa	6811290166 8812190217 8812210107 6811290577 8912090101	WASTE RES WASTE RES 50-275 40-7604 70-704	P
8011280136 8011280150 8011280027 8011290210 8011300072	50-336 50-423 50-213 60-213 60-213	88000	Oak Ridgo National Laboratory	6812090104* 8812190054* 6612020166 6812190133 6612210169*	70-734 70-925 NUREG NUREG 40-8027	
8611300093 8612010034 8612010055 8812010055 8612020125	50-213 50-423 60-213 50-336 50-213	Р О Н Н Е	Ohio Citizens for Responsible Energy Ohio Univ., Athans, OH Omaha Public Power District	8812290261 8808310128* 6811230038 6811280120 6811280124	FOIA 60-440 60-285 50-285 50-285	P S S
8812050326 6812060036 8812060277 8812070075 8812070078	50-423 50-213 50-213 50-213 50-245	Q Q P P		8811300005 8811300176 8812010340 6812010347 8812020103	60-285 60-285 60-286 50-285 50-285	Р F 8 H
8812120063 8812120064° 8812120178 8812120214 8812130113	50-245 50-245 50-423 50-245 60-336	6 to C to C		8812020314* 8812050334 8812060125 8912060237 8812070056	60-285 60-285 50-285 50-285 50-285	Q8PQF
8812130200 8812140021 8812160097 8812190412 8812200113	50-336 50-245 60-423 50-336 50-245	P R R S		8812070236 8812080035 8812080036' 8812080037' 8812090147	50-285 50-265 50-285 50-285 50-285	8 P P P
8812200122 8812200133 8812200162 8812200284 8812200287	60-245 60-423 50-245 50-245 50-423	ssss		8812090150 8812130015 8812130217 8812130224 8812130234	50-285 50-285 50-285 50-285 60-285	6 8 8 9
8812210054 8812210083 8812220042 8812220328 8811290346	50-423 50-423 60-213 50-336 50-282	0 5 F P Q		6812140015 8812190290 6812190399 6812200282 6612210277	60-285 60-285 50-285 60-285 60-286	OP OR S
8811290381° 8811300044 8812020084 8812070209 8812080147	50-282 50-282 50-282 50-282 60-263	0888		8812210330 8812230069 8812230071* 8812230073* 8812270211	50-285 50-285 50-285 50-285 50-285	F P P S
8812120110 8812140249 8812140253 8812190396 8812200056	50-262 50-263 50-282 50-282 50-282	Q R R Q S	Oregon State Univ., Corvall's, OR Orrick, Herington & Sutchife PX Engineering Pacific Ges & Electric Co.	8811290446 8812020135 8812210214 8811290426 8911290426	50-243 50-224 PT21 50-275 50-275	F G R A
8812200240 8812200241 8812200246 6812200253 8812210198	60-263 60-263 60-263 60-263 60-282	S Q S S F		8811300077 8811300077 8812050055 8812050183 8812050183	60-276 50-275 50-275 50-275 60-276	F F K K
8812130058 8812070249 8812070254* 8812120157 8812120167	71-9010 71-4909 71-4909 <i>FOIA</i> FOIA			8812050236 8812060094 8812060094 8812060117 8812060117	50-275 50-275 50-276 50-275 60-276	8 0 0 P
8812090195* 8612010099 8812020256	COMMISSIO 70-143 70-143	N		8812070187 8812070187 8812070188* 8812070188*	50·276 50·276 60·276 50·276	Р Р Р

Power Co.

ce Corp. ers, Inc. Institute

Services, Inc. rvices, Inc. (subs. of

	8812090313 8812090334 8812090334	60-323 50-275 50-275	F F		8812120080 8812120206 8812120247	50-3 50-2 50-2
	8812130172 8812130191 8812150248 8812150268 8812150268	50-323 50-275 50-323 50-276 50-275	SOSPP		8812130084 8812130125 8812150090 6812150275 8812200009	50-2 50-2 50-3 50-2 50-3
	8812160008 8812160011 8812160011 8812180014 8812160014	50-275 50-275 50-275 50-275 60-275	20 p p p		8812200121 8812200195 8812210094 8812210292 8812210320	50-2 50-3 50-2 50-3 50-2
	8812160028 8812160028 8812180072 8812180072 8812180233	50-275 50-276 50-276 50-276 50-275	3 4 4 4 4		8812210357 8812220020 8812220058 8812220058 8812270165	50-3 50-1 50-3 50-3
Pacific Nuclear Systems, Inc.	8812190233 8812200098 8812270203 8812270205 8812050155	50-275 50-275 50-323 50-323 71-9080	R S Q S	Plymouth, MA Portland General Electric Co.	8812280206 8811230088* 8812140150* 8811230237 8811290023	50-2 50-2 50-3 50-3
Parameter, Inc. Pathfinder Mines Corp. Patriot, Harrisburg, PÅ	8612080127 8812080135* 8612010349 8811230243 8612060013	71-9200 71-9200 NUREG 40-6622 FOIA			8811290581 8812020023 8812050021 8812050176 8812050178*	50-3 50-3 50-3 50-3 60-3
Pennsylvania Power & Light Co.	8811220341 8811230306 8811230306 8811290375 8811300068	50-387 50-387 50-387 50-387 50-387	P R P F		8812050207 6812050210 8812050302 8812050313 8812070066	50-3 50-3 50-3 50-3 50-3
	8811300321 8811300321 8812020097 8812080205 8812090282	60-387 50-387 50-387 50-387 60-387	A R O S P		8812090177 8812140174 8812160046 8812210061 8812210340	50-3 60-3 50-3 60-3 50-3
	8812120172 8812120191* 8812130053 6812190122 8812190122	50-387 50-387 50-387 50-387 50-387	F 8 F F	Portugal, Govt. of Public Critzen's Critical Mass Energy Project	8812210365 8812270163 8812200332 8812010348	50-3 50-3 REV PR
	8812190232 8812190232 8812190235° 8812190235° 8812190237°	50-387 50-387 50-387 50-387 50-387	P P P P	Public Service Co. of Colorado	8812010355 8812050058 8812090037 8811290266 8811290272*	PR PR PR 50-2- 50-2
	8812190237* 8812190377 8812190377 8812200198 8812200196	50-387 50-387 50-387 50-387 50-387	P P R R		8811300083 8811300424 8812010393 8812020109 8812180248	50-2 50-2 50-2 50-2
	8812210008 8812210010 8812210364 8812210366* 8812210366*	50-387 50-388 50-387 50-387 50-387	\$ F F	Public Service Co. of New Hampshire	8812190354 8812200019 8812200149 8812230276 8811280135	50-2 50-2 50-2 50-4
Pennsylvania, Commonwealth of Philadelphia Electria Co.	8812060278 8812080049* 8811020184 8811020184 8811020187*	FOIA 50-277 50-352 50-352 50-352	ዝ F F		8811300149 8811300289 8812020019 8812020166 6812020166	50-4 50-4 50-4 50-4
	8811020187* 8811280139 8811290350 8811290350 8811290380	50-352 50-353 50-277 50-277 50-353	F A P A		8812020163 8812020163 8812080100 8812060199 8812090165	50-4 50-4 50-4 50-4 50-4
	8811290362* 8811300432 8811300432 8811300462 8812010033	50-353 50-352 50-352 50-277 PR	A P P S		6812120210 8612120213 6812140002 8612140028 6812140028	50-4 50-4 50-4 50-4 50-4
	6812010144 8812010157 8812010384 8812020217 6812020217	50-277 50-277 PR 50-277 60-277	9 9 P		8812140034 8812140034 8812140037 8812140037 8812140043	50-4 50-4 50-4 50-4 50-4
	8812020225 8812020225 8812020298 8812050046 8812060052	50-277 50-277 50-277 50-352 50-277	8 9 Q 8 P		8812140043 6812140057 8812140057 6812140126 8812140128	50-4 50-4 50-4 50-4 50-4
	8812060295 8812070044 8812090137 8812090143	50-352 50-353 50-353 50-353	S S Q A		8812140172 8812200265 8812270078 8812270105	50-4 50-4 50-4 50-4

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	6812270115 8812280085 6812280085 8812280090 8812280090	50-443 50-443 50-443 50-443 50-443	G G G G		8812140028 8812140028 8812140034 8812140034 8812140037	60-443 50-443 50-443 50-443 50-443	00000
್ರಜ Service Electric & Gas Co of New ಕ್ಷಾ	8901030055* 8901030055* 8811280024	50-443 50-443 50-311	G G P S		8812140057 8812140057 8812140075 8812140093 8812140111	50-443 50-443 50-271 50-271 50-271	00000
	8811290237 8811290465 8811290494 8811290550 8811290554 8811300351	50-354 50-272 60-311 50-311 50-311 50-272	S S S S O		8812140126 8812140126 8812270079 8812270105 8812270115	50-443 50-443 50-443 60-443 60-443	00000
	8812010292 8812010296* 8812010338 8812020133 8812050041	50-354 50-354 60-272 50-272 50-272	P Q F P		8812280085 8812280085 8812280090 8812280090 8901030055*	50-443 50-443 50-443 50-443 50-443	99999
	8812050041 8812050041 8812070065 8812070069 8812080047	50-272 60-272 60-272 50-311 50-354	P P S S S	Ross & Smith SIMCO Co , Inc. SRI International	8901030055* 8812010160 8812020202* 8812050326 8812090013*	50-443 PR PR POIA 50-247	G.
	8812090076 8812090304 8812130114 8812130178 8812130239	50-272 50-354 50-272 50-354 50-354	0 8 8 8 8	Sacramonto Municipal Utility District	8811280091 8811280095* 8811290343 8811290346 8811300013	50-312 50-312 50-312 50-312 50-312	reco o
	8812140012 8812140014* 8812150004 8812150094 8812150264	50-354 60-354 60-272 60-272 50-272	ե Ե Ե		8811300019 8811300020 8811300244 8811300256 8812010130	50-312 50-312 50-312 50-312 50-312	000E01
	8812190026 8812190256 8812190271 8812190306 8812190398	60-354 60-311 60-272 50-311 50-354	P R S R		8812050110 8812060009 8812140017 8812190408 8812200124	60:312 60:312 60:312 60:312 50:312	44044
	8812200108 8812220055 8812220057* 8812220061* 8812220083*	60-272 60-364 50-364 60-364 60-364	Р Р Р	Safety Light Corp.	8812200130* 8812200180 8812210141 8812150235* 8812190046	60-312 50-312 50-312 XPORTLIC XPORTLIC	466
wra Mining Co. ely Associates, Inc. farence Technology, Inc. d 3 Priest	8812050019 8812200383 8812210155* 8812010286* 8812140086	40-8905 40-8905 50-426 CONTRACT 50-271	Q G	Sandia National Laboratorles	8811280115 8812010293 8812010353 8812140156 8812190075	WASTE RES WASTE RES NUREQ WASTE RES NUREG	
moids Electrical & Engineering Co.,	6812120235	WASTE MGT			8812190131 8812190149 8812190173	WASTE RES WASTE RES WASTE RES	
Algom Mining Corp.	8812120238* 8812050014 8812060002	WASTE MGT 40-8084 40-8084			8812190273 8812190322	WASTE RES NUREG	
chester Gas & Electric Corp.	8812210274 8811290047 8811290226 8811290531 8811290536*	40-8084 50-244 50-244 50-244 50-244	Q P P	Sargent & Lundy, Inc. Science Applications International Corp. (formerly Science Applications, Inc.)	8812280114 8812090294* 8809130095* 8812010343	NUREG 50:454 TOPREP NUREG	
	8811290539* 8811300201 8811300527 8812010098 8812010410	50-244 50-244 50-244 50-244 50-244	P S P H	Scientech, Inc.	8812020179 8812120055 8812150274 8812190040* 8812190300*	NUREG 60-604 WASTE MGT CONTRACT CONTRACT	
	8812060320 8812070183 8812070218 8812070222* 8812070225*	50-244 50-244 50-244 50-244 50-244	P P P P	Scientists & Engineers for Secure Energy Scripps-Howard Newspapers Seacoast Anti:Pollution League	0012190102° 8812050303 8812020060 8812190044 8812190044	60-322 50-390 50-443 50-443 50-443	
s 2004 Industrias IRC	6812090058 8812190248 6812190387 8812220017 8811290578	PR 50-244 50-244 50-244 40-8801	K R P		8012180080 8812180080 8812180205 8812180215 8812270093	60-443 50-443 50-443 50-443 60-443	
ck Road Industries, Inc. ckeleffer Univ., New York, NY ckeell International Corp.	8612060298 8612060305 8612220004 8612220005 8812220008	PRM PRM 71-3005 71-3005 71-3005		Senate Sequoyah Fuels Corp. (subs. of Kerr-McGe	8812280024 8812080018* 8812080240 8812210311* 9811230008	50-443 COMMISSIO PR 50-443 40-8027	
gers & Associates Engineering Corp.	8812230283 8812050107* 8812050114* 8812050119* 8812020019	71-5971 WASTE MGT WASTE MGT WASTE MGT 50-443	G	Nuclear Corp.)	8811300113 8811300118° 8812050026 8812210056	40-8027 40-8027 40-8027 40-8027	
ges & Gray	8812020168 8812020156 8812020163 8812020163	50-443 50-443 50-443 50-443	G G G		0812210069 8812210239 8812210241 0812210290	40-8768 40-8768 40-8768 40-8027	

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGORY		AUTHOR AFFILIATION	NUMBER	CATEGORY
Shaines & McEachern Shaw, Piltman, Potts & Troworldge	8812020081 8812190107 8812190121 8812190138 8812270037	50-443 50-320 50-320 50-320 50-320	G G G		8812200152 8812200163 8812210080* 8812210087* 8812210087*	50.361 50.206 60.206 50.206 50.206
Sheehan, Phinney, Bass & Green,	8812270044 8812190206	50-320 50-443	G G		8812210087° 8812210091° 8812210091°	50-206 50-206 50-208
Professional Association Sidley & Austin	8811300041 8812270202	50-254 50-254	0		6812210084.	50 206 50-206
Sma'l Business Administration	8812190300° 8812160161° 8812160161° 8812160161°	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT			8812210096* 8812210096* 8812210146 8812210185* 8612210216	50-206 60-206 50-361 60-206 50-361
Small Business High Technology Institute Society for Clinical Social Workers Software Certification Institute, Santa Maria, CA Solution Mining Corp.	8812270213 8812010382 8812090207* 8812210147	FOIA PR COMMISSIO 40-8973	N		6812210265 8812210323 6812210325* 8812210325*	50-206 50-361 50-361 50-361 50-361
Source Production & Equipment Co., Inc.	8811290336 8811300028	71-102 71-102			8812210327° 8812210327°	50-361 50-361
South Carolina Electric & Gas Co.	8811300271 8811300428 8811300448	50-395 50-395 50-395	Q Q P		8812210410 8812220126 8812220126	50-206 50-206 50-208
	8611300462* 8812010002 8812010408 8812060077 8812120084	50-395 50-395 50-395 50-395 50-395	P & X F Q		6812220130 6812230044 6812230044 6812230046* 8812230046*	50-362 50-361 50-361 50-361 50-361
Southampton, NY	8812130124 8812140026 8812270271 8812020046 6812020104	50-395 50-395 50-395 50-322 50-322	P R OG G		8812230067* 8812230067* 8812270112 8812270112 6812270117*	50-361 50-361 50-361 50-361 50-361
	8812020113* 8812020123* 8812020130* 8812020168 8812140058	50-322 50-322 50-322 50-322 50-322	6 6 6 6	Southern Company Services, Inc.	8812270117* 8812270186* 8812270186* 8812060202 8812060207*	50-361 50-361 60-361 60-425 50-425
	8812140068* 8812140071	50-322 50-322	G G	State, Dept. of, Bureau of Oceans & Intl Environ. & Scientific Affairs	8812080160	XPORTUG
	8812140073 8812140139 8812190156	50-322 50-322 50-322	. G	Suffalk County, NY	8812190089 6812020032 8812020046	XPORTLIC 50-322 50-322
	8812270014 8812270024* 8812270033 8812270052 8812270068	50-322 50-322 50-322 50-322 60-322	9 9 9 9		8812020052 8812020104 8812020113* 8812020123* 8812020130*	60-322 60-322 60-322 60-322
Southern California Edison Co.	8812260012* 8812260086 8811230271 8811230271 8611230311	60-322 50-322 50-361 50-361 50-206	990		8812020168 8812050109 8812140050 8812140058 8812140088*	50-322 50-322 50-322 50-322 50-322
	8811280110 8811290085 8811290263 8811290263 8811290389	50-361 60-206 50-361 60-361 50-361	S P P P		8812140071 8812140073 8812140139 8812180166 8812190172*	50-322 50-322 50-322 50-322
	8811290389 8811300057 8812010114 8812010177 8812010345	50-361 50-361 PR PR 50-206	e E		8812190220 8812210291 8812230092* 8812230094* 8812270014	50-322 50-322 50-322 50-322 60-322
	8812020242 8812050050 8812060040 8812060121 8812060124	50-361 50-206 50-206 50-206 60-361	<i>8</i> 0 € € €		8812270024* 8812270033 8812270062 8812270068 8812280012*	60-322 60-322 50-322 60-322 50-322
	8812060128 8812060290	50-206 50-361	Q S	Custos Nallan Alliana I accepte	8612280033° 8812280088 8812270077	60-322 50-322 50-320
	8812060321 8812120007 8812120200	50-206 60-361 60-206	Ossa P	Susquehanna Valley Alliance, Lancaster, PA System Energy Resources, Inc.	8811280107	50-418
	8812120203* 8812120207* 8812130142 8812130142 8812130268	60-206 60-206 50-361 60-361 50-361	P Q O S		8811290339 8811290438 8811290549 8811300283 8812020289	50-416 50-416 50-416 50-416 50-418
	8812130266 8812130266 8612130269* 8812130269* 8812130260	60-361 50-361 50-361 60-361 50-206	P		8812050281 6812060017 8812070017 8812070018* 6812080104	50-416 50-416 50-416 50-416 50-418
	8812130290 8812190061 6812190061 8812200162	60-206 60-361 50-361 60-361	S P P R		8812090106° 8812090188 8812090204 8812090348	50-416 60-416 50-416 50-416

JTHOR AFFILIATION	ACCESSION NUMBER	CATEGORY		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	NUMBER	CATEGORY	
	8812120127 8812120131* 8812120138* 8812120140* 8812130145	50-416 50-416 50-416 50-416 50-416	P P P P		8812210163 8812220011 8812220016 8812220016 6812220071	50-445 50-445 50-445 50-445 50-445	5 S A A
	8812130295 8812160013 8812200028 8612200231 8812200380	50-416 50-416 50-416 50-416 50-416	Р V I R P		8812220071 8812270170 8812270170 8812270174 8812270174	50-445 50-445 50-445 50-445 50-445	A A S S
merly Texas Utilities	8812200381° 8812210251 8812090212° 8811230007	50-416 50-416 COMMISSIO 50-445	P P N S		8812270175 8812270175 8812270177 8812270177 8812270184	50-445 50-445 50-445 60-445 60-445	ទទទទ
,	8811230007 8811230044 8811230044 881123024B 8811290042	50-445 50-445 50-445 50-445 50-445	S S S A Q		8612270184 8812270189 8812270180 8812270190 8812270224	50-445 50-445 50-445 50-445 50-445	S A A S
	8811300172 8812020034 8812020034 8812020107 8612020219	50-445 50-445 50-445 PR 50-445	A F F	Tennossee Valley Authority	8812270224 8809280002 8811220017 8811230101 8811230101	50-445 50-259 TOPREP 60-390 60-390	S Q A
	8812020219 8812020221 8812020221 8812050205 8812050205	50-445 50-445 50-445 50-445 50-445	A Q S S		6811230104* 8611230104* 8811290082 6811290110 6811290512	50-390 50-390 50-327 50-327 50-259	A A A S F
	8812050211 8812050211 8812050215 8812050215 8812050220	50-445 50-445 50-445 50-445 50-445	0 9 8 0		88113000B 8811300070 8811300140 8811300164 8811300183	50-259 50-259 50-259 60-259 50-390	R S O P O
	8612050220 8812050329 8812050329 8812060007 8812060007	60-445 60-445 50-445 60-445 50-445	g ទ ទ ទ ទ		8811300243 8811300243 8811300365 8811300486 8811300486	50-327 50-327 50-327 50-327 60-327	P P P P S S
	8612060012 8812060012 8812060032 8812060032 8812060035	50-445 50-445 50-445 50-445 50-445	0000		8812010024 8812010042 8812010303 8812010310 8812010324	50-259 60-390 PRM 50-260 60-269	S P P
	8812060035 8812060162 8812060162 8812060158 8812060158	60-445 60-445 50-445 50-445 50-445	នទទទ		8812010324 9812010330 8812010341 8812010359 8812020022	50-259 60-327 50-518 50-327 60-327	P Q F F
	88 12060168 88 12060168 88 12060168 88 12060168 88 12120013	50-445 50-445 50-445 50-445 50-445	ននន ន		8812050198 8812050198 8812050203* 8812050203* 8812050242	50-327 50-327 50-327 60-327 60-327	P P P
	8812130271 6812130271 8812150055 8812150055 8812200038	50-445 50-445 50-445 50-445 50-445	A 8 8 8		8812050242 8812050247* 8812050247* 6812050289 8812050291*	50-327 60-327 50-327 50-328 50-328	6 6 6 6 6 7
	8812200040 8812200040 8812200044 8812200044 8812200065	50-445 50-445 50-445 50-445 50-446	A 8 5 5		8812060055 8812060055 8812060058* 8812060058*	60-327 60-327 50-327 50-327 50-327	P P P P
	8812200065 8812200086 8812200083 8812200083 8812200143	50-445 50-445 50-445 50-445 50-445			8812060072 6812060079° 8812060079° 6912060086 8812080112	50-327 50-327 60-327 60-259 60-259	P P P
	8812200143 8812200156 8812200156 8812200179 8812200184	50-446 50-445 50-445 50-445 50-445	958E8		8812060112 8812070207 8812070223 8812070228 8812070227	50-259 50-327 50-328 50-328 50-327	P & & & & & & & & & & & & & & & & & & &
	8812200184 8812210073 8812210073 8812210078 8812210078	50-445 60-445 50-445 50-445 50-445	s s Q		8812070230 8812070237 8812070237 8812070240 8812070240	60-328 60-327 60-327 50-327 60-327	S P P P
	8812210081 8812210081 8812210129 8812210129 8812210135	60-445 50-445 50-445 60-446 50-445	99888		8812070258 8812070258 8812070257 8812070257 8812070258	1 60-327 70-2917	P P P
	8812210135 8812210157 8812210167 8812210163	50-445 50-445 50-445 60-445	s s s		8812080133 8812080145 8812080145 8812080187	50-327 60-327	P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		aoitaili97a fortua	ACCESSION NUMBER	SUB. CATE
	8812080200 8812080227 8812080227 8812080229* 8612080229*	50-327 50-327 50-327 50-327 50-327	8 6 6 8	Three M.Io Island Alert Toledo Edison Co.	8812200111* 8812270077 8808020344* 8811300122 8811300125	71-454 50-320 50-346 50-346 50-346
	8812120018 6812120236 8812120271 8812120271 8812130022	50-259 50-327 50-327 50-327 50-327 50-259	S F Q Q P		8812020129 8812050209 8812050307 8812070088 8812090201	PR 50-348 50-346 50-346 50-346
	8812130022 8812130022 8812140157 8812140157 8812140157	50-259 50-259 50-259 50-259 50-259	6 6 6		8812120028 8812120030 8812120192 8812120249 8812120251°	50-346 50-346 50-346 50-346 50-346
	8812140159° 8812140159° 8812140159° 8812140165 8812140165	50-259 50-259 50-259 50-259 50-259	ង ប្រជា		8812120255* 8812140010 8812140195 8812150059 8812200272	50-346 50-346 50-346 50-346 50-346
	8812140165 8812140165 8812140185 8812140165 8812140171	50-259 50-259 50-259 50-259 50-390	P P P S	Transnuclear, Inc.	8812080024 8812080031* 8812080151 8812120061 8812130062*	71-9233 71-9233 XPORTLIC 70-1426 XPORTLIC
	8812140234 8812140236 8812140248 8812140248 8812140250	50-260 50-296 50-328 50-327 50-328	ននិង		8812130064* 8812130065* 8812200129 8812200132* 8812220188	XPORTLIO XPORTLIO XPORTLIO XPORTLIO XPORTLIO
	8812150103 8812150103 8812150184 8812160091 8812160096*	50-327 50-327 REGGD 50-259 60-259	0 0 F F	Trensportation, Dept. of Twomey, Letham & Shea	8812230125 8812020046 8812020104 8812020113* 8812140058	71-3006 50-322 50-322 50-322 50-322
	8812200061 8812200079 8812200144 8812200145 8812200151	50-328 50-259 60-327 50-259 50-326	s + s s s		8812140068* 8812140071 8812140073 8812140139 8812190156	60-322 60-322 60-322 60-322 50-322
	8812200177 8612200177 8812200222 8812200244 8812200323	50-259 50-259 60-259 50-259 70-2917	P P S S		8812270014 8812270024* 8812270033 8812270052 8812270066	50-322 50-322 50-322 50-322 50-322
	8812210051 8812210084 8812210074 8812210143 8812210195	60-259 50-296 50-259 50-327 50-259	55 55 55 F	U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.)	8812070082 8812150151 8812230165 8812230173	27-48 27-48 27-48 27-48
	8812210195 8812210195 8812210195 8812210195 8812210195	50-259 50-259 50-259 60-259 50-259	# F F	UMETCO Minorals Corp. (aubs. of Union Carbide Corp.)	8912230183 8812230195 8812020194 8812050070	27-48 27-48 40-299 40-299
	8812210188 8812210200* 8812210206 8812210208 8812210208	50-260 50-260 50-269 50-269 50-269	ь ь ь	UNC Recovery Systems	8812050315 8012210250 8812210287 8812210350 8812010402	40-299 40-8681 40-8881 40-299 70-820
	8812210217 8812210221* 8812210221* 8812210221* 8812210273*	50-390 50-390 50-390 60-390 60-259	A A A F	US Council for Energy Awareness Ultrasonic Specialists, Inc. Union Electric Co.	8812990050 8811210133 8811210135* 8811300334 8811300581	PR 71-665 71-665 50-483 50-483
	8612210276* 8812210276* 8812210276* 8812210297 8812210297	50-259 50-259 50-259 50-390 60-390	F F A A		8812050040 8812050319 8812060016 8812060033 8812130062	60-483 50-483 50-483 50-483 60-483
	8812210302* 8812210302* 8812220125 8812230012 8812230012	50-390 50-390 TOPREP 50-390 50-390	A A A		8812130291 8812210057 8812210197 8812210372 8812270208	50-483 50-483 50-483 50-483 60-483
	8812230014° 8812230014° 8812230017 8812230017 8812230017	50-390 50-390 60-259 50-259 50-259	A A P P	Union of Concerned Scientists United Brotherhood of Carpenters & Joiners of America	8812050058 8812010181 8812020054 8812050022	PA PA PA PA
	8812230198 8812230198 8812270104 8812270107* 8812270107*	60-380 50-390 50-259 60-259 50-259	A A P P	United Nuclear Corp. (subs. of UNC Resources, Inc.)	6811230228 8811230240 8812050020 8812050023	70-371 70-371 40-8907 40-8907
Texas, Univ. of, Austin, TX Textron, Inc. Theratronics International, Ltd.	8812270107° 8812080965 8812200041° 8812200103	50-259 60-802 50-416 71-454	P A I	Uranerz USA, Inc.	8812050096 8812050097* 8812070221 8811300379	40-8907 40-8907 70-371 40-8958

AUTHOR APPLIATION	NUMBER	CATEGORY		AUTHUR AFFICIATION	ACCESSION NUMBER	SUBJECT	
Jarum Resources, Inc.	8811300381° 8811300386° 8812200311 8811280050 8812210282	40-8958 40-8958 40-8959 40-8786 40-8968			8812060084* 8812060288 8812070045 8612080124 8812130130	50-397 50-397 50-397 50-397 50-397	>00s0
gry Workers Union of America	8812010077 8812010156 8812010233 8811280174 8811280178*	PR PR PR 50-271 50-271	P P		8812130138 8812150013 8812200086 8512200185 8912200188*	50:397 50:397 50:397 50:397 50:397	F P P P
	8812010087 8812010133 8812060150 8812070029 8812070133	50 271 50 271 50 271 50 271 50 271	H F K P	Washington, Stato of	8612210254 8612210255* 8612220353 8612120095 8812120102	50-397 50-397 50-397 WASTE MGT WASTE MGT	Ö P
	8812070134* 8812090298 8812090306 8812090307* 8812120015	50-271 50-271 60-271 50-271 50-271	O P P O	Washington, Univ. of, Seattle, WA Water, Waste & Land, Inc. West Nowbury, MA	881212010B 8812190146 8811290176* 8812020074 8812270075	WASTE MGT 50-139 WASTE RES 50-443 50-443	F G
	8812140075 8812140086 8812140093 8812140111 8812140229	50-271 50-271 50-271 50-271 50-271	G G G F	West Val'oy Nuclear Services Co∵inc.	8812270075 8812270087 8812270087 8812280091 8812050160*	50-443 50-443 50-443 50-443 PROJ	6 6 6
litures, inc. (subs. of Sheller-Globe	8812140264 8811290574	50-271 PT21	П	Waster Services, Inc. Western Nuclear, Inc. (subs. of Phelps	8812090188° 8811280053	COMMISSIO 40-1182	N
(cr) (rana Power (Virginia Electric & Powe (c)	8811230272	50-280	s	Dodge Corp.)	8812050174 8812050309	40-1162 40-1162	
w1	8811230387 8811280072 8811290019 6811300374 8811300394	50-280 50-280 60-338 50-260 50-280	р S О Р F	Western Water Consultants, Inc Westinghouse Electric Corp.	8812060167* 8811280117* 8811300582* 8812070182* 8812090283*	40-8502 TOPREP 50-483 50-338 50-266	P P
	8812010031 8812010031 8812010032' 8812010032' 8812010037	50-338 50-338 60-338 60-338 50-280	Р Р Р		6812090265* 8812130111 8812130171* 8812150107* 8812150269*	50-266 70-1151 CONTRACT 50-309 50-275	P P
	8812010037 8812010187 8812020093 8812050105 8812080025	50-280 50-339 PR 50-281 60-338	F S P S		8812150270* 8812160016* 0812160018* 8812160027* 8812160028*	60-275 50-276 50-276 50-276 50-276	Р Р Р
	8812060085 8812060085 8812060102 8812060102 8812060281	50-338 50-338 50-280 50-280 60-280	P P P S		8812200270 8812200317 8812210031* 8812210034* 8812210145	TOPREP 70-1151 50-498 50-498 71-24	р Р
	8612070084 8812070089° 8812070208 8812130066 8812130066	50-338 50-338 50-280 50-280 50-280	P P S F		8812210152* 8812220037 8812220130 8812220163 8812220211*	71-24 TOPHEP 71-9229 50-482 50-295	P P
	8812130071 8812130071	50-260 50-260	F	Westinghouse Hanford Co Westinghouse Operating Plants Owners	8812270284 8811280108	XPORTLIC TOPREP	
	8812130071 8812130081 8812130081	50-280 50-280 50-280	F F F	Group Weston (Roy F. Weston, Inc.) Weston Geophysical	8812020189° 8812060251°	40-8902 50-440	Я
	8812130081 8812150122 8812160135 8812160135 8812150137*	50-280 50-280 50-280 50-280 50-280	F S P P	Weston Geophysical Corp. Whittaker Corp. Winthrop-Univ. Hosp., Long Island, NY	8812010278* 8811230220 8812230169 8812230174 8812080228	CONTRACT 40-7455 40-7455 40-7455 PRM	
	6612160137* 6812160190 6812190397 8812200067 6812200067	50-280 50-280 50-338 50-280 50-280	\$ 8 G G	Wiscons'n Electric Power Co.	8811290021 8812010008 8812050121 8812050121 8812050188	50-256 50-266 50-266 50-268 50-266	Q S P P
	8812200104 8812200104 8812200157 8812200157 8812200170	50-280 60-280 60-338 50-338 50-280	R R R R O		8812080221 8812080090 8812080090 8812090281 8812090281	50-301 50-268 60-266 50-266 50-268	Q የ የ የ
	8812200170 8812220080 8812220080 8812230275 8812270201	60-280 50-338 50-338 50-338 50-280	Q F F P		8812190218 8812190218 8812200173 8812210095 8812270234	60-286 60-266 50-268 50-266 60-286	R C S S
Vignia, Univ. of, Charlottesville, VA Washington Public Power Supply System	8812270232 8812270243* 8812010059 8812010079* 8811300235	60-280 50-280 50-396 60-396 50-508	Р Р Р А	Wisconsin Public Service Corp.	8811290038 8812010413 8812060030 8812090107 8812090109*	50-305 60-305 60-305 50-305 50-305	QHPP P
	8812010001 8812020098 8812020259 8812050015	50-397 50-397 50-397 PR	J P Q	Wolf Creek Nuclear Operating Corp.	8612090146° 8812140040 8812220132 8810280324°	50-305 50-305 50-305 50-482	P P Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	ſ : Y	AUTHOR AFFILIATION	ACCESSION NUMBER	
Wyoming, State of	8812200208 8812200349 6812210119 8812210401	50-482 50-482	הייסה ממ יה סממממ ממדס	Yankee Atomic Electric Co.	8812050079 8812210020 8812210305 8812210307 8812210307 8812210309 8812210309 881220309 8812050003 8812060185 8812060278 8812060277 8812080044 8812090062	40.898 40.449 40.4997 40.897 40.897 50.29 50.29 50.29 50.29 50.29 50.29 50.29 50.29 50.29 50.29

REPORT NUMBER INDEX

The subject category column in this index gives the acket number and the symbol for the category of formation within that docket; for example,50-233 P. The docket subject categories are defined in Appendix A.

\$5);ect categories for nondocketed items are also elered in this column by symbol; for example, 40RS.

These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUB- JECT CATE- GORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	N SUB- JECT CATE- GORY	OTHER REPORT NUMBER
(801-17 527 DRFC P04 5110,11258 (6548 P01 5163743-17	8812190201* 8812220064* 8812140201* 8812050172* 8811280040*	WASTE RES WASTE MGT WASTE MGT 50-440 TOPREP	NRC-02-85-002	NUREG-1272 V02 N02 NUREG-1275 V03 NUREG-1328 NUREG-1329 NUREG-1330	8812020172 8812180085 8812280105 8812280087 8812280076	NUREG NUREG NUREG NUREG NUREG	
#3061-07 90120-07 9700 901-01-800 1933-3-87 DRFT	8812190335* 8812190337* 8812270243* 8812190409* 8811180348	50-454 50-280 50-312	К К Р Р О ТАС M66591	NUREG-1333 DRFT FC NUREG/CP-0095 NUREG/CP-0099 NUREG/CR-2000 V07N10 NUREG/CR-2907 V07	8812020311 8812260114 8812020368 8812190133 8812010047	NUREG NUREG NUREG NUREG NUREG	SAND88-1836 PNL-SA-18308 ORNL/NSLIC-200 BNL-NUREG-51581
1953-3-87(-1) R90 1953-3-87(-2) R00 1953-3-87(-3) R00 1964-2-R90 490/E706	8811180327 8811180341 8811210080 8811210050 8812050054	50-352 50-322	Q TAC M66591 Q TAC M66591 Q TAC M66591 Q TAC M66591	NUREG/CR-4527 V02 NUREG/CR-4639 V03 P1 NUREG/CR-4639 V03 P2 NUREG/CR-4839 V03 P3 NUREG/CR-4828	6812190075 6812190018 6812190037 6812190066 6812190123	NUREG NUREG NUREG NUREG NUREG	SAND86-0336 EGG-2458 EGG-2458 EGG-2458 MEA-2188
(\$28-140) (\$28-150) (\$28-88,NP) \$00 \$41:915Å XEJEA-0368	8812120145* 8812120147* 8812220341* 8812210130* 8811140171*	60-416	թ թ	NUREG/CR-4918 NUREG/CR-4960 NUREG/CR-5053 NUREG/CR-5133 NUREG/CR-5135	8812190322 8812010073 8812010086 8812010060 8812020179	NUREG NUREG NUREG NUREG NUREG	SAND87-0958 ANL-87-22 BNL-NUAEG-52118 LBL-21967 LA-UR-88-2871
XEE S-0136 XEELW-72T VO3 XELLW-72T VO4 XELLW-73T XELLW-73T VO2	8812090141* 8812050114* 8812050119* 8812050102* 8812050107*	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT		NUREG/CR-5171 NUREG/CR-5180 NUREG/CR-5183 NUREG/CR-6190 NUREG/CR-5219	8812190120 8812190153 8812020166 8812010349 8812010353	NUREG NUREG NUREG NUREG NUREG	ANL-88-27 ANL-88-30 ORNL/TM-10830 PARAMETER IE172 SAND88-7118
E:521 E:30007 R A E3-EA-7106 R02 E6-4TA-7301 E5-4TA-7317	8812080031* 8811290272* 8811180312 8811210007* 8811170247*	71-9233 60-267 50-247 50-458 60-397	S Q TAC M66591 P GL-83-28 P GL-83-28	NUREG/CR-5220 V01 NUREG/CR-5220 V02 NUREG/CR-5226 NUREG/CR-5232 NUREG/CR-5240	6812020164 6812020159 6812190094 6812010333 6812010069	NUREG NUREG NUREG NUREG NUREG	CREARE TM-1189 CREARE TM-1189 EGG-2548 BNL-NUREG-52164
53 NTA-7432 55-YTA-8142 55-REQ-7601 DRFT 55-REQ-7746 ORFT 55-SQ-7537	8811220443* 8810120268* 8811180299 8811210082 8710140322*		P GL-83-28 P GL-83-28 O TAC M66591 O TAC M66591	NUREG/CR-5248 ORAU 88/J-79 ORO-4014-18 PGE-1043 A 02 PSE-03-103 R00	8012010343 8812090104* 8812070170 8812270163 8812190031*	NUREG 70-734 60-83 50-344 60-354	PNL-6701 FI P P
6550-7619 5550-7623 5555RE-8016 DRFT 9 A1301CA A 10 908 65 V31 R01	8710140219* 8710140231* 6811180354 8812210403* 6812220303*	50-275 50-276 50-423 TOPREP 71-8346	Q Q TAC M68591 GA-LTR-11	RDE 13-0587 RDS-25506-01-NP-A R1 SAIC-88/3028 PT02 SASR 88-82 R01 SASR 88-84 R01	8812070146* 8812080060* 8809130098* 8811290357* 8811290355*	50-220 TOPREP TOPREP 50-277 50-277	Q DRF C11-00184
143316 1/302488 9 4031577 4500-83-003 R00 456-0033 R00	8812200249* 8811150355* 8812190355* 8812120151* 8812220214*	50-425 60-277 50-454 60-416 50-295	А Р К Р Р	SECY-86-101A SECY-86-243 SECY-88-223 SECY-88-039C SECY-88-083	6812120162* 6609040334* 6611170087* 6811280026 6604120011	FOIA FOIA FOIA SECY SECY	2 206 AC56-1 16
4451/68-9 R02 4.9EG-0020 V12 N10 4.9EG-0020 V12 N11 4.9EG-0366 D04 F110 4.9EG-0540 V10 N08	8812160274 8812020180 8812190096 8812190168 8812010368	WASTE MGT NUREG NUREG NUREG NUREG		SECY-88-127 SECY-88-284 SECY-88-302 SL-4482 R01 TDR 950 R00	8812140224* 8811040189* 8812140222* 8812090294* 8812270141*	FOIA FOIA FOIA 50-454 50-219	P S
MRE3-0540 VIO NO9 MRE3-0750 V28 NO3 MREG-0750 V28 NO4 MRE3-0797 S17 VRE3-0797 S18	8812190333 8812020157 8812280060 8812160177 8812160178	NUREG NUREG NUREG 50-445 50-445	E	TR-203A R00 WCAP 9245 AOD 01 R00 WCAP-11695 WCAP-11791 WCAP-11916 R00	8611210070' 8612210152' 8612150270' 8612070162' 8611280117'	50-293 71-24 50-275 50-338 TOPREP	P P P
VAEG-0797 S19 VAEG-0797 S20 VAEG-0933 S08 VAEG-1214 R04	8812180181 8812190088 8812020170 8812010358	60-445 60-445 NUREG NUREG	E	WCAP-11966 WCAP-12065 WCAP-12071 V02 ADD02 WCAP-12087	8812160018° 8812160029° 8812090285° 8812210034°	50-276 50-275 50-266 50-408	P P P

listed as enclosures are those indicated by an isk following the accession number in the indexne second column gives the accession number of principal document under which the enclosure ed. Knowing the accession number of the prindocument, the date issued, and the category enclosure the title listing of the enclosure.

subject category column in this index gives the et number and the symbol for the category of nation within that docket; for example, 50-320P. docket subject categories are defined in Appen-

ACCCUAN MUMBED

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

CCESSIO	N NUMBER				ACCESSIO	ON NUMBER			
WRE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	1
213	8812120044	88/11/28	FOIA		8811210135	8811210133	88/11/16	71-665	
350	8812120044	88/11/28	FOIA		8811220208	B812050060	88/11/18	50-440	S P
393	6812010234	88/02/12		P	8811220443	8812070135	88/11/29	50 528	Į,
997	6812010234	88/02/12			8811230010	6811220324	88/11/10	50-213	Ò
075 364	8811160211 8812010234	88/11/22 88/02/12	18E REVIEW GR		8811230019 8811230065	8811230015 8811230054	88/11/10 88/11/08	50-400	ā
365 153	9912190181	88/12/15	40-2253		9811230088	8811230077	88/11/17	MISC 50-293	F
159	8812190161	68/12/15	40.2253		8811230104	8811230101	BB/11/18	50-283	Ä
334	8812290266	88/12/20	FOIA		8811230186	88112301B3	88/11/04	70-143	•
125	8812290268	88/12/20	FOIA		8811230217	8811230215	88/11/03	50-397	Р
387	8812290228	68/12/27	FOIA		8811230219	8811230216	80/11/17	50-445	Q
292	8812290266	88/12/20	60-440 P	<u>m</u> i	8811230227	8811230225	88/10/31	50-275	b
224	8812120189	88/12/08			8811230233	8811230232	88/10/28	50-206	P
2:0	8812230121	88/12/14 88/12/14	50·275 C 50·275 C 50·483 C 50·293 C 50·341 C	Q :	8811230256	B811230254	88/10/31	40-8971	
231 322	8812230121 8812210283	88/12/14	50·483 C	Ģ :	8811230267 8811230269	8811230266 6811230266	88/11/09	70-1151	
322 334	8812120189	88/12/08	50.293	ă i	BB11230301	8B11230299	88/11/09 88/11/09	70-1151 40-8903	
252	8811300058	88/11/23	50-265 C	ă i	9B11230324	8811230319	88/10/31	40-6622	
507	8812290266	88/12/20	60-440 F	P i	9011280040	8811280038	88/10/18	TOPNEP	
281	8812090279	88/12/02	FOIA		8811280046	8811280042	08/11/04	50-43B	Q
344	8811290342	88/11/21		Q I	8811200051	8811280044	88/11/16	50-344	F
58	8812290266	88/12/20			8811280057	B811280054	88/11/04	50-390	Q
128 051 095	8812290266	88/12/20			8811280059	8811280044	88/11/18	50-344	F
D51	8812060322	88/12/01	70-622		8811280078	B811280073	88/11/23	50-454	Q.
795	8812160037 8812200312	88/12/09 88/12/09	TOPREP 50:255 F	P	3611280087 3611280088	8611280081 8811280083	88/11/10	50-261	ŭ
195 258	6811300099	8B/11/18	50-255 F	r i	9B11280095	8811280091	88/11/23 88/08/17	50-155 50-312	ĕ
C48	8812090174	88/12/07	FOIA		9811280096	8811280081	88/11/10	50-261	ò
684	8812130210	88/12/12	FOIA		8611280097	8811280094	88/11/22	50 295	õ
472	8812060322	88/12/01	70-622		8811280103	8811260101	88/11/15	50-336	P
024	8812060253	88/11/30	60-482 0		8811280105	8811260102	88/11/21	50-305	GFGFGGGFGGPGP
187	8811020184	88/10/21	50-352 F		8811280109	8811280106	88/11/21	50 424	Р
343	8812010210	88/11/18		<u>P</u> !	8811280113	6811280106	88/11/21	50 424	P
125	6811290448	88/11/23			9811280117	8811280108	88/11/21	TOPREP	P
189 281	8812050277 8811100222	68/11/29 68/11/03	FOIA PR		9811280118 9811280125	0812150121 8811280123	88/12/09 88/11/18	50-352 50-163	P
283	8811100222	88/11/03	PR		8811280127	8811280123	88/11/18	50-163	þ
291	8811100222	88/11/03	PR		8811280130	8811280128	88/11/28	ORG	•
291 293	8811100222	88/11/03	PA		8811280132	8811280128	88/11/28	ÖRG	
295	8811100222	88/11/03	PFI		8611280134	8811280128	88/11/28	ORG	
171	8011140164	88/11/08	WASTE MGT	1	8811280137	8811260131	88/11/23	WASTE MGT	
221 356 357	8811150217	86/11/03			8811280152	8811280148	68/11/21	60 316	Р
355	6811300322	88/11/23			8811280165	8811280163	88/11/23	50-286	P
J57	6812200108	68/12/09	50-318 C		9811280176	6811280123	98/11/18	50-163	P
247 307	8812080120 8811300056	88/11/30 88/11/23	50-397 F 50-468 F	P (9611280178 9611280180	8811280174 8811280175	88/11/18 88/11/21	50-271 50-281	P
307 316	8B12010210	88/11/23 8B/11/18	50-408 F		3811280180 3811280182	8811280175	88/11/21	50-281	5
029	8812010210	88/11/18	50-203 F	P	9811280187	8011280185	88/11/21	50-462	P
331	B812010210	88/11/18	50-293		8611280213	8811280212	88/11/16	50-45B	Р
038 033	8812010210	88/11/18	50.293	je i	8811280214	8811280212	98/11/16	50-45B	Ρ
033	6812010210	88/11/18	50-293 F	Р ;	8811280217	8811280215	88/11/18	50-387	P
C41	8812010210	88/11/18	50-293 F	Р (3811280218	8811280215	88/11/18	60-387	P
042	8812010210	88/11/18	50-293 F	P 1	3811280220	8812210145	88/11/03	71-24	~
042 045 067 070	8812010210	88/11/18	60-293 F	P !	8811290008	8811290006	88/11/18	50-409	ä
767 036	8612010210	88/11/18	60-293 F	۱ ا	3811290011	8611200007	88/11/23	50-322 50-320	×
074	6812010210 6812010210	88/11/18	60-293 F 50-293 F	P 1	3811290026 3811290032	8811290024 8811290025	88/11/23 88/11/10	50-320 50-2 06	X
C77	8812010210 8812010210	88/11/18 88/11/18	50-293 F		9811290035	8811290034	88/11/22	50-272	ă
čei	6812010210	8B/11/18	50-293		BB11290040	8811290034	88/11/22	50-272	aoooooo
Č94	8812010210	88/11/18	50-293 F		9811290043	8811290038	BB/11/16	50-413	ā
Γ΄-	2415410510	00, 11, 10	00 200						

Accession Million

ACCESSIO	N NUMBER			ACCESSI	ON NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGORY
8811293049	8811293036	88/11/16	50-413 Q	8811300272	8811300231	88/11/22	50-458 F
8811290074	8611290059	89/11/21	50-247 Q	8811300290	8811300288	88/11/23	50-5 L
8911290076	8811290059	88/11/21	50-247 Q	8811300295	8811300293	ge/11/17	50-461 u
8811290122	8811290115	87/12/15	50-309 Q	8811300298	8811300298	88/11/15	50:213 0
8811290131	8811290129	88/11/15	50-254 P	8811300309	8811300307	88/11/17	50:387 0
8811290139	8811290134	88/11/23	50-247 Р	8811300312	8811300307	88/11/17	50 387
8811290155	8811290149	88/11/18	50-206 Р	8811300323	8811300317	88/11/16	
8811290156	8811293149	88/11/18	50 206 P	6811300325	8811300322	88/11/23	50-277 P
8811290175	8811290164	88/11/22	50 498 P	8811300326	8811300317	88/11/16	50:333 0
8811290176	8811293166	88/11/18	WASTE HES	8811300329	8811300327	88/11/18	50:267 C
8811290178	8611290145 8811290183	88/11/23 88/11/02	WASTE MGT 50 440 F	8811300338	8811300333	88/11/14	50-387 C 50-277 O
8911290191 8811290205	8811290203	84/12/03	CONTRACT	8811300346 8811300357	8811300342 8811300352	88/11/14 88/11/17	50-346 0
8811290218	8811290213	88/11/25	WASTE MGT	8811300381	8811300379	68/10/03	40-8958
8811290222	8811290219	89/10/31	50:213 P	8811300386	8811300379	88/10/03	40-6958
8B11290229	8811290224	88/11/07	REVIEW GR P	8811300398	8911300379	88/10/03	40-9956
8811290272	8811290266	88/11/22	50-287 5	8811300406	8811300400	88/11/23	50-456 0
8811290276	8811290271	88/11/18	50-313 Q	8811300417	8811300389	88/11/23	XPORTLIC
8811290278	8811290271	89/11/18	50-313 Q	8811300423	8811300421	89/11/18	50-275 U
8811290301	8811290250	88/11/14	TOPREP	8811300438	8811300425	69/11/16	71-6078
8811290314	8811290310	88/11/14	50-263 Q	8811300446	8811300442	88/11/25	50-295 0
8811290344	8811290342	89/11/21	50-346 Q	8811300449	8811300442	88/11/25	50-265 0
8811290355	8811290350	88/11/23	50-277 P	8811303452	8811300448	89/11/18	50-195 R
8811290357	8811290350	88/11/23	50-277 P	8811300453	8811300450	88/11/07	50-237 R
8811290362	8811290360	88/10/24	50-353 A	8811300457	8811300455	88/11/23	50-260 -
8811290365	8811290364	88/11/22	50-272 D	8811300466	8811300432	80/11/23	50-352 A
8811290368	8811290366	89/11/18	70-27	8811300489	8811300482	88/11/23	REVIEW SPIR
8811290374	8811290373	88/11/23	50-346 Q	8811300494	8811300487	88/11/16	50-305 0
8811290377	8811290376	88/11/23	50-346 Q	8811300495	8811300493	88/11/23	50-245 0
88112903 81	8811290345	88/11/18	50 282 Q	8811300512	8811300506	88/11/21	50-282 0
8811290398	8811290392	88/11/15	50 272 C	8811300516	8811300505	88/11/28	40 4492
8811290412	8811290404	88/11/21		8811300517	8811300506	88/1 1/21	50-282
8811290415	8911290408	88/11/23	50-454 P	8811300521	8811300508	88/11/14	50-400
8811290419	8911290408	88/11/23	50-454 P	8811300522	8911300518	88/11/22	50-291
8811290433	8811290429	88/11/18	50 409 J	8811300531	8811300525	88/11/21	50-346
8811290441	8811290434	88/11/21	50 275 P	8811300540	8811300534	88/11/23	50-255
8811290449	8611290444	88/11/16	50-16 J	8811300542	8811300536	88/11/17	50-373
8811290457	8811290451	88/11/23	50-206 P	8811300543	8811300537	88/11/22	50-354 F
8811290460	8811290459	88/11/23	50-298 O	8811300551	8811300547	98/11/17	50-456 0
0811290464	8811290462	88/11/18	50-133 J	8811300554	8811300552	88/11/17	50-297 F
8811290476	8811290474	88/11/23	50-382 D	8811300555	8811300553	88/11/21	50-346 (
8811290477	8811290474	88/11/23	50 382 Q	8811300558	8811300553	88/11/21	60-346
8811290496	8811290490	88/11/21	50-286 Q	8811300561	8811300560	88/11/17	50-267
8811200510	8811290504	88/11/18	50-220 Q	8811300563	8811300560	88/11/17	50-287
8811290511	8811290505	88/11/23	50-255 P	8811300567	8811300565	88/11/1 8	50-250 (
8811290519	8811290514	88/11/28	71-6400	8811300573	8811330571	99/11/1 8	50-424 (
8811290536	8811290531	88/11/21	50-244 P	8811300574	8811300571	88/11/18	50-424
8811290539	8811290531	88/11/21	50-244 P	8811330582	8811300581	88/11/18	50-483
8911290551	8811290548	88/11/21	50 333 O	8912010012	8612010009	B8/11/17	50-313
8811290553	8811290548	88/11/21	50-333 Q	8812010013	8812010010	88/11/29	FOIA
8811290565	8611290563	88/11/21	50-277 Q	8812010032	8812010331	88/11/23	50-338
8811290567 8811290576	8811290583 8811280573	98/11/21 88/11/21	50-277 O 50-277 O 50-293 O	8812010079 8812010083	8812010059 8812010080	88/11/22 88/12/01	50 396 50 499
8811290580	8611233579	88/11/23	50 265 O	8812010085	8812010080	88/12/01	50 493
8811300009	8811330007	88/11/22	50 331 O	8812010091	8812010090	88/11/23	50 320
8811300015	8811300014	88/11/22	70-3054	8812010092	8812010090	88/11/23	50-320
8811300016	8811300014	88/11/22	70-3054	8812010119	8812010116	68/11/28	50-382
8811300017	8811300014	88/11/22	70-3054	8812010124	9812010123	88/11/22	50-331
8811300018	8811300014	88/11/22	70-3054	8812010127	8812010123	88/11/22	60-331
8811300043	8811300040	88/11/22	50-458 P	8812010166	8812010164	88/11/29	60-339
8811300046	8811300040	88/11/22	50-458 P	8812010174	8811230285	88/11/21	50-220
8811300048	8811300040	88/11/22	50-458 P	8812010175	8812010171	88/11/25	50-237
8811300060	8811300058	88/11/23	50-341 Q	8812010182	0812010100	88/11/22	50-277
8811300082 8811300082	881130005B 8811300087	98/11/23 88/11/23	50-341 O 50-237 P 50-458 P	8812010184 8812010188	8812010180 8812010186	88/11/22 88/11/23	50-277 50-259
8811300105	88113000 99	08/11/18	50-458 P	8812010203	8812010201	88/11/30	70-1113
8811300114	8811300112	00/11/18	50-171 J	8812010213	8812010211	88/11/30	50 331
8811300118 8811300119	8811300113 8811300115	88/11/17	40-8027	8812010216	8812010211	88/11/30	60-331 50-416
8811300129	8811300126	88/11/16 88/11/22	60-424 P	8812010220 8812010221	8812010215 8812010214	88/11/29 88/11/18	CONTRACT
8811300132	8811300128	88/11/18	XPORTLIC	8812010237	8812010226	88/11/18	CONTRACT
8811300134	8811300130	88/11/22	50-302 P	8812010245	8812010240	88/11/28	50-327
8811300138 8811300150	8811300128 8811300147	88/11/22 88/11/18 88/11/14	XPORTLIC 50-220 Q	8812010249 8812010252	8812010246 8812010250	88/11/28 88/11/29	50-261 50-219
8811300160 8811300166	8811300159	88/11/22	50-313 Q	0812010253	8812010248	88/11/17 88/11/29	50-334
8811300202	8811300161 8811300199	88/11/18 88/11/18	50-313 Q 50-313 Q 50-139 P	8812010258 8812010260	8812010256 8812010256	88/11/29	50-220 50-220
8811300205	8811300199	88/11/18	50-139 P	8812010287	8812010261	88/11/28	50-416
8811300207	8811300162	88/10/20	ORG	8812010275	8812010274	88/11/29	50-269
8811300214	8811300210	88/11/17	50-382 O	8812010278	8812010276	88/11/18	CONTRACT
8811300222	8811300220	88/11/23	50-289 H	8812010282	8812010280	88/11/18	CONTRACT
8811300224	8811300220	88/11/23 88/11/23	50-289 H	8812010286	8812010284	88/11/18	CONTRACT 70-734
8811300242 8811300246	8811300241 8811300239	88/11/18	50-458 P 50-298 Q	8812010287 8812010204	8812010285 8812010291	88/11/25 88/11/18	CONTRACT
8811300248 8811300257	8911300239 8811300254	89/11/18 88/11/23	50-298 Q 50-298 Q 50-313 Q 50-344 P	8812010296 8812010301	8812010292 8812010297	88/11/28 88/11/23	50:354 50:416
8811300258	8811300253	88/11/16	50-344 P	8812010309	8812010234	88/02/12	REVIEW GR

ACCESSION NUMBER ACCESSION NUMBER

NUCESSIO	M MOWREH			ACCES	DION NOROEN		
BICLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
g+2010620	8812010234	88/02/12	REVIEW GR	P 8812050160	8812050149	88/11/29	PRÓJ
(812010026 (812010331	8812010319	B8/11/28	50-116 I	P 8812050170	8812050169	88/11/28	60-440
(812010331	8812010319	88/11/28		P 6812050172 8812050178	8812050169 8812050176	88/11/28 88/11/30	50-440 50-344
(812019371 (812019376	8812010369 8812010373	88/11/17 88/11/21	40-8943 50-604	A 6812050184	8812050180	88/11/09	40-8911
8812010417	8812010234	88/02/12	REVIEW GR 1	P 6812050166	8812050180	88/11/09	40-8911
817020004	8812020002	88/11/28		J 6812050194	6812050192	88/12/02	50-298 50-208
(a) 2020005 (a) 2020009	8812020003 8812020008	88/11/15 88/11/30	CONTRACT 50-416	8812050196 P 8812050201	6812050192 6812050200	88/12/02 88/11/10	50-298 50-275
412020010 بي	8812020008	88/11/30	50-416	P 8812050203	881205019B 8812050202	88/12/02	50-327
6812020014	8812020012	88/11/28 88/11/21		F 8812050204 3 8812050214	8812050202	88/11/15	60-52 8 50-263
6812020038 6812020043	8912020032 8812020033	88/11/17	50-322 (40-8102	3 8812050214 8812050222	8812050213 8812050148	88/11/29 88/11/30	50-205
6812020042	8812020025 8812020033 8812020026 6812020048 6812020048 6812020068 8812020104	88/11/25	50-443	3 BB12050224	86 12050148 86 12050146 88 12050231	88/11/30	50-425
(a)2020045 (a)2020051	8812020033	88/11/17 88/11/25	40-8102 50-443 (8812050233 8812050244	8812050231 8812050240	88/11/30 88/11/18	50-265 WASTE RES
gs12020053	8812020048	88/11/15	40-299	3 8812050244 8812050245	6812050241	88/11/25	50-425
88*2020059	8812020048	88/11/15	40-299	8812050245 8812050247 P 8812050255	8812050242 8812050250	88/12/02	50-327
8:2020071 8:2020113	8812020068 8812020104	88/11/28 88/11/23		P 8812050255 3 8812050262	881205025U 881205025G	88/11/25 88/11/22	50-424 50-395
15:2020121	9915050104	88/11/23	50-322 (3 8812050264	8812050259 8812050283	88/11/30	60-261
W12020123	8812020104	88/11/23		3 8812050287	8812050265	88/11/23	50-280
812020124 812020130	8812020122 8812020104	88/11/16 88/11/23	40-8857 50-322 (9812050269 3 9812050271	8812050268 8811300101	88/12/01 88/11/23	50-294 TOPREP
88:2020131	8812020122	88/11/16	40-8857	8812050272	6811300209	88/11/18	60-260
8212020141	8812020135	88/11/21	50-224 (50-255 (3 8812050274	8812050273	88/11/23	50-324
812020144 812020148	8812020143 8812020145	88/11/22 88/11/22	50-255 C 50-331 C	9812050275 8812050279	8812050273 8812050277	88/11/23 88/11/29	50-324 FOIA
8812020150	8812020147	88/11/29	50-440 (3 8812050282	8612050280	88/11/23	50- 26 9
&12020151 &12020153	8812020142 8812020152	88/11/30 88/11/29	50-289 £ 50-277 C	P 8812050284 D 8812050285	8811300101 8812050277	88/11/23 88/11/29	TOPREP FOIA
812020154	8812020147	88/11/29		8812050287	8812050277	88/11/29	FOIA
£12020155	8812020146	88/11/14	40-4492	8812050288	8812050283	88/11/30	50-171
8:2020158 8:2020162	8812020142 8812020146	88/11/30 88/11/14	50-289 (40-4492	P 8812050290 8812050291	8812050288 8812050289	88/11/25 88/12/02	50-348 50-328
M*202C175	8812020171	88/11/30	50-293 I	F 8812050298	8812050297	88/12/02	50-285
812020178 812020183 812020187	8812020173 8812020182	88/11/29 88/11/17		P 8812050299 D 8812050311	8812050207 8812050306 8812050327	88/12/02 88/12/02	60-285 60-3 9 0
£ 2020187	8812020167	88/11/29	50-255	8812050330	8812050327	88/12/02	FOIA
89.5050188	8812020185	88/11/18		P 8812050331	8811300327	88/11/18	60-267
8:2020169 8:2020190	8812020174 8812020187	88/11/17 88/11/29	40-8902 50-255	8812050332 8 8812050333	8811300327 8812050327	88/11/18 88/12/02	50-267 FOIA
£12020191	8812020185	88/11/18	60-259	P 8812050337	8812050327	88/12/02	FOIA
612020196 612020201	8812020193 8812020198	88/11/29 88/11/28		0 8812050339 0 8812050342	8912050327 8812050327	88/12/02 88/12/02	FOIA FOIA
£12020202	8812010160	68/11/07	PR	8812060014	8812050308	88/12/02	WASTE RES
8212020206 8212020211	8812020204 8812020207	88/11/28 88/11/30	50-263 0 50-425 /	3 8812060019 A 8812060027	6812060015 6812060023	88/11/28 88/11/28	50-170 50-334
B12020214	8812020186	88/11/28	50-295 C	8812060041	8811300093	88/11/10	50-213
B12020215	8812020213	88/11/23		2 88120 6 0058	6812060051	88/12/01	FOIA
8812020216 8812020234	8812020213 8812020232	88/11/23 88/11/29		3 8812060058 P 8812060066	8812060055 8811300099	88/12/02 88/11/18	50-327 50-458
8812020245	BB12020244	88/11/28	60-328 1	P 8812060067	8812060051	88/12/01	FOIA
8812020246 8812020263	8812020244 8812020264 8812020261 8812020265 8812020268 8812020181	88/11/28 88/11/30		P 6812060070 P 6812060074	6812060051 8812060073	88/12/01 88/12/02	FOIA 50-206
\$5°2C20264	8812020261	88/11/29	70-1100	8812080075	B812060051	88/12/01	FOIA
85-2020264 85-2020268 85-2020270	8812020265	88/11/28		P 8812080076	8812060073	88/12/02	50-206
6812020274	8812020208	88/11/28 88/11/21		P 8812060078 P 8812060079 P 8812060081	8812060069 8812060072	88/12/01 88/12/02	50-265 50-327
8812020276	8812020181	88/11/21	50-260 I	P 8812060081	8812060051	88/12/01	FOIA
M15050589	8812020283 8812020283	88/11/28 88/11/28		P 8812060082 P 8812060084	8812060060 8812060080	88/11/10 88/11/10	60-397 60-397
8112020304	8812020303	88/11/29	50-382	2 8812060087	8812060051	88/12/01	FOIA
812920305 812920307	8812020303 8812020306	88/11/29 88/11/28		2 8812060089 2 8812060091	8812060069 8812060083	88/12/01 88/11/28	50-255 50-206
8412020309	8812020306	88/11/28		3 B812060093	8812060083	88/11/28	50-206
8812020314	6812020313	88/11/29	50-285	3 6812060096	8812060083	88/11/28	50-206
812050010 812050037	8812050006 8812050036	88/11/16 88/11/29	CONTRACT 50-316	B812060097 P B812060099	8812060069 8812060051	88/12/01 88/12/01	50-255 FOIA
8812050047	6812050044	88/11/28	60-293	F 8812060101	8812060069	88/12/01	50-255
8812050057 8812050061	6812050066 8812050060	87/06/04 88/11/30	PFI 50-268 I	8812060108 P 8812060110	8812060051 8812060073	88/12/01 88/12/02	FOIA 50-206
6412050067	8812050060	88/11/18	50-260	S 8812060113 P 8812060119	8812060073	88/12/01	FOIA
8812050084	8812050083	88/11/30			8812060051	88/12/01	FOIA
6312060093 6312060097	8812050059 8812050060 8812050083 6812050091 6812050096	88/11/30 88/11/08	50-425 40-8907	A 8812060123 8812060130	8812060051 8812060051	68/12/01 88/12/01	FOIA FOIA
8312050102	8811090114	88/11/07	WASTE MGT	8812060132	8812060051	88/12/01	FOIA
6812050106 6812050107	8811210133 8811090114	88/11/16 88/11/07	71-865 WASTE MGT	8812060138 8812060140	8812060051	88/12/01 88/12/01	FOIA FOIA
68120601 64	8811090114	88/11/07	WASTE MGT	8812060145	8812060051 8812060142	88/11/30	60-456
812050118 812050131	8811090114 8812050130	88/11/07 88/11/10	WASTE MGT 50-269	8812060146 F 8812060151	8812060051	68/12/01	FOIA
8812050132	8812050130	B8/11/10	50-269	F 8812060153	8812060149 8812060051	88/11/30 88/12/01	60-282 FOIA
8612050135	8812050133	88/10/31	40-8064	8812060166	B812060051	88/12/01	FOIA
8:12050138 8:12050139	8812050133 8812050134	98/10/31 98/11/28	40-8064 60-20 I	6812060159 P 8812060164	8812060051 8812060051	88/12/01 88/12/01	FOIA FOIA
8612050141	8812050127	88/11/29		P 8812060167	8812060161	88/10/31	40-8602

ACCESSION NUMBER ACCESSION NUMBER

ACCESSION	II NOMOLII			70020010	N HOMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8812060169	8812080051	88/12/01	FQIA	8812060015	8812080014	88/11/28	50-320 P
8812060173	8812060170 8812060181	88/11/28	50-280 Q	8812080016	8812080011	88/12/01	COMMISSIO N
8812060174 8812060178	8812080051	88/10/31 88/12/01	40-8502 FOIA	8812080019 8812080020	8812080014 8812080017	88/11/28 88/11/21	50-320 P 50-335 O
8812050180	8812060051	88/12/01	FOIA	8812080021	8812080014	88/11/28	50-320 P
8812060184 8812060185	8812080181	88/12/01 88/11/22	50-424 P 50-29 P	8812080022 8812080028	8812080014 8812080026	88/11/28 88/11/22	£0-320 P 70-1151
8812060189	8811300109 8812060051	88/12/01	FOIA	8812080031	6812080014 6812080026 6812080024 6812080032	88/11/22	71-9233
8812060189 8612060192 8812060194	8812060051 8812060161	88/12/01 88/10/31	FOIA 40-8502	8812080034 8812080036	8812080032 8812080035	88/12/05 88/12/02	50-338 P 50-285 P
8812060197 8812060198	8812060161	88/10/31	40-8502	8812080037	8812080035 8812080033	88/12/02	50-285 P
8812060198 8812060200	8812060161 8812060051	88/10/31 88/12/01	40-8502 FOIA	8812080039 8812080041	8812080033 8812080038	88/11/23	50-260 Q 50-338 P
8812060200	8812060181	88/10/31	40-8502	8812080041	8812080038	88/12/05 88/12/05	50-338 P
8812060201 8812060203	8812060051	88/12/01	FOIA	8812080044	8812050268	88/12/01	50-294 P
8812060205 8812060207	8812080051 8812060202	88/12/01 88/11/30	FOIA 50-425 Q	8812080045 8812080049	8812080040 8812080048	88/11/18 88/11/10	COMM SSIO N 50-277 H
8812060209	8812060051	88/12/01	FOIA	8812080051	8812080050	88/11/23	50-250 0
8812060211 8812060212	8812060051 8812060210	88/12/01 88/10/31	FOIA 40-8684	8812080054 8812080058	8812080050 8812080057	88/11/23 88/11/23	50-250 0 60-250 0
8812060215	8812060051	88/12/01	FOIA	8812080059	8812080057	88/11/23	50-250 0
8812060216 8812060220	8812080213 8812060051	88/11/29 88/12/01	50-317 P FOIA	8812080060 8812080084	8812080056 8811170122	88/11/23 88/11/10	TOPAEP 50-341 U
8812060223	8812060051	89/12/01	FOIA	8812080067	8812050268	88/12/01	50-294 P
8812060225 8812060228	8812060051 8812060051	88/12/01 88/12/01	FOIA FOIA	8812080072 8812080087	8809130261 8812080088	88/07/01 88/11/30	PROJ VIJTEORK
8812060233	8812060051	88/12/01	FOIA	6812080091	8812080089	88/12/05	50-322 K
8812060240	8812060051	68/12/01	FOIA 50-320 P	8812080093	6812080090	88/12/02	XPORTUC
8812060241 8812060243	8812060239 8812060235	88/12/01 88/11/22	50-320 P 50-259 P	8B12080094 B812080095	8812080089 8812080080	88/12/05 88/12/02	50-322 K XPORTLIC
8812060245	8812060051	88/12/01	FOIA	8812080099	8812080096	88/11/29	50-333 P
8812080248 8812060251	8812060235 8812060249	88/11/22 88/11/28	50-259 P 50-440 R	8812080106 8812080107	8912080104 8812080103	88/12/01 88/12/01	50-416 K 50-334 P
8812060261	8812060260	88/11/30	50-333 Q	8812080116	8812080113	88/11/22	50-400 (2
8812060264 8812060268	8812060262 8812060262	88/12/02 88/12/02	WASTE MGT WASTE MGT	8812080118 8812080121	8812080113 8812080120	88/11/22 88/11/30	50 400 Q 50 397 P
8812080270	B812060285	88/12/01	FOIA	8812080130	8812080128	88/12/05	50 317 P
8812060271 8812060275	8812060267 8812150246	99/11/23 88/12/09	50-400 Q WASTE MGT	8812080135 8812080148	8812080127 8812080142	88/11/28 88/12/02	71-9200 xPORTLIC
8812060289	8812010050 8812060291	88/11/28	ЯФ	8812080164	8812080163	88/11/28	50-247 Q
8812060292 8812060304	8812060291 8812060303	98/11/22 88/11/30	50-309 P 50-219 Q	8812080156 8812080162	8812080165 8812080159	88/11/30 88/11/30	50-244 Q 50-280 Q
8012080307	8812060303	88/11/30	50-219 Q	8812080185	6812080163	88/11/29	50-280 Q
8812060314 8812060316	8812060303 8812060312	88/12/01 88/12/01	70-2932 70-2032	8812080168	8812080167	88/11/28 88/11/28	50-280 0 50-327 0 60-327 0
8812060317	8812060312 8812060312	88/12/01	70-2032	8812080170 8812080173	8812080167 8812080171	88/12/02	XPORTLIC
8812060327	0012000322	88/12/01	70-622	8812080182	8812080181	88/11/29	50-280 Q 50-280 Q
8812060328 8812060330	8812060322 8812060322	88/12/01 88/12/01	70-822 70-622	8812080184 8812080188	8812080181 8812080185	88/11/29 88/12/02	50-280 O XPORTLIC
8612060337	8812060336	88/12/05	50-483 P	8812080190	8812080189	88/11/28	50-327 0
8812060338 8812080339	8812080335 8812060336	99/11/30 88/12/05	50-322 P 50-483 P	8812080193 8812080195	6812080192 8812080194	88/11/29 88/11/30	50-250 O 50-327 O
8812060340	8812060335	88/11/30	50-322 P	8812080212	8812080209	88/11/26	60-244 Q
8812070016 8812070018	8812070010 8812070017	88/12/01 88/12/02	50-293 F 50-418 P	8812080224 8812080229	8812080222 8812080227	88/12/01 88/12/05	50-327 O 50-250 O 50-327 O 60-244 O 50-264 O 50-327 P 50-334 O
8812070027	8812070025	88/11/28	60-369 P	881 <i>2</i> 080234	8812080232	88/11/21	50-334 Q
8812070034 8812070038	8812070033 8812070035	88/11/18 88/12/02	50-264 P 60-295 P	8812080235 8812080242	8812080233 8812080240	88/11/30 88/11/01	50-335 Q PR
8812070042	8812070040	88/11/29	50-373 P	8812090004	8812090003	88/11/22	50 458 P
8812070070 8812070089	8812070088 8812070084	88/11/22 88/11/30	50-312 Q 50-338 P	8812090008 8812090009	8812090007 8812090007	88/07/05 88/07/05	50-170 P 50-170 P
8812070107	8812070106	88/12/02	50-499 Q	8812090010	8812090007	88/07/05	50-170 P
8912070112 8812070120	8812070110 8812070116	80/12/05	50-317 P 50-338 P	8812090011	8812090007	88/07/05 88/11/30	50-170 P 60-247 P
8812070134	8812070133	88/12/05 88/11/30	50-271 P	8812090013 8812090034	8812090012 8812090029	88/11/22	50-269 F
6812070146	8812070141	88/12/02	50-220 Q	8812090060	8812090036	88/12/05	50-315 P TOPPEP
8812070160 8812070161	8812070157 8812070157	88/12/05 88/12/05	50-416 P 50-416 P	6812090086 8812090087	8812090082 8812090085	88/11/28 88/12/05	60-269 P
8812070182	8812070157	88/12/05	50-416 P	8812090093	8812080091	88/12/06	50-440 P
8812070173 8812070182	8811300456 8812070084	88/11/17 88/11/30	50-499 Q 50-338 P	8812090098 8812090104	8812090097 8812090101	88/12/06 88/11/30	60-333 F 70-734
8812070188	6812070187	88/11/29	50-275 P	8812090109	8812090107	88/11/23	50-305 F
8812070189 8812070202	8812070187 8812070201	88/11/29 88/12/01	60-275 P ORG	8812090120 8812090132	8812090118 8812090128	88/11/25 88/11/22	50-83 V 70-143
8812070222	8812070218	88/11/29	50-244 P	8812090140	8812090138	88/11/22	50·425 C
8812070225 8812070231	8812070218	88/11/29 88/12/02	50-244 P 60-374 P	8812090141	8812090139	88/12/06 88/11/25	WASTE MOT 50-424 Y
8812070240	8812070229 8812070237	88/12/06	50-327 P	8812090142 8812090145	8812090134 8812090134	88/11/25	50-424 V
8812070245 8812070246	8812070241 8812070242	88/11/28	50-293 H	8812090146	8812060030	88/11/30 86/12/05	50-305 F 50-424 F
8812070248	6812070247	88/11/18 88/11/23	70-27 50-280 Q	8812090154 8812090158	8812090153 8812090153	88/12/05	50-424 F
8812070254	8812070249	88/11/28	71-4909	8812090159	8812090158	88/12/02	50-382 F 50-382 F
8812070257 8812080005	8812070256 6812080004	88/12/06 88/12/05	50-327 P 50-322 G	8812090160 8812090165	8812090158 8812090163	88/12/02 88/12/06	50-336 F
8812080006	8812080001	88/11/28	50-424 Q	8812090166	8812090163	88/12/06	50-336 F
8812080009 8812080012	8812080001 8812080010	88/11/28 88/11/22	50-424 Q 50-424 Q	8812090167 8812090169	8812090164 8812090164	88/12/07 88/12/07	60:331 F 50:331 F
-3:4000-14			JU-10-1	401400100	001200101		

ACCESSION NUMBER

ccessio.	HOMOEN			ACCESSI	ON NUMBER			
URE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
50	8812090178 8812090178 8812090179 8812090178 8812090178 8812090187 8812090178 8812090178 8812090178 8812090194 8812090178	88/11/30	COMMISSIO N	8812120131	8812120127	88/12/08	50-416 F	P
30 82 83 48 53 83 53 83 85 75	8812090178 6812090179	88/11/30 86/12/05	COMMISSIO N 40-7604	8812120138 8812120140 8812120145	8812120127 8812120127	88/12/06 88/12/06	50-416 F	P P P P
ŝ	8812090178	88/11/30	40-7604 COMMISSIO N COMMISSIO N	8812120145	8812120127	9B/12/06	50-416 F	É
9.8 31	8812090178 8812090187	88/11/30 88/11/28	COMMISSIO N 60-57 Q	BR12120147	BB12120127 BB12120127	88/12/06 88/12/06	50-416 F	Þ
ěά	8812090178	88/11/30	COMMISSIO N	8812120151 8812120162 8812120165 8812120181	B812120159	88/12/09	FOIA	•
35 37	8812090178	88/11/30 88/11/28	COMMISS:O N 50-219 Q	8812120165	8812080068 8812120172	88/12/01	WASTE MGT	_
 58	8812090178	88/11/30	COMMISSIO N	8812120201 8812120203	8812120199	88/11/22 88/12/05	50-387 F 50-289 C 50-206 F	3
00 7.7	8812090194	88/11/28 88/11/30	50-219 Q COMMISSIO N	8812120203 8812120207	8812120200	80/12/08	50-206 F	5
11	8812090206	88/11/21	50-454 R	8812120207 8812120238	8812120200 8812120235	88/12/08 88/12/08	WASTE MGT	•
12 15	8812090178 8812090214	88/11/30 88/12/06	COMMISSIO N 50-213 P		8812120189 8812120241	88/12/08 88/12/05	50-293 F 50-354 F	-
17	8812090214 8812090178	88/11/30	COMMISSIO N	8812120242 8812120248 8812120248 8812120250 8812120251	B812120189	88/12/08	50-293 F	2
115 20	6812090214 6812090178	88/12/06 88/11/30	50-213 P COMMISSIO N	8812120248 8812120250	8812120245 8812120214	88/12/02 88/12/09	50-317 P 50-245 P	3
21	8812090206	88/11/21	50-454 R	8812120251	8812120214 8812120249	88/12/01	50-346 F	•
25 23	8812090178 8812090208	88/11/30 88/11/21	COMMISSIO N 50-454 R	8812120255 8812120261		88/12/01 88/12/05	50-346 F 50-298 J]
28	8812090178	88/11/30	COMMISSIO N	8812120262 8812120265	8612120266 8612120169 8612120169 8612120169 8612120169 8612120169 8612120003	88/12/08	50-293 R	
31 31	8812090206 8812090222	88/11/21 88/12/05	50-454 R 50-390 A	8812120265 8812120268	8812120264 8812120189	88/12/06 88/12/08	50-293 R 50-424 F 50-293 F 50-293 F	3
38	8812090178	88/11/30	COMMISSIO N	8812120269	8812120189	88/12/08	50-293 F	•
118 221 225 227 238 40 448 552 553 71 77	8812090239 8812090246	88/12/08 88/12/03	50-346 P WASTE RES	8812120270 8812130004	8812120189 8812130003	88/12/08 88/12/08	60·293 F 50·286 F	,
5ê	8812090246 8812090253	86/11/22		8812130005	0012130002	88/12/02 88/12/02	50.315 (*)	٥
62 68	8812090260 8812090263	88/12/05 88/11/25	50-425 Q 50-341 Q 50-424 Q 50-440 P 60-440 P	8812130009 8812130020	8B12130007	88/12/02	50-286 P	,
\tilde{n}	0012000020	88/12/08	50-440 P	8812130021	8812130018 8812130018	88/11/30	50-352 Q	í
75 72	8812090270 8812090284	88/12/08 88/11/29	60-440 P PROJ	8812130036 8812130045	8812130034 8812130007	88/11/30 88/11/30 88/12/05 88/12/02 88/12/02	50-286 F 50-352 Q 50-352 Q 50-352 Q 50-286 P 50-286 P	į
78	8812090273	88/11/25	50-324 Q 60-266 P	8812130046	8B12130044	88/12/02	50-285 J 50-286 P 50-331 Q 50-286 P	•
33 34	8812090270 8812090264 8812090273 8812090281 8812090273	88/11/30 88/11/25	50-324 Q 50-266 P 60-324 Q 50-268 P	8812130048 8812130051	8812130003 8812130050	88/12/08 88/12/05	50-286 P	
78 33 34 35 95 96 91 96 01 07	8812080281	88/11/30	60-268 P	8812130051 8812130057	8812130050 8812130054 8812130061	98/12/08	50-254 Q 50-260 P XPORTLIC	5
9C	8812090279 8812090288	88/12/02 88/11/21	FOIA 60-302 Q	8812130062 8812130064	8812130061 8812130061	88/12/06 88/12/06	XPORTUC	
94	8612090286	88/11/30	60-454 P	8812130065	8812130061 8812130061	88/12/06	XPORTLIC XPORTLIC	
96 41	8812090288 8812090279	88/11/21 88/12/02	60-302 Q FOIA	8812130067 8812130070	8812120189 8812130083	88/12/08 88/12/01	50-293 P 40-6500	,
Ŏ7	8812090306	88/12/05	60-271 P	8812130073 8812130074	8B12120189	88/12/08	50-293 A XPORTLIC	t
08 09	8812090279 8812090302	88/12/02 88/12/05	FOIA 60-482 P	8812130074 8812130078	8B12120189 8B12130068 8B12120189 8B12130075	68/12/07 88/12/08	XPORTLIC 50-293 P	,
(1	8812090302 8812090312	88/12/05	60-482 P	8812130078 8812130080	8812130075	88/12/07	XPORTLIC	
15 16	8812090312 8812090310	88/12/02 88/11/29	60-302 Q WASTE MGT		8812120189 8812130032 8812120189	88/12/08 88/12/09	50-293 P 50-315 P	,
16 17	8812090279	88/12/02	FOIA	8812130063 8812130063 8812130067 8812130068 8812130090 8812130092	8812120189	88/12/08	50-293 P	•
18 22	8812090302 8812090319	88/12/05 88/12/01	50-482 P 60-336 O 60-498 O 60-425 O 50-499 J	8812130087 8812130088	8812120189 8812130075	00/12/08 88/12/07	50-293 P XPORTLIC	,
26	8812090320 8812090323	88/12/05	60-335 O 60-498 O	8812130090	B812120169	88/12/08	50-293 P	>
27 29	8812090323 8812090324	88/12/01 88/12/05	60-425 Q 50-499 J	8812130092 8812130098	8812120189 8812130093	88/12/08 88/12/06	50-293 P 50-390 Q	,
33	8812090279	88/12/02	FOIA	8812130096 8812130106	6812120189	86/12/08	50-293 P	5
39 £2	8812090279 8812090341	88/12/02 88/12/02	FOIA 60-395 Q	8812130120 8812130122	8812130119 8812130119	88/12/07 88/12/07	50-338 P 50-338 P	'n
43	8812090341	88/12/02	50-395 Q	8812130129	B81213D127	88/12/02	50-285 Q)
02 03	8812120001 8812120001	86/11/23 88/11/23	50-397 Q 50-397 Q	8812130132 8812130134	8812130127 6812130133	88/12/02 88/12/05	50-285 C 50-373 C	;
09	8812120005	88/12/08	50-397 Q 50-282 Q	9812130134 9812130136	BB 12130133	88/12/05	50-373 C	į
14 21	8812120012 8812120020	88/12/07 88/11/18	60:395 Q 50:395 Q 50:397 Q 50:397 Q 50:282 Q 50:289 P 50:254 P	8812130141 8812130160	BB12130139 BB12130143	88/12/02 88/10/19	50.390 C 50.293 P 50.238 P 50.338 P 50.285 C 50.373 C 50.373 C 50.458 C 50.259 P 50.229 P	}
118 226 227 239 339 339 342 343 343 344 341 441 441 443	8812120024	88/12/01	50-295 Q	6812130168	6812130149	88/12/08		•
32 35	8812120031 8812120034	88/12/05 88/12/01	70.887	8812130164 8812130165 8812130171	8812130149 6812130169	88/12/08 88/12/07	50-29 P 50-346 P	,
ÃÕ.	8812120034 8812120037 8812120039	88/11/30	50-322 P	8812130171	8812130168	88/11/28	CONTRACT	
41 42	8812120039 8812090279	88/12/02 88/12/02	50-213 Q FOIA	8812130174 8812130180	8812130143 8812130177	88/10/19 88/12/02	50-259 P 60-269 P	
	8812120037	88/11/30	50-322 P	8812130186	8812130184	88/12/02 88/12/07	XPORTLIC	
49 53	8812120048 8812090279	88/12/04 88/12/02	50-309 Q FOIA	8812130187 8812130193	6812130163 8812130186	88/12/12 88/12/07	FOIA XPORTLIC	
62	8812090279	88/12/02	FOIA	8812130194	BB120B0073	BB/12/07	WASTE MGT	
164 165	8812120063 8812090279	88/12/02 88/12/02	50-245 P FOIA	8812130195 8812130201	B812130188 B812080073	88/12/07 88/12/07	XPORTLIC WASTE MGT	
69	8812120066	88/12/04	60-333 O	8812130202	B812130200 B812130204 B812130203	88/12/08	50-346 F	9
49 53 62 64 65 65 70 72	8812090279 8812120044	88/12/02 88/11/28	FOIA FOIA	8812130206 8812130208	6812130204 6812130203	88/12/06 88/09/26	50-315 F FOIA	P
47	8812120085	06/12/06	60-341 Q	8812130209	B812130204	88/12/06	50- 31 5 F	P
68 91 98	6812120078 8812090279	88/12/06 88/12/02	60-339 P FOIA	8812130212 8812130214	BB12130210 BB12130210	88/12/12 88/12/12	FOIA FOIA	
98	8812090279	88/12/02	FOIA	8812130220	8812130210	88/12/12	FOIA	_
99 11	8812120096 8812090279	88/12/05 88/12/02	60-445 Q FOIA	8812130221 8812130228	8812130177 8812130226	88/12/02 88/12/06		P
13	8812120105	88/12/08	60-382 P	8612130230	8812130228	88/12/06	50-416 F	Ρ
22 28	8812090279 8812090279	88/12/02 88/12/02	FOIA FOIA	8812130232 8812130240	8612130226 8612130237	88/12/06 88/12/06	50-416 F 50-418 F	P
		30. /E/ VE		33,2100270	44.2.0000		· · · ·	

ACCES510	N NUMBER			ACCESSIO	N NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8812133241	8812130237	88/12/06	50-416 P	8812150109	8812150102	68/12/08	50-313
8812130242	8812130237	88/12/06 88/11/23	50-416 P 50-275 Q	8812150110 9812150113	8812150092	88/12/02	50-309
8812130245 8812130247	8812130244 8812130246	88/12/07	50-499 A	8812150124	8812150092 8812150123	88/12/02 88/12/08	50-309 50-285
8812130251	8812130205	88/12/07	50-29 P STATE PRO G	8812150127	8812150125	88/12/06	50-206
8812130255 8812130256	8812130253 8812130250	88/12/05 88/12/07	50-499 A	8812150131 8812150137	8812150130 8812150135	88/12/02 88/11/23	50-254 50-280
8812130259	8812130205	88/12/07	50·29 P	8812150141	8812150133	88/11/25	50-206
8812130269 8812130276	8812130266 8812130275	88/12/07 88/12/02	50 293 H	8812150159 8812150173	8812150156 8812150166	88/11/25 88/12/12	50-206 50-219
8812130278	8812130277	68/12/02	50-346 P	8812150200	8812150193	88/12/07	50-267
8812130281 8812130282	8812130279 8812130279	88/12/05 88/12/05	50-327 P	8812150226 8812150233	8812150224 8812150231	88/12/07 88/12/08	50-498 (70-143
8812130289	8812130283	88/12/07	50 219 P	8812150234	8812150232	88/12/08	50-445
8812130292 8812130298	8812130275 8812130296	88/12/02 88/12/09	50-293 H 50-424 P	8812150235 8812150236	8812150221 8812150230	88/12/09 88/12/12	XPORTLIC WASTE MOT
8812130302	8812130299	88/10/27	50-336 P	881215023 <i>7</i>	8812150232	88/12/08	50-445
8812130310 8812140014	8812130309 8812140012	88/12/01 88/12/05	50-247 O 50-354 P	8812150238 8812150257	8812150232 8812150255	88/12/08 88/12/12	50-445 71-506
0812140018	8812130297	88/12/06	50-499 Q	8812150258	8812150256	88/12/12	WASTE MGT
8812140030 8812140033	8812140023 8812140029	88/11/28 88/12/08	50-499 Q 50-443 G 50-259 F 50-260 P	8812150260 8812150282	8812150259 8812150261	88/11/18 88/12/12	50-322 71-849
8812140048	8812140042	88/12/08	50-260 P	8812150263	8812150256	88/12/12	WASTE MOT
8812140084 8812140068	8812140054 8812140058	88/12/02 88/11/29	50-322 G 50-322 G	8612150265 8812150269	8812130204 8812150268	88/12/06 88/12/09	50-315 60-275
8812140077	8812140069	88/12/05	50-285 Q	8812150270	8612150268	88/12/09	60-275
8812140081 8812140083	8812140066 8812140066	88/12/07 88/12/07	50-458 Q 50-458 Q	8812150271 8812160016	8812150267 8812160014	88/12/12 88/12/12	40-8500 50-275
8812140096	8812130311	89/12/08	CONTRACT	8812180018	8812160014	88/12/12	50-275
8812140112 8812140123	8812140105 8812140119	88/12/06 88/12/12	CONTRACT WASTE RES	8812160021 8812160025	8812160020 8812160023	88/12/12 88/12/13	50-298 50-482
8812140124	8812140114	08/12/02	50-443 G	8812160027	8812160026	89/12/12	50-276
8812140125 9812140128	8812140119 8812140114	88/12/12 88/12/02	WASTE RES 50-443 G	8812160029 8812160032	8812160026 8812160030	88/12/12 88/12/05	50-276 50-482
8812140135	8812140114	68/12/02	50-443 G	8812160033	8812160030	88/12/05	50-462
8812140140 8812140142	6812140134 6612140136	88/12/12 88/12/05	WASTE RES 50-274 O	8812160039 8812160060	8812160037 8812160058	88/12/09 88/12/13	TOPREP 71-9180
8812140145	8812010234	88/02/12	50 274 O REVIEW GR P	8612160067	8812180082	68/12/12	50-346
8812140148 8812140150	8812140114 8812140129	88/12/02 88/12/05	50-443 G 50-293 F	8812160075 8812160090	8812180073 8812160089	88/12/09 88/12/13	50-255 50-336 50-338
8812140151	8812140114	88/12/02	50-443 G	8812160093	8812160092	88/12/12	50-338
8812140155 8812140159	8812010234 8812140157	88/02/12 88/12/09	REVIEW GA P 60-259 P	8812160094 8B12160096	8812160092 8812160091	88/12/12 88/08/04	50-338 50-269
8812140161	8812140152	88/12/07	50-482 Q	8812160100	8812160095	88/12/09	60-361
8812140164 8812140166	8812140160 8812140152	88/11/18 88/12/07	50-293 P 50-482 Q	8812160105 8812160106	8812160104 8812160104	88/12/07 88/12/07	50-352 50-352
8812140168	8812140160	88/11/18	50-293 P	8812160109	8812160107	68/12/12	60-255
8812140179 8812140192	8812140173 8812140191	88/12/09 88/12/08	WASTE RES 50-443 Q	8812160110 8812160113	8812160107 8812160099	88/12/12 88/11/15	50-255 50-412
8812140194	8812140191	88/12/06	50-443 Q	8812160115	8812160108	88/12/07	60-424
8812140201 8812140209	8812140199 8812140207	88/12/12 88/12/07	WASTE MGT 50-298 V	8812160124 8812160125	8812160121 8812160123	88/11/18 88/12/12	PROJ 50-261
8812140213	8812140207	88/12/07	50-298 V	8812160128	8812160119	88/12/06	60-324
8812140215 8812140220	8812140214 8811230009	88/12/97 88/10/17	50-285 C 40-8027	8812160127 8812160130	8812160119 8811290392	88/12/06 88/11/15	50-324 50-333
8612140221	8811230008	88/10/17	40-8027	8812160134	8912160132	88/12/07	70-1201
8812140222 8812140224	8812120169 8812120159	88/12/09 88/12/09	FOIA FOIA	8812160135 8812160136	8812160133 8812160131	88/12/13 88/12/05	50-285 50-416
8612140228 8812140238	8812140227	88/12/05	50-413 P	8812160139 8812160144	8812160138	BB/12/18	50-364 50-424
8812140239	8812140235 8812140237	68/12/07 88/12/06	50-461 Q 50-282 Q	8612160155	0812160141 8812160153	88/12/02 88/12/06	60-313
8812140242	8812140240 8812140240	88/12/01	60-315 G	8812160156	8812160140	88/12/05	50-250
8812140244 8812140258	8812140255	88/12/01 88/12/09	50-315 Q 50-456 Q	8812160157 8812160161	8812160153 8812160159	86/12/06 86/11/29	50-313 CONTRACT
8812140257	0812140255	88/12/09	60-466 Q	6812160166	8812160182	88/12/06	50-369 50-369
8812140259 8812150002	8812120256 8812150001	88/12/05 88/11/25	60-466 Q 50-298 J 60-397 Q 50-334 Q	8812160167 8812160169	8812160163 8812180162	88/12/05 88/12/08	50-369 50-369
8812150009	8812150006 8812150008	88/12/07	50-334 Q	8812160170	8812160163	88/12/05	50-369 60-321
8812150016	8812150014	88/12/07 88/12/06	50-334 Q 50-213 Q	8812160174 8812190004	8812160171 8812190001	88/12/06 88/12/09	60-443
8812150043	9812150038 8812150038 8812150038	88/12/08	70-27	8812190005	68121 9 0003	88/12/09 86/12/02	50-390 50-443
8812150049	8812150038	88/12/08 88/12/08	70·27 70·27	8812190007 8812190009	8812190001 8812190006	68/12/09 88/12/05	60-424
8812150065	8812150061	88/12/13 88/12/06	70-2932 CONTRACT	8812180023	8812160187	88/12/10	WASTE RES 60-354
8812150016 8812150043 8812150046 8812150049 8812150066 8812150066 8812150068	8812150061 8812150060 8812150061	88/12/13 88/12/13	70-2932	8812190031 8812190033	8812190026 8812190027	88/12/09 88/12/02	70-143
8812150071 8812150073	8812150061 8812150067	88/12/13	70-2932	8812190040	8812190039	88/12/12 88/12/07	CONTRACT 50-424
8812150073 8812150077 8812150080	8812150007 8812150075 8812150075	88/12/09 88/12/07	50-482 Q 50-244 Q	8812190050 8812190053	8812190045 8812190045	88/12/0/ 88/12/07 88/12/07	50-424
8812150080 8812150084	8812150075 8812150083	88/12/07 88/12/06	60 244 Q	8812190054	8812180045 8812140154 8812180063	88/12/07	70-925 XPORTUC
8812150091	8812130034	88/12/05	50-285 J	8812190065 8812190074	8812190062	88/12/14 88/12/13	50-289
8812150096 8812150104	8812150092 8812150034	88/12/02	50 309 P	8812190077	8812190062	88/12/13 88/12/13	50-289 50-289
8812150105	8812150101 8812150092	88/12/05 88/12/08	XPQRTUC 50-498 Q 50-309 P	8812190081 8812190098	8812190062 8812190093	88/12/07	60-603
8812150107 8812150108	8812150092 8812150106	88/12/02 88/12/01		8812190117	8812190103	88/12/05 88/12/12	50-322 50-424
0016130100	9012100100	00/15/01	50-206 P	8812190118	8812190116	00/12/12	VU-727

ACCESSION NUMBER

ACCESSION NUMBER

CLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
2190126	8812190119	88/12/06	50-603	Ģ	8812190414	8812190413	68/12/02	50 528	Q
12190130 12190139	8612190127 8612190127	88/12/08 88/12/08		G G	8812190415 8812200005	8812190413 8812200003	89/12/02 89/12/14	50-528 50-445	8
12190162	8812190157	88/12/12	50-416 ∣	P	8812200011	6812200007	88/12/14	50-445	OOOR
12190167 12190163	8812190159 8812190159	88/12/15 88/12/15	WASTE RES WASTE RES		8812200013 8812200015	нв12200009 8Б12200008	88/12/13 88/12/13	50-250 50-250	R R
12190172	8812190156	89/12/09	50-322	Ģ	8612200030	8812200025	88/12/14	50 155	P
12190174 12190178	8812190171 8812190171	88/12/01 88/12/01	50-528 (50-520 (0	8812200041 8812200051	6812200028 8812260048	88/12/14 88/12/13	50-416 50-263	þ
12190179	8812190166	88/12/09	50-322	G	B5122C0055	8812200352	68/12/12	50 483	Ċ P
12190192 12190191	8612190176 8812190180	88/12/07 88/12/12	50-322 (40-6500	G	8812200060 8812200063	8812200348 8B12200354	88/12/13 89/12/15	50-263 XPO9TUC	þ
2190199	8812190193	89/12/05	50-327	P	8812200075	881220006B	88/12/08	50 341	Q
2190201 2190202	8812190192 8812190193	88/12/14 88/12/05	WASTE RES 50-327	Р	8812200000 8812200094	8812200037 6812200039	86/12/01 86/12/02	50-206 50-344	COOFC
2190215	8812190205	88/12/07	50 443 (G	8812200097	88122000∋1	68/12/14	50 454	F
12190216 12190222	8612190196 8612190221	88/12/14 88/11/30		K V	8812260098 8812260109	8812200080 8812200108	68/12/02 69/12/09	50-344 50-316	ö
12:90228	8812190225	88/11/30	70-143	P	8812203111	8612200103	88/12/15	71.454	
12 : 90235 12 : 90236	88 12 190232 88 12 190196	88/12/12 88/12/14		K	8812200114 8812200120	0812200110 8312200108	88/12/12 88/12/09	50-322 50-316	Ö
12190237	8812190232	88/12/12	50 387	P	8812200125	8812200103	88/12/15	71 454	
12190259 12190245	8812190234 8812190243	66/12/13 88/12/08	WASTE MGT 50-302 (o	8812200126 8812200130	8612230991 8812209124	88/12/06 88/12/12	50-295 50-312	R P
12190250	8612190196	88/12/14	50-454 H	K	8812200132	6812200129	88/12/07	XPORTLIC	
12190251 12190254	8912190249 8812190196	88/12/08 88/12/14		O K	881220(1148 8812200150	6912200023 8812200023	88/12/15 86/12/15	50-369 50-369	R R
2190258	8812190257	88/12/05	50-424 (Q	8812200164	8812200161	88/12/15	50-250	ŭ
12190259 12190263	8812190196 8812190262	88/12/14 88/12/07		K O	6812200167 6812200176	86122001G1 6812200171	88/12/15 88/12/15	50-250 50-302	0000
2190267	8812190265	88/12/13	50 456 (a	8812200188	8812200185	69/12/02	50-397	ě
2190282 2190293	8812190269 8812190289	88/12/09 88/12/13	CONTRACT FOIA		8812200190 8812200193	8912260023 8812260023	6B/12/15 6B/12/15	50-369 50-369	Ħ R
2190297	8812190289	88/12/13	FOIA	P	8812200204	8812200100	20/12/19	50-309	P
2190299 2190300	0812190292 0812190296	88/12/15 88/11/29	50-364 F	r	6812200210 6812200211	8812200104 8812230177	88/12/19 88/12/12	50-389 50-368	S
2190901	8812190289	88/12/13	FOIA	^	8812200223	6912190196	69/12/14	50-454	S K K
2190305 2190323	8812190303 8812190321	88/12/05 88/12/08		Q Q	8812200226 8812200234	8812190196 8812190196	88/12/14 88/12/14	50-464 50-454	K
2190326	6 612180186	88/12/14	60-454 f	K	6812200237	6812193196	88/12/14	50-454	K
2190327 2190329	8812190196 8812190196	66/12/14 68/12/14	50-454 H 50-454 H	K K	8812200238 8812200242	6812200233 8812200233	88/12/14 88/12/14	50-321 50-321	ä
2190330 2190331	8812190198	88/12/14	50 454	K K	8812200249	E012200202	86/12/13 86/12/09	50-425	K00400PBB
2190332	8812190196 8812190196	88/12/14 88/12/14	50-454 1 50-454 I	Ŕ	8812200271 8812200273	8812200269 6812200260	88/12/09	50-413 50-413	ä
2190335 2190337	8812190196 8812190196	88/12/14	60 464 H	K K	8812200276 8812200277	6812200274 8612200217	88/12/12 88/12/15	50-454 50-413	þ
2190338	8812190196	88/12/14 88/12/14	50-454	K	8812200270	8612260217	88/12/15	50-413	Я
219C339 219C340	8812190334 8812190336	88/12/06 88/12/14	50-312 (50-315 (8812200283 8812200294	6812200217 6812200200	88/12/15 88/12/14	50-413 50-322	R P
2190342	8812190334	88/12/06	60 312	ä	8812200295	8812200242	88/12/12	71.421	
2190344 2190345	8812190196 8812190196	88/12/14 88/12/14		K K	8812200296 8812200297	&B12200231 &B12200232	88/12/13 88/12/15	50-395 50- 2 69	Q R R
2190346	6812190343	98/12/13	50-254 (Q	8812200300	6812270391	88/12/15	50-341	R
2190347 2190349	6612190196 8812190196	88/12/14 88/12/14		K K	8812200301 8812200335	8012200212 8012200334	88/12/15 89/12/68	50-269 50-528	R
2190350	8812190343	88/12/13	50 254 (۵	8812200338	8612200337 6612200339	BB/12/09	50-261	R > 0000 P
2190351 12190352	8812190196 8812190196	88/12/14 88/12/14		K K	8812200341 8812200346	8812200339 8812200345	88/12/12 88/12/12	50-338 50-285	ü
2190353	8812190196	88/12/14	50-454	K	BB12200350	8812200333	69/03/53	REVIEW GR	ē
12190355 12190356	8812190106 8812270057	88/12/14 88/12/16	50-454 I 50-440 I	к 5	8812200353 8812200355	8812200351 8812200351	88/12/69 88/12/09	60-259 50-259	ò
12190357	BB12190196	88/12/14	50-454	K	8812200353 8812200355 8812200372 8812200374	DB12200366	68/15/15	60 341	F
12190360 12190368	8812190196 8812190196	88/12/14 88/12/14	60-454 1 50-454 1	K K	8812200374	0812200366 8912200376)	88/12/12 88/12/14	50-341 50-416	F
2190367	8812190196	08/12/14	50 454	K	8812210018	8812210013	88/12/13	50-317	
12190369 12190370	6812190196 6812190365	88/12/14 88/12/13	50-264 (K O	8812210019 8812210022	8812210017 8812210013	88/11/35 88/12/13	50-528 50-317	99999
2190372	8812190198	88/12/14	50-454	ĸ	8812210023	8812210017	88/11/30	50-528	ŏ
2190373 2190376	8812190196 8812190365 8812190196	88/12/14 88/12/13		K Q	8812210024 8812210031	8812210015 8812210029	88/12/09 88/12/09	50-445 50-498	ě
12190380 12190382	8812190196	89/12/13 88/12/14	50-454	K	8812210034 8812210035	8812210029 8812210028	68/12/09 68/12/05	50-498 50-528	Q
12199383	8812190196 8812190196	88/12/14 98/12/14	50-454 (50-454 (K K	8612216038	8812210033	88/12/14	50-348	ř
2190389 2190390	6812190196 9B12190196	88/12/14	50-454	K K	8612210045 8812210049	8812210041 881221004(88/12/08 88/12/06	40-1162 50-424	Р
2199391	8812190196	88/12/14 88/12/14	50-454	K	8812210050	8612210044	88/12/14	50-395	Ρ
2190392 12190093	8812190196 8812190196	88/12/14 88/12/14	50 454	K K	8812210053 8812210077	8812210017 8812210055	88/12/0B 68/12/14	50:327 50:206	Q
12100094	8812140202	88/12/14 88/10/28	70-143		8812210090	8012210065	88/12/14	60 206	P
12190395 12190400	8812190196 8812190196	88/12/14	50-454	K	8812210366 9812210087	8612210070 8312210065	88/12/16 88/12/14	60 302 50 200	P
12190431	8812190196	88/12/14 88/12/14	50-454 50-454	K K	8812210088	8812210085	08/12/12	50-313	S
12190402 12190403	8812190196 8812190196	0B/12/14 88/12/14	50-454	K K	8812210091 8812210096	8812210065 8812210065	88/12/14 89/12/14	50-206 50-206	P
12190404	8812190196	88/12/14	50-454	K	8812210102	8812210099	68/12/13	50-327	à
12190409	8812190408	88/12/09	50-312	P	8812210104	0812210C98	88/12/01	40-8857	

ACCESSION NUMBER ACCESSION NUMBER

ACCESSIO	it Homben			ACCESSIC	or Homber		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGORY
8812210103	8812210098	88/12/01	40 8857	8812220201	6812220198	88/12/14	50-294
8812210115	8812210114	88/12/15	50-269 P	8812220202	6912220199	88/12/19	50-334
8812210120 8812210122	8812210118 8912210118	88/12/19 89/12/19	50-275 T 50-275 T	8812220204 8812220211	8812220199 8812220206	88/12/19 88/12/15	50-334 50-295
8812210128	8812210118	88/12/19	50-275 T	8812220214	8812220206	88/12/15	50-295
8812210130	8812210126	89/11/23 88/05/18	TOPREP CONTRACT	8812220215	8812220212 8812220208	88/10/03 88/12/12	50-259 (50-298 7
8812210140 6812210152	8812210134 8812210145	88/11/03	71-24	8812220221 8812220224	6812220222	88/12/14	50-338 R
8812210155 8812210171	8812210154	88/12/15 88/11/28	50-425 O 40-3453	8812220224 8812220227	8812220222 8812220222	88/12/14	50-336 50-339
8812210173	8812210139 8812210168	88/12/12	50-289 F	8812220228 8812220235	8812220232	88/12/14 88/12/19	50-335 50-416
8812210185	8812210065	88/12/14 88/12/07	50-206 P 40-8027	8812220236 8812220253	0012220232	88/12/19	50-416
8812210189 8812210193	8812210186 8812210043	88/12/12	50-313 S 50-260 P	8812220255	8812220252 9812220254	89/12/12 88/12/12	40-8828 40-8928
0612210200	8612210199	88/12/16		8812220255 8812220258	8912220257	88/12/16	50-369 F
8812210208 8812210209	8812210204 8812210204	88/12/13 88/12/13	50-458 P	8812220260 8812220260 8812220263 8812220275 8812220273 8812220276 8812220276 8812220283 8812220303 8812220303	8812220257 8812220262	88/12/16 88/12/15	50-389 50-245
8812210210	8812210204	88/12/13 88/12/14	50 458 P 50 390 A	8812220265	8812220262	88/12/15	50-245 F
8812210221 8812210224	6812210223	88/12/14	40-8857	8812220273	8812270268 8812220268	88/12/13 88/12/13	50-334 50-334
8812210233	8612210204 8612210201 86122102217 8612210223 8612210232 8612210232 8612210206 8612210206	88/08/02	WASTE MGT 50-282 O	8812220276	8812220268	88/12/13	60-334
8812210244 8812210255	8812210254	00/12/09 88/12/12	50 397 P	8812220303	8812220282 8812220301	88/12/12 88/12/12	40-8904 71-8348
8812210273	8812210208	88/12/16	60-259 F 50-259 F	6812220323	8812220308 8812220326	88/12/19	60-255 g
8812210278 8812210278	8812210201 6812210184 8812210283 8812210294 8812210297	88/12/16 88/12/12			8812220331	88/12/19 88/12/15	50-346 F 50-271 C
8812210281	8812210184	08/12/12	50-368 S	8612220335	8812220326	88/12/19	50-346 F
8812210284 8812210298	8812210283	88/12/14 88/12/20	50-313 S 50-368 S 50-463 Q 50-322 F	8812220337 8812220338	8812220326 8812220331	88/12/19 88/12/15	50-346 F 50-271 C
8812210302	8812210297	88/12/14	50-390 A	8812220341	8812220328	88/12/16	50-336 P
8812210304 8812210311	8812210301 8812210306	88/12/13 88/12/12	60-313 O 50-443 H 50-285 O	8812220352 8812220371	8812220343 8812220367	68/12/05 86/12/21	50-335 V WASTE MGT
8812210312	8812210308	88/12/14	50-285 Q	8812220385	8812220382	68/12/15	50-456 C
8812210313 8812210315	8812210308 8812210314	88/12/14 88/12/14	50-285 Q 50-317 P	8812220388 8812220391	8812220384 8812220384	88/12/18 88/12/16	50-499 50-489
8812210317	8812210310	88/12/16	QA999	8812220394	8812220384	88/12/16	50-499 P
8812210319 8812210321	8812210310 8812210310	88/12/16 88/12/16	QA999 QA999	8812220397 8812220401	881222039B 8812220400	88/12/15 88/12/12	50-353 Q 50-289 Q
8812210325	8612210323	88/12/16	50-361 P	8812230014	8812230012	88/12/16	50-390
8812210327 8812210328	8812210323 8812210324	98/12/16 88/12/16	50-361 P QA999	8812230022 8812230029	8812230020 8812230027	88/12/15 88/12/20	50:338 0 50:250 8
8812210329	8812210324	88/12/16	QA999	8812230032	8812230030	88/12/08	50-309 Q
8812210335 8812210336	8812210332 8812210332	88/12/15 88/12/15	50-410 P 50-410 P	8812230046 8812230067	8812230044 8812230044	86/12/19 88/12/19	50-361 50-361
8812210337	8812210331	88/12/15	50 482 Q	8812230071	8812230069	88/12/16	50-265 P
8812210338 8812210339	6812210334 8812210334	88/12/16 88/12/16	QA999 QA999	8812230073 8812230084	8812230069 8812230081	88/12/16 88/12/06	50-285 50-295 F
8812210340	6812210334	88/12/18	QA999	8612230080	8812230086	88/12/17	50-322
8812210341 8812210342	8812210331 8812210331	88/12/15 88/12/16	50-482 Q 50-482 Q	8812230092 8812230094	8812230086 8812230086	88/12/17 88/12/17	60-322 50-322
8812210347	8812210346	88/12/14	50-313 Q	8812230107	8812230099	88/12/02	raon .
8812210360 8812210382	8812210356 8812210381	88/11/18 88/12/08	70-27 40-8684	8812230108 8812230109	8812230099 8812230104	88/12/02 88/12/15	PROJ 50-313
8812210366 8812210376	8812210364	88/12/15	50-387 F	8812230111	8812230104	88/12/15	50-313 F 71-3006
8812210393	8812210371 8812210390	88/12/14 88/12/09	50-165 Q 50-454 Q 50-312 P	8812230129 8812230139	8812230125 8812230121	88/11/22 88/12/14	50-275 Q
8812210394 8812210398	8812210383 8812210390	88/12/14 88/12/08	50-312 P	8812230140	8812230134	88/12/06	50-277 Q
8812210398	8812210383	88/12/14	50-454 Q 60-312 P	8812230141 8812230165	8812230134 8812230121	88/12/06 88/12/14	80-277 C 60-276 C
8812210403 8812210405	8812210400 8812210404	88/12/06 88/12/09	TOPREP 50-155 Q	8812230172 8812270024	8812230162	88/12/12 88/12/15	50.454 50.322
8812210408	8812210407	88/12/08	70-1703	8812270045	8812270014 8812270040	68/12/16	50-346 Q
8812220003 8812220019	8812220002 8812220015	88/12/07 88/12/07	50-142 W 50-112 P	8812270048 8812270062	8812270040 8812270057	88/12/16 88/12/16	50-348 0 50-440 5
8812220026	8812220021	88/12/15	50-280 Q	8612270098	8812270091	88/12/16	60-341 F
8812220027 8812220028	8812220025 8812210298	88/12/12 88/12/01	60-482 Q 40-2269	8812270107 8812270117	8812270104 8812270112	88/12/20 88/12/19	50-259 50-361
8812220036	8812220032	88/12/14	50-321 P	8812270127	8812270123	88/12/15	50-440 4
8812220045 8812220057	8812190093 8812220055	88/12/07 88/12/14	50-603 A 50-354 P	8812270131 8812270141	8812270123 8812210355	88/12/15 88/12/15	50-440 4 50-219
8812220058	8812220056	88/12/14	50-352 P	8812270153	8812270151	68/12/15	50-454
8812220061 8812220063	8812220055 8812220055	88/12/14 88/12/14	50-354 P 50-354 P	8812270162 8812270188	8812270160 8812270112	88/12/16 88/12/19	50-220 0 50-361
8812220064	8812220060	88/12/13	WASTE MGT	8812270216	8812210220	88/12/16	WASTE MOT
8812220067 8812220068	8812220062 8812220065	88/12/14 88/12/14	50-333 P 50-382 P	8812270218 8812270219	8812270214 8812270214	88/12/15 88/12/15	60-341 50-341
8812220088 8812220088	8812220065	88/12/14	50-382 P	8812270227	8812270221	88/12/22	FOIA
8812220088 8812220000	8812220085 8812220082	88/12/14 88/12/14	40-3453 50-382 P	8612270229 8812270230	8812270225 8812270228	88/12/16 88/12/16	50-443 C 50-29 C
8812220090 8812220092 8812220100 8812220105 8812220119	8812220082	88/12/14	50-392 P	8812270235	8812270233	88/12/19	60-28 8 0
8812220100 8812220105	8812220104 9812220101	88/11/02 88/09/01	70-687 50-259 Q	8812270240 8812270243	8812270238 8812270232	88/12/22 88/12/20	70-398 50-280
8812220119	8812220115	88/10/28	60-327 Q	8812270245	8812270244	88/09/08	60-259 C
8812220120 8812220127	8812220112 8812220124	88/12/05 88/12/09	60-327 Q 50-424 Q 50-424 P	8812270246 8812270248	8812270238 8812270238	88/12/22 88/12/22	70-398 70-398
8812220176	8812220174	88/12/07	50-285 P	8812270260	8812270249	88/12/20	60-333 0
8812220177	8812220172	88/12/19	71-6386	8812270251	8812270249	88/12/20	60-333

ACCESSION NUMBER			ACCESSION NUMBER						
OSURE	PRINCIPAL DATE DOCUMENT ISSUED		SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
20275 70276 70278 70278 70225 70225 70227 70239 70394 50003 50006 50006 50008 50012 60021 50026 50028	8812270273 8812270272 9812270275 9812270289 8812270284 8812270284 8812270303 8812270303 8812280002 8812280002 8812280002 8812280002 8812280002 8812280002 8812280002 8812280002	83/12/19 88/12/20 88/12/16 88/12/13 88/12/13 88/12/13 88/12/13 88/12/19 88/12/22 88/12/19 88/12/19 88/12/19 88/12/19 88/12/19 88/12/19 88/12/19 88/12/19 88/12/19 88/12/19	50-286 50-335 50-423 CONTRACT XPORTLIC XPORTLIC 50-341 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322	999 PP6666666666	8812280040 8812280088 8812280113 8812280116 8812280124 8812280160 8812280160 8812280160 8812280273 6812290289 6812290289 6812290289 6812290289 6812290289 6812290289 6812290289 6812290289	8812280009 8812280009 8812280009 8812280009 8812280108 8812280160 8812280165 6812280165 6812290266 6812290266 6812290266 6812290266 6812290266 6812290266 6812290266 6812290266 6812290266	88/12/19 88/12/19 88/12/19 88/12/19 88/12/19 88/12/19 88/12/14 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20	50 335 50-335 50-335 50-335 50-335 50-335 50-443 50-603 FOIA FOIA FOIA FOIA FOIA FOIA FOIA FOIA	TTTTTGGG

ACCESSION NUMBER ACCESSION NUMBER

ACCESSIO	ACCESSION NUMBER						
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8012210108	8812210098	88/12/01	40-8857	8812220201	8812220198	88/12/14	50-294
8512210115	8812210114 8812210118	88/12/15 88/12/19	50 269 P 50 275 T	8812220202	8812220199	89/12/19	50-334 50-334
8812210120 8812210122	8812210118	88/12/19	50-275 T	8812220204 8812220211	8812220199 8812220206	88/12/19 88/12/15	50-295
8812210128	8812210118	88/12/19	50-275 T TOPREP	8812220214	8812220206	88/12/15	50-295
8612210130 6812210140	8812210128 8812210134	88/11/23 88/05/18	CONTRACT	8812220215 8812220221	8812220212 8812220208	08/10/03 88/12/12	50-259 50-293
8812210152	8812210145	88/11/03 88/12/15	71-24	8812220224	8812220222	88/12/14	50-338
8612210155 6812210171	8812210154 8812210139	08/11/28	40-3453	8812220227 8812220228	8812220222 8812220222	88/12/14 88/12/14	50-338 50-338
8812210173 8812210185	8812210168 8812210065	88/12/12 88/12/14	50-289 F 50-206 P	8812220235 8812220236	8812220232 8812220232	88/12/19 88/12/19	50-416 50-418
8812210189	8812210186	88/12/07	40-8027	8812220253	8812220252	88/12/12	40-8829
8612210193 8812210200	9812210043 8812210199	88/12/12 88/12/16	50-313 S 50-260 P	8812220255 8812220258	8812220254 8812220257	88/12/12 88/12/18	40-8926 50-369
8812210208	8812210204	88/12/13	50-458 P	8812220260	8812220257	88/12/16	50-389
8812210209 8812210210	0012210204 8812210204	88/12/13 88/12/13	50-458 P 50-458 P	8812220283 8812220265	8812220262 8812220262	88/12/15 88/12/15	50-245 50-245
8812210221	8812210217	88/12/14	50-390 A	8812220272 8812220273 8812220276 8812220283	8812220268	88/12/13	50-334
8812210224 8812210233	8812210223 8812210231	88/12/14 88/08/02	40-8857 Waste Mgt	8812220273 8812220278	8812220268 8812220268	88/12/13 88/12/13	50-334 50-334
0812210244	8812210232	88/12/09	50-282 C)	8612220283	8812220282	88/12/12	40-8904
8812210255 8812210273	8812210254 8812210206	88/12/12 88/12/16	50-397 P 50-259 F	8812220303 8812220323	8812220301 8812220308	88/12/12 88/12/19	71-6348 50-255
8812210276	8812210206	88/12/16	50 259 F	8812220330	8812220326 8812220331	89/12/19	50-346
8812210278 8812210281	8812210211 8812210184	88/12/12 88/12/12	50-313 S 50-368 S	8812220334 8812220335	8812220331 8812220326	88/12/15 88/12/19	60-271 50-346
0812210284	8812210283	88/12/14	50-483 Q	8812220337	8612220326 8812220326	BB/12/19	50-348
8812210298 8812210302	8812210294 8812210297	08/12/20 88/12/14	50-322 F 50 390 A	8812220338 8812220341	8812220331 8812220328	88/12/15 88/12/16	50-271 50-336
8912210304	8812210301	88/12/13	50-313 Q	8812220352	8812220343	88/12/05	50-335
8812210311 8812210312	8612210306 8812210308	88/12/12 88/12/14	50-443 H 50-285 O	8812220371 8812220385	8812220367 8812220382	88/12/21 88/12/15	WASTE MGT 60-466
8812210313	8812210308	88/12/14	50-285 Q	8812220388	8812220384	88/12/16	50-499
8812210315 8812210317	8812210314 8812210310	88/12/14 88/12/16	50-317 P QA999	8812220391 8812220394	8812220384 8812220384	88/12/16 88/12/16	50-499 50-499
6812210319 8812210321	8812210310	88/12/16	QA999 QA999	8812220397 8812220401	8812220396 8812220400	88/12/15	50-353 50-289
8812210325	8812210310 8812210323	88/12/16 88/12/16	50-361 P	8812230014	8812230012	88/12/12 88/12/16	50-390
8812210327 8812210328	8812210323 8812210324	88/12/16 88/12/16	60-361 P QA999	8812230022 8812230029	8812230020 8812230027	88/12/15 88/12/20	50-336 50-250
8812210329	8812210324	88/12/18	QA999	8812230032	8812230030	88/12/08	50-309
0012210335 8812210336	8812210332 8812210332	88/12/15 88/12/15	50-410 P 50-410 P	8812230046 8812230067	8812230044 8812230044	88/12/19 88/12/19	60-361 50-361
8812210337	8812210331	88/12/15	60-482 Q	8812230071	8812230069	88/12/16	60-285
8812210338 8812210339	8812210334 8812210334	88/12/16 88/12/16	QA999 QA999	8812230073 8812230084	8812230069 8812230081	88/12/16 88/12/06	60-205 60-295
8812210340	8812210334	88/12/16	QA999	8812230089	8812230086	88/12/17	60-322
8812210341 8812210342	8812210331 8812210331	88/12/15 88/12/15	50-482 Q 50-482 Q 50-313 Q	8812230092 8812230094	8812230086 8812230086	88/12/17 88/12/17	50-322 50-322
8812210347 8812210360	8812210346	88/12/14 88/11/18		8812230107	8812230099	88/12/02	PROJ PROJ
881 <i>2</i> 210362	8812210356 8812210361	88/12/08	70-27 40-8684	8812230108 8812230109	8812230099 8812230104	88/12/02 88/12/15	60-313
8812210366 8812210376	8812210364 8812210371	88/12/15 88/12/14	50-387 F 50-155 Q	8812230111 8812230129	8812230104 8812230125	88/12/15 88/11/22	50-313 71-390 0
8812210393	0812210390	88/12/08	50-454 Q	8812230139	8812230121	88/12/14	50-275
8812210394 8812210396	8812210383 8812210390	88/12/14 88/12/08	50-312 P 50-454 Q	8812230140 8812230141	8812230134 8812230134	88/12/06 88/12/06	50-277 50-277
8812210398	8812210383	88/12/14	50-312 P	8812230155	8812230121	88/12/14	50-275
8812210403 8812210405	8812210400 8812210404	88/12/06 88/12/09	TOPREP 50-155 Q	8812230172 8812270024	8812230162 8812270014	88/12/12 88/12/15	50-454 60-322
8812210408	8812210407	88/12/08	70-1703	8812270045	8812270040	88/12/16	50-346
8812220003 8812220019	8812220002 8812220015	88/12/07 88/12/07	50-142 W 50-112 P	8812270048 8812270062	8812270040 8812270057	88/12/16 88/12/16	50-346 50-440
8812220026	8812220021	88/12/16	50-280 Q	8812270098	8812270091	88/12/15	50-341
8812220027 8812220028	0B12220025 8B122102 9 6	68/12/12 86/12/01	50-482 Q 40-2259	8812270107 8812270117	8812270104 8812270112	86/12/20 88/12/19	60-259 50-361
8812220036 8812220045	8812220032 8812190093	88/12/14	50-321 P 50-603 A	8812270127 8812270131	ØB12270123	68/12/15	50-440 50-440
8812220057	8812220055	88/12/07 88/12/14	50-354 P	8812270141	8812270123 8812210355	88/12/15 88/12/15	50-218
8812220058 8812220061	8812220056 8812220055	88/12/14 88/12/ 1 4	50-352 P 60-354 P	8812270153 8812270182	8812270151 8812270160	88/12/16 88/12/16	50-454 50-220
8812220083	8812220055	88/12/14	50-354 P	8812270188	8812270112	68/12/19	50-381
8812220064 8812220067	8812220060 8812220062	88/12/13 88/12/14	WASTE MGT 50-333 P	8612270215 8812270218	8812210220 8812270214	88/12/16 88/12/15	WASTE MOT 60-341
8812220068	8812220065	88/12/14	50-382 P	8812270219	B812270214	88/12/16	50-341
8812220072 8812220088	8812220065 8812220085	88/12/14 88/12/14	50-382 P 40-3453	8812270227 8812270229	8812270221 8812270225	88/12/22 88/12/15	FOIA 50-443
6812220090	8812220082	88/12/14	50-382 P	8812270230	8812270228	88/12/16	60-28
8812220092 8812220100	8812220082 8812220104	88/12/14 88/11/02	50-382 P 70-687	8812270235 8812270240	8812270233 8812270238	88/12/19 88/12/22	50-266 70-398
8812220100 8812220105 8812220119	8812220104 8812220101 8812220115 8812220112	86/09/01	50-259 Q	8812270243	8612270232	88/12/20	50-250 50-259
8812220120 8812220127	8812220112	88/10/28 88/12/05	50-327 O 50-424 O	8812270245 8812270246	8812270244 8812270238	88/09/08 88/12/22	70-398
8812220127 8812220176	8812220124 8812220174	88/12/09 88/12/07	50-424 P 50-285 P	8812270248 8812270250	8812270238 8812270249	88/12/22 88/12/20	70-398 50-333
8812220176 8812220177	8812220172	88/12/19	71-6386	8812270251	8812270249	88/12/20	60-333

ACCESSION NUMBER									
SURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO	
0275 0276 0278 0278 0285 0285 0364 0304 0005 0005 0003 0012 0003 0012 0021 0026	6812270273 B812270272 8812270277 8812270268 8612270284 8612270284 8612270284 8612270303 8612280002 8612280002 8612280002 8812280002 8812280002 8812280002 8812280002 8812280002 8812280002 8812280002	88/12/19 68/12/20 88/12/16 68/12/21 68/12/13 68/12/13 68/12/13 68/12/12 68/12/19 68/12/19 68/12/19 68/12/19 68/12/19 68/12/19 68/12/19 68/12/19 68/12/19 68/12/19 68/12/19 68/12/19 68/12/19	50-286 50-335 50-423 CONTRACT XPORTLIC XPORTLIC 50-341 50-322 50-322 60-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322 50-322	000 1100000000000	6012280040 6812280066 6812280103 6812280116 6812280124 6812280156 6812280157 6812280158 6812280273 6812290281 6812290281 6812290282 6812290282 6812290288 6812290288 6812290288 6812290288	8812280009 8812280009 8812280009 8812280009 8812280128 6812280128 6812280165 8812280165 8812280286 8812290286 8812290286 8812290286 8812290286 8812290286 8812290286 8812290286 8812290286	88/12/19 88/12/19 88/12/19 88/12/19 88/12/19 88/12/19 88/12/14 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20 88/12/20	50-335 50-335 50-335 50-335 50-335 50-443 50-603 FO:A FOIA FOIA FOIA FOIA FOIA FOIA FOIA FOI	TTTTTGGGG PPG

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- i. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

- This category is strictly limited to the items listed below. All related correspondence falls in category A or P.
 - 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
 - 2. Amendments and changes to the FSAR.
 - 3. Federal register notices citing availability of items 1 and 2.
 - 4. Transmittal and acknowledgement letters.
 - 5. Certificates of service to the FSAR.

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWAs.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- Statements and written testimony by ACRS members or presented by individuals at ACRS
 proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 4. Petteral register morrees entire attended by
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

This coregory mendeus performe reports of a routine mature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- Periodic personnel exposure reports.
- Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
- 8. Corrections to above items.

inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

- License applications, licenses, amendments and proposed amendments to possess power reactor spent
 fuel and other radioactive materials associated with spent storage in an independent spent fuel
 storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate
 site.)
- 2. All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements: description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM - NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

- 1. Charters of each advisory committee.
- 2. Verbatim transcripts of committee meetings.

5. Committee related correspondence.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

- 1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any,

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2 Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
- Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. 1&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.
- NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC cants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, includi: dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT -- Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- in the Waste Isolation Pilot Plan (WIPP) for buries of defense wastes.
- NRC draft staff guides for developing positions on the content and format of environmenta reports for geological repositories.

WASTE RES - Waste Management Research Reports

Contains interim and final reports, as d correspondence submitted to NRC by its contractors doing research on topics related to the storage of high-level radioactive waste.

- 1. Periodic progress reports on the status of research.
- 2. Trip reports of travel by NRC and contractor personnel.
- 3. Draft, partial or related reports submitted for NRC review or information.
- Correspondence between NRC staff and contractors relating to technical questions or issues to be resolved.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- Correspondence from foreign governments, international organizations, and members of the public.
- Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses,
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- Hearing records and decisions.
- Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Co. imission decision on iscuance of a proposed license.
- 10. Licenses liceuse amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissione: consideration or information, see 10CFR category.

ASTRUCTIONS ON THE REVERSE	1 1011 10, 110	. 12				
TLE AND SUBTITLE	3 LEAVE BLANK					
Title List of Documents Made Publicly Available						
December 1-31, 1988						
		REPORT COMPLETED				
1rOAISI	MONTH	YEAR				
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	6 DA1	E REPORT ISSUED				
	MONTH	YEAR				
	March	1989				
AFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zio Code)	B PROJECT/TASK/WORK	JNIT NUMBER				
ivision of Freedom of Information and Publications Ser	L					
ffice of Administration .S. Nuclear Regulatory Commission	9 FIN OR GRANT NUMBE	9				
ashington, DC 20555						
15h Higcon, DC 20000	1					
POSSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)	11. TYPE OF REPORT					
Same as 7, above.	Monthly					
·		December 1-31, 1988				
	becember 1-	31, 1900				
. PPLEMENTARY NOTES						
ISTRACT 1200 word, of fail. This document is a monthly publication containing des						
and generated by the U.S. Nuclear Regulatory Commissi includes (1) docketed material associated with civili uses of radioactive materials, and (2) nondocketed ma NRC pertinent to its role as a regulatory agency. Th Personal Author, Corporate Source, Report Number, and Documents.	an nuclear power terial received e following inde	plants and other and generated by xes are included:				
OCUMENT ANALYSIS - & KEYWORDS/DESCRIPTORS		15 AVAILABILITY				
7247- 12-1		1				
Title list		Unlimited				
		16. SECURITY CLASSIFICATIO				
		(This page)				
INTIFIE ASJOPEN ENDED TERMS		Unclassified				
		Unclassified				
		17 NUMBER OF PAGES				
		IS PRICE				